

*S. DUNBAR*

MIT/IL SOFTWARE ANOMALY REPORT

RECORDED  
L-1B-03

1.1 ORIGINATOR: R. GOSS	1.2 ORGANIZATION: MIT/IL	1.3 DATE: 8/27/69	1.4 ORIGINATOR CONTROL NO.
1.5 DESCRIPTION OF ANOMALY:			

PROJECT:  
LUMINARY 1B  
PROGRAM/REVISION:  
Rev 116

The quantity COEFFR, computed in the 1/ACCS Program, will be incorrectly determined to be an extremely small (essentially zero) value whenever the quantities 1JACCO and 1JACCR are equal. In the present program (and previous programs), 1JACCO and 1JACCR must differ by at least one bit and the anomaly is not observed. Modifications in future programs, however, might result in the occurrence of the anomaly. In particular, if values of LM descent mass...

CONTINUED ON PAGE 2

1.6 EXECUTION OF TEST: The hybrid simulator was used with Luminay 116. The fixed constant IHDESCNT was changed to allow higher values of LM descent mass to be used in the computations of 1JACCO and 1JACCR. A mass was loaded in such that 1JACCO and 1JACCR were computed to be exactly equal. Under these conditions the anomaly...
CONTINUED ON PAGE 2

-MIT ANALYSIS-

2.1 CAUSES: In the "COMMEQS" section of 1/ACCS, the expression (1JACCO-1JACCR)/1JACCR is computed whenever 1JACCR is greater or equal to 1JACCO.
CONTINUED ON PAGE 2

2.2 CONSEQUENCE: The occurrence of the anomaly would result in a buildup of attitude errors and error rates about the Z-axis during each two-second interval in which the condition occurs.
CONTINUED ON PAGE 2

2.3 POSSIBLE FIXES: The anomaly cannot occur for the present program. If it were to occur in a future program, control would be lost about the vehicle Z-axis for every two-second period in which the quantities 1JACCO and...
CONTINUED ON PAGE 2

2.4 LM DESCENT: For powered descent, the value of initial LM descent mass loaded into the computer should be selected to lie below the regions in which the anomaly can occur.
CONTINUED ON PAGE

2.5 LM ASCENT: If anomaly were to occur in powered ascent, the DAP would automatically begin correcting errors at the end of the two-second interval. In powered...
CONTINUED ON PAGE 2

2.6 FAULT CORRECTION: To correct anomaly, a ZJ instruction should be added at "COMMEQS" in the 1/ACCS section.
CONTINUED ON PAGE

2.7 RECOMMENDED DISTURBANCE (Rx, Ry, Rz, Curr, Disk): For missions after Apollo 12, fix should be made.
CONTINUED ON PAGE

2.8 RECOMMENDED TESTING: When fix is made, above testing should be repeated.
CONTINUED ON PAGE

3.1 FAULT DIRECTIVE: <i>Fix in 11664.1.28 EC</i>	2.9 FINAL SIGNATURE: <i>J. S. Dunbar</i>	2.10 DATE: <i>9/1/69</i>
4.1 CLOSING ACTION LIST: <i>fix in 1.28</i>		

CONTINUED ON PAGE
CONTINUED ON PAGE

CONTINUED ON PAGE
CONTINUED ON PAGE

CONTINUED ON PAGE
CONTINUED ON PAGE

CONTINUED ON PAGE
CONTINUED ON PAGE

CONTINUED ON PAGE
CONTINUED ON PAGE

# MIT/IL SOFTWARE ANOMALY REPORT

1.1 CREDITS	1.2 DATE ISSUED	1.3 PAGE	1.4 CREDIT	1.5 SUBJECT
R. CROSS	MIT/IL	8/27/69	CROSS, R.	LUMINARY 1B Rev 116

## 1.6 Description of Anomaly, cont'd.

... exceeding 10120 it were to be altered in computing 1JACCO and 1JACCR, then the values returned by 1JACCO and 1JACCR could be equal. (The fixed constant 101200000 would have to be increased for this situation to occur.) Also, if the coefficients used to compute 1JACCO and 1JACCR as a function of mass were to be modified, the anomaly might occur in either descent or ascent.

## 1.6 Description of Anomaly, cont'd.

... was observed. Examination of individual computations provided an explanation for this anomaly.

## 2.1 Causes, cont'd.

The result of this computation shall be either a negative number or zero. However, when 1JACCO = 1JACCR, a non-zero positive number may result from the division. This results from the fact that 1JACCO and 1JACCR are single precision numbers, and the division computation uses both the upper and lower account data for the numerator. Since L was not zeroed before the computation, a positive number rather than zero can result from the division. This quotient is later subtracted from NEGMAX leading to an overflow and the subsequent incorrect value for COEFF1.

## 2.3 Mission Effect, cont'd.

... 1JACCR were computed to be equal. If the anomaly were to occur during powered ascent, it would not be expected to exist in more than one two-second period. In descent, however, it could conceivably occur for several two-second periods. Appropriate action could prevent necessity for mission abort.

## 2.5 Recovery Procedure, cont'd.

... descent, it would be necessary for the astronaut to decrease the value of mass (through R03) to a value which lies below the regions in which the anomaly can occur.