MIT/IL SOFTWARE ANOMALY REPCRT MESCAL IMSC REPORT NO. L-113-04 1.4 ORIGINATOR PROGRAM 1.1 ORIGINATOR: 1.2 ORGANIZATION 1.3 DATE: LUMINARY CONTROL NO. MIT/IL 9/17/69 B. McCoy PROGRAM REVISION 116 1.5 DESCRIPTION OF ANOMALY: During the Descent, switching the RR Mode Control into LGC position and then out disables the X-pointer meter for FORWARD and LATERAL VELOCITY display. CONTINUED ON PAGE 1.6 DESCRIPTION OF RUN: Normal Descent, with closed RR CBs, the RR mode was changed from SLEW-to-LGC-to SLEW. The X-pointers then stayed at the null center position. CONTINUED ON PACE - MIT ANALYSIS -2.1 CAUSE: Routine R10 sets the RR Error Counter ENABLE bit (Chan 12 bit 2). T4RUPT sees that RR mode went out of LGC and removes the RR Error Counter Enable. R10 . CONTINUED ON PAGE doesn't subsequently set this bit 2.2 RECOGNITION: Observing no display on X-pointers after cycling RR mode switch. CONTINUED ON PAGE 2.3 MISSION EFFECT: No FORWARD or LATERAL VELOCITY displayed on X-pointers; makes final CONTINUED ON PAGE landing phase difficult. 2.4 AVOIDANCE PROCEDURE: Keep RR CBs open during Descent or leave RR mode switch out of LGC mode. CONTINUED ON PAGE 2.5 RECOVERY PROCEDURE: Cycle the MODE SELECT switch from PGNS to AGS to PGNS. CONTINUED ON PAGE 2.6 PROGRAM CORRECTION: Set RR Error Counter Enable every time SPEEDRUN is called in SERVICER, if it is not already set. CONTINUED ON PAGE 2.7 RECOMMENDED DISPOSITION (Fix, Work-around, etc): Fix for LUMINARY 1C. CONTINUED ON PAGE 2.8 RECOMMENDED RE-TESTING: 2.10 DATE: Do run of 1.6 and verify X-pointers 2.9 MIT/IL SIGNATURE 9-22-69 display velocity data. CONTINUED ON PAGE 41 CLOSING ACTION TAXEN: 3.1 NASA DIRECTION: CONTINUED ON PAGE CONTINUED ON PAGE 4.3 ORGANIZATION: L4 DAIL: 3.3 ORGANIZATION 3.4 DATE: 4.2 SIGNATURE: 3.2 MASAVIASC SIGNATURE:

NSC Form 1400 (Rev May 68)