

CAP COMM

APOLLO 8

CMP CHECKLIST

PART NO.	S/N
SKB 32100028-201	1004

00:00

CDR

CMP

LMP

72.2°
90.2°
108.2°

POST INSERTION CONFIG
SM/CM RCS/C&W CK

REMOVE HELMET & GLOVES

ECS POST
INSERT CK

ECS POST
INSERT CK

GDC ALIGN

EPS PER MON
ECS MON CK
SPS PER MON
PUGS TEST
ECS REDUND
COMP CK
FC PURGE CK

MOUNT ORDEAL

JETT OPTICS
INSTALL COAS COVER
COAS HORIZ CK

00:30

72.2°
90.2°
108.2°

OPTICS CK
&
IMU REALIGN
P52

01:00

72.2°
90.2°
108.2°

01:30


72.2°
90.2°
108.2°

CMP INSERT CKS

G&C CHECKLIST

P22

P23



Basic Date - Nov. 6, 1968
Changed - Dec. 13, 1968

103

POST INSERTION CHECKLIST

- 1 SM RCS HTRS (4) - PRIM
CM RCS PRPLNT (both) - OFF, tb-bp
C/W FUNCTION - NORMAL
HATCH GEAR BOX - LATCH (verify)
ACTR HNDL SELECTOR - neutral
- 2 SM RCS ck
SM RCS SEC PRPLNT TB (4) - bp
He 1&2 TB (8) - GRAY
PRIM PRPLNT TB (4) - GRAY
RCS IND SW - SM A, B, C, D
PKG TEMP - 105°-195°F
He PRESS - Record _____
MANF PRESS - 178-192 psig
He TK TEMP - Record _____
PRPLNT QTY - Record _____
- 3 CM RCS ck
CM RCS PRPLNT TB (both) - bp
RCS IND SW - CM 1, 2
He TEMP - 60-90°F
He PRESS - 4000-4450 psia
FUEL PRESS - 25-~~60~~^{12.5} psia
OXID PRESS - 25-~~60~~^{12.5} psia
- 4 C&WS OPER ck
C/W LAMP TEST - 1 (hold)
M/A Pnl 1 - ON
LH C/W lts (16) - ON
C/W LAMP TEST - 2 (hold)
M/A Pnl 1 - OFF
LH C/W lts (16) - OFF
M/A Pnl 3 - ON
RH C/W lts (23) - ON
C/W LAMP TEST - OFF (lts OFF)
C/W CSM - CM
CM RCS lt (both) - ON
M/A tone & lts (3) - ON, RESET
M/A tone & lts (3) - OFF
C/W CSM - CSM
CM RCS lts (both) - OFF

CMP INSERT CKS

G&C CHECKLIST

P22

P23

CMP
I-1

CMP
I-2

CMP to LEB

PYRO A&B SEO A&B cb(both)-open
SECS LOGIC (both) - OFF (CDR)

MAIN REG B vlv - CLOSE

EMER CAB PRESS vlv - 1

PUSH TO TEST - PUSH (O2 FLOW INC)

MAIN REG B vlv - OPEN

MAIN REG A vlv - CLOSE

EMER CAB PRESS vlv - 2

PUSH TO TEST - PUSH (O2 FLOW INC)

MAIN REG A vlv - OPEN

EMER CAB PRESS vlv - BOTH (OFF if suited)

SUIT CKT RET vlv - OPEN (pulled)

REMOVE HELMETS & GLOVES

SEC RAD LEAK CK

Notify LMP when ready to commence

SEC GLY to RAD vlv - NORMAL

Allow 30 sec for LMP to monitor accum qty

SEC GLY to RAD vlv - BYPASS

ECS POST INSERT CONFIG (CDR & LMP)

DRINKING WATER SUP vlv - ON (CCW)

SYS VERIF & MONITORING

UNSTOW CAMERAS

B3 - 16 mm DAC, 18 mm lens, Rt angle mirror,
16 mm C-EX mag, Pwr cable,

70 mm camera, 80 mm lens, 70 mm C-mag

R13- Spot

OPTICS DUST COVER JETT

Install Eyepieces

OPTICS ZERO - OFF

G/N OPT PWR - ON

OPT MODE - MAN

OPT COUPLING CONT - DIRECT

OPT SPEED CONT - HI

OHC - MAX RIGHT - OBS EJECT thru eyepiece

IMU REFSMMAT REALIGN ck (P52), pg G-56

X Torquing angle _____

G/N PWR OPTICS - OFF

G&C CHECKLIST TABLE OF CONTENTS

ITEM

PAGE

Star List	G-1
Verb List	G-2
Noun List	G-5
VO5 NO9 Alarm Codes	G-10
V50 N25 Checklist Codes	G-13
VO4 N06 Option Codes	G-13
CMC Power Up Procedure	G-14
IMU Power Up Procedure	G-14
P06 CMC Power Down Program	G-14
IMU Power Down Procedure	G-15
P17 TPI Search or P77 LM TPI Search	G-16
P20 Rendezvous Navigation	G-17
P21 Ground Track Determination	G-18
P22 Orbital Navigation	G-19
LDG Site - Auto Optics	G-21
Unkn Cont Pt. - Man Optics	G-23
Kn Cont Pt. - Auto Optics	G-25
P23 Optics Calibrations	G-27
P23 Cislunar Midcourse Nav. Measurement	G-28
P27 CMC Update	G-33
P30 External ΔV	G-35
P31 General Lambert Prethrust	G-35
P34 TPI Prethrust (P74 LM)	G-36
P35 TPM Prethrust (P75 LM)	G-38
P37 Return to Earth Program	G-39
P38 SOR Targeting (P78 LM)	G-41
P39 Stable Orbit Mid (P79 LM)	G-42
P40 SPS Thrusting	G-43
P41 RCS Thrusting	G-50
P47 Thrust Monitor	G-54
P51 IMU Orientation	G-55
P52 IMU Realign	G-56
P53 Backup IMU Orient Determination	G-59
P54 Backup IMU Realign	G-60
P76 Target ΔV	G-62
V41 N91 Coarse Align OCDU's	G-62
V41 N20 Coarse Align ICDO's	G-63
V42 Gyro Torquing	G-63

CMP INSERT CKS 5

6

7

8

9

1

2

3

Basic Date Nov. 6, 1968
Changed Dec. 15, 1968

Basic Date Nov. 6, 1968
Changed Nov. 27, 1968

103

CSM 103

G&C CHECKLIST

P22

P23

V48 DAP Activation	G-64
V48 DAP Data Load Procedure	G-64
V49 Crew Defined Maneuver	G-65
V55 CMC Time Update	G-65
V64 Start S-Band Antenna	G-66
V67 W-Matrix Error Display	G-66
V74 CMC Downlink	G-66
V79 Lunar Landmark	G-67
V82 Orbit Parameter Display	G-67
V83 Rndz Parameter Display #1	G-68
V85 Rndz Parameter Display #2	G-68
V89 Rendezvous Final Attitude	G-68
V90 Out-of-Plane Display	G-69
V91 Compute Banksum	G-69
CMC Self Check	G-70
Measurement and Loading of PIPA Bias	G-70
Flag Word Set/Reset	G-71
Binary-to-Decimal Conversion	G-72
Review Data in Erasable Memory	G-73
To Change Data in Erasable Memory	G-73
COAS LOS Determination	G-74
P22 Raw Data Readout	G-75
DSKY Condition Light Test	G-76
Monitor of Input/Output Channels	G-76
Load Output Channels	G-76
Flag Word Listing	G-77
V60-63 Description	G-80
SCS Power Up	G-81
SCS Power Down	G-81
GDC Alignment to IMU Gimbal Angles	G-82
SCS Attitude Reference Comparison	G-82
Backup GDC Alignment	G-83
Backup GDC & IMU Alignment	G-83
In-plane GDC Alignment	G-84
PGNS ORDEAL Initialization	G-85
SCS ORDEAL Initialization	G-85
PASSIVE THERMAL CONTROL	G-86
(X axis Roll, Pitch & Yaw Hold)	
No Comm procedures	N.C.-1

CSM 103

Basic Date Nov. 6, 1968
 Changed Dec. 15, 1968

CSM 103

Basic Date Nov. 6, 1968
 Changed

STAR LIST		
STAR NAME (Numerical)	STAR NAME (Alphabetical)	
00 Planet	Acamar	6
1 Alpheratz	Achernar	4
2 Diphda	Acrux	25
3 Navi	Aldebaran	11
4 Achernar	Alkaid	27
5 Polaris	Alphard	21
6 Acamar	Alphecca	32
7 Menkar	Alpheratz	1
10 Mirfak	Altair	40
11 Aldebaran	Antares	33
12 Rigel	Arcturus	31
13 Capella	Atria	34
14 Canopus	Canopus	14
15 Sirius	Capella	13
16 Procyon	Dabih	41
17 Regor	Deneb	43
20 Dnoces	Denebola	23
21 Alphard	Dephda	2
22 Regulus	Dnoces	20
23 Denebola	Earth	47
24 Gienah	Enif	44
25 Acrux	Fomalhaut	45
26 Spica	Gienah	24
27 Alkaid	Menkar	7
30 Menkent	Menkent	30
31 Arcturus	Mirfak	10
32 Alphecca	Moon	50
33 Antares	Navi	3
34 Atria	Nunki	37
35 Rasalhague	Peacock	42
36 Vega	Planet	00
37 Nunki	Polaris	5
40 Altair	Procyon	16
41 Dabih	Rasalhague	35
42 Peacock	Regor	17
43 Deneb	Regulus	22
44 Enif	Rigel	12
45 Fomalhaut	Sirius	15
46 Sun	Spica	26
47 Earth	Sun	46
50 Moon	Vega	36

VERB LIST (Decimal)

- 01 Display Oct Compnt 1 (R1)
- 02 Display Oct Compnt 2 (R1)
- 03 Display Oct Compnt 3 (R1)
- 04 Display Oct Compnt 1, 2 (R1, R2)
- 05 Display Oct Compnt 1, 2, 3 (R1,R2,R3)
- 06 Display Decimal (R1 or R1, R2 or R1,R2,R3)
- 07 Display DP Decimal (R1,R2)
- 11 Monitor Oct Compnt 1 (R1)
- 12 Monitor Oct Compnt 2 (R1)
- 13 Monitor Oct Compnt 3 (R1)
- 14 Monitor Oct Compnt 1, 2 (R1, R2)
- 15 Monitor Oct Compnt 1, 2, 3 (R1,R2,R3)
- 16 Monitor Decimal (R1 or R1,R2 or R1,R2,R3)
- 17 Monitor DP Decimal (R1,R2)
- 21 Load Compnt 1 (R1)
- 22 Load Compnt 2 (R2)
- 23 Load Compnt 3 (R3)
- 24 Load Compnt 1, 2 (R1, R2)
- 25 Load Compnt 1, 2, 3 (R1, R2, R3)
- 27 Display Fixed Memory
- 30 Request Executive
- 31 Request Waitlist
- 32 Recycle Prog
- 33 Proceed Without DSKY inputs
- 34 Terminate Function
- 35 Test Lights
- 36 Request Fresh Start
- 37 Change Prog (Major Mode)
- *40 Zero ICDU (N20)
- 41 Coarse Align CDU (N20 & N91)
- 42 Fine Align IMU
- *44 Set surface flag
- *45 Reset surface flag
- *46 Activate DAP
- *47 Set LM State Vector into CSM State Vector
- 48 Load DAP (R03)
- 49 Start Crew Defined MNVR(R62)
- 50 Please Perform

- 51 Please Mark
- *52 Marked on offset landing site
- 53 Please Mark alternate LOS
- 54 Start REND backup sighting mark (R23)
- 55 Increment CMC Time (Decimal)
- *56 Terminate Tracking (P20)
- 57 Start REND sighting mark (R21)
- *58 Reset Stick FLAG
- 59 Please Calibrate
- *60 Set N17 = N20
- *61 Display DAP att error
- *62 Display total att error (N22-N20)
- *63 Display total astro att error (N17-N20)
- 64 Start S-band ant routine (R05)
- *65 Verify Prelaunch Align Optics (CSM)
- *66 Set CSM State Vector into LM State Vector
- 67 W-Matrix RMS Error Display
- *69 Restart
- 70 Update Liftoff Time (P27)
- 71 Univ Update-BLOCK ADR (P27)
- 72 Univ Update-SINGLE ADR (P27)
- 73 Update CMC Time (Octal) (P27)
- *74 Initialize erasable dump via downlink
- *75 Backup Liftoff
- *76 Set preferred att flag
- *77 Reset preferred att flag
- *78 Update prelaunch azimuth
- 79 Start lunar LMK selection (R35)
- *80 Update LM State Vector
- *81 Update CSM State Vector
- 82 Start Orbit Param Disp (R30)
- 83 Start REND Param Display (R31)
- 85 Start REND Param Display No.2 (R34)
- *86 Reject REND backup sighting mark
- *87 Set VHF range flag
- *88 Reset VHF range flag
- 89 Start REND Final ATT Routine (R63)

Basic Date Nov. 6, 1968
 Changed

Basic Date Nov. 6, 1968
 Changed

CSM 107

CSM 103

- 90 Request REND out of plane display (R36)
 91 Compute Banksum
 *92 Start IMU performance test (P07)
 *93 Enable REND W matrix initialization
 *94 Enable CISELUNAR Tracking recycle
 *96 Terminate integration and go to P00
 97 SPS Thrust Fail (R40)
 99 Enable engine ignition

*Callable with other extended verb in use
 and does not lock out other extended verbs.

Basic Date 7. 6, 1968
 Changed

Basic Date 7. 6, 1968
 Changed

CSM

CSM 103

NOUN LIST (Decimal)

01	Specify Machine Address (Fract) (R1,R2,R3)	.XXXXX
02	Specify Machine Address (Whole) (R1,R2,R3)	
03	Specify Machine Address (can be R1,R2,R3)	.01°
05	Angular Error/Diff	.01°
06	Option Code (R1 & R2)	OCTAL
07	FLAGWORD operator, ECADR, BIT ID, Action	
08	Alarm Data	OCTAL
09	Alarm Codes	OCTAL
10	Channel to be Specified (R1)	OCTAL
15	Increment Machine Address (R1)	OCTAL
16	Time of event	hrs,min,.01sec
17	Astronaut total att	R,P,Y .01°
18	Auto Maneuver	R,P,Y .01°
20	Present ICDU Angles	R,P,Y .01°
21	PIPA PULSES X,Y,Z	Pulses
22	New ICDU Angles	R,P,Y .01°
24	Delta CMC Clock Time	hrs,min,.01sec
25	Checklist (please perform)	
26	Prio/Delay, ADRES, BBCON(R1,R2 & R3)	OCTAL
27	Self-Test on/off sw	
29	X SM LAUNCH Azimuth	.01°
30	Target Code(Gyrocomp verif)	
31	Time of landing site	hrs,min,.01sec
32	Time from Perigee	hrs,min,.01sec
33	Time of Ignition (GETI)	hrs,min,.01sec
34	Time of Event	hrs,min,.01sec
35	Time from Event	hrs,min,.01sec
36	Time of CMC Clock	hrs,min,.01sec
37	GETI-TPI	hrs,min,.01sec
38	State Vector Time	hrs,min,.01sec
39	Δ Time of Transfer	hrs,min,.01sec

40	TF GETI/TFC	min-sec
	VG	.1 FPS
	ΔV (Accumulated)	.1 FPS
41	Target	Azimuth .01°
		Elevation .001°
		Ident 0000X
42	Apogee Alt (HA)	.1 NM
	Perigee Alt (HP)	.1 NM
	ΔV (Required)	.1 FPS
43	Lat	.01°
		(+ North)
	Long	.01°
		(+ East)
	Alt	.1 NM
44	Apogee Alt (HA)	.1 NM
	Perigee Alt (HP)(N50)	.1 NM
	TFF	min-sec
45	Marks	XXBXX
	TF GETI of next burn	min-sec
	MGA	.01°
46	DAP Config (R1&R2)	OCTAL
47	CSM weight	LBS
	LM Weight	LBS
48	Pitch Trim	.01°
	Yaw Trim	.01°
49	ΔR	.1 NM
	ΔV	.1 FPS
	SOURCE CODE	0000X.
50	ΔR (miss distance)	.1 NM
	PERIGEE (HP)	.1 NM
	TFF	min-sec
51	RHO	.01°
	GAMMA	.01°
52	CENTANG (active veh)	.01°
53	RANGE	.01 NM
	RANGE RATE	.1 FPS
	PHI (lcl horiz)	.01°
54	Range	.01 NM
	Range Rate	.1 FPS
	Theta (lcl horiz)	.01°

Basic Date - Nov. 6, 1968

Changed

CSM 103

Basic Date - Nov. 6, 1968

Changed

CSM 103

968

55	Perigee code	CODE
	R2 E(ELEV ANGLE)	.01°
	R3 CENTANG (passive veh)	.01°
57	ΔR offset (SOR)	.1 NM
	(+ indicated behind LM)	
58	HP alt (post TPI)(SOR for P38)	.1 NM
	ΔV (TPI)(SOR for P38)	.1 FPS
	ΔV (TPF)(SOR FINAL for P38)	.1 FPS
59	ΔV LOS 1	.1 FPS
	ΔV LOS 2	.1 FPS
	ΔV LOS 3	.1 FPS
60	G Max	.01 G
	V Pred	FPS
	Gamma EI	.01°
61	Impact Lat	.01°
		(+ North)
	Impact Long	.01°
		(+ East)
	Head Up/Down	+/-00001
		(+ Heads up)
		FPS
62	VI-Inertial Vel Mag	FPS
	H Dot-Alt Rate	FPS
	H-Alt Above Pad Radius	.1 NM
63	RTGO from 0.05 G	.1 NM
	To Splash	
	VIO, Predicted Iner Vel	FPS
	TFE, time from .05G	min-sec
64	Drag Acceleration	.01 G
	VI, Inertial Velocity	FPS
	RTGO to Target	.1 NM
65	Sampled CMC Time	hrs,min,.01 sec
	(fetched in interrupt)	
66	Beta, CMD Bank Angle	.01°
	CRSRNG Error	.1 NM
	DNRNG Error	.1 NM
67	RTGO to Target	.1 NM
	Lat, Present Position	.01°
		(+ North)
	Long, Present Position	.01°
		(+ East)

68	Beta, CMD Bank Angle	.01°
	VI, Inertial Vel.	FPS
	H Dot, Alt Rate	FPS
69	Beta	.01°
	DL	.01 G
	VL	FPS
70	Star Code(before mark)	OCTAL
	LMK Data	OCTAL
	Horiz data	OCTAL
71	Star code (after mark)	OCTAL
	LMK Data	OCTAL
	Horiz data	OCTAL
72	Δ ang	.01°
	Δ alt	.1 NM
	Search option	
81	ΔVX,Y,Z (lcl vert)	.1 FPS
83	ΔVX,Y,Z (Body Control Axis)	.1 FPS
84	ΔVX,Y,Z (Other Vehicle)	.1 FPS
85	VGX,Y,Z (Body Control Axis)	.1 FPS
87	Opt Calib Data - Shaft (R1)	.01°
	Trunnion(R2)	.001°
88	Planet X	.XXXXX
	Y	.XXXXX
	Z	.XXXXX
89	Landmark - Lat	.001°
	(+ North)	
	Long/2	.001°
	(+ East)	
	Alt	.01 NM
90	REND out of Y	.01 NM
	Plane para Y DOT	.1 FPS
	PSI	.01°
91	OCDU Angles Shaft (R1)	.01°
	Trunnion (R2)	.001°
92	New OCDU Angles Shaft (R1)	.01°
	Trunnion (R2)	.001°
93	Delta Gyro Angles X,Y,Z	.001°
94	OCDU ANGLES (R56 & R23)	
	R1 SHAFT	.01°
	R2 TRUNNION	.001°

Basic Date Nov. 6, 1968

Changed

CS 103

95	Pref att ICDU angles	.01°
96	+X axis att ICDU angles	.01°
97	System Test Inputs	XXXXX.
		XXXXX.
		XXXXX.
98	System Test Results	XXXXX.
		.XXXXX
		XXXXX.
99	POS ERR	.01 NM
	VEL ERR	.1 FPS
	OPTION Code	000X.

968

Basic Date Nov. 6, 1968

Changed

CS 103

V05 N09 ALARM CODES

- 00110 Mark reject has been entered but ignored
- 00112 Mark reject with no marks being accepted
- 00113 No inbits (chan 16)
- 00114 More marks made than desired
- 00115 V41 N91 keyed with OPTICS MODE not in CMC
- 00116 Optics switch altered before 15 sec zero time elapsed
- 00117 V41 N91 keyed but CMC has reserved OCDU (from start of gimbal test in P40 until termination of TVC functional allocation of the "optics" CDU Driving Output)
- 00120 Optics torque has been requested but optics have not been zeroed since last FRESH START or RESTART
- (m)00121 In 0.05 sec following mark, an ICDU changed by more than 0.033°
- 00122 Marking not called for
- 00124 P17(77) TPI search unsuccessful
- (m)00205 PIPA saturated
- 00206 The IMU zero routine has been entered with both the GMBL LOCK lt and NO ATT lt on
- (m)00207 ISS turn-on request not present for 90 sec
- (m)00210 The IMU is not operating
- (m)00211 Coarse align error
- (m)00212 PIPA fail, but PIPA is not being used
- (m)00213 IMU not operating with turn-on request
- 00214 Program using IMU when turned OFF

- (m)00217 IMU coarse align or pulse torque difficulty has occurred
- 00220 IMU orientation unknown
- 00401 Desired middle gimbal angle is excessive
- 00404 Target out of view (90 deg test)
- 00405 Acceptable star pair is not available
- 00406 Rend navigation not operating
- 00407 Target out of view (50° test)
- 00421 W-matrix overflow
- 00605 Number of iterations exceeds loop maximum
- 00611 No TIG for given ELEV angle
- 00612 State vector in wrong sphere of influence
- 00613 Reentry angle out of limits
- 00777 ISS warning caused by PIPA fail
- 01102 CMC self test error
- *01103 Unused CCS branch executed
- **01104 Delay routine busy
- (m)01105 Downlink too fast
- (m)01106 Uplink too fast
- 01107 Phase table failure assume erasable memory is destroyed
- **01201 Executive overflow - no vac. area
- **01202 Executive overflow - no core sets
- **01203 Waitlist overflow - too many tasks
- *01206 Second job attempts to go to sleep via keyboard and display program
- **01207 No vac area for marks
- *01210 Second attempt is made to stall
- **01211 Illegal interrupt of extended verb
- *01301 Arcsin or arccos input is greater than one
- *01302 SQRT called with negative argument
- (m)01407 VG increasing
- 01426 IMU unsatisfactory
- 01427 IMU reversed

Basic Date Nov. 6, 1968
Changed

Basic Date Nov. 6, 1968
Changed

CJ 103

CS 103

898

- *01501 Keyboard and display alarm during internal use (NVSUB)
- *01502 Illegal flashing display
- 01520 V37 request not permitted at this time
- 01600 Overflow in drift test
- 01601 Bad IMU torque abort
- 01602 Bad optics during verification
- 01703 Insufficient time for integration
TIG slipped
- 03777 ISS warning caused by ICDU fail
- 04777 ISS warning caused by ICDU & PIPA fail
- 07777 ISS warning caused by IMU fail
- 10777 ISS warning caused by IMU & PIPA fail
- 13777 ISS warning caused by IMU & ICDU fail
- 14777 ISS warning caused by IMU,ICDU & PIPA fail
- (m) - Malfunction procedure indicated
- * - Generates Restart, F37
- ** - Restart and program continues
(i.e. attempted recovery)

Basic Date Nov. 6, 1968
Changed

Basic Date Nov. 6, 1968
Changed

968

V50 N25 CHECKLIST CODES

<u>R1 Code</u>	<u>ACTION</u>	<u>FUNCTION</u>
00014	Key in	Fine Align Option
00015	Perform	Celestial Body Acquisition
00016	Key in	Terminate Mark Sequence
00041	Switch	CM/SM SEP to UP
00062	Key	CMC to STBY
00202	Perform	PGNS AUTO MNVR
00204	Key in	Engine gimbal test option

V04 N06 OPTION CODES

<u>R1 Code</u>	<u>Purpose</u>	<u>Input for R2</u>
00001	Specify IMU Orientation	1=REFS, 2=NOM 3=REFS, 4=LDG SITE
00002	Specify vehicle	1=CSM, 2=LM
00003	Specify tracking Attitude	1=Preferred, 2=+X-axis
00005	Specify SOR Phase	1=First, 2=Second
00007	Specify Propulsion System	1=SPS, 2=RCS

CS 103

CS 103

CMC POWER UP PROCEDURE

1 PRO, push until STBY Lt - out
(repeat, if necessary)
CMC warning, RESTART, PROG ALARM
*RSET and continue *

2 F 37 OOE

IMU POWER UP PROCEDURE

LOGIC POWER 2/3 - on
FDAI POWER - both
FDAI SELECT - 1/2
CMC MODE - FREE

1 G/N IMU PWR - on (up)
NO ATT Lt - on (90 sec)
NO ATT Lt - out
Wait 20 sec

2 V37E XXE
*If CMC Failed: *
* G/N IMU PWR - on(up) *
* Wait 90 sec *
* IMU CAGE - on(up) 5 sec, then off* *

P06 - CMC POWER DOWN PROGRAM

1 F 04 46 V48E
Load 0 (NO DAP) in left digit of R1
PRO
PRO
PRO
V46E

2 F 50 25 V37E 06E
00062 CMC PWR DN
PRO, push until STBY Lt - on

IMU POWER DOWN PROCEDURE
CMC MODE - FREE

1 G/N IMU PWR - OFF
ISS warning
*RSET *

968

Changed

P17 - TPI SEARCH

or

P77 - LM TPI SEARCH

CMC - on (req)

1 F 06 37 V37E 17E or V37E 77E
GETI (TPI) (hrs,min,.01sec)
Load desired GETI
PRO

2 F 06 72 ΔANG(TPI),ΔALT(TPI),SEARCH OPT
(.01°, .1nm,0000X)
(Do not key V82 during this display)
R3=SEARCH OPT 00001<180°
00002>180°
(change GETI TPI) V32E To 1
(change Search opt) V23E
PRO
F 05 09 00124 alarm code
*V32E, RSET To 1 *

3 F 06 58 HP,ΔV(TPI,ΔV(TPF) (.1nm,.1fps,.1fps)
(RECYCLE) V32E To 1 to adjust
GETI or Search option
PRO

4 F 06 55 R1=Perigee Code, R3=CENTANG(0000X,.01°)
00001, perigee between TPI and TPF
00002, perigee after TPF
(RECYCLE) V32E To 1 to adjust
GETI or Search option
PRO

5 F 37 XXE

Basic Date Nov. 6, 1968

Changed

Basic Date Nov. 6, 1968

Dec. 11, 1968

Basic Date

Changed

P20 - RENDEZVOUS NAVIGATION

CMC - on (req)
ISS - on and aligned (req)
SCS - on (des)
BMAG MODE (3) - RATE 2
G/N OPT PWR - on (verify)
OPT ZERO - ZERO (verify)
OPT MODE - CMC

1 F 50 18 V37E 20E
Request MNVR to FDAI RPY angles (.01°)
If only F 50 - KEY RLSE
(AUTO) SC CONT - CMC
CMC MODE - AUTO
PRO
06 18 RPY (.01) To 1 (when MNVR complete)
(MAN) SC CONT - SCS
PRO To 1
or V62E
RHC - MNVR To 1

When attitude OK:

CMC MODE - AUTO
ENTR
OPTIC ZERO - OFF

*POSS prog alarm *
*Key V5N9E 00407 (TA>50°) *
*V16N 22E *
GMBL ANGLES RPY (.01°)
*or V16N 92E *
OPTICS SHAFT,TRUN (.01°, .001°)
*(AUTO) SCS CONT - CMC *
* CMC MODE - AUTO *
* V58E *
*(MAN) MNVR to 2 (SXT) *
* or to 3 (COAS) *

2 F 51 V57E (SXT)
OPT MODE - MAN
OHC - Cntr Target in SXT
MARK (repeat as necessary)

SM 103

SM 103

P30-39

P22

P23

POSS F 06 49 ΔR, ΔV, source code
 * (.1nm, .1fps, 00001) *
 *(REJECT) V32E *
 *(ACCEPT) PRO *
 Drive Trunnion to <5°
 OPT ZERO - ZERO

PRO (return to program in process)
 (To terminate P20 - V56E)

3 F 06 94 V54E (COAS)
 SHAFT, TRUNNION (.01°, .001°)
 PRO

4 F 53 Request Alt LOS MARK
 RHC - ALIGN Target in COAS
 ENTR (V86E To reject)
 POSS F 06 49 ΔR, ΔV, source code
 * (.1nm, .1fps, 00001) *
 *(REJECT) V32E *
 *(ACCEPT) PRO *
 PRO (return to Program in process)
 (To Terminate P20 - V56E)

P21 GROUND TRACK DETERMINATION

Note: Do not key V82 during step 1 or 2
 CMC - on (req)

1 F 04 06 V37E 21E
 00002, Specify Vehicle
 00001, CSM
 00002, LM
 PRO

2 F 06 34 GET LAT, LONG (hrs, min, .01sec)
 Load desired GET
 PRO

3 F 06 43 LAT, LONG, ALT (.01°, .01°, .1nm)
 (RECYCLE) V32E to 2 (Increment GET 10 min)
 (EXIT) PRO

4 F 37 XXE above 10,000 nm Key V16 N02E, 1107E
 ALT nm = R1(XXXXX.) x 17.7

Basic Date Nov. 6, 1968
 Changed Dec. 11, 1968

103

LANDMARK LIGHTING EVALUATION (CMP)

- 1 ATTACH SEQ. CAM ADAPTER TO SXT
1/125, 6 FPS
- 2 REVIEW OPB AND LC
- 3 NOTE TRACKING DATA
 ACQ IP-I _____
 LMK LAT _____
 LMK LONG/2 _____
- 4 CONFIRM ORBRATE ATTITUDE (LMP)
 000, 355, 000
- 5 SET OPTICS MAN AT IP-I - 5 MIN
 SHAFT 0
 TRUNNION 0
- 6 START SEQ CAM AT IP-I - 2 MIN
- 7 NOTE GET IP-I _____
- 8 DETERMINE GET IP-II (LMP)
- 9 EVALUATE BOULDER VISIBILITY
- 10 NOTE GET IP-II _____
- 11 DETERMINE GET LMK (LMP)
- 12 EVALUATE SCENE AT IP-II AND EVERY 20 SEC
 AMOUNT STD CRATER VISIBLE
 BEST STD CRATER MARKING POINT
 BEST RECOGNITION PATTERNS
 BOULDER OBSERVATIONS
- 13 MONITOR CMP DESCRIPTION (LMP)

- 14 EVALUATE SCENE AT EACH LMK OR EVERY 20 SEC
MINIMUM CRATER SIZE FOR MARKING
AMOUNT STD CRATER VISIBLE
BEST STD CRATER MARKING POINT
BEST RECOGNITION PATTERNS
- 15 MONITOR CMP DESCRIPTION (LMP)
- 16 EVALUATE SCENE IN EARTHSHINE EVERY 20 SEC
DARK ADAPTATION
TYPES OF FEATURES VISIBLE
MINIMUM CRATER SIZE FOR MARKING
CHANGE WITH EARTH-ANGLE
BEST RECOGNITION PATTERNS

Basic Date ~~Nov. 6, 1968~~
Changed ~~Nov. 27, 1968~~

SM 103

P22 - ORBITAL NAVIGATION

CMC - on (req)
ISS - on and aligned (req)
SCS - on (req)
BMAG MODE (3) - RATE 2
G&N PWR OPTICS - on (verify)
OPTICS COUPLING - RESOLVED
SPEED - MED
OPT ZERO - ZERO (verify)
OPT MODE - CMC

- 1 F 06 45 V37E 22E (.01°)
R3=MAX MGA
(REJECT) R3>60° to P52
R3<60° IMU ALIGNED
MNVR To SIGHTING ATTITUDE
Roll to keep shaft axis >10° from
plane defined by X axis & LOS to
LMK
(MAN) OPT MODE - MAN
OPT ZERO - OFF
PRO (To 3 for earth orbit)
(AUTO) OPT ZERO - OFF
PRO (To 3 for earth orbit)
- 2 F 05 70 (lunar orbit only)
R2 ABCDE lmk code
Load lmk code
A=1(known), 2(unknown)
B=INDEX OF OFFSET designator
C=not used
DE=LMK ID
IF A=2
OPT MODE - MAN
PRO to 5
or IF A=1 & DE≠00
PRO to 4 (To 5 if OPTICS - MAN)
or IF A=1 & DE=00
PRO to 3
- 3 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
Load lmk coords
PRO (To 5 IF OPTICS - MAN)

- 4 06 92 SHAFT, TRUN NEW OCDU (.01°, .001°)
 *POSS Prog Alarm lt (Trun > 50°)**
 * MNVR to acquire **
 * F 05 09 00404 (TRUN > 90°)*
 * MNVR to acquire *
 * PRO *
 * or V34E, F 37 *
 Establish proper pitch rate *
 OPTICS MODE - MAN *
- 5 F 51 MARK REQUEST
 MARK (wait 10 sec between MARKS)
 After sufficient MARKS:
 *After 5 MARKS: *
 F 50 25 00016 TERM MARKS
 PRO
- 6 F 05 71 R2 ABCDE LMK DATA
 Load lmk code (if nec)
 A=1 if KNOWN LMK
 A=2 if UNKNOWN LMK
 B=INDEX OF OFFSET DESIGNATOR
 (If only 1 mark made, insure B=0)
 C=Not used in P22
 DE=LMK ID no.
 PRO - if A=2 (or A is 1 & DE ≠ 0) to 9
- 7 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
 PRO
- 8 F 06 49 ΔR, ΔV (ORB PARA) (.1nm, .1fps)
 (REJECT CYCLE) V32E to 2
 (ACCEPT) PRO
- 9 F 06 89 LAT, LONG/2, ALT LMK ID (.001°, .001°, .01nm)
 (DON'T STORE) V32E to 2
 (STORE-CODE 01) PRO to 2
 (terminate Prog) V34E
- 10 F 37 XKE
 OPT ZERO - ZERO

Basic Date Nov. 6, 1968
 Changed Dec. 11, 1968

103

CSM 103

P22 - ORBITAL NAVIGATION
 (LDG SITE - AUTO OPTICS)

- CMC - on (req)
 ISS - on & aligned (req)
 SCS - on (req)
 ORB RATE BALL (des)
 G/N PWR OPTICS - on (verify)
 OPTICS COUPLING - RESOLVED
 SPEED - MED
 OPT ZERO - ZERO (verify)
 OPT MODE - CMC
 16mm camera - installed
- 1 F 06 45 V37E 22E
 R3=Max MGA with X axis in-plane
 If R3 > 60°, Go To P52
- MNVR to SIGHTING ATTITUDE
 Roll to keep shaft axis > 10° from
 plane defined by X axis & LOS to LMK
 PRO
- 2 F 05 70 R2=LMK DATA
 Load 10001
 OPT ZERO - OFF
 PRO
- 3 06 92 AUTO OPTICS SHAFT, TRUN (.01°, .001°)
 POSS Prog Alarm lt (Trun > 50°)
 * MNVR to acquire *
 * F 05 09 00404 (Trun > 90°)*
 * MNVR to acquire *
 * PRO *
 * or V34E, F 37 *
 Establish proper pitch rate
 OPTICS MODE - MAN

Basic Date Nov. 27, 1968
 Changed

P22

P30-39

P40, 41, 47

P23

4 F 51 REQUEST MARK
 MARK (wait 10 sec between MARKS)
 After sufficient MARKS:
 *After 5 MARKS:
 *F 50 25 00016 TERM MARKS *
 PRO

5 F 05 71 R2=10001 LMK DATA
 PRO

6 F 06 49 AR, ΔV ORB PARA (.1nm, .1fps)
 Hold 1 min
 PRO

7 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
 Compare with map
 V34E

8 F 37 XXE
 OPT ZERO - ZERO

Basic Date Nov. 6, 1968

Changed Dec. 11, 1968

SM 103

P22 ORBITAL NAVIGATION
 (UNKN CONT PT. - MAN OPTICS)

CMC - on (req)
 ISS - on & aligned (req)
 SCS - on (req)
 ORB RATE BALL (des)
 BMAG MODE (3) - RATE 2
 G/N PWR OPTICS - on (verify)
 OPT ZERO - ZERO (verify)
 OPT MODE - MAN
 16mm camera - installed
 RCDR - LBR/RCD/FWD (Verify)

1 F 06 45 V37E 22E
 R3=Max MGA with X axis in-plane
 If R3 > 60°, Go to P52

MNVR to SIGHTING ATTITUDE
 Roll to keep shaft axis > 10° from
 plane defined by X axis & LOS to LMK

PRO

2 F 05 70 R2=LMK DATA
 LOAD 20000
 Establish proper pitch rate
 OPT ZERO - OFF
 PRO

3 F 51 REQUEST MARK
 V16 N91E

4 F 16 91 SHAFT, TRUN (.01°, .001°)
 MARK (wait 10 sec between MARKS)
 After sufficient MARKS:
 *After 5 MARKS: *
 F 50 25 00016 TERM MARKS

KEY RLSE
 PRO

Basic Date Nov. 6, 1968

Changed Dec. 11, 1968

SM 103

5 F 05 71 R2 20000 LMK DATA
PRO (If only 1 MARK to 6)

6 F 06 49 $\Delta R, \Delta V$ ORB PARA (.1nm, .1fps)
PRO

7 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
Record for future use
(RECYCLE) V32E to 2
(EXIT) V34E

8 F 37 XXE
OPT ZERO - ZERO

Basic Date: Nov. 6, 1968
Changed: Dec. 11, 1968

CSM 103

P22 ORBITAL NAVIGATION
(KN CONT PT. - AUTO OPTICS)

CMC - on (req)
ISS - on & aligned (req)
SCS - on (req)
ORB RATE BALL (des)
BMAG MODE (3) - RATE 3
G/N PWR OPTICS - on (verify)
OPTICS COUPLING - RESOLVED
SPEED - MED
OPT ZERO - ZERO (verify)
OPT MODE - CMC
RCDR - LBR/RCD/FWD (Verify)

1 F 06 45 V37E 22E
R3=Max MGA with X axis in-plane
If R3 >60°, Go to P52

MNVR to SIGHTING ATTITUDE
Roll to keep shaft axis > 10° from
plane defined by X axis & LOS to LMK
PRO

2 F 05 70 R2=LMK DATA
LOAD 10000
PRO

3 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
Load lmk coords
OPT ZERO - OFF
PRO

4 06 92 AUTO OPTICS SHAFT, TRUN (.01°, .001°)
POSS Prog Alarm lt (Trun >50°)
* MNVR to acquire *
F 05 09 00404 (Trun >90°)
* MNVR to acquire *
* PRO *
* or V34E, F 37 *
Establish proper pitch rate
OPTICS MODE - MAN

Basic Date: Dec. 11, 1968
Changed: Dec. 11, 1968

CSM 103

G-26

5 F 51 REQUEST MARK
 MARK (wait 10 sec between MARKS)
 After sufficient MARKS:
 *After 5 MARKS: *
 *F 50 25 00016 TERM MARKS *

PRO

6 F 05 71 R2=10000 LMK DATA
 PRO

7 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
 Verify data
 PRO

8 F 06 49 ΔR, ΔV ORB PARA (.1nm, .1fps)
 PRO

9 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
 Rcrd for future use
 (RECYCLE) V32E to 2
 (EXIT) V34E

10 F 37 XXE
 OPT ZERO - ZERO

SM 103

Basic Date Nov. 6, 1968
 Changed Dec. 11, 1968

CSM 103

Basic Date Dec. 11, 1968
 Changed

G-27

P23 OPTICS CALIBRATION

CMC - on
 OPT ZERO - ZERO (verify)
 OPT MODE - MAN

1 F 05 70 V37E 23E (IMU NOT ALIGNED - To 3)
 STAR ID(ABCDE)/LMK ID/HOR ID
 Insure R1 DE#00 and R3#00000
 PRO

2 F 50 25 00202 MNVR/CALIB REQUEST
 ENTR

3 F 59 PERFORM OPTICS CALIB
 OPT MODE - MAN (verify)
 OPTICS COUPLING - DIRECT
 SPEED - LOW
 OPT ZERO - OFF
 SUPERIMPOSE LLOS TO SLOS
 MARK

4 F 06 87 R2 TRUNNION ANGLE BIAS (.001°)
 (repeat until 2 measurements
 agree within .003°)

(ACCEPT) PRO
 (REJECT) V32E to 3

5 F 51 V37E XXE
 OPT ZERO - ZERO

**P23 - CISLUNAR MIDCOURSE NAV MEASUREMENT
(AUTO MANEUVER FIRST)**

If alt above earth or moon <432 am, do not
mark on secondary body.

CMC - on
SCS - on
ISS - on & aligned
G/N PWR OPTICS - on (30 min prior)
OPT ZERO - ZERO (verify)
OPT MODE - CMC
RCDR - LBR/RCD/FWD (Verify)

1 F 05 70 V37E 23E
STAR ID/LMK ID/HOR ID (OCTAL)
Load codes

STAR/ENH	STAR/LNH	STAR/EL
000DE	000DE	000DE
00000	00000	00100
00110	00210	00000

STAR/EFH	STAR/LFH	STAR/LL
000DE	000DE	000DE
00000	00000	002XX
00120	00220	00000

(STAR/LMK) PRO to 2 (XX#00 to 3)
(STAR/HOR) PRO to 3

2 F 06 89 LAT, LONG/2, ALT(LMK) (.001°, .001°, .01nm)
Load lmk coords
PRO

3 F 50 25 00202 MNVR REQUEST
PRO

4 F 50 18 REQUEST MNVR TO FDAI RPY ANGLES (.01°)
(AUTO) SC CONT - CMC
CMC MODE - AUTO
PRO
(BYPASS MNVR/TRIM) - ENTR to 7
(If no cal go to 6)

Basic Date - Nov. 6, 1968
Changed - Dec. 11, 1968

Basic Date - Nov. 6, 1968
Changed - Dec. 11, 1968

5 06 18 AUTO MNVR TO FDAI RPY ANGLES (.01°)
AUTO MNVR complete return to 4
MAN MNVR - V62E
RHC - NULL ERROR NEEDLES Return to 4

6 F 59 REQUEST OPTICS CALIB
OPT MODE - CMC (verify)
OPT ZERO - OFF
ENTR (Until step 10, auto mnvr repeat -
V94E to 4)
*F 05 09 00404 (TA>90°) *
*V94E to 4 (AUTO MNVR) *
* or MAN MNVR - PRO to 7 *

7 06 92 AUTO OPTICS SHAFT, TRUN (.01°, .001°)
*PROG ALARM *
*V5N9E - 00407 (TA >50°) *
*V94E to 4 (AUTO MNVR) *
*or MAN MNVR - KEY RLSE to 7 *

MNVR TO POSITION LMK/HOR IN FOV
OPT MODE - MAN

8 F 51 REQUEST MARK
OPTICS COUPLING - RESOLVED
SPEED - LOW
SUPERIMPOSE STAR ON LMK/HOR
MARK

9 F 50 25 00016 TERMINATE MARKS
(MARK REJECT) To 8
(TERM) PRO

10 F 05 71 STAR ID/LMK ID/HOR ID (OCTAL)
Verify codes
(STAR/LMK) PRO to 11 (LMK XX#00 to 12)
(STAR/HOR) PRO to 12

11 F 06 89 LAT, LONG/2, ALT(LMK) (.001°, .001°, .01nm)
Verify coords
PRO

G-30

12 F 06 49 $\Delta R, \Delta V$ (SV Para) (.1nm, .1fps)
 Record data (R1&R2)
 Wait 30 sec
 V1 N1E
 2754E
 Record data (R1-Trun in octal)
 Wait 30 sec
 KEY RLSE
 N38E (hr,min,.01sec)
 Record MARK TIME
 KEY RLSE
 (REJECT i.e. $\Delta R, \Delta V > 0050.0$) V37E 23E to 1
 (UPDATE) PRO

13 F 37 23E to 1
 or 00E
 OPT ZERO - ZERO

Basic Date - Nov. 6, 1968
 Changed - Dec. 11, 1968

P23

G-31

P23 - CISELUNAR MIDCOURSE NAV MEASUREMENT
 (AUTO OPTICS FIRST)

If alt above earth or moon <432nm do not
 mark on secondary body.

CMC - on
 SCS - on
 ISS - on & aligned
 G/N PWR OPTICS - on (30 min prior)
 OPT ZERO - ZERO (verify)
 OPT MODE - CMC
 RCDR - LBR/RCD/FWD (Verify)

1 F 05 70 V37E 23E (OCTAL)
 STAR ID/LMK ID/HOR ID
 Load codes

STAR/ENH	STAR/LNH	STAR/EL
000DE	000DE	000DE
00000	00000	00100
00110	00210	00000
STAR/EFH	STAR/LFH	STAR/LL
000DE	000DE	000DE
00000	00000	002XX
00120	00220	00000

(STAR/LMK) PRO to 2 (XX#00 to 3)
 (STAR/HOR) PRO to 3

2 F 06 89 LAT, LONG/2, ALT (LMK) (.001°, .001°, .01nm)
 Load lmk coords
 PRO

3 F 50 25 00202 MNVR/CALIB REQUEST
 ENTR

4 F 59 REQUEST OPTICS CALIB
 OPT MODE - CMC (verify)
 OPT ZERO - OFF
 ENTR

F 05 09 00404 (TA>90°)
 *V94E to 6 (AUTO MNVR) *
 or MAN MNVR - PRO to 5

5 06 92 AUTO OPTICS SHAFT,TRUN (.01°, .001°)
 *PROC ALARM *
 *V5N9E-00407(TA>50°) *
 *V94E to 6 (AUTO MNVR) *
 *or MAN MNVR - KEY RLSE to 5 *
 V94E

6 F 50 18 REQUEST MNVR TO FDAI RPY ANGLES (.01°)
 V62E
 (AUTO) SC CONT - CMC
 CMC MODE - AUTO
 PRO
 (MAN MNVR) SC CONT - SCS
 or CMC MODE - HOLD or FREE to 6
 (For recal - PRO as desired)
 (BYPASS MNVR/TRIM) - ENTR - To 8

7 06 18 AUTO MNVR TO FDAI RPY
 AUTO MNVR complete - To 6
 or RHC - NULL ERROR NEEDLES - To 6 (.01°)

8 06 92 AUTO OPTICS SHAFT,TRUN (.01°, .001°)
 MNVR TO POSITION LMK/HOR IN FOV
 OPT MODE - MAN

9 F 51 REQUEST MARK
 (MNVR) V94E - To 6
 (MARK) OPTICS COUPLING - DIRECT
 SPEED - LOW
 SUPERIMPOSE STAR ON LMK/HOR
 MARK

10 F 50 25 00016 TERMINATE MARKS
 (MARK REJECT) To 9
 (TERM) PRO

11 F 05 71 STAR ID/LMK ID/HOR ID (OCTAL)
 Verify codes
 (STAR/LMK) PRO - To 12 (LMK XX#00 to 13)
 (STAR/HOR) PRO - To 13

12 F 06 89 LAT, LONG/2, ALT(LMK) (.001°, .001°, .01nm)
 Verify coords
 PRO

13 F 06 49 ΔR, ΔV (SV Para) (.1nm, .1fps)
 Record data (R1&R2)
 Wait 30 sec
 VIN 1E
 2754E
 Record data (R1-Trun in octal)
 Wait 30 sec
 KEY RLSE
 (REJECT i.e. ΔR, ΔV > 0050.0) V37E 23E to 1
 (UPDATE) PRO

14 F 37 23E to 1
 or 00E
 OPT ZERO - ZERO

Basic Date Nov. 6, 1968
 Changed Dec. 11, 1968

Basic Date Nov. 6, 1968
 Changed Dec. 11, 1968

P23 CISELUNAR MIDCOURSE NAV MEASUREMENT
(IMU NOT AVAIL)

If alt above earth or moon <432nm, do not
 mark on secondary body

CMC - on
 SCS - on
 G/N PWR OPTICS-in(30min prior)
 OPT ZERO - ZERO (verify)
 OPT MODE - MAN
 RCDR-LBR/RCD/FWD(verify)

1 F 59

V37E 23E
 REQUEST OPTICS CALIB
 OPTICS ZERO - OFF
 ENTR

2 F 51

SIGHTING MARK ROUTINE

- a. MNVR S/C to acquire LMK in center
 of Sct & LLOS
- b. Tel Trun - 25° (To increase star
 acquisition potential) Note:(1) Only
 shaft control available (2) LMK will
 now appear at 0° position on R line
- c. Acquire star in SCT by rotating shaft.
 Line up R line on star read trun
 angle on mech. counter.
- d. SCT MODE - Slave to SXT. Set trun to
 angle observed in SCT. This will
 roughly align SLOS and SCT on star.
 Star will also move to 0° MSCT. Now
 star (through SLOS) and landmark
 (through LLOS) should be seen
 through SXT.

Basic Date Nov. 6, 1968
 Changed Dec. 11, 1968

Basic Date Nov. 6, 1968
 Changed Dec. 11, 1968

e. Tracking procedures - Position S/C
 to put vertical lines of sextant
 recticle perpendicular to horizon
 (or centered on LMK). Use min
 impulse control. Use optics control
 (resolved and low) to place star on
 horizon (or center if LMK) and in
 middle of double lines.

MARK

3 F 50 25 R1 00016 Terminate Marks
 (MARK REJECT) To 2
 (TERM) PRO

4 05 71 STAR ID/LMK ID/HOR ID (Octal)
 Verify Codes
 (STAR/LMK) PRO To 5 (LMK XX#00 to 6)
 (STAR/HOR) PRO To 6

5 F 06 89 Lat, Long/2, Alt(LMK) (.001°, .001°, .01nm)
 Verify Coords
 PRO
 F 06 49 ΔV, ΔV (SV Para) (.1nm, .1fps)
 Record data (R1 & R2)
 Wait 30 sec
 V1 N1E
 2754E
 Record data (R1 - Trun in octal)
 Wait 30 sec
 KEY RLSE
 N38E (hr, min, .01sec)
 Record MARK TIME
 KEY RLSE
 (REJECT i.e. ΔR, ΔV > 0050.0) V37E 23E to 1
 (UPDATE) PRO

P27 CMC UPDATE

CMC - on (req)

Auto Update:

V37E 00E

1

UP TLM CM - ACCEPT

Note: UPTLM(LEB) always ACCEPT

UPLINK ACTY lt - on

* POSS LOS before completion *

* If V33 NO2 showing: *

* Key PRO *

* UPLINK ACTY lt - out *

* POO displayed *

* If V21 NO1 *

* or V21 NO2 *

* Key V34E *

* UPLINK ACTY lt - out *

* POO displayed *

* UP TLM CM - BLOCK *

Update complete:

UPLINK ACTY lt - out

V37E 00E

UP TLM CM - BLOCK

Basic Date: Nov. 6, 1960
Changed

Voice Transmission Update:

1 V37E 00E

2 V70E LIFT-OFF TIME
or V71E LOAD DATA CONSEC ADD
or V72E LOAD DATA IN NON CONSEC
or V73E LOAD CMC TIME

3 P27 Displayed

4 F 21 01 R3 UPDATE BUFFER ADD (initially 304)
R1 Data E (R3 Increments)
(If change - To 6)
Repeat Step 4 for all data

5 F 21 02 R3 330
(Verify Data) V1 N1E
R3 304E
R1 Verify Data
N15E (R3 305)
R1 Verify Data
Consecutive ENTR's display
remaining comps. Note octal
ident (01-24) of comps which
need change
KEY REL To 6

6 F 21 02 R3 330
(CHANGE) Load octal ident, XXE to 4
(ACCEPT UPDATE) PRO

7 P00 Displayed

Basic Date May 6, 1968
Changed

CSM

P30 EXTERNAL ΔV

If uplinked REFSMMAT, do P52 (PREF OPT)
before P30

1 F 06 33 V37E 30E
GETI (hrs,min,.01sec)
Load desired GETI
PRO

2 F 06 81 ΔVXYZ(LV) (.lfps)
Load desired ΔV's
PRO

3 F 06 42 HA,HP,ΔV(REQ) (.1nm,.1nm,.lfps)
PRO

4 F 16 45 M,TFI,MGA (0,min-sec,.01°)
PRO (MGA set to -00002 if
REFSMMAT Flag not set)
Set DET

5 F 37 Note: For Closest Point of Approach,
Load LOI TIG & ΔV=0,.1,0

P31 GENERAL LAMBERT PRETHRUST
TARG PARAMS - LOADED FROM GND (P27)

1 F 06 33 V37E 31E
GETI (hrs,min,.01sec)
Load desired GETI
PRO

2 F 06 81 ΔVXYZ(LV) (.lfps)
PRO

3 F 06 42 HA,HP,ΔV (REQ) (.1nm,.1nm,.lfps)
PRO

4 F 16 45 M, TFI, MGA (0,min-sec,.01°)
PRO (MGA set to -00002 if
REFSMMAT Flag not set)
Set DET

5 F 37

Basic Date May 6, 1968
Changed

CSM

P34 TPI PRETHRUST (P74 LM)

P27
1 F 06 37 V37E (34E or 74E)
TIG (TPI) (hrs,min,.01sec)
Load desired TIG
PRO

2 F 06 55 R2 ELEV ANG, R3 wt (.01°, .01°)
Load desired values
+00000 in R2 to CALC ELEV
ANGLE AT TIG TIME)
PRO

P30-39
3 F 16 45 MARKS,TFI,-00001 (min-sec)
(RECYCLE) V32E
(FINAL PASS) PRO (Term Marking)

F 05 09 (00611 NO SOL)
*PRO To 1 *

4 F 06 37 TIG (TPI) (hrs,min,.01sec)
(IF ELEV ANGLE COMPUTED BY CMC
THIS DISPLAY WILL BE REPLACED
BY F 06 55 AS IN 2 ABOVE)
PRO

P22
5 F 06 58 HP,ΔV(TPI,.ΔV(TPI)) (.1nm,.1fps,.1fps)
PRO (If Recycle - To 7)
(If Final - To 6)

P23

6 F 06 81 ΔVXYZ(LV)TPI (.1fps)
(For Out-Of-Plane Corr in final Comp only)
Key V90E
F 06 16 GET EVENT (hrs,min,.01sec)
PRO
F 06 90 Y,YDOT,PSI (.01nm,.1fps,.01°)
RECORD YDOT _____
PRO
INSERT-YDOT in R2 of ΔV TPI
* LOAD OF NEW DATA INTERRUPTED *
* BY F06 49, F50 18 OR RESTART *
* HANDLE INTERRUPTION *
* RELOAD DATA WHEN *
* N81 REAPPEARS *

PRO

7 F 06 59 ΔVXYZ(LOS)TPI (.1fps)
PRO (If Recycle - To 3)

8 F 16 45 MARKS,TFI,MGA (marks,min-sec,.01°)
PRO (MGA SET To -00002 IF NO
REFSMAT SET or If P74)

9 F 37
P74 - Transmit Mnv Parameters To LM

P40,41,47

Basic Date Nov. 6, 1967
Changed

103

P35 TPM PRETHRUST (P75 LM)

1 V37E (35E or 75E)
 F 16 45 MARK,TFI,-00001 (marks,min-sec)
 (RECYCLE) V32E To 3
 (FINAL PASS) PRO (Terminate Marking)

2 F 06 81 ΔVXYZ(LV)TPM (.lfps)
 (For Out-of-Plane Corr
 V90E
 F 06 16 GET EVENT (hrs,min,.01sec)
 PRO
 F 06 90 Y,YDOT,PSI (.01um,.lfps,.01°)
 RECORD YDOT _____
 PRO
 ZERO Out-of-Plane Corr (R2) on First TPM)
 * LOAD OF NEW DATA INTERRUPTED *
 * BY F06 49, F50 18 OR RESTART *
 * HANDLE INTERRUPTION *
 * RELOAD DATA WHEN *
 * N81 REAPPEARS *
 PRO

3 F 06 59 ΔVXYZ(LOS)TPM (.lfps)
 PRO (If Recycle - To 1)

4 F 16 45 MARKS,TFI MGA (marks,min-sec,.01°)
 PRO (MGA SET TO -00002 IF NO
 REFSMMAT SET or If P75)

5 F 37
 P75 - Transmit Mnvr Parameters To LM

Basic Date ~~Nov. 6, 1968~~

Changed

C1103

P37 RETURN TO EARTH PROGRAM

1 V37E 37E
 F 06 33 TIG (hrs,min,.01sec)
 Load desired TIG
 PRO

2 F 06 60 BLANK,V PRED,GAMMA EI (lfps,.01°)
 Load desired values
 For Min ΔV: Load +00000 in R2
 For Mid-corridor: Load +00000 in R3
 PRO
 *F 05 09 00605-Solution Not *
 * Convergent *
 * 00612-State Vector in *
 * Lunar Influence *
 * *
 * *
 *V32E,RSET To 1 *

3 F 06 61 IMPACT LAT, IMPACT LONG (.01°)
 (RECYCLE) V32E To 1
 PRO

4 F 06 39 ΔT TRANSFER (hrs,min,.01sec)
 (RECYCLE) V32E To 1
 PRO

5 F 06 60 BLANK, V400K, GAMMA EI (fps,.01°)
 (RECYCLE) V32E To 1
 PRO

6 F 06 81 ΔVXYZ(LV) TIG (.lfps)
 PRO (To 3 on first pass)
 *F 05 09 00605 Solution Not *
 * Convergent *
 * 00613 Flt Path Angle*
 * Not Reached *
 * RSET *
 * V32E To 1 *

P27

P30-39

P22

P23

P40,41,47

7 F 04 06 THRUST OPTION (Do not key V82 during this display)
 R1 00007
 R2 0000X
 X=1 (SPS)
 2 (RCS)
 PRO

8 F 06 33 TIG (hrs,min,.01sec)
 PRO

9 F 16 45 MARK,TFI MGA (mark,min-sec,.01°)
 PRO (MGA SET TO -00002 If No
 REFSMMAT SET)

10 F 37 (40E or 41E)

Basic Date - Nov. 6, 1968
 Changed

CS 003

P38 SOR TARGETING (P78 LM)

If P20 in background, do not start
 rend mark routine (V57,V54) until
 step 4

1 F 06 33 V37E (38E or 78E)
 TIG (SOR) (hrs,min,.01sec)
 Load desired TIG
 PRO

2 F 06 55 R3 wt (.01°)
 Load desired wt
 PRO

3 F 04 06 R1 00005 Specify Phase Option
 (Do not key V82 during this display)
 R2 0000X X=1 or 2
 PRO (To 6 If R2=2)

4 F 06 57 ΔR SOR (.1nm)
 Load desired ΔR
 PRO

5 F 06 34 SOR TIME (hrs,min,.01sec)
 PRO

6 F 16 45 MARK,TFI,-00001 (mark,min-sec,.01°)
 (RECYCLE) V32E
 (FINAL PASS) PRO (Terminate Marks)

7 F 06 58 HP(SOR),ΔV(SOR),ΔV(SOR-FINAL)
 PRO (.1nm,.1fps,.1fps)

8 F 06 81 ΔVXYZ(LV) (.1fps)
 PRO (If Recycle - To 6)

9 F 16 45 MARKS,TFI MGA (marks,min-sec,.01°)
 PRO (MGA SET TO -00002 IF NO
 REFSMMAT SET OR P78)

10 F 37

Transmit Mnv Parameters To LM

P39 STABLE ORBIT MID (P79 LM)

- 1 V37E (39E or 79E)
- 2 F 16 45 MARK,TFI,-00001 (mark,min-sec,.01°)
(RECYCLE) V32E
(FINAL PASS) PRO (Terminate Marks)
- 3 F 06 81 ΔVXYZ(LV) (.1fps)
PRO (If Recycle - To 2)
- 4 F 16 45 MARK,TFI,MGA (mark,min-sec,.01°)
PRO (MGA SET TO -00002
IF NO REFSMAT SET or P79)
- 5 F 37

Transmit Mnv Parameters To LM

P27

P30-39

P22

P23

CS 103

Basic Date: Nov. 6, 1968
ChangedBasic Date: Nov. 6, 1968
ChangedSPS THRUSTING (P40)

P30 or P37 Complete
CMC - on
ISS - on
SCS - OPERATING
TEST C/W LAMPS
EMS MODE - STBY
EMS FUNC - ΔV SET
SET ΔV ind To 1586.8 fps
EMS MODE - AUTO
EMS FUNC - ΔV TEST
SPS THRUST LIT - on/off (10 sec)
ΔV ind. stops at -20.8 ± 20.7
EMS MODE - STBY
EMS FUNC - ΔV SET
SET ΔVC
EMS FUNC - ΔV
NONESS BUS - MNB

Cycle CRYO Fans

BMAG MODE (3) - RATE 2
ΔVCG - CSM
CMC MODE - FREE
AUTO RCS SELECT (16) - As req'd for ullage

LOAD DAP
ROT CONTR PWR NORM (both) - AC/DC
DET SET

V37E 00E
SC CONT - CMC
CMC MODE - AUTO

P40,41,47

MNVR TO PAD BURN ATT
V62E

V49E

F 06 22 DESIRED FINAL GMBL ANGLES (.01°)
LOAD MNVR PAD GMBL ANGLES
PRO

F 50 18 REQ MNVR TO FDAI RPY ANGLES (.01°)
(AUTO) PRO
(MAN) SC CONT - SCS
MNVR to 6

06 18 AUTO MNVR TO FDAI RPY ANGLES (.01°)

F 50 18 REQ TRIM TO FDAI RPY ANGLES (.01°)
(AUTO TRIM) PRO to 5
(BYPASS) ENTR

BORESIGHT & SXT STAR CHECK

OPT MODE - CMC
OPT ZERO - OFF

V41 N91E

F 21 92 SHAFT, TRUN (.01°,.001°)
LOAD SXTS angles

41 OPTICS DRIVE

CHECK SXT STAR

Drive Trunnion to <5°
OPT ZERO - ZERO
G/N PWR OPTICS - OFF

CHECK BORESIGHT STAR (If avail)

11 V37E 40E

12 F 50 18 REQUEST MNVR TO FDAI RPY ANGLES (.01°)
(AUTO) BMAG MODE (3) - RATE 2
SC CONT - CMC
CMC MODE - AUTO

PRO to 13

(MAN/DAP) BMAG MODE (3) - RATE 2
SC CONT - CMC
CMC MODE - HOLD

MNVR to 14

(MAN/SCS) SC CONT - SCS
MNVR to 14

13 06 18 AUTO MNVR TO FDAI RPY ANGLES (.01°)

14 F 50 18 REQUEST TRIM MNVR TO FDAI RPY ANGLES
ALIGN S/C ROLL (.01°)
GDC ALIGN

TVC CHECK & PREP

STAB CONT SYS cb (Pnl 8) - close

SPS cb (12) - close

DEADBAND - MIN

RATE - LOW

LIMIT CYCLE - ON

MAN ATT (3) - RATE CMD

BMAG MODE (3) - ATT1/RATE 2

ROT CONTR PWR DIRECT (both) - OFF

SCS TVC (2) - RATE CMD

If SCS, SCS TVC (2) - AUTO

* SC CONT - SCS *

TVC GMBL DRIVE P&Y - AUTO

MN BUS TIES (both) - ON

TVC SERVO PWR 1 - AC1/MNA

2 - AC2/MNB

TRANS CONTR PWR - ON

ROT CONTR PWR NORMAL 2 - AC

RHC #2 - ARMED

+54:00m
(-06:00)

Basic Date: Nov. 6, 1968
Changed: Dec. 13, 1968

Basic Date: Nov. 6, 1968
Changed: Dec. 6, 1968

CS/103

M 103

55:00m
(-05:00)PRIMARY TVC CHECK

GMBL MOT P1-Y1-START/ON(LMP confirm)
 If SCS, verify Thumbwheel Trim
 THC - CW
 Verify NO MTVC

SEC TVC CHECK

GMBL MOT P2-Y2-START/ON (LMP confirm)
 SET GPI TRIM
 Verify MTVC
 THC NEUTRAL
 GPI returns to 0,0(CMC) or trim (SCS)
 ROT CONT PWR NORM 2 - AC/DC

(TRIM) Go to step 12
 (BYPASS) BMAG MODE (3) - ATT1/RATE 2 (verify)
 ENTR

15 F 50 25 00204 GMBL TEST OPTION
 (ACCEPT) SC CONT - CMC (verify)
 PRO

Monitor GPI Response:
 00,20,-20,00,02,0-2,00,Trim
 *TEST FAIL: *
 *SC CONT - SCS *
 SCS TVC (2) - AUTO

(REJECT) ENTR

16 06 40 TFI, VG, ΔVM (min-sec,.lfps)
 PROG ALM - TIG Slipped
 *V5N9E 01703 *
 *KEY RLSE To 16 *
 ROT CONTR PWR DIRECT (both) - MNA/B
 SPS He VLVS (both) - AUTO (verify)
 LIMIT CYCLE - OFF
 FDAI SCALE - 50/15
 SPS P2,Y2 cb - open (for crit. burn)

58:00
(-02:00)

ΔV THRUST A(B) - NORMAL
 THC - ARMED
 RHC (both) - ARMED
 TAPE RCDR - RECORD/STOP/HBR/FWD

59:25
(-00:35)

DSKY BLANKS

59:30
(-00:30)

(AVE G ON)
 FLT RCDR - RECORD
 EMS MODE - AUTO

06 40 TFI, VG, ΔVM (min-sec,.lfps)
 CHECK PIPA BIAS < 2fps for 5 sec

59:XX
(-00:XX)

ULLAGE AS REQ

*IF NO ULLAGE
 DIR ULLAGE PB - PUSH
 *CONTROL ATT W/RHC *

MONITOR ΔVM (R3) COUNTING UP

Basic Date: Nov. 6, 1968
 Changed: Dec. 15, 1968

M 103

P27

P30-39

P40.41.47

P23

LOT MODE 1 ABORT

59:55
(-00:05)

F 99 40 ENG ON ENABLE REQUEST *Don't use V34*
(AUTO IGN) PRO AT TFI >0 Sec
(BYPASS IGN) ENTR To 19
~~V34E~~ - EXIT *V37E OOE*

17 00:00 IGN * IF SCS - THRUST PB - PUSH *

06 40 TFC, VG, ΔVM (min-sec, .lfps, .lfps)
* F 97 40 SPS Thrust fail *
* ~~(TERM) V34E EXIT~~ *
* (RESTART) PRO to IGN *
* (RECYCLE ENTR to TIG-05 sec) *

SPS THRUST LITE - ON
MONITOR THRUSTING *ΔV THRUST (A) - NORMAL*

Pc 95-105 psia
EMS COUNTING DOWN
SPS INJ VLVS (4) - OPEN
SPS He VLVS tb - gray
SPS FUEL/OXID PRESS - 175-195 psia
PUGS - BALANCED
* PROG ALARM *
* V5 N9E 01407 VG INC *
* LOI & TEI *
* THC-CW, FLY MTVC *
* LOI₂ & MCC *
* ΔV THRUST A/B-OFF *

00:XX ECO

* EMER SPS CUTOFF: *
* ΔV THRUST A/B-OFF *
* LOI - BT +6 sec *
* LOI₂ - BT +1 sec *
* TEI - BT +2 sec & *
* ΔV CTR <-40 fps *

18 F 16 40 TFC(STATIC), VG, ΔVM (min-sec, .lfps)
ΔV THRUST A/B - OFF
VERIFY THRUST OFF
SPS INJ VLVS (4) - CLOSED
SPS He TB (2) - BP

Basic Date: Nov. 6, 1968
Dec. 4, 1968
Changed

103

Basic Date: Nov. 6, 1968
Dec. 13, 1968
Changed

CSI 103

SPS P2, Y2 cb - closed
GMBL MOTS (4) - OFF (LMP Confirm)
TVC SERVO PWR 1&2 - OFF
FLT RCDR - OFF
MN BUS TIES (both) - OFF

19 F 16 85 PRO VG XYZ(CM) (.lfps)

NULL RESIDUALS (TEI & MCC)
RECORD ΔV CTR & RESIDUALS
EMS FUNC - OFF
EMS MODE - STBY
BMAG MODE (3) - RATE 2
DEADBAND - MAX
TAPE RCDR - STOP
NONESS BUS - OFF
TRANS CONT PWR - OFF
ROT CONTR PWR DIRECT - OFF
SPS P1&2, Y1&2 cb - open

20 F 37 PRO V82E

21 F 16 44 HA, HP, TFF (.1nm, min-sec)
R3-59B59 HP >49.4 nm/35K ft

22 F 37 PRO OOE

23 V66E

BURN STATUS REPORT

_____	ΔTIG	_____	VI
_____	BT	_____	HDOT
_____	VGX	_____	H
_____	R	_____	ΔVC
_____	P	_____	FUEL
_____	Y	_____	OXID
		_____	UNBAL

REMARKS

P27

P30-39

D/AO 41 47

...

LOI MODE 1 ABORT

P51-56

RCS THRUSTING (P41)

P30 or P37 Complete

CMC - on

ISS - on

SCS - OPERATING

TEST C/W LAMPS

EMS MODE - STBY

EMS FUNC - ΔV SET

SET ΔV ind to 1586.8 fps

EMS MODE - AUTO

EMS FUNC - ΔV TEST

SPS THRUST Lt - on/off

ΔV ind stops at -20.8 ± 20.7 (10 sec)

SET ΔVC

EMS FUNC - ΔV

BMAG MODE (3) - RATE 2

CMC MODE - FREE

AUTO RCS SELECT (16) - As Req'd

LOAD DAP

ROT CONTR PWR NORMAL (both) - AC/DC

DIRECT (both) - MNA/B

DET SET

V37E OOE

SC CONT - CMC

CMC MODE - AUTO

MNVR TO PAD BURN ATTITUDE

V62E

V49E

3 F 06 22 DESIRED FINAL GMBL ANGLES (.01°)

LOAD MNVR PAD GMBL ANGLES

PRO

4 F 50 18 REQ MNVR TO FDAI RPY ANGLES (.01°)

(AUTO) PRO

(MAN) SC CONT - SCS

MNVR To 6

5 06 18 AUTO MNVR To FDAI RPY ANGLES (.01°)

6 F 50 18 REQ TRIM To FDAI RPY ANGLES (.01°)

(AUTO TRIM) PRO To 5

(BYPASS) ENTR

7 BORESIGHT & SXT STAR CHECK

OPT MODE - CMC

OPT ZERO - OFF

8 V41 N91E

9 F 21 92 SHAFT, TRUN (.01°, .001°)

LOAD SXTS angles

10 41 OPTICS DRIVE

CHECK SXT STAR

Drive Trunnion to <5°

OPT ZERO - ZERO

CHECK BORESIGHT STAR (if avail)

11 V37E 41E

12 F 50 18 REQUEST MNVR TO FDAI RPY ANGLES (.01°)

(AUTO) BMAG MODE (3) - RATE 2

SC CONT - CMC

CMC MODE - AUTO

PRO To 13

(MAN/DAP) BMAG MODE (3) - RATE 2

SC CONT - CMC

CMC MODE - HOLD

MNVR To 14

(MAN/SCS) SC CONT - SCS

MNVR To 14

13 06 18 AUTO MNVR TO FDAI RPY ANGLES (.01°)

Basic Date - Nov. 6, 1968
Changed - Dec. 13, 1968Basic Date - Nov. 6, 1968
Changed - Dec. 4, 1968

CSM 103

CSM 103

14 F 50 18 REQUEST MNVR TO FDAI RPY ANGLES (.01°)
 (AUTO TRIM) BMAG MODE (3) - RATE 2
 ALIGN SC ROLL
 SC CONT - CMC
 CMC MODE - AUTO

PRO To 13
 (BYPASS) DEADBAND - MIN
 RATE - LOW
 MAN ATT (3) - RATE CMD
 BMAG MODE (3) - ATT1/RATE 2
 GDC ALIGN

ENTR

15 06 85 VG X,Y,Z (.1fps)

* PROG Alarm lt *
 * V5N9E - 01703 - TIG SLIPPED *
 * KEY RLSE To 15 *

55:00
 (-05:00)

TRANS CONT PWR - on (up)
 HAND CONTROLLERS - ARMED

59:25
 (-00:35)

DSKY BLANKS

59:30
 (-00:30)
 16 16 85

V X,Y,Z (AVE G ON)
 TAPE RCDR - CMD RSET/HBR/RECORD/FWD
 LIMIT CYCLE - OFF
 EMS MODE - AUTO

00:00
 17 F 16 85

VG X,Y,Z (.1fps)
 NULL COMPONENTS
 RECORD ΔV COUNTER & RESIDUALS
 TAPE RCDR - STOP
 HAND CONTROLLERS - LOCKED
 EMS FUNC - OFF
 EMS MODE - STBY
 TRANS CONT PWR - OFF
 BMAG MODE (3) - RATE 2

PRO

18 F 37

V82E

19 F 16 44

HA,HP,TFF (.1nm,min-sec)

* R3-59B59 HP>49.4 nm/35K ft *

PRO

20 F 37

00E

21

V66E

BURN STATUS REPORT

_____	ΔTIG	_____	VI
_____	BT	_____	HDOT
_____	VGX	_____	H
_____	R	_____	ΔVC
_____	P	_____	FUEL
_____	Y	_____	OXID
		_____	UNBAL

REMARKS

SM 103
 Basic Date: Nov. 6, 1968
 Changed: Dec. 4, 1968

CSM 103
 Basic Date: Nov. 6, 1968
 Changed: Dec. 13, 1968

P47 Thrust Monitor Program

CMC - on
ISS - on & aligned
G/N PWR OPTICS - OFF

V37E 47E

F 16 83

ΔV XYZ(CSM)

(.1fps)

- * VI, HDOT, H available by N62E *
- * KEY RLSE to return to N83 *
- * In lunar orbit, add 2500nm to H*

(RECYCLE)
(TERM)

V32E
PRO

2 F 37

XXE

Basic Date Nov. 6, 1968
Changed Dec. 13, 1968

Basic Date Nov. 6, 1968
Changed Dec. 15, 1968

M 103

LOI MODE I ABORT

ABORT - Stop Clock
 ΔV Thrust A/B - OFF
 Verify Thrust Off
 SPS INJ VLVS(4) -CLOSED
 SPS He tb(2)-bp
 GMBL MOTS(4)-OFF (LMP Verify)
 TVC SERVO PWR 1&2 - OFF
 FLT RCDR - OFF
 TAPE RCDR - STOP/LBR/FWD
 SC CONT-SCS

RECORD DATA AND COMPUTE PAD

F 97 40

Record TFC 59 59

Vg _____

Vm _____

EMS Vc _____

ENTR

F 99 40

Maneuver to LOI₁ Attitude

ENTR

F 16 85

Record Vx _____

Vy _____

Vz _____

PRO

F37 V82E

F 16 44

Record H_A _____

H_p _____

TFF _____

PRO

F 37 00E

V66E

PRIMARY

G&N ΔV_m _____

VcABORT(Chart) _____

GET LOI₁ _____

Bt Watch + _____

+15:00

GET TEI ABORT : : _____

Bt ABORT _____

from Nomigram for Vc

ABORT P&Y TRIM(Chart)

ALTERNATE

ΔV_{cLOI_1} PAD _____

EMS Vc(Shutdown) _____

Vc(Burned) _____

Vc ABORT(Chart) _____

SCS

LOI MODE I ABORT

P11-5

007

P30-30

P40 41 47

P77

MAN ATT PITCH - ACCEL CMD
 SET In GDC THUMBWHEELS - (177.9,27.9,1.6)
 MAN MNVR To ABORT R,P,Y
 GDC ALIGN
 CHECK DAP (P&Y TRIM)
 EMS FUNC - ΔV SET
 SET ΔV_c ABORT

TVC CHECK & PREP
 STAB CONT SYS cb (Pnl 8)-Close
 SPS cb (12) - close
 Verify Rate - LOW
 Limit Cycle - ON
 MAN ATT(3)-RATE CMD
 BMAG MODE(3)-ATT1/RATE2
 ROT CONTR PWR DIR(2)-OFF
 SCS TVC(2)-AUTO
 TVC GMBL DRIVE P&Y-AUTO
 VERIFY MN BUS TIES(2)-ON
 TVC SERVO PWR 1 - AC1/MNA
 TVC SERVO PWR 2 - AC2/MNB
 TRANS CONTR PWR - ON
 ROT CONTR PWR NORMAL #2-AC
 RHC #2-ARMED

PRIMARY TVC CHECK
 GMBL MOT P1-Y1-START/ON(LMP Verify)
 THC-CW
 VERIFY NO MTVC

SEC TVC CHECK
 GMBL MOT P2-Y2-START/ON(LMP Verify)
 SPS P2-Y2 cb's - open
 SET GPI TRIM
 Verify MTVC
 THC NEUTRAL
 Verify GPI Returns To Trim POS
 ROT CONTR PWR NORM 2 - AC/DC
 Verify DEADBAND - MIN
 ROT CONTR PWR DIR(2) - MNA/B

Basic Date Nov. 6, 1968
 Changed Dec. 15, 1968

Basic Date Nov. 6, 1968
 Changed Dec. 15, 1968

-2m

-10s
00

SPS HE VLVS(2)-AUTO,Verify tb-bp
 LIMIT CYCLE - OFF
 Verify FDAI SCALE - 50/15
 EMS MODE - AUTO
 V37E 47E
 ΔV THRUST A&B - NORMAL
 Verify THC - ARMED
 RHC (Both) - ARMED
 TAPE RCDR - STOP/HBR/FWD
 FLT RCDR - RECORD
 ULLAGE
 THRUST PB-PUSH
 SPS THRUST LITE-ON
 MONITOR THRUSTING
 Pc 95-105 psia
 EMS COUNTING DOWN
 SPS INJ VLVS(4)-OPEN
 SPS HE VLVS tb-GRAY
 SPS FUEL/OXID PRESS - 175 to 195 psi
 ECO
 ΔV THRUST A/B - OFF
 VERIFY THRUST OFF
 SPS INJ VLVS(4)-CLOSED
 SPS He tb(2) - bp
 SPS P2-Y2 cb's - close
 GMBL MOTS(4)-OFF (LMP Verify)
 TVC SERVO PWR 1&2 - OFF
 TAPE RCDR - OFF/LBR/FWD
 FLT RCDR - OFF
 NONESS BUS - OFF
 BMAG MODE(3) - RATE 2
 F 16 83
 RECORD Vx _____
 Vy _____
 Vz _____
 PRO
 F37 00E
 V66E
 EMS ΔV_c _____

P51 - IMU ORIENTATION

CMC - on
 ISS - on
 SCS - operating
 BMAG MODE (3) - RATE 2
 G/N PWR OPTICS - on (verify)
 OPT ZERO - ZERO (verify)
 OPT MODE - MAN

- 1 F 50 25 V37E 51E
 00015 MNVR TO ACQ STARS
 (Coarse Align IMU To 0,0,0) - ENTR to 2
 (BYPASS) PRO to 3
- 2 41 22 DESIRED GIMBAL ANGLES (0,0,0)
 NO ATT Lt - on then off, to 1
- 3 F 51 PLEASE MARK
 OPT ZERO - OFF
 MARK
- 4 F 50 25 00016 TERMINATE MARKS
 PRO
- 5 F 01 71 000DE STAR CODE
 Load desired code
 PRO to 3 after 1st MARK (to 6 if DE=00)
 to 7 after 2nd MARK (to 6 if DE=00)
- 6 F 06 88 CELESTIAL BODY VECTOR
 Load desired vector
 PRO to 3 after 1st MARK
 to 7 after 2nd MARK
- 7 F 06 05 STAR ANGLE DIFFERENCE (.01°)
 (RECYCLE) V32E to 1
 (ACCEPT) PRO
- 8 F 37 52E Bypass ZERO OPTICS
 or XXE
 OPT ZERO - ZERO

Basic Data Nov. 6, 1968
 Changed Dec. 13, 1968

CS-103

LOI MODE 1 ABORT

DAN 11 17

P77

D77

P51-54

No Cam

SCS

P52 IMU REALIGN

Note: Do not key V82 during step 1 or 2

CMC - on
 ISS - on
 SCS - operating
 BMAG MODE (3) - RATE 2
 G/N PWR OPTICS - on (verify)
 CMC MODE - FREE
 OPT ZERO - ZERO (verify)
 OPT MODE - CMC

1 F 04 06 V37E 52E
 R1 00001 IMU ALIGN OPTION
 R2 00001 PREF PRO to 4
 2 NOM PRO to 2
 3 REFSMMAT PRO to 5
 4 LDG SITE PRO to 2

2 F 06 34 GET ALIGN (0,0,0 initially) (hr,min,sec)
 Load desired GET
 TO SPECIFY PRESENT TIME - PRO on (0,0,0)
 PRO (NOM go to 4)

3 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
 Load ldg site coords
 PRO

4 F 06 22 NEW ICDU ANGLES OG, IG, MG (.01°)
 (IF MG>70°, MNVR) V32E - to 4
 PRO NO ATT Lt - on then off

5 F 50 25 00015 STAR SELECT
 (MNVR If Necessary)
 (PICAPAR) PRO
 *F 05 09 00405 NO PAIR *
 (CREW SPECIFY) PRO - to 6
 *(PICAPAR) V32E to 5 *
 (MAN ACQ) ENTR

Basic Date Nov. 6, 1968
 Changed

Basic Date Nov. 6, 1968
 Changed

6 F 01 70 000DE STAR CODE
 Load desired code
 OPT MODE - CMC (verify)
 OPT ZERO - OFF
 PRO to 8 (to 7 if DE=00)
 F 05 09 00404 (TA>90°)
 *MNVR - PRO To 8 *

7 F 06 88 CELESTIAL BODY VECTOR
 Load desired vector
 PRO
 F 05 09 00404 (TA>90°)
 *MNVR - PRO To 8 *

8 06 92 SHAFT, TRUN (.01°, .001°)
 PROG ALARM (TA>50°)
 *V5N9E 00407 *
 *KEY RLSE *
 *MNVR till R2<50000 *
 (MARK ROUTINE) OPTICS MODE - MAN

9 F 51 PLEASE MARK
 MARK

10 F 50 25 00016 TERMINATE MARKS
 PRO

11 F 01 71 000DE STAR CODE
 Load code (if necessary)
 PRO to 6 after 1st MARK (to 12 if DE=00)
 to 13 after 2nd MARK (to 12 if DE=00)

12 F 06 88 CELESTIAL BODY VECTOR
 Load vector
 PRO to 6 after 1st MARK
 to 13 after 2nd MARK

C 103

No Cam

13 F 06 05 STAR ANGLE DIFFERENCE (.01°)
 If restart and 06 05 reappears
 *with changed R1:
 *V32E to 15
 *PRO to repeat sightings
 (REJECT) V32E to 15
 (ACCEPT) PRO

14 F 06 93 TORQUING ANGLES OG, IG, MG (.001°)
 (TORQUE) PRO (CMC - FREE)
 (BYPASS) V32E

15 F 50 25 00014 ALIGNMENT CHECK
 (RECHECK) PRO To 5
 (BYPASS) ENTR

16 F 37
 OPT ZERO - ZERO
 XXE

Basic Date Nov. 6, 1968
 Changed Dec. 13, 1968

Basic Date Nov. 6, 1968
 Changed Dec. 13, 1968

P53 - BACKUP IMU ORIENT DETERMINATION

CMC - on
 ISS - on
 SCS - operating
 MAN ATT (3) - MIN IMP
 COAS LOS DETERMINATION - Complete pg
 G-74

1 F 50 25 V37E 53E
 00015 MNVR To ACQ STARS
 (BYPASS) Coarse Align IMU to 0,0,0 - ENTR to 2
 PRO to 3

2 41 22 DESIRED GIMBAL ANGLES (0,0,0)
 NO ATT Lt - on then off, to 1

3 F 06 94 ALT LOS OPT ANGS SHAFT, TRUN (.01°, .001°)
 Load proper angles
 PRO

4 F 53 PLEASE MARK
 Center Target
 ENTR

5 F 50 25 00016 TERMINATE MARKS
 (REJECT) ENTR to 4
 PRO

6 F 01 71 000DE STAR CODE
 Load desired code
 PRO to 3 after 1st MARK (to 7 if DE=00)
 to 8 after 2nd MARK (to 7 if DE=00)

7 F 06 88 CELESTIAL BODY VECTOR
 Load desired vector
 PRO to 3 after 1st MARK
 to 8 after 2nd MARK

8 F 06 05 STAR ANGLE DIFFERENCE (.01°)
 (RECYCLE) V32E to 1
 (ACCEPT) PRO

9 F 37 XXE

C 103

C 103

P54 - BACKUP IMU REALIGN

Note: Do not key V82 during step 1 or 2

CMC - on

ISS - on

SCS - operating

MAN ATT (3) - MIN IMP

COAS LOS DETERMINATION - complete pg

G-74

- 1 F 04 06 V37E 54E
R1 00001 IMU ALIGN OPTION
R2 00001 PREF PRO to 4
2 NOM PRO to 2
3 REFSMMAT PRO to 5
4 LDG SITE PRO to 2
- 2 F 06 34 GET ALIGN (0,0,0 initially)(hr,min,sec)
Load desired GET
TO SPECIFY PRESENT TIME - PRO on (0,0,0)
PRO (NOM go to 4)
- 3 F 06 89 LAT, LONG/2, ALT (.001°, .001°, .01nm)
Load ldg site coords
PRO
- 4 F 06 22 NEW ICDU ANGLES OG, IG, MG (.01°)
(IF MG > 70°, MNVR) V32E to 4
PRO - NO ATT Lt - on then off
- 5 F 50 25 00015 STAR SELECT
(Mnvr If Necessary)
(PICAPAR) PRO
*F 05 09 00405 NO PAIR *
(CREW SPECIFY) PRO to 6
*(PICAPAR) V32E to 5 *
(MAN ACQ) ENTR
- 6 F 01 70 000DE STAR CODE
Load desired code
PRO to 8 (to 7 if DE=00)

- 7 F 06 88 CELESTIAL BODY VECTOR
Load desired vector
PRO
- 8 F 06 94 ALT LOS OPT ANGS SHAFT, TRUN(.01°, .001°)
Load angles
PRO
- 9 F 53 PLEASE MARK
Center Target
ENTR
- 10 F 50 25 00016 TERMINATE MARKS
(REJECT) ENTR to 9
PRO
- 11 F 01 71 000DE STAR CODE
Load code (if necessary)
PRO to 6 after 1st MARK (to 12 if DE=00)
to 13 after 2nd MARK (to 12 if DE=00)
- 12 F 06 88 CELESTIAL BODY VECTOR
Load vector
PRO to 6 after 1st MARK
to 13 after 2nd MARK
- 13 F 06 05 STAR ANGLE DIFFERENCE (.01°)
If restart and 06 05 reappears
*with changed R1: *
*V32E To 15 *
*PRO to repeat sightings *
(REJECT) V32E to 15
(ACCEPT) PRO
- 14 F 06 93 TORQUING ANGLES OG, IG, MG (.001°)
(TORQUE) PRO (CMC - FREE)
(BYPASS) V32E
- 15 F 50 25 00014 ALIGNMENT CHECK
(RECHECK) PRO to 5
(BYPASS) ENTR
- 16 F 37 XXE

Basic Date: Nov. 6, 1968

Changed

Basic Date: Nov. 6, 1968

Changed

CS 103

CS 103

P76 - TARGET ΔV

1 F 06 84 V37E 76E
 ΔV XYZ (.1fps)
 Load ΔV
 PRO

2 F 06 33 TIG (hrs,min,.01sec)
 Load TIG
 PRO

3 F 37

V41 N91 COARSE ALIGN OCDU's

CMC - on
 ISS - on
 G/N PWR OPTICS - on
 OPT MODE - CMC
 OPT ZERO - OFF

1 V41N 91E

2 F 21 92 SHAFT, TRUN NEW OCDU (.01°, .001°)
 Load desired shaft and trun

3 41 OPTICS DRIVE TO SPECIFIED ANGLES

V41 N20 COARSE ALIGN ICPU's

CMC - on
 ISS - on

V41N 20E

2 F 21 22 NEW ICPU ANGLES RPY (.01°)
 Load desired ICPU angles

3 41 NO ATT Lt - on
 *POSS PROG ALARM *
 V5 N9 211 Coarse align error
 *Repeat V41 N20 *

4 V40 N20E
 NO ATT Lt - off
 Wait 20 sec

5 V37E XXE

V42 GYRO TORQUING
 CMC MODE - FREE

1 F 21 93 V42E
 LOAD DELTA GYRO ANGLES (XYZ) (.001°)
 (In flight - 90° max)

2 42 NO ATT Lt - off
 Monitor Gyro Torquing on FDAI

Basic Date Nov. 6, 1968
 Changed Dec. 13, 1968

CSM 103

Basic Date Nov. 6, 1968
 Changed Dec. 13, 1968

CSM 103

No Cam

SCS

V48 - DAP ACTIVATION
CMC MODE - FREE

1 F 04 46 V48E
R1 ABCDE
R2 ABCDE
INSURE Left Digit of R1 is:
0-NO DAP
1-CSM
2-CSM/LM
3-SATURN DAP
6-CSM/LM ASC
PRO
PRO
PRO To Prog in progress
V46E

V48 - DAP DATA LOAD PROCEDURE

1 F 04 46 V48E
R1 ABCDE
R2 ABCDE

Vehicle Config	Quad A/C for \bar{x}	Quad B/D for \bar{x}	Err Deadband	Rate Select
R1 0 = No Dop 1 = CSM 2 = CSM & LM 3 = CSM & SIVB 4 = CSM & LM (Recent Eng only)	0 = Fail A/C 1 = Use A/C	0 = Fail B/D 1 = Use B/D	0 = $\pm 0.5^\circ$ 1 = $\pm 0.0^\circ$	0 = 000°/sec 1 = 03°/sec 2 = 08°/sec 3 = 40°/sec
Ball Quad Select	Quad A	Quad B	Quad C	Quad D
R2 0 = Use B/D 1 = Use A/C	0 = Fail 1 = Use	0 = Fail 1 = Use	0 = Fail 1 = Use	0 = Fail 1 = Use

PRO

2 F 06 47 CSM WT, LM WT (lbs,lbs)
Load correct values
PRO

3 F 06 48 TRIM ENGINE GMBL (.01°)
Load correct values
PRO

Basic Date: Nov. 6, 1968
Changed: Dec. 13, 1968

CSM 103

V49 CREW DEFINED MANEUVER

CMC - on
ISS - on
SCS - operating

1 V37E 00E
V62E

2 V49E
OPR ERR Lt - on
RSET
F 06 22 NEW ICDU ANGLES RPY (.01°)
Load desired angles
PRO

3 F 50 18 REQ MNVR TO FDAI RPY ANGLES (.01°)
(AUTO) BMAG MODE (3) - RATE 2
SC CONT - CMC
CMC MODE - AUTO
PRO
(MAN) MNVR - To 5

4 06 18 AUTO MNVR TO FDAI RPY ANGLES (.01°)

5 F 50 18 REQ TRIM MNVR TO FDAI RPY ANGLES
(TRIM) PRO To 4
(BYPASS) ENTR

Basic Date: Nov. 6, 1968

Basic Date: Nov. 6, 1968
Changed:

CSM 103

V55 - CMC TIME UPDATE

1 F 21 24 V55E
LOAD Δ CMC TIME (hrs,min,.01sec)

V64 START S-BAND ANTENNA

1 V37E 00E
 2 V64E
 F 06 51 RHO, GAMMA (.01°, .01°)
 S-BAND ANT - S
 TRACK - MAN
 Check P&Y Angle Ind
 TRACK - AUTO
 PRO

V67 - W-MATRIX ERROR DISPLAY

1 V67E
 F 06 99 POS ERR, VEL ERR, OPT CODE (.01nm, .1fps)
 R3 00001=Rend
 00002=Orbital
 00003=Cislunar

Load desired data
 To reinitialize Cislunar W-matrix,
 Load: R1 +00094
 R2 +00057
 R3 +00003


PRO

V74 CMC DOWNLINK

1 (If needed) V21 N01E 333E
 F 21 01 R3 333
 R1 20000E for 4 Dumps
 or 10000E for 2 Dumps
 or 04000E for 1 Dump
 2 V74E (Places erasable memory on downlink)

SM 103

Basic Date: Nov. 6, 1968
 Changed: Dec. 13, 1968



V79 LUNAR LANDMARK

- 1 V37E 00E, V96E when COMP ACTY-out
 2 V79E
 F 06 34 LAT - LONG TIME (hrs,min,.01sec)
 Load desired time
 PRO
- 3 F 06 31 LDG SITE TIME (hrs,min,.01sec)
 PRO
- 4 F 05 70 LMK CODE: R2=000DE
 (RECYCLE) V32E To 4
 PRO
- 5 F 06 34 LMK TIME (hrs,min,.01sec)
 PRO To 4 Until 5 LMK Are Cycled Then Exit

V82 ORBIT PARAMETER DISPLAY

Note: If high CMC activity (e.g.P4Xw.Lambert)
 POSS PROG ALARM and restart (no light)
 - code 1201 or 1202 stored.

- 1 F 04 06 V82E (If AVE G On Go To 2)
 R1 00002 Specify Vehicle
 R2 00001 CSM
 00002 LM
 PRO
- 2 F 16 44 HA, HP, TFF (.1nm,.1nm,min-sec)
 (RECYCLE) V32E To 2 (Not Nec If AVE G On)
 (Δ R-miss dist DISP-P11 only) N50E To 3
 (TF PER) N32E To 4
 (EXIT) PRO
- 3 F 16 50 Δ R (miss dist) HP,TFF (.1nm,.1nm,min-sec)
 KEY RLSE To 2
- 4 F 16 32 TIME FROM PER (Useful only if TFF=-59B59)
 (hrs,min,.01sec)
 KEY RLSE To 2

Basic Date Nov. 6, 1968
 Changed Dec. 13, 1968

CSM 103

V83 RNDZ PARAMETER DISPLAY #1

Note: If high CMC activity (e.g. P3X or P7X w P20), POSS PROG ALARM and restart (no light) - code 1201 or 1202 stored
 If alt above earth or moon >432 nm:
 P23 running - do not key V83 (or 85)
 P23 not running:
 Wait for no integration (COMP ACTY not on continuously)
 V96E (selects P00)
 V83E (or 85E) - perform routine
 V37E OOE

1
 F 16 54 V83E
 RANGE, RANGE RATE, THETA (.01nm,.1fps,.01°)
 PRO

V85 - RNDZ PARAMETER DISPLAY #2

Note: See V83 restrictions

1
 F 16 53 V85E
 RANGE, RANGE RATE, PHI (.01nm,.1fps,.01°)
 PRO

V89 - RENDEZVOUS FINAL ATTITUDE

Note: This routine will change N17 cells
 CMC - on
 ISS - on
 SCS - operating

1
 V37E OOE
 V62E

2
 F 04 06 V89E
 R1 00003 SPECIFY TRACKING ATTITUDE
 R2 00001 (PREF)
 00002 (+X AXIS)
 PRO

Basic Date Nov. 6, 1968
 Changed Dec. 13, 1968

CSM 103

3 F 06 18 FINAL FDAI RPY ANGLES (.01°)
 (MNVR) PRO
 (UPDATE DISPLAY) V32E

4 F 50 18 REQ MNVR TO FDAI RPY ANGLES (.01°)
 (AUTO) BMAG MODE (3) - RATE 2
 SC CONT - CMC
 CMC MODE - AUTO
 PRO
 (MAN) MNVR To 6

5 06 18 AUTO MNVR TO FDAI RPY ANGLES (.01°)

6 F 50 18 REQ MNVR TO FDAI RPY ANGLES (.01°)
 (TRIM) ALIGN SC In ROLL
 PRO To 5
 (BYPASS) ENTR

V90 - OUT-OF-PLANE DISPLAY

1
 F 06 16 V90E
 GET EVENT (hrs,min,.01sec)
 Load desired time
 PRO

2 F 06 90 Y,YDOT,PSI (.01nm,.1fps,.01°)
 (RECYCLE) V32E To 1
 (EXIT) PRO

V91 - COMPUTE BANKSUM

CMC - on (req)
 V37E OOE

1
 F 05 01 V91E
 R1 - Sum of all cells in bank
 R2 - Bank number
 R3 - Bugger word
 Verify R1=R2 or R1+R2=77777
 If not, rcd R2
 (NEXT BANK) PRO
 (TERM) V34E

Basic Date Nov. 6, 1968
 Changed Dec. 13, 1968

CSM 103

CMC SELF CHECK

1 F 21 01 V25 N01E, 1365E
E,E,E

2 F 15 01 V15 N01E, 1365E
R1 NUMBER OF ERRORS
R2 NUMBER OF TESTS STARTED
R3 NUMBER OF TESTS SUCCESSFUL

3 V21 N27E 10E SELF TEST, FIXED & ERASABLE
(4E SELF CHECKS ERASABLE
5E SELF CHECKS FIXED)

4 F 15 01 KEY REL
TEST SUCCESSFUL WHEN R2>3 (78 sec)
* IF PROG Lt - On *
* V05 N09E 01102 SELF *
* TEST ERROR *
(TERM) V21N27E 0E

MEASUREMENT & LOADING OF PIPA BIAS

1 DET - RESET
S/C RATES <0.1°/sec

2 V25N 21E, E,E,E/Start Event Timer

3 16 21 V16 N21E
XYZ PIPA COUNTS

4 At T + 4:16 - VERB
T4:16
(X) R1 ____ (Y) R2 ____ (Z) R3 ____ (XXXAB)

5 F 21 01 V21N 01E
LOAD 1452 E (CALCULATED X BIAS)E,E, (+ABXXX)
1454 E (CALCULATED Y BIAS)E,E
1456 E (CALCULATED Z BIAS)E

Basic Date Nov. 6, 1968
Changed

CS 103

FLAG WORD SET/RESET

1 F 21 07 V25N 07E
(LOAD FLAG WORD ADDRESS) E

2 F 22 07 (LOAD CODE FOR BIT TO BE CHANGED)ABCDE ENTR

	A			B			C			D			E		
BIT	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
CODE	4	2	1	4	2	1	4	2	1	4	2	1	4	2	1

3 F 23 07
(SET BIT) Key 1E
(RESET BIT) Key 0E

4 (To Verify) V01 N01E (FLAG Word ADD) ENTR

5 F 01 01 R1 FLAG WORD (ABCDE)
R3 FLAG WORD ADDRESS
EXAMPLE: To cause reinitialization of W-matrix for
mid-course (P23) or landmark (P22) naviga-
tion

Key:

V25N 07E	This resets bit 6 of
77E	flagword 3.
40E	Verification should
	show D<4
0E	

EXAMPLE: To set REFSMMAT flag:

Key:

V25N 07E	This sets bit 13 of
77E	flagword 3
10000E	Verification should show
	A odd
1E	

Basic Date Nov. 6, 1968
Changed

CSM 103

BINARY-TO-OCTAL CONVERSION

000-0	100-4
001-1	101-5
010-2	110-6
011-3	111-7

OCTAL-TO-DECIMAL CONVERSION

1-1	11-9	21-17	31-25	41-33
2-2	12-10	22-18	32-26	42-34
3-3	13-11	23-19	33-27	43-35
4-4	14-12	24-20	34-28	44-36
5-5	15-13	25-21	35-29	45-37
6-6	16-14	26-22	36-30	46-38
7-7	17-15	27-23	37-31	47-39
10-8	20-16	30-24	40-32	50-40

Basic Data Nov. 6, 1968
Changed

Basic Data Nov. 6, 1968
Changed

103

103

REVIEW DATA IN ERASABLE MEMORY

Perform During Any Flashing Display

V01 N01E (OCTAL ADD) E

01 01 R1 DATA R3 OCTAL ADD

N15E (For next succeeding word)

ENTR (For each succeeding word)

TO CHANGE DATA IN ERASABLE MEMORY

V21 N01E (ADDRESS) E

F 21 01 R3 ADDRESS

Load New Data in R1 E

N15E (For next succeeding word)

ENTR (For each succeeding word)

COAS LOS DETERMINATION

CMC - on
ISS - on
SCS - operating
SC CONT - SCS
MAN ATT (3) - MIN IMP
G/N PWR OPTICS - on
OPT MODE - CMC
OPT ZERO - ZERO (verify)

1 V37E 52E
2 F 04 06 00001
V22E 3E
PRO
3 F 50 25 00015
ENTR
4 F 01 70 000DE STAR CODE
LOAD BORESIGHT STAR CODE
OPT ZERO - OFF
PRO (Ignore PROG ALARM)
5 06 92 SHAFT, TRUN (.01°, .001°)
Center target
MARK with VERB key
Record SHAFT, TRUN _____
(REPEAT) KEY RLSE
(EXIT) V37E XXE
OPT ZERO -ZERO

Basic Date Nov. 6, 1968
Changed Dec. 13, 1968

Basic Date Nov. 6, 1968
Changed Dec. 13, 1968

CSM 103

CSM 103

P22 RAW DATA READOUT

CMC - on, HOLDING AT 06 49 FLASH
IN P22

1 F 06 49 VIN1E
2 F 01 01 3537E
Rcrd R1
N15E
Rcrd R1
3 01 15 ENTR
Rcrd R1
4 Repeat 3 till 7 pieces of data recorded
for each mark
5 KEY RLSE
6 F 06 49 Continue P22

SCS

No Cam

DSKY CONDITION LIGHT TEST
CMC - on

1 Key V37E 00E (desired)
DSKY - P00

2 Key V35E

3 Monitor the following events

- a. All DSKY condition lts - on
 - b. ISS warning lt - on
CMC warning lt - on
 - c. All DSKY numerical windows display 8
Sign positions in R1, R2, R3 show +
V, N windows flash
- Wait 5 sec
- d. All DSKY warning lts - off
 - e. ISS lt - off
CMC lt - off
 - f. Old PROG number will be displayed
Interrupted display (if any) will be
restarted

MONITOR OF INPUT/OUTPUT CHANNELS

1 F 11 10 V11 N10E
(LOAD CHANNEL ADDRESS) E
R1 Octal Contents of Specified
Channel

LOAD OUTPUT CHANNELS

1 F 21 10 V21 N10E
(LOAD CHANNEL ADDRESS) E
R1 (Load Octal Data) E

Basic Date Nov. 6, 1968
Changed -

FLAG WORD LISTING

<u>TITLE</u>	<u>ADDRESS</u>	<u>BIT</u>	<u>WHEN SET</u>	<u>WHEN RESET</u>
RNDZ	00074	7	P20 initiated	P20 terminated
UPDATE	00075	7	State vector up- date by marks allowed	State vector up- dating by marks not allowed
Track	00075	5	RNDZ Tracking allowed	Rendezvous tracking not allowed
Pref Att	00076	4	Pref Att computed	Preferred S/C attitude not computed
Steer	00076	11	Steering to be done	Steering omitted
REFSMAT	00077	13	REFSMAT good	REFSMAT not good
IMU	00074	8	IMU in use	IMU not in use
State Vector	00075	8	CSM State vector updated	LM state vector updated

Basic Date Nov. 6, 1968
Changed 12/13/68

Terminate	00103	15	Terminate R52,R53	Do not terminate
Trunnion drive	00074	4	Enables CMC contr of trunnion	CMC control of optics trunnion not enabled
Target 1	00075	10	LM sighting	Not sighting LM
Target 2	00075	9	LMK Sighting	Sighting star
W-matrix (ORBFLAG)	00077	6	P22, P23 W-matrix valid	P22, P23 W-matrix invalid
3 axis	00101	6	MNVR Specified by 3 axis	Maneuver speci- fied by 1 axis
External ΔV	00076	8	Ext ΔV VG comp	Lambert VG computations
Active vehicle	00076	5	LM active	CSM active
Final comp.	00076	6	Final RNDZ comp	Interim pass through rendezvous program computations

G-78

CSM 103

Basic Date Nov. 6, 1968
Changed 12/13/68

Sighting mark	00074	6	V51 initiated	V51 not initiated
Stick flag	00075	14	RHC out of detent	RHC in detent (auto maneuver enabled)
CMOON flag	00104	12	Permanent CSM SV in Lunar Sphere of Influence	Permanent CSM SV in Earth Sphere of Influence
<u>NON-FLAGS</u>				
MARKSTAT	1330	10	After mark	After mark reject
IMODES 30	1320	9	IMU not operating	IMU operating

G-79

A	B	C	D	E	1 Set	BINARY - OCTAL
15,14,13	12,11,10	9,8,7	6,5,4	3,2,1	0 Reset	000 0
						001 - 1
						010 - 2
						011 - 3
						100 - 4
						101 - 5
						110 - 6
						111 - 7

V60-63 DESCRIPTION

Before any of the following verbs will be effective, the RCS DAP must be activated.

- V60 - Keying V60E will load present gimbal angles (N20) into N17 cells.
- V61 - Keying V61E will display DAP phase plane errors on error needles provided the CMC has access to one of the FDAI displays.
- V62 - Keying V62E will display the difference between present gimbal angles (N20) and N22 desired gimbal angles provided the CMC has access to one of the FDAI displays. The difference is resolved into CSM control axes before being displayed.
- V63 - Keying V63E will display the difference between present gimbal angles (N20) and N17 (astronaut) desired gimbal angles provided the CMC has access to one of the FDAI displays. If V60E is keyed while V63 needles are active, the needles will be zeroed.

Basic Date Nov. 6, 1968
Changed

Basic Date Nov. 6, 1968
Changed

FORM 103

SCS POWER UP

AUTO RCS SELECT (16) - OFF
 BMAG MODE (3) - RATE 2
 CMC MODE - FREE
 SC CONT - CMC
 CB SCS LOGIC PWR (4) - CLOSE
 AV CG - as required
 LOGIC PWR 2/3 - on (up)
 SIG COND/DRIVER BIAS PWR (both) - AC1
 SCS ELEC PWR - GDC/ECA (170 watts)
 FDAI PWR - OFF (verify)
 BMAG PWR (both) - ON (110 watts)
 FDAI PWR - BOTH (104 watts)
 AUTO RCS SELECT (16) - enable

SCS POWER DOWN

EMS FUNCTION - OFF
 EMS MODE - STBY
 FDAI SCALE - 5/1
 FDAI SELECT 1/2
 FDAI SOURCE - ATT SET
 ATT SET - IMU
 MAN ATT (3) - MIN IMP
 ATT DEADBAND - MAX
 RATE - LOW
 TRANS CONTR PWR - OFF
 ROT CONTR PWR NORMAL (both) - OFF
 DIRECT (both) - OFF
 AUTO RCS SELECT (16) - OFF
 CMC MODE - FREE
 BMAG MODE (3) - RATE 2
 SCS TVC (both) - RATE CMD
 .05G sw - OFF
 d/Pc sw - Pc
 TVC GMBL DRIVES PITCH & YAW - AUTO
 BMAG PWR (both) - WARMUP (38 watts)
 TVC SERVO PWR (both) - OFF
 FDAI PWR - OFF
 LOGIC PWR 2/3 - OFF
 SCS ELEC PWR - OFF
 SIG COND/DRIVER BIAS PWR (both) - OFF

GDC ALIGNMENT TO IMU GIMBAL ANGLES

IMU - on
SCS - operating

Damp vehicle rates

ATT SET dials - set to IMU angles on
FDAI 1

FDAI SELECT - 1
FDAI SOURCE - ATT SET
ATT SET - IMU
ATT SET dials - null FDAI 1 err
needles

ATT SET - GDC
GDC ALIGN PB - push until needles
nulled

SCS ATTITUDE REFERENCE COMPARISON

CMC - on
IMU - on
SCS - operating
If SIVB SEPARATED: Damp vehicle rates

Key V16 N20E (press IMU angs)

FDAI SELECT - 1
FDAI SOURCE - ATT SET
ATT SET - GDC
ATT SET dials - null FDAI 1 error
needles

Key VERB when nulled (freeze display)

Record from DSKY:
R °, P °, Y °
Record ATT SET dials:
R °, P °, Y °

Basic Date: Nov. 6, 19


Changed

11/6/68

Basic Date: 12/13/68

Changed


NORTHERN



SHFT 180° TRUN 7.5°

REFS	_____	_____	_____
R	_____	_____	_____
P	_____	_____	_____
Y	_____	_____	_____
REFS	_____	_____	_____
R	_____	_____	_____
P	_____	_____	_____
Y	_____	_____	_____

SOUTHERN



SHFT 180° TRUN 7.5°

REFS	_____	_____	_____
R	_____	_____	_____
P	_____	_____	_____
Y	_____	_____	_____
REFS	_____	_____	_____
R	_____	_____	_____
P	_____	_____	_____
Y	_____	_____	_____

Changed north set to
SIRIUS & RIGEL @ 19:00
BASED ON RESULTS
of JKT star vis. ck.

SCS

1
2

1
2

No Comm

BACKUP GDC ALIGNMENT (IMU FAILED)

SCS - operating

RECORD: R,P,Y ALIGN from MSFN

Set SCT to 180° SHFT, 7.5° TRUN

ATT SET dials - R,P,Y ALIGN

MNVR to STARS:	North	South
R line -	Polaris (5)	Atria (34)
50° Mark -	Navi (3)	Acrux (25)

FDAI SELECT - 1

ATT SET - GDC

GDC ALIGN - push

BACKUP GDC & IMU ALIGNMENT (CMC FAILED)

ISS - on

SCS - operating

RECORD: R,P,Y ALIGN from MSFN

Set SCT to 180° SHFT, 7.5° TRUN

ATT SET dials - R,P,Y ALIGN

FDAI SELECT - 1/2

CAGE IMU and hold

MNVR to STARS:	North	South
R line -	Polaris (5)	Atria (34)
50° Mark -	Navi (3)	Acrux (25)

FDAI SELECT - 1

ATT SET - GDC

GDC ALIGN - push

ATT SET dials - 0,0,0

MNVR to 0,0,0 and null error needles

UNCAGE IMU

FDAI SELECT - 1/2

Basic Date Nov. 6, 1968
 Changed Dec. 13, 1968

103

IN-PLANE GDC ALIGNMENT

CMC - on
 ISS - on
 SCS - operating

1 V37E 52E
 F 04 06 00001
 Load R2=00002
 PRO

2 F 06 34 GET ALIGN 0,0,0
 PRO

3 F 06 22 R,P,Y

4 Set ATT SET dials to R,P,Y on DSKY

5 FDAI SELECT - 1
 ATT SET - GDC
 GDC ALIGN - push

6 V37E XXE

Basic Date Nov. 6, 1968
 Changed

Basic Date Nov. 6, 1968
 Changed

CSM 103

PGNS ORDEAL INITIALIZATION
(IN-PLANE ALIGNMENT REQ'D)

FDAI 1 or 2 - ORB RATE
 EARTH/LUNAR - as req'd

1

2 F 04 06 V82E
 00002 SPECIFY VEHICLE
 00001
 PRO

3 F 16 44 HA, HP (.1nm,.1nm)
 Calculate Average
 ALT SET - Set Average
 PRO

4 F 16 54 V83E
 R,RDOT,THETA (.01nm,.1fps,.01°)
 MODE - HOLD/FAST
 SLEW - To THETA
 MODE - OPR/SLOW
 PRO

SCS ORDEAL INITIALIZATION
(IN-PLANE GDC ALIGNMENT REQ'D)

FDAI 1 or 2 - ORB RATE
 EARTH/LUNAR - as req'd

MSFN Supply Altitude
 ALT SET - Set

SC +X at the horizon

MODE - HOLD/FAST
 SLEW FDAI
 MODE - OPR/SLOW

PASSIVE THERMAL CONTROL
(X axis Roll, Pitch & Yaw Hold)

CMC - on (for CMC MNVR)
ISS - on (for CMC MNVR)
SCS - operating
CMC MODE - FREE
BMAG MODE (3) - RATE 2
AUTO RCS SEL (12) - MNA/B
LOAD DAP
ROT CONTR PWR NORMAL 2 - AC/DC

V37E OOE

RECORD: R,P,Y PTC from MSFN

MNVR TO PTC ATT

V62E

V49E

1

2

3 F 06 22 DESIRED FINAL GMBL ANGLES (.01°)
LOAD R,P,Y PTC
PRO

4 F 50 18 REQ MNVR TO FDAI R,P,Y ANGLES (.01°)
(AUTO) SC CONT - CMC
CMC MODE - AUTO
PRO
(MAN) SC CONT - SCS
MNVR to 6

5 06 18 AUTO MNVR TO FDAI R,P,Y ANGLES (.01°)

Basic Date Nov. 6, 1968
Changed 11/27/68

103

Basic Date Nov. 6, 1968
Dec. 13, 1968
Changed

CSM 103

6 F 50 18 REQ TRIM TO FDAI R,P,Y ANGLES (.01°)
(AUTO TRIM)

SC CONT - CMC
CMC MODE - AUTO
PRO to 5
(BYPASS) DEADBAND - MAX
RATE - HIGH
LIMIT CYCLE - on (up)
AUTO RCS SEL PITCH & YAW -
Set for single jet operation
MAN ATT (PITCH, YAW) - RATE CMD
MAN ATT (ROLL) - ACCEL CMD
SC CONT - SCS
BMAG MODE (3) - ATT1/RATE 2

ENTR

Initiate .1°/sec roll rate

Terminate PTC

MAN ATT (ROLL) - RATE CMD
BMAG MODE(3) - RATE 2
LIMIT CYCLE - OFF

7

8

No Comm

P37 RETURN TO EARTH PROGRAM
(with -MA)

Nominal TEI - completed

1 F 04 06

V37E 21E
R1 00002
R2 00001
PRO

2 F 06 34

GET LAT, LONG
Load TEI TIG + 24 hrs.
PRO

(hrs,min,.01sec)

3 F 06 43

LAT, LONG, ALT
V6N2E, 1107E

4 F 06 02

GERU
If GERU>07990
V32E to 2 and increment time by
1 hr.
If GERU<07990
Rcrd GERU
Rcrd GET LAT, LONG

hrs
min
sec

PRO

5 F 37
F 06 33

37E
TIG
Load TIG
P RO

(hrs,min,.01sec)

6 F 06 60

BLANK, V PRED, GAMMA EI
Load R2 and R3 = +00000
PRO
V24 N1E
3651E
70000E,E (-MA)
KEY RLSE

(fps,.01^o)

Basic Data Nov. 6, 1968
Changed Dec. 17, 1968

No Comm

SCS


- 7 F 06 61 IMPACT LAT, LONG (.01°)
PRO
- 8 F 06 39 ΔT TRANSFER (hrs,min,.01sec)
PRO
- 9 F 06 60 BLANK, V 400K, GAMMA EI (fps,.01°)
PRO
- 10 F 06 81 ΔVXYZ (LV) TIG (.1fps)
PRO
V16 N38E
- 11 16 38 S.V. TIME

*N38 oscilation (EI±5hrs) *
 * V96E *
 * V37E 37E to 5 and *
 * advance TIG by 15 min *
 *PROG ALARM: *
 * KEY RLSE-(F 05 09) *
 * V32E to 5 and use TIG *
 * + 15 min *
 *If second attempt Go to *
 *P37 RETURN TO EARTH PROGRAM *
 * (without -MA) N.C.-Y *

12 KEY REL Lt - on
 RCRD GET EI _____ hrs
 (N38) _____ min
 _____ sec
 KEY RLSE

- 13 F 06 61 IMPACT LAT, LONG (.01°)
LONG _____
PRO

Basic Date Nov. 6, 1968
 Changed Dec. 17, 1968



Δ LONGITUDE CORRECTION - DEG

CMC INERTIAL VELOCITY AT 400K ALTITUDE - FT/SEC

N.C.-3

14 F 06 39 ΔT TRANSFER (hrs,min,.01sec)
Rcrd _____
PRO

15 F 06 60 BLANK, V400K, GAMMA EI (fps,.01°)
V400K _____
Determine Δ Long from V400K
vs Long Bias Chart
IMPACT LONG=LONG- Δ LONG= _____

16 F 06 81 PRO
 Δ VXYZ (LV) TIG (.1fps)
Rcrd _____
 Δ VX _____
 Δ VZ _____
PRO

17 F 04 06 THRUST OPTION
R1 00007
R2 0000X
X=1 (SPS)
X=2 (RCS)
PRO

18 F 06 33 TIG (hrs,min,.01sec)
PRO

19 F 16 45 MARK, TFI,MGA (mark,min-sec,.01°)
Set DET
PRO (MGA SET TO-00002 IF
REFSMAT FLAG NOT SET)

20 F 37 If IMPACT LONG unsatis, go to N.C.-7
If IMPACT LONG satis:
40E or 41E

Nov. 6, 1968
Dec. 17, 1968
Basic Date Changed

N.C.-4
P37 RETURN TO EARTH PROGRAM
 (without -MA)


Nominal TEI-completed
 P37-with-MA-no solution

- 1 F 06 33 V37E 37E
 TIG (hrs,min,.01sec)
 Load TIG (GET LAT, LONG from P21)
 PRO
- 2 F 06 60 BLANK, V PRED, GAMMA EI (1fps,.01°)
 Load R2 and R3 = +00000
 PRO
- 3 F 06 61 IMPACT LAT, LONG (.01°)
 PRO
- 4 F 06 39 ΔT TRANSFER (hrs,min,.01sec)
 PRO
- 5 F 06 60 BLANK, V400K, GAMMA EI (fps,.01°)
 PRO
- 6 F 06 81 ΔVXYZ (LV) TIG (.1 fps)
 PRO
- V16 N38E
 When KEY REL-On, RCRD GET EI _____ hrs
 (N38) _____ min
 _____ sec
- 7 F 06 61 KEY RLSE
 IMPACT LAT, LONG (.01)
 LONG _____
 PRO
- 8 F 06 39 ΔT TRANSFER (hrs,min,.01sec)
 Rcrd _____
 PRO
- 9 F 06 60 BLANK, V400K, GAMMA EI (fps,.01)
 V400K
 Get Δ LONG from V400K vs Long Bias Chart
 IMPACT LONG=LONG-Δ LONG=_____
 Δ LONG=LONG(PAD)-IMPACT LONG

Basic Date Nov. 6, 1968
 Changed Dec. 17, 1968

SJS

AT FOR P21 REQUIRED FOR 1350 N.M. ENTRY RANGE SPLASH PREDICTION



Basic Date Nov. 6, 1968
Changed Dec. 17, 1968

N.C.-5

10 F 06 81 Rcrd ΔV's
 ΔVX _____
 ΔVY +0000.0
 ΔVZ _____

11 V37E 00E
 Go to N.C.-7
 & calculate burn to achieve
 PAD LONG

LANDING SITE DETERMINATION FOR P61

Last MCC-complete and targeted via
 P37 procedure

1 F 04 06 V37E 21E
 R1 00002
 R2 00001
 PRO

2 F 06 34 GET LAT, LONG *see below*
 Load GET EI (N38) or ~~RET .05G (PAD)~~
 plus ΔT from V400k vs ΔT chart

_____	GET EI (N38)
+ _____	ΔT
_____	GET LAT, LONG(N34)

PRO

3 F 06 43 Rcrd _____ LAT (P61)
 _____ LONG
 + _____ 1.00
 _____ LONG (P61)

Add 1.00° to LONG
 PRO

4 F 37 XXE

*if no P37 (-ma) then
 determine GET EI by
 iterating P21 to an altitude
 solution of 66 nm. Start by
 using RET .05G (PAD)*

N.C.-6
ENTRY ALIGNMENT (No comm)

To be performed at TEI + 1 hr
 P37 targeting-complete

- 1 F 06 33 V37E 30E
 GETI (hrs,min,.01sec)
 Load GET EI (N38) from P37-with -MA
 or RET .05G (PAD)
 PRO
- 2 F 06 81 ΔVXYZ (LV) (.1fps)
 Load ΔVX=00100
 ΔVY=ΔVZ=+00000
 PRO
- 3 F 06 42 HA, HP, ΔV (REQ) (.1nm,.1nm,.fps)
 PRO
- 4 F 16 45 M, TFI, MGA (0,min-sec,.01°)
 PRO
- 5 F 37 40E
- 6 F 50 18 V37E 52E
PERFORM P52, PREFERRED OPTION
 (pg G-56)

SC ORIENTATION FOR NO COMM RTE MCC-NO IMU


P37 tarteting - complete

ΔV's determined: ΔVX= _____
 ΔVY= _____
 ΔVZ= _____

- 1 F 06 33 V 37E 30E
 GETI
 Load GET of MCC
 PRO
- 2 F 06 81 ΔVXYZ(LV) (.1fps)
 Load ΔV's from above
 PRO
- 3 F 06 42 HA,HP, ΔV (REQ)
 Rcrd ΔV (REQ) _____
V37E00E
 Calculate $r = \Delta VZ / \Delta V (REQ)$ _____
 Calculate $\theta = \sin^{-1}(r) =$ _____

Notes

1. If no longitude control required make
 $\theta = 0$, burn will be 090 or 270
 after FOAI (SCS) alignment.



- 2.
3. To determine θ use S scale (black figure)
 for angles use C scale for r values.
 Direct readout. θ takes same sign
 as r.

Example $\Delta VZ = -40' / \text{sec}$
 $\Delta VX = -20' / \text{sec}$
 $\Delta V(REQ) = 44.7' / \text{sec}$

$$r = \frac{\Delta VZ}{\Delta V(REQ)} = \frac{-40}{44.7} = -.895$$

$$\therefore \theta = -63.5^\circ$$


Burn angle would be

$$\Delta \angle = 90^\circ - (-63.5) = 153.5^\circ$$

$$\text{Ball angle} = 360 - 153.5 = 206.5^\circ$$

Basic Date Nov. 6, 1968
 Changed Dec. 17, 1968

SCS



Inplane orientation of the Earth's terminator for midcourse corrections during the Earth coast.

Basic Date: Nov. 6, 1968
 Changed: Dec. 17, 1968

ignore with -ma →

LONG CONTROL FOR NO COMM

MCC 6 & subs - go to 3
 $\Delta V_X(P37)$ _____
 $\Delta V_Z(P37)$ _____

(Biased) ΔT TRANSFER _____ (N39)
 IMPACT LONG (N61) _____

V400K _____

1 Enter GERU vx RADIAL SPEED chart.

Find REF point corresponding to GERU and either V400K or ΔT TRANSFER. Move along GERU line the desired Δ LONG or $\Delta \Delta T$ TRANSFER (Each Δ TRANS line = 30°).

Rcrd Δ RADIAL SPEED (i.e. distance between pts. in fps):
 $\Delta V_Z(\text{LONG}) = \Delta V_Z(\text{DES}) - \Delta V_Z(\text{REF})$

Determine Avg. V400K between DES pt and REF pt.

Enter GERU vs K chart
 Use GERU and Avg V400K to determine K = _____

N.C.-7

4 Center earth in COAS:
 Terminator - horizontal
 Sunlit side down (+Z SC)

5 Roll left 6° - slow return
 12° - fast return

6 FDAI SELECT - 1
 FDAI SOURCE - ATT SET
 ATT SET - GDC
 ATT SET dials - 0°, 0°, 0°
 GDC ALIGN PB - push

7 If ΔV_X positive: pitch up 90°-0°
 If ΔV_X negative: pitch down 90°-0°

8 Perform burn: $\Delta V(\text{REQ})$

N.C.-8

Calc $\Delta VX(\text{LONG}) = (K) \times \Delta VZ(\text{LONG})$ $\underline{\hspace{1cm}} = \underline{\hspace{1cm}} \times \underline{\hspace{1cm}}$ Calc P30 ΔV 's: $\Delta VX(\text{P30}) = \Delta VX(\text{P37}) + \Delta VX(\text{LONG}) = \underline{\hspace{1cm}}$ $\Delta VY = 0 = \underline{\hspace{1cm}}$ $\Delta VZ(\text{P30}) = \Delta VZ(\text{P37}) + \Delta VZ(\text{LONG}) = \underline{\hspace{1cm}}$

ΔV 's not acceptable or GERU vs RADIAL SPEED
chart too small, go to 3 for corridor
control only

2 V37E 30E To P30 pg G-35

Use $\Delta VX(\text{P30}), \Delta VY(\text{P30}), \Delta VZ(\text{P30})$

Use GET LAT, LONG for GETI

3 Enter GERU vs K chart

Use GERU and V400K to determine

 $K = \underline{\hspace{1cm}}$ Calculate $K \times \Delta VZ(\text{P37}) = \underline{\hspace{1cm}}$ Calculate $\Delta VX(\text{P30}) = \Delta VX(\text{P37}) - K \Delta VZ(\text{P37})$

4 V37E30E to P30 pg G-35

Use $\Delta VX(\text{P30})$ $\Delta VY(\text{P30}) = \Delta VZ(\text{P30}) = 0$

Use GET LAT, LONG for GETI

Basic Date Nov. 6, 1968
Changed Dec. 17, 1968Basic Date Nov. 6, 1968
Changed Dec. 17, 1968

1. Before TLL+32 hrs:

- Make abort burn.
- Re-initialize w-matrix. (MIT says no but NASA says yes)
- Initiate sightings as soon as possible after abort (3 sets)
- Scan stars on Fly-by (FB) for possible targets (preliminary data indicates stars available for last half of aborts nearly identical to FB).
- Three sets every 2.5 hours for 20 to 40 hour return times.
- Last interval before final MCC starts at MCC-1.5 hour and consists of 5 sets.

2. After TLL+32 hrs:

- Make sightings as per nominal flight plan.
- If possible, add extra sightings close to moon.
- Re-initialize w-matrix at perilune.
- Proceed with fly-by schedule as per Figures 1(a)(b)(c)(d).

3. LO aborts (detailed schedules provided - Figures 1(a)(b)(c)(d))

- The first and last 17 hours of the schedule should not be changed.
- The data in the middle of the TE leg may be moved around for rest periods and MCC's.
- Change to EI chart at EI-40.

4. Fly-by aborts (schedule provided Figures 2(a)(b)(c)(d).

- a. Fly-by schedule for communication loss on trans-lunar (TL) leg assumes TL sightings made as per nominal schedule.
- b. Data provided is for pericyynthion of 60n.mi. (data for higher perisynthion will be similar but AOS and LOS times may vary).
- c. Pericynthion greater than 60 n.mi. check LO abort chart for additional targets.

5. General trans-earth optical navigation rules:

- a. A sighting is to consist of three marks.
- b. A sighting interval is to consist of at least 3 star/horizon sightings - two stars as close to the orbit plane as possible and one star as far out of the orbit plane as possible.
- c. 15 sightings within the LSOI.
 - (1) At least 8 lunar sightings, as soon after TEI as possible and before TEI + 3 hours.
 - (2) Three sighting intervals within the LSOI.
- d. At least 4 sightings prior to a MCC and at least 3 sightings after each MCC except the last MCC.
- e. In the interval 35000 n.mi. from the moon to 100,000 n.mi. from the earth use at least 5 sighting intervals spaced evenly.
- f. 25 sightings within 100K n.mi. radius of the Earth.
 - (1) One hour of optical sightings preceding the last MCC at Entry - 2 hours.
 - (2) One sighting interval must use the moon as reference body and must precede the last sighting interval prior to MCC at Entry - 2.

SCS

Changed

Basic Date

Basic Date - May. 6, 1968
Changed - Dec. 17, 1968

N.C.-9

DIRECT ABORT PROCEDURES

Time From	
*DAM+	P23 - 3 sets ENH Stars 22, 26, 31.
DAM + 1 hr	Determine ENTRY Alignment (N.C. -6) IMU Realign P52 Option 1-Preferred
DAM + 2.5 hrs.	P23 - 3 sets ENH Stars 22, 26, 31. 1 set LH stars 33N, 40N, 42F, 45F -for abort after TLI+20hrs
DAM+3hrs	P37 Criteria for MCC $\Delta V > 1$ fps. IMU Realign P52 Option 2-REFSMAT (If MGA $> 45^\circ$ do a preferred align specified by P40/41 MCC ₁)
DAM + 5 hrs.	
DAM + 6 hrs.	P23 - 3 sets (22,26,31 for remainder of sighting)
DAM + 11 hrs.	P23 - 6 sets
DAM + 12 hrs.	P37
EI - 11 hrs	P23 - 6 sets
EI - 7 hrs	IMU Realign P52 Option 3 - REFSMAT
EI - 6 hrs	P23 - 3 sets
EI - 4 hrs	P23 - 3 sets
EI - 3 hrs	P 37 Landing Site Determination for P61 (N.C)
EI - 2:30 hrs	MNVR To Burn Attitude
EI - 2 hrs	MCC
EI - 1:50 hrs	P23 - 1 set

b

e

nd

if

9

3

3

EI - 1:35 hrs IMU Realign P52 Go to E-6 (P)
Option 3 - REFSMMAT

* DAM - Direct Abort Maneuver

FRESH START RECOVERY (Not Verified)

In case of a CMC Fresh Start (Blank Prog Register) and no distruction of E-Memory
No 1107 Alarm

Attempt:

- Validate CMC if GND Support is not available
- 1 V36E
- 2 V48 Load DAP
- 3 V46 Start DAP
- 4 V16N36E Verify CMC Clock and Correct if necessary (V55)
- 5 Verify CSM & LM State Vectors Via P21 and available NAV check Data
NOTE: If in lunar sphere - CMoon Flag and LMoon Flag will have to be set via V25N07E 104E 6000E 1E
- 6 V37E OOE
- 7 Validate REFSMMAT Cells: V25N07E 77E 10000E 1E Call P52 and verify. Do P51 if invalid.
- 8 Select P47 and observe ΔV 's (To observe proper Pipa Compensation) Exit P47 and call P00 anytime after average G Starts (To insure proper initialization of IMU drift compensation routines.)
- 9 Most Ephem Data can be verified by using P22 Auto Optics on a known Lunar Ldmk (CSM altitude less than 425 NM) or using P23 Auto Maneuver and Optics LLos on a Lunar Landmark (CSM alt greater than 425 NM)

Basic Date Nov. 6, 1968
Changed Dec. 17, 1968

Basic Date
Changed

Changed

SYSTEMS MANAGEMENT TABLE OF CONTENTS

PROPULSION SYS	S-1
1 SPS MON CK	S-1
2 SM RCS MON CK	S-1
3 CM RCS MON CK	S-1
EPS PER VERIF	S-3
1 CRYO PRESS QTY CK	S-3
2 FC PWR PLANT CK	S-3
3 DC VOLT AMP CK	S-3
4 AC VOLT CK	S-4
5 BATT CHARGING	S-4
6 FC PWR PLANT PURGE	S-4
7 H2/O2 QTY BAL CORR	S-4
ECS PER VERIF	S-5
1 ECS MON CK	S-6
2 ECS PRE-TLI/LOI REDUN COMPON CK	S-6
3 ECS PERIODIC REDUN COMPON CK	S-7
ECS SPECIAL PROCEDURES	S-8
1 GLY ACCUM REFILL	S-8
2 CO2 ABSORB FILT REPLACEMENT	S-8
3 DEBRIS SCREEN CK	S-8
4 POT H2O CHLORIN	S-9
PGA MODE CHANGES	S-9
1 DOFFING	S-9
2 DONNING	S-9
3 PARTIAL	S-9
4 DISCON COMM UMB	S-10
5 SUIT CKT INTEG CK	S-10
6 PGA INTEG CK	S-10
CAB ATMOS MODE CHANGES	S-11
1 CM PRESS DUMP	S-11
2 CAB REPRESS (NORM, 30 MIN)	S-12
3 CAB REPRESS (ATL, 52 MIN)	S-12
4 CM O2 SUPPLY REFILL	S-12

Rev. 6, 1968

Double D
Changed.

SM 103

SYSTEMS MANAGEMENT

PROPULSION SYSTEM

WASTE MGMT	
1 VERIF OF CLEAR UR VENT LINE	S-13
2 PGA UR COLL BAG DUMP	S-13
3 UTS (COLLECTION)	S-13
4 UTS/VACUUM (DUMP)	S-13
5 WASTE WATER TANK DRAIN	S-15
6 SIDE HATCH DUMP	S-15
7 WATER COLLECTION	S-16
CABIN COLD SOAK	
1 ACTIVATE	S-16
2 DEACTIVATE	S-17
C&WS OPER CK	S-17
SYS TEST METER READOUTS	S-18
TELECOM PROCEED	
HI-GAIN ANT	S-19
TV OPER	S-20
ANT POSITIONS	S-21
RCS ENG VENT LOCATION	S-22

- 1 **SPS MONITORING CKS**
 SPS PRPLNT TK TEMP - +45° to +75°F
 * If <45°F-SPS LINE HTR-A *
 SPS PRPLNT TK PRESS: He - 3900 psia max.
 N2A & B - 2900 psia max.
 SPS PRESS IND sw - He
 FUEL & OXID PRESS - 170-195 psia
 SPS ENG INJ VLVS (4) - CLOSE
 SPS OX, FUEL & UNBAL QTY - record
 OXID FLOW VLV - PRIM
 SPS He VLV (both) - AUTO
 SPS He VLV tb (both) - bp
- 2 **SM RCS MONITORING CK**
 SM RCS SEC PRPLNT tb (4) - bp (If PRIM in use)
 SM RCS He 1 & 2 tb (8) - gray
 SM RCS PRIM PRPLNT tb - gray (If PRIM in use)
 RCS IND sw - SM A, B, C, D
 PKG TEMP - 105-195°F
 He PRESS - record
 MANF PRESS - 178-192 psig
 He TK TEMP - record
 PRPLNT QTY - record
 When PRPLNT QTY is 43%: (He PRESS tbd psig)
 SM RCS SEC PRPLNT A(B,C,D) - ON
 SEC PRPLNT A(B,C,D) tb - gray
 PRIM PRPLNT A(B,C,D) - OFF
 PRIM PRPLNT A(B,C,D) tb - bp
- 3 **CM RCS MONITORING CK**
 CM RCS PRPLNT tb (both) - bp
 RCS IND sw - CM 1,2
 He TEMP - 60-90°F
 He PRESS - 4000-4450 psia
 FUEL & OXID PRESS - 15-125 psia
 After CM RCS Activation:
 He PRESS-3700-4150 psia
 FUEL & OXID PRESS - 285-302 psia
 CM RCS HTRS - OFF

Basic Date Nov. 6, 1968

Changed

103

Basic Date Nov. 6, 1968

Change

CSM 103

Dec. 4, 1968

EPS PERIODIC VERIFICATION AND TESTS

- 1 Cryogenic Pressure - Quantity Check
 H2 PRESS (both) - 225-260 psia
 SURGE TK PRESS - 865-935 psia
 O2 PRESS (both) - 865-935 psia 80-100% - 7 hr
 H2 QTY (both) - record 50-80% - 8 hr
 O2 QTY (both) - record
 CRYO FANS - OFF; ON as req'd *C/W LT - out before*
 continuing
- 2 FC Power Plant Check
 FC IND sw - 1,2,3
 H2 FLOW - 0.03-0.15 lb/hr
 O2 FLOW - 0.25-1.2 lb/hr
 MOD SKIN TEMP - 390-450°F
 MOD COND EXH TEMP - 150-175° F
 FC TB (2) - gray
 FC RAD TB (3) - gray
 FC REACS (3) - gray
 FC REACS & RAD cb (6) - out all others in (verify)
- 3 DC Voltage-Amperage Check
 MN BUS TIE (both) - OFF (verify)
 FC MNA TB - 1 & 2 gray, 3 BP
 FC MNB TB - 1 BP, 2 & 3 gray
 FC 1, 2, & 3 (RECORD AMPS)
 MAIN BUS A, B, (26.5-31 vdc-Record)
 BAT BUS A, B, & BAT C (34-38 vdc < 3 amp)
 PYRO BAT A, B (37 VDC) *TC PYRO BAT ck desired: PYRO A/B SEP A/B cb (both) - close*
 DC IND - MAIN BUS B *Pyro A/B SEP A/B cb (both) - open*
 SYS TEST 4B (BAT RLY BUS - 3.7-4.1 vdc)
 SYS TEST 4A (BAT COMPT PRESS) - <1.5 vdc
 (NA UNTIL 1st VENT)
 If >1.5: BAT VENT VLV -
 VENT (to 0) then CLOSED
- 4 AC VOLTS - 115 ± 2 all PHASES

- 5 Battery Charging BAT A (B)
 MAIN BUS TIE A/C (B/C) - OFF
 BAT BUS A & B PYRO BUS TIE cb - open (verify)
 BAT C BAT BUS A & B cb - open
 BAT RLY BUS BAT A(B) cb - open
 DC IND sw - BAT CHARGER
 BAT CHARGE - A(B,C)
 DC VOLTS - 37.5-40 vdc
 DC AMPS - 2.0-0.4 amps
 BAT CHARGE - OFF at 0.4 amps or 100% re-charge
 BAT RLY BUS BAT A(B) cb - closed
 SYS TEST 4A (BAT VENT <1.5)
 If >1.5: BAT VENT VLV -
 VENT (to ~0) then CLOSED

6 Fuel Cell Power Plant Purging

A. O2 PURGING

FC IND sw - 1(2,3)
 FC PURGE 0 1(2,3) - O2 (2 min.)
 FC FLOW-O2 Flow incr 0.6 lb/hr
 M/A FC 1(2,3) - On/Reset
 FC PURGE - 1(2,3) - OFF

B. H2 PURGING

H2 PURGE LINE HTR - ON (20 min prior)
 FC IND sw - 1(2,3)
 FC PURGE - 1(2,3) - H2 (1 min, 20 sec)
 FC H2 FLOW - Flow incr 0.67 lb/hr
 M/A FC 1(2,3) - On/Reset
 FC PURGE - 1(2,3) - OFF
 H2 PURGE LINE HTR - OFF

- 7 H2 or O2 Quantity Balance Correction
 ON LOW Tank, H2 or O2 HTRS 1(2) - OFF,
 THEN AUTO, WHEN BALANCED

ECS PERIODIC VERIFICATION

1 ECS MONITORING CHECK

+CABIN ΔP - -1 to -3.5 in H2O
 +O2 FLOW - 0.2-0.45 lb/hr (after changeover)
 O2 SURGE TANK PRESS - 865-935 psia
 PRIM RAD tb - gray
 *If PRIM RAD tb - 2 *
 * ECS RAD FLOW AUTO CONT - 1 until *
 * tb gray, then AUTO *
 ECS RAD TEMP PRIM IN - 67-97° F
 ECS RAD TEMP PRIM OUT - -20° to +63°F (-20° to
 97°F for lunar orb)
 REPRESS O2 >865 psia
 +GLY EVAP PRIM TEMP OUT - 40-50.5°F
 +GLY EVAP PRIM STEAM PRESS
 .1-.15 boiling, > .16 not boiling
 +PRIM GLY DISCH PRESS - 40-52 psig
 +SUIT TEMP - 45-55°F
 +CABIN TEMP - 70-80°F
 +SUIT PRESS/CABIN PRESS - 4.8-5.2 psia(14.7 for launch)
 +PART PRESS CO2 < 7.6 mm Hg
 +SUIT COMP ΔP - 0.3-0.4 psid
 +PRIM GLY ACCUM QTY 30-70% (expect 20-50% at insert)
 *If <30% - PRIM ACCUM FILL vlv - *
 * ON (until 40-55%) *
 +POT H2O QTY - 10-100%
 +WASTE H2O QTY - 25-85%
 *If >85% - Dump, pg S-15

Basic Date: Nov. 6, 1968
 Changed: Dec. 4, 1968

SM 103

SM 103

2 ECS PRE-TLI/LOI REDUNDANT COMPONENT CKSuit Compressor

SUIT COMPR (both) - sw to other compr
 SUIT COMPR ΔP ind - 0.3-0.4 psid

Main O2 Regulators

MAIN REG B vlv - close
 EMER CABIN PRESS vlv - 1
 PUSH TO TEST PB-PUSH (O2 FLOW INC)
 O2 press - 90-110 psig (from MSFN if avail)
 MAIN REG B vlv - open
 MAIN REG A vlv - close
 EMER CABIN PRESS vlv - 2
 PUSH TO TEST PB - PUSH (O2 FLOW INC)
 O2 press - 90-110 psig (from MSFN if avail)
 MAIN REG A vlv - open
 EMER CABIN PRESS vlv - BOTH (OFF if suited)

Secondary Glycol Loop

Open cool atten panel (If req'd)
 EVAP H2O CONT SEC vlv - AUTO
 ECS IND sw - SEC
 SEC COOL LOOP PUMP - AC1
 GLY DISCH SEC PRESS - 39-51 psig
 ACCUM SEC QTY IND - 30-55%
 SEC COOL LOOP EVAP - EVAP
 SEC EVAP STEAM PRESS .1-.15 boiling
 >.16 not boiling

After 5 min

SEC EVAP TEMP OUT - 40-50.5°F
 SEC COOL LOOP EVAP - RESET for 58 sec minimum,
 then off (ctr)

ECS IND sw - PRIM

SEC COOL LOOP PUMP - off (ctr)
 EVAP H2O CONT SEC vlv - OFF

3 ECS PERIODIC REDUNDANT COMPONENT CKMain O2 Regulators

MAIN REG B vlv - close
 EMER CABIN PRESS vlv - 1
 PUSH TO TEST PB-PUSH (O2 FLOW INC)
 O2 press - 90-110 psig (from MSFN if avail)
 MAIN REG B vlv - open
 MAIN REG A vlv - close
 EMER CABIN PRESS vlv - 2
 PUSH TO TEST PB - PUSH (O2 FLOW INC)
 O2 press - 90-110 psig (from MSFN if avail)
 MAIN REG A vlv - open
 EMER CABIN PRESS vlv - BOTH (OFF if suited)

Secondary Glycol Loop

Open cool atten panel (If req'd)
 EVAP H2O CONT SEC vlv - AUTO
 ECS IND sw - SEC
 SEC COOL LOOP - AC 1 (AC 2)
 GLY DISCH SEC PRESS - 39-51 psig
 ACCUM SEC QTY IND - 30-55%
 SEC COOL LOOP EVAP - EVAP
 SEC EVAP STEAM PRESS .1-.15 boiling,
 >.16 not boiling

After 5 min
 SEC EVAP TEMP OUT - 40-50.5F
 SEC COOL LOOP EVAP - RESET for 58 sec minimum,
 then off (ctr)

ECS IND sw - PRIM
 SEC COOL LOOP PUMP - off (ctr)
 EVAP H2O CONT SEC vlv - OFF

Basic Date Nov. 6, 1968
 Changed Dec. 4, 1968

Basic Date Nov. 6, 1968
 Changed Dec. 4, 1968

ECS SPECIAL PROCEDURES

- 1 GLYCOL ACCUMULATOR REFILL (IF <30%)
 PRIM ACCUM FILL vlv - ON
 GLY ACCUM PRIM QTY - 40-55%
 PRIM ACCUM FILL vlv - OFF
 IF OVER FILL
 GLYCOL RESVR INLET - OPEN (MOM)
- 2 CO2 ABSORBER FILTER REPLACEMENT
 CO2 CSTR DIVERT vlv - A(B)
 BLEED vlv - PRESS
 COVER LATCHING HANDLE - UNLOCK
 REPLACE FILTER
 COVER LATCHING HANDLE - LOCK
 SHIM STOWAGE - B5 & B6
- 3 DEBRIS SCREEN CHECK
 Check cabin ht exch inlet screen
 Check SUIT RET AIR vlv screen
 CABIN FANS (both) - OFF
 SUIT RET AIR vlv - CLOSE (PUSH)
 Clean screens
 SUIT RET AIR vlv - OPEN (PULL)
 CABIN FANS (both) - on

SYSTEMS MANAGEMENT

 Basic Date: Nov. 6, 1968
 Changed: Dec. 4, 1968

SM 103

CSM 103

- 4 POTABLE WATER CHLORINATION
 Unstow chlorination unit
 Remove chlor port cap
 Attach needle assembly to injection port
 Insert chlorine ampoule into casing
 Connect knob assembly & rotate (CW) until
 piston contacts ampoule
 Install ampoule assembly on needle assembly
 (push & turn CW)
 Rotate knob (CW) until ampoule is empty
 (3 turns for half empty if H2O qty <50%)
 Disconnect ampoule assembly from needle assembly
 Rotate knob CCW & stow used ampoule
 Repeat above steps with buffer ampoule
 Replace chlor port cap
 Stow chlorination unit
 Do not drink for 30 min
 PGA MODE CHANGES
- POT H2O - OPEN
 Wait 10 min.
 Remove 2 ampoules of H2O
- 1 DOFFING PGA
 EMER CABIN PRESS vlv - BOTH
 SUIT RET AIR vlv - OPEN (PULL)
 Install hose screen on return hose
 PWR - OFF
 SUIT PWR - OFF for disconnect
 Audio CONT - NORM
 Don lt wt hdsets
 SUIT PWR - ON
 PWR - AUDIO/TONE
 SUIT FLOW vlv - CABIN FLOW (unsuited)
- 2 DONNING PGA
 SUIT PWR - OFF for comm cable connect
 PWR - OFF
 AUDIO CONT - NORM
 Connect supply and return hoses to PGA
 Connect COMM control head to PGA
 SUIT FLOW vlv - FULL FLOW (suited)
 SUIT RET AIR vlv - CLOSED (PUSH)
 EMERG CABIN PRESS vlv - OFF
- 3 PARTIAL SUIT CKLIST
 EMER CAB PRESS vlv - BOTH
 SUIT CKT RET vlv - OPEN (Pull)
 Reverse 02 umbilicals

4 DISCONNECTING COMM UMBILICAL

Before disconnecting umbilical from head set:

SUIT PWR - OFF
POWER - OFF
AUDIO CONT - NORM

5 SUIT CKT INTEGRITY CK

DIRECT O2 vlv - CLOSE (CW)
SUIT PRESS - 4.8-5.2 psia
O2 FLOW - 0.2-0.4 lb/hr
SUIT TEST vlv - PRESS
O2 FLOW - 1.0 lb/hr (pegged)
O2 FLOW HI lt - ON
M/A - ON, Reset
SUIT PRESS - 8.9-9.7 psia
PGA PRESS (3) - 4.1-4.5 psig
O2 DEMAND REG vlv - OFF
O2 FLOW - 0.2 lb/hr (pegged)
O2 FLOW HI lt - OFF
PGA PRESS (3) - 0.5 psi/min decay
O2 DEMAND REG vlv - Both (O2 flow inc)
SUIT TEST vlv - DEPRESS
O2 FLOW - 0.2-0.4 lb/hr
SUIT PRESS - slightly > CAB PRESS
SUIT TEST vlv - OFF

6 PGA INTEGRITY CK

DIRECT O2 vlv - CLOSE (CW)
SUIT PRESS - 4.8-5.2 psia
O2 FLOW - 0.2-0.4 lb/hr
SUIT TEST vlv - PRESS
O2 FLOW - 1.0 lb/hr (pegged)
O2 FLOW HI lt - ON
M/A - ON, Reset
SUIT PRESS - 8.9-9.7 psia
PGA PRESS (3) - 4.1-4.5 psig
SUIT FLOW vlv - OFF
MONITOR For 0.5 psi/min decay
SUIT FLOW vlv - SUIT FULL FLOW
SUIT TEST vlv - DEPRESS
O2 FLOW HI lt - OFF
O2 FLOW - 0.2-0.4 lb/hr
SUIT PRESS - slightly > CAB PRESS
SUIT TEST vlv - OFF

CABIN ATMOS MODE CHANGES

1 CM PRESSURE DUMP

EMER CABIN PRESS vlv - OFF (verify)
CAB REPRESS vlv - OFF (verify)
SUIT RTN AIR vlv - CLOSED (verify)
CABIN FANS (both) - OFF
DIR O2 vlv - CLOSE (CW)
CAB PRESS REL vlv (RH) - DUMP (latch off)
CABIN PRESS - 3.0-3.25 psia
CAB PRESS REL vlv (RH) - BOOST ENTRY
O2 FLOW - 0.24 lb/hr
SUIT PRESS - 3.5-4.0 psia
CAB PRESS REL vlv - (RH) - DUMP
CABIN PRESS - 0.0 psia
CAB PRESS REL vlv (both) - NORMAL (latch on)

2 CABIN REPRESS (NORM, 30 min)

CAB PRESS REL vlv (both) - NORMAL (latch on)
MONITOR SURGE TANK PRESS
PLSS vlv - FILL
REPRESS O2 vlv - OPEN
AT 150 psia ON SURGE TANK:
PLSS vlv - OFF
CABIN REPRESS vlv - ADJUST TO 150 psia on SURGE TK

AT ZERO psia on EMERG O2 GAUGE:

REPRESS O2 vlv - CLOSE
CAB REPRESS vlv - OPEN (CW)
WHEN CABIN PRESS = 4.7-5.3
CAB FAN (both) - ON
O2 PRESS ind - TANK 1
CAB REPRESS - CLOSE (CW)

- 3 CABIN REPRESS (ALT, 52 min)
 CAB PRESS REL vlv (both) - NORMAL (Safety latch on)
 EMER CAB PRESS vlv - BOTH
 CAB REPRESS vlv - OPEN (CW)
 MONITOR SURGE TANK PRESS
 AT 150 psia on SURGE TANK:
 EMER CAB PRESS vlv - OFF
 CAB REPRESS vlv - Adj to 150 psia on SURGE TANK
 WHEN CAB PRESS \geq 4.7
 CAB FAN (both) - ON
 O2 PRESS IND - TANK ;
 CAB REPRESS vlv - CLOSE (CCW)

- 4 CM O2 SUPPLY REFILL *after cabin dump*
 SURGE TANK PRESS \geq 500 psia
 CAB REPRESS vlv - CLOSE (CCW)
 REPRESS O2 vlv - CLOSE
 PLSS vlv - FILL
 SURGE TANK PRESS - 865-935 psia
 O2 PRESS IND - TANK 1
 PLSS vlv - OFF

- 5 O2 TOP OFF for ENTRY
 SURGE TANK vlv - ON (verify)
 REPRESS O2 vlv - ON until:
 TANK PRESS = CRYS PRESS - 50
 REPRESS O2 vlv - OFF

WASTE MANAGEMENT PROCEDURES

- 1 VERIFICATION OF CLEAR URINE VENT LINE
URINE DUMP HTR - ON (verify)
 Waste storage vent vlv - open 5 sec - then closed
 Batt vent vlv - open
 Systems test ind 4A -
 Monitor Batt Manif Press 0
 Batt Vent vlv - Close
 SYS TEST - 4B if desired
 Pressure not 0 or Decay to 0 - Line not clear -
 Use Side Hatch Water/Urine Dump Procedure
 pg S-15
- 2 PGA URINE COLL BAG DUMP
 Connect Urine transfer hose & filter
 to urine feces QD.
 Connect urine transfer hose to thigh OP
 Waste mgt drain vlv - dump until bag empty
 Disconnect urine transfer hose from PEA
 Replace cap on PEA
 Install vacuum fit in to UT Hose
 Purge dump line 30 sec
 Waste mgt onbd drain off
- 3 UTS (Collection)
 Obtain UTS & verify vlv - Closed
 Attach UTS - open vlv - Perform task
 UTS vlv - Closed & disconnect
- 4 UTS/VACUUM (Dump)
 Verify vent line clear
 Connect UT hose/filter to urine/Feces QD
 Attach UTSVACUUM to hose
 Waste mgt ovbd drain - DUMP
 UTS vlv - OPEN (If UTS DUMP)
 Purge lines 30 sec
 Waste mgt ovbd drain - OFF

Basic Date - Nov. 6, 1968
 Changed

CSM 103

Basic Date - Nov. 6, 1968
 Changed

CSM 103

5 WASTE WATER TANK DRAIN

Used as req to maintain water level
between 25 & 85%

UR DUMP HTR - ON (verify)

Verify Urine Vent Line Clear-(Step 1A Above)

Attach Hose/Filter to Urine/Feces QD
Waste Tank SVC vlv - CLOSED
Remove WASTE TANK SVC PLUG (tool L)
Install Female QD to waste tank SVC port
Attach Hose to QD on Waste Water Panel

Waste Mgt Drain - DUMP
Waste Tank SVC vlv - OPEN
Monitor waste tank decreasing qty
Monitor potable tank quantity stable
At approximately 25% - Waste Tank SVC vlv -
CLOSED

Detach UT hose at Waste Tank QD
Install UTS or vacuum fitting on UT hose
Purge 30 sec
Ovbd drain - close
Detach & stow

6 SIDE HATCH URINE/WATER DUMP

Remove Dump Nozzle Conn Cover
Remove Plug & Stow
Withdraw Wire Guard & Wires from Slot
Install Male QD on Dump Nozzle
Connect cable to heater connector
Util Pwr - off
Connect cable to utility outlet
Util Pwr - on (wait 1 hr before dumping)
Connect Urine Dump Hose to Dump Nozzle QD
Connect other end of UT hose to UTS/
Waste Servicing Tank (See Step 5 for
waste water dump)
Dump Waste Water/Urine
Disconnect UT hose from UTS/Waste Servicing
Tank and Purge
Disconnect UT Hose from Dump Hozzle & stow
Util Pwr - off
Disconnect Cable from heater & outlet & stow
Install plug & dump nozzle connector

- 7 WATER COLLECTION WITH SUIT HOSE
 If collecting more than 1/2 pint H₂O,
 remove CO₂ Absorber Filter from
 canister A (or B) & replace cover.
 CO₂ Cstr Divert vlv - Both (Ctr)
 (until interlock pin is engaged)
 CO₂ Cstr Divert vlv - A (or B)
 (flows through empty canister)
 Begin water collection
 Monitor part CO₂ Press ind -
 <7.6mm Hg (during time flow is
 through empty canister)
 Complete water collection
 allow 1 min add flow
 Return CO₂ absorber canister
 to original configuration.

CABIN COLD SOAK

- 1 ACTIVATE
 SUIT HT EXCH SEC GLY vlv - FLOW
 EVAP H₂O CONT SEC vlv - AUTO
 GLY TO RAD SEC vlv - BYPASS
 CAB TEMP - MAN
 PRIM CAB TEMP vlv - C (CW)
 SEC CAB TEMP vlv - OFF (CCW)
 SUIT CKT HT EXCH - BYPASS (20sec), then OFF
 ECS IND - SEC
 SEC COOL LOOP PUMP - AC1
 GLY DISCH SEC PRESS - 39-51 psig
 SEC ACCUM QTY - 30-55%
 SEC COOL LOOP EVAP - EVAP
 SEC GLY EVAP OUT TEMP - 40-50.5°F
 SEC GLY EVAP STM PRESS -
 0.1-0.15 psia, >.16 not boiling
 ECS IND - PRIM
 PRIM ECS RAD OUT TEMP >-20°F

If <-20°F, deactivate

- 2 DEACTIVATE
 SEC CAB TEMP vlv - COOL MAX (CW)
~~PRIM CAB TEMP - AUTO~~
 SUIT CKT HT EXCH - ON (20 sec), then OFF
 SEC COOL LOOP EVAP - RESET 58 sec, min,
 then OFF
 SEC COOL LOOP PUMP - OFF
 EVAP H₂O CONT SEC vlv - OFF (AUTO for ENTRY)

C&WS OPER CK

- C/W LAMP TEST - 1 (hold)
 M/A Pnl 1 - ON
 LH C/W lts (16) - ON
 C/W LAMP TEST - 2 (hold)
 M/A Pnl 1 - OFF
 LH C/W lts (16) - OFF
 M/A Pnl 3 - ON
 RH C/W lts (23) - ON
 C/W LAMP TEST - OFF (lts OFF)
 C/W CSM - CM
 CM RCS lt (both) - ON
 M/A Tone & Lts (3) - ON, RESET
 M/A Tone & Lts (3) - OFF
 C/W CSM - CSM
 CM RCS lts (both) - OFF

Nov. 6, 1968

Basic Date
Changed

Nov. 6, 1968

Basic
Change

Nov. 27, 1968

CSM-103

CSM-103

SYSTEMS TEST METER READOUTS

Systems Test Meter Display	N ₂ , O ₂ , H ₂ Pressure (PSIA)	EPS Radiator Outlet Temperature (°F)	CM-RCS Oxidizer Valve Temperature (°F)	LM Power (Amps)	SPS Temperature (°F)	Battery Manifold Pressure (PSIA)	Battery Relay Bus (VDC)
0.0	0	-50	-50	0	0	0.00	0
0.2	3	-36	-46	0.4	8	0.72	1.8
0.4	6	-22	-42	0.8	16	1.44	3.6
0.6	9	-8	-38	1.2	24	2.16	5.4
0.8	12	+6	-34	1.6	32	2.88	7.2
1.0	15	+20	-30	2.0	40	3.60	9.0
1.2	18	+34	-26	2.4	48	4.32	10.8
1.4	21	+48	-22	2.8	56	5.04	12.6
1.6	24	+62	-18	3.2	64	5.76	14.4
1.8	27	+76	-14	3.6	72	6.48	16.2
2.0	30	+90	-10	4.0	80	7.20	18.0
2.2	33	+104	-6	4.4	88	7.92	19.8
2.4	36	+118	-4	4.8	96	8.64	21.6
2.6	39	+132	0	5.2	104	9.36	23.4
2.8	42	+146	+4	5.6	112	10.08	25.2
3.0	45	+160	+10	6.0	120	10.80	27.0
3.2	48	+174	+14	6.4	128	11.52	28.8
3.4	51	+188	+18	6.8	136	12.24	30.6
3.6	54	+202	+22	7.2	144	12.96	32.4
3.8	57	+216	+26	7.6	152	13.68	34.2
4.0	60	+230	+30	8.0	160	14.40	36.0
4.2	63	+244	+34	8.4	168	15.12	37.8
4.4	66	+258	+38	8.8	176	15.84	39.6
4.6	69	+272	+42	9.2	184	16.56	41.4
4.8	72	+286	+46	9.6	192	17.28	43.2
5.0	75	+300	+50	10.0	200	18.00	45.0

103

Basic Date Nov. 6, 1968
Changed Nov. 27, 1968

CSM 103

Basic Date Nov. 6, 1968
Changed Nov. 6, 1968

TELECOMM PROCEDURES

HI-GAIN ANTENNA OPERATION

cb HI-GAIN ANT FLT BUS - closed
 cb HI-GAIN ANT ac GRP 2 - closed
 HI-GAIN ANT TRACK - MAN
 HI-GAIN ANT SERVO ELEC - PRIM
 HI-GAIN ANT BEAM - WIDE
 HI-GAIN ANT PWR - POWER
 Go to V64 START S-BAND ANTENNA procedures
 Verify required coordinates within full coverage region

*If required coordinates are in scan limit zone or skin reflection zone, one or more of the following may be done:

- Change CSM attitude to provide antenna coordinates in the full coverage region
- Allow up to 60 seconds for the expected CSM attitude variation to alleviate the condition

c. In attitude hold condition, operate in wide beam mode

d. Switch to narrow beam and acquire manually

HI-GAIN ANT PITCH & YAW POS (2) - Set in required coordinates

*If in earth orbit, S-BD NORM PWR AMPL HI-off(ctr)
 S-BD ANT OMNI - HI-GAIN

HI-GAIN ANT S-BD ANT ind - >1/2 scale

HI-GAIN ANT TRACK - AUTO or REACQ

HI-GAIN ANT BEAM - as required depending on range

HI-GAIN ANT S-BD ANT ind - >1/2 scale

CAUTION

HI-GAIN ANT TRACK-MAN when omni antenna operation is selected to prevent damage to the HGA due to jitter.

TV CAMERA OPERATION

Unstow camera, lens, and cables

S-BD AUX TV - OFF

Connect power and RF cables

Install proper lens

(telephoto out of focus at < 143 ft)

(wide angle out of focus at < 18 in)

S-BD AUX TV - TV

ALC (camera) - IN (normally)

OUT (when detail on dim objects
in presence of bright objects
is desired)

Power (camera) - ON

When TV operation is completed -

Power (camera) - OFF

S-BD AUX TV - off (center)

Disassemble and stow equipment as desired


Basic Date Nov. 6, 1968
Changed

Basic Date Nov. 6, 1968
Changed


CSM-103

CSM-103

ANTENNA POSITIONS




RCS ENG VENT



RCS Engine, Vent, and Radiator Location

CSM-103

Basic Date Nov. 6, 1968
 Changed _____



SM RCS propellant profile.

PREDICTED SM-RCS PROPELLANT TRANSLATION COST (CSM-103)

Spacecraft Weight (lbs)	$\pm X$ 4 Jet PGNC (lb/fps)	$\pm X$ 4 Jet SCS (lb/fps)	+X 2 Jet AC PGNC (lb/fps)	+X 2 Jet AC SCS* (lb/fps)	+X 2 Jet BD PGNC (lb/fps)	+X 2 Jet BD SCS** (lb/fps)	$\pm Y$ or $\pm Z$ PGNC (lb/fps)
63600 (Translunar)	7.3	9.1	7.6	9.1	8.0	9.1	9.7
46200 (Lunar Orbit)	5.3	6.4	5.6	6.4	5.7	6.5	6.5
32200 (Transearth)	3.6	4.3	3.5	4.3	4.0	4.3	4.2

* Jets 3 and 4 disabled (A3, C4)

** Jets 7 and 8 disabled (B3, D4)

Minimum impulse control ≈ 0.005 lb/pulse

EMERGENCY PROCEDURES

FIRE/SMOKE IN CM (CREW SUITED)

- 1 CAB FAN (both) - OFF
- 2 Monitor EPS for excessive current and remove power from affected bus
- 3 Verify suit compressor on good AC BUS
- 4 Use fire extinguisher as appropriate

FIRE IS OUT

- 5 Remove smoke from cabin per "Contamination in CM" procedures before removing helmets

FIRE PERSISTS - DUMP CABIN

- 6 Verify:
 - SUIT CKT RET vlv - PUSH TO CLOSE
 - EMER CAB PRESS vlv - OFF
 - O2 PLSS vlv - OFF
- 7 Visually check suit integrity
- 8 CAB PRESS RELF (RH) - DUMP to 3.0 psia
then to BOOST ENTRY
REMARK: Provides controlled cabin dump until
suit circuit pressure is verified
- 9 Verify Suit pressure > 3.5 psia
- 10 CAB PRESS RELF (RH) - DUMP
and/or Hatch Vent vlv - open
- 11 CAB PRESS ind 0.0 psia for 6 min
- 12 CAB PRESS RELF (RH) - NORMAL
- 13 Hatch Vent vlv - close
- 14 Do not repress cabin until fire source is removed

FIRE/SMOKE IN CM (CREW UNSUITED)

- 1 CAB FAN (both) - OFF
- 2 SUIT COMPR (both) - OFF
- 3 Monitor EPS for excessive current and remove power from affected bus
- 4 Don emergency O2 masks
- 5 Use fire extinguishers as appropriate

FIRE IS OUT

- 6 Remove smoke from cabin per "Contamination in CM" procedure before removing O2 masks

FIRE PERSISTS - DON SUITS and DUMP CABIN

- 7 Don PGA's except helmets and verify O2 connectors (Use O2 masks as long as possible)
- 8 DIRECT O2 vlv - OPEN (CCW)
REMARK: Purges suit circuit of smoke and fumes
- 9 Don helmet
- 10 Suit flow vlv (3) - SUIT FULL FLOW
- 11 SUIT COMPR 1 (2) - AC1 (AC2)
- 12 DIRECT O2 vlv - CLOSE (CW)
- 13 EMER CAB PRESS vlv - OFF
- 14 Visually check suit integrity

SYSTEMS MANAGEMENT

EMERGENCY

CSM-103

Basic Date Nov. 6, 1968
Changed

Nov. 6, 1968

Changed

- 15 CAB PRESS RELF (RH) - DUMP to 3.0 psia
then to BOOST ENTRY
- 16 Verify Suit pressure holding >3.5 psia
- 17 CAB PRESS REL (RH) - DUMP
and/or Hatch Vent vlv - open
- 18 CAB PRESS ind 0.0 psia for 6 min.
- 19 CAB PRESS RELF (RH) - NORMAL
- 20 Hatch Vent vlv - close
- 21 Do not repress cabin until fire source is removed

103

Contamination in CM

- 1 Don O2 masks and/or PGA's immediately
- 2 Evaluate contamination level (isolate & correct source of contamination if possible) and proceed with one of the following steps:
 - a. Retain O2 masks or remain in suit and accept contamination level in cabin.

CAUTION

If in PGA's, adjust DIRECT O2 to maintain suit to cabin $\Delta P > 0.38$ psi.

- b. Retain O2 masks and scrub cabin atmosphere through suit loop. If initially suited, establish partially suited or shirtsleeve configuration and don O2 masks.

CAUTION

Change LiOH cartridges after scrub completed.

- c. Retain PGA's or don PGA's
Verify suit integrity (visually)
Perform Cabin Dump
Perform Cabin Repress

Contamination In Suit

- | | | |
|---|---|---|
| 1 | SUIT COMPR 2 - AC1 | 4 |
| 2 | SUIT COMPR 1 - OFF | |
| 3 | DIRECT O2 vlv - OPEN (CCW) for 1 minute then close (CW) | 7 |

If condition persists:

- | | |
|---|------------------------|
| 4 | SUIT COMPR 2 - OFF |
| 5 | DIRECT O2 vlv - OFF |
| 6 | Doff helmet |
| 7 | Don emergency O2 masks |

EMERGENCY POWER DOWN

NOTE: Use only after FC or BATT loss, no short verified, & main bus voltage < 26.0 VDC.

Powerdown the following components until til bus voltage ≥ 26.5 VDC:

O2 HTRS(both)-OFF	11.0amps
NONESS BUS-OFF	4.9
FLT QUAL RCDR-OFF	.74
GMBL MTRS(4) - OFF/ON	20.0
MN A&B BAT C cb(both)-Close	-
ECS RAD HTRS PRIM & SEC-OFF	17.3
FC PUMPS (3)-OFF	3.0ea
SM RCS HTRS A,B,C&D-OFF	2.86ea
POT H2O HTR-OFF	1.6
H2 HTRS (both)-OFF	1.44
CAB FANS(both)-OFF	1.94
SPS LINE HTR-OFF	1.03ea
LIGHTS - Min reqd	-
CMC To STBY	
V48E	
F04 46 Load 0 Left digit R1	
PRO,PRO,PRO, V46E	
F 50 25 00062 CMC PWR ON	
PRO-HOLD until STBY Lt On	
G&N PWR DN (STBY)	
CMC MODE - FREE	
G&N IMU PWR-OFF	
S-Bd PWR AMP-OFF	3.53
TAPE RCDR-OFF	
GLY/EVAP STM PRESS-MAN	
STM PRESS-INCR(58sec)	
H2O FLOW-OFF.	
TEMP IN-MAN	2.77ea
ECS GLY PUMPS - OFF	
SEC COOL LOOP EVAP -RESET(58sec)	
PUMP -OFF	2.69
ECS RAD CONT/HTR cb(both)-OPEN	

SYSTEMS MANAGEMENT

EMERGENCY

Basic Date: Nov. 6, 1968
Changed

Basic Date: Nov. 6, 1968
Changed

C-103

EMERGENCY POWER DOWN (CONT)

PWR SCE-OFF .65
 VHF(both)-OFF
 HGA PWR-OFF
 TELECOM GRP 1&2
 CONFIG for single inverter-Open
 INSTRUM ESS MN A&B cb(both)OPEN 5.54
 SUIT COMPR(both)-OFF
 DIR 02-ON(If Suited) -

UNACCEPTABLE VEHICLE DYNAMICS DURING CRITICAL SPS THRUSTING

- 1 THC - CW
- 2 DAMP RATES USING RATE NEEDLES
- 3 CHECK FDAI #1 ATTITUDE: If attitude and error needles are not steady use FDAI #2 to return to desired burn attitude.
- 4 If above fails - with small divergence attempt rolling vehicle to cancel errors.

PREMATURE SPS SHUTDOWN DURING CRITICAL BURN

- 1 SPS THRUST DIRECT SW - ON
- 2 CHECK ΔV THRUST A/B - ON
- 3 CHECK SPS PILOT vlvs and SPS Helium vlv CB's CLOSED (PNL 8)
- 4 CHECK EPS GRP 3 & 5 CB's CLOSED (PNL 229)
- 5 FCSM (2) - RESET/OVERRIDE
- 6 SPS He vlv (2) - ON
- 7 S/C CONT - SCS
- 8 SCS TVC - AUTO
- 9 THRUST - ON

SPS ENGINE DOES NOT SHUTDOWN AUTOMATICALLY

- 1 ΔV THRUST A/B - OFF
- 2 THC - CW
- 3 CHECK SPS DIRECT ON - OFF
- 4 SPS PILOT vlv (2) CB's - OPEN (PNL 8)
- 5 EPS Group 5 CB's - OPEN (PNL 229)

Basic Data
 Nov. 6, 1968
 Dec. 17, 1968

Basic Data
 Nov. 6, 1968
 Dec. 17, 1968
 Changed

SPS FLANGE TEMP LIGHT DURING LOI₁ BURN

- 1 If <120 sec, shutdown and perform Mode I 15 min abort
- 2 If >120 sec, shutdown

SPS PRESSURE LIGHT ON DURING CRITICAL BURN

- 1 Pressure high - SPS He vlv (2) - OFF
- 2 Pressure low
 - a. SPS He vlv (2) - ON
 - b. If pressure does not increase - Except during TEI

SM RCS THRUSTER FAILED - ON

- 1 SC CONT to Alternate Source
- 2 ROT CONTR PWR DIRECT(both)-MN A/B (Control Rates In Direct)
- 3 AUTO RCS SEL - OFF (In Affected Axis)
- 4 DIRECT Ullage cl(both)- Open
- 5 If vehicle rates are still uncontrolled:
 - a. AUTO RCS SEL (16) - ON
 - b. MAN ATT(3)-ACCEL CMD
 - c. ROT CONTR PWR DIRECT (both)-OFF
- 6 If rates are still uncontrolled: SM RCS Prplnt - OFF

FC 1(2)(3) LIGHT ON DUE TO PH H1 tb-bp

- 1 FC 1(2)(3) PUMPS - OFF
- 2 POTABLE TANK INLET vlv - CLOSE

MN BUS A(B) UNDERVOLT LIGHT ON

- 1 Check pertinent bus voltage
- 2 If only one bus low and high current isolate & reconfig
- 3 If both busses low use powerdown cklist, pg 5 EMG-5.

AC BUS 1(2) LIGHT ON WITH MN BUS A(B) UNDERVOLT AND/OR BUS 1(2) OVERLOAD

Turn OFF associated inverter within 5 sec

CABIN PRESSURE <5psia AND DECREASING

- 1 CABIN PRESSURE REL vlv(both)-CLOSED
- 2 Don PGA's - unstow O₂ masks if not 100% O₂ atmosphere

O₂ HI LIGHT ON - CABIN PRESSURE NORMAL OR HIGH

- 1 Check O₂ flow ind - if not pegged isolate C&W or ind failure by turning on DIRECT O₂ valve moment.
- 2 If O₂ flow ind is pegged, check for low surge tank press. If cryo tank - surge tank ΔP <50psi the flow sensor has failed
- 3 With low surge tank - MAIN REG A&B-CLOSED

SUIT COMPRESSOR FAILS WHILE SUITED

- 1 Select redund suit compr on alt AC bus
- 2 At critical time turn on DIRECT O₂ valve
- 3 When feasible, remove helmets

H₂ or O₂ FC FLOW HIGH

- 1 Check O₂ & H₂ Flow Rates
 - 2 If one is High, cycle approp purge valve several times
- CAUTION: If H₂ flow is high turn on H₂ purge line htr before cycling purge valve

PRIM EVAP OUT TEMP HIGH (APPROACHING 60°)

- 1 ECS IND SEL - SEC
- 2 SEC COOL LOOP PUMP - AC1 or AC2
- 3 SEC COOL LOOP EVAP Sw - EVAP

Basic Data
Nov. 6, 1968
Dec. 17, 1968