

EVA Checklist

STS-119 Flight Supplement

**Mission Operations Directorate
EVA, Robotics, and Crew Systems
Operations Division**


**Final, Rev A
January 23, 2009**

NOTE

This supplement is to be integrated into the generic edition to provide a complete document for the specific flight. Some pages in the generic edition may be replaced with supplemental pages identified as 'TEMP'. These generic pages, if any, must be retained for use on future flights.

National Aeronautics and
Space Administration

Lyndon B. Johnson Space Center
Houston, Texas



MISSION OPERATIONS DIRECTORATE

**EVA CHECKLIST
STS-119 FLIGHT SUPPLEMENT**


FINAL, REVISION A
January 23, 2009

PREPARED BY:



Glenda S. Brown
Book Manager


APPROVED BY:



Tomas L. Gonzalez-Torres
Lead, EVA Systems Group



Dina E. Contella
Lead, EVA Task Group



Angela R. Prince
Chief, EVA Operations Branch

This document is under the configuration control of the Crew Procedures Control Board (CPCB). All proposed changes must be submitted via FDF Workflow Crew Procedure Change Request (CR) to DO3/FDF Manager.

Additional distribution of this book, for official use only, may be requested in writing to DO3/PMO Administrator. The request must include justification and requester's name, organization, position, and phone number. Contractor requests are made through the NASA or DOD organization supported. Deletions, reduction in quantity, or change of address may be submitted to DO3/FDF Management Office, 281-244-1184.

Incorporates the following:			
482#:	EVA FS-0215	EVA FS-0227	MULTI-1762
	EVA FS-0216	EVA FS-0228	
	EVA FS-0217	EVA FS-0229	
	EVA FS-0218	EVA FS-0230	
	EVA FS-0219	EVA FS-0231	
	EVA FS-0220	EVA FS-0232	
	EVA FS-0221	EVA FS-0233	
	EVA FS-0222	EVA FS-0234	
	EVA FS-0223	EVA FS-0235	
	EVA FS-0224	EVA FS-0236	
	EVA FS-0225	EVA FS-0237	
	EVA FS-0226		

AREAS OF TECHNICAL RESPONSIBILITY

Book Manager

DX3/G. Brown

281-244-0131

EVA CHECKLIST
STS-119 FLIGHT SUPPLEMENT

LIST OF EFFECTIVE PAGES

FINAL 12/19/08
REV A 01/23/09

Sign Off	*	119/FIN A	3-3	generic
FS ii	*	119/FIN A	3-4	generic
iii	*	generic	3-5	generic
iv	*	generic	3-6	generic
FS v	*	119/FIN A	3-7	generic
FS vi	*	119/FIN A	3-8	generic
FS vii	*	119/FIN A	3-9	generic
FS viii	*	119/FIN A	CC 3-10	generic
FS ix	*	119/FIN A	CC 3-11	generic
FS x	*	119/FIN A	3-12	generic
FS xi		119/FIN A	4-1	generic
FS xii		119/FIN A	4-2	generic
FS xiii		119/FIN A	4-3	generic
FS xiv		119/FIN A	4-4	generic
FS xv		119/FIN A	4-5	generic
FS xvi		119/FIN A	4-6	generic
FS xvii		119/FIN A	4-7	generic
FS xviii		119/FIN A	4-8	generic
1-1		generic	4-9	generic
1-2		generic	4-10	generic
1-3		generic	4-11	generic
1-4		generic	4-12	generic
1-5		generic	5-1	generic
1-6		generic	5-2	generic
1-7		generic	5-3	generic
1-8		generic	5-4	generic
1-9		generic	A6-1	generic
1-10		generic	CC A6-2	generic
TEMP FS 2-1		119/FIN A	6-3	generic
TEMP FS 2-2		ALL/FIN A	CC 6-4	generic
2-3		generic	FS 7-1	119/FIN A
2-4		generic	FS 7-2	119/FIN A
TEMP FS 2-5		119/FIN A	FS 7-3	119/FIN A
TEMP FS 2-6		ALL/FIN A	FS 7-4	119/FIN A
FS 2-7		119/FIN A	FS 7-5	119/FIN A
FS 2-8		119/FIN A	FS 7-6	119/FIN A
FS 2-9		119/FIN A	FS 7-7	119/FIN A
FS 2-10		119/FIN A	FS 7-8	119/FIN A
FS 2-11		119/FIN A	FS 7-9	119/FIN A
FS 2-12		119/FIN A	FS 7-10	119/FIN A
FS 2-13		119/FIN A	FS 7-11	119/FIN A
FS 2-14		119/FIN A	FS 7-12	119/FIN A
FS 2-15		119/FIN A	FS 7-13	⊗ 119/FIN A
FS 2-16		119/FIN A	FS 7-14	⊗ 119/FIN A
FS 2-17		119/FIN A	FS 7-15	119/FIN A
FS 2-18		119/FIN A	FS 7-16	119/FIN A
3-1		generic	FS 7-17	⊗ 119/FIN A
3-2		generic	FS 7-18	⊗ 119/FIN A

* – Omit from flight book

⊗ – Flight copies of this page contain color

FS 7-19	119/FIN A	FS 7-75	119/FIN A
FS 7-20	119/FIN A	FS 7-76	⊗ 119/FIN A
FS 7-21	119/FIN A	FS 7-77	119/FIN A
FS 7-22	119/FIN A	FS 7-78	⊗ 119/FIN A
FS 7-23	119/FIN A	FS 7-79	119/FIN A
FS 7-24	⊗ 119/FIN A	FS 7-80	119/FIN A
FS 7-25	⊗ 119/FIN A	FS 7-81	119/FIN A
FS 7-26	119/FIN A	FS 7-82	⊗ 119/FIN A
FS 7-27	119/FIN A	FS 7-83	⊗ 119/FIN A
FS 7-28	⊗ 119/FIN A	FS 7-84	119/FIN A
FS 7-29	119/FIN A	FS 7-85	119/FIN A
FS 7-30	119/FIN A	FS 7-86	119/FIN A
FS 7-31	119/FIN A	FS 7-87	△ 119/FIN A
FS 7-32	119/FIN A	FS 7-88	△ 119/FIN A
FS 7-33	⊗ 119/FIN A	FS 7-89	⊗ 119/FIN A
FS 7-34	119/FIN A	FS 7-90	119/FIN A
FS 7-35	⊗ 119/FIN A	FS 7-91	119/FIN A
FS 7-36	119/FIN A	FS 7-92	119/FIN A
FS 7-37	119/FIN A	FS 7-93	119/FIN A
FS 7-38	119/FIN A	FS 7-94	119/FIN A
FS 7-39	⊗ 119/FIN A	FS 7-95	119/FIN A
FS 7-40	⊗ 119/FIN A	FS 7-96	119/FIN A
FS 7-41	⊗ 119/FIN A	FS 7-97	119/FIN A
FS 7-42	119/FIN A	FS 7-98	⊗ 119/FIN A
FS 7-43	119/FIN A	FS 7-99	⊗ 119/FIN A
FS 7-44	119/FIN A	FS 7-100	119/FIN A
FS 7-45	⊗ 119/FIN A	FS 7-101	119/FIN A
FS 7-46	119/FIN A	FS 7-102	119/FIN A
FS 7-47	⊗ 119/FIN A	FS 7-103	119/FIN A
FS 7-48	119/FIN A	FS 7-104	119/FIN A
FS 7-49	119/FIN A	FS 7-105	119/FIN A
FS 7-50	119/FIN A	FS 7-106	⊗ 119/FIN A
FS 7-51	△ 119/FIN A	FS 7-107	⊗ 119/FIN A
FS 7-52	△ 119/FIN A	FS 7-108	119/FIN A
FS 7-53	119/FIN A	FS 7-109	119/FIN A
FS 7-54	119/FIN A	FS 7-110	⊗ 119/FIN A
FS 7-55	119/FIN A	FS 7-111	⊗ 119/FIN A
FS 7-56	119/FIN A	FS 7-112	⊗ 119/FIN A
FS 7-57	119/FIN A	FS 7-113	119/FIN A
FS 7-58	119/FIN A	FS 7-114	⊗ 119/FIN A
FS 7-59	119/FIN A	FS 7-115	⊗ 119/FIN A
FS 7-60	119/FIN A	FS 7-116	119/FIN A
FS 7-61	119/FIN A	FS 7-117	⊗ 119/FIN A
FS 7-62	⊗ 119/FIN A	FS 7-118	⊗ 119/FIN A
FS 7-63	⊗ 119/FIN A	FS 7-119	⊗ 119/FIN A
FS 7-64	119/FIN A	FS 7-120	⊗ 119/FIN A
FS 7-65	⊗ 119/FIN A	FS 7-121	119/FIN A
FS 7-66	119/FIN A	FS 7-122	119/FIN A
FS 7-67	⊗ 119/FIN A	FS 7-123	⊗ 119/FIN A
FS 7-68	⊗ 119/FIN A	FS 7-124	119/FIN A
FS 7-69	119/FIN A	FS 7-125	⊗ 119/FIN A
FS 7-70	⊗ 119/FIN A	FS 7-126	⊗ 119/FIN A
FS 7-71	119/FIN A	FS 7-127	⊗ 119/FIN A
FS 7-72	119/FIN A	FS 7-128	⊗ 119/FIN A
FS 7-73	⊗ 119/FIN A	FS 7-129	⊗ 119/FIN A
FS 7-74	119/FIN A	FS 7-130	⊗ 119/FIN A

⊗ – Flight copies of this page contain color

△ – Tear-out page

FS 7-131	⊗	119/FIN A	FS 7-187	⊗	119/FIN A
FS 7-132	⊗	119/FIN A	FS 7-188	⊗	119/FIN A
FS 7-133		119/FIN A	TEMP FS 8-1		119/FIN A
FS 7-134	⊗	119/FIN A	TEMP FS 8-2		119/FIN A
FS 7-135	⊗	119/FIN A	TEMP FS 8-2a		119/FIN A
FS 7-136		119/FIN A	TEMP FS 8-2b		119/FIN A
FS 7-137		119/FIN A	8-3		generic
FS 7-138		119/FIN A	8-4		generic
FS 7-139	Δ	119/FIN A	8-5		generic
FS 7-140	Δ	119/FIN A	8-6		generic
FS 7-141		119/FIN A	8-7		generic
FS 7-142		119/FIN A	8-8		generic
FS 7-143		119/FIN A	FS 8-9		119/FIN A
FS 7-144		119/FIN A	FS 8-10	⊗	119/FIN A
FS 7-145		119/FIN A	FS 8-11		119/FIN A
FS 7-146		119/FIN A	FS 8-12		119/FIN A
FS 7-147		119/FIN A	FS 8-13		119/FIN A
FS 7-148		119/FIN A	FS 8-14		119/FIN A
FS 7-149		119/FIN A	FS 8-15	⊗	119/FIN A
FS 7-150	⊗	119/FIN A	FS 8-16	⊗	119/FIN A
FS 7-151	⊗	119/FIN A	FS 8-17	⊗	119/FIN A
FS 7-152		119/FIN A	FS 8-18		119/FIN A
FS 7-153		119/FIN A	9-1		generic
FS 7-154	⊗	119/FIN A	9-2		generic
FS 7-155		119/FIN A	9-3		generic
FS 7-156	⊗	119/FIN A	9-4		generic
FS 7-157	⊗	119/FIN A	9-5		generic
FS 7-158	⊗	119/FIN A	9-6		generic
FS 7-159		119/FIN A	TEMP FS 10-1		119/FIN A
FS 7-160		119/FIN A	TEMP FS 10-2		ALL/FIN A
FS 7-161		119/FIN A	10-3		generic
FS 7-162	⊗	119/FIN A	10-4		generic
FS 7-163		119/FIN A	10-4a		generic
FS 7-164		119/FIN A	10-4b		generic
FS 7-165	⊗	119/FIN A	10-5		generic
FS 7-166		119/FIN A	10-6		generic
FS 7-167		119/FIN A	10-7		generic
FS 7-168		119/FIN A	10-8		generic
FS 7-169	⊗	119/FIN A	10-9		generic
FS 7-170		119/FIN A	10-10		generic
FS 7-171		119/FIN A	10-11		generic
FS 7-172	⊗	119/FIN A	10-12		generic
FS 7-173	⊗	119/FIN A	10-13		generic
FS 7-174		119/FIN A	10-14		generic
FS 7-175		119/FIN A	FS CC 10-15		119/FIN A
FS 7-176		119/FIN A	FS CC 10-16	⊗	119/FIN A
FS 7-177	Δ	119/FIN A	11-1		generic
FS 7-178	Δ	119/FIN A	11-2		generic
FS 7-179		119/FIN A	11-3		generic
FS 7-180	⊗	119/FIN A	11-4		generic
FS 7-181		119/FIN A	12-i		generic
FS 7-182		119/FIN A	12-ii		generic
FS 7-183	⊗	119/FIN A	TEMP FS 12-1		119/FIN A
FS 7-184	⊗	119/FIN A	TEMP FS 12-2		ALL/FIN A
FS 7-185	⊗	119/FIN A	12-3		generic
FS 7-186	⊗	119/FIN A	12-4		generic

⊗ – Flight copies of this page contain color

Δ – Tear-out page

12-5	generic	15-5	generic
12-6	generic	15-6	generic
12-7	generic	15-7	generic
12-8	generic	15-8	generic
12-9	generic	15-9	generic
12-10	generic	15-10	generic
12-11	generic	15-11	generic
12-12	generic	15-12	generic
12-13	generic	15-13	generic
12-14	generic	15-14	generic
12-15	generic	16-i.....	generic
12-16	generic	16-ii.....	generic
12-17	generic	TEMP FS 16-1	119/FIN A
12-18	generic	TEMP FS 16-2.....	119/FIN A
12-19	generic	FS 16-3.....	119/FIN A
12-20	generic	FS 16-4.....	119/FIN A
12-21	generic	FS 16-5.....	119/FIN A
12-22	generic	FS 16-6.....	119/FIN A
12-23	generic	FS 16-7.....	119/FIN A
12-24	generic	FS 16-8.....	⊗ 119/FIN A
12-25	generic	FS 16-9.....	⊗ 119/FIN A
12-26	generic	FS 16-10.....	119/FIN A
FS CC 12-27	⊗ 119/FIN A	FS 16-11.....	119/FIN A
FS CC 12-28	119/FIN A	FS 16-12.....	119/FIN A
FS 12-29	⊗ 119/FIN A	FS 16-13.....	119/FIN A
FS 12-30	⊗ 119/FIN A	FS 16-14.....	119/FIN A
FS 12-31	⊗ 119/FIN A	FS 16-15.....	119/FIN A
FS 12-32	119/FIN A	FS 16-16.....	119/FIN A
FS 13-1	119/FIN A	FS 16-17.....	119/FIN A
FS 13-2	119/FIN A	FS 16-18.....	119/FIN A
14-1	generic	FS 16-19.....	119/FIN A
14-2	generic	FS 16-20.....	119/FIN A
14-3	generic	FS 16-21.....	119/FIN A
14-4	generic	FS 16-22.....	119/FIN A
14-5	generic	FS 16-23.....	119/FIN A
14-6	generic	FS 16-24.....	119/FIN A
14-7	generic	FS 16-25.....	⊗ 119/FIN A
14-8	generic	FS 16-26.....	⊗ 119/FIN A
14-9	generic	FS 16-27.....	⊗ 119/FIN A
14-10	generic	FS 16-28.....	⊗ 119/FIN A
14-11	generic	FS 16-29.....	⊗ 119/FIN A
14-12	generic	FS 16-30.....	⊗ 119/FIN A
14-13	generic	FS 16-31.....	⊗ 119/FIN A
14-14	generic	FS 16-32.....	⊗ 119/FIN A
14-15	generic	FS 16-33.....	⊗ 119/FIN A
14-16	generic	FS 16-34.....	⊗ 119/FIN A
14-17	generic	FS 16-35.....	⊗ 119/FIN A
14-18	generic	FS 16-36.....	⊗ 119/FIN A
14-19	generic	FS 16-37.....	⊗ 119/FIN A
14-20	generic	FS 16-38.....	⊗ 119/FIN A
14-21	generic	FS 16-39.....	⊗ 119/FIN A
14-22	generic	FS 16-40.....	⊗ 119/FIN A
15-1	generic	FS 16-41.....	⊗ 119/FIN A
15-2	generic	FS 16-42.....	119/FIN A
15-3	generic	FS 16-43.....	⊗ 119/FIN A
15-4	generic	FS 16-44.....	⊗ 119/FIN A

⊗ – Flight copies of this page contain color

FS 16-45	⊗	119/FIN A	FS 16-101		119/FIN A
FS 16-46	⊗	119/FIN A	FS 16-102	⊗	119/FIN A
FS 16-47	⊗	119/FIN A	FS 16-103	⊗	119/FIN A
FS 16-48	⊗	119/FIN A	FS 16-104	⊗	119/FIN A
FS 16-49	⊗	119/FIN A	FS 16-105	⊗	119/FIN A
FS 16-50	⊗	119/FIN A	FS 16-106	⊗	119/FIN A
FS 16-51	⊗	119/FIN A	FS 16-107		119/FIN A
FS 16-52	⊗	119/FIN A	FS 16-108	⊗	119/FIN A
FS 16-53		119/FIN A	FS 16-109		119/FIN A
FS 16-54		119/FIN A	FS 16-110		119/FIN A
FS 16-55		119/FIN A	FS 16-111	⊗	119/FIN A
FS 16-56	⊗	119/FIN A	FS 16-112	⊗	119/FIN A
FS 16-57	⊗	119/FIN A	FS 16-113	⊗	119/FIN A
FS 16-58	⊗	119/FIN A	FS 16-114	⊗	119/FIN A
FS 16-59	⊗	119/FIN A	FS 16-115	⊗	119/FIN A
FS 16-60	⊗	119/FIN A	FS 16-116		119/FIN A
FS 16-61	⊗	119/FIN A	FS 16-117	⊗	119/FIN A
FS 16-62		119/FIN A	FS 16-118	⊗	119/FIN A
FS 16-63		119/FIN A	FS 16-119		119/FIN A
FS 16-64		119/FIN A	FS 16-120		119/FIN A
FS 16-65	⊗	119/FIN A	FS 16-121	⊗	119/FIN A
FS 16-66	⊗	119/FIN A	FS 16-122	⊗	119/FIN A
FS 16-67	⊗	119/FIN A	FS 16-123	⊗	119/FIN A
FS 16-68		119/FIN A	FS 16-124		119/FIN A
FS 16-69		119/FIN A	FS 16-125	⊗	119/FIN A
FS 16-70		119/FIN A	FS 16-126	⊗	119/FIN A
FS 16-71		119/FIN A	FS 16-127	⊗	119/FIN A
FS 16-72	⊗	119/FIN A	FS 16-128	⊗	119/FIN A
FS 16-73	⊗	119/FIN A	FS 16-129		119/FIN A
FS 16-74		119/FIN A	FS 16-130	⊗	119/FIN A
FS 16-75	⊗	119/FIN A	FS 16-131	⊗	119/FIN A
FS 16-76	⊗	119/FIN A	FS 16-132	⊗	119/FIN A
FS 16-77	⊗	119/FIN A	FS 16-133		119/FIN A
FS 16-78		119/FIN A	FS 16-134		119/FIN A
FS 16-79	⊗	119/FIN A	FS 16-135		119/FIN A
FS 16-80	⊗	119/FIN A	FS 16-136		119/FIN A
FS 16-81	⊗	119/FIN A	FS 16-137	⊗	119/FIN A
FS 16-82	⊗	119/FIN A	FS 16-138	⊗	119/FIN A
FS 16-83	⊗	119/FIN A	FS 16-139		119/FIN A
FS 16-84	⊗	119/FIN A	FS 16-140		119/FIN A
FS 16-85	⊗	119/FIN A	FS 16-141		119/FIN A
FS 16-86	⊗	119/FIN A	FS 16-142		119/FIN A
FS 16-87	⊗	119/FIN A	FS 16-143		119/FIN A
FS 16-88	⊗	119/FIN A	FS 16-144		119/FIN A
FS 16-89	⊗	119/FIN A	FS 16-145		119/FIN A
FS 16-90		119/FIN A	FS 16-146		119/FIN A
FS 16-91		119/FIN A	FS 16-147		119/FIN A
FS 16-92		119/FIN A	FS 16-148		119/FIN A
FS 16-93	⊗	119/FIN A	17-1	*	generic
FS 16-94		119/FIN A	17-2	*	generic
FS 16-95		119/FIN A	FS 18-1		119/FIN A
FS 16-96		119/FIN A	FS 18-2		119/FIN A
FS 16-97	⊗	119/FIN A	FS 18-3		119/FIN A
FS 16-98	⊗	119/FIN A	FS 18-4		119/FIN A
FS 16-99		119/FIN A	FS 18-5		119/FIN A
FS 16-100		119/FIN A	FS 18-6		119/FIN A

⊗ – Flight copies of this page contain color

* – Omit from flight book

FS 18-7	119/FIN A	FS 18-39.....	⊗	119/FIN A
FS 18-8	119/FIN A	FS 18-40.....	⊗	119/FIN A
FS 18-9	119/FIN A	FS 18-41.....	⊗	119/FIN A
FS 18-10	119/FIN A	FS 18-42.....	⊗	119/FIN A
FS 18-11	119/FIN A	FS 18-43.....	⊗	119/FIN A
FS 18-12	119/FIN A	FS 18-44.....	⊗	119/FIN A
FS 18-13	⊗ 119/FIN A	FS 18-45.....	⊗	119/FIN A
FS 18-14	119/FIN A	FS 18-46.....	⊗	119/FIN A
FS 18-15	⊗ 119/FIN A	FS 18-47.....	⊗	119/FIN A
FS 18-16	119/FIN A	FS 18-48.....	⊗	119/FIN A
FS 18-17	119/FIN A	FS 18-49.....		119/FIN A
FS 18-18	119/FIN A	FS 18-50.....	⊗	119/FIN A
FS 18-19	119/FIN A	FS 18-51.....	⊗	119/FIN A
FS 18-20	119/FIN A	FS 18-52.....	⊗	119/FIN A
FS 18-21	119/FIN A	19-i.....		generic
FS 18-22	119/FIN A	19-ii.....		generic
FS 18-23	⊗ 119/FIN A	19-1		generic
FS 18-24	119/FIN A	19-2		generic
FS 18-25	119/FIN A	19-3		generic
FS 18-26	119/FIN A	19-4		generic
FS 18-27	119/FIN A	19-5		generic
FS 18-28	⊗ 119/FIN A	19-6		generic
FS 18-29	⊗ 119/FIN A	19-7		generic
FS 18-30	⊗ 119/FIN A	19-8		generic
FS 18-31	⊗ 119/FIN A	19-9		generic
FS 18-32	⊗ 119/FIN A	19-10		generic
FS 18-33	⊗ 119/FIN A	19-11		generic
FS 18-34	⊗ 119/FIN A	19-12		generic
FS 18-35	⊗ 119/FIN A	19-13		generic
FS 18-36	⊗ 119/FIN A	19-14		generic
FS 18-37	119/FIN A	20-1	*	generic
FS 18-38	⊗ 119/FIN A	20-2	*	generic

EVA CUE CARDS

<u>Title</u>	<u>Ref. Page</u>	<u>Card No.</u>
SAFER CHECKOUT RESULTS (Front).....	CC 3-10	generic
SAFER STATUS TROUBLESHOOTING (Back)	CC 3-11	generic
DEPRESS/REPRESS (NOM A/L) (Front).....	CC A6-2	generic
FAILED LEAK CHECK (Back of DEPRESS/REPRESS)	CC 6-4	generic
CONSUMABLES TRACKING CUE CARD (Front)	FS CC 10-15	EVA-6a/119/O/B
BATTERY RECHARGE/METOX REGEN CUE CARD (Back)	FS CC 10-16	EVA-6b/119/O/B
EMERGENCY UNDOCKING EVA TRANSFER (Front)	FS CC 12-27	EVA-5a/119/O/A
EXPEDITED SUIT DOFFING CUE CARD (Back)	FS CC 12-28	EVA-5b/119/O/A

⊗ – Flight copies of this page contain color

* – Omit from flight book

<u>CONTENTS</u>	<u>PAGE</u>
10.2 PSI CABIN	1-1
MASK PREBREATHE INITIATE	1-2
PREP FOR 10.2 PSI CABIN	1-3
CABIN DEPRESS TO 10.2 PSI.....	1-4
10.2 PSIA DEPRESS CHART	1-5
10.2 PSI CABIN CONFIG	1-6
MASK PREBREATHE TERMINATE	1-6
10.2 PSI MAINTENANCE.....	1-7
CABIN REPRESS TO 14.7 PSI.....	1-8
14.7 PSI CABIN CONFIG	1-9
AIRLOCK CONFIG.....	TEMP FS 2-1
AIRLOCK PREP	TEMP FS 2-2
EMU SWAP	2-3
BOOSTER FAN DEACTIVATION/REMOVAL.....	2-4
BOOSTER FAN INSTALLATION/ACTIVATION	2-4
EMU REMOVAL	2-4
EMU INSTALLATION	2-4
EMU CHECKOUT PREP	TEMP FS 2-5
LTA RESTRAINT STRAP REMOVAL	TEMP FS 2-6
LTA RESTRAINT STRAP INSTALLATION	TEMP FS 2-6
EVA PREP FOR TRANSFER TO ISS.....	FS 2-7
POST-DOCKING EVA TRANSFER AND RECONFIG.....	FS 2-9
EMU RESIZE.....	FS 2-10
EMU SWAP FOR EVA 2	FS 2-11
EMU SWAP FOR EVA 3	FS 2-12
EMU SWAP FOR EVA 4	FS 2-13
POST EVA EMU RECONFIG AND TRANSFER.....	FS 2-14
EVA UNPACK AND STOW	FS 2-17
CHECKOUTS.....	3-1
EMU CHECKOUT	3-2
EMU POWERUP AND COMM CHECK.....	3-2
PRIMARY REGULATOR/FAN/PUMP CHECK	3-4
SOP CHECK.....	3-5
BATTERY CHARGE CHECK INIT.....	3-6
BATTERY CHARGE CHECK TERM	3-6
EMU SWAP DURING CHECKOUT	3-7
POST EMU C/O RECONFIG.....	3-7
SAFER CHECKOUT	3-8
SELF TEST SEQUENCE	3-9
SAFER CHECKOUT RESULTS.....	CC 3-10
SAFER STATUS TROUBLESHOOTING	CC 3-11
REBA POWERED HARDWARE CHECKOUT	3-12
EVA PREP	4-1
MIDDECK PREP	4-2
EVA PREP.....	4-3
PREP FOR DONNING.....	4-3
EMU DONNING	4-5
EMU CHECK	4-7
EMU PURGE.....	4-7
EMU PREBREATHE	4-8
SAFER DONNING	4-8
EVA COMM CONFIG	4-10
EVA COMM DECONFIG	4-10
APPROVED NON-EMU HARDWARE MATRIX.....	4-11

EMU STATUS	5-1
EMU STATUS	5-2
DEPRESS/REPRESS	A6-1
DEPRESS/REPRESS (NOM A/L)	CC A6-2
FAILED LEAK CHECK	6-3
FAILED LEAK CHECK (5 PSI)	CC 6-4
FAILED LEAK CHECK (14.7/10.2 PSI)	CC 6-4
TIMELINES	FS 7-1
119 (15A) EVA OV BASELINE	FS 7-3
EVA 1	
EVA 1 SUMMARY TIMELINE	FS 7-5
EVA 1 INHIBIT PAD	FS 7-6
EVA 1 NOTES, CAUTIONS, AND WARNINGS	FS 7-8
EVA 1 TOOL CONFIG	FS 7-13
EVA 1 A/L EGRESS AND SETUP	FS 7-15
EVA 1 ATTACH S6 TO S5	FS 7-18
EVA 1 CONNECT S5 TO S6 UMBILICALS	FS 7-26
EVA 1 RELEASE SABB RESTRAINTS	FS 7-30
EVA 1 PVR RADIATOR CINCHES AND WINCH RELEASE	FS 7-34
EVA 1 ROTATE IEA KEEL PIN AND RELEASE SAW BETA GIMBAL RESTRAINTS	FS 7-36
EVA 1 UNSTOW SABB, RELEASE MAST, AND REMOVE ECU/SSU SHROUD	FS 7-42
EVA 1 S6 MMOD SHIELD BOLT TORQUE RELEASE (GET-AHEAD)	FS 7-46
EVA 1 CLEANUP	FS 7-48
EVA 1 A/L INGRESS	FS 7-49
EVA 2	
EVA 2 SUMMARY TIMELINE	FS 7-53
EVA 2 INHIBIT PAD	FS 7-54
EVA 2 NOTES, CAUTIONS, AND WARNINGS	FS 7-57
EVA 2 TOOL CONFIG	FS 7-62
EVA 2 A/L EGRESS AND SETUP	FS 7-64
EVA 2 BATTERY PREP	FS 7-67
EVA 2 P3 NADIR UCCAS DEPLOY	FS 7-69
EVA 2 P1 RBVM MLI REPAIR, P1/P3 FLUID JUMPER INSTALL, AND FHRC P-CLAMP RELEASE	FS 7-73
EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY	FS 7-77
EVA 2 TOOL STANCHION RELOCATE/APFR RETRIEVE	FS 7-85
EVA 2 CLEANUP/INGRESS	FS 7-86
EVA 3	
EVA 3 SUMMARY TIMELINE	FS 7-89
EVA 3 INHIBIT PAD	FS 7-91
EVA 3 NOTES, CAUTIONS, AND WARNINGS	FS 7-93
EVA 3 TOOL CONFIG	FS 7-98
EVA 3 EGRESS	FS 7-100
EVA 3 SETUP	FS 7-102
EVA 3 CETA CART RELOCATION	FS 7-103
EVA 3 SPDM COVERS	FS 7-108
EVA 3 LEE B REPAIR	FS 7-113
EVA 3 S1/S3 SSAS PANEL BBC RECONFIG	FS 7-122
EVA 3 S1/S3 FLUID QD JUMPER INSTALL	FS 7-123
EVA 3 S1 FHRC P-CLAMP RELEASE	FS 7-124
EVA 3 S0 1A_D RPCM REMOVE/REPLACE	FS 7-126
EVA 3 P1 1A_A RPCM REMOVE/REPLACE	FS 7-131
EVA 3 CLEANUP	FS 7-136
EVA 3 A/L INGRESS	FS 7-137

EVA 4	
EVA 4 SUMMARY TIMELINE	FS 7-141
EVA 4 INHIBIT PAD.....	FS 7-142
EVA 4 NOTES, CAUTIONS, AND WARNINGS	FS 7-145
EVA 4 TOOL CONFIG	FS 7-150
EVA 4 A/L EGRESS	FS 7-152
EVA 4 S1/P1 RADIATOR IMAGING.....	FS 7-154
EVA 4 JLP GPS ANTENNA INSTALL	FS 7-156
EVA 4 Z1 PATCH PANEL.....	FS 7-158
EVA 4 S3 TASK SETUP	FS 7-159
EVA 4 CP1 WETA INSTALL.....	FS 7-160
EVA 4 S3 OUTBOARD NADIR PAS DEPLOY	FS 7-164
EVA 4 S3 INBOARD ZENITH PAS DEPLOY	FS 7-168
EVA 4 CLEANUP/INGRESS.....	FS 7-175
GET-AHEADS	
S3 INBOARD NADIR PAS DEPLOY	FS 7-179
CONNECTOR INSULATING SLEEVE – CHANNEL 1/4 (S0)	FS 7-183
CONNECTOR INSULATING SLEEVE – MBS	FS 7-184
CONNECTOR INSULATING SLEEVE – SSPTS (NODE 1 FWD)	FS 7-185
CONNECTOR INSULATING SLEEVE – SSPTS (LAB FWD)	FS 7-186
CONNECTOR INSULATING SLEEVE – SSPTS (PMA2 PORT)	FS 7-187
CONNECTOR INSULATING SLEEVE – SSPTS (PMA2 STBD).....	FS 7-188
TOOLS AND STOWAGE	
HW TOOL STOWAGE ASSEMBLY (TSA).....	TEMP FS 8-1
PGT CHECKOUT	TEMP FS 8-2
PGSC-PGT CONNECTION (A31P AND 760XD).....	8-3
PROGRAM PGT SETTINGS.....	8-4
DOWNLOAD/ERASE EVENT LOG.....	8-5
PGT CONTINGENCIES	8-5
PGT STANDARD SETTINGS	8-6
TOOLBOX STOWAGE – STS-119/15A	8-7
APFR MANAGEMENT – STS-119/15A.....	FS 8-9
SAFETY TETHERS – STS-119 (15A).....	FS 8-10
TOOLBOX PANEL AND SLOT LABELS.....	FS 8-11
Z1 TOOLBOX INTERNAL LAYOUT	FS 8-12
AIRLOCK TOOLBOX INTERNAL LAYOUT	FS 8-13
APFR THERMAL SHIELD REMOVAL	FS 8-14
GREASE GUN NOZZLE MLI MODIFICATION	FS 8-15
POST EVA	FS 8-16
POST EVA.....	9-1
SUIT DOFFING.....	9-2
SAFER DOFFING.....	9-2
EMU WATER RECHARGE.....	9-2
SAFER STOW	9-3
SUIT DRYING/SEAL WIPE	9-3
OXYGEN RECHARGE VERIFICATION.....	9-4
WATER FILL VERIFICATION.....	9-4
EMU POWERDOWN/OVERNIGHT STOW.....	9-4
EMU MAINT/RECHARGE	9-5
WATER RECHARGE	TEMP FS 10-1
EMU POWERUP	TEMP FS 10-2
WATER FILL.....	TEMP FS 10-2
WATER FILL VERIFICATION.....	TEMP FS 10-2
EMU LiOH CHANGEOUT	TEMP FS 10-2
	10-4

MIDDECK EMU BATTERY RECHARGE (STAND-ALONE)		10-4a
MIDDECK EMU BATTERY RECHARGE/LiOH REPLACEMENT		10-5
INITIATE		10-5
TERMINATE		10-6
IN-SUIT EMU BATTERY RECHARGE/CHARGE VERIFICATION		10-7
INITIATE		10-7
TERMINATE		10-7
EMU POWERDOWN.....		10-7
HELMET LIGHT/PGT BATTERY RECHARGE		10-8
INITIATE		10-8
TERMINATE		10-9
REBA BATTERY INSTALLATION.....		10-9
EMU BATTERY REMOVAL/INSTALL		10-10
HELMET LIGHT BULB CHANGEOUT		10-11
REBA BATTERY RECHARGE		10-12
INITIATE		10-12
TERMINATE		10-13
CONSUMABLES TRACKING CUE CARD.....	FS CC	10-15
BATTERY RECHARGE/METOX REGEN CUE CARD	FS CC	10-16
POST EVA ENTRY PREP		11-1
POST EVA ENTRY PREP.....		11-2
SAFER ENTRY STOW		11-2
POST ISS EVA ENTRY PREP		11-3
<u>OFF-NOMINAL PROCEDURES</u>		12-i
EMU CONTINGENCY PROCS	TEMP FS	12-1
DISPLAY LOSS DURING POWER TRANSFER		
(WARM RESTART)	TEMP FS	12-2
VACUUM H2O RECHARGE (MANNED)	TEMP FS	12-2
LiOH REPLACEMENT (MANNED)		12-3
BATTERY REPLACEMENT (MANNED)		12-4
WATER DUMP		12-6
SCU SWAP (UNMANNED)		12-7
SCU SWAP (MANNED)		12-7
EMU COLD RESTART (MANNED).....		12-7
12.1 STS EVA DECONTAMINATION		12-8
CONTAMINATION TEST		12-15
SAFER BATTERY CHANGEOUT		12-18
BENDS TREATMENT ADAPTER (BTA) INSTALLATION (IN-SUIT)		12-19
BTA PREP		12-19
BTA TREATMENT		12-19
BENDS TREATMENT ADAPTER (BTA) INSTALLATION		
(POST SUIT DOFFING)		12-21
BTA PREP		12-21
BTA TREATMENT		12-21
EMU RESIZE.....		12-24
EMERGENCY UNDOCKING EVA TRANSFER.....	FS CC	12-27
EXPEDITED SUIT DOFFING CUE CARD	FS CC	12-28
STS-119 NOMINAL EMU SIZING	FS	12-29
EMU CONTINGENCY RESIZE MATRIX (STS-119/15A)	FS	12-32
TPS REPAIR.....	FS	13-1

ORBITER CONTINGENCY EVA.....	14-1
PAYLOAD BAY EVA NOMENCLATURE	14-2
RMS/PRLA CONTINGENCY EVA	14-3
96 BOLT PRE-EVA TOOL CONFIG.....	14-13
96 BOLT EVA TIMELINE	14-14
CAPTURE LATCH MANUAL RELEASE (ODS/PMA)	14-19
96 BOLT EVA LAYOUT.....	14-21
PLBD LATCH TOOL PLACEMENT WITH DUAL LATCH GANG FAILURES	14-22
EVA CUFF CHECKLIST (CIL)	15-1
NORMAL EVA STATUS.....	15-2
DCM CONFIGURATION	15-2
EMU MALFUNCTION INDEX.....	15-2
DECOMPRESSION SICKNESS (DCS)	15-3
DECOMPRESSION SICKNESS (DCS) (CONT).....	15-3
ABORT EVA.....	15-3
TERMINATE EVA.....	15-3
SUIT P EMERG.....	15-4
SOP O2 ON.....	15-4
BATT AMPS HIGH	15-4
BATT V DECAY OR BATT VDC LOW	15-4
SUIT P LOW.....	15-5
SUIT P HIGH.....	15-5
SOP P LOW	15-5
O2 USE HIGH	15-5
SUBLM PRESS.....	15-6
H2O GP LOW.....	15-6
RESRV H2O ON	15-6
H2O WP HIGH	15-6
NO VENT FLOW	15-7
CO2 HIGH OR MONITOR CO2	15-7
CO2 SNSR BAD.....	15-7
COMM FAILURE	15-7
AIR FLOW CONTAMINATION	15-8
LOSS OF COOLING	15-8
RLF V FAIL.....	15-8
MISC MSGS 1	15-8
MISC MSGS (CONT)/TIME LF.....	15-9
AIRLOCK LATCH DISCONNECT	15-9
AIRLOCK INGRESS.....	15-9

FOLLOWING PAGES NOT IN EV CUFF

RADIATOR ACTUATOR DISCONNECT	15-9
PLBD DRIVE CUT.....	15-10
DOOR DRIVE RESTRAINT	15-10
DOOR DRIVE DISCONNECT	15-10
WINCH OPERATIONS.....	15-10
WINCH OPERATIONS (CONT)	15-11
3-PT TOOL INSTALLATION	15-11
CL LATCH TOOL	15-11
RMS JOINT ALIGN	15-11
MPM STOW/DEPLOY	15-12
RMS TIEDOWN.....	15-12
RMS FLIGHT RELEASABLE GRAPPLE FIXTURE RELEASE	15-12
PRLA OPEN/CLOSE	15-12
PRLA OPEN/CLOSE (CONT)	15-13
KU ANTENNA STOW.....	15-13
KU ANTENNA STOW (CONT)	15-13
AIRLOCK EGRESS.....	15-13

<u>FLIGHT SPECIFIC REFERENCE</u>	16-i
UNSCHEDULED/CONTINGENCY EVA TASKS	TEMP FS 16-1
15A WORKAROUNDS CRIBSHEET	
EVA 1.....	FS 16-3
EVA 2.....	FS 16-6
EVA 3.....	FS 16-6
EVA 4.....	FS 16-9
GENERIC	
APFR/IAPFR	FS 16-10
BALLSTACK	FS 16-10
BRT	FS 16-11
CANNON CONNECTOR	FS 16-11
EVA WRENCH (TORQUE AND RATCHET)	FS 16-11
FLUID QD OPS.....	FS 16-11
MUT EE.....	FS 16-14
MWS	FS 16-15
NZGL CONNECTORS	FS 16-15
PAD.....	FS 16-17
PGT.....	FS 16-17
SAFETY TETHER.....	FS 16-18
SCOOPS.....	FS 16-19
SOCKET CADDY.....	FS 16-19
TA CLAMP	FS 16-19
TETHER SHUTTLE	FS 16-19
TORQUE MULTIPLIER.....	FS 16-20
TSA (HW TSA).....	FS 16-21
S5/S6 ATTACH	
16.1a RTAS GAP CLOSURE (CORNER 1 OR 2).....	FS 16-22
16.1b RTAS GAP CLOSURE (CORNER 3 OR 4).....	FS 16-24
CAPTURE BAR ROTATION.....	FS 16-25
ATTACH S6 TO S5 USING CONTINGENCY FASTENERS	FS 16-27
PRD S5-S6 OVERVIEW	FS 16-30
PRD RTAS CORNER 1 (PRIMARY)	FS 16-31
PRD RTAS CORNER 1 (PRIMARY) NBL	FS 16-32
PRD RTAS CORNER 2	FS 16-33
PRD RTAS CORNER 2 NBL	FS 16-34
PRD RTAS CORNER 3	FS 16-35
PRD RTAS CORNER 3 NBL (STRAP ROUTING)	FS 16-36
PRD RTAS CORNER 3 NBL	FS 16-38
PRD RTAS CORNER 4 (PRIMARY)	FS 16-39
PRD RTAS CORNER 4 (PRIMARY) NBL	FS 16-40
PRD RTAS CORNER 4 (PRIMARY) (STRAP ROUTING)	FS 16-41
PVR	
S6 RADIATOR MANUAL OVERRIDE TO DEPLOY/RETRACT.....	FS 16-43
SAW	
PRD 4-BAR ROUTING	FS 16-48
MANUAL OVERRIDE TO DISENGAGE BETA GIMBAL	
ANTI-ROTATION LATCH	FS 16-52
BMRRM ANTI-ROTATION LATCH TABLE	FS 16-53
MANUAL RELEASE OF SABB RESTRAINT PINS.....	FS 16-54
MANUAL OVERRIDE TO UNLATCH/LATCH (TENSION) SABB	FS 16-57
MANUAL OVERRIDE TO EXTEND/RETRACT MAST.....	FS 16-59
ASSISTED SOLAR ARRAY DEPLOY/RETRACT	FS 16-62
SABB SPOOL RE-TENSION.....	FS 16-68
MANUAL SAW JETTISON	FS 16-74

TIE-DOWN PLAN	
GAP CHECK TOOL TIE-DOWN.....	FS 16-80
SABB LAUNCH RESTRAINT TIE-DOWN.....	FS 16-81
UCCAS/PAS TIE-DOWN.....	FS 16-82
RPCM TIE-DOWN.....	FS 16-84
WETA/DUMMY BOX TIE-DOWN.....	FS 16-85
MISC	
BMRRM REMOVE/REPLACE.....	FS 16-89
DCSU REMOVE AND REPLACE.....	FS 16-94
DDCU REMOVE AND REPLACE.....	FS 16-99
DLA REMOVE AND REPLACE.....	FS 16-104
MBSU REMOVE/REPLACE.....	FS 16-112
RJMC REMOVE AND REPLACE.....	FS 16-119
SSRMS JOINT DRIVE.....	FS 16-120
SARJ – TBA REMOVE/INSTALL.....	FS 16-124
BCDU REMOVE/REPLACE.....	FS 16-130
GENERIC EVA INHIBIT PAD.....	FS 16-139
GENERIC NOTES, CAUTIONS, & WARNINGS.....	FS 16-144
GENERIC EVA REFERENCE.....	17-1
FLIGHT SPECIFIC EVA REFERENCE.....	FS 18-1
PAYLOAD BAY CONFIGURATION.....	FS 18-3
S6	
S6 OVERVIEW.....	FS 18-4
S6 LONG SPACER.....	FS 18-5
S6 IEA (NON-KEEL SIDE) AND NON-PVR SIDE.....	FS 18-8
S6 IEA (KEEL SIDE) AND NON-PVR SIDE.....	FS 18-9
S6 IEA (KEEL SIDE) AND PVR SIDE.....	FS 18-10
S6 STARBOARD, NON-KEEL UP.....	FS 18-11
S6 STARBOARD, KEEL UP.....	FS 18-12
GAP CHECK TOOL.....	FS 18-13
S5 CAPTURE LATCH ASSEMBLY (CLA).....	FS 18-14
S6 SSU SHROUD MLI FOLDING SEQUENCE.....	FS 18-15
SAW	
BGA PRIMARY POWER CABLE CLAMPS.....	FS 18-16
RELEASE BETA GIMBAL LAUNCH RESTRAINTS.....	FS 18-17
FOUR BAR IN LOCKED POSITION.....	FS 18-18
SABB UNSTOW.....	FS 18-19
4-BAR STOWED AND DEPLOYED CONFIGURATIONS.....	FS 18-22
MAST CANISTER MDA.....	FS 18-23
CETA CART	
CETA CART – TOP VIEW.....	FS 18-24
CETA CART – SWING ARMS AND WIF MARKINGS.....	FS 18-25
CETA CART – COUPLERS.....	FS 18-26
CETA CART – WHEEL BOGIES.....	FS 18-27
SPDM/SSRMS	
SPDM ASSY.....	FS 18-28
SPDM CAMERA LIGHT ASSY (CLA).....	FS 18-29
SPDM CAMERA LIGHT PAN TILT ASSY (CLPA).....	FS 18-31
SPDM ORU TOOL CHANGEOUT MECHANISM (OTCM).....	FS 18-33
SPDM ELECTRONICS PLATFORM (EP) #1.....	FS 18-35
SPDM ELECTRONICS PLATFORM 1 (EP1) COVER.....	FS 18-37
LEE SNARE REPAIR.....	FS 18-38
UCCAS/PAS	
UCCAS/PAS DEPLOY.....	FS 18-40

JLP	
JLP GPS ANTENNA WITH COVER	FS 18-43
JLP GPS ANTENNA OVERVIEW.....	FS 18-44
JLP GPS ANTENNA CABLE/CONNECTOR LOCATION AND ID	FS 18-46
WETA	
WETA ASSY AND S3 CP1 INSTALL BRACKET	FS 18-47
CP1 WETA INSTALL.....	FS 18-48
ETVCG DUMMY BOX	FS 18-49
MISC	
S0 1A_D RPCM.....	FS 18-50
CONNECTOR GROUNDING SLEEVES.....	FS 18-51
ORU CONTINGENCY TIE-DOWN DEFINITIONS	FS 18-52
<u>EVA EMERGENCY</u>	19-i
EMERGENCY PROCEDURES.....	19-1
EMERGENCY AIRLOCK REPRESS	19-3
EMERGENCY AIRLOCK REPRESS.....	19-4
POST EMERGENCY AIRLOCK REPRESS.....	19-4
SAFER RESCUE.....	19-5
SAFER RESCUE	19-6
DAP/EVA RESCUE/RETRIEVE	19-7
EVA ORBITER CONFIG.....	19-7
EVA RESCUE/RETRIEVE	19-9
19.1 DCS TREATMENT	19-10
CONTINGENCY SHUTTLE AIRLOCK INGRESS FROM ISS	19-13
CUE CARD CONFIGURATION	20-1

AIRLOCK CONFIG

AIRLOCK PREP TEMP FS 2-2
EMU SWAP 2-3
BOOSTER FAN DEACTIVATION/REMOVAL 2-4
BOOSTER FAN INSTALLATION/ACTIVATION 2-4
EMU REMOVAL 2-4
EMU INSTALLATION 2-4
EMU CHECKOUT PREP TEMP FS 2-5
LTA RESTRAINT STRAP REMOVAL TEMP FS 2-6
LTA RESTRAINT STRAP INSTALLATION TEMP FS 2-6
EVA PREP FOR TRANSFER TO ISS FS 2-7
POST-DOCKING EVA TRANSFER AND RECONFIG FS 2-9
EMU RESIZE FS 2-10
EMU SWAP FOR EVA 2 FS 2-11
EMU SWAP FOR EVA 3 FS 2-12
EMU SWAP FOR EVA 4 FS 2-13
POST EVA EMU RECONFIG AND TRANSFER FS 2-14
EVA UNPACK AND STOW FS 2-17

AIRLOCK
CONFIG

AIRLOCK PREP (50 min)

MF28G	Retrieve or unstow following equipment:
IFM Tool Kit	3/8-in breaker bar, 4-in ext w/3/8-in drive
Vol H	1/2-in socket w/3/8-in drive
	EMU Equipment Bag – attach to middeck wall
	EMU Servicing Kit
	Helmet Lights
	EVA Bag
	Contamination Detection Kit (location flight specific)
<u>FDF Locker</u>	Cuff Checklists (2) – stow in EMU Equipment Bag
	<u>DEPRESS/REPRESS</u> Cue Card

- AW18A
1. ✓ Inner hatch Equal vlv (two) – OFF
 2. LTG FLOOD (four) – ON
 3. Remove from airlock, as reqd:
 - Airlock Stowage Bag
 - Airlock Floor Pallet using 3/8-in breaker bar, 4-in ext w/3/8-in drive, and 1/2-in socket w/3/8-in drive
 4. Stow Vol H Bags in Vol H
 5. Transfer to airlock:
 - EVA Bag – install on airlock wall
 - DEPRESS/REPRESS Cue Card
 - Helmet Lights
 - Contamination Detection Kit – install on airlock wall
 6. Install IVA foot restraint, as reqd
 7. Unbuckle SCU straps, Velcro SCU to wall
 8. Install EMU lights on helmets (EMU 1, EMU 2)
 9. Disconnect helmets from Airlock EMUs, temp stow
 10. Remove comm caps from LTA Restraint Bags and connect to electrical harnesses
 11. Install helmets (not reqd if proceeding directly to EMU Checkout)
 12. Remove LTA Restraint Bags
 13. Disconnect waist rings; remove and stow any equipment stowed in HUT/LTA
 14. Stow LTA Restraint Bags on AAPs
 15. ✓ Thermal cover clear of waist ring
 16. Waist ring – engage posn
 17. Connect LTA to HUT, lock
 18. Remove 20-g Crash Bag from middeck EMU, as reqd

AIRLOCK
CONFIG

EMU CHECKOUT PREP (30 min)

- Airlock
1. LTG FLOOD (four) – on
 2. If necessary, remove Airlock Floor Bag from Airlock
 3. Unstow from Airlock Floor Bag:
 - Sw 1 LCVG
 - An 1 LCVG
 - Temp stow in Airlock
 4. Unbuckle SCU straps, Velcro SCU to wall
 5. Disconnect helmets from EMUs, temp stow
 6. ✓DIDB restraint bags installed
 7. Remove comm caps (4) from LTA Restraint Bags (kangaroo pouches)
 - For EMU 3017 (Sw)
 - Connect comm cap Sw 1 to EMU electrical harness
 - Temp stow comm cap Sw 2 (for Sw ECOK, step 10)
 - For EMU 3006 (An)
 - Adjust An 1 earcups ~ 1/2 inch lower
 - Connect comm cap An 1 to EMU electrical harness
 - Stow comm cap Ac 1 in Airlock Floor Bag
 8. Disconnect LTA Restraint Bag straps from AAP; temp stow
 9. Disconnect waist rings; remove Sw, An ECOKs
 10. Stow comm cap Sw 2 in Sw ECOK
 11. Temp stow Sw, An ECOKs in Airlock
 12. Temp stow LTA Restraint Bags on AAPs (bottom)
 13. ✓Thermal cover clear of waist rings
 14. Waist rings – engage position
 15. Connect LTAs to HUTs, lock
- Middeck
Vol H
(MD23R)
16. Unstow:
 - Inboard Bag:
 - From EMU Equipment Bag (Danny Bag)
 - Temp stow for EMU Checkout
 - SCOFs (2)
 - LTA Donning Handles (2)
 - EMU Servicing Kit s/n 5004
 17. Stow Inboard Bags in Vol H
(NOTE: SCOFs (2) and LTA Donning Handles (2) will be stowed back in EMU Equipment Bag after EMU Checkout)
- Airlock
18. As required, temp stow Airlock Floor Bag, ECOKs, EMU Servicing Kit s/n 5004 (for EVA Prep for Transfer to ISS)
 19. Remove 85-ft Safety Tethers (2) from Bag C, stow on EMUs
 20. Unstow ISS EVA Cuff C/L (3) from SODF locker
 - Stow Sw, An C/L on EMUs, left arm
 - Stow Ac C/L in Airlock Floor Bag

LTA RESTRAINT STRAP REMOVAL (15 min)

NOTE

May be performed on EMU 1 and 2 simultaneously.
Perform steps as reqd for current EMU config


1. As reqd, remove comm cap from LTA Restraint Bag; temp stow
2. Remove EMU from AAP
3. Disconnect all restraint attachments from SAFER mount brackets (two)
4. Loosen cinch strap mechanism, remove SAFER mount brackets
5. Remove strap from PLSS
6. Stow strap in LTA Restraint Bag Pouch with D-rings (three) connected
7. Engage EMU in AAP
8. Stow LTA Restraint Bag/strap

LTA RESTRAINT STRAP INSTALLATION (15 min)

NOTE

May be performed on EMU 1 and 2 simultaneously. Perform steps as reqd for current EMU config. Procedure written to install in Launch/Landing config shown below

1. Unstow LTA Restraint Bag/strap
2. Remove EMU from AAP
3. Install SAFER mount brackets (two)
4. Install elastic band of strap around SOP
5. Tighten cinch strap mechanism
6. Attach strap French hooks (two) to SAFER mount brackets
7. Engage EMU in AAP
8. Stow LTA, suit arms inside LTA Restraint Bag
9. Connect upper spring hooks (two) over suit shoulders to upper AAP attachment rings (two)
10. Connect lower spring hooks (two) around suit arms to SAFER mount brackets (two)
11. Tighten all LTA bag straps with bag as high as possible on EMU



NOTE

French hooks should be attached to SAFER mount brackets for launch and landing

EVA PREP FOR TRANSFER TO ISS (90 min)

- BOTH EMUs/
DCM
1. ✓ SCOFs and Donning Handles stowed
 2. ✓ PWR – SCU
 3. ✓ PURGE vlv – op (up)
 4. ✓ WATER – OFF, switch guard installed
 5. ✓ O₂ ACT – OFF
 6. Retrieve the following:

Airlock Floor Bag
EMU Servicing Kit

7. Configure/verify items according to tables below:

<p style="text-align: center;"><u>EMU 3017 (Sw)</u></p> <ul style="list-style-type: none"> <input type="checkbox"/> DIDB Restraint Bag (verified during EMU CO) <input type="checkbox"/> Comm Cap (Sw 1) (installed during EMU CO) <input type="checkbox"/> Helmet (✓sun shade down, cover installed) <ul style="list-style-type: none"> <input type="checkbox"/> Valsalva <input type="checkbox"/> EMU Gloves (Sw 1) <input type="checkbox"/> Cuff C/L <input type="checkbox"/> Wrist Mirror (2) <input type="checkbox"/> EMU Battery (verify s/n at REBA Installation) <input type="checkbox"/> CCC (LiOH, verify s/n at REBA Installation) <input type="checkbox"/> LTA <input type="checkbox"/> ECOK <input type="checkbox"/> LTA Restraint and Strap <input type="checkbox"/> 85-ft Safety Tether 	<p style="text-align: center;"><u>EMU 3006 (An)</u></p> <ul style="list-style-type: none"> <input type="checkbox"/> DIDB Restraint Bag (verified during EMU CO) <input type="checkbox"/> Comm Cap (An 1) (installed during EMU CO) <input type="checkbox"/> Helmet (✓sun shade down, cover installed) <ul style="list-style-type: none"> <input type="checkbox"/> Valsalva <input type="checkbox"/> EMU Gloves (An 1) <input type="checkbox"/> Cuff C/L <input type="checkbox"/> Wrist Mirror (2) <input type="checkbox"/> EMU Battery (verify s/n at REBA Installation) <input type="checkbox"/> CCC (LiOH, verify s/n at REBA Installation) <input type="checkbox"/> LTA <input type="checkbox"/> ECOK <input type="checkbox"/> LTA Restraint and Strap <input type="checkbox"/> 85-ft Safety Tether
<p style="text-align: center;"><u>EMU Crew Options Kit (Sw)</u></p> <ul style="list-style-type: none"> <input type="checkbox"/> ECOK – Mesh Bag <ul style="list-style-type: none"> <input type="checkbox"/> Sw EVA 1, 2 & 4 Ziplock Bags <ul style="list-style-type: none"> <input type="checkbox"/> 2 per EVA, MAGs (w/Ziplock Bags) <input type="checkbox"/> TCUs (top, bottom) <input type="checkbox"/> Socks <input type="checkbox"/> Wristlets <input type="checkbox"/> Comfort Gloves <input type="checkbox"/> 3, 7/8-in dia Velcro loop <input type="checkbox"/> 3, 7/8-in dia Velcro hook EVA 2 bag only: <ul style="list-style-type: none"> <input type="checkbox"/> EV identifier stripes (EV1) <input type="checkbox"/> Mission patch (STS-119) <input type="checkbox"/> US flag <input type="checkbox"/> Mesh Bags (2) <input type="checkbox"/> Comm Cap (Sw 2) <input type="checkbox"/> Crew personal items for Campout (as reqd) 	<p style="text-align: center;"><u>EMU Crew Options Kit (An)</u></p> <ul style="list-style-type: none"> <input type="checkbox"/> ECOK – Mesh Bag <ul style="list-style-type: none"> <input type="checkbox"/> An EVA 1, 3 & 4 Ziplock Bags <ul style="list-style-type: none"> <input type="checkbox"/> 2 per EVA, MAGs (w/Ziplock Bags) <input type="checkbox"/> TCUs (top, bottom) <input type="checkbox"/> Socks <input type="checkbox"/> Wristlets <input type="checkbox"/> Comfort Gloves <input type="checkbox"/> 3, 7/8-in dia Velcro loop <input type="checkbox"/> 3, 7/8-in dia Velcro hook EVA 3 bag only: <ul style="list-style-type: none"> <input type="checkbox"/> EV identifier stripes (EV2) <input type="checkbox"/> Mission patch (STS-119) <input type="checkbox"/> US flag <input type="checkbox"/> Crew personal items for Campout (as reqd)

EVA PREP FOR TRANSFER TO ISS (90 min) (Cont)

<p style="text-align: center;"><u>Airlock Floor Bag</u></p> <ul style="list-style-type: none"><input type="checkbox"/> EMU Battery s/n 2076<input type="checkbox"/> EMU Gloves – 4 pair (Ac 1, Ac 2, An 2, Sw 2)<input type="checkbox"/> Comm Cap – 2 (Ac 1, Ac 2)<input type="checkbox"/> LCVG – 3 (Sw 1, An 1, Ac 1)<input type="checkbox"/> Cuff C/L<input type="checkbox"/> Wrist Mirrors (2)<input type="checkbox"/> ECOK (Ac) – Mesh Bag<ul style="list-style-type: none"><input type="checkbox"/> Ac EVA 2 & 3 Ziplock Bags<ul style="list-style-type: none"><input type="checkbox"/> 2 per EVA, MAGs (w/Ziplock Bags)<input type="checkbox"/> TCUs (top, bottom)<input type="checkbox"/> Socks<input type="checkbox"/> Wristlets<input type="checkbox"/> Comfort Gloves<input type="checkbox"/> 3, 7/8-in dia Velcro loop<input type="checkbox"/> 3, 7/8-in dia Velcro hook<input type="checkbox"/> EV identifier stripes (EV3)<input type="checkbox"/> Mission patch (STS-119)<input type="checkbox"/> US flag<input type="checkbox"/> Crew personal items for Campout (as reqd) <input type="checkbox"/> Crewlock Bag <input type="checkbox"/> Adjustable Equipment Tethers (2) Gap Spanners (6)<ul style="list-style-type: none"><input type="checkbox"/> 4 – 307 (72 in)<input type="checkbox"/> 2 – 305 (45 in) Connector Sleeve (8)<ul style="list-style-type: none"><input type="checkbox"/> 4 – Cnctr Sleeve 21/25<input type="checkbox"/> 4 – Cnctr Sleeve 33/37 <u>(Not Planned for Use)</u><ul style="list-style-type: none"><input type="checkbox"/> EMU LiOH Canister (2)<input type="checkbox"/> Crack Repair Pallet (2)	<ul style="list-style-type: none"><input type="checkbox"/> EMU Servicing Kit s/n 5004
--	---

POST-DOCKING EVA TRANSFER AND RECONFIG (60 min)

NOTE

This procedure assumes that transfer items were preconfigured per EVA PREP FOR TRANSFER TO ISS

1. Transfer the following EVA equipment to ISS:

Item	Final Destination	Transfer Status
EMU 3017 (Sw)	E-Lk aft EDDA	
EMU 3006 (An)	E-Lk fwd EDDA	
EMU Servicing Kit	E-Lk	
Airlock Floor Bag	E-Lk	

2. Stow EMU Servicing Kit s/n 5004 in E-Lk (for ISS CDR)
 3. Remove LTA Restraint Strap and LTA Restraint Bag
Perform LTA restraint removal
Stow LTA Restraint Strap and LTA Restraint Bag in EVA Systems Transfer Bag
 4. Install Helmet Lights/EMU TV assembly per
STS-119 EVA CONSUMABLES TRACKING CUE CARD
- During REBA INSTALLATION:
5. Verify expected LiOH and EMU Battery s/n's installed per
STS-119 EVA CONSUMABLES TRACKING CUE CARD

BOTH EMUs

EMU RESIZE (30 min)

EMU 3005 CONFIGURATION FOR ACABA

NOTE

Procedure assumes Expedition 18 has already completed the following:

- REBA, METOX canister and EMU Battery installed in EMU 3005
- EMU 3005 resized for Ac (sizing cams verified per Ac NOMINAL RESIZE)
- EMU 3005 installed on forward EDDA, aft EDDA empty

- | | | | |
|-------------------|--------------------------|--|--|
| Airlock Floor Bag | <input type="checkbox"/> | 1. Unstow Ac 1 Comm Cap from Airlock Floor Bag | |
| EMU 3005 (Ac) | <input type="checkbox"/> | 2. Disconnect helmet
Connect Comm Cap Ac 1 to EMU electrical harness
√DIDB restraint bag installed
Connect Helmet, √locked and cover installed | |
| | <input type="checkbox"/> | 3. Retrieve EV3 cuff checklist from Airlock Floor Bag
Install on left arm | |
| | <input type="checkbox"/> | 4. Remove lower arm covers, stow in Ac ECOK
Unstow Ac 1 gloves from Airlock Floor Bag
Connect Ac 1 gloves to lower arms
√Glove heater cable connected at upper arm
√Arms aligned
Connect glove heater cables
√Lower arms cams in S - S position | |
| | <input type="checkbox"/> | 5. Install Wrist Mirrors (2) from Airlock Floor Bag | |
| | <input type="checkbox"/> | 6. Retrieve EVA 2 ziplock bag from Ac ECOK
Install the following items on EMU 3005:
<input type="checkbox"/> STS-119 Mission patch
<input type="checkbox"/> US flag
<input type="checkbox"/> EV3 Crew Identifier stripes (PLSS/LTA)
Return EVA 2 ziplock to Ac ECOK | |
| | <input type="checkbox"/> | 7. Stow Ac ECOK in Airlock Floor Bag | |
| | <input type="checkbox"/> | 8. √Helmet PV closed/locked
√LTA locked | |
| | <input type="checkbox"/> | 9. √METOX, EMU Battery, REBA Installed
Reference <u>STS-119 EVA CONSUMABLES CUE CARD</u> | |
| | <input type="checkbox"/> | 10. Remove EMU 3005 from fwd EDDA
Install LTA Restraint Strap and LTA Restraint Bag
Perform LTA Restraint installation | |
| | <input type="checkbox"/> | 11. Transfer EMU 3005 to Node 1 | |

EMU SWAP FOR EVA 2 (30 min)

NOTE

This procedure assumes the following procedures have been completed following EVA 1:
{1.240 POST EVA} (SODF: ISS EVA SYS: EVA PREP/POST)
{1.605 BSA BATTERY RECHARGE - term} (SODF: ISS EVA SYS: BATTERY OPS)

- EMU 3006 (An)
- 1. ✓Helmet installed, sun shades down, sun visor retracted
Remove helmet cover, temp stow
Remove helmet lights/EMU TV assembly
Temp stow helmet lights/TV assembly
 - 2. ✓Used EV2 undergarments (TCUs, socks, wristlets, comfort gloves) stowed for return on Shuttle
 - 3. Connect waist ring to HUT
 - 4. Connect An 1 gloves to lower arms
 - 5. ✓LiOH (used) installed, EMU Battery removed
 - 6. Retrieve LTA Restraint Strap and LTA Restraint Bag from Airlock Floor Bag
Perform LTA Restraint installation
 - 7. Remove EMU from fwd EDDA
Transfer EMU to Node 1
 - 8. Gather EV2 (An) EMU crew-specific items and place in An ECOK
Stow An ECOK and LCVG in Airlock Floor Bag
- EMU 3005 (Ac)
- 9. Transfer EMU to E-Lk
Perform LTA Restraint removal
Install EMU on fwd EDDA
Stow LTA Restraint Bag and LTA Restraint Strap in Airlock Floor Bag
 - 10. Install Helmet Lights/EMU TV assembly
✓Sun shades down. Install helmet cover
 - 11. Unstow Ac ECOK and LCVG from Airlock Floor Bag
- During 1.515 EMU METOX/LiOH/BATTERY REPLACEMENT:
- EMU 3017 (Sw)
- 12. When LiOH (used) removed, cover canister ports with METOX caps or Kapton tape
 - 13. Temp stow LiOH (used) in Airlock Floor Bag

EMU SWAP FOR EVA 3 (30 min)

NOTE

This procedure assumes the following procedures have been completed following EVA 2:
{1.240 POST EVA} (SODF: ISS EVA SYS: EVA PREP/POST)
{1.605 BSA BATTERY RECHARGE - term} (SODF: ISS EVA SYS: BATTERY OPS)

CONFIGURE SWANSON'S EMU FOR STOWAGE

- EMU 3017 (Sw)
- 1. ✓Helmet installed, sun shades down, sun visor retracted
Remove helmet cover, temp stow
Remove helmet lights/EMU TV assembly
Temp stow helmet lights/TV assembly
 - 2. ✓Used EV1 undergarments (TCUs, socks, wristlets, comfort gloves) stowed for return on Shuttle
 - 3. Connect waist ring to HUT
 - 4. Connect Sw 1 gloves to lower arms
 - 5. Retrieve LTA Restraint Strap and LTA Restraint Bag from Airlock Floor Bag
Perform LTA Restraint installation
 - 6. Remove EMU from aft EDDA
Transfer EMU 3017 to Node 1
 - 7. Gather EV1 (Sw) EMU crew-specific items and place in Sw ECOK
Stow Sw ECOK and LCVG in Airlock Floor Bag

CONFIGURE ARNOLD'S EMU FOR EVA 3

- EMU 3006 (An)
- 8. Transfer EMU 3006, An ECOK and LCVG to E-Lk
Perform LTA Restraint removal
Install EMU on aft EDDA
Stow LTA Restraint Bag and LTA Restraint Strap in Airlock Floor Bag
 - 9. Install Helmet Lights/EMU TV assembly
✓Sun visors down, cover installed
 - 10. ✓Wrist Mirrors (two) installed

During 1.515 EMU METOX/LiOH/BATTERY REPLACEMENT:

- EMU 3006 (An)
- 11. When LiOH (used) removed, cover canister ports with METOX caps or Kapton tape
 - 12. Temp stow LiOH (used) in Airlock Floor Bag
- EMU 3005 (Ac)
- 13. Stow EMU Battery s/n 2037 in Airlock Floor Bag

EMU SWAP FOR EVA 4 (90 min)

NOTE

This procedure assumes the following procedures have been completed following EVA 3:
{1.240 POST EVA} (SODF: ISS EVA SYS: EVA PREP/POST)
{1.605 BSA BATTERY RECHARGE - term} (SODF: ISS EVA SYS: BATTERY OPS)

- EMU 3005 (Ac)
- 1. Remove Helmet Lights/EMU TV assembly; temp stow
 - 2. Disconnect Comm Cap (Ac 1), stow in Airlock Floor Bag
 - 3. Install helmet, √sun shades down and visor up; install helmet cover
 - 4. Connect waist ring to HUT
 - 5. Remove Wrist Mirrors (2); temp stow in Airlock Floor Bag
 - 6. Remove Ac 1 gloves and install lower arm covers
Stow gloves and LCVG in Airlock Floor Bag
 - 7. Remove Cuff C/L
If desired, remove crew notes pages and stow pages in Ac ECOK
Stow Cuff C/L in Airlock Floor Bag
 - 8. Remove mission patch, US flag and stripes
Stow in Ac ECOK
 - 9. Gather EV3 (Ac) EMU crew-specific items and place in Ac ECOK
Stow Ac ECOK in Airlock Floor Bag
 - 10. √Used EV3 undergarments (TCUs, socks, wristlets, comfort gloves)
stowed for return on Shuttle
 - 11. Retrieve LTA Restraint Strap and Bag from Airlock Floor Bag
Remove EMU from fwd EDDA
Perform LTA Restraint installation
Stow EMU in Node 1
- EMU 3006 (An)
- 12. Remove EMU from aft EDDA
Install in fwd EDDA
- EMU 3017 (Sw)
- 13. Transfer EMU 3017 (Sw) from Node 1 to E-Lk
Perform LTA Restraint removal
Install EMU in aft EDDA
Stow LTA Restraint Bag and LTA Restraint Strap in Airlock Floor Bag
Unstow Sw ECOK and LCVG from Airlock Floor Bag
 - 14. Remove helmet cover, install Helmet Lights and EMU TV
√Sun shades down, visor up and install cover

POST EVA EMU RECONFIG AND TRANSFER (90 min)

This procedure configures an ISS suit 3004 for Arnold's return EMU (leaving his Shuttle EMU 3006 and helmet on ISS) and leaves Swanny's LTA on ISS (swapping LTAs with EMU 3004). Also, this procedure assumes EMUs have been left disassembled (helmet, gloves, LTA loose) post EVA 4 for overnight suit dry-out

EMU 3017/ (Sw)1. Remove Comm Caps, stow in Airlock Floor Bag
EMU 3006 (An)

2. Remove Cuff C/Ls
If desired, remove crew notes pages and stow pages in your ECOK
Stow Cuff C/Ls in Airlock Floor Bag
3. Remove mission patch, US flag and stripes (DCM/PLSS/LTA)
Stow in Sw, An ECOKs
4. Remove Sw 2 comm cap from Sw ECOK
Stow in Airlock Floor Bag
5. Inspect and compare all on-orbit EMU wrist mirrors (12) – 2 Ac Airlock Floor Bag, 2 each on Sw, An suits
Stow best quality wrist mirrors (6) in ISS A/L MO2 bag, s/n 1038
Report serial numbers and final stowage locations to MCC

Install remaining wrist mirrors (6) in Airlock Floor Bag

EMU 3017 (Sw) 6. Remove METOX canister, EMU Battery and REBA
Stow in ISS A/L MO2 Bag, s/n 1038

7. Install expended LiOH canister from Airlock Floor Bag
Install designated EMU battery for return (use Return ↓Config) per STS-119 CONSUMABLES TRACKING CUE CARD

DCMs

8. √PWR – SCU
√PURGE vlv – op (up)
√O2 ACT – OFF
√WATER – OFF, switch guard installed

EMU 3006 Config for ISS

EMU 3006 (An↑)9. Install lower arm covers (from EMU 3004)
√DIDB Restraint Bag in HUT
Install An helmet, s/n 1078, with helmet lights/EMU TV installed
√Helmet locked, sun shades down, cover installed
Connect Sw LTA s/n 2076 (bladder 045)
Remove EMU 3006 from fwd EDDA, temp stow

Arnold EMU Return Config

EMU 3004 (An↓)10. Install EMU 3004 in fwd EDDA, remove LTA Restraint Bag if required
Install gloves, An 1
Remove LTA s/n 2057 (bladder 007), install on Sw EMU 3017
√DIDB Restraint Bag in HUT
Stow An ECOK and LCVG in HUT
Install An LTA s/n 2081 (bladder s/n 018)

11. Unzip rear PLSS TMG, remove vent port plugs and stow in Danny Bag
Install expended LiOH canister from Airlock Floor Bag
Install designated EMU battery for return (use Return ↓Config) per STS-119 CONSUMABLES TRACKING CUE CARD

POST EVA EMU RECONFIG AND TRANSFER (90 min) (Cont)

- EMU 3004 12. Retrieve LTA Restraint strap and bag from Airlock Floor Bag
Remove EMU 3004 from fwd EDDA
Perform LTA Restraint installation
Stow EMU 3004 in Node 1 pending transfer

Swanson EMU Config

- EMU 3017 13. √DIDB Restraint Bag in HUT
Install Sw helmet, s/n 1071
Remove Helmet lights/TV assembly; stow on ISS
√Helmet locked, sun shades down, cover installed
14. Stow Sw ECOK and LCVG in HUT
Install LTA s/n 2057 (bladder s/n 007)
15. Retrieve LTA Restraint strap and bag
Remove EMU 3017 from aft EDDA
Perform LTA Restraint installation
Stow EMU 3017 in Node 1 pending transfer

EMU 3006 Config for ISS

- EMU 3006 16. Install EMU 3006 in fwd EDDA
17. Install 3005 in aft EDDA
18. Stow following in Airlock Floor Bag:
Transfer to Shuttle mesh bag
85-ft Safety Tethers – 2 (s/n 1001, 1004)
EMU Servicing Kit (s/n 5005)
19. Verify all items for transfer per table (next page):

POST EVA EMU RECONFIG AND TRANSFER (90 min) (Cont)

<p align="center"><u>EMU 3017 (Sw)</u></p> <input type="checkbox"/> DIDB Restraint Bag <input type="checkbox"/> Sw ECOK <input type="checkbox"/> Sw LCVG <input type="checkbox"/> Helmet s/n 1071 <input type="checkbox"/> EMU Gloves (Sw 1) <input type="checkbox"/> EMU Battery <input type="checkbox"/> CCC (LiOH) (used) <input type="checkbox"/> LTA <input type="checkbox"/> LTA Restraint and Strap	<p align="center"><u>EMU 3004 (An)</u></p> <input type="checkbox"/> DIDB Restraint Bag <input type="checkbox"/> An ECOK <input type="checkbox"/> An LCVG <input type="checkbox"/> Helmet s/n 1069 <input type="checkbox"/> EMU Gloves (An 1) <input type="checkbox"/> EMU Battery <input type="checkbox"/> CCC (LiOH) (used) <input type="checkbox"/> LTA <input type="checkbox"/> LTA Restraint and Strap
<p><u>ECOK (Sw)</u></p> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> EVA 1, 2, & 4 Ziplock Bags (less used items) <input type="checkbox"/> MAGs <input type="checkbox"/> TCUs (top, bottom) <input type="checkbox"/> Socks <input type="checkbox"/> Wristlets <input type="checkbox"/> Comfort Gloves <input type="checkbox"/> Flag, patch and EV1 stripes	<p><u>ECOK (An)</u></p> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> EVA 1, 3, & 4 Ziplock Bags (less used items) <input type="checkbox"/> MAGs <input type="checkbox"/> TCUs (top, bottom) <input type="checkbox"/> Socks <input type="checkbox"/> Wristlets <input type="checkbox"/> Comfort Gloves <input type="checkbox"/> Flag, patch and EV2 stripes
<p align="center">Airlock Floor Bag</p> <input type="checkbox"/> EMU Battery s/n 2037 <input type="checkbox"/> Ac ECOK: <input type="checkbox"/> <input type="checkbox"/> EVA 2 & 3 Ziplock Bags (less used items) <input type="checkbox"/> MAGs <input type="checkbox"/> TCUs (top, bottom) <input type="checkbox"/> Socks <input type="checkbox"/> Wristlets <input type="checkbox"/> Comfort Gloves <input type="checkbox"/> <input type="checkbox"/> Flag, patch and EV3 stripes <input type="checkbox"/> LCVG (Ac 1) <input type="checkbox"/> Comm Cap – 5 (Ac 1, Ac 2, Sw 1, Sw 2, An 1) <input type="checkbox"/> EMU Gloves 4 pair (Ac 1, Ac 2, Sw 2, An 2) <input type="checkbox"/> Cuff C/L – 3 (Ac, An, Sw) <input type="checkbox"/> Wrist Mirrors (6) <input type="checkbox"/> 85-ft Safety Tether (2) (s/n 1001, 1005) <input type="checkbox"/> EMU Servicing Kit (s/n 5005)	
<p align="center">Transfer to Shuttle Bag</p> <input type="checkbox"/> Torque wrench s/n 1007 <input type="checkbox"/> 4 locking strut aids	
<p>(Not Planned for Use)</p> <input type="checkbox"/> EMU LiOH Canister (2) <input type="checkbox"/> Crack Repair Pallet (2)	

20. Transfer following EVA equipment to Shuttle:

Item	Destination	Transfer Status
EMU 3017 (Sw)	Temp stow in Middeck	
EMU 3004 (An)	Temp stow in Middeck	
Airlock Floor Bag	Temp stow in Middeck	

21. Report transfer status to MCC

EVA UNPACK AND STOW (60 min)

NOTE

This procedure assumes that transfer items were preconfigured per EVA PREP FOR TRANSFER TO SHUTTLE

1. Unpack and stow items per table below; report status to MCC when complete:

Current Location	Item	Final Stowage Location	Status
Middeck	EMU 3017 (Sw)	External A/L (Stbd AAP)	
	EMU 3004 (An)	External A/L (Port AAP)	
Middeck (Airlock Floor Bag)	Comm Cap (Sw 1 & Sw 2)	EMU 3017 LTA Restraint Bag (kangaroo pouch)	
	Comm Cap (An 1 & Ac 1)	EMU 3004 LTA Restraint Bag (kangaroo pouch)	
	EMU Servicing Kit (s/n 5005)	Vol H Inboard (MD23R)	

This Page Intentionally Blank

TIMELINES

119 (15A) EVA OV BASELINE FS 7-3

EVA 1

- EVA 1 SUMMARY TIMELINE FS 7-5
- EVA 1 INHIBIT PAD..... FS 7-6
- EVA 1 NOTES, CAUTIONS, AND WARNINGS FS 7-8
- EVA 1 TOOL CONFIG FS 7-13
- EVA 1 A/L EGRESS AND SETUP..... FS 7-15
- EVA 1 ATTACH S6 TO S5..... FS 7-18
- EVA 1 CONNECT S5 TO S6 UMBILICALS..... FS 7-26
- EVA 1 RELEASE SABB RESTRAINTS..... FS 7-30
- EVA 1 PVR RADIATOR CINCHES AND WINCH RELEASE FS 7-34
- EVA 1 ROTATE IEA KEEL PIN AND RELEASE SAW BETA GIMBAL RESTRAINTS FS 7-36
- EVA 1 UNSTOW SABB, RELEASE MAST, AND REMOVE ECU/SSU SHROUD FS 7-42
- EVA 1 S6 MMOD SHIELD BOLT TORQUE RELEASE (GET-AHEAD) FS 7-46
- EVA 1 CLEANUP..... FS 7-48
- EVA 1 A/L INGRESS FS 7-49

EVA 2

- EVA 2 SUMMARY TIMELINE FS 7-53
- EVA 2 INHIBIT PAD..... FS 7-54
- EVA 2 NOTES, CAUTIONS, AND WARNINGS FS 7-57
- EVA 2 TOOL CONFIG FS 7-62
- EVA 2 A/L EGRESS AND SETUP FS 7-64
- EVA 2 BATTERY PREP FS 7-67
- EVA 2 P3 NADIR UCCAS DEPLOY FS 7-69
- EVA 2 P1 RBVM MLI REPAIR, P1/P3 FLUID JUMPER INSTALL, AND FHRC P-CLAMP RELEASE FS 7-73
- EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY FS 7-77
- EVA 2 TOOL STANCHION RELOCATE/APFR RETRIEVE FS 7-85
- EVA 2 CLEANUP/INGRESS..... FS 7-86

EVA 3

- EVA 3 SUMMARY TIMELINE FS 7-89
- EVA 3 INHIBIT PAD..... FS 7-91
- EVA 3 NOTES, CAUTIONS, AND WARNINGS FS 7-93
- EVA 3 TOOL CONFIG FS 7-98
- EVA 3 EGRESS..... FS 7-100
- EVA 3 SETUP..... FS 7-102
- EVA 3 CETA CART RELOCATION..... FS 7-103
- EVA 3 SPDM COVERS FS 7-108
- EVA 3 LEE B REPAIR FS 7-113
- EVA 3 S1/S3 SSAS PANEL BBC RECONFIG FS 7-122
- EVA 3 S1/S3 FLUID QD JUMPER INSTALL..... FS 7-123
- EVA 3 S1 FHRC P-CLAMP RELEASE..... FS 7-124
- EVA 3 S0 1A_D RPCM REMOVE/REPLACE FS 7-126
- EVA 3 P1 1A_A RPCM REMOVE/REPLACE..... FS 7-131
- EVA 3 CLEANUP..... FS 7-136
- EVA 3 A/L INGRESS FS 7-137

EVA 4

- EVA 4 SUMMARY TIMELINE FS 7-141
- EVA 4 INHIBIT PAD..... FS 7-142
- EVA 4 NOTES, CAUTIONS, AND WARNINGS FS 7-145
- EVA 4 TOOL CONFIG FS 7-150
- EVA 4 A/L EGRESS FS 7-152
- EVA 4 S1/P1 RADIATOR IMAGING..... FS 7-154

TIMELINES

EVA 4 JLP GPS ANTENNA INSTALL	FS 7-156
EVA 4 Z1 PATCH PANEL.....	FS 7-158
EVA 4 S3 TASK SETUP	FS 7-159
EVA 4 CP1 WETA INSTALL.....	FS 7-160
EVA 4 S3 OUTBOARD NADIR PAS DEPLOY	FS 7-164
EVA 4 S3 INBOARD ZENITH PAS DEPLOY	FS 7-168
EVA 4 CLEANUP/INGRESS.....	FS 7-175
GET-AHEADS	
S3 INBOARD NADIR PAS DEPLOY	FS 7-179
CONNECTOR INSULATING SLEEVE – CHANNEL 1/4 (S0)	FS 7-183
CONNECTOR INSULATING SLEEVE – MBS	FS 7-184
CONNECTOR INSULATING SLEEVE – SSPTS (NODE 1 FWD)	FS 7-185
CONNECTOR INSULATING SLEEVE – SSPTS (LAB FWD)	FS 7-186
CONNECTOR INSULATING SLEEVE – SSPTS (PMA2 PORT)	FS 7-187
CONNECTOR INSULATING SLEEVE – SSPTS (PMA2 STBD).....	FS 7-188

119 (15A) EVA OV BASELINE

	00:00	01:00	02:00	03:00	04:00	05:00	06:00	07:00			
EVA 1	Egr	Setup	Attach S6 to S5	Connect S5 to S6 Umbilicals	PVR Cinches & Winch Release	Keel Pin	BGA Release	Unstow Nadir (1B) SABB	SSU ECU MLI	Cleanup	Ing
	Egr	Setup	Attach S6 to S5	Connect S5 to S6 Umbilicals	Release SABB Restraints		Unstow Zenith (3B) SABB	SSU ECU MLI	Cleanup	Ing	
EVA 2	Egr	Setup	P6 Battery Prep	P3 Nadir UCCAS	P1 RBVM MLI	P1 FHRC Clamps	S3 Outboard/Zenith PAS	Tool Stanchion Relocate	Cleanup	Ing	
	Egr	Setup	P6 Battery Prep	P3 Nadir UCCAS	P1/P3 Fluid Jumper	P1 FHRC P-Clamps	S3 Outboard/Zenith PAS	APFR Retrieve	Cleanup	Ing	
EVA 3	Egr	Setup	CETA Cart Relocation	SPDM Covers		LEE B Repair		Cleanup	Ing		
	Egr	Setup	CETA Cart Relocation	S1 Tasks			S0 1A_D RPCM	P1 1A_D RPCM	Cleanup	Ing	
EVA 4	Egr	Set-up	JLP GPS Antenna B Install	Z1 Patch Panel	S3 Task Setup	CP1 WETA Install	S3 Outboard/Nadir PAS	S3 Inboard/Zenith PAS	Cleanup	Ing	
	Egr	Set-up	S1/P1 Radiator Imaging		S3 Task Setup	CP1 WETA Install	S3 Outboard/Nadir PAS	S3 Inboard/Zenith PAS	Cleanup	Ing	

119 (15A) EVA OV BASELINE (Cont)

Get-Aheads	Applicable EVAs:				Constraints:	Completed On:
	EVA 1	EVA 2	EVA 3	EVA 4		
S6 MMOD Shield Bolt Torque Release	X				Stbd SARJ locked	
Nadir/Inboard PAS Deploy		X	X	X	Stbd TRRJ & SARJ locked	
Return Adj Tether to Port Z1 TB	X	X	X	X	None	
Grounding Sleeve Install:						
SSPTS Node 1 FWD		X	X	X	Inhibits: RPCM Z1 3B_A2 and Z1 4B_A2	
SSPTS Lab FWD		X	X	X		
SSPTS PMA2 Port		X	X	X	Inhibits: RPCM LA 1A4A-D3 and Z1 4B_A2	
SSPTS PMA2 Starboard		X	X	X	Inhibits: RPCM LA 2A3B-D1 and Z1 3B_A2	
MBS Cables		X	X	X	For WS4: RPC S0 4B_A1 and S0 3A_A1	
Channel 1/4 CR 8018 Cable (W4148)			X		DDCU S0 1A; MT is over Bay 0 if access is through Face 1 then task not possible	

EVA 1 SUMMARY TIMELINE

PET HR : MIN	IV/SSRMS	EV1 – Swanson	EV2 – Arnold	PET HR : MIN
00:00	SSRMS: S6 Pre-Install setup	<u>EVA 1 POST DEPRESS, EGRESS & SETUP (00:50)</u> <ul style="list-style-type: none"> Post Depress/Egress (00:20) Setup (00:30) Translate to S5 (retrieve APFR from CETA cart) Install APFR in S5 WIF 11 	<u>EVA 1 POST DEPRESS, EGRESS & SETUP (00:50)</u> <ul style="list-style-type: none"> Post Depress/Egress (00:20) Setup (00:30) Translate to S5 Temp stow crewlock bag on S5 	00:00
01:00	SSRMS: S6 Pre-install Position SSRMS: GCA to first contact SSRMS: Limp after initial CLA contact	<u>ATTACH S6 to S5 (01:05)</u> <ul style="list-style-type: none"> RTAS Bolt 1 & 2 Check at 150 cm GCA at 30 cm GCA at 15 cm GCA to first contact Verify Impending CLA contact Bolt initial torque Bolt 1 and 3 final torque 	<u>ATTACH S6 to S5 (01:05)</u> <ul style="list-style-type: none"> RTAS Bolt 3 & 4 Check at 150 cm GCA at 30 cm GCA at 15 cm GCA to first contact Drive CLA Ground strap install Bolt 2 and 4 final torque Release CLA 	01:00
02:00	√MCC-H GO for S5 to S6 umbilicals √MCC-H in CMG Control	<u>CONNECT S5 to S6 UMBILICALS (00:55)</u> <ul style="list-style-type: none"> Connect umbilicals (4) Move APFR to S6 	<u>CONNECT S5 to S6 UMBILICALS (00:55)</u> <ul style="list-style-type: none"> Connect umbilicals (assist EV1) 	02:00
03:00	SSRMS: S6 ungrapple	<u>PVR CINCHES AND WINCH RELEASE (00:45)</u> <ul style="list-style-type: none"> Release cinches (6) Release winch PIP pin (2) 	<u>RELEASE SABB RESTRAINTS (01:35)</u> <ul style="list-style-type: none"> Release Nadir/Inboard SABB Release Nadir/Outboard SABB Release Zenith/Inboard SABB Release Zenith/Outboard SABB 	03:00
04:00		<u>KEEL PIN ROTATION (00:15)</u>		04:00
		<u>BGA RELEASE (00:30)</u> <ul style="list-style-type: none"> Release TA Clamps, Zenith BGA Bolts (00:15) Release TA Clamps, Nadir BGA Bolts (00:15) 		04:00
05:00		<u>UNSTOW NADIR (1B) SABB (01:00)</u> <ul style="list-style-type: none"> Deploy Nadir SABB Wing Release Mast Tip Fasteners 	<u>UNSTOW ZENITH (3B) SABB (01:00)</u> <ul style="list-style-type: none"> Deploy Zenith SABB Wing Release Mast Tip Fasteners 	05:00
06:00		<u>SSU AND ECU COVER REMOVAL (00:10)</u> <u>CLEANUP AND A/L INGRESS (00:55)</u>	<u>SSU AND ECU COVER REMOVAL (00:10)</u> <u>CLEANUP AND A/L INGRESS (00:55)</u>	06:00
	EVA 1 PET = 06:30 hr	<u>PRE-REPRESS (00:05)</u>	<u>PRE-REPRESS (00:05)</u>	06:00

EVA 1

EVA 1 INHIBIT PAD

Orbiter

ALL EVAs
TCS L12 1. √TCS POWER – OFF
KU-BAND ANTENNA {Performed during egress}
MCC-H 1. √KU-BAND Mask – active 2. √KU-BAND EVA Protect Box – active

Ground

ALL EVAs
Ground Radar
MCC-H 1. √TOPO console, ground radar restrictions in place of EVA

USOS (1)

ALL EVAs
PCU
<p style="text-align: center;"><u>NOTE</u> PCUs may require up to a 1-hr warmup period before they are operational</p>
MCC-H 1. √PCUs (two) operational in discharge mode and one of the following: a. CCS PCU EVA hazard control FDIR enabled b. No more than two arrays unshunted and oriented < 105° from velocity vector If one or both PCUs failed 2. No more than two arrays unshunted and oriented < 105° from velocity vector
EuTEF COL-CC Verify PLEGPAY Power Status (ETF_PLEGPAY_Pwr_Stat) – OFF
LOCATION DEPENDENT INHIBITS
Lab Window {On call, EV crew not expected to be in this area} IV If EV crew less than 10 ft from window or in window FOV, close window shutter
KU-Band (SGANT) Antenna {On call, EV crew not expected to be in this area} MCC-H If EV crew < 3.3 ft from KU-BAND antenna 1. Park KU-BAND: 1.1 Pointing Mode – Inhibit 1.2 PLC – Reset 1.3 Autotrack Continuous Retry – Inhibit
Mobile Transporter MCC-H 1. √MT latched

EVA 1 INHIBIT PAD (Cont)

USOS (2)

EVA 1 SPECIFIC INHIBITS	
S6 TO S5 MATE {Expect inhibits in place prior to egress}	
MCC-H	1. MBSU 1 RBI 8 – Open, Close Cmd Inhibit 2. MBSU 3 RBI 8 – Open, Close Cmd Inhibit
MCC-H	For EV crew working outboard of starboard SARJ: Lock starboard SARJ at 110 deg and port SARJ at desired angle: 1. √DLA (1) – LOCKED 2. All motor set points set to zero 3. All motors deselected OR 4. Both DLAs – LOCKED
STBD TRRJ	
MCC-H	1. √DLA (1) – LOCKED

RSOS (1)

ALL EVAs	
SM Antennas	
IV	1. GTS – Deactivate 2. ARISS (Ham Radio) – Deactivate or VHF (144-146 MHz) TX only

USOS (3)

EVA LOCATION DEPENDENT INHIBITS	
S-Band (SASA) Antennas {On call, EV crew not expected to be in this area}	
MCC-H	If EV crew < 3.6 ft from S1 SASA [P1 SASA] 1. P1 SASA (S1 SASA) – Active 2. S1 SASA [P1 SASA] – Powered down
FPMU {On call, EV crew not expected to be in this area}	
MCC-H	If EV crew working within 5 ft of Floating Potential Measurement Unit 1. FPMU power – Off
SSPTS {On call, EV crew not expected to be in this area}	
MCC-H	If EV crew working within 2 ft of SSPTS cables 1. RPCM LA1A4A D RPC 3 – Open, Close Cmd Inhibit 2. RPCM LA2A3B D RPC 1 – Open, Close Cmd Inhibit 3. RPCM Z14B A RPC 2 – Open, Close Cmd Inhibit 4. RPCM Z13B A RPC 2 – Open, Close Cmd Inhibit
BGA	
MCC-H	S4 BGAs will be locked at the following angles: *1. 1A Solar Array – +125 thru +230 deg 2. 3A Solar Array – +270 deg *Pre-flight analysis determined any angle in this range is compatible with Phalcon, ROBO and EVA operations

EVA 1 NOTES, CAUTIONS, AND WARNINGS

NOTES

1. Bolt install: Report torque and turns
Bolt release: Report torque and turns
(if different from published range)
2. EVA connectors: After dis-connection and prior to connection; verify pin and EMI band integrity. Verify connector free of FOD
3. Inspect Fluid QDs for damage, prior to mating
4. Toolbox doors must be closed with one latch per door, when EV crew not in immediate vicinity
5. Avoid contact with OBSS striker bars (Vitrolube coating)

CAUTION

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture shafts (drylube)
 2. PIP pins
 3. EVA Crane [PMA1]
 4. TCS Reflectors [PMA2,PMA3]
 5. APAS hardware [PMA2,PMA3]
 6. CETA Lights (Z-93 paint) [LAB,S1,Node 1]
 7. Deployed MISSEs [Columbus EPF]
 8. Passive UMAs
 9. MBS/SSRMS/SPDM/JEMRMS taped radiative surfaces: VDU, ACU, JEU, LEU, MCU, CRPCMs, and Cameras
 10. Deployed TUS cable [Nadir CETA rail]
 11. S0 aft face Radiator
 12. GPS Antennas (S13 paint) [S0,JLP]
 13. UHF Antennas [LAB,P1]
 14. ETCS Radiator flexhoses and panels [S1,P1]
 15. EETCS/PV Radiator flexhoses, bellows and panels [P6,P4,S4,S6]
 16. SASA RF Group [S1,P1]
 17. Heat pipe radiators [Z1]
 18. PCU cathode and HCA ports [Z1]
 19. Ku-Band Antenna (SGANT) dish [Z1]
 20. CMG cover/shells [Z1]
 21. SPDM SJEU, EP, OTCM, LEU, and LEE VDU Radiator surfaces
 22. Open CBM petal covers, LAB window shutter, and JPM window shutter
 23. FPMU [S1]
 24. OTSD
 25. COL HAM radio antennas [COL-Nadir]
 26. JTVE Cameras [JEM]
 27. JEM A/L Target and Pins
 28. S0/Node 2 Fluid Tray Hardlines at Node 2 end are limited to 25 lb

CAUTION (Cont)

ISS Constraints (Cont)

- B. Electrical cables
1. Avoid bend radii < 10 times cable diameter
- C. Fiber optic cables
1. Avoid bend radii < 10 times cable diameter
 2. Avoid pulling on cable during mate/demate
- D. Fluid line flex hoses and QDs
1. Avoid bend radii < 5 in for hoses with diameter < 1 in on LAB, S0, S1, P1, and 10-in for hoses with diameter < 1 in on all other elements
 2. Avoid bend radii < 14 in for hoses with a diameter ≥ 1 in
 3. Additional care should be taken to not exceed bend radii when applying loads at the flexible hose to rigid tube stub interfaces
 4. Ensure fluid QD booties are fully closed prior to leaving worksite; wire tie if reqd
- E. For structural reasons
1. Avoid vigorous body motions, quick grabs and kickoffs against tether restraints
 2. Avoid performing shaking motions (sinusoidal functions) more than four cycles
 3. Avoid kicking S1/P1 radiator beam
If any of these occur, wait 2 to 5 min to allow structural response to dissipate

EVA 1 NOTES, CAUTIONS, AND WARNINGS (Cont)

CAUTION (Cont)

ISS Constraints (Cont)

F. Other

1. ITT Cannon connector: On demated connectors, do not rotate collar or manipulate cable/connector using collar or connector tool
2. WIS Antennas: Do not use as handholds [Node 1,P6,Z1]
3. Lubricant from Ku-Band SGANT gimbals [Z1], CMGs [Z1], and RTAS Ground Strap fasteners [P6,P4,S4] can contaminate EMU
4. MLI handholds are not rated for crewmember translation loads
5. CBM petal covers may not be used as handholds unless both launch restraint pins are engaged
6. Prevent inadvertent contact of the tether shuttle with ETRS when the P3/S3 Tether Shuttle Stop is raised away from the rail

CAUTION (Cont)

Shuttle Constraints

A. Avoid inadvertent contact with

1. OBSS and SRMS Composite Sections, Joint Torque Arms, Grapple Fixture Shafts, and Cable Harnesses
2. LCS (silver Teflon) and LDRI (silver Teflon) and ITVC (gold foil) [OBSS]
3. WVS Antenna [ODS Truss & PLB Sill]
4. Payload Bay and Camera wire harnesses, cables, cable guides, and connectors

B. No touch

1. LDRI diffuser [OBSS]
2. OBSS saddle contacts (when OBSS unberthed) [OBSS]
3. Monkey fur [PLB]
4. Cameras: Metallic surfaces [PLB]
5. Ku-Band Antenna black dish and gold thermal blankets [PLB]

EVA 1 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture targets and target pins
 2. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off
 3. Stay inboard of SARJ when active
 4. Stay 2 ft from S1/P1 radiator beam rotational envelope when beam is free to rotate
 5. Stay 5 ft from moving MT on face 1
 6. SOLAR and EuTEF [COL EPF]
- B. Handrails
1. Handrails previously used for MISSE attachment may not be used as a safety tether point [A/L endcone 564 & 566, A/L Tank 2 nad/fwd & port/fwd, P6 5389]
- C. Pinch
1. NZGL connector linkage. Use caution when mating/locking
 2. ITT Cannon Connector rotating housing
 3. EV side of IV Hatch during Hatch operation (also snag hazard) [A/L]
 4. LAB window shutter and CBM petal cover and JPM window shutter linkages during operation
 5. JEMRMS HRM capture latches
 6. JEM Cameras (JTVEs, EVE, WVE)
 7. JEM EFBM capture latches
- D. QDs
1. If QD is in FID when valve is opened (bail fwd), QD will leak and fluid line may whip
 2. Do not rotate if in mated/valve open config

WARNING (Cont)

ISS Constraints (Cont)

- E. RF radiation exposure
1. Stay 3.6 ft from S-Band (SASA) high gain Antenna when powered [S1,P1]
 2. Stay 1.3 ft from S-Band (SASA) low gain Antenna when powered [S1,P1]
 3. Stay 1 ft from UHF Antenna when powered [LAB,P1]
 4. Stay 0.3 ft from fwd/aft JPM PROX antenna
- F. Sharp Edges
1. Inner edges of WIF sockets
 2. APFR active WIF probes
 3. Mating surfaces of EVA connectors
Avoid side loads during connector mating
 4. Back side of MMOD shield fasteners
 5. Spring loaded captive EVA fasteners (e.g., 6B-boxes, BMRRM, RTAS, SARJ Covers); the end of the spring may protrude
 6. PMA umbilical launch restraints-exposed bolt threads
 7. Adjustable Fuse Tether (Fish Stringer) buckles stowed in Node Bag
 8. Nickel coated braided copper Ground Straps may contain frayed wires [P6,P4,S4,S6]
 9. SPDM OTCM gripper jaws

WARNING (Cont)

ISS Constraints (Cont)

- F. Sharp Edges (Cont)
10. Solar Array Blanket Box [P6,S6]
 11. Keep hands away from SSRMS LEE/POA/SPDM LEE/JEMRMS EE opening, snares, and PDGF curvic coupling (teeth)
 12. Fastener threads on back of Z1 U-jumper male FQD panel, if nutplate cap missing
 13. Outboard MT rail attachment lug near P6 handrail 5333 and gap spanner
 14. P2 connector on EWIS box TAA-06 [Zenith/Forward Corner 1 of P5 – SARJ at 0 deg]
 15. Port/Aft portion of A/L circular HR [HR 0506]
 16. Interior of JEMRMS HRMs
 17. JEM A/L hatch corners
- G. Thermal
1. EVA connectors with booties may become hot if left uncovered. Handling may need to be limited
 2. PMA handrails may be hot. Handling may need to be limited
 3. Turn off glove heaters when comfortable temp reached to prevent bladder damage. Do not pull fingers out of gloves when heaters are on
 4. Uncovered trunnion pins may be hot
 5. SSRMS/MBS/SPDM/JEMRMS/JTV operating cameras and lights may radiate large amounts of heat

EVA 1 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING (Cont)

ISS Constraints (Cont)

G. Thermal (Cont)

6. Stay ≥ 1 ft away from PMAs and MMOD shields > 270 degF if EMU sun visor up; limit time to 15 min or less if > 300 degF
7. Stay at least 0.5 ft away from PMA and MMOD shields > 325 degF
8. Do not touch EMU protective visor if temp has been < -134 degF for > 15 min
9. No EMU TMG contact with PMAs and MMOD shields > 320 degF
10. No EMU boot contact with foot restraint when temp < -120 degF or > 200 degF
11. Columbus end cones may violate touch temperature constraints when $-75 \leq \beta \leq -60$ or $60 \leq \beta \leq 75$
12. PDGF surfaces may not meet touch temperature requirements for unlimited contact when $\beta \leq -70$ or $\beta \geq 70$
13. JPM port end cones and JLP port nadir may violate touch temperature constraints when $\beta > 60$ deg

WARNING (Cont)

ISS Constraints (Cont)

H. Electrical Shock

1. Stay ≥ 2 ft from ungrounded floating connectors if not unpowered
 - SSPTS connectors include NOD1 Stbd/Fwd HR 0130, Lab Stbd/Fwd HR 0273, PMA2 Stbd and Port
 - MBS Cross-Connect jumpers (translate past these using UMA handrails) Include S0 EVA Power Cables (inside S0 Bay 00 Face 4, Bay 01 Face 3) ESP2 jumper (inside S0 Bay 03 Face 4)
2. Do not touch SPDM CLPA 1 electrical connector prior to camera installation

WARNING (Cont)

Shuttle Constraints

A. Arcing/Molten Debris

1. Stay ≥ 2 ft from exposed EFGF connector when OBSS berthed, powered, and EFGF not grappled [PLB]
2. Stay ≥ 2 ft from exposed Stbd Fwd MPM contacts [PLB]
3. Stay above PLB sill when within 1 ft of powered ROEU connector [PLB]

B. Pinch

1. PRLA operation [PLB]

C. RF radiation exposure

1. Stay 3.28 ft from S-Band Antenna when powered
2. Stay 1 ft from top and side of UHF PLB Antenna radome surface when in high powered mode [ODS truss]
3. Stay 0.33 ft from top and side of UHF PLB Antenna radome surface when in low powered mode [ODS truss]
4. Remain below the level of the PLB door mold line for first 20 in Aft of Fwd bulkhead when S-Band Antenna powered [PLB]
5. Remain on the inboard side of the Stbd slidewire (sill handrails if slidewire not installed) for first 20 ft Aft of Fwd bulkhead when Ku-Band Antenna powered [PLB]

EVA 1 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING (Cont)

Shuttle Constraints (Cont)

D. Sharp Edges

1. PRLA grounding wipers [PLB]
2. LDRI baffles (also an entrapment hazard) [OBSS]
3. Keep hands away from SRMS EE opening and snares
4. TCS connector backshells have exposed threads [ODS]

E. Thermal

1. Illuminated PLB lights; do not touch
2. OBSS grapple fixture shafts/cams may be hot. Limit handling if required
3. Stay 27 ft from PRCS when powered
4. Stay 3 ft from VRCS when powered
5. Stay 3 ft from APU when operating

F. Contamination

1. Stay out of the immediate vicinity of leaking jet or APU

G. Lasers

1. Do not look at LDRI diffuser or LCS laser aperture window

EVA 1 TOOL CONFIG (00:30)

EV1

EMU D-rings

- 2 – D-ring Tether Extenders
- 1 – Waist Tethers [right D-ring extender]

- 1 – 85-ft Safety Tether [right D-ring extender]

MWS

- Small trash bag [right inside]
- 1 – Adj tether
- 1 – RET (sm-sm) [left]
- 1 – 5/8-7.8-in socket ext
 - 1 – RET w/PIP pin
- 2 – Wire ties
- Swing Arm [right side]
 - PGT (no socket installed) s/n _____
 - 1 – RET (sm-sm)
- BRT [left side]
 - 2 – Wire ties (short)
 - 1 – RET (sm-sm)

- SAFER

EV2

EMU D-rings

- 2 – D-ring Tether Extenders
- 1 – Waist Tethers [right D-ring extender]

- 1 – 85-ft Safety Tether [right D-ring extender]

MWS

- Small trash bag [right inside]
- 1 – RET (sm-sm) [left]
- 1 – RET(w/PIP pin) [right]
- 2 – Wire ties
- Swing Arm [right side]
 - PGT w/7/16-6-in wobble ext s/n _____
 - 1 – RET (sm-sm)
- BRT [left side]
 - 2 – Wire ties (short)
 - 1 – RET (sm-sm)

- SAFER

CREWLOCK

- RET (Lg-Sm) [between Crewlock Bag outside TP and Crewlock internal HR]
- Crewlock Bag #1
 - 2 – Adjustable Tethers to outside TPs [tethers used to secure Torque Wrench MLI Bag to outside of Crewlock Bag]
 - Torque Wrench (preset to 57 ft-lb) [int RET #1 to Torque Wrench handle]
 - Torque Wrench Bag
 - EV1 spare 85-ft ST [outside TPs]
 - EV2 spare 85-ft ST [outside TPs]
 - Ratchet Wrench [int RET #2]
 - 5/8-7.8-in extension
 - Socket Caddy [int RET #3]
 - 7/16-6-in wobble extension
 - 7/16-2-in rigid ext
 - Round TM w/5/8 Prd Socket [int RET #4]
 - Cannon connector tools (2)
 - 2 – RET (sm-sm) to int TPs
 - EVA Camera w/bracket & int RET
 - 1 – RET (sm-sm) to int TP
 - Adj tether on outside of bag (temp stow)

- Tether ext on A/L D-ring

NOTE: Prior to use, inspect the following hardware:

- RET cords for fraying
- Safety Tether & Waist Tether load alleviating straps: No red visible
- Sm Trash Bag: Bristle deformation/damage, after stowing tools in trash bag

Use Blue RETs only		(total)
RET Counts (blue group):	<u>used</u>	(ISS qty)
RETs (sm-sm)	= 10	(16)
RETs (PIP pin)	= 2	(5)
RETs (lg-sm)	= 1	(8)
Adj Eq Tethers	= 4	(10)
8 Adj (sm-sm) on ISS, 2 from STS		
D-ring Tether Extenders	= 5	(6)

Bag Color Key: **119 EVA Tools**, **Staging**, **Crewlock** **MWS** **Shuttle**

EVA 1 TOOL CONFIG (00:30) (Cont)

CREWLOCK (Cont)

Staging Bag

- Fish Stringer #1
 - Wire Tie Caddy (hook #1)
 - 9 wire ties
 - Velcro/Tape Caddy (hook #2)
 - PGT (hook #3) s/n 1008
 - PGT Battery s/n _____
 - 7/16-in (wobble) Socket-6 ext
 - Vise Grips (hook #4)
 - Ratchet Wrench (hook #5)
 - 7/16-in (rigid) Socket-9 ext
 - Cheater Bar (hook #6)
 - Hammer (hook #7)
 - Spare 55-ft Safety Tether (to strap)
- Fish Stringer #2
 - Connector Cleaner Tool Kit (hook #1)
 - Pin Straightener Assy (hook #2)
 - Probe (hook #3)
 - Pry Bar (hook #4)
 - Needle Nose Pliers (hook #5)
 - Spare Torque Wrench w/bag (set @ 57 ft-lb) (hook #6)
 - Locking Strut Aid #1 s/n _____ (hook #7)
 - RET (between Locking Strut Aid TPs)
 - Locking Strut Aid #2 s/n _____
 - 2 Long-Duration Tie-Down Tethers (to strap)
 - MWS Key Strap Assy (on wire tie, to strap)

IV Bag

- 2 – Towels
- Contamination Detection Kit
- 2 – GP Caddy
 - 2 – Adjustable Thermal Mittens
- Socket Caddy (hatch cont) w/RET (sm-sm, blk)
- 1/2-in Socket-8 ext
- 7/16-in (wobble) Socket-6 ext (spare)
- 2 – DCM Plug (SAFER Hardmount)
- 2 – RET (sm-sm, black)

Mesh Bag #1 (119 EVA Tools)

- WIF Adapter
- 4 – EVA Wipes
- Ratchet Wrench
 - 7/16-in x 2 ext socket
- RCC Gap Gauge
- Gap Spanner (72-in)
- Sm Trash bag
- Grease Gun
 - EVA Wipe & WireTie
- Ziplock Bag w/grease gun caps
- 2 – Wire Ties (short)
- 2 – Wire Ties (long)
- BRS Pin Tool
- BRS Pin Tool Sheath

Mesh Bag #2 Done Tools

Empty

Mesh Bag #3 Transfer to Shuttle

- Locking Strut Aids (2)

Crewlock Bag #2

- Round Scoop
- RPCM s/n C326597

Crewlock Bag #3

- Ratchet Wrench
 - 7/16-in x 2 ext socket
- RET w/PIP pin
 - 7/16-in x 18 ext socket
- Gap Spanner 72 (2)
- Gap Spanner 45 (2)

Crewlock Bag #4

- Round Scoop
- RPCM s/n C235299

- Review PGT ops
 - Report “green light” (for torque down ops)
 - Report torque and turns
 - Expect LOTORQ fault msg, Fault LED and Red LED for bolt release ops

Medium ORU Bag

Empty

Medium ORU Bag

- Fish Stringer
- JLP GPS Antenna


Small ORU Bag

Empty

- WETA

Bag Color Key: 119 EVA Tools, Staging, Crewlock, MWS, Shuttle

EVA 1 A/L EGRESS AND SETUP (00:50)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
 <div data-bbox="121 743 682 933" style="border: 1px solid black; padding: 5px;"> <p>1 – 85-ft A/L tether – EV1 > EMU 1 – 85-ft A/L tether – EV2 > EMU</p> <p>1 – 85-ft TS tether – EV1 > Crewlock Bag 1 – 85-ft TS tether – EV2 > Crewlock Bag</p> </div> <p>EVA PET = ____ : ____</p> <p>Start Torque Wrench thermal clock (03:30 hr max): GMT = ____ : ____ : ____</p> <p>1. Post crew egress: WVS Software: Select page – RF Camera sel ‘Advanced controls’ S-Band level (two) – max</p>	<p>INITIAL CONFIG</p> <p>Verify:</p> <ul style="list-style-type: none"> <input type="checkbox"/> EV1 right waist tether connected to EV2’s 85-ft safety tether <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed (both hooks) <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked (both hooks) <input type="checkbox"/> <input checked="" type="checkbox"/> Safety Tether Reel unlocked <p>EGRESS (00:20)</p> <ol style="list-style-type: none"> 1. Open hatch thermal cover 2. Egress crewlock 3. Verify EV2 SAFER Configuration: <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> R Handle down (HCM door – Closed) <input type="checkbox"/> <input checked="" type="checkbox"/> L Handle down (MAN ISO Valve – Open) 4. Translate to S1/S3 tether swap location (S1 nadir-forward, near CP3; fairlead safety tether forward of CETA Light) 5. Attach EV1 85-ft safety tether hook to S1 HR 3215 (position up and out of the way for EV2 translation) <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked <input type="checkbox"/> <input checked="" type="checkbox"/> Safety Tether Reel unlocked 6. Attach EV2 85-ft safety tether hook to S1 HR 3222 <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked <input type="checkbox"/> <input checked="" type="checkbox"/> Safety Tether Reel unlocked 	<p>INITIAL CONFIG</p> <p>Verify:</p> <ul style="list-style-type: none"> <input type="checkbox"/> EV2 right waist tether connected to Airlock D-ring extender <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked <p>EGRESS (00:20)</p> <ol style="list-style-type: none"> 1. RET and attach Crewlock Bag to BRT 2. Egress crewlock (IV records GMT start of Torque Wrench thermal clock) 3. Verify EV1 SAFER Configuration: <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> R Handle down (HCM door – Closed) <input type="checkbox"/> <input checked="" type="checkbox"/> L Handle down (MAN ISO Valve – Open)

EVA 1 A/L EGRESS AND SETUP (00:50) (Cont)


IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
<p style="text-align: center;"><u>NOTE</u></p> <p>Sunrise/Sunset checks</p> <ul style="list-style-type: none"> • √Helmet lts, visor, as reqd • √Gloves, gauntlets • √Tool, MWS tethers • √MWS, BRT latches 	<p><u>EGRESS</u> (00:30) (Cont)</p> <ol style="list-style-type: none"> 7. Release EV1 waist tether from EV2 safety tether 8. Give EV2 GO to release EV2 waist tether from airlock D-ring 	<p><u>EGRESS</u> (00:30) (Cont)</p> <ol style="list-style-type: none"> 4. On EV1 GO, release right waist tether from airlock D-ring 5. Close hatch thermal cover 6. Perform translation adaptation, as reqd

WARNING
 2-ft Keep-Out Zone for floating cables between MT and MBS. Stay on UMA handrails during translation underneath MT

EVA 1 A/L EGRESS AND SETUP (00:50) (Cont)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
<p><input type="checkbox"/> IV verify with MCC-H:</p> <ul style="list-style-type: none"> All required EVA 1 inhibits are in place <ul style="list-style-type: none"> 3A Solar Array @ +270 deg 1A Solar Array @ +125 to +230 deg (provides clearance for EVA and ROBO ops) 	<p><u>SETUP</u> (00:30)</p> <div style="border: 3px double black; padding: 5px; text-align: center; margin: 10px 0;"> <p>WARNING Collision hazard. Stay inboard of the S5 stbd plane to avoid interference/contact w/S6 and SSRMS unless needed to work Ready to Mate Verification</p> </div> <ol style="list-style-type: none"> Translate to CETA Cart #2 (outboard cart) Retrieve APFR w/ingress aid from CETA Cart 2 WIF 01 (port-nadir corner): Pre-configure APFR [QQ,C,11] Before release, attach APFR to BRT RET Translate to S5 umbilical connector loc (S5 stbd-fwd) Release Utility Panel TA clamps on cables J159 and J160, as reqd (up to 6) <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Install APFR in S5 WIF 5 (near S5 HR 2117): APFR [10,QQ,C,11] <input type="checkbox"/> √Blk-Blk, pull/twist test Translate zenith to Crewlock Bag, stowed at S5 HR 2122 – HR 2125 Retrieve spare 85-ft safety tether, stow on MWS Translate to S4/S5 tether swap location (near S5 HR 2102 – aft-nadir-middle HR) Attach spare 85-ft safety tether to S5 HR 2114 Leave primary 85-ft safety tether at S5 HR 2107 Perform Safety Tether swap. Verify tether config: <input type="checkbox"/> <input type="checkbox"/> √Gate closed <input type="checkbox"/> <input type="checkbox"/> √Hook locked <input type="checkbox"/> <input type="checkbox"/> √Safety Tether Reel unlocked Translate to S5 aft-nadir, Bolt 1 then Bolt 2 location (fairlead, as reqd) 	<p><u>SETUP</u> (00:30)</p> <ol style="list-style-type: none"> Translate to S5 safety tether swap location (EV1 anchored EV2 safety tether hook at S1 HR 3222) Temp stow Crewlock Bag at S5 HR 2122 – HR 2125 (located zenith-aft) Retrieve spare 85-ft safety tether, stow on MWS Configure EVA camera on outside of Crewlock Bag Translate to S5 RTAS Bolt 3 location (zenith-aft) Verify S6 is at the 150 cm pre-install position Perform READY TO MATE VERIFICATION steps (5) on next page for Bolt 3 (aft) Translate forward to S4/S5 tether swap location (near S5 HR 2108 – port-zenith-forward HR) Attach spare 85-ft safety tether to S5 HR 2116 Leave primary 85-ft safety tether at S4 HR 2116 Perform Safety Tether swap. Verify tether config: <input type="checkbox"/> <input type="checkbox"/> √Gate closed <input type="checkbox"/> <input type="checkbox"/> √Hook locked <input type="checkbox"/> <input type="checkbox"/> √Safety Tether Reel unlocked Translate to S5 zenith-forward (RTAS Bolt 4)

EVA 1 ATTACH S6 TO S5 (01:05)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)																													
<p>Current S6 location: 150 cm stbd (away) from S5 (Pre-Install Setup Position)</p>  <p>S6 Port End as Viewed from S5 Looking Starboard (RTAS bolts are on the S5 side)</p> <ol style="list-style-type: none"> 1. Notify M1 approaching S6 mate (on ICOM) 2. Obtain glove inspection report from EV1 and EV2 	<p><u>READY TO MATE VERIFICATION</u></p> <ol style="list-style-type: none"> 1. Translate to Corner 1 (may go to Corner 2 first) 2. Verify S6 is at the 150 cm pre-install position 3. Perform READY TO MATE VERIFICATION steps (5) for Bolts 1 and 2: <table border="1" data-bbox="787 755 1932 966"> <thead> <tr> <th rowspan="2">READY TO MATE VERIFICATION</th> <th colspan="2">EV1</th> <th colspan="2">EV2</th> </tr> <tr> <th>Bolt 1</th> <th>Bolt 2</th> <th>Bolt 3</th> <th>Bolt 4</th> </tr> </thead> <tbody> <tr> <td>1. √S5 RTAS Primary bolt below fine alignment cone plane</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>2. √S5 RTAS 2-7 threads visible by bolt shoulder</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>3. √S6 RTAS Contingency ball/nuts (2) centered</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>4. √S5-S6 mating interface free of debris</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </tbody> </table> <ol style="list-style-type: none"> 4. Remain at Corner 1 5. EV1 perform glove/gauntlet inspection, report status 	READY TO MATE VERIFICATION	EV1		EV2		Bolt 1	Bolt 2	Bolt 3	Bolt 4	1. √S5 RTAS Primary bolt below fine alignment cone plane	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	2. √S5 RTAS 2-7 threads visible by bolt shoulder	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	3. √S6 RTAS Contingency ball/nuts (2) centered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4. √S5-S6 mating interface free of debris	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<p><u>READY TO MATE VERIFICATION</u></p> <ol style="list-style-type: none"> 1. Translate to Corner 4 2. Verify S6 is at the 150 cm pre-install position 3. Perform READY TO MATE VERIFICATION steps (5) for Bolt 4: (also perform for Bolt 3, if not done) <ol style="list-style-type: none"> 4. Remain at Corner 4 5. EV2 perform glove/gauntlet inspection, report status
READY TO MATE VERIFICATION	EV1		EV2																												
	Bolt 1	Bolt 2	Bolt 3	Bolt 4																											
1. √S5 RTAS Primary bolt below fine alignment cone plane	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																											
2. √S5 RTAS 2-7 threads visible by bolt shoulder	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																											
3. √S6 RTAS Contingency ball/nuts (2) centered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																											
4. √S5-S6 mating interface free of debris	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>																											

EVA 1 ATTACH S6 TO S5 (01:05) (Cont)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)								
<p><input type="checkbox"/> √EV1, EV2 ready for mnvr from 150 cm to 30 cm position</p> <p>3. Hand over comm. to M1/M2 for “Alignment 1” maneuver pre-brief</p> <p style="text-align: center;"><u>NOTE</u></p> <p>Check periodically with EV2 for clearance between nadir-pointed S5 FRGF and S6.</p> <p>When SSRMS is in limp mode and EV2 is driving the CLA, M2 will report “good comm.” at ~10 sec intervals. EV2 will stop driving the CLA immediately if he fails to receive the “good comm.” report from M2 after 2 turns of the PGT (~12 sec), or if “Cease Drive” is called</p> <p><input type="checkbox"/> √M1 GO to drive CLA to point just prior to contact [SSRMS is in standby] (CLA drive interface access from zenith-stbd end of S5)</p> <p>4. Verify Topological capture with EV1</p> <p>5. Give M1/M1 GO for Limp mode. <input type="checkbox"/> √SSRMS in Limp mode</p> <p>6. Give CLA closure Prebrief to indicate “All Stop” protocol</p> <p>7. Give EV GO to drive CLA to hard stop</p> <p style="text-align: center;"><u>NOTE</u></p> <p>Gap between all four S6 and S5 housing surfaces must be < 0.6 in prior to primary bolt driving</p>	<p><u>CLEARANCE AND ALIGNMENT VERIFICATIONS</u></p> <ol style="list-style-type: none"> 1. Monitor clearances as required (S5 FRGF to S6) Install 5/8-7.8-in socket on PGT (stowed in trash bag) 2. Participate in M2 maneuver pre-brief, acknowledge items 3. Verify tools and tethers clear from S5/S6 interface <p>Give M1/M2 GO to maneuver SSRMS to alignment position:</p> <ol style="list-style-type: none"> 4. 30 cm position. Monitor motion and clearances. At 30 cm: Give M1/M2 alignment corrections, as reqd 5. 15 cm position. Monitor motion and clearances. At 15 cm: Give M1/M2 alignment corrections, as reqd 6. Give M1/M2 GO to maneuver to first contact. Monitor motion and clearances, and call at first contact. (If alignment correction needed, backout to 15 cm position. Monitor motion and clearances. Repeat step 6) 7. √All four alignment pins are within alignment cups <p><u>ENGAGE S5 CAPTURE LATCH</u></p> <div style="border: 3px double black; padding: 5px; text-align: center;"> <p><u>WARNING</u></p> <p>EV crewmembers must remain clear of S6/S5 mating interface. Pinch Hazard. Area between S6 and S5 must be clear prior to latch actuation to prevent crew injury</p> </div> <ol style="list-style-type: none"> 8. Position to monitor capture latch motion (plan is to make call, just prior to first contact) 9. Prior to contact, report “CLA About To Touch” 10. Monitor CLA motion 11. √Gap with small equip hook on corners 1 and 2 <table border="1" style="width: 100%; text-align: center;"> <tr> <td style="width: 25%;">Corner 1</td> <td style="width: 25%;"><input type="checkbox"/></td> <td style="width: 25%;">Corner 2</td> <td style="width: 25%;"><input type="checkbox"/></td> </tr> </table>	Corner 1	<input type="checkbox"/>	Corner 2	<input type="checkbox"/>	<p style="text-align: center;"><u>ENGAGE S5 CAPTURE LATCH</u></p> <ol style="list-style-type: none"> 6. BRT to S5 HR 2122, as reqd (head in first, for access to CLA drive) 7. Drive S5 CLA: PGT, 7/16-6-in ext: [A6 8.3 ft-lb, CW2 30 rpm, MTL 30.5]; until EV1 call “CLA Impending Contact” (~20 turns) Turns: _____ <p>On IV GO, confirming SSRMS is in Limp Mode</p> <ol style="list-style-type: none"> 8. Drive S5 CLA: PGT, 7/16-6-in ext: [A6 8.3 ft-lb, CW1 10 rpm, MTL 30.5]; to hard stop (~106 turns) Turns/Torque: Turns: _____ Torque: _____ 9. √Gap with small equip hook on corners 3 and 4 <table border="1" style="width: 100%; text-align: center;"> <tr> <td style="width: 25%;">Corner 3</td> <td style="width: 25%;"><input type="checkbox"/></td> <td style="width: 25%;">Corner 4</td> <td style="width: 25%;"><input type="checkbox"/></td> </tr> </table>	Corner 3	<input type="checkbox"/>	Corner 4	<input type="checkbox"/>
Corner 1	<input type="checkbox"/>	Corner 2	<input type="checkbox"/>							
Corner 3	<input type="checkbox"/>	Corner 4	<input type="checkbox"/>							

EVA 1 ATTACH S6 TO S5 (01:05) (Cont)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)																																													
<p style="text-align: center;"><u>NOTE</u> Gap between all four S6 and S5 housing surfaces must be < 0.478 inch after primary bolt seating</p> <div style="text-align: center;"> </div> <p style="text-align: center;">S6 Port End as Viewed from S5 Looking Starboard (RTAS bolts are on the S5 side)</p> <p style="text-align: center;"><u>NOTE</u> Once 4 of 4 RTAS bolts are tightened to initial torque, EV1 and EV2 are GO for translation on S6 truss</p>	<p style="text-align: center;"><u>RTAS BOLTS INITIAL TORQUE</u></p> <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;"><u>CAUTION</u> Primary bolt hardware sensitive to crew loads. Do not apply a push force on the RTAS primary bolt. Damage to self feeding nut may result</p> </div> <p style="text-align: center;"><u>NOTE</u> EV1: Bolt 1 must be fastened first, followed by Bolt 2. The order of Bolt 3 and 4 is not critical EV1 & EV2: S6 is not approved for translation during bolting</p> <ol style="list-style-type: none"> <input type="checkbox"/> Install 5/8-7.8-in socket on PGT (stowed in trash bag) Drive RTAS Bolt 1: PGT, 5/8-7.8-in ext: [B7 25.5 ft-lb, CW2 30 rpm, MTL 30.5], ~27 turns to hard stop <input type="checkbox"/> √Bolt shoulder is seated against housing Drive RTAS Bolt 2: PGT, 5/8-7.8-in ext: [B7 25.5 ft-lb, CW2 30 rpm, MTL 30.5], ~27 turns to hard stop <input type="checkbox"/> √Bolt shoulder is seated against housing (Fairlead safety tether inboard of APFR) Drive RTAS Bolts 4 and 3: PGT, 5/8-7.8-in ext: [B7 25.5 ft-lb, CW2 30 rpm, MTL 30.5]; ~27 turns to hard stop (reset PGT) After Bolt 4 is driven: <input type="checkbox"/> √Bolt shoulder is seated against housing (fairlead EV2 safety tether inboard of HR 2125) <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th>Bolt Order</th> <th>BRT HR</th> <th>Turns</th> <th>Torque</th> <th>√Seated</th> </tr> </thead> <tbody> <tr> <td>Bolt 1 – aft/nadir</td> <td>2126 2103</td> <td></td> <td></td> <td><input type="checkbox"/></td> </tr> <tr> <td>Bolt 2 – fwd/nadir</td> <td>2123 2140</td> <td></td> <td></td> <td><input type="checkbox"/></td> </tr> <tr> <td>Bolt 4 – fwd/zenith</td> <td>2131 2132</td> <td></td> <td></td> <td><input type="checkbox"/></td> </tr> <tr> <td>Bolt 3 – aft/zenith</td> <td>2138 2135</td> <td></td> <td></td> <td><input type="checkbox"/></td> </tr> </tbody> </table>	Bolt Order	BRT HR	Turns	Torque	√Seated	Bolt 1 – aft/nadir	2126 2103			<input type="checkbox"/>	Bolt 2 – fwd/nadir	2123 2140			<input type="checkbox"/>	Bolt 4 – fwd/zenith	2131 2132			<input type="checkbox"/>	Bolt 3 – aft/zenith	2138 2135			<input type="checkbox"/>	<p style="text-align: center;"><u>RTAS GROUND STRAPS</u></p> <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;"><u>CAUTION</u> Due to fault currents and EMI, 2 ground straps are required prior to activation, all 4 are required for activation</p> </div> <div style="border: 3px double black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;"><u>WARNING</u> Exposed braided wire on ground straps and protruding spring on ground strap bolt may present sharp edge hazard</p> </div> <ol style="list-style-type: none"> Release Corner 4 S6 Grounding Strap from S6: PGT, 7/16-6-in ext: [B1 12.0 ft-lb, CCW2 30 rpm, MTL 30.5]; ~11-13.5 turns to release Install Corner 4 S6 Grounding Strap on S5: Start by hand (to avoid cross-threading), then: PGT, 7/16-6-in ext: [A6 8.3 ft-lb, CW2 30 rpm, MTL 30.5]; ~6 turns to hard stop Reset PGT [B1 12.0 ft-lb, CCW2 30 rpm] (for Grounding Strap Release) Repeat steps 1 and 2 for Corners 3, 1, and 2 <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th>Ground Strap Order</th> <th>BRT HR</th> <th>Turns</th> <th>Torque</th> </tr> </thead> <tbody> <tr> <td>Corner 4 – fwd/zenith</td> <td>2142</td> <td></td> <td></td> </tr> <tr> <td>Corner 3 – aft/zenith</td> <td>2138 2135</td> <td></td> <td></td> </tr> <tr> <td>Corner 1 – aft/nadir</td> <td>2103</td> <td></td> <td></td> </tr> <tr> <td>Corner 2 – fwd/nadir</td> <td>2123 2140</td> <td></td> <td></td> </tr> </tbody> </table>	Ground Strap Order	BRT HR	Turns	Torque	Corner 4 – fwd/zenith	2142			Corner 3 – aft/zenith	2138 2135			Corner 1 – aft/nadir	2103			Corner 2 – fwd/nadir	2123 2140		
Bolt Order	BRT HR	Turns	Torque	√Seated																																											
Bolt 1 – aft/nadir	2126 2103			<input type="checkbox"/>																																											
Bolt 2 – fwd/nadir	2123 2140			<input type="checkbox"/>																																											
Bolt 4 – fwd/zenith	2131 2132			<input type="checkbox"/>																																											
Bolt 3 – aft/zenith	2138 2135			<input type="checkbox"/>																																											
Ground Strap Order	BRT HR	Turns	Torque																																												
Corner 4 – fwd/zenith	2142																																														
Corner 3 – aft/zenith	2138 2135																																														
Corner 1 – aft/nadir	2103																																														
Corner 2 – fwd/nadir	2123 2140																																														

EVA 1 ATTACH S6 TO S5 (01:05) (Cont)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)																																				
<p>Torque wrench out of bag GMT: ____ : ____</p> <p>8. Give EV1 and EV2 GO for translation on S6 truss</p> <p>Once all RTAS bolts (4) at final torque and verified tools and tethers clear, give SSRMS GO for S6 ungrapple</p> <p>9. Obtain glove inspection report from EV1</p> <p>Torque wrench re-stowed GMT: ____ : ____</p>	<p>6. Retrieve torque wrench from Crewlock Bag 7. Transfer 5/8-7.8-in ext from PGT to torque wrench</p> <p>8. On IV call: EV1 has GO for translation on S6 truss</p> <p>RTAS BOLT 3 AND 4 FINAL TORQUE</p> <p>9. Torque RTAS Bolts 3 and 4 (any order) Torque Wrench, 5/8-7.8-in ext: 57 ft-lb cw, to torque √Gap with small equip hook</p> <table border="1"> <thead> <tr> <th>Bolt Order</th> <th>BRT HR</th> <th>*Turns to Torque</th> <th>Gap Check</th> </tr> </thead> <tbody> <tr> <td rowspan="2">Bolt 3 – zenith/aft</td> <td>2138</td> <td>_____ <input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>2135</td> <td>_____ <input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td rowspan="2">Bolt 4 – zenith/fwd</td> <td>2129</td> <td>_____ <input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>2131</td> <td>_____ <input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </tbody> </table> <p>*Turn count record reqd only when not ~27 turns to hard stop</p> <p>10. Transfer torque wrench to EV2</p> <p>11. Retrieve tools from Crewlock Bag and stow on MWS: <input type="checkbox"/> 7/16-6-in ext from socket caddy (for PVR) Install wobble socket on PGT <input type="checkbox"/> Canon Connector Tools (2) (Use MWS RETs on connector tools. Leave crewlock RETs on connector tool)</p> <p>12. EV1 perform glove/gauntlet inspection, report status to IV</p> <p>13. Translate to S5/S6 umbilical worksite (radiator side)</p>	Bolt Order	BRT HR	*Turns to Torque	Gap Check	Bolt 3 – zenith/aft	2138	_____ <input type="checkbox"/>	<input type="checkbox"/>	2135	_____ <input type="checkbox"/>	<input type="checkbox"/>	Bolt 4 – zenith/fwd	2129	_____ <input type="checkbox"/>	<input type="checkbox"/>	2131	_____ <input type="checkbox"/>	<input type="checkbox"/>	<p>5. On IV call: EV2 has GO for translation on S6 truss</p> <p>RTAS BOLT 2 AND 1 FINAL TORQUE</p> <p>6. Receive torque wrench from EV1 Attach torque wrench to left MWS RET</p> <p>7. Torque RTAS Bolts 2 and 1 (any order): Torque Wrench, 5/8-7.8-in ext: 57 ft-lb cw, to torque √Gap with small equip hook</p> <p>NOTE: Once 3 of 4 RTAS bolts at final torque, inform M1/M2 on RTAS bolt status</p> <table border="1"> <thead> <tr> <th>Bolt Order</th> <th>BRT HR</th> <th>Turns to Torque</th> <th>Gap Check</th> </tr> </thead> <tbody> <tr> <td rowspan="2">Bolt 2 – nadir/fwd</td> <td>2128</td> <td>_____ <input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>2140</td> <td>_____ <input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td rowspan="2">Bolt 1 – nadir/aft</td> <td>2126</td> <td>_____ <input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> <tr> <td>2103</td> <td>_____ <input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </tbody> </table> <p>8. Translate to crewlock bag</p> <p>9. Remove 5/8-7.8-in socket; stow in trash bag</p> <p>10. Stow torque wrench in torque wrench bag on Crewlock Bag with RET</p>	Bolt Order	BRT HR	Turns to Torque	Gap Check	Bolt 2 – nadir/fwd	2128	_____ <input type="checkbox"/>	<input type="checkbox"/>	2140	_____ <input type="checkbox"/>	<input type="checkbox"/>	Bolt 1 – nadir/aft	2126	_____ <input type="checkbox"/>	<input type="checkbox"/>	2103	_____ <input type="checkbox"/>	<input type="checkbox"/>
Bolt Order	BRT HR	*Turns to Torque	Gap Check																																			
Bolt 3 – zenith/aft	2138	_____ <input type="checkbox"/>	<input type="checkbox"/>																																			
	2135	_____ <input type="checkbox"/>	<input type="checkbox"/>																																			
Bolt 4 – zenith/fwd	2129	_____ <input type="checkbox"/>	<input type="checkbox"/>																																			
	2131	_____ <input type="checkbox"/>	<input type="checkbox"/>																																			
Bolt Order	BRT HR	Turns to Torque	Gap Check																																			
Bolt 2 – nadir/fwd	2128	_____ <input type="checkbox"/>	<input type="checkbox"/>																																			
	2140	_____ <input type="checkbox"/>	<input type="checkbox"/>																																			
Bolt 1 – nadir/aft	2126	_____ <input type="checkbox"/>	<input type="checkbox"/>																																			
	2103	_____ <input type="checkbox"/>	<input type="checkbox"/>																																			

EVA 1 ATTACH S6 TO S5 (01:05) (Cont)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
10. Obtain glove inspection report from EV2		<p><u>RELEASE S5 CAPTURE LATCH PRE-LOAD</u></p> <ol style="list-style-type: none">1. Once all 4 RTAS bolts are torqued, drive S5 CLA: PGT, 7/16-6-in ext: [A6 8.3 ft-lb, CCW3 60 rpm, MTL 30.5], ~60 turns2. EV2 perform glove/gauntlet inspection, report status to IV3. Translate to S5/S6 umbilical worksite (radiator side)

EVA 1 ATTACH S6 TO S5 – TASK DATA

Tools:

EV1 (FF)	EV2 (FF)
PGT	PGT
5/8-7.8-in ext	5/8-7.8-in ext
Torque Wrench	Torque Wrench
7/16-6-in ext	7/16-6-in ext

EVA Fasteners:

Fastener Name	Label	Head Size	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
S5 capture latch		7/16-in	3.3 (to close)	7.5 (to open)	14.6	126 – close 60 – open	60 initial, 30 – close 60 – open
S5 RTAS bolts (Initial)	1,2,3,4	5/8-in	w/RAD: 9.2 w/o RAD: 25.5	N/A	119.7	24 turns min, 36 turns max	30
S5 RTAS bolts (Final)	1,2,3,4	5/8-in	57	N/A	119.7	Until torque reached	N/A
S6 Grounding Strap	N/A	7/16-in	8.3	12.0	Inst: 11.8 Rel: 31.1	Inst: 5-8 Rel: 11-13.5	30
Gap Check Tool	N/A	7/16-in		8.3	12.2	12-14	30

EVA Connectors: None

Foot Restraints:

Task	WIF	APFR Setting	NOTE
Capture CLA drive	S5-09	4, SS, B, 11	
RTAS bolt 1	S5-04	5, LL, L, 9	
RTAS bolt 2	S5-05	8, PP, B, 1	APFR position is within sweep of SSU for beta angles 240-15 deg on S4 SA 3A; SSU – footplate is w/in inches of contact
RTAS bolt 3	S5-03	7, PP, A, 2	
RTAS bolt 4	S5-06	3, PP, K, 12	

Cautions:

1. Primary bolt hardware sensitive to crew loads. Do not apply push force on bolt or damage to self feeding nut could occur
2. Due to fault currents and EMI, 2 ground straps are required prior to activation, all 4 are required for activation

Warnings:

1. Exposed braided wire on ground straps and protruding spring on ground strap bolt may present sharp edge hazard
2. EMU collision hazard. EV1 and EV2 must stay below the plane defined by S5/S6 interface until needed for verification of ready to latch condition
3. Pinch Hazard. Area between S6 and S5 must be clear prior to latch actuation to prevent crew injury

Notes:

RTAS GAP CHECK:

Minimum: 0.330 inches

Nominal: 0.406 inches

Maximum before primary bolt driving: 0.576 inches

Maximum after primary bolt seating: 0.478 inches

RET hook: 0.43 inches



7/16-6 in ext drop-proof tether end: 0.66 inches

1. Gap Check Tools (2) are located on S5 inboard and outboard Corner 1
2. Translation on S6 not permitted during bolting (however, no requirement on number of RTAS bolts for limited activities)

Thermal Constraints:


1. Torque wrench thermal clock: 3.5 hr

EVA 1 ATTACH S6 TO S5 – TASK DATA (Cont)



RTAS S5 SIDE

EVA 1 ATTACH S6 TO S5 – TASK DATA (Cont)



RTAS S6 SIDE

EVA 1 CONNECT S5 TO S6 UMBILICALS (00:55)


IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)																										
<p><u>S6 TO S5 INHIBITS</u> {see Task Data for reqd inhibits}</p> <p>1. <input type="checkbox"/> IV verify with MCC-H S5-S6 inhibits in place</p> <p>2. Give EV GO for P253 demate</p> <p>3. <input type="checkbox"/> Notify MCC-H P253 mated to S6: Give MCC-H GO to reconfigure S6/S5 – 1553 buses to Bus A. Reconfiguration to Bus A must be completed prior to performing 1553 bus reconfiguration in EV1 step 7</p> <p>4. <input type="checkbox"/> IV verify with MCC-H, GO for P254 demate (EV1 step 7)</p> <p>5. Give EV1 GO to demate P254</p>	<p><u>CONNECT S6 UMBILICALS</u></p> <p>1. Stow cannon connector tools on HR 2140 and HR 2142</p> <p>2. Open TA clamps (10): P253 (2) <input type="checkbox"/> <input type="checkbox"/>, P254 (2) <input type="checkbox"/> <input type="checkbox"/>, P259 (3) <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>, P260 (3) <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></p> <p style="text-align: center;"><u>NOTE</u></p> <p style="text-align: center;">√Connectors for straight pins, no FOD, EMI band intact, and good bend radius.</p> <p style="text-align: center;">RET to caps when both connector tools are in use, as reqd</p> <p>3. On IV GO, perform the following 1553 Bus A demate/mates and swap connector cap from S5 to S6 dummy connector:</p> <table border="1" data-bbox="527 625 1969 690"> <thead> <tr> <th>EV2 – Demate cap from S6</th> <th>EV1 – Demate cable from S5</th> <th>EV2 – Insp/Mate cable to S6</th> <th>EV1 – Insp/Mate cap on S5</th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/> S6 cap ← → S6 J153</td> <td><input type="checkbox"/> S5 P253 ← → S5 J153</td> <td><input type="checkbox"/> S5 P253 → ← S6 J153</td> <td><input type="checkbox"/> S6 cap → ← S5 J153</td> </tr> </tbody> </table> <p>4. Give IV/MCC-H GO for 1553 bus reconfiguration. Continue with power cap/connector demates:</p> <table border="1" data-bbox="730 781 1959 878"> <thead> <tr> <th>EV2 – Demate cap from S6</th> <th>EV1 – Demate cable from S5</th> <th>EV1 – Insp and mate cable to S6</th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/> S6 cap ← → S6 J160</td> <td><input type="checkbox"/> S5 P260 ← → S5 J160</td> <td><input type="checkbox"/> S5 P260 → ← S6 J160</td> </tr> <tr> <td colspan="3">EV2: Keep cap on tool</td> </tr> </tbody> </table> <p>5. Ingress APFR, as reqd. Continue with power cap/connector swap:</p> <table border="1" data-bbox="730 963 1959 1060"> <thead> <tr> <th>EV2 – Demate cap from S6</th> <th>EV1 – Demate cable from S5</th> <th>EV1 – Insp/Mate cable to S6</th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/> S6 cap ← → S6 J159</td> <td><input type="checkbox"/> S5 P259 ← → S5 J159</td> <td><input type="checkbox"/> S5 P259 → ← S6 J159</td> </tr> <tr> <td colspan="3">EV2: Keep cap on RET/tool</td> </tr> </tbody> </table> <p>6. Mate connector caps (2) to S5 P260 <input type="checkbox"/> and S5 P259 <input type="checkbox"/></p>	EV2 – Demate cap from S6	EV1 – Demate cable from S5	EV2 – Insp/Mate cable to S6	EV1 – Insp/Mate cap on S5	<input type="checkbox"/> S6 cap ← → S6 J153	<input type="checkbox"/> S5 P253 ← → S5 J153	<input type="checkbox"/> S5 P253 → ← S6 J153	<input type="checkbox"/> S6 cap → ← S5 J153	EV2 – Demate cap from S6	EV1 – Demate cable from S5	EV1 – Insp and mate cable to S6	<input type="checkbox"/> S6 cap ← → S6 J160	<input type="checkbox"/> S5 P260 ← → S5 J160	<input type="checkbox"/> S5 P260 → ← S6 J160	EV2: Keep cap on tool			EV2 – Demate cap from S6	EV1 – Demate cable from S5	EV1 – Insp/Mate cable to S6	<input type="checkbox"/> S6 cap ← → S6 J159	<input type="checkbox"/> S5 P259 ← → S5 J159	<input type="checkbox"/> S5 P259 → ← S6 J159	EV2: Keep cap on RET/tool			<p><u>CONNECT S6 UMBILICALS</u></p> <p>1. Assist EV1, as reqd</p>
EV2 – Demate cap from S6	EV1 – Demate cable from S5	EV2 – Insp/Mate cable to S6	EV1 – Insp/Mate cap on S5																									
<input type="checkbox"/> S6 cap ← → S6 J153	<input type="checkbox"/> S5 P253 ← → S5 J153	<input type="checkbox"/> S5 P253 → ← S6 J153	<input type="checkbox"/> S6 cap → ← S5 J153																									
EV2 – Demate cap from S6	EV1 – Demate cable from S5	EV1 – Insp and mate cable to S6																										
<input type="checkbox"/> S6 cap ← → S6 J160	<input type="checkbox"/> S5 P260 ← → S5 J160	<input type="checkbox"/> S5 P260 → ← S6 J160																										
EV2: Keep cap on tool																												
EV2 – Demate cap from S6	EV1 – Demate cable from S5	EV1 – Insp/Mate cable to S6																										
<input type="checkbox"/> S6 cap ← → S6 J159	<input type="checkbox"/> S5 P259 ← → S5 J159	<input type="checkbox"/> S5 P259 → ← S6 J159																										
EV2: Keep cap on RET/tool																												
<p>6. <input type="checkbox"/> Notify MCC-H P254 mated (Give GO for S6 activation)</p>	<p>7. Egress APFR, as reqd. On IV GO, perform 1553 Bus B cap/connector swap:</p> <table border="1" data-bbox="527 1198 1969 1263"> <thead> <tr> <th>EV2 – Demate cap from S6</th> <th>EV1 – Demate cable from S5</th> <th>EV2 – Insp/Mate cable to S6</th> <th>EV1 – Insp/Mate cap on S5</th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/> S6 cap ← → S6 J154</td> <td><input type="checkbox"/> S5 P254 ← → S5 J154</td> <td><input type="checkbox"/> S5 P254 → ← S6 J154</td> <td><input type="checkbox"/> S6 cap → ← S5 J154</td> </tr> </tbody> </table> <p>8. Retrieve APFR</p> <p>9. Stow APFR on BRT (preset APFR [NN,E,1])</p>	EV2 – Demate cap from S6	EV1 – Demate cable from S5	EV2 – Insp/Mate cable to S6	EV1 – Insp/Mate cap on S5	<input type="checkbox"/> S6 cap ← → S6 J154	<input type="checkbox"/> S5 P254 ← → S5 J154	<input type="checkbox"/> S5 P254 → ← S6 J154	<input type="checkbox"/> S6 cap → ← S5 J154	<p>2. Verify TA clamps closed, as reqd</p> <p>3. Cleanup worksite. Retrieve connector tools (2)</p>																		
EV2 – Demate cap from S6	EV1 – Demate cable from S5	EV2 – Insp/Mate cable to S6	EV1 – Insp/Mate cap on S5																									
<input type="checkbox"/> S6 cap ← → S6 J154	<input type="checkbox"/> S5 P254 ← → S5 J154	<input type="checkbox"/> S5 P254 → ← S6 J154	<input type="checkbox"/> S6 cap → ← S5 J154																									

EVA 1 CONNECT S5 TO S6 UMBILICALS (00:55) (Cont)


IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
<p>7. Obtain glove inspection report from EV1</p> <p>8. Obtain glove inspection report from EV2</p> <p>9. After both EV1 & EV2 clear of S4 BGAs, gve MCC-H GO to rotate S4 BGAs</p>	<p>10. Translate to S6 Nadir SABB Inboard Restraint location</p> <p>11. Install APFR [9,NN,E,1] in S6 WIF 27</p> <p>12. Place RET on S6 HR 2061 to six-pack clamp</p> <p>13. EV1 perform glove/gauntlet inspection, report status to IV</p> <p>14. Translate to PVR worksite (fairlead safety tether, to minimize radiator contact)</p>	<p>4. Translate to Crewlock Bag</p> <p>5. Stow Cannon Connector Tools and EVA Camera in Crewlock Bag</p> <p>6. Remove 7/16-6-in wobble from PGT and stow 6-in wobble on socket caddy</p> <p>7. Retrieve Rd TM, stow on MWS</p> <p>8. Attach Crewlock Bag to BRT</p> <p>9. EV2 perform glove/gauntlet inspection, report status to IV</p> <p>10. Translate to S6 Nadir SABB Inboard Restraint</p>

CAUTION
Avoid imparting loads into cables under the S6 gap spanners


EVA 1 CONNECT S5 TO S6 UMBILICALS – TASK DATA



**View of Umbilical Panels
Radiator Side (Forward Face)**



View Radiator (Fwd) Side



EVA 1 CONNECT S5 TO S6 UMBILICALS – TASK DATA (Cont)

Tools:

EV1 (FF)	EV2 (FF)
Cannon Connector tool	Cannon Connector tool
APFR	

EVA Fasteners: None

EVA Connectors:

Harness	From (S5)	To (S6)	Clamps	Size	Inhibit	Function
P253-W02	J153	J153 – sockets	1	37	N/A	1553 Bus A (Data)
P254-W07	J154	J154 – sockets	1	37	N/A	1553 Bus B (Data)
P259-W01	J159	J159 – sockets	4	37	MBSU 1 RBI 8 – Open, Close Cmd Inh	Power to/from Ch 1B
P260-W08	J160	J160 – sockets	4	37	MBSU 3 RBI 8 – Open, Close Cmd Inh	Power to/from Ch 3B

Foot Restraints:

Task	WIF	APFR Setting
Power connector mate	S5-05	10, QQ, C, 11
Data connector mate (optional)	S5-06	9, SS, A, 11

Cautions:

Warnings:





Timeline Considerations:

1. Due to cable interference, P260 must be demated from S5 prior to P259. P260 must also be mated to S6 prior to P259



Notes:

1. Tool interference exists on the S5 P260 connector
2. In order to prevent side-loads on connectors, will need to react cable stiffness

EVA 1 RELEASE SABB RESTRAINTS (01:35)

IV	EV2
<p>Clam Shell Nadir Inboard Bolt Release Tracking</p>  <p>Six-Pack Nadir Outboard Bolt Release Tracking</p> 	<p>RELEASE NADIR (NON-KEEL SIDE) SABB (1B) RESTRAINTS (00:45)</p> <ol style="list-style-type: none"> Temp stow Crewlock Bag on S6 HR 2040 (near WIF 19, non-keel/inboard corner) or HR 2028 (fairlead along truss to stay clear of SABBs) APFR: S6 WIF 27 [9,NN,E,1] <input type="checkbox"/> √Blk-Blk, pull/twist test Ingress APFR <p>RELEASE NADIR INBOARD RESTRAINTS</p> <ol style="list-style-type: none"> PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-Rd TM with 5/8-in: √Anti-Backlash in Neutral: Break torque on Inboard SABB fasteners (2), ~5 turns PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-5/8-7.8-in socket ext: Release Inboard SABB fasteners (2), ~9 turns Stow 5/8-7.8-in socket in trash bag Egress APFR Open clam shell hinge until detent engages  <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Unfasten jack bolt (#06) last</p> </div> <p>RELEASE NADIR OUTBOARD RESTRAINTS</p> <ol style="list-style-type: none"> √Six-pack clamp secured to S6 HR 2061 w/RET APFR: S6 WIF 27 [2,NN,E,11] <input type="checkbox"/> √Blk-Blk, pull/twist test Ingress APFR PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-Rd TM with 5/8-in socket: √Anti-Backlash Neutral: Break torque on Outboard SABB fasteners (6), ~5 turns each <div style="border: 3px double black; padding: 5px; text-align: center;"> <p>WARNING Sharp edge hazard. Avoid contact with exposed threads on jack bolt #06 after SABB six-pack shell restraint released</p> </div> <ol style="list-style-type: none"> PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-5/8-7.8-in ext: Release Outboard SABB fasteners (6), ~9 turns each  Temp stow six-pack clamp on S6 HR 2060 using RET Temp stow 5/8-7.8-in socket in trash bag Egress APFR Retrieve APFR [NN,E,1], stow on BRT Translate to ZENITH (Keel Side) INBOARD RESTRAINTS location (translate inboard)

EVA 1 RELEASE SABB RESTRAINTS (01:35) (Cont)

IV	EV2
<p>Clam Shell Zenith Inboard Bolt Release Tracking</p>  <p>Six-Pack Zenith Outboard Bolt Release Tracking</p> 	<p>RELEASE ZENITH (KEEL SIDE) SABB (3B) RESTRAINTS (00:45)</p> <ol style="list-style-type: none"> APFR S6 WIF 25 [9,NN,E,1] <input type="checkbox"/> √Blk-Blk, pull/twist test Ingress APFR <p>RELEASE ZENITH INBOARD RESTRAINTS</p> <ol style="list-style-type: none"> PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-RAD, TM with 5/8-in socket: Anti-Backlash in Neutral: Break torque on Inboard SABB fasteners (2), ~5 turn PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-5/8-in socket 7.8-ext: Release Inboard SABB fasteners (2), ~9 turns Stow 5/8-7.8-in socket in trash bag. Egress APFR. Open clam shell hinge until detent engages <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Unfasten jack bolt (#06) last</p> </div> <p>RELEASE ZENITH OUTBOARD RESTRAINTS</p> <ol style="list-style-type: none"> √Six-pack clamp to secured S6 HR 2072 or HR 2071 using RET from BRT (located near keel side/outboard corner of MMOD shield) APFR: S6 WIF 25 [2,NN,E,11]. <input type="checkbox"/> √Blk-Blk, pull/twist test Ingress APFR PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-Rd TM with 5/8: √Anti-Backlash Neutral: Break torque on Outboard SABB fasteners (6), ~5 turns each <div style="border: 3px double black; padding: 5px; text-align: center;"> <p>WARNING Sharp edge hazard. Avoid contact with exposed threads on jack bolt #06 after SABB six-pack shell restraint is released</p> </div> <ol style="list-style-type: none"> PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-7.8-5/8-in ext: Release Outboard SABB fasteners (6), ~9 turns each Temp stow six-pack clamp on HR S6 2072 (zenith-aft) <input type="checkbox"/> Egress AFPR. Remove APFR (RET to MWS) Translate to WIF 34 (PVR face, near trunnion pin) Temp stow APFR in WIF 34 Translate to Crewlock Bag (S6 HR 2040 or HR 2028). Preposition EVA Camera for EV1 retrieval Transfer tools to Crewlock Bag: Rd TM, integral RET and 5/8-7.8-in ext socket from PGT to socket caddy Retrieve 7/16-6-in ext socket from socket caddy and install on PGT (for Mast Tip Fastener release) If time permits: Retrieve six-pack clamp and RET, previously temp stowed at HR 2072 Translate port-nadir to S6 external stow bin and stow six-pack clamp. √RET is now stowed on MWS

EVA 1 RELEASE SABB RESTRAINTS – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	02:00
Two EV Crew	N/A	01:00

Tools:

EV1 (FF)	EV2 (FF)
N/A	PGT
	Rd TM with 5/8 PRD socket
	5/8-7.8-in ext socket (rigid)
	APFR

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Inboard SABB Launch Restraint	N/A	5/8	2	98	119	389	10 [1]	30
Outboard SABB Launch Restraint (Six-Pack Clamp)	1-6	5/8	6	97	118	390	10 [1]	30

[1] – Turn count measured on flight hardware 5/27/03

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting
Release nadir-inboard SABB Launch Restraint	S6-27	[9,NN,E,1] or [9,NN,E,12]
Release nadir-outboard SABB Launch Restraint	S6-27	[2,NN,E,11] or [2,NN,F,12]
Release forward-inboard SABB Launch Restraint	S6-25	[9,NN,E,1] or [9,NN,E,12]
Release forward-outboard SABB Launch Restraint	S6-25	[2,NN,E,11] or [2,NN,F,12]

Notes:

- If outboard SABB launch restraint tether point is not accessible prior to removal, Rd TM may be installed and locked onto a bolt to provide a tether point until the launch restraint is removed and the tether point is better accessible


Cautions:

- Unfasten Jack bolt #6 (nearest the tether point) last. Fasteners #1-5 can be released in any order


Warnings:

- Sharp edge hazard. Avoid contact with exposed threads on jack bolt #6 after SABB six-pack restraint released


EVA 1 RELEASE SABB RESTRAINTS – TASK DATA (Cont)




SABB Inboard Launch Restraint



SABB Outboard Launch Restraint



SABB Outboard and Inboard Restraints (left to right in view)



EVA 1 PVR RADIATOR CINCHES AND WINCH RELEASE (00:45)

IV	EV1 – Swanson (FF)																								
<p>The diagram shows a perspective view of the PVR radiator structure. Labels include: Zenith (pointing to the top), Inboard (pointing to the right side), CH11, CH12, CH13, CH14, CH15, and CH16. Arrows indicate the locations of these cinches on the radiator panels.</p>	<p>RELEASE PVR CINCHES</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Avoid contact with radiator bellows and thermal outer coating</p> </div> <ol style="list-style-type: none"> Release PVR Cinches H11 and H12, followed by H13 – H16 (any order) PGT [B7 25.5 ft-lb, CCW2 30 RPM, MTL 30.5] – 7/16-6-in ext: 8-14 turns, as reqd to disengage Stow cinch in clip. Verify positive retention <table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th>√</th> <th>Cinch</th> <th>BRT – HR</th> <th>√</th> <th>Cinch</th> <th>BRT – HR</th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/></td> <td>H12 outboard</td> <td>2063</td> <td><input type="checkbox"/></td> <td>*H11 inboard</td> <td>2042 (head zenith, feet nadir)</td> </tr> <tr> <td><input type="checkbox"/></td> <td>H16 zenith</td> <td>2009</td> <td><input type="checkbox"/></td> <td>H15 nadir</td> <td>2052</td> </tr> <tr> <td><input type="checkbox"/></td> <td>H14 zenith</td> <td>2053</td> <td><input type="checkbox"/></td> <td>H13 nadir</td> <td>2046</td> </tr> </tbody> </table> <p>*NOTE: For efficiency, stow Crewlock Bag when able to new location. Crewlock Bag stowage location is on S6 HR 2073 and HR 2074/HR 2072 (MMOD shield)</p> <p>RELEASE OUTBOARD AND INBOARD PVR WINCH PIP PIN</p> <div style="border: 3px double black; padding: 5px; text-align: center;"> <p>WARNING Moving hardware hazard. PVR panels are free to move after winch release</p> </div> <ol style="list-style-type: none"> <input type="checkbox"/> Verify tools and tethers clear of deploy envelope On IV GO, release Outboard and Inboard winch bar PIP pin from winch clevis: <ul style="list-style-type: none"> <input type="checkbox"/> Outboard PIP Pin (H34) <input type="checkbox"/> Inboard PIP Pin (H33) Remove winch bar from radiator panel, reinsert PIP pin into winch clevis <input type="checkbox"/> Verify PIP pin, lanyard and winch bar clear of radiator deploy envelope Translate to Keel Pin location (S6 zenith-outboard) (Leave PGT 7/16-6-in ext on PGT – for Keel Pin Rotation) 	√	Cinch	BRT – HR	√	Cinch	BRT – HR	<input type="checkbox"/>	H12 outboard	2063	<input type="checkbox"/>	*H11 inboard	2042 (head zenith, feet nadir)	<input type="checkbox"/>	H16 zenith	2009	<input type="checkbox"/>	H15 nadir	2052	<input type="checkbox"/>	H14 zenith	2053	<input type="checkbox"/>	H13 nadir	2046
√	Cinch	BRT – HR	√	Cinch	BRT – HR																				
<input type="checkbox"/>	H12 outboard	2063	<input type="checkbox"/>	*H11 inboard	2042 (head zenith, feet nadir)																				
<input type="checkbox"/>	H16 zenith	2009	<input type="checkbox"/>	H15 nadir	2052																				
<input type="checkbox"/>	H14 zenith	2053	<input type="checkbox"/>	H13 nadir	2046																				
<ol style="list-style-type: none"> <input type="checkbox"/> IV verify with MCC-H, vehicle in CMG control (thrusters inhibited) prior to PIP pin release <div style="border: 3px double black; padding: 5px; text-align: center;"> <p>WARNING ISS must be CMG-Thruster inhibited during partial deployment when unwinched to avoid damage to PV radiator</p> </div> <ol style="list-style-type: none"> IV give EV1 GO to pull winch bar PIP pins IV inform MCC-H when cinches and winch are released 																									

EVA 1 PVR RADIATOR CINCHES AND WINCH RELEASE – TASK DATA

Tools:

EV1 (FF)	EV2 (FF)
PGT	PGT
7/16-6-in ext	7/16-6-in ext

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns
Cinch	H11-H16	7/16-in	6	H11-H12: 15.8 H13-H16: 24.6	H11-H12: 35.7 H13-H16: 39.7	8-14


EVA Connectors: None

Foot Restraints:

Task	WIF	APFR Setting
Cinch H12 (CH12)	S6-32	6, WW, D, 11
Cinch H14 (CH14)	S6-24	6, UU, C, 1
Cinch H16 (CH16)	S6-20	6, SS, D, 1
Cinch H11 (CH11)	S6-20	6, WW, G, 1
Cinch H15 (CH15)	S6-23	6, TT, J, 11
Cinch H13 (CH13)	S6-19	6, TT, J, 11



PVR FQDC



RADIATOR CINCH AND WINCH PIP PIN

Warnings:


1. Moving hardware hazard. Radiators are free to move after winches released
2. ISS must be CMG-Thruster inhibited during partial deployment when unwinned to avoid damage to PV radiator

Notes:



1. Incidental contact with silver radiator surface is acceptable
2. H11 and H12 must be released prior to the others

Constraints:





1. APFR ingress/egress cannot happen concurrently with radiator deploy




EVA 1 ROTATE IEA KEEL PIN AND RELEASE SAW BETA GIMBAL RESTRAINTS (00:45)

IV	EV1	EV2
 <p>X denotes side of 4-bar hinge to inspect for lock indicator</p> <p>IEA Bulkhead looking inboard</p>	<div style="border: 2px solid black; padding: 5px; text-align: center;"> <p>WARNING</p> <p>Sharp edge. The Keel fastener has exposed bolt threads when removed from the Keel body</p> </div> <p>ROTATE IEA KEEL PIN (ZENITH) (00:15)</p> <ol style="list-style-type: none"> 1. BRT to keel structure handrail (S6 HR 2067) 2. PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-7/16-6-in ext: Release fastener (~43 turns) 3. Remove the keel fastener completely from keel body 4. Rotate keel pin until hard dock detent capture 5. Verify alignment marks (view from side) 6. Re-install keel fastener into keel body 7. PGT [B7 25.5 ft-lb, CW2 30RPM, MTL 30.5]-7/16-6-in ext: Engage fastener, 10 turns  8. Translate to Crewlock Bag (keep tether aft and clear of SABB) 9. Attach BRT RET from HR 2071 or 2072 to zenith six-pack clamp 10. Retrieve Ratchet Wrench from Crewlock Bag 11. Temp stow wrench on MWS (If MMOD Bolt Rel Get-Ahead complete, finish PVR Cinch Rel) <div style="border: 2px solid black; padding: 5px; text-align: center;"> <p>WARNING</p> <p>Stored energy and collision hazard. Entire area behind the IEA bulkhead, Beta Gimbal/Solar Array Wing must be clear prior to Beta Gimbal Restraint disengagement</p> <p>Verify that Beta Gimbal/Solar Array motion has stopped before exiting worksite</p> </div> <p>RELEASE NADIR WING (1B) BGA RESTRAINTS (00:15)</p> <ol style="list-style-type: none"> 12. Release Primary Power Cable TA clamps (3) <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 13. Remove PIP pins (2) from launch restraint assembly <input type="checkbox"/> <input type="checkbox"/> Fwd Aft 14. Verify EV2 is clear of stored energy hazard 15. Ratchet Wrench – 5/8-7.8-in ext: Release Nadir Wing Beta Gimbal restraints (2), 11 turns <input type="checkbox"/> <input type="checkbox"/> <p>If PGT w/Rd TM required to break torque: PGT [B7 25.5 ft-lb, CCW2 30 rpm, MTL 30.5]-Rd TM with 5/8: $\sqrt{\text{Anti-Backlash}}$ in Neutral: 5 turns</p> <ol style="list-style-type: none"> 16. Re-insert Beta Gimbal Restraint PIP pins (2) <input type="checkbox"/> <input type="checkbox"/> Fwd Aft 	

EVA 1 ROTATE IEA KEEL PIN AND RELEASE SAW BETA GIMBAL RESTRAINTS (00:45) (Cont)

IV	EV1	EV2
<p>1. Receive glove inspection report from EV1</p>	<p>17. Stow ratchet wrench and return RET to MWS</p> <p>18. Inspect 4-bar linkages to verify they are fully deployed and locked. Minimum 3 of 4 locked required</p> <p>(Perform manual assist to fully deploy/lock, as reqd. 4-bar linkage inspection may be deferred to later step for better view of indicators)</p> <p>19. Close TA clamps (3)    </p> <p>20. Perform glove/gauntlet inspection. Report glove status to IV</p> <p>21. Translate to zenith wing BGA restraints worksite (Follow previous safety tether routing)</p>	




EVA 1 ROTATE IEA KEEL PIN AND RELEASE SAW BETA GIMBAL RESTRAINTS (00:45) (Cont)

IV	EV1	EV2
<div data-bbox="105 272 703 633"> <p>Zenith Mast Canister</p> </div> <p data-bbox="241 657 577 738">X denotes side of 4-bar hinge to inspect for lock indicator IEA Bulkhead looking inboard</p> <p data-bbox="115 803 556 836">1. IV, verify EV1 and EV2 tool inventories</p> <div data-bbox="661 1218 724 1242" style="text-align: right;"> </div>	<div data-bbox="829 292 1354 381" style="border: 1px solid black; padding: 5px;"> <p align="center">CAUTION</p> <p>IEA Keel Pin must be rotated prior to the release of the Beta Gimbal Restraints</p> </div> <div data-bbox="829 414 1375 625" style="border: 3px double black; padding: 5px; margin-top: 10px;"> <p align="center">WARNING</p> <p>Stored energy and collision hazard. Entire area behind the IEA bulkhead, Beta Gimbal/Solar Array Wing must be clear prior to Beta Gimbal Restraint disengagement</p> <p>Verify that Beta Gimbal/Solar Array motion has stopped before exiting worksite</p> </div> <p data-bbox="745 657 1375 682"><u>RELEASE ZENITH WING (3B) BGA RESTRAINTS (00:15)</u></p> <ol data-bbox="745 690 1375 1388" style="list-style-type: none"> 1. Release Primary Power Cable TA clamps (3) <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> (if TA clamps not released earlier) 2. Remove PIP pins (2) from launch restraint assy Fwd Aft <input type="checkbox"/> <input type="checkbox"/> <p data-bbox="745 795 913 820">If time permits:</p> <ol data-bbox="745 828 1375 1388" style="list-style-type: none"> 3. Retrieve nadir six-pack and stow in external Stow Bin 4. Perform UNSTOW NADIR WING (3B) SABB, next proc 5. Verify EV2 is clear of stored energy hazard 6. Verify tools, TA clamps, PIP pins, and 4-bar linkages locked 7. Ratchet Wrench w/5/8-7.8-in ext: Release fasteners (2), 11 turns <input type="checkbox"/> <input type="checkbox"/> 8. Re-insert Beta Gimbal Restraint PIP pins (2) Fwd Aft <input type="checkbox"/> <input type="checkbox"/> 9. Translate to Crewlock Bag 10. Stow Ratchet Wrench in Crewlock Bag 11. Retrieve EVA Camera and stow on swing arm 12. Perform glove check and report status to IV 13. Translate to nadir SABB wing for unstow, as reqd 	<p data-bbox="1407 1063 2005 1144">1. Inspect to verify 4-Bar linkages have been fully deployed and locked (min 3 of 4 locks reqd, both nadir and zenith)</p> <p data-bbox="1407 1161 2005 1218">2. Perform manual assist to fully deploy/lock, as reqd</p> <p data-bbox="1407 1193 2005 1218">3. Close TA clamps (3) <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></p> <div data-bbox="1816 1226 2005 1307" style="text-align: right;"> <p><u>4-Bar Linkage Deploy</u></p> <p>Nadir Zenith <input type="checkbox"/> <input type="checkbox"/></p> </div> <p data-bbox="1407 1323 2005 1388">4. Perform glove/gauntlet check and report status</p> <p data-bbox="1407 1356 2005 1388">5. Translate to zenith SABB wing for unstow, as reqd</p>

EVA 1 ROTATE IEA KEEL PIN AND RELEASE SAW BETA GIMBAL RESTRAINTS – TASK DATA



Aft Beta Gimbal Restraints and IEA Keel Structure



EVA 1 ROTATE IEA KEEL PIN AND RELEASE SAW BETA GIMBAL RESTRAINTS – TASK DATA (Cont)

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	00:30
Two EV Crew	N/A	N/A

Tools:

EV1	EV2
PGT (prime)	N/A
7/16 wobble socket-6 ext	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
IEA Keel Pin Restraint Bolt	N/A	7/16	1	4 gnd	38	168 removal 44 install	43	60

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting
Rotate IEA Keel Pin	S6-32	11,MM,G,2
Rotate IEA Keel Pin	S6-40	12,QQ,G,12 (1B 4-bar must be deployed)

Notes:


None

Cautions:

None

Warnings:

1. Sharp edge. The Keel fastener has exposed bolt threads when removed from the Keel body



Beta Gimbal Restraints and IEA Keel Pin



Beta Gimbal Restraints and IEA Keel Pin

EVA 1 ROTATE IEA KEEL PIN AND RELEASE SAW BETA GIMBAL RESTRAINTS – TASK DATA (Cont)

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	00:40
Two EV Crew	N/A	N/A

Tools:

EV1	EV2
Ratchet wrench	N/A
5/8 (rigid) Socket-7.8 ext	
BRT	
Rd TM with 5/8 prd (backup)	
PGT (backup)	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Beta Gimbal Launch Restraint Bolts	N/A	5/8	2	60 gnd	60 @ 70F, 118 @200F	496	10-12	60

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting
Release Nadir Beta Gimbal Restraints		
Release Zenith Wing Beta Gimbal Restraints		

Notes:

- Do not release the third clamp from the BMRRM. This is a sliding clamp which the Primary power cable is intended to slide through


Cautions:

The following must be complete prior to release of BGA Restraints:


- SABB Restraints Released (2 per wing)
- Primary Power cable TA clamps released (3 per wing)
- APFR relocated from SABB Restraint location
- IEA Keel Pin rotated prior to BGA Restraint release

Warnings:

- Entire area behind the IEA bulkhead, Beta Gimbal/Solar Array wing, must be clear prior to fastener disengagement
- Verify that Beta Gimbal/Solar Array wing motion has stopped before exiting worksite



Beta Gimbal Restraints (Aft Wing)



Primary Power Cable TA Clamps (Aft Wing)

EVA 1 UNSTOW SABB, RELEASE MAST, AND REMOVE ECU/SSU SHROUD (01:10)

IV	EV1 – SWANSON	EV2 – ARNOLD						
<p>1. <input type="checkbox"/> IV verify MCC-H is GO for ECU/SSU shroud jettison</p> <p>2. IV inform MCC-H of impending shroud jettison</p> <p>3. IV give EV GO for shroud jettison</p> <p>4. IV receive shroud speed/direction report from EV crew</p> <table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; text-align: center;"><u>Nadir (1B) Shrouds</u></td> <td style="width: 50%; text-align: center;"><u>Zenith (3B) Shrouds</u></td> </tr> <tr> <td>ECU ____ ft/s _____</td> <td>____ ft/s _____</td> </tr> <tr> <td>SSU ____ ft/s _____</td> <td>____ ft/s _____</td> </tr> </table>	<u>Nadir (1B) Shrouds</u>	<u>Zenith (3B) Shrouds</u>	ECU ____ ft/s _____	____ ft/s _____	SSU ____ ft/s _____	____ ft/s _____	<div style="border: 2px solid black; padding: 5px; text-align: center; margin-bottom: 10px;"> <p>WARNING Pinch Point – Stay clear of pivot fitting and lockout arm during SABB rotation</p> </div> <p><u>UNSTOW NADIR WING (1B) SABB</u></p> <ol style="list-style-type: none"> 1. Remove PIP pin from Lockout arm 2. Rotate blanket box to deploy position 3. Verify pivot arm is locked with locking sleeve over joint 4. Install PIP pin through the Lockout arm 5. Repeat steps 2-5 for other blanket box <div style="border: 2px solid black; padding: 5px; text-align: center; margin-bottom: 10px;"> <p>WARNING When captive EVA fasteners are released, the pop-up spring could protrude out between the bolt head and housing producing a puncture hazard</p> </div> <ol style="list-style-type: none"> 6. PGT [A7 9.2 ft-lb, CCW2 30 rpm, MTL 30.5]-7/16-6-in ext: Release Mast Tip fasteners (3), ~14 turns 7. Verify Mast Tip Fasteners are released <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <p><u>NADIR (1B) ECU/SSU SHROUD REMOVAL AND JETTISON</u></p> <ol style="list-style-type: none"> 8. Translate to position near nadir ECU/SSU (zenith-forward-outboard) 9. Release SSU long strap on cover 10. Release ECU short straps (2) <input type="checkbox"/> <input type="checkbox"/> 11. Remove ECU shroud 12. Release ECU ground strap PIP pin <p>13. Time permitting, take photos</p> <p>14. Translate to shroud jettison location (retrograde, forward-nadir)</p> <p>On IV GO:</p> <ol style="list-style-type: none"> 15. Jettison ECU shroud 16. EV1 report speed/direction to IV 	<div style="border: 2px solid black; padding: 5px; text-align: center; margin-bottom: 10px;"> <p>WARNING Pinch Point – Stay clear of pivot fitting and lockout arm during SABB rotation</p> </div> <p><u>UNSTOW ZENITH WING (3B) SABB</u></p> <ol style="list-style-type: none"> 1. Remove PIP pin from Lockout arm 2. Rotate blanket box to deploy position 3. Verify pivot arm is locked with locking sleeve over joint 4. Install PIP pin through the Lockout arm 5. Repeat steps 2-5 for other blanket box <div style="border: 2px solid black; padding: 5px; text-align: center; margin-bottom: 10px;"> <p>WARNING When captive EVA fasteners are released, the pop-up spring could protrude out between the bolt head and housing producing a puncture hazard</p> </div> <ol style="list-style-type: none"> 6. PGT [A7 9.2 ft-lb, CCW2 30 rpm, MTL 30.5]-7/16-6-in ext: Release Mast Tip fasteners (3), ~14 turns 7. Verify Mast Tip Fasteners are released <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <p><u>ZENITH (3B) ECU/SSU SHROUD REMOVAL AND JETTISON</u></p> <ol style="list-style-type: none"> 8. Translate to position near zenith ECU/SSU (nadir-aft-outboard) 9. Release SSU long strap on cover 10. Release ECU short straps (2) <input type="checkbox"/> <input type="checkbox"/> 11. Remove ECU shroud 12. Release ECU ground strap PIP pin Stow PIP pin in ECU shroud pocket <p>13. Time permitting, take photos</p> <p>14. Translate to shroud jettison location (retrograde, forward-nadir)</p> <p>On IV GO:</p> <ol style="list-style-type: none"> 15. Jettison ECU shroud 16. EV1 report speed/direction to IV
<u>Nadir (1B) Shrouds</u>	<u>Zenith (3B) Shrouds</u>							
ECU ____ ft/s _____	____ ft/s _____							
SSU ____ ft/s _____	____ ft/s _____							

EVA 1 UNSTOW SABB, RELEASE MAST, AND REMOVE ECU/SSU SHROUD (01:10) (Cont)

IV	EV1	EV2										
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Tool Inventory List</th> </tr> <tr> <th style="width: 50%;">EV1</th> <th style="width: 50%;">EV2</th> </tr> </thead> <tbody> <tr> <td> <ul style="list-style-type: none"> <input type="checkbox"/> PGT w/7/16-6-in ext + RET <input type="checkbox"/> 2 – RETs (1 w/PIP pin) <input type="checkbox"/> 1 – BRT w/RET <input type="checkbox"/> 1 – Trash Bag <input type="checkbox"/> 1 – Adj Tether <input type="checkbox"/> 2 – Wire Ties </td> <td> <ul style="list-style-type: none"> <input type="checkbox"/> PGT w/7/16-6-in ext + RET <input type="checkbox"/> 2 – RETs (1 w/PIP pin) <input type="checkbox"/> 1 – BRT w/RET <input type="checkbox"/> 1 – Trash Bag <input type="checkbox"/> 2 – Wire Ties </td> </tr> <tr> <th colspan="2" style="text-align: center;">Crewlock Bag</th> </tr> <tr> <td colspan="2"> <ul style="list-style-type: none"> <input type="checkbox"/> 1 – Adjustable Tethers (on outside of bag) <input type="checkbox"/> 1 – Torque Wrench (on outside of bag) w/adj tethers (2) <input type="checkbox"/> EVA Camera w/bracket + RET <input type="checkbox"/> 2 – Cannon Connector Tools w/RETs (2) <input type="checkbox"/> Rnd TM w/5/8-in prd socket <input type="checkbox"/> 1 – Socket caddy w/2-in socket + 5/8-7.8-in socket <input type="checkbox"/> Ratchet Wrench w/5/8-7.8-in socket </td> </tr> </tbody> </table>	Tool Inventory List		EV1	EV2	<ul style="list-style-type: none"> <input type="checkbox"/> PGT w/7/16-6-in ext + RET <input type="checkbox"/> 2 – RETs (1 w/PIP pin) <input type="checkbox"/> 1 – BRT w/RET <input type="checkbox"/> 1 – Trash Bag <input type="checkbox"/> 1 – Adj Tether <input type="checkbox"/> 2 – Wire Ties 	<ul style="list-style-type: none"> <input type="checkbox"/> PGT w/7/16-6-in ext + RET <input type="checkbox"/> 2 – RETs (1 w/PIP pin) <input type="checkbox"/> 1 – BRT w/RET <input type="checkbox"/> 1 – Trash Bag <input type="checkbox"/> 2 – Wire Ties 	Crewlock Bag		<ul style="list-style-type: none"> <input type="checkbox"/> 1 – Adjustable Tethers (on outside of bag) <input type="checkbox"/> 1 – Torque Wrench (on outside of bag) w/adj tethers (2) <input type="checkbox"/> EVA Camera w/bracket + RET <input type="checkbox"/> 2 – Cannon Connector Tools w/RETs (2) <input type="checkbox"/> Rnd TM w/5/8-in prd socket <input type="checkbox"/> 1 – Socket caddy w/2-in socket + 5/8-7.8-in socket <input type="checkbox"/> Ratchet Wrench w/5/8-7.8-in socket 		<ul style="list-style-type: none"> 17. Release SSU short straps (2) <input type="checkbox"/> <input type="checkbox"/> 18. Remove SSU shroud 19. Release SSU ground strap PIP pin Stow PIP pin in SSU shroud pocket 20. Time permitting, take photos 21. Translate to shroud jettison location (retrograde, forward-nadir) On IV GO: <ul style="list-style-type: none"> 22. Jettison SSU shroud 23. EV1 report speed/direction to IV 24. Verify both six-pack clamps are stowed in ext Stow Bin If six-pack clamps not already stowed in ext Stow Bin: <ul style="list-style-type: none"> <input type="checkbox"/> <input type="checkbox"/> Retrieve clamp(s) from temp stow location(s) (nadir at HR 2060 and zenith at HR 2072) <input type="checkbox"/> <input type="checkbox"/> Stow clamp(s) in external Stow Bin <input type="checkbox"/> <input type="checkbox"/> Verify Stow Bin MLI is secured (Velcro covered) 25. Translate to Crewlock Bag (S6 HR 2073 and HR 2074/HR 2072) 26. Transfer EVA Camera to EV2 27. Translate to APFR (S6 WIF 34) 28. Retrieve APFR. Stow APFR on BRT 29. Perform tool inventory 30. Perform glove/gauntlet inspection 	<ul style="list-style-type: none"> 17. Release SSU short straps (2) <input type="checkbox"/> <input type="checkbox"/> 18. Remove SSU shroud 19. Release SSU ground strap PIP pin Stow PIP pin in SSU shroud pocket 20. Time permitting, take photos 21. Translate to shroud jettison location (retrograde, forward-nadir) On IV GO: <ul style="list-style-type: none"> 22. Jettison SSU shroud 23. EV1 report speed/direction to IV 24. Translate to Crewlock Bag (S6 HR 2073 and HR 2074/HR 2072) 25. Receive EVA Camera from EV1 26. Stow EVA Camera in Crewlock Bag 27. BRT to Crewlock Bag 28. Perform tool inventory 29. Perform glove/gauntlet inspection
Tool Inventory List												
EV1	EV2											
<ul style="list-style-type: none"> <input type="checkbox"/> PGT w/7/16-6-in ext + RET <input type="checkbox"/> 2 – RETs (1 w/PIP pin) <input type="checkbox"/> 1 – BRT w/RET <input type="checkbox"/> 1 – Trash Bag <input type="checkbox"/> 1 – Adj Tether <input type="checkbox"/> 2 – Wire Ties 	<ul style="list-style-type: none"> <input type="checkbox"/> PGT w/7/16-6-in ext + RET <input type="checkbox"/> 2 – RETs (1 w/PIP pin) <input type="checkbox"/> 1 – BRT w/RET <input type="checkbox"/> 1 – Trash Bag <input type="checkbox"/> 2 – Wire Ties 											
Crewlock Bag												
<ul style="list-style-type: none"> <input type="checkbox"/> 1 – Adjustable Tethers (on outside of bag) <input type="checkbox"/> 1 – Torque Wrench (on outside of bag) w/adj tethers (2) <input type="checkbox"/> EVA Camera w/bracket + RET <input type="checkbox"/> 2 – Cannon Connector Tools w/RETs (2) <input type="checkbox"/> Rnd TM w/5/8-in prd socket <input type="checkbox"/> 1 – Socket caddy w/2-in socket + 5/8-7.8-in socket <input type="checkbox"/> Ratchet Wrench w/5/8-7.8-in socket 												

EVA 1 UNSTOW SABB, RELEASE MAST TIP – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	00:45
Two EV Crew	N/A	00:20

Tools:

EV1	EV2
PGT	
7/16 (wobble) Socket-6 ext	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Mast Canister Tip Fitting	Yes	7/16	3	7	8	12.8	14	30

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting
N/A		

Notes:

1. Mast Tip Fasteners will pop-up when disengaged

Cautions:

1. Deploy SABB no faster than 6 degrees/second (15 seconds minimum for complete deployment)
2. 4-bar linkage must be deployed and SABBs rotated into the deployed position before Mast Canister Tip Fitting restraints can be disengaged

Warnings:

1. Pinch point hazard – Stay clear of pivot fitting and lockout arm during SABB rotation
2. When captive EVA fasteners are released, the pop-up spring could protrude out between the bolt head and housing producing a puncture hazard

EVA 1 UNSTOW SABB, RELEASE MAST TIP – TASK DATA (Cont)

EVA Tools:

EV1 (FF)	EV2 (FF)
N/A	N/A


EVA Fasteners: None

EVA Connectors: None

Foot Restraints: None

Notes:

1. If only one shroud set is removed, 1B covers are preferred
2. If only one shroud of a set is removed, ECU is preferred



Left Side of SSU Shroud – 2 Short Straps



Right Side of SSU Shroud – 1 Long Strap

**EVA 1 S6 MMOD SHIELD BOLT TORQUE RELEASE (00:20)
(GET-AHEAD)**

IV	EV1/2 – Swanson/Arnold (FF)
<ol style="list-style-type: none"> 1. Verify with MCC-H, station configuration good for MMOD Shield bolts release (SARJ DLA locked) 2. Give EV GO for MMOD shield bolt release 	<p><u>IEA MMOD SHIELD BOLT RELEASE</u> (00:20) (GET-AHEAD)</p> <ol style="list-style-type: none"> 1. On IV GO, translate to S6 MMOD shield 2. PGT[B7 25.5 ft-lbs, CCW1 10 RPM, MTL 30.5]-6ext 7/16: Release IEA MMOD Shield bolts, ~1 turn <ul style="list-style-type: none"> <input type="checkbox"/> Zenith (Keel side) – Inboard (#1) <input type="checkbox"/> Zenith (Keel side) – Outboard (#2) <input type="checkbox"/> Nadir (Non-Keel side) – Outboard (#3) <input type="checkbox"/> Nadir (Non-Keel side) – Inboard (#4) 3. Report to IV when MMOD Shield bolts (4) are released (Retrieve ratchet wrench and stow at Keel Pin location, as reqd)

EVA 1 S6 MMOD SHIELD BOLT TORQUE RELEASE – TASK DATA (GET-AHEAD)

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	01:00
Two EV Crew	N/A	00:30

Tools:

EV1	EV2
PGT	PGT
7/16 (wobble) Socket-6 ext	7/16 (wobble) Socket-6 ext
	EVA Temp Rail Stop

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
MMOD Shield Bolt	Yes	7/16	4	37.5 gnd	42.2	93.5	1	10
SVS Target bolts	No	7/16	4	3.3-4.2	3.8	7.5	11.5	60
ETRS Bolts	No	7/16	2	4.2-6.6	NA	12.8	4-6	30

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting
Zenith (Keel side) Inboard (#1)		
Zenith (Keel side) Outboard (#2)		
Nadir (Non-Keel side) Outboard Bolt (#3)		
Nadir (Non-Keel side) Inboard Bolt (#4)		

Notes:

- Requirement for releasing torque on IEA MMOD Shield Bolts is within 1 year of launch

Cautions:

- ETRS bolts are not captive. Bolts may be lost if released more than 15 turns
- During removal of SVS fasteners:
 - Limit turn count to minimum required for fastener release
 - Minimize side loading bolt head
 - Maintain axial force on fastener to compress spring during rotation

Warnings:

None



IEA MMOD Shield Bolt

EVA 1 CLEANUP (00:40)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
<p>1. Record APFR settings _____</p> <p>2. IV verify both EV crew are inboard of the starboard SARJ. Then, give MCC-H GO to rotate starboard SARJ, as reqd</p>	<p><u>CLEANUP</u></p> <ol style="list-style-type: none"> 1. Translate to spare safety tether stow location (S5 HR 2114) 2. Tether swap back to primary 85-ft safety tether <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Safety Tether Reel unlocked 3. Stow spare Safety Tether on Crewlock Bag 4. Translate to CETA Carts 5. Stow APFR at CETA Cart 2 (outboard) WIF 04 (zenith-outboard); report settings 6. Translate to EV2 prime Safety Tether anchor point (S1 HR 3222) 7. EV1 remain at S1 HR 3222 until EV2 gives GO for Safety Tether swap 8. EV1 give GO to IV for starboard SARJ rotation, when inboard of SARJ 	<p><u>CLEANUP</u></p> <ol style="list-style-type: none"> 1. Translate to spare safety tether temp stow location (S5 HR 2116) 2. Tether swap back to primary 85-ft safety tether <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Safety Tether Reel unlocked 3. Stow spare Safety Tether on Crewlock Bag 4. Translate to Airlock

EVA 1 A/L INGRESS (00:15)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
<p>1. Perform prior to ingress: WVS PWRDN (PHOTO/TV, <u>WVS CUE CARD</u>)</p> <p>2. EV1 and EV2 – begin cold soak, as reqd</p>	<p><u>INGRESS</u></p> <p>1. On EV2 GO, connect right waist tether to EV2 safety tether hook and release EV1 Safety Tether and attach to MWS</p> <p>2. Adjust TCV to begin cold soak, as reqd</p> <p>3. Translate to Airlock</p> <p>4. Ingress Airlock</p> <p>5. Close thermal cover. Attach Velcro straps</p> <p>DCM 6. Retrieve SCU, remove DCM cover</p> <p>7. Connect SCU to DCM. √SCU locked</p> <p>8. WATER – OFF (fwd), expect H2O IS OFF msg</p> <p>9. Verify outer hatch clear of hardware</p> <p>10. EV Hatch – verify handle position per hatch decal. Close and lock hatch</p> <p>11. Go to PRE REPRESS portion of {CREWLOCK DEPRESS/REPRESS CUE CARD} (SODF: ISS EVA SYS: EVA PREP/POST)</p>	<p><u>INGRESS</u></p> <p>1. Open hatch thermal cover</p> <p>2. Ingress Airlock</p> <p>3. Attach right waist tether to EVA hatch D-ring extender</p> <p>4. Give EV1 GO to attach right waist tether to EV2 safety tether</p> <p>5. Release Crewlock Bag from BRT, stow bag in Airlock</p> <p>6. Adjust TCV to begin cold soak, as reqd</p> <p>7. Perform EVA Camera ops, as reqd</p> <p>DCM 8. Retrieve SCU, remove DCM cover</p> <p>9. Connect SCU to DCM. √SCU locked</p> <p>10. WATER – OFF (fwd), expect H2O IS OFF msg</p> <p>11. Go to PRE REPRESS portion of {CREWLOCK DEPRESS/REPRESS CUE CARD} (SODF: ISS EVA SYS: EVA PREP/POST)</p>
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> <p>CAUTION Do not close hatch until EMU WATER – OFF for 2 min</p> </div>		

This Page Intentionally Blank

NOTES

NOTES

EVA 2 SUMMARY TIMELINE

PET HR : MIN	IV	15A EVA 2 EV1 – Swanson	EV3 – Acaba	PET HR : MIN
00:00		<u>EVA 2 POST DEPRESS, EGRESS & SETUP (00:50)</u> <ul style="list-style-type: none"> • Post Depress/Egress (00:20) • Setup (00:30) 	<u>EVA 2 POST DEPRESS, EGRESS & SETUP (00:50)</u> <ul style="list-style-type: none"> • Post Depress/Egress (00:20) • Setup (00:30) 	00:00
01:00		<u>P6 BATTERY PREP (01:10)</u> <ul style="list-style-type: none"> • APFR Install • Gap Spanner Install • Break Torque on P6 Batteries 	<u>P6 BATTERY PREP (01:10)</u> <ul style="list-style-type: none"> • APFR Install • Gap Spanner Install • Break Torque on P6 Batteries 	01:00
02:00		<u>P3 NADIR UCCAS (01:15)</u>	<u>P3 NADIR UCCAS (01:15)</u>	02:00
03:00		<u>P1 RBVM MLI (00:15)</u>	<u>P1/P3 FLUID JUMPER (00:30)</u>	03:00
04:00		<u>P1 FHRC P-CLAMPS (00:50)</u>	<u>P1 FHRC P-CLAMPS (00:35)</u>	04:00
05:00		<u>S3 OUTBOARD/ZENITH PAS (01:00)</u>	<u>S3 OUTBOARD/ZENITH PAS (01:00)</u>	05:00
06:00		<u>TOOL STANCHION RELOCATE (00:25)</u>	<u>APFR RETRIEVE (00:25)</u>	06:00
		<u>EVA 2 CLEANUP & INGRESS (00:40)</u> <ul style="list-style-type: none"> • Cleanup (00:15) • Ingress (00:25) 	<u>EVA 2 CLEANUP & INGRESS (00:40)</u> <ul style="list-style-type: none"> • Cleanup (00:15) • Ingress (00:25) 	06:00
-06:30	EVA 2 PET = 06:30 hr	<u>PRE-REPRESS (00:05)</u>	<u>PRE-REPRESS (00:05)</u>	-06:30

EVA 2

EVA 2 INHIBIT PAD

Orbiter (1)

ALL EVAs
TCS L12 1. √TCS POWER – OFF
KU-BAND ANTENNA MCC-H 1. √KU-BAND Mask – active 2. √KU-BAND EVA Protect Box – active

Ground

ALL EVAs
Ground Radar MCC-H 1. √TOPO console, ground radar restrictions in place for EVA

USOS (1)

TASK SPECIFIC INHIBITS
P6 Battery Prep MCC-H 1. BGA 2B locked 2. BGA 4A locked (Will be unlocked once EV on P6 IEA)

USOS (2)

ALL EVAs
PCU <p style="text-align: center;"><u>NOTE</u> PCUs may require up to a 1-hr warmup period before they are operational</p> MCC-H 1. √PCUs (two) operational in discharge mode and one of the following: a. CCS PCU EVA hazard control FDIR enabled b. No more than two arrays unshunted and oriented < 105° from velocity vector If one or both PCUs failed 2. No more than two arrays unshunted and oriented < 105° from velocity vector
EuTEF COL-CC Verify PLEGPAY Power Status (ETF_PLEGPAY_Pwr_Stat) – OFF
LOCATION DEPENDENT INHIBITS
Lab Window {For APFR relocation} IV When EV crew less than 10 ft from window or in window FOV, close window shutter
KU-Band (SGANT) Antenna {On call, EV crew not expected to be in this area} MCC-H If EV crew < 3.3 ft from KU-BAND antenna 1. Park KU-BAND: 1.1 Pointing Mode – Inhibit 1.2 PLC – Reset 1.3 Autotrack Continuous Retry – Inhibit
Mobile Transporter MCC-H 1. √MT latched

EVA 2 INHIBIT PAD (Cont)

USOS (3)

LOCATION DEPENDENT INHIBITS

S-Band (SASA) Antennas

{On call, EV crew not expected to be in this area}

MCC-H If EV crew < 3.6 ft from S1 SASA [P1 SASA]

1. P1 SASA (S1 SASA) – Active
2. S1 SASA [P1 SASA] – Powered down

SARJ

{P6 Battery Prep & P3 Nadir UCCAS}

MCC-H When EV crew working within 2 ft or outboard of Port SARJ

1. √DLA (1) – LOCKED
2. All motor setpoints set to zero
3. All motors deselected

{S3 Outboard/Zenith PAS}

MCC-H When EV crew working within 2 ft or outboard of Stbd SARJ

1. √DLA (1) – LOCKED
2. All motor setpoints set to zero
3. All motors deselected

TRRJ

{EVA Start through P1 FHRC P-Clamps}

MCC-H When EV crew working or safety tether within 2 ft of P1 TRRJ rotation envelope

1. √DLA (1) – LOCKED

{S3 Outboard/Zenith PAS}

MCC-H When EV crew working or safety tether within 2 ft of S1 TRRJ rotation envelope

1. √DLA (1) – LOCKED

FPMU

{On call, EV crew not expected to be in this area}

MCC-H If EV crew working within 5 ft of Floating Potential Measurement Unit

1. FPMU power – Off

SSPTS

{On call, EV crew not expected to be in this area}

MCC-H If EV crew working within 2 ft of SSPTS cables

1. RPCM LA1A4A D RPC 3 – Open, Close Cmd Inhibit
2. RPCM LA2A3B D RPC 1 – Open, Close Cmd Inhibit
3. RPCM Z14B A RPC 2 – Open, Close Cmd Inhibit
4. RPCM Z13B A RPC 2 – Open, Close Cmd Inhibit

EVA 2 INHIBIT PAD (Cont)

RSOS (1)

ALL EVAs	
SM Antennas IV	<ol style="list-style-type: none">1. GTS – Deactivate2. ARISS (Ham Radio) – Deactivate or VHF (144-146 MHz) TX only
EVAs ON PMA1 OR RSOS (LOCATION DEPENDENT)	
FGB Thrusters {APFR Relocate} MCC-M	<ol style="list-style-type: none">1. √FGB MCS unpowered2. √All FGB Attitude Control Thruster Valves (eighty) – closed3. √FGB Attitude Control Manifold Valves – closed KШK1, KШK2, KШK4, KШK5, KШK9, OKO3, OKГ3, OKO6, OKГ6, OKO7, OKГ7, OKO8, OKГ8
Soyuz Thrusters {APFR Relocate} MCC-M	<ol style="list-style-type: none">1. √Soyuz manifolds (four) – closed ЭKO1, ЭKO2, ЭKГ1, ЭKГ22. √Soyuz MCS unpowered3. √Soyuz Attitude Control Thruster Valves (fifty-two) – closed4. √Soyuz Main Engine Valves (K1, K2, K3, K4, K5, K6) – closed
FGB Antennas {APFR Relocate} MCC-M	<ol style="list-style-type: none">1. √FGB KURS P [KYPC P] – Deactivated
Soyuz Antennas {APFR Relocate} MCC-M	<ol style="list-style-type: none">1. √Soyuz KURS A [KYPC A] – Deactivated

EVA 2 NOTES, CAUTIONS, AND WARNINGS

NOTES

1. Bolt install: Report torque and turns
2. Bolt release: Report torque and turns (if different from published range)
3. EVA connectors: After dis-connection and prior to connection; verify pin and EMI band integrity. Verify connector free of FOD
4. Inspect Fluid QDs for damage, prior to mating
5. Toolbox doors must be closed with one latch per door, when EV crew not in immediate vicinity
6. Avoid contact with OBSS striker bars (Vitrolube coating)

CAUTION

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture shafts (drylube)
 2. PIP pins
 3. EVA Crane [PMA1]
 4. TCS Reflectors [PMA2,PMA3]
 5. APAS hardware [PMA2,PMA3]
 6. CETA Lights (Z-93 paint) [LAB,S1,Node 1]
 7. Deployed MISSEs [Columbus EPF]
 8. Passive UMAs
 9. MBS/SSRMS/SPDM/JEMRMS taped radiative surfaces: VDU, ACU, JEU, LEU, MCU, CRPCMs, and Cameras
 10. Deployed TUS cable [Nadir CETA rail]
 11. S0 aft face Radiator
 12. GPS Antennas (S13 paint) [S0,JLP]
 13. UHF Antennas [LAB,P1]
 14. ETCS Radiator flexhoses and panels [S1,P1]
 15. EETCS/PV Radiator flexhoses, bellows and panels [P6,P4,S4,S6]
 16. SASA RF Group [S1,P1]
 17. Heat pipe radiators [Z1]
 18. PCU cathode and HCA ports [Z1]
 19. Ku-Band Antenna (SGANT) dish [Z1]
 20. CMG cover/shells [Z1]
 21. SPDM SJEU, EP, OTCM, LEU, and LEE VDU Radiator surfaces
 22. Open CBM petal covers, LAB window shutter, and JPM window shutter
 23. FPMU [S1]
 24. OTSD
 25. COL HAM radio antennas [COL-Nadir]
 26. JTVE Cameras [JEM]
 27. JEM A/L Target and Pins
 28. S0/Node 2 Fluid Tray Hardlines at Node 2 end are limited to 25 lb

CAUTION (Cont)

ISS Constraints (Cont)

- B. Electrical cables
1. Avoid bend radii < 10 times cable diameter
- C. Fiber optic cables
1. Avoid bend radii < 10 times cable diameter
 2. Avoid pulling on cable during mate/demate
- D. Fluid line flex hoses and QDs
1. Avoid bend radii < 5 in for hoses with diameter < 1 in on LAB, S0, S1, P1, and 10-in for hoses with diameter < 1 in on all other elements
 2. Avoid bend radii < 14 in for hoses with a diameter ≥ 1 in
 3. Additional care should be taken to not exceed bend radii when applying loads at the flexible hose to rigid tube stub interfaces
 4. Ensure fluid QD booties are fully closed prior to leaving worksite; wire tie if reqd
- E. For structural reasons
1. Avoid vigorous body motions, quick grabs and kickoffs against tether restraints
 2. Avoid performing shaking motions (sinusoidal functions) more than four cycles
 3. Avoid kicking S1/P1 radiator beam
If any of these occur, wait 2 to 5 min to allow structural response to dissipate

EVA 2 NOTES, CAUTIONS, AND WARNINGS (Cont)

CAUTION (Cont)

ISS Constraints (Cont)

F. Other

1. ITT Cannon connector: On demated connectors, do not rotate collar or manipulate cable/connector using collar or connector tool
2. **WIS Antennas: Do not use as handholds [Node 1,P6,Z1]**
3. Lubricant from Ku-Band SGANT gimbals [Z1], CMGs [Z1], and RTAS Ground Strap fasteners [P6,P4,S4] can contaminate EMU
4. **MLI handholds are not rated for crewmember translation loads**
5. CBM petal covers may not be used as handholds unless both launch restraint pins are engaged
6. Prevent inadvertent contact of the tether shuttle with ETRS when the P3/S3 Tether Shuttle Stop is raised away from the rail

CAUTION (Cont)

Shuttle Constraints

A. Avoid inadvertent contact with

1. OBSS and SRMS Composite Sections, Joint Torque Arms, Grapple Fixture Shafts, and Cable Harnesses
2. LCS (silver Teflon) and LDRI (silver Teflon) and ITVC (gold foil) [OBSS]
3. WVS Antenna [ODS Truss & PLB Sill]
4. Payload Bay and Camera wire harnesses, cables, cable guides, and connectors

B. No touch

1. LDRI diffuser [OBSS]
2. OBSS saddle contacts (when OBSS unberthed) [OBSS]
3. Monkey fur [PLB]
4. Cameras: Metallic surfaces [PLB]
5. Ku-Band Antenna black dish and gold thermal blankets [PLB]

EVA 2 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture targets and target pins
 2. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off
 3. Stay inboard of SARJ when active
 4. Stay 2 ft from S1/P1 radiator beam rotational envelope when beam is free to rotate
 5. Stay 5 ft from moving MT on face 1
 6. SOLAR and EuTEF [COL EPF]
- B. Handrails
1. Handrails previously used for MISSE attachment may not be used as a safety tether point [A/L endcone 564 & 566, A/L Tank 2 nad/fwd & port/fwd, P6 5389]
- C. Pinch
1. NZGL connector linkage. Use caution when mating/locking
 2. ITT Cannon Connector rotating housing
 3. EV side of IV Hatch during Hatch operation (also snag hazard) [A/L]
 4. LAB window shutter and CBM petal cover and JPM window shutter linkages during operation
 5. JEMRMS HRM capture latches
 6. JEM Cameras (JTVEs, EVE, WVE)
 7. JEM EFBM capture latches
- D. QDs
1. If QD is in FID when valve is opened (bail fwd), QD will leak and fluid line may whip
 2. Do not rotate if in mated/valve open config

WARNING (Cont)

ISS Constraints (Cont)

- E. RF radiation exposure
1. Stay 3.6 ft from S-Band (SASA) high gain Antenna when powered [S1,P1]
 2. Stay 1.3 ft from S-Band (SASA) low gain Antenna when powered [S1,P1]
 3. Stay 1 ft from UHF Antenna when powered [LAB,P1]
 4. Stay 0.3 ft from fwd/aft JPM PROX antenna
- F. Sharp Edges
1. Inner edges of WIF sockets
 2. APFR active WIF probes
 3. Mating surfaces of EVA connectors
Avoid side loads during connector mating
 4. Back side of MMOD shield fasteners
 5. Spring loaded captive EVA fasteners (e.g., 6B-boxes, BMRRM, RTAS, SARJ Covers); the end of the spring may protrude
 6. PMA umbilical launch restraints-exposed bolt threads
 7. Adjustable Fuse Tether (Fish Stringer) buckles stowed in Node Bag
 8. Nickel coated braided copper Ground Straps may contain frayed wires [P6,P4,S4,S6]
 9. SPDM OTCM gripper jaws

WARNING (Cont)

ISS Constraints (Cont)

- F. Sharp Edges (Cont)
10. Solar Array Blanket Box [P6,S6]
 11. Keep hands away from SSRMS LEE/POA/SPDM LEE/JEMRMS EE opening, snares, and PDGF curvic coupling (teeth)
 12. Fastener threads on back of Z1 U-jumper male FQD panel, if nutplate cap missing
 13. Outboard MT rail attachment lug near P6 handrail 5333 and gap spanner
 14. P2 connector on EWIS box TAA-06 [Zenith/Forward Corner 1 of P5 – SARJ at 0 deg]
 15. Port/Aft portion of A/L circular HR [HR 0506]
 16. Interior of JEMRMS HRMs
 17. JEM A/L hatch corners
- G. Thermal
1. EVA connectors with booties may become hot if left uncovered. Handling may need to be limited
 2. PMA handrails may be hot. Handling may need to be limited
 3. Turn off glove heaters when comfortable temp reached to prevent bladder damage. Do not pull fingers out of gloves when heaters are on
 4. Uncovered trunnion pins may be hot
 5. SSRMS/MBS/SPDM/JEMRMS/JTVE operating cameras and lights may radiate large amounts of heat

EVA 2 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING (Cont)

ISS Constraints (Cont)

G. Thermal (Cont)

6. Stay ≥ 1 ft away from PMAs and MMOD shields > 270 degF if EMU sun visor up; limit time to 15 min or less if > 300 degF
7. Stay at least 0.5 ft away from PMA and MMOD shields > 325 degF
8. Do not touch EMU protective visor if temp has been < -134 degF for > 15 min
9. No EMU TMG contact with PMAs and MMOD shields > 320 degF
10. No EMU boot contact with foot restraint when temp < -120 degF or > 200 degF
11. Columbus end cones may violate touch temperature constraints when $-75 \leq \beta \leq -60$ or $60 \leq \beta \leq 75$
12. PDGF surfaces may not meet touch temperature requirements for unlimited contact when $\beta \leq -70$ or $\beta \geq 70$
13. JPM port end cones and JLP port nadir may violate touch temperature constraints when $\beta > 60$ deg

WARNING (Cont)

ISS Constraints (Cont)

H. Electrical Shock

1. Stay ≥ 2 ft from ungrounded floating connectors if not unpowered
 - SSPTS connectors include NOD1 Stbd/Fwd HR 0130, Lab Stbd/Fwd HR 0273, PMA2 Stbd and Port
 - MBS Cross-Connect jumpers (translate past these using UMA handrails) Include S0 EVA Power Cables (inside S0 Bay 00 Face 4, Bay 01 Face 3) ESP2 jumper (inside S0 Bay 03 Face 4)
2. Do not touch SPDM CLPA 1 electrical connector prior to camera installation

WARNING (Cont)

Shuttle Constraints

A. Arcing/Molten Debris

1. Stay ≥ 2 ft from exposed EFGF connector when OBSS berthed, powered, and EFGF not grappled [PLB]
2. Stay ≥ 2 ft from exposed Stbd Fwd MPM contacts [PLB]
3. Stay above PLB sill when within 1 ft of powered ROEU connector [PLB]

B. Pinch

1. PRLA operation [PLB]

C. RF radiation exposure

1. Stay 3.28 ft from S-Band Antenna when powered
2. Stay 1 ft from top and side of UHF PLB Antenna radome surface when in high powered mode [ODS truss]
3. Stay 0.33 ft from top and side of UHF PLB Antenna radome surface when in low powered mode [ODS truss]
4. Remain below the level of the PLB door mold line for first 20 in Aft of Fwd bulkhead when S-Band Antenna powered [PLB]
5. Remain on the inboard side of the Stbd slidewire (sill handrails if slidewire not installed) for first 20 ft Aft of Fwd bulkhead when Ku-Band Antenna powered [PLB]

EVA 2 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING (Cont)

Shuttle Constraints (Cont)

D. Sharp Edges

1. PRLA grounding wipers [PLB]
2. LDRI baffles (also an entrapment hazard) [OBSS]
3. Keep hands away from SRMS EE opening and snares
4. TCS connector backshells have exposed threads [ODS]

E. Thermal

1. Illuminated PLB lights; do not touch
2. OBSS grapple fixture shafts/cams may be hot. Limit handling if required
3. Stay 27 ft from PRCS when powered
4. Stay 3 ft from VRCS when powered
5. Stay 3 ft from APU when operating

F. Contamination

1. Stay out of the immediate vicinity of leaking jet or APU

G. Lasers

1. Do not look at LDRI diffuser or LCS laser aperture window

EVA 2 TOOL CONFIG

EV1

EMU D-rings

- Ext on left side
- Ext on right side
- Waist Tether [right D-ring extender]
- 85-ft Safety Tether [right D-ring extender]

MWS

- Small Trash Bag [right inside]
- Adj tether
- RET (sm-sm) [left]
- RET(w/PIP pin) [right]
- 2 – Wire ties

- Swing Arm [right side]
 - PGT w/7/16-6-in ext s/n _____
 - RET (sm-sm)

- BRT [left side]
 - 2 – Wire ties (short)
 - RET (sm-sm)

- SAFER

NOTE: Prior to use, inspect the following hardware:

- RET cords for fraying
- Safety Tether & Waist Tether load alleviating straps: No red visible
- Sm Trash Bag: Bristle deformation/damage, after stowing tools in trash bag

EV3

EMU D-rings

- Ext on left side
- Ext on right side
- Waist Tether [right D-ring extender]
- 85-ft Safety Tether [right D-ring extender]

MWS

- Small Trash Bag [left inside]
 - Adj tether
 - Gap Spanner, 72-in
 - Adj tether
 - Small Trash Bag [right inside]
 - RET (sm-sm) [left]
 - RET(w/PIP pin) [right]
 - 2 – Wire ties

- Swing Arm [right side]
 - PGT w/7/16-6-in ext s/n _____
 - RET (sm-sm)

- BRT [left side]
 - 2 – Wire ties (short)
 - RET (sm-sm)

- SAFER

Use Blue RETs Only

Tether Count:	(used)	(total) ISS qty
RET (sm-sm)	7	16
RET (w/PIP pin)	4	5
RET (Lg-sm)	2	8
Adj Tethers (sm-sm)	4	10
Adj Tethers (Lg-sm)	0	2
D-ring Extenders	5	6

CREWLOCK

- Tether Ext on A/L D-ring

- RET (Lg-sm)

- Crewlock Bag #3

- Adj tether [to outside of bag]
- EV1 spare 85-ft ST [outside TPs]
- EV3 spare 85-ft ST [outside TPs]
- Ratchet Wrench (int RET #1)
 - 7/16-2-in rigid ext
- Ratchet Wrench (int RET #2)
 - 7/16-2-in rigid ext
- RET (w/PIP pin)
 - 7/16-18-in ext
- RET (sm-sm or int RET #3)
 - EVA Camera w/bracket
- RET (w/PIP pin) (for 6-in wobble)
 - Gap Spanners, 72-in
 - Gap Spanners, 45-in
 - Gap Spanners, 72-in
 - Gap Spanners, 45-in (buckles in the middle)

- RET (Lg-sm) (Attach to A/L D-ring ext)
 - APFR

Bag Color Key: 119 EVA Tools, Staging, Crewlock MWS

EVA 2 TOOL CONFIG (Cont)

CREWLOCK (Cont)

Staging Bag

- Fish Stringer #1
 - Wire Tie Caddy (hook #1)
 - 9 wire ties
 - Velcro/Tape Caddy (hook #2)
 - PGT (hook #3) s/n 1008
 - PGT Battery s/n _____
 - 7/16-in (wobble) Socket – 6 ext
 - Vise Grips (hook #4)
 - Ratchet Wrench (hook #5)
 - 7/16-in (rigid) Socket – 9 ext
 - Cheater Bar (hook #6)
 - Hammer (hook #7)
 - 55-ft Safety Tether (to strap)
- Fish Stringer #2
 - Connector Cleaner Tool Kit (Hook #1)
 - Pin Straightener Tool (Hook #2)
 - Probe (Hook #3)
 - Prybar (Hook #4)
 - Needle Nose Pliers (Hook #5)
 - Torque Wrench w/bag
 - (set to 31) (Hook #6)
 - Right Angle Drive (Hook #7)
 - Long-Duration Tie-Down Tether (to strap)
 - Long-Duration Tie-Down Tether (to strap)
 - MWS Key Strap Assy (on Wire Tie to strap)
 - EVA Camera (Int RET to strap)
- RET (Lg-sm)
 - Sm ORU Bag
 - Fish Stringer #3 (May be in Staging Bag)
 - Cnctr Insulating Sleeve Size 21/25 (Hook #1)
 - Cnctr Insulating Sleeve Size 21/25 (Hook #2)
 - Cnctr Insulating Sleeve Size 21/25 (Hook #3)
 - Cnctr Insulating Sleeve Size 21/25 (Hook #4)
 - Cnctr Insulating Sleeve Size 33/37 (Hook #5)
 - Cnctr Insulating Sleeve Size 33/37 (Hook #6)

CREWLOCK (Cont)

IV Bag

- 2 – Towel
- Contamination Detection Kit
- 2 – GP Caddy
 - Thermal Mittens (1 pair)
- RET (sm-sm) (Black)
 - Socket Caddy
 - 1/2-in (wobble) Socket – 8 ext
 - 7/16-in (wobble) Socket – 6 ext
- 2 – DCM Plug (SAFER Hardmount)
- 2 – RET (sm-sm, black)

EQUIPMENT LOCK

Med ORU Bag

Empty

Med ORU Bag

- Fish Stringer
 - JLP GPS Ant B
- WETA

- Review PGT ops
 - Report “green light” (for torque down ops)
 - Report torque and turns
 - Expect LOTORQ fault msg, Fault LED and Red LED for bolt release ops

EQUIPMENT LOCK(Cont)

Mesh Bag #1 (119 EVA Tools)

- WIF Adapter
- 2 – EVA Wipes
- Grease Gun
 - EVA Wipe & Wire Tie
- 2 – Wire Ties (short)
- 2 – Wire Ties (long)
- BRS Pin Tool w/Sheath
- Ziplock w/Grease Gun Caps

Mesh Bag #2 (Done Tools)

- 5/8-7.8-in extension
- 5/8-7.8-in extension
- Round TM w/5/8-in Prd Socket
- Socket Caddy
- Torque Wrench Bag
- Cannon Connector Tool
- Cannon Connector Tool
- Cnctr Insulating Sleeve Size 33/37

Mesh Bag #3 (Transfer to Shuttle)

- Locking Strut Aid
- Locking Strut Aid
- Locking Strut Aid
- Locking Strut Aid
- Torque Wrench (s/n 1007)

Crewlock Bag #1 (EVA 3)

- RCC Gap Gauge (Int RET #1)
- Adj tether (Int RET #2)
 - EVA Wipe
 - EVA Wipe

Crewlock Bag #2 (EVA 3)


- RPCM (Int RET #1)
- Round Scoop (Int RET #2)

Crewlock Bag #4 (EVA 3)



- RPCM (Int RET #1)
- Round Scoop (Int RET #2)

Bag Color Key: 119 EVA Tools, Staging, Crewlock MWS Shuttle

EVA 2 A/L EGRESS AND SETUP (00:50)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
 <div data-bbox="142 722 703 885" style="border: 1px solid black; padding: 5px;"> <p>1 - 85-ft A/L tether - EV1 1 - 85-ft A/L tether - EV3 > EMU</p> <p>1 - 85-ft tether - EV1 1 - 85-ft tether - EV3 > Crewlock Bag 3</p> </div> <ol style="list-style-type: none"> 1. Post crew egress: WVS Software: Select page – RF Camera sel 'Advanced controls' S-Band level (two) – max (Required after A/L egress) <p style="text-align: center;"><u>NOTE</u></p> <p>Sunrise/Sunset checks</p> <ul style="list-style-type: none"> • \sqrtHelmet lts, visor, as reqd • \sqrtGloves & Gauntlets • \sqrtTool, MWS tethers • \sqrtMWS, BRT latches 	<p><u>INITIAL CONFIG</u></p> <p>Verify:</p> <ul style="list-style-type: none"> <input type="checkbox"/> EV1 right waist tether connected to EV3's 85-ft safety tether <input checked="" type="checkbox"/> \sqrtGate closed (both hooks) <input checked="" type="checkbox"/> \sqrtHook locked (both hooks) <input checked="" type="checkbox"/> \sqrtReel unlocked <p><u>EGRESS (00:20)</u></p> <ol style="list-style-type: none"> 1. Open hatch thermal cover 2. Egress crewlock 3. Receive C/L bag #3 from EV3 and attach to BRT 4. Verify EV3 SAFER Configuration: <ul style="list-style-type: none"> <input checked="" type="checkbox"/> \sqrtR Handle down (HCM door – Closed) <input checked="" type="checkbox"/> \sqrtL Handle down (MAN ISO Valve – Open) 5. Translate to P1/P3 tether swap location (P1 nadir-outboard, near CP9) 6. Attach EV1 85-ft safety tether hook to P1 HR 3652 out of EV3s translation path (nadir of P1 FHRC) <ul style="list-style-type: none"> <input type="checkbox"/> \sqrtGate closed <input checked="" type="checkbox"/> \sqrtHook locked <input checked="" type="checkbox"/> \sqrtReel unlocked 7. Attach EV3 85-ft safety tether hook to P1 HR 3651 <ul style="list-style-type: none"> <input type="checkbox"/> \sqrtGate closed <input checked="" type="checkbox"/> \sqrtHook locked 8. Release EV1 waist tether from EV3 safety tether 9. Give EV3 GO to release EV3 waist tether from Airlock D-ring 10. Translate to LAB WIF 7 	<p><u>INITIAL CONFIG</u></p> <p>Verify:</p> <ul style="list-style-type: none"> <input type="checkbox"/> EV3 right waist tether connected to Airlock D-ring extender <input checked="" type="checkbox"/> \sqrtGate closed <input checked="" type="checkbox"/> \sqrtHook locked <p><u>EGRESS (00:20)</u></p> <ol style="list-style-type: none"> 1. Transfer C/L bag #3 to EV1; RET(Lg-sm) to A/L D-ring ext 2. Egress crewlock 3. Verify EV1 SAFER Configuration: <ul style="list-style-type: none"> <input checked="" type="checkbox"/> \sqrtR Handle down (HCM door – Closed) <input checked="" type="checkbox"/> \sqrtL Handle down (MAN ISO Valve – Open) 4. Perform translation adaptation as reqd 5. <input type="checkbox"/> \sqrtReel unlocked 6. On EV1 GO, release right waist tether from Airlock D-ring 7. Close hatch thermal cover


EVA 2 A/L EGRESS AND SETUP (00:50) (Cont)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
<p>View of P6 IEA (Non-Keel Side)</p>  <p>HR 5304 HR 5306 WIF 30</p> <p>Gap spanner placement</p> <p>HR 5332 #2 2B3_2 (EV3) waist tether #4 2B1_2 (EV1) HR 5371 #3 2B2_2 (EV1)</p> <p>HR 5333 #1 2B3_1 (EV3) HR 5348 #1 2B1_1 (EV1) HR 5358 #2 2B2_1 (EV1)</p> <p>HR 5342 PV radiator HR 5353</p> <p>outboard (port end)</p> <p>Inspect bolts on Adapter Plate not WIF (2 of 4 shown)</p>	<p>SETUP (00:30)</p> <ol style="list-style-type: none"> Attach C/L bag #3 to APFR Retrieve APFR [RR,D,12] and install on BRT Fairlead at P1 HR 3654 Translate zenith to P5 HR 5202 Tether swap to spare 85-ft ST <ul style="list-style-type: none"> <input type="checkbox"/> <input type="checkbox"/> √Gate closed (both hooks) <input type="checkbox"/> <input type="checkbox"/> √Hook locked (both hooks) <input type="checkbox"/> √Reel unlocked Attach old ST to HR 5202 and unlock reel Retrieve EV3 spare 85-ft ST, stow on P5 HR 5226 <div style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p>WARNING Outboard MT rail attachment lug near P6 handrail 5333 and gap spanner may be sharp</p> </div> <ol style="list-style-type: none"> Translate to P6 (non-keel side IEA), WIF 30 Install APFR [12,RR,D,12] in WIF 30 <ul style="list-style-type: none"> <input type="checkbox"/> √Blk-Blk, pull/twist test Remove C/L bag #3 from APFR Temp stow C/L bag #3 on HR 5306 & HR 5305 	<p>SETUP (00:30)</p> <ol style="list-style-type: none"> Translate to LAB WIF 11 Retrieve APFR [GG,F,6] from LAB WIF 11 Translate nadir to P5 HR 5226 <ol style="list-style-type: none"> Perform safety tether swap on P5 HR 5218 <ul style="list-style-type: none"> <input type="checkbox"/> <input type="checkbox"/> √Gate closed (both hooks) <input type="checkbox"/> <input type="checkbox"/> √Hook locked (both hooks) <input type="checkbox"/> √Reel unlocked Attach old ST to HR 5218 and unlock reel <ol style="list-style-type: none"> Translate to P6 (long spacer) WIF 10 Inspect P6 WIFs 9 and 10 baseplates <ul style="list-style-type: none"> <input type="checkbox"/> √4 fasteners present and flush with WIF baseplate <input type="checkbox"/> √No visible gap at WIF/structural interface Install APFR [12,GG,F,6] in P6 WIF 10 <ul style="list-style-type: none"> <input type="checkbox"/> √Blk-Blk, pull/twist test <input type="checkbox"/> √WIF for any motion Translate to P6 (non-keel side IEA)

EVA 2 A/L EGRESS AND SETUP (00:50) (Cont)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
<p>2. Inform MCC-H EV crew ready for BGA 4A rotation</p>	<p>12. Inform IV when ready for BGA 4A rotation (EV on P6 IEA)</p> <p style="text-align: center;"><u>NOTE</u> Loop gap spanners around HR and hook back onto strap</p> <p>13. Retrieve ratchet wrench from C/L bag #3</p> <p>14. Retrieve gap spanner from C/L bag #3 and fully extend. Fairlead on APFR as reqd</p> <p>15. Install Gap Spanner across IEA, HR 5306-5353 (Route strap around inboard stanchion of HR 5353, and outboard stanchion of HR 5306) (Rotate buckle of gap spanner 180 deg to ensure proper tension)</p> <p>16. Check gloves and gauntlets</p>	<p>10. Inform IV when ready for BGA 4A rotation (EV on P6 IEA)</p> <p>11. Retrieve ratchet wrench from C/L bag #3</p> <p>12. Retrieve gap spanner from C/L bag #3 and fully extend</p> <p>13. Install Gap Spanner across IEA, HR 5304-5342 (Route strap around inboard stanchion of HR 5342, and around inboard stanchion of HR 5304) (Rotate buckle of gap spanner 180 deg to ensure proper tension)</p> <p>14. Check gloves and gauntlets</p>

EVA 2 BATTERY PREP (01:10)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)								
<p>View of P6 IEA (Non-Keel Side)</p> 	<div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;">CAUTION</p> <ul style="list-style-type: none"> • When breaking torque, release H1 before H2 (jacking bolt) • Do not exceed more turns on H2 than H1 • When re-torquing bolts, H2 must be tightened before H1 </div> <p><u>RELEASE TORQUE ON BATTERY BOLTS</u></p> <p>[EV1 Battery List (4): 2B1_1, 2B2_1, 2B2_2, 2B1_2]</p> <ol style="list-style-type: none"> 1. Break torque on H1 and H2: <ul style="list-style-type: none"> Ratchet wrench, ccw: <ol style="list-style-type: none"> a. Release torque on H1 bolt (expect ~31.7 ft-lb), 1 turn b. Release torque on H2 bolt (expect ~33.5 ft-lb), ½ turn 2. Re-torque H2 and H1: <ul style="list-style-type: none"> Ratchet wrench, cw (Set between 1 & 60 ft-lb): <ol style="list-style-type: none"> a. Tighten H2 bolt b. Tighten H1 bolt <table border="0" style="width: 100%; margin-top: 10px;"> <tr> <td style="width: 50%;">2B1_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5348)</td> <td style="width: 50%;">2B3_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5333)</td> </tr> <tr> <td style="padding-left: 40px;">Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1</td> <td style="padding-left: 40px;">Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1</td> </tr> <tr> <td>2B2_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5358)</td> <td>2B3_2: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5331)</td> </tr> <tr> <td style="padding-left: 40px;">Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1</td> <td style="padding-left: 40px;">Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1</td> </tr> </table>	2B1_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5348)	2B3_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5333)	Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1	Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1	2B2_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5358)	2B3_2: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5331)	Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1	Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1	<p><u>RELEASE TORQUE ON BATTERY BOLTS</u></p> <p>[EV3 Battery List (2): 2B3_1, 2B3_2]</p> <ol style="list-style-type: none"> 1. Break torque on H1 and H2 (assist EV1, as reqd): 2. Re-torque H2 and H1:
2B1_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5348)	2B3_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5333)									
Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1	Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1									
2B2_1: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5358)	2B3_2: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (use HR 5331)									
Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1	Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1									

EVA 2 BATTERY PREP (01:10) (Cont)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
<p>View of P6 IEA (Non-Keel Side)</p> <p>1. Inform MCC-H EV crew ready for BGA 2B rotation</p> <p><u>Crewlock Bag #3 Inventory</u></p> <ul style="list-style-type: none"> <input type="checkbox"/> Adj tether [to outside of bag] <input type="checkbox"/> Ratchet Wrench (int RET #1) <ul style="list-style-type: none"> <input type="checkbox"/> 7/16-2-in rigid ext <input type="checkbox"/> Ratchet Wrench (int RET #2) <ul style="list-style-type: none"> <input type="checkbox"/> 7/16-2-in rigid ext <input type="checkbox"/> RET (w/PIP pin) <ul style="list-style-type: none"> <input type="checkbox"/> 7/16-18-in ext <input type="checkbox"/> RET (sm-sm or int RET #3) <ul style="list-style-type: none"> <input type="checkbox"/> EVA Camera w/bracket <input type="checkbox"/> RET (w/PIP pin) (for 6-in wobble) 	<p>2B2_2: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (HR 5371) Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1</p> <p>2B1_2: Release <input type="checkbox"/> H1 <input type="checkbox"/> H2 (waist tether) Tighten <input type="checkbox"/> H2 <input type="checkbox"/> H1</p> <ol style="list-style-type: none"> 3. Stow ratchet in C/L bag #3 4. Reconfigure APFR [12,QQ,F,12] 5. Check gloves and gauntlets 6. Retrieve C/L bag #3 and stow on BRT 7. Inform IV when ready for BGA 2B rotation (EV clear of P6 IEA) 8. Translate to P5 HR 5202 and swap to A/L 85-ft ST <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked <input type="checkbox"/> <input checked="" type="checkbox"/> Reel unlocked 9. Attach safety tether to MWS 10. Temp stow C/L bag #3 inboard of UCCAS on P3 HR 3800 (Inboard Stanchion) 11. Attach safety tether to C/L bag #3 12. Translate to P3 Nadir UCCAS 	<ol style="list-style-type: none"> 3. Stow ratchet in C/L bag #3 4. Inventory C/L bag #3 5. Check gloves and gauntlets 6. Inform IV when ready for BGA 2B rotation (EV clear of P6 IEA) 7. Translate to P5 HR 5218 and swap to A/L 85-ft ST <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked <input type="checkbox"/> <input checked="" type="checkbox"/> Reel unlocked 8. Attach safety tether to MWS 9. Translate to C/L bag #3 at P3 HR 3800 10. Attach safety tether to C/L bag #3 11. Translate to P3 Nadir UCCAS

EVA 2 P3 NADIR UCCAS DEPLOY (01:15)

IV	EV1 – Swanson/EV3 – Acaba										
<p>1. Verify CP9 camera group aimed at UCCAS</p> <p>Deploy Clevis Bracket Bolts Released</p> <table border="1" data-bbox="111 435 516 505"> <thead> <tr> <th></th> <th>1</th> <th>2</th> <th>3</th> <th>4</th> </tr> </thead> <tbody> <tr> <td>Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		1	2	3	4	Bolt					<p><u>P3 Nadir UCCAS DEPLOY</u></p> <div data-bbox="716 326 1465 383" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Avoid inadvertent contact with grapple fixture shafts and target pins.</p> </div> <ul style="list-style-type: none"> <input type="checkbox"/> <u>Swivel Deploy Clevis Bracket/Release Pins</u> (EV1) <ol style="list-style-type: none"> 1. RET to Deploy Clevis Bracket 2. Swivel Deploy Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext 3. Temp stow Deploy Clevis Bracket <input type="checkbox"/> <u>Install Gap Spanner</u> (EV3) <ol style="list-style-type: none"> 4. Attach gap spanner to yoke 5. Attach Adj/Gap Spanner/Adj tether to hinge line HR 3851 <p style="margin-left: 40px;">NOTE: Route under braces and attach to outboard portion of yoke</p> <input type="checkbox"/> <u>Release Yoke ADP and PIP Pin</u> (EV1) <div data-bbox="770 732 1717 868" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION When attempting to remove the Yoke PIP pin and ADP, do not impart more than 10 lbf</p> <p>Yoke ADP does not have a stowage hole. Do not close ADP lock bracket when ADP is not inserted in a stowage/clevis hole</p> </div> <ol style="list-style-type: none"> 6. Release yoke PIP pin, secure using pre-installed wire tie → If unsuccessful, go to step 8, else skip 8 7. Release yoke ADP, secure using pre-installed wire tie → If unsuccessful, go to step 8, else skip 8 <input type="checkbox"/> <u>ADP/PIP Pin Contingency Removal</u> <ol style="list-style-type: none"> 8. Complete step 8 only if step 6 and/or 7 were no joy: <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Stow Clevis Bracket bolts (4) <p style="margin-left: 40px;">PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext, approx 4 turns each</p> <input type="checkbox"/> Re-attempt removal of yoke PIP pin and/or yoke ADP; secure using pre-installed wire tie <input type="checkbox"/> <u>Hinge Line Prep</u> (EV3) <ol style="list-style-type: none"> 9. Remove hinge line ADPs (2), insert in stowage hole (toward station forward), confirm ADP closed <ul style="list-style-type: none"> <input type="checkbox"/> Inboard <input type="checkbox"/> Outboard
	1	2	3	4							
Bolt											

EVA 2 P3 NADIR UCCAS DEPLOY (01:15) (Cont)

IV	EV1 – Swanson/EV3 – Acaba																									
<p>Stow Clevis Bracket Bolts Released</p> <table border="1"> <tr> <td></td> <td>5</td> <td>6</td> <td>7</td> <td>8</td> </tr> <tr> <td>Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </table> <p style="text-align: center;">**SYNC POINT**</p> <p style="text-align: center;">**SYNC POINT**</p> <p>Stow Clevis Bracket:</p> <table border="1"> <tr> <td>Bolt #</td> <td>5</td> <td>6</td> <td>7</td> <td>8</td> </tr> <tr> <td>Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>		5	6	7	8	Bolt					Bolt #	5	6	7	8	Torque					Turns					<p><input type="checkbox"/> <u>Reposition Braces</u> (EV3)</p> <ol style="list-style-type: none"> 10. Release SARJ Launch Bolt by hand, approx 3 turns ccw necessary If reqd, PGT [B6 24.0 ft-lb, CCW2 30 RPM, 30.5] 11. Release SARJ Brace (cup-cone bolt), stop on turns; 35 turns, do not exceed 37 <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B6 24.0 ft-lb, CCW3 60 RPM, 30.5]-7/16-6-in ext (use A7, CCW2 if desired to go to hardstop) 12. Attach SARJ Brace to Diagonal Strut, hand tighten SARJ Launch Bolt 1 turn cw 13. Release Diagonal Brace (cup-cone bolt), stop on turns; 35 turns, do not exceed 37 <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B6 24.0 ft-lb, CCW3 60 RPM, 30.5]-7/16-6-in ext (use A7, CCW2 if desired to go to hardstop) <div style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p>CAUTION Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <ol style="list-style-type: none"> 14. Guide Diagonal Brace and temp stow with tether to HR 3844 15. Swing yoke inside to provide room for removal of stow clevis bracket <p><input type="checkbox"/> <u>Swivel Stow Clevis Bracket</u> (EV1)</p> <ol style="list-style-type: none"> 16. RET to Stow Clevis Bracket 17. Swivel Stow Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext 18. Temp stow Stow Clevis Bracket <p><input type="checkbox"/> <u>Deploy UCCAS to Detent</u> (EV3)</p> <ol style="list-style-type: none"> 19. Deploy UCCAS to detent, Tend with Adj/Gap Spanner/Adj Lead with yoke (10 deg past vertical) 20. Reposition Adj/Gap Spanner/Adj, at hinge end to take up slack <hr style="border-top: 1px dashed red;"/> <p><input type="checkbox"/> <u>Reinstall Stow Clevis Bracket</u> (EV1)</p> <p>** THIS MUST BE DONE BEFORE UCCAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <ol style="list-style-type: none"> 21. Finger start Stow Clevis Bracket bolts (4), approx 1-2 turns 22. Engage Stow Clevis Bracket bolts (4) to hard stop, expect 10 turns <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext <p>← Report torque and turns</p> <ol style="list-style-type: none"> 23. Retrieve RET from bracket
		5	6	7	8																					
	Bolt																									
Bolt #	5	6	7	8																						
Torque																										
Turns																										

EVA 2 P3 NADIR UCCAS DEPLOY (01:15) (Cont)

IV	EV1 – Swanson/EV3 – Acaba																													
<p>Record Torque and Turns for the Brace Bolts:</p> <table border="1" data-bbox="184 545 518 659"> <thead> <tr> <th>Bolt</th> <th>Diagonal</th> <th>SARJ Brace</th> </tr> </thead> <tbody> <tr> <td>Torque</td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> </tr> </tbody> </table> <p>Record Torque and Turns of Deploy Clevis Brackets:</p> <table border="1" data-bbox="111 930 592 1044"> <thead> <tr> <th>Bolt #</th> <th>1</th> <th>2</th> <th>3</th> <th>4</th> </tr> </thead> <tbody> <tr> <td>Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Final Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Bolt	Diagonal	SARJ Brace	Torque			Turns			Bolt #	1	2	3	4	Initial Torque					Turns					Final Torque					<p><input type="checkbox"/> <u>Reposition Braces</u> (EV3)</p> <p>** THIS MUST BE DONE BEFORE UCCAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <p>24. Move Diagonal Brace into position for re-installation</p> <p>25. Engage Diagonal Brace (cup-cone bolt) to hard stop, approx 35 turns <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns</p> <p>26. Release SARJ Brace via SARJ Launch Bolt by hand, approx 1 turn ccw necessary</p> <p>27. Engage SARJ Brace (cup-cone bolt) to hard stop, approx 38 turns <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns</p> <p>28. Re-engage SARJ Launch Bolt for temp stow; hand tighten cw 2-3 turns</p> <p>29. Retrieve tether from brace temp stow location</p> <hr/> <p><input type="checkbox"/> <u>Re-install Deploy Clevis Bracket</u> (EV1)</p> <p>** THIS MUST BE DONE BEFORE UCCAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <p>30. Finger start Deploy Clevis Bracket bolts (4), approx 1-2 turns</p> <p>31. Engage Deploy Clevis Bracket bolts (4) to hard stop, expect 10 turns <input type="checkbox"/> PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns</p> <p>32. Apply Final Torque to Deploy Clevis Bracket bolts (4) in Ratchet Mode <input type="checkbox"/> PGT [RCW, 30.5]-7/16-6-in ext, two clicks each bolt</p> <p>33. Retrieve RET from bracket</p> <hr/> <p><input type="checkbox"/> <u>Move UCCAS From Detent to Final Deploy Position</u></p> <p>34. Move platform from detent into install position, tend with Adj/Gap Spanner/Adj</p> <p>35. Install yoke into Deploy Clevis Bracket <input type="checkbox"/> Release wire tie securing PIP pin and ADP to yoke</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION When attempting to install the Yoke PIP pin and ADP, do not impart more than 10 lbf</p> </div> <p><input type="checkbox"/> Install yoke ADP, √lock bracket engaged → If unsuccessful, go to step 36, else skip 36</p> <p><input type="checkbox"/> Install yoke PIP pin → If unsuccessful, go to step 36, else skip 36</p>
Bolt	Diagonal	SARJ Brace																												
Torque																														
Turns																														
Bolt #	1	2	3	4																										
Initial Torque																														
Turns																														
Final Torque																														

EVA 2 P3 NADIR UCCAS DEPLOY (01:15) (Cont)

IV	EV1 – Swanson/EV3 – Acaba												
<p>IV: Obtain GO from MCC-H for RTL checkout</p> <table border="1" data-bbox="111 544 499 657"> <tr> <td>RTL #</td> <td>1</td> <td>2</td> <td>3</td> </tr> <tr> <td>PIP Pin</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Test Complete</td> <td></td> <td></td> <td></td> </tr> </table> <p><u>EV1</u></p> <ul style="list-style-type: none"> <input type="checkbox"/> Small Trash Bag [right inside] <input type="checkbox"/> Adj tether <input type="checkbox"/> RET (sm-sm) [left] <input type="checkbox"/> RET(w/PIP pin) [right] <input type="checkbox"/> Swing Arm [right side] <ul style="list-style-type: none"> <input type="checkbox"/> PGT w/7/16-6-in ext <ul style="list-style-type: none"> <input type="checkbox"/> RET (sm-sm) <input type="checkbox"/> BRT [left side] <ul style="list-style-type: none"> <input type="checkbox"/> RET (sm-sm) <p><u>EV3</u></p> <ul style="list-style-type: none"> <input type="checkbox"/> Small Trash Bag [left inside] <ul style="list-style-type: none"> <input type="checkbox"/> Adj tether <ul style="list-style-type: none"> <input type="checkbox"/> Gap Spanner, 72-in <ul style="list-style-type: none"> <input type="checkbox"/> Adj tether <input type="checkbox"/> Small Trash Bag [right inside] <input type="checkbox"/> RET (sm-sm) [left] <input type="checkbox"/> RET(w/PIP pin) [right] <input type="checkbox"/> Swing Arm [right side] <ul style="list-style-type: none"> <input type="checkbox"/> PGT w/7/16-6-in ext <ul style="list-style-type: none"> <input type="checkbox"/> RET (sm-sm) <input type="checkbox"/> BRT [left side] <ul style="list-style-type: none"> <input type="checkbox"/> RET (sm-sm) <p>2. Inform MCC-H EV crew ready for Port SARJ rotation</p> 	RTL #	1	2	3	PIP Pin				Test Complete				<p><input type="checkbox"/> <u>ADP/PIP Pin Contingency Install</u></p> <p>36. Complete step 36 only if step 35 was no joy:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Deploy Clevis Bracket bolts (4), approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCW, 30.5]-7/16-6-in ext <input type="checkbox"/> Re-attempt ADP installation <input type="checkbox"/> Re-attempt PIP pin installation <input type="checkbox"/> Engage Deploy Clevis Bracket bolts (4) to hard stop, approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require RAD (attempt w/fingers first) PGT [A7 9.2 ft-lb, CW2 30 RPM, 30.5]-RAD w/7/16-2-in ext (count turns at bolt head) <input type="checkbox"/> Remaining bolts, PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext <input type="checkbox"/> Apply Final Torque <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCW, 30.5]-7/16-6-in ext <p><input type="checkbox"/> <u>Clean Up/Prep UCCAS</u></p> <p>37. Translate under UCCAS UMA</p> <p>38. Tether to hitch pin from EVA OVERRIDE anti-rotation cap, remove hitch pin</p> <p>39. <input type="checkbox"/> Remove anti-rotation cap and stow in trash bag</p> <p>40. Translate to each Guide Vane (3) and perform:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Remove launch restraint PIP pin from guide vane; stow in trash bag <input type="checkbox"/> On MCC-H GO, depress and hold RTL lever for 15 sec, then release <input type="checkbox"/> Verify with MCC-H good checkout, move to next guide vane <p>41. Release Adj/Gap Spanner/Adj fully extend and stow in trash bag</p> <p>42. Translate to EBCS Target and perform:</p> <div data-bbox="772 1073 1572 1143" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION EBCS target has finished surface that is susceptible to damage by contact</p> </div> <ul style="list-style-type: none"> <input type="checkbox"/> Verify both EV crewmembers are clear of target area <input type="checkbox"/> Remove target cover, stow on backside of target assembly <p>43. Glove check</p> <p>44. Perform tool inventory</p> <p>45. Inform IV when ready for port SARJ rotation (Crew, tools, and tethers clear of SARJ and braces installed)</p> <p>46. EV3 – Translate to P1/P3 location for FLUID JUMPER INSTALL EV1 – Translate to P1 RBVM MLI REPAIR location</p>
RTL #	1	2	3										
PIP Pin													
Test Complete													

EVA 2 P1 RBVM MLI REPAIR, P1/P3 FLUID JUMPER INSTALL, AND FHRC P-CLAMP RELEASE (01:05)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
<div data-bbox="121 597 688 743" style="border: 1px solid black; background-color: #e0ffe0; padding: 5px;"> <p>DEMATE QD</p> <ol style="list-style-type: none"> √Forward white band visible, button up Demate QD (pull back on release ring) </div> <div data-bbox="121 743 688 1057" style="border: 1px solid black; background-color: #e0ffff; padding: 5px;"> <p>MATE QD</p> <ol style="list-style-type: none"> Inspect QDs for FOD or damage √Detent button is up √Forward white band is NOT visible Assess side loads Mate QD. √Forward white band is visible Perform snap back test (√Fwd white band is visible) Perform pull test Perform gap check (visual) </div> <ol style="list-style-type: none"> Request EV3 to perform survey of jumper connections <div data-bbox="121 1154 688 1321" style="border: 1px solid black; background-color: #ffe0ff; padding: 5px;"> <p>OPEN VALVE</p> <ol style="list-style-type: none"> Press button, move bail forward (open valve) √Aft white band visible, button up Verify detent button can be depressed </div>	<p><u>P1 RBVM MLI REPAIR (00:15)</u></p> <div data-bbox="793 345 1331 537" style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">CAUTION</p> <p>Do not impart loads into radiator beam when greater than 130 inches from TRRJ center (outboard edge of the outboard trunnion scuff plate). If inadvertent kick load is applied anywhere along the radiator beam, wait 2 min to allow the response to dissipate</p> </div> <ol style="list-style-type: none"> Translate to P1 outboard Translate to P1 outboard RBVM; go zenith at Bay 18 (Y₀ 9795) BRT to P3 HR 3804 or 3805 Reinstall FQD MLI on M1/F151 Install wire tie around FQD MLI Perform WVS survey of RBVM Check gloves and gauntlets If Crewlock Bag #3 is by fluid jumper, retrieve and place on BRT Translate to P1 FHRC for P-Clamp Release if PET < 04:30 	<p><u>P1/P3 FLUID JUMPER INSTALL (00:30)</u></p> <ol style="list-style-type: none"> Translate to P1/P3 Face 6 (nadir) interface Open shroud on P1 nadir umbilical tray <div data-bbox="1430 391 1967 521" style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">CAUTION</p> <p>QDs exposed to direct sunlight can overtemp in 20 min. Shading by EMU or thermal shroud can lengthen acceptable time with bootie removed</p> </div> <ol style="list-style-type: none"> For QD F187, perform DEMATE QD steps (F187 is on M1 panel A504) BRT to HR 3688 Open thermal bootie and remove QD cap from M3 on P1 panel A503. Stow cap in trash bag BRT to HR 3810 Open thermal bootie and remove QD cap from M1 on P3 panel A501. Stow cap in trash bag Open TA clamp BRT to HR 3688 RET to jumper For QDs F186, perform DEMATE QD steps (F186 is on M2 panel A503) Perform MATE QD steps to mate QD F186 to M3 on P1 panel A503 For QD F186, perform OPEN VALVE steps Reinstall thermal bootie BRT to HR 3810 Perform MATE QD steps to mate QD F187 to M1 on P3 panel A501 For QD F187, perform OPEN VALVE steps Reinstall thermal bootie Close TA clamps, as reqd Perform WVS survey of jumper connections Replace P1 nadir umbilical tray shroud Check gloves and gauntlets Retrieve C/L bag #3, if reqd Translate to P1 for FHRC P-Clamp Release if PET < 04:30

EVA 2 P1 RBVM MLI REPAIR, P1/P3 FLUID JUMPER INSTALL, AND FHRC P-CLAMP RELEASE (01:05) (Cont)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)																																																																
<p>P1 FHRC P-Clamps:</p> <table border="1" data-bbox="157 332 630 600"> <thead> <tr> <th colspan="4">Hose Box</th> </tr> <tr> <th>√</th> <th>P-Clamp</th> <th>Tool</th> <th>Socket</th> </tr> </thead> <tbody> <tr><td></td><td>1</td><td>PGT</td><td>6-in ext</td></tr> <tr><td></td><td>2</td><td>PGT</td><td>6-in ext</td></tr> <tr><td></td><td>3</td><td>Ratchet</td><td>2-in ext</td></tr> <tr><td></td><td>4</td><td>PGT</td><td>6-in ext</td></tr> <tr><td></td><td>5</td><td>PGT</td><td>6-in ext</td></tr> <tr><td></td><td>6</td><td>Ratchet</td><td>2-in ext</td></tr> </tbody> </table> <table border="1" data-bbox="147 633 661 933"> <thead> <tr> <th colspan="4">Stinger</th> </tr> <tr> <th>√</th> <th>P-Clamp</th> <th>Tool</th> <th>Socket</th> </tr> </thead> <tbody> <tr><td></td><td>1</td><td>PGT</td><td>6 or 18-in ext</td></tr> <tr><td></td><td>2</td><td>PGT</td><td>6 or 18-in ext</td></tr> <tr><td></td><td>3</td><td>PGT</td><td>6 or 18-in ext</td></tr> <tr><td></td><td>4</td><td>PGT</td><td>6 or 18-in ext</td></tr> <tr><td></td><td>*5</td><td>PGT</td><td>18-in ext</td></tr> <tr><td></td><td>^6</td><td>PGT</td><td>6 or 18-in ext</td></tr> </tbody> </table> <p>*18-in required for this bolt ^18-in ext doable w/difficulty</p> <ul style="list-style-type: none"> <input type="checkbox"/> Crewlock Bag #3 <ul style="list-style-type: none"> <input type="checkbox"/> Adj tether [to outside of bag] <input type="checkbox"/> EV1 spare 85-ft ST [outside TPs] <input type="checkbox"/> EV3 spare 85-ft ST [outside TPs] <input type="checkbox"/> Ratchet Wrench (int RET #1) <ul style="list-style-type: none"> <input type="checkbox"/> 7/16-2-in rigid ext <input type="checkbox"/> Ratchet Wrench (int RET #2) <ul style="list-style-type: none"> <input type="checkbox"/> 7/16-2-in rigid ext <input type="checkbox"/> RET (w/PIP pin) <ul style="list-style-type: none"> <input type="checkbox"/> 7/16-18-in ext <input type="checkbox"/> RET (sm-sm or int RET #3) <ul style="list-style-type: none"> <input type="checkbox"/> EVA Camera w/bracket <input type="checkbox"/> RET (w/PIP pin) (for 6-in wobble) <p>1. Check with MCC-H: S1 TRRJ locked</p>	Hose Box				√	P-Clamp	Tool	Socket		1	PGT	6-in ext		2	PGT	6-in ext		3	Ratchet	2-in ext		4	PGT	6-in ext		5	PGT	6-in ext		6	Ratchet	2-in ext	Stinger				√	P-Clamp	Tool	Socket		1	PGT	6 or 18-in ext		2	PGT	6 or 18-in ext		3	PGT	6 or 18-in ext		4	PGT	6 or 18-in ext		*5	PGT	18-in ext		^6	PGT	6 or 18-in ext	<p><u>RELEASE FHRC P-CLAMPS</u> (00:50) Hose Box (Outboard)</p> <ol style="list-style-type: none"> Temp stow C/L Bag #3 on Nadir FHRC HR, if reqd Retrieve ratchet wrench from C/L bag PGT [A7 9.2 ft-lb, CCW2 30 rpm, 30.5]-7/16-6-in ext: Release Hose Box P-clamps (6). Start at end furthest from QD, ~7-12.5 turns Check gloves and gauntlets <p><u>PORT SIDE CLEANUP</u></p> <ol style="list-style-type: none"> Stow ratchet wrench in C/L bag Retrieve Crewlock Bag #3 and attach to BRT Perform tool inventory Translate P1 HR 3652 <ol style="list-style-type: none"> Prepare Safety Tether for S3 PAS deploy <ul style="list-style-type: none"> <input type="checkbox"/> On EV3 GO: Connect EV1 Waist Tether to EV3 Safety Tether (while EV3 safety tether anchor remains on HR) <input type="checkbox"/> On EV3 GO: Release EV3 Safety Tether from P1 HR (3651) <ul style="list-style-type: none"> <input type="checkbox"/> <input type="checkbox"/> √Gate closed (both hooks) <input type="checkbox"/> <input type="checkbox"/> √Hook locked (both hooks) <input type="checkbox"/> Release EV1 Safety Tether from P1 HR (3652) <p>10. On IV GO: Translate to S1 HR (3214)</p>	<p><u>RELEASE FHRC P-CLAMPS</u> (00:35) Stinger/Torque Box (Inboard)</p> <ol style="list-style-type: none"> Temp stow C/L bag #3 on Nadir FHRC HR, if reqd Retrieve PGT and install 18-in ext from crewlock bag PGT [A7 9.2 ft-lb, CCW2 30 rpm, 30.5]-7/16-18-in ext: Release Torque Box P-clamps (6), ~7-12.5 turns Stow 7/16-18-in ext in Crewlock Bag Install 6-in extension on PGT Check gloves and gauntlets <p><u>PORT SIDE CLEANUP</u></p> <ol style="list-style-type: none"> Translate to Airlock Complete safety tether re-config at A/L <ul style="list-style-type: none"> <input type="checkbox"/> Connect EV3 waist tether to A/L D-ring ext <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked Give EV1 GO to attach Waist Tether to EV3 Safety Tether Give GO to EV1 to release EV3 safety tether anchor
Hose Box																																																																		
√	P-Clamp	Tool	Socket																																																															
	1	PGT	6-in ext																																																															
	2	PGT	6-in ext																																																															
	3	Ratchet	2-in ext																																																															
	4	PGT	6-in ext																																																															
	5	PGT	6-in ext																																																															
	6	Ratchet	2-in ext																																																															
Stinger																																																																		
√	P-Clamp	Tool	Socket																																																															
	1	PGT	6 or 18-in ext																																																															
	2	PGT	6 or 18-in ext																																																															
	3	PGT	6 or 18-in ext																																																															
	4	PGT	6 or 18-in ext																																																															
	*5	PGT	18-in ext																																																															
	^6	PGT	6 or 18-in ext																																																															

EVA 2 P1 RBVM MLI REPAIR, P1/P3 FLUID JUMPER INSTALL, AND FHRC P-CLAMP RELEASE (01:05) (Cont)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
	<p>11. Set safety tether anchor (for both EV1/2):</p> <ul style="list-style-type: none"> <input type="checkbox"/> Attach EV1 safety tether anchor to S1 HR (3214) <input checked="" type="checkbox"/> Gate closed <input checked="" type="checkbox"/> Hook locked <input checked="" type="checkbox"/> Reel unlocked <input type="checkbox"/> Attach EV3 safety tether anchor to S1 HR (3215) <input checked="" type="checkbox"/> Gate closed <input checked="" type="checkbox"/> Hook locked <p>12. Release EV1 waist tether from EV3 safety tether</p> <p>13. Give EV3 GO to release EV3 waist tether from A/L D-ring</p>	<p>11. <input checked="" type="checkbox"/> Reel Unlocked</p> <p>12. On EV1 GO, release waist tether from A/L D-ring</p> <p>13. Close hatch thermal cover</p>
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> <p>WARNING 2-ft Keep-Out Zone for floating cables between MT and MBS. Stay on UMA handrails during translation underneath MT</p> </div>		
	<p>14. Translate to S3 Outboard Zenith PAS</p> <p>15. Temp stow C/L bag on S3 HR 3056</p>	<p>14. Translate to S3 Outboard Zenith PAS</p>

EVA 2 P1 FHRC P-CLAMP RELEASE – TASK DATA

FHRC P-Clamps – Hose Box (Outboard)

Aft

Zenith

Nadir

TA

TA

1

2

3

4

5

6

QD: M3/F169

QD: M4/F168

Fwd

QD: M5/F167

QD: M6/F166

Hose Box		
P-Clamp	Tool	Socket
1	PGT	6-in ext
2	PGT	6-in ext
3	Ratchet	2-in ext
4	PGT	6-in ext
5	PGT	6-in ext
6	Ratchet	2-in ext

○ = P-Clamp Location

⊗ = TA Clamp (not released)

FHRC P-Clamps – Stinger (Inboard)

Port

Zenith

Nadir

1

2

3

4

5

6

QD: M1/F165

QD: M2/F164

Stbd

Torque Box Assy

Stinger		
P-Clamp	Tool	Socket
1	PGT	6 or 18-in ext
2	PGT	6 or 18-in ext
3	PGT	6 or 18-in ext
4	PGT	6 or 18-in ext
*5	PGT	18-in ext
^6	PGT	6 or 18-in ext

○ = P-Clamp Location

⊗ = P-Clamp (not released)

*18-in required for this bolt
^18-in ext doable w/difficulty

EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY (01:00)

IV	EV1/2										
1. Verify S3/S4 SARJ locked with MCC-H 2. Verify SSRMS Camera aimed at PAS Deploy Clevis Bracket Bolts Released <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="width: 20px;">1</th> <th style="width: 20px;">2</th> <th style="width: 20px;">3</th> <th style="width: 20px;">4</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		1	2	3	4	Bolt					On IV GO: <u>S3 PAS DEPLOY – OUTBOARD ZENITH</u> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Avoid inadvertent contact with grapple fixture shafts and target pins.</p> </div> <ul style="list-style-type: none"> <input type="checkbox"/> <u>Swivel Deploy Clevis Bracket/Release Pins</u> (EV1) <ol style="list-style-type: none"> 1. RET to Deploy Clevis Bracket 2. Swivel Deploy Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext 3. Temp stow Deploy Clevis Bracket with RET on HR 3056 <input type="checkbox"/> <u>Install Gap Spanner</u> (EV3) <ol style="list-style-type: none"> 4. Attach gap spanner to yoke 5. Attach Adj/Gap Spanner/Adj tether to hinge line HR 3047 <p style="margin-left: 20px;">NOTE: Route under braces and attach to outboard portion of yoke</p> <input type="checkbox"/> <u>Release Yoke ADP and PIP Pin</u> (EV1) <div style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p>CAUTION When attempting to remove the Yoke PIP pin and ADP, do not impart more than 10 lbf Yoke ADP does not have a stowage hole. Do not close ADP lock bracket when ADP is not inserted in a stowage/clevis hole</p> </div> <ol style="list-style-type: none"> 6. Release yoke PIP pin, secure using pre-installed wire tie → If unsuccessful go to step 8, else skip 8 7. Release yoke ADP, secure using pre-installed wire tie → If unsuccessful go to step 8, else skip 8 <input type="checkbox"/> <u>ADP/PIP Pin Contingency Removal</u> <ol style="list-style-type: none"> 8. Complete step 8 only if step 6 and/or 7 were no joy: <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Stow Clevis Bracket bolts (4) PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext, approx 4 turns each <input type="checkbox"/> Re-attempt removal of yoke PIP pin and/or yoke ADP, secure using pre-installed wire tie <input type="checkbox"/> <u>Hinge Line Prep</u> (EV3) <ol style="list-style-type: none"> 9. Remove hinge line ADPs (2), insert in stowage hole (toward station forward), confirm ADP closed <ul style="list-style-type: none"> <input type="checkbox"/> Inboard <input type="checkbox"/> Outboard
	1	2	3	4							
Bolt											

EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY (01:00) (Cont)

IV	EV1/2																									
<p>Stow Clevis Bracket Bolts Released</p> <table border="1"> <tr> <td></td> <td>5</td> <td>6</td> <td>7</td> <td>8</td> </tr> <tr> <td>Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </table> <p style="text-align: center;">**SYNC POINT**</p> <p style="text-align: center;">**SYNC POINT**</p> <p>Record Torque and Turns of Stow Clevis Brackets:</p> <table border="1"> <tr> <td>Bolt #</td> <td>5</td> <td>6</td> <td>7</td> <td>8</td> </tr> <tr> <td>Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>		5	6	7	8	Bolt					Bolt #	5	6	7	8	Initial Torque					Turns					<p><input type="checkbox"/> <u>Reposition Braces</u> (EV3)</p> <ol style="list-style-type: none"> 10. Release SARJ Launch Bolt by hand, approx 3 turns ccw necessary If reqd, PGT [B6 24.0 ft-lb, CCW2 30 RPM, 30.5] 11. Release SARJ Brace (cup-cone bolt), stop on turns; 35 turns, do not exceed 37 turns <input type="checkbox"/> PGT [B6 24.0 ft-lb, CCW3 60 RPM, 30.5]-7/16-6-in ext (use A7, CCW2 if desired to go to hardstop) 12. Attach SARJ Brace to Diagonal Strut, hand tighten SARJ Launch Bolt 1 turn cw 13. Release Diagonal Brace (cup-cone bolt), stop on turns; 35 turns, do not exceed 37 turns <input type="checkbox"/> PGT [B6 24.0 ft-lb, CCW3 60 RPM, 30.5]-7/16-6-in ext (use A7, CCW2 if desired to go to hardstop) <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <ol style="list-style-type: none"> 14. Guide Diagonal Brace and temp stow with tether to HR 3040 15. Swing yoke inside to provide room for removal of stow clevis bracket <p><input type="checkbox"/> <u>Swivel Stow Clevis Bracket</u> (EV1)</p> <ol style="list-style-type: none"> 16. RET to Stow Clevis Bracket 17. Swivel Stow Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns <input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext 18. Temp stow Stow Clevis Bracket <p><input type="checkbox"/> <u>Deploy PAS to Detent</u> (EV3)</p> <ol style="list-style-type: none"> 19. Deploy PAS to detent, tend with Adj/Gap Spanner/Adj, lead with yoke – (10 deg past vertical) 20. Reposition Adj/Gap Spanner/Adj at hinge end to take up slack to on HR 3053 <hr style="border-top: 2px dashed red;"/> <p><input type="checkbox"/> <u>Reinstall Stow Clevis Bracket</u> (EV1)</p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <ol style="list-style-type: none"> 21. Finger start Stow Clevis Bracket bolts (4), approx 1-2 turns 22. Engage Stow Clevis Bracket bolts (4) to hard stop, expect 10 turns <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns 23. Retrieve RET from bracket
		5	6	7	8																					
	Bolt																									
Bolt #	5	6	7	8																						
Initial Torque																										
Turns																										

EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY (01:00) (Cont)

IV	EV1/2																																
<p>Record Torque and Turns for the Brace Bolts:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 25%;">Bolt</th> <th style="width: 25%;">SARJ Brace</th> <th style="width: 25%;">Diagonal</th> <th style="width: 25%;"></th> </tr> </thead> <tbody> <tr> <td>Torque</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> </tr> </tbody> </table> <p>Record Torque and Turns of Deploy Clevis Brackets:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 12.5%;">Bolt #</th> <th style="width: 12.5%;">1</th> <th style="width: 12.5%;">2</th> <th style="width: 12.5%;">3</th> <th style="width: 12.5%;">4</th> </tr> </thead> <tbody> <tr> <td>Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Final Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Bolt	SARJ Brace	Diagonal		Torque				Turns				Bolt #	1	2	3	4	Initial Torque					Turns					Final Torque					<p><input type="checkbox"/> <u>Reposition Braces</u> (EV3)</p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <p>24. Move Diagonal Brace into position for re-installation 25. Engage Diagonal Brace (cup-cone bolt) to hard stop, approx 35 turns <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns 26. Release SARJ Brace via SARJ Launch Bolt by hand, approx 1 turn ccw necessary 27. Engage SARJ Brace (Cup-Cone bolt) to hard stop, approx 38 turns <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns 28. <input type="checkbox"/> Re-engage SARJ Launch Bolt bolt for temp stow; hand tighten cw 2-3 turns 29. Retrieve tether from brace temp stow location</p> <hr/> <p><input type="checkbox"/> <u>Re-Install Deploy Clevis Bracket</u> (EV1)</p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <p>30. Finger start Deploy Clevis Bracket bolts (4), approx 1-2 turns 31. Engage Deploy Clevis Bracket bolts (4) to hard stop, expect 10 turns <input type="checkbox"/> PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns 32. Apply final Torque to Deploy Clevis Bracket bolts (4) in Ratchet Mode ← <input type="checkbox"/> PGT [RCW, 30.5]-7/16-6-in ext, two clicks each bolt 33. Retrieve RET from bracket</p> <hr/> <p><input type="checkbox"/> <u>Move PAS from Detent to Final Deploy Position</u></p> <p>34. Disconnect Gap Spanner and Move platform from detent into install position, tend with Adj/Gap Spanner/Adj 35. Install yoke into Deploy Clevis Bracket <input type="checkbox"/> Release wire tie securing PIP pin and ADP to yoke</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION When attempting to install the Yoke PIP pin and ADP, do not impart more than 10 lbf</p> </div> <p><input type="checkbox"/> Install yoke ADP, √lock bracket engaged → If unsuccessful go to step 36, else skip 36 <input type="checkbox"/> Install yoke PIP Pin → If unsuccessful go to step 36, else skip 36</p>
Bolt	SARJ Brace	Diagonal																															
Torque																																	
Turns																																	
Bolt #	1	2	3	4																													
Initial Torque																																	
Turns																																	
Final Torque																																	


EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY (01:00) (Cont)

IV	EV1/2												
<p>IV: Obtain GO from MCC-H for RTL Checkout</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">RTL #</th> <th style="text-align: center;">1</th> <th style="text-align: center;">2</th> <th style="text-align: center;">3</th> </tr> </thead> <tbody> <tr> <td>PIP Pin</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Test Complete</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	RTL #	1	2	3	PIP Pin				Test Complete				<p><input type="checkbox"/> ADP/PIP Pin Contingency Install</p> <p>36. Complete step 36 only if step 35 was no joy:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Deploy Clevis Bracket bolts (4), approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCCW, 30.5]-7/16-6-in ext <input type="checkbox"/> Re-attempt ADP Installation <input type="checkbox"/> Re-attempt PIP pin Installation <input type="checkbox"/> Engage Deploy Clevis Bracket bolts (4) to hard stop, approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require RAD (attempt w/fingers first) PGT [A7 9.2 ft-lb, CW2 30 RPM, 30.5]-RAD w/7/16-2-in ext (count turns at bolt head) <input type="checkbox"/> Remaining bolts, PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext <input type="checkbox"/> Apply final Torque <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCW, 30.5]-7/16-6-in ext <p><input type="checkbox"/> Clean Up/Prep PAS</p> <p>37. Release Adj/Gap Spanner/Adj</p> <p>38. Extend Gap Spanner to full length and stow with Adj in trash bag</p> <p>39. Translate under PAS UMA</p> <p>40. Tether to hitch pin from EVA OVERRIDE anti-rotation cap, remove hitch pin</p> <p>41. <input type="checkbox"/> Remove anti-rotation cap and stow in trash bag</p> <p>42. Translate to each Guide Vane (3) and perform:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Remove launch restraint PIP pin from guide vane, stow in trash bag <input type="checkbox"/> On MCC-H GO, depress and hold RTL lever for 15 sec, then release <input type="checkbox"/> Verify with MCC-H good checkout, move to next guide vane <p>43. Translate to EBCS Target and perform:</p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">CAUTION EBCS target has finished surface that is susceptible to damage by contact</p> </div> <ul style="list-style-type: none"> <input type="checkbox"/> Verify both EV crew are clear of target area <input type="checkbox"/> Remove target cover, stow on backside of target assembly <p>44. Check gloves and gauntlets</p>
RTL #	1	2	3										
PIP Pin													
Test Complete													

EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY (01:00) (Cont)

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
	<p><u>TETHER RECONFIG</u></p> <ol style="list-style-type: none"> 1. Place C/L bag #3 on BRT 2. Translate to S1 Safety Tether Anchor 3. Prepare Safety Tether for return to A/L <ul style="list-style-type: none"> <input type="checkbox"/> On EV3 GO: Connect EV1 Waist Tether to EV3 Safety Tether (while EV3 safety tether anchor remains on HR) <input type="checkbox"/> On EV3 GO: Release EV3 Safety Tether from S1 HR (3215) <input type="checkbox"/> <input type="checkbox"/> √Gate closed (both hooks) <input type="checkbox"/> <input type="checkbox"/> √Hook locked (both hooks) <input type="checkbox"/> Release EV1 Safety Tether from S1 HR (3214) 4. Translate to A/L 5. Hand C/L bag #3 to EV3 6. Anchor EV1 Safety Tether to fwd A/L D-ring <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked 7. Anchor EV3 Safety Tether to aft A/L D-ring <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked 8. Give EV3 GO to release waist tether 	<p><u>TETHER RECONFIG</u></p> <ol style="list-style-type: none"> 1. Translate to A/L 2. Complete safety tether re-config to A/L <ul style="list-style-type: none"> <input type="checkbox"/> Connect EV3 waist tether to A/L D-ring ext <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked 3. Give EV1 GO to attach Waist Tether to EV3 Safety Tether 4. Give GO to EV1 to release EV3 safety tether anchor 5. Receive C/L bag #3 from EV1 and stow C/L bag #3 in A/L 6. <input type="checkbox"/> √Reel unlocked 7. On EV1 GO: Disconnect waist tether from A/L D-ring ext 8. Close A/L thermal cover

EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY – TASK DATA



EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY – TASK DATA (Cont)



HINGE LINE ADP ORIENTATION

EVA 2 S3 OUTBOARD ZENITH PAS DEPLOY – TASK DATA (Cont)

Estimated Task Duration:

	Without SSRMS
One EV Crew	N/A
Two EV Crew	01:00

Tools:

EV1	EV3
PGT	PGT
7/16-6-in socket ext	7/16-6-in socket ext
	Adj – 45-72-in Gap Spanner (Large) – Adj

EVA Fasteners:

Fastener Name	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns
SARJ Brace Launch Lock Bolt	7/16	1	16.0	21.5	32.3	9-13.5
SARJ Brace cup/cone Bolt	7/16	1	16.0	28.8	14.0 and 31.6	37-40
Diagonal cup/cone bolt	7/16	1	16.0	22.7	14.0 and 31.6	37-40
Stowage Clevis	7/16	4	16.0	25.5	46.7	9-16.5
Deploy Clevis	7/16	4	30.5	25.5	106.6	7-10.5

Inhibits:

Inhibit
S3/S4 SARJ Locked

Foot Restraints (Contingency Yoke Alignment):

Task	WIF	APFR Setting
Zenith/Outboard PAS	S3-11	5, PP, G, 12
Zenith/Inboard PAS	S3-15	3, RR, F, 10
Nadir/Outboard PAS	S3-17	3, PP, F, 12
Nadir/Inboard PAS	S3-25	11, PP, F, 12
Nadir UCCAS	P3-11	3, PP, H, 12

Notes:

1. UMA EVA Override anti-rotation cap must be removed prior to first use of UMA on PAS
2. EBCS target cover must be removed prior to cargo attachment to PAS. Protects target from MMOD and inadvertent contact. Remove as last activity
3. RAD may be needed for re-install of deployed clevis bracket. It will likely exceed RAD limits and need to be returned for refurb

Cautions:

1. Do not lift diagonal brace greater than 7 deg out of rotation plane when rotating to temp stowage location so as to not bend hinge end
2. Do not close ADP lock bracket when ADP is not inserted in a stowage/clevis hole. The pin can fall apart
3. EBCS target has finished surface that is susceptible to damage by contact

Warnings:

EVA 2 TOOL STANCHION RELOCATE/APFR RETRIEVE

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
	<p><u>RELOCATE TOOL STANCHION</u></p> <ol style="list-style-type: none"> 1. Translate to Z1 WIF 8 2. Retrieve Tool Stanchion, place on BRT 3. Translate to LAB WIF 4 4. Reconfigure APFR to [1,MM,C,11] 5. Rotate TS collar to nadir 6. Install Tool Stanchion on APFR with tool head fwd, then pitch TS toward Lab 7. Adjust TCV to begin cold soak, as reqd 8. Translate to A/L 	<p><u>RETRIEVE APFR</u></p> <ol style="list-style-type: none"> 1. Translate to Z1 WIF 8 2. Retrieve APFR, place on BRT 3. Adjust TCV to begin cold soak, as reqd 4. Translate to A/L 5. Open A/L thermal cover 6. Stow APFR in A/L

EVA 2 CLEANUP/INGRESS

IV	EV1 – Swanson (FF)	EV3 – Acaba (FF)
<p>Prior to Ingress: 1. Perform WVS PWRDN (PHOTO/TV, <u>WVS CUE CARD</u>)</p>	<p><u>INGRESS</u></p> <ol style="list-style-type: none"> Prepare Safety Tether for ingress <ul style="list-style-type: none"> <input type="checkbox"/> On EV3 GO: Connect EV1 Waist Tether to EV3 Safety Tether (while EV3 safety tether anchor remains achored) <input type="checkbox"/> On EV3 GO: Release EV3 Safety Tether from aft A/L D-ring <input type="checkbox"/> <input type="checkbox"/> √Gate Closed (both hooks) <input type="checkbox"/> <input type="checkbox"/> √Hook Locked (both hooks) <input type="checkbox"/> Release EV1 Safety Tether from fwd A/L D-ring Ingress A/L Remove SCU from stowage pouch Remove DCM cover; Velcro to DCM Connect SCU to DCM; √SCU Locked WATER – OFF (fwd), expect H2O IS OFF msg Close thermal cover; attach Velcro strap <div data-bbox="919 911 1493 992" style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px auto; width: fit-content;"> <p>CAUTION Do not close hatch until EMU Water OFF for 2 min. Verify outer hatch clear of hardware</p> </div> <ol style="list-style-type: none"> √EV hatch clear of FOD and obstructions Verify EV hatch handle position per hatch decal; close and lock <p>Go to PRE-REPRESS (<u>DEPRESS/REPRESS</u> Cue Card)</p>	<p><u>INGRESS</u></p> <ol style="list-style-type: none"> Complete safety tether re-config for ingress <ul style="list-style-type: none"> <input type="checkbox"/> Connect EV3 waist tether to A/L D-ring ext <input type="checkbox"/> √Gate Closed <input type="checkbox"/> √Hook Locked Give EV1 GO to attach Waist Tether to EV3 Safety Tether Give GO to EV1 to release EV3 safety tether anchor Ingress A/L Remove SCU from stowage pouch Remove DCM cover; Velcro to DCM Connect SCU to DCM; √SCU Locked WATER – OFF (fwd), expect H2O IS OFF msg <p>Go to PRE-REPRESS (<u>DEPRESS/REPRESS</u> Cue Card)</p>

NOTES

NOTES

EVA 3 SUMMARY TIMELINE

PET HR : MIN	IV/SSRMS	EV2 – Arnold	EV3 – Acaba	PET HR : MIN
00:00		EVA 3 POST DEPRESS, EGRESS & SETUP (00:50) <ul style="list-style-type: none"> Post Depress/Egress (00:25) Setup (00:20) Egress w/Med ORU Bag [Crewlock Bags (2) inside] 	EVA 3 POST EGRESS & SETUP (00:50) <ul style="list-style-type: none"> Post Depress/Egress (00:25) Setup (00:20) Egress w/APFR, Crewlock Bag, WIF adapter 	00:00
01:00	EV3 – Acaba (SSRMS) for CETA Cart Ops	CETA CART RELOCATION (01:00) <ul style="list-style-type: none"> CETA Cart (01:00) 	CETA CART RELOCATION (01:00) <ul style="list-style-type: none"> CETA Cart (01:00) 	01:00
02:00		SPDM COVERS (01:30) <ul style="list-style-type: none"> OTCM Cover Reconfiguration (00:30) EP1 Cover Removal (00:40) SPDM Cover Cleanup (00:20) 	S1 TASKS (02:10) <ul style="list-style-type: none"> S1/S3 SSAS BBC PNL RECONFIG (00:30) S3 FLUID QD JUMPER INSTALL (00:35) S1 FHRC P CLAMP RELEASE (01:05) <ul style="list-style-type: none"> Torque Box (00:30) Hose Box [Stinger] (00:25) FHRC Cleanup (00:10) 	02:00
03:00	EV2 – Arnold (SSRMS) for SPDM & LEE B Lube (EV2 egresses SSRMS prior to LEE REPAIR)			03:00
		LEE B REPAIR (01:45) <ul style="list-style-type: none"> LEE B Snare Repair (01:15) 		
04:00			S0 1A D RPCM R&R (00:45)	04:00
		<ul style="list-style-type: none"> LEE B Cleanup (00:30) 		
05:00		CLEANUP AND INGRESS (00:50)	P1 1A A RPCM R&R (00:45)	05:00
			CLEANUP AND INGRESS (00:25)	
06:00	EVA 3 PET = 06:00 hr	PRE-REPRESS (00:05)	PRE-REPRESS (00:05)	06:00
-06:30				-06:30

EVA 3

EVA 3 SUMMARY TIMELINE (Cont)

EVA 3 Constraints and Bingo Times Summary

1. Powerdown required to put inhibits in place for S0-1A_D and P1-1A_A RPCM R&Rs will take approximately 15-20 min of ground commanding to execute; thus, **MCC-H** will begin powerdown operations when EV3/Acaba completes the S1 tasks and starts translation to the RPCM R&R location.
2. The maximum amount of time that the powerdown can be in place is 3:00 hr due to thermal constraints on S-Band ORUs. Thus, the DDCU that provides inhibits for the RPCMs must be powered up within 3:00 hr of powerdown.
3. Some of the ISS cameras that will be powered down in support of the RPCM R&Rs are required to verify that the SSRMS is in a good configuration for the LEE B Lube task and that EV2/Arnold is in good position to begin the EVA task. The cameras will not be de-routed for powerdown until the SSRMS operator verifies the arm is in a good configuration and EV2/Arnold has egressed the APFR.
4. **MCC-H** will proactively make a call to ISS and Discovery that the cameras are about to be de-routed and powered down before it is executed.
5. Per their procedure, crewmembers will confirm w/**MCC-H** that inhibits are in place prior to beginning the RPCM R&R.
6. Per their procedure, crewmembers will notify **MCC-H** that the RPCM R&Rs are complete.
7. **MCC-H** will make a call to the crewmembers confirming that DDCU powerup is beginning, once the RPCM R&Rs are complete.
8. To manage the timeline and ensure LEE B Lube and RPCM R&R tasks are completed, EV2/Arnold needs to stop the SPDM Covers and start the LEE B Lube at an EVA PET of NLT 3:45 hr, and EV3/Acaba needs to stop the S1 Tasks and start the first RPCM R&R at an EVA PET of NLT 4:00 hr.
9. The bingo time to begin the second RPCM R&R is EVA PET of NLT 5:00 hr, to support a nominal EVA PET of 6:30 hr total.
10. If only one RPCM R&R is performed, the priority is the S01A_D RPCM, per the Flight Priorities. Per their procedure, crewmembers will R&R the S0 RPCM first.

EVA 3 INHIBIT PAD

Orbiter (1)

ALL EVAs	
TCS L12	1. √TCS POWER – OFF
KU-BAND ANTENNA {Performed during egress}	
MCC-H	1. √KU-BAND Mask – active 2. √KU-BAND EVA Protect Box – active

Ground

ALL EVAs	
Ground Radar	
MCC-H	1. √TOPO console, ground radar restrictions in place for EVA

USOS (1)

ALL EVAs	
PCU	<p style="text-align: center;"><u>NOTE</u></p> PCUs may require up to a 1-hr warmup period before they are operational
MCC-H	1. √PCUs (two) operational in discharge mode and one of the following: <ol style="list-style-type: none"> a. CCS PCU EVA hazard control FDIR enabled b. No more than two arrays unshunted and oriented < 105° from velocity vector If one or both PCUs failed <ol style="list-style-type: none"> 2. No more than two arrays unshunted and oriented < 105° from velocity vector
EuTEF COL-CC	Verify PLEGPAY Power Status (ETF_PLEGPAY_Pwr_Stat) – OFF
LOCATION DEPENDENT INHIBITS	
Lab Window {On call, EV crew not expected to be in this area}	IV If EV crew less than 10 ft from window or in window FOV, close window shutter
KU-Band (SGANT) Antenna {On call, EV crew not expected to be in this area}	MCC-H If EV crew < 3.3 ft from KU-BAND antenna <ol style="list-style-type: none"> 1. Park KU-BAND: <ol style="list-style-type: none"> 1.1 Pointing Mode – Inhibit 1.2 PLC – Reset 1.3 Autotrack Continuous Retry – Inhibit
Mobile Transporter	MCC-H 1. √MT latched

EVA 3 INHIBIT PAD (Cont)

USOS (2)

EVA 3 SPECIFIC INHIBITS

RPCM R&R

{Prior to performing RPCM P1 1A_A and S0 1A_D R&R}

NOTE

Phalcon plan is to take DDCU S01A Converter – Off, prior to the first RPCM R&R task, and leave in off until both RPCM R&Rs are complete

RPCM S01A_D

MCC-H 1. Verify DDCU S01A Converter – Off

RPCM P11A_A

MCC-H 1a. Verify RPCM S01A_A RPC 01 Open, Close Inhibited

Or

MCC-H 1b. Verify DDCU S01A Converter – Off

S1-S3 SSAS Panel BBC Inhibits (16)

1. RPCM S13A G: RPC 01 – Open, Close Cmd Inhibit
RPC 02 – Open, Close Cmd Inhibit
RPC 13 – Open, Close Cmd Inhibit
RPC 14 – Open, Close Cmd Inhibit
RPC 15 – Open, Close Cmd Inhibit
2. RPCM S12B A: RPC 05 – Open, Close Cmd Inhibit
RPC 11 – Open, Close Cmd Inhibit
RPC 13 – Open, Close Cmd Inhibit
3. RPCM S14B G: RPC 01 – Open, Close Cmd Inhibit
RPC 05 – Open, Close Cmd Inhibit
RPC 13 – Open, Close Cmd Inhibit
RPC 14 – Open, Close Cmd Inhibit
RPC 15 – Open, Close Cmd Inhibit
4. RPCM S11A A: RPC 03 – Open, Close Cmd Inhibit
RPC 04 – Open, Close Cmd Inhibit
RPC 13 – Open, Close Cmd Inhibit

RSOS (1)

ALL EVAs

SM Antennas

IV

1. GTS – Deactivate
2. ARISS (Ham Radio) – Deactivate or VHF (144-146 MHz) TX only

USOS (3)

LOCATION DEPENDENT INHIBITS

S-Band (SASA) Antennas

{On call, EV crew not expected to be in this area}

MCC-H If EV crew < 3.6 ft from S1 SASA [P1 SASA]

1. P1 SASA (S1 SASA) – Active
2. S1 SASA [P1 SASA] – Powered down

SARJ

{On call, EV crew not expected to be in this area}

MCC-H If EV crew working within 2 ft or outboard of SARJ

1. √DLA (1) – LOCKED
2. All motor setpoints set to zero
3. All motors deselected

TRRJ

For S1/S3 Fluid QD Jumper & FHRC P-Clamps:

MCC-H

While EV crew working within 2 ft of S1 TRRJ rotation envelope

1. √DLA (1) – LOCKED (locked at 0 deg for FHRC P-Clamps)

FPMU

{On call, EV crew not expected to be in this area}

MCC-H

If EV crew working within 5 ft of Floating Potential Measurement Unit

1. FPMU power – Off

SSPTS

{On call, EV crew not expected to be in this area}

MCC-H

If EV crew working within 2 ft of SSPTS cables

1. RPCM LA1A4A D RPC 3 – Open, Close Cmd Inhibit
2. RPCM LA2A3B D RPC 1 – Open, Close Cmd Inhibit
3. RPCM Z14B A RPC 2 – Open, Close Cmd Inhibit
4. RPCM Z13B A RPC 2 – Open, Close Cmd Inhibit

EVA 3 NOTES, CAUTIONS, AND WARNINGS

NOTES

1. Bolt install: Report torque and turns
Bolt release: Report torque and turns
(if different from published range)
2. EVA connectors: After dis-connection and prior to connection; verify pin and EMI band integrity. Verify connector free of FOD
3. Inspect Fluid QDs for damage, prior to mating
4. Toolbox doors must be closed with one latch per door, when EV crew not in immediate vicinity
5. Avoid contact with OBSS striker bars (Vitrolube coating)

CAUTION

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture shafts (drylube)
 2. PIP pins
 3. EVA Crane [PMA1]
 4. TCS Reflectors [PMA2,PMA3]
 5. APAS hardware [PMA2,PMA3]
 6. CETA Lights (Z-93 paint) [LAB,S1,Node 1]
 7. Deployed MISSEs [Columbus EPF]
 8. Passive UMAs
 9. MBS/SSRMS/SPDM/JEMRMS taped radiative surfaces: VDU, ACU, JEU, LEU, MCU, CRPCMs, and Cameras
 10. Deployed TUS cable [Nadir CETA rail]
 11. S0 aft face Radiator
 12. GPS Antennas (S13 paint) [S0,JLP]
 13. UHF Antennas [LAB,P1]
 14. ETCS Radiator flexhoses and panels [S1,P1]
 15. EETCS/PV Radiator flexhoses, bellows and panels [P6,P4,S4,S6]
 16. SASA RF Group [S1,P1]
 17. Heat pipe radiators [Z1]
 18. PCU cathode and HCA ports [Z1]
 19. Ku-Band Antenna (SGANT) dish [Z1]
 20. CMG cover/shells [Z1]
 21. SPDM SJEU, EP, OTCM, LEU, and LEE VDU Radiator surfaces
 22. Open CBM petal covers, LAB window shutter, and JPM window shutter
 23. FPMU [S1]
 24. OTSD
 25. COL HAM radio antennas [COL-Nadir]
 26. JTVE Cameras [JEM]
 27. JEM A/L Target and Pins
 28. S0/Node 2 Fluid Tray Hardlines at Node 2 end are limited to 25 lb

CAUTION (Cont)

ISS Constraints (Cont)

- B. Electrical cables
1. Avoid bend radii < 10 times cable diameter
- C. Fiber optic cables
1. Avoid bend radii < 10 times cable diameter
 2. Avoid pulling on cable during mate/demate
- D. Fluid line flex hoses and QDs
1. Avoid bend radii < 5 in for hoses with diameter < 1 in on LAB, S0, S1, P1, and 10-in for hoses with diameter < 1 in on all other elements
 2. Avoid bend radii < 14 in for hoses with a diameter ≥ 1 in
 3. Additional care should be taken to not exceed bend radii when applying loads at the flexible hose to rigid tube stub interfaces
 4. Ensure fluid QD booties are fully closed prior to leaving worksite; wire tie if reqd
- E. For structural reasons
1. Avoid vigorous body motions, quick grabs and kickoffs against tether restraints
 2. Avoid performing shaking motions (sinusoidal functions) more than four cycles
 3. Avoid kicking S1/P1 radiator beam
If any of these occur, wait 2 to 5 min to allow structural response to dissipate

EVA 3 NOTES, CAUTIONS, AND WARNINGS (Cont)

CAUTION (Cont)

ISS Constraints (Cont)

F. Other

1. ITT Cannon connector: On demated connectors, do not rotate collar or manipulate cable/connector using collar or connector tool
2. WIS Antennas: Do not use as handholds [Node 1,P6,Z1]
3. Lubricant from Ku-Band SGANT gimbals [Z1], CMGs [Z1], and RTAS Ground Strap fasteners [P6,P4,S4] can contaminate EMU
4. **MLI handholds are not rated for crewmember translation loads**
5. CBM petal covers may not be used as handholds unless both launch restraint pins are engaged
6. Prevent inadvertent contact of the tether shuttle with ETRS when the P3/S3 Tether Shuttle Stop is raised away from the rail

CAUTION (Cont)

Shuttle Constraints

A. Avoid inadvertent contact with

1. OBSS and SRMS Composite Sections and Cable Harnesses, Joint Torque Arms, Grapple Fixture Shafts,
2. LCS (silver Teflon) and LDRI (silver Teflon) and ITVC (gold foil) [OBSS]
3. WVS Antenna [ODS Truss & PLB Sill]
4. Payload Bay and Camera wire harnesses, cables, cable guides and connectors

B. No touch

1. LDRI diffuser [OBSS]
2. OBSS saddle contacts (when OBSS unberthed) [OBSS]
3. Monkey fur [PLB]
4. Cameras: Metallic surfaces [PLB]
5. Ku-Band Antenna black dish and gold thermal blankets [PLB]

EVA 3 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture targets and target pins
 2. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off
 3. Stay inboard of SARJ when active
 4. Stay 2 ft from S1/P1 radiator beam rotational envelope when beam is free to rotate
 5. Stay 5 ft from moving MT on face 1
 6. SOLAR and EuTEF [COL EPF]
- B. Handrails
1. Handrails previously used for MISSE attachment may not be used as a safety tether point [A/L endcone 564 & 566, A/L Tank 2 nad/fwd & port/fwd, P6 5389]
- C. Pinch
1. NZGL connector linkage. Use caution when mating/locking
 2. ITT Cannon Connector rotating housing
 3. EV side of IV Hatch during Hatch operation (also snag hazard) [A/L]
 4. LAB window shutter and CBM petal cover and JPM window shutter linkages during operation
 5. JEMRMS HRM capture latches
 6. JEM Cameras (JTVEs, EVE, WVE)
 7. JEM EFBM capture latches
- D. QDs
1. If QD is in FID when valve is opened (bail fwd), QD will leak and fluid line may whip
 2. Do not rotate if in mated/valve open config

WARNING (Cont)

ISS Constraints (Cont)

- E. RF radiation exposure
1. Stay 3.6 ft from S-Band (SASA) high gain Antenna when powered [S1,P1]
 2. Stay 1.3 ft from S-Band (SASA) low gain Antenna when powered [S1,P1]
 3. Stay 1 ft from UHF Antenna when powered [LAB,P1]
 4. Stay 0.3 ft from fwd/aft JPM PROX antenna
- F. Sharp Edges
1. Inner edges of WIF sockets
 2. APFR active WIF probes
 3. Mating surfaces of EVA connectors
Avoid side loads during connector mating
 4. Back side of MMOD shield fasteners
 5. Spring loaded captive EVA fasteners (e.g., 6B-boxes, BMRRM, RTAS, SARJ Covers); the end of the spring may protrude
 6. PMA umbilical launch restraints-exposed bolt threads
 7. Adjustable Fuse Tether (Fish Stringer) buckles stowed in Node Bag
 8. Nickel coated braided copper Ground Straps may contain frayed wires [P6,P4,S4,S6]
 9. SPDM OTCM gripper jaws

WARNING (Cont)

ISS Constraints (Cont)

- F. Sharp Edges (Cont)
10. Solar Array Blanket Box [P6,S6]
 11. Keep hands away from SSRMS LEE/POA/SPDM LEE/JEMRMS EE opening, snares, and PDGF curvic coupling (teeth)
 12. Fastener threads on back of Z1 U-jumper male FQD panel, if nutplate cap missing
 13. Outboard MT rail attachment lug near P6 handrail 5333 and gap spanner
 14. P2 connector on EWIS box TAA-06 [Zenith/Forward Corner 1 of P5 – SARJ at 0 deg]
 15. Port/Aft portion of A/L circular HR [HR 0506]
 16. Interior of JEMRMS HRMs
 17. JEM A/L hatch corners
- G. Thermal
1. EVA connectors with booties may become hot if left uncovered. Handling may need to be limited
 2. PMA handrails may be hot. Handling may need to be limited
 3. Turn off glove heaters when comfortable temp reached to prevent bladder damage. Do not pull fingers out of gloves when heaters are on
 4. Uncovered trunnion pins may be hot
 5. SSRMS/MBS/SPDM/JEMRMS/JTVE operating cameras and lights may radiate large amounts of heat

EVA 3 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING (Cont)

ISS Constraints (Cont)

G. Thermal (Cont)

6. Stay ≥ 1 ft away from PMAs and MMOD shields > 270 degF if EMU sun visor up; limit time to 15 min or less if > 300 degF
7. Stay at least 0.5 ft away from PMA and MMOD shields > 325 degF
8. Do not touch EMU protective visor if temp has been < -134 degF for > 15 min
9. No EMU TMG contact with PMAs and MMOD shields > 320 degF
10. No EMU boot contact with foot restraint when temp < -120 degF or > 200 degF
11. Columbus end cones may violate touch temperature constraints when $-75 \leq \beta \leq -60$ or $60 \leq \beta \leq 75$
12. PDGF surfaces may not meet touch temperature requirements for unlimited contact when $\beta \leq -70$ or $\beta \geq 70$
13. JPM port end cones and JLP port nadir may violate touch temperature constraints when $\beta > 60$ deg

WARNING (Cont)

ISS Constraints (Cont)

H. Electrical Shock

1. Stay ≥ 2 ft from ungrounded floating connectors if not unpowered
 - SSPTS connectors include NOD1 Stbd/Fwd HR 0130, Lab Stbd/Fwd HR 0273, PMA2 Stbd and Port
 - MBS Cross-Connect jumpers (translate past these using UMA handrails) Include S0 EVA Power Cables (inside S0 Bay 00 Face 4, Bay 01 Face 3) ESP2 jumper (inside S0 Bay 03 Face 4)
2. Do not touch SPDM CLPA 1 electrical connector prior to camera installation

WARNING (Cont)

Shuttle Constraints

A. Arcing/Molten Debris

1. Stay ≥ 2 ft from exposed EFGF connector when OBSS berthed, powered, and EFGF not grappled [PLB]
2. Stay ≥ 2 ft from exposed Stbd Fwd MPM contacts [PLB]
3. Stay above PLB sill when within 1 ft of powered ROEU connector [PLB]

B. Pinch

1. PRLA operation [PLB]

C. RF radiation exposure

1. Stay 3.28 ft from S-Band Antenna when powered
2. Stay 1 ft from top and side of UHF PLB Antenna radome surface when in high powered mode [ODS truss]
3. Stay 0.33 ft from top and side of UHF PLB Antenna radome surface when in low powered mode [ODS truss]
4. Remain below the level of the PLB door mold line for first 20 in Aft of Fwd bulkhead when S-Band Antenna powered [PLB]
5. Remain on the inboard side of the Stbd slidewire (sill handrails if slidewire not installed) for first 20 ft Aft of Fwd bulkhead when Ku-Band Antenna powered [PLB]

EVA 3 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING (Cont)

Shuttle Constraints (Cont)

D. Sharp Edges

1. PRLA grounding wipers [PLB]
2. LDRI baffles (also an entrapment hazard) [OBSS]
3. Keep hands away from SRMS EE opening and snares
4. TCS connector backshells have exposed threads [ODS]

E. Thermal

1. Illuminated PLB lights; do not touch
2. OBSS grapple fixture shafts/cams may be hot. Limit handling if required
3. Stay 27 ft from PRCS when powered
4. Stay 3 ft from VRCS when powered
5. Stay 3 ft from APU when operating

F. Contamination

1. Stay out of the immediate vicinity of leaking jet or APU

G. Lasers

1. Do not look at LDRI diffuser or LCS laser aperture window

EVA 3 TOOL CONFIG

EV2

EMU D-rings

- 2 – Tether Extender
- Waist Tether [on right]
- 85-ft Safety Tether [on right]
- 55-ft Safety Tether (spare)
[on right] [to MWS]

MWS

- Small trash bag
- RET (w/PIP pin) [right]
- RET (sm-sm)
- Adj tether [right]
- 2 – Wire ties

Swing Arm [right side]

- PGT w/6-in wobble s/n _____
- RET (sm-sm)

- Wire tie loop (holster) for Lube Gun

BRT [left side]

- 2 – Wire ties, short
- RET (sm-sm)

SAFER

Use Blue RETS only

RET Counts:	used	total
		(ISS qty)
RETs (sm-sm)	= 9	(16)
RETs (PIP pin)	= 4	(5)
RETs (lg-sm)	= 4	(8)

Adj Eq Tethers (sm-sm) = 6 (10)

Adj Eq Tethers (lg-sm) = 2 (2)

D-ring Tether Extenders = 5 (6)

NOTE: Prior to use, inspect the following hardware:

- RET cords for fraying
- Safety Tether & Waist Tether load alleviating straps: No red visible
- Sm Trash Bag: Bristle deformation/damage, after stowing tools in trash bag

EV3

EMU D-rings

- 2 – Tether Extender
- Waist Tether [on right]
- 85-ft Safety Tether [on right]
- 55-ft Safety Tether (spare)
[on right] [to MWS]

MWS

- Small Trash Bag
- RET (w/PIP pin) [right]
- RET (sm-sm)
- WIF Adapter**
- 2 – Wire ties

Swing Arm [right side]

- PGT w/no socket s/n _____
- 6-in wobble socket
- RET (sm-sm)

BRT [left side]

- 2 – Wire ties, short
- RET (sm-sm)

SAFER

CREWLOCK

RET (Lg-sm)

- LEE B Lube C-Lk Bag (#1)
- ***Grease Gun w/Straight Nozzle**
(Int RET #1, outside of bag)
- EVA Wipe** w/Wire Tie (thru wipe TP)
- Adj tether (around Grease Gun)
- Adj tether (Int RET #2)
- 2 – EVA Wipe
- RCC Gap Gauge (Int RET #3)
- Needle Nose pliers (Int RET #4)**

*Prime grease gun by disengaging plunger and gently pushing fwd on back of triangle until resistance met

Bag Color Key: **119 EVA Tools**, **Staging**, **Crewlock Bag**, MWS

CREWLOCK (Cont)

RET (Lg-sm)

Med ORU Bag

- 2 – Adj Equip Tether to outside of bag
- RET (sm-sm) (for EP MLI Cover)

EP MLI Cover

RET (sm-sm)

WIF Adapter

2 – EVA Wipes to bag straps (lid)

EVA Camera

RET (sm-sm)

RET (sm-sm)

PGT w/6-in wobble s/n _____

Adj tether (Lg-sm)

RPCM P1 1A_A Crewlock Bag (#2)

RPCM for P1 1A_A s/n C326597 (Int RET #1)

Rnd scoop (Int RET #2)

Adj tether (Lg-sm)

RPCM S0 1A_D Crewlock Bag (#4)

RPCM for S0 1A_D s/n C235299 (Int RET #1)

Rnd scoop (Int RET #2)

Cnctr Insul. Sleeve, size 33/37 (Int RET #3)

Adj tether (sm-sm) (to Med ORU Bag Lid)

S1 Tasks Crewlock Bag (#3)

RET w/PIP pin

6-in ext – 7/16-in wobble socket

RET w/PIP pin

18-in ext – 7/16-in

Ratchet w/2-in rigid ext (Int RET #1)

EVA Camera

RET (sm-sm)

Tether ext on A/L D-ring

EVA 3 TOOL CONFIG (Cont)

CREWLOCK (Cont)

Staging Bag

- Fish Stringer #1
 - Wire Tie Caddy (hook #1)
 - 9 – wire ties
 - Velcro/Tape Caddy (hook #2)
 - PGT s/n _____ (hook #3)
 - PGT Battery s/n _____
 - 7/16-in (wobble) Socket-6 ext
 - Vise Grips (hook #4)
 - Ratchet Wrench (hook #5)
 - 7/16-in (rigid) Socket-9 ext
 - Cheater Bar (hook #6)
 - Hammer (hook #7)
 - Spare 55-ft Safety Tether (to strap)
- Fish Stringer #2
 - Connector Cleaner Tool Kit (hook #1)
 - Pin Straightener Assy (hook #2)
 - Probe (hook #3)
 - Pry Bar (hook #4)
 - Sm Trash Bag (hook #5)
 - 72-in Gap Spanner
 - Torque Wrench (preset to 31 ft-lb) (hook #6)
 - RAD (hook #7)
 - Long-Duration Tie-Down Tether #1 (to strap)
 - Long-Duration Tie-Down Tether #2 (to strap)
 - MWS Key Strap Assy (on wire tie, to strap)
- RET (lg-sm)
 - Sm ORU Bag
 - Fish Stringer #3
 - Cnctr Insulating Sleeve, size 21/25 (hook #1)
 - Cnctr Insulating Sleeve, size 21/25 (hook #2)
 - Cnctr Insulating Sleeve, size 21/25 (hook #3)
 - Cnctr Insulating Sleeve, size 21/25 (hook #4)
 - Cnctr Insulating Sleeve, size 33/37 (hook #5)
 - Cnctr Insulating Sleeve, size 33/37 (hook #6)

EQUIPMENT LOCK

Mesh Bag #1 (119 EVA Tools Bag)

- Fish Stringer
- ORU Tether
- Grease Gun
- BRS Pin Tool w/sheath
- Ziploc bag w/grease gun caps

Mesh Bag #2 (EVA Done Bag)

- Socket ext 5/8-in, 7.8-in #2
- Rnd TM w/5/8-in prd socket
- Socket Caddy
- Torque Wrench Bag
- Cannon Connector Tool #1
- Cannon Connector Tool #2
- Ratchet Wrench
- Socket ext 7/16-in, 2-in #1
- Cnctr Insulating Sleeve 33/37

IV Bag

- 2 – Towels
- Contamination Detection Kit
- 2 – GP Caddy
 - 2 – Adjustable Thermal Mittens
- Skt Caddy (hatch cont) w/RET (sm-sm) (black)
 - 1/2-in Socket-8 ext
 - 7/16-in (wobble) Socket-6 ext (spare)
- 2 – DCM Plug (SAFER Hardmount)
- 2 – RET (sm-sm, black)

Mesh Bag #3 (Transfer to Shuttle)


- Locking Strut Aid #1
- Locking Strut Aid #2
- Locking Strut Aid #3
- Locking Strut Aid #4
- Torque Wrench (s/n 1007)

- Review PGT ops
 - Report “green light” (for torque down ops)
 - Report torque and turns
 - Expect LOTORQ fault msg, Fault LED and Red LED for bolt release ops


- Empty Trash Bag into Ziplock bag
 - Place Ziplock bag into EVA Done Bag
- Check Trash Bag zipper is closed

Bag Color Key: 119 EVA Tools, Staging, Crewlock Bag, MWS

EVA 3 EGRESS (00:25)

IV	EV2 – Arnold (FF)	EV3 – Acaba (SSRMS)
 <p>The diagram illustrates the egress configuration for EV2 and EV3. EV2 is on the left, and EV3 is on the right. EV2 has a left (L) and right (R) side with a waist tether and a safety tether (85 ft) connected to an aft anchor. EV3 has a left (L) and right (R) side with a waist tether and a safety tether (85 ft) connected to a forward anchor. A UJA D-ring is shown at the top left, and an EVA hatch D-ring with an extender is at the top center. External D-rings are located post-egress. A note box contains equipment lists for EV2 and EV3, and a 'NOTE' section with sunrise/sunset checks.</p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p>EV2: 1 – 85-ft Safety Tether (to Airlock)</p> <p>EV3: 1 – 85-ft Safety Tether (to Airlock) 1 – 55-ft Safety Tether (spare for SSRMS)</p> </div> <p>NOTE Sunrise/Sunset checks:</p> <ul style="list-style-type: none"> • √Helmet lts, visor, as reqd • √Glove heaters • √Tool, MWS tethers • √MWS, BRT latches 	<p>INITIAL CONFIG</p> <p>Verify Safety Tether configuration:</p> <ul style="list-style-type: none"> <input type="checkbox"/> EV2 right Waist Tether connected to EV3 Safety Tether <input type="checkbox"/> √Gate closed (both hooks) <input type="checkbox"/> √Hook locked (both hooks) <p>EGRESS (00:25)</p> <ol style="list-style-type: none"> 1. Open hatch thermal cover 2. Egress crewlock 3. Attach EV2 85-ft Safety Tether hook to aft D-ring anchor point. Verify Safety Tether configuration: <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Safety Tether Reel unlocked 4. Attach EV3 85-ft Safety Tether to forward D-ring anchor point <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> Release EV2 waist tether 5. Give EV3 GO to release waist tether 6. EV2 receive APFR from EV3 Stow APFR in airlock toolbox starboard WIF (Low-profile, record APFR settings: [_,_,_,_]) <ul style="list-style-type: none"> <input type="checkbox"/> √Blk-Blk, pull/twist test 7. EV2 receive med ORU Bag Attach med ORU to BRT 8. EV2 receive LEE Lube Crewlock Bag #1 Hold LEE Lube Crewlock Bag #1 for EV3 	<p>INITIAL CONFIG</p> <p>Verify Safety Tether configuration:</p> <ul style="list-style-type: none"> <input type="checkbox"/> EV3 right Waist Tether connected to airlock hatch D-ring extender <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <p>EGRESS (00:25)</p> <ol style="list-style-type: none"> 1. <input type="checkbox"/> √EV3 Safety Tether Reel unlocked 2. On EV2 GO, release waist tether 3. EV3 retrieve APFR and transfer to EV2 4. EV3 retrieve Med ORU Bag Transfer Med ORU Bag to EV2 5. EV3 retrieve LEE Lube Crewlock Bag #1 Transfer LEE Lube Crewlock Bag #1 to EV2 [Keep RET (lg-sm) on bag]

EVA 3 EGRESS (00:25) (Cont)


IV	EV2 – Arnold (FF)	EV3 – Acaba (SSRMS)
 <p>EV2 waist tether</p> <p>UJA D-ring</p> <p>EVA hatch D-ring w/ extender</p> <p>EV3 waist tether</p> <p>EV2 (L)</p> <p>EV3 (L)</p> <p>EV2 waist tether</p> <p>EV3 safety tether (85)</p> <p>EV2 safety tether (85)</p> <p>EV3 safety tether (85)</p> <p>external D-rings, post egress</p> <p>aft</p> <p>fwd</p> <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p>EV2: 1 – 85-ft Safety Tether (to Airlock)</p> <p>EV3: 1 – 85-ft Safety Tether (to Airlock) 1 – 55-ft Safety Tether (spare for SSRMS)</p> </div> <p>1. Post crew egress: WVS Software: Select page – RF Camera sel 'Advanced controls' S-Band level (two) – max</p>	<p><u>EGRESS</u> (Cont) (00:25)</p> <p>9. Verify EV3 SAFER Configuration:</p> <ul style="list-style-type: none"> <input type="checkbox"/> √R Handle down (HCM door – Closed) <input type="checkbox"/> √L Handle down (MAN ISO Valve – Open) <p>10. Close hatch thermal cover</p> <div style="border: 3px double black; padding: 5px; margin: 10px auto; width: 80%; text-align: center;"> <p>WARNING</p> <p>Maintain a 2-ft Keep-Out-Zone for floating cables between MT and MBS. Stay on UMA handrails during translation underneath MT</p> </div> <p>11. Translate to S0 HR 3528</p>	<p><u>EGRESS</u> (Cont) (00:25)</p> <p>6. Attach LEE Lube Crewlock Bag #1 to BRT</p> <p>7. Egress Airlock</p> <p>8. Verify EV2 SAFER Configuration:</p> <ul style="list-style-type: none"> <input type="checkbox"/> √R Handle down (HCM door – Closed) <input type="checkbox"/> √L Handle down (MAN ISO Valve – Open) <p>9. Translate to CETA Cart 2 location (outboard) (fairlead, as reqd)</p>

EVA 3 SETUP (00:20)


IV	EV2 – Arnold (FF)	EV3 – Acaba (SSRMS)
<div data-bbox="107 300 609 389" style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;">CETA Carts starting position – Port side of MT</p> </div> <ol style="list-style-type: none"> IV: Verify SSRMS at EVA 3 Setup position, then, give EV2 GO for APFR Install Use GCA, as reqd 	<p><u>SETUP</u> (00:20)</p> <ol style="list-style-type: none"> Temp stow med ORU Bag on S0 HR 3528 <p>Time permitting:</p> <ol style="list-style-type: none"> Deploy Med ORU Bag – adj tethers (2) to HR 3528 Deploy S1 Tasks Crewlock Bag #3. Temp stow Crewlock Bag Translate to CETA Cart’s location (MT at WS 4) Assist EV3 with GCA/clearances, as reqd <ol style="list-style-type: none"> Stow EV3 airlock Safety Tether stbd of CETA Cart pickup location at HR S0 3530 stand-off (nadir) 	<p><u>SETUP</u> (00:20)</p> <ol style="list-style-type: none"> Prep CETA Cart 2 for transfer <ul style="list-style-type: none"> <input type="checkbox"/> CETA Cart 2 coupler to UNLOCK <input type="checkbox"/> Translate CETA 2 to Bay 04. Align inboard TFR w/truss marker 8070 <input type="checkbox"/> Engage parking brake (left handle) <input type="checkbox"/> CETA Cart 2 coupler to CAPTURE <input type="checkbox"/> Stow brake handles (4) (forward) <input type="checkbox"/> √Swing arms (3) stowed Temp stow LEE Lube Crewlock Bag #1 on S0 HR 3546 On IV GO: When SSRMS at the EVA 3 Setup position: Give M1/M2 GO (“ready”) for APFR install and ingress. Use GCA, as reqd Install WIF adapter on SSRMS (TP toward EE) <ul style="list-style-type: none"> <input type="checkbox"/> √PIP pin installed <input type="checkbox"/> Perform pull test Retrieve APFR from CETA Cart 2 WIF 4 Install APFR [12,PP,F,6] in WIF adapter <ul style="list-style-type: none"> <input type="checkbox"/> √Blk-Blk, pull/twist test Attach 55-ft safety tether to SSRMS EE HR, and perform tether swap. Verify tether configuration: <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Safety Tether Reel unlocked <input type="checkbox"/> Release EV3 85-ft Safety Tether and transfer to EV2

CAUTION
Do not impart loads into CETA Cart with less than 3 of 4 wheel bogies latches closed


EVA 3 CETA CART RELOCATION (01:00)

IV/RMS	EV2 – Arnold (FF)	EV3 – Acaba (SSRMS)
<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="border: 1px solid black; padding: 2px;">MT</div> <div style="border: 1px solid black; padding: 2px;">CETA Cart 1 (inboard)</div> <div style="border: 1px solid black; padding: 2px;">CETA Cart 2 (outbd)</div> </div> <p>CETA Carts starting position – Port side of MT</p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="border: 1px solid black; padding: 2px;">CETA Cart 2 (outbd)</div> <div style="border: 1px solid black; padding: 2px;">MT</div> <div style="border: 1px solid black; padding: 2px;">CETA Cart 1 (outbd)</div> </div> <p>CETA Cart 2 relocated – Stbd side of MT</p> <ol style="list-style-type: none"> 1. M1/M2: Receive report from EV3 when APFR ingress is complete 2. IV: <input type="checkbox"/> Verify good EV3 glove heaters, visor, and TCV configuration 3. M1/M2: On EV3 GO, CETA Cart 2 ready for removal 4. M1/M2: On EV3 GO, maneuver CETA Cart 2 to Port Clearance position  <p style="text-align: center; font-size: small;">FS 18-34</p>	<p><u>CETA CART 2 REMOVAL FROM P1</u></p> <ol style="list-style-type: none"> 1. Assist EV3 with APFR ingress, as reqd 2. On EV3 GO: Release brake (tap pedal twice) 3. Release wheel bogies (4) <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 4. Inform EV3 when brakes/wheel bogies are released, and Safety Tethers are clear 5. EV2: Provide GCA to EV3/M1 for clearances, as reqd 6. Verify CETA Cart 2 is clear of structure before translating 7. Verify CETA Cart 1 brake handles forward and locked 8. Retrieve S1 Crewlock Bag #3 and put on BRT (keep adj tether w/Crewlock Bag) <p><u>INSTALL CETA CART 2 ON S1</u></p> <ol style="list-style-type: none"> 9. Translate to starboard side of MT (via nadir path) 10. Verify MT coupler is in CAPTURE 11. Temp stow S1 Crewlock Bag #3 on S1 FHRC 12. Temp stow EVA camera outboard of CETA Cart 2 install location 13. Perform Get-Aheads (time permitting): <ul style="list-style-type: none"> <input type="checkbox"/> S1 Tasks: SSAS BBC PNL RECONFIG, FLUID QD JUMPER, FHRC P-CLAMP RELEASE 	<p><u>CETA CART 2 REMOVAL FROM P1</u></p> <ol style="list-style-type: none"> 1. Ingress SSRMS APFR. Use GCA, as reqd 2. Attach waist tether to ingress aid <div style="border: 3px double black; padding: 5px; text-align: center; margin: 10px 0;"> <p>WARNING Do not touch APFR Ingress Aid shaft for more than 2:30 min (after initial 1:30 hr of exposure)</p> </div> <ol style="list-style-type: none"> 3. Inform M1/M2 APFR ingress is complete 4. ✓Glove heaters, visor, and TCV setting 5. Tether to CETA Cart 2 using RET. Use GCA, as reqd 6. Grasp CETA Cart 2 at grids B & H (recommended) 7. Give EV2 GO for CETA Cart 2 brake release and wheel bogie release 8. Receive report from EV2 that brakes/wheel bogies release 9. Give M1/M2 GO – Ready for CETA Cart 2 removal 10. Remove CETA Cart 2 from rails: <ul style="list-style-type: none"> Lift CETA Cart 2 from rails (ISS forward), until wheel bogies are clear of structure. Use GCA, as reqd 11. EV3: Inform M1/M2 CETA Cart 2 is separated from rail 12. Give M1/M2 GO for CETA Cart Port Clearance position maneuver <p><u>INSTALL CETA CART 2 ON S1</u></p>


EVA 3 CETA CART RELOCATION (01:00) (Cont)

IV/RMS	EV2 – Arnold (FF)	EV3 – Acaba (SSRMS)
<p>5. M1/M2: On EV2 GO, maneuver SSRMS to the CETA Cart 2 Delivery position</p> <p>6. M1/M2: Receive EV3 report that APFR egress is complete</p> <p>7. IV receive glove inspection report from EV2</p>  <p>8. M1/M2: Receive EV2 report that EV2 is ready for ingress and GCA, as reqd</p> <p>9. M1/M2: On EV2 GO, maneuver SSRMS to the Starboard Clearance position</p>	<p>14. Verify safety tethers clear of CETA Cart 2 install area</p> <p>15. Give M1/M2 GO for maneuver to CETA Cart 2 Delivery position. Use GCA, as reqd</p> <p>16. Rotate and lock wheel bogies (4) onto MT rail <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></p> <p>17. Engage CETA Cart 2 Parking Brake</p> <p>18. Give EV3 GO to release CETA Cart 2 and remove RET</p> <p>19. Inspect gloves/gauntlets. Report glove status to IV</p> <p>20. Perform prep for Safety Tether swap: Attach Waist Tether to handrail Verify tether configuration: <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked</p> <p>21. Swap to 55-ft SSRMS Safety Tether: <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked <input type="checkbox"/> <input checked="" type="checkbox"/> Safety Tether Reel Unlocked</p> <p>22. Attach Waist Tether to ingress aid</p> <p>23. EV2: Inform M1/M2, EV2 ready for APFR ingress. Use GCA, as reqd</p> <p>24. Ingress APFR. When ingress complete: Give M1/M2 GO to perform Starboard Clearance maneuver</p>	<p>13. Install CETA Cart 2 on rail</p> <p>14. On EV2 GO, release CETA Cart 2 and remove RET</p> <p>15. Inform M1/M2, EV3 is ready for APFR egress</p> <p>16. Egress APFR. Use GCA, as reqd</p> <p>17. EV3: Inform M1/M2 APFR egress for EV3 is complete (APFR ready for EV2 ingress, after tether swap)</p> <p>18. Perform prep for Safety Tether swap: Attach Waist Tether to handrail Verify tether configuration: <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked</p> <p>19. Swap to EV2 85-ft airlock Safety Tether: <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked <input type="checkbox"/> <input checked="" type="checkbox"/> Safety Tether Reel Unlocked</p> <p>20. Provide clearance for SSRMS back away</p>


EVA 3 CETA CART RELOCATION (01:00) (Cont)

IV/RMS	EV2 – Arnold (FF)	EV3 – Acaba (SSRMS)
<p style="text-align: center;"><u>NOTE</u></p> <p>IV: The next step is for M1/M2 and EV2, and requires no IV action</p> <p>10. M1/M2: On EV2 GO, begin maneuver to OTCM 2 Blanket Setup position</p>  <p style="text-align: center;">FS 18-34</p>	<p>25. Give M1/M2 GO to begin maneuver to OTCM 2 Blanket Setup position for SPDM COVERS</p>	<p><u>COUPLE CETA CART 2 TO MT</u></p> <p>21. Verify configuration ready for CETA Cart 2 coupling to MT</p> <ul style="list-style-type: none"> <input type="checkbox"/> Brake handles (4) forward <input type="checkbox"/> MT coupler in CAPTURE <p>22. Release brakes (tap pedal twice)</p> <p>23. Translate CETA Cart 2 to MT</p> <p>24. Couple CETA Cart 2 to MT</p> <ul style="list-style-type: none"> <input type="checkbox"/> Couple CETA Cart 2 to MT, max rate 0.5 ft/sec <input type="checkbox"/> MT coupler to LOCK <p>25. Verify CETA Cart 2 brakes handles forward and locked</p> <p>26. Retrieve EVA camera from temp stow location</p> <p><u>CLEANUP</u></p> <p>27. Inspect gloves/gauntlets. Report glove status to IV</p> <p>28. Translate to S1 for S1 TASKS</p>


EVA 3 CETA CART RELOCATION – TASK DATA




Active coupler



TFR and Brakes



Swing arm



Swing Arm WIF

EVA 3 CETA CART RELOCATION – TASK DATA (Cont)

Tools: None


Foot Restraints:

Task	WIF	APFR Setting
CETA CART Install/Remove	SSRMS	12, PP, F, 6

EVA Fasteners: None

EVA Connectors: None

CETA Cart Mass = 560 lb



Timeline Considerations:

1. CETA carts must be moved to the starboard side of MT for STS-127 (2J/A) P6 Battery R&R (MT WS 8)

Notes:

1. Ensure safety tethers are clear of CETA cart during safety tether swap, CETA cart relocation, and CETA cart install
2. CETA to MT max coupling rate is 0.5 ft/sec; CETA to CETA max coupling rate is 1 in/sec
3. 3 of 4 wheel bogies are required to be installed prior to un-tethering (from a safety, fault tolerance standpoint). Can leave CETA Carts in this configuration – MT okay to translate

Cautions:

1. Do not impart loads into CETA cart with less than 3 of 4 wheel bogies engaged

Warnings:

1. None

EVA 3 SPDM COVERS (01:30)


IV/SSRMS	EV2 – Arnold (SSRMS)
<ol style="list-style-type: none"> 1. M1/M2: On EV2 GO, maneuver SSRMS to SPDM OTCM 2 Blanket Maintenance position Expect EV2 GCA to position SSRMS for “2.6 Flaps” access 2. M1/M2: Expect EV2 GCA to position SSRMS for “Wrist Roll Flaps”, side 1 access 3. M1/M2: Expect EV2 GCA to position SSRMS/OTCM 2 for “Wrap Blanket” access 4. M1/M2: Expect EV2 GCA to position OTCM 2 for “Wrist Roll Flaps”, side 2 access 5. M1/M2: On EV2 GO, maneuver to OTCM 2 Blanket Setup position 6. M1/M2: Expect EV2 GCA to EP1 Blanket Removal position 7. M1/M2: Expect EV2 GCA to release EP1 quarter-turn fasteners 	<p><u>OTCM COVER RECONFIGURATION</u> (00:30)</p> <ol style="list-style-type: none"> 1. Adjust MWS down (increase clearance with SPDM), as reqd 2. Give M1/M2 GO to maneuver to OTCM 2 Blanket Maintenance position 3. GCA SSRMS to the “2.6 Flaps” position, as reqd 4. Mate “2.6 Flaps” (2) to corresponding Velcro patches (see “2.6 Flaps” – see detail on task data sheet) 5. GCA SSRMS for “Wrist Roll Flaps,” side 1 access, as reqd 6. Mate “Wrist Roll Flaps” (4) to corresponding Velcro patches (solid line and barber pole side must be closed first) (see task data sheet) 7. GCA SSRMS/OTCM 2 for “Wrap Blanket” access and to reach “Wrap Blanket” edge, as reqd 8. Pull out edge of “Wrap Blanket” which is rolled under itself (see task data sheet) 9. GCA OTCM 2 for “Wrist Roll Flaps,” side 2 access, as reqd 10. Mate “Wrist Roll Flaps” (4) to corresponding Velcro patches (solid line and barber pole side must be closed first) (see task data sheet) 11. When “2.6 Flaps,” “Wrist Roll Flaps,” and “Wrap Blankets” are reconfigured: Give M1/M2 GO to maneuver to OTCM 2 Blanket Setup position (OTCM 2 Blanket maintenance complete) <p><u>EP1 THERMAL BLANKET REMOVAL</u> (00:40)</p> <ol style="list-style-type: none"> 12. When maneuver to OTCM 2 Blanket Setup position complete: Expect SSRMS OCAS maneuver to EP 1 Blanket Setup position (zenith) 13. Attach RET to adj tether 14. When maneuver to EP1 Blanket Setup position complete: Use GCA to maneuver SSRMS to the EP 1 Blanket Removal position 15. Release quarter-turn fasteners, as reqd, to fold back nadir end of EP1 cover 16. Attach adj tether to EP1 Blanket tether loop 17. Release quarter-turn fasteners (14 total) and lift corresponding tabs GCA SSRMS into position to reach fasteners, as reqd (see task data sheet) 18. Remove blanket from Electronics Platform 1 19. Wrap EP1 blanket with adjustable tether and stow behind MWS (need hands free for covering grounding patches, in next step) 20. On SPDM, fold over Velcro flaps to cover thermal blanket grounding patches (2) and Velcro patches (3), which are now exposed (see task data sheet for details on grounding patch locations)

EVA 3 SPDM COVERS (01:30) (Cont)

IV/SSRMS	EV2 – Arnold (SSRMS)
<p>8. M1/M2: On EV2 GO, maneuver SSRMS to EP1 Blanket Setup position</p> <p>9. M1/M2: Inform EV2, maneuvering SSRMS to egress location (S0 HR 3416) Expect EV2 GCA during SSRMS maneuver to APFR egress position (EV2 airlock safety tether located at S0 3530 – port-nadir from HR 3416)</p> <p>10. Expect EV2 GCA for APFR Removal</p> <p>11. On EV2 GO: Maneuver SSRMS LEE Lube Clearance position</p>	<p><u>SPDM CLEANUP</u> (00:20)</p> <p>21. When EP1 Blanket Removal complete: Give M1/M2 GO to maneuver to EP1 Blanket Setup position</p> <p>22. Adjust MWS up, as reqd</p> <p>23. Perform glove check</p> <p>24. Expect M1/M2 to maneuver to EV2 SSRMS egress position Use GCA for maneuver to APFR egress position, as reqd</p> <p>25. Inform M1/M2: EV2 is ready for APFR egress Egress APFR</p> <p>26. Translate to S0 HR 3530</p> <p>27. Perform Safety Tether Transfer to EV3 airlock 85-ft Safety Tether:</p> <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Safety Tether Reel unlocked <p>28. Use GCA to position SSRMS for APFR Removal, as reqd</p> <p>29. Release/remove APFR from WIF adapter</p> <p>30. Install APFR [4,HH,F,6] at WIF S0 WIF 45 (located on Face 6)</p> <ul style="list-style-type: none"> <input type="checkbox"/> √Blk-Blk, pull/twist test <p>31. RET to and remove WIF adapter from SSRMS</p> <p>32. Remove 55-ft Safety Tether hook from SSRMS and attach to MWS</p> <p>33. When APFR and Safety Tether removed from LEE: Give M1/M2 GO to maneuver to LEE Lube Clearance position</p> <p>34. Stow 55-ft Safety Tether on S0 HR 3545</p> <p>35. Stow EP1 Blanket on RET in med ORU bag</p> <p>36. Stow WIF adapter on RET in med ORU Bag</p> <p>37. Retrieve LEE B Lube Crewlock Bag #1 from HR 3546</p> <p>38. Stow LEE Lube Crewlock Bag #1 on BRT</p>

Post 1JA SPDM Configuration – Overview


Post 1JA SPDM Configuration



2.6 Flaps (SJEU) – Detail





Wrap Blanket – Detail 1





EVA 3 SPDM COVERS – TASK DATA (Cont)

Wrist Roll Flaps – Detail




Wrap Blanket – Detail



EVA 3 SPDM COVERS – TASK DATA (Cont)

EP 1 Cover – Detail



EP 1 Cover – View 1

EP 1 Cover ¼-Turn Fasteners

¼-Turn Fasteners (14) – Rotate to release EP Cover



NOTE: ¼-Turn Fasteners may require effort to complete the rotation to the 90 deg. release orientation

- = indicates ¼-turn fastener location (14)
- = indicates ground tab location (2)
- = indicates tether point location (1)
- = indicates Velcro patch location (3)





EP 1 Cover – View 2




EVA 3 LEE B REPAIR (01:45)

IV/SSRMS	EV2 – Arnold (FF)
 <p>○ MOVING BEARING ⊕ FIXED BEARING</p>	<ol style="list-style-type: none"> 1. Ingress APFR 2. Adjust MWS down (increase clearance with SSRMS) 3. Deploy holster 4. Inform M1/M2, APFR ingress is complete 5. Give M1/M2 GO to maneuver to the LEE Lubrication position Use GCA to maneuver SSRMS to LEE Lubrication position, as reqd 6.  Retrieve EVA Camera from Crewlock Bag. Take pictures of LEE: <ul style="list-style-type: none"> • Bearings #1 & #2 • Bearings #3 & #4 • Bearings #5 & #6 • Overall view of LEE 7. Stow EVA Camera on swing arm <div style="border: 2px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Avoid touching LEE curvic coupling, grounding springs, snares, and internal mechanisms inside LEE with gloved hand</p> </div> <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Avoid inadvertent contact with LEE grounding springs, torsional springs, latch covers, shrouds, and camera</p> <p>Do not stress torsional spring more than 90 deg (rod-end perpendicular to LEE housing) when exercising bearing</p> </div> <p style="text-align: center;"><u>NOTE</u></p> <p>Grease should not extend more than ¼ inch from bearing</p>


EVA 3 LEE B REPAIR (01:45) (Cont)

IV/SSRMS	EV2 – Arnold (FF)
<ol style="list-style-type: none"> 1. M1/M2: Receive GO from EV2 for Snare Checkout 2. IV/MCC-H: Receive EV2 report on snare condition <p>Prep grease gun:</p> <ul style="list-style-type: none"> • Engage teeth by rotating plunger 180 deg (black triangle up) • Remove MLI. Stow on gun in way to prevent contact w/LEE • Point tip away from LEE • Rotate shutoff knob such that FLOW points toward nozzle <p>Stow grease gun:</p> <ul style="list-style-type: none"> • Disengage teeth by rot plunger 180 deg (black triangle down) • Rotate shutoff knob such that FLOW points \perp to nozzle • Install MLI tip cover 	<p>LEE B SNARE REPAIR (00:40)</p> <ol style="list-style-type: none"> 8. Inform M1/M2, tools and EV crew clear of LEE. Give SSRMS GO for Snare Checkout (Close and Open Snares) 9. Report to IV/MCC-H: Snare condition (in or out of groove) 10. Push top right and bottom right snares (#1 & #3) into groove with needle nose pliers, as reqd 11. Use gap gauge to get left snare (#2) out of groove, as reqd (form “C” curve) 12. Exercise lower left outer bearing (#2) in x-axis using needle nose pliers [15 sec] 13. Report to IV/MCC-H: Bearing mobility (This report is used to calibrate the initial bearing stiffness) 14. Push left snare (#2) into groove with needle nose pliers 15. Prep grease gun 16. Apply grease to lower left bearings (#1 & #2) (use box pattern, apply to inside first). Pack grease using gap gauge, as reqd 17. Give M1/M2 GO to maneuver a +120 deg (ccw) wrist roll 18. Apply grease to lower left bearings (#3 & #4) (use box pattern, apply to inside first). Pack grease using gap gauge, as reqd 19. Give SSRMS GO to maneuver a +120 deg (ccw) wrist roll 20. Apply grease to lower left bearings (#5 & #6) (use box pattern, apply to inside first). Pack grease using gap gauge, as reqd 21. Stow grease gun 22. GCA SSRMS wrist roll to access both sides of lower right snare (#1), as reqd 23. Pull lower right snare (#1) fully out into C-curve with gap gauge, apply force perpendicular to rod-end 24. Prep grease gun 25. Apply grease to rod-end/fork interface to lower left bearing (#5) 26. Apply grease to rod-end/fork interface to lower right (#4) 27. Stow grease gun 28. Pack grease using gap gauge, as reqd 29. Use gap gauge to get snare out of groove, as reqd (form “C” curve) 30. Exercise lower left bearing (#5) in x-axis using needle nose pliers [1 min/40 cycles] 31. Report to IV/MCC-H: Noticeable change in bearing motion 32. Exercise lower right (#4) in x-axis using needle nose pliers [1 min/40 cycles] 33. Report to IV/MCC-H: Noticeable change in bearing motion 34. Push lower right snare (#1) into groove with needle nose pliers 

EVA 3 LEE B REPAIR (01:45) (Cont)

IV/SSRMS	EV2 – Arnold (FF)
<p>Prep grease gun:</p> <ul style="list-style-type: none"> Engage teeth by rotating plunger 180 deg (black triangle up) Remove MLI. Stow on gun in way to prevent contact w/LEE Point tip away from LEE Rotate shutoff knob such that FLOW points toward nozzle <p>Stow grease gun:</p> <ul style="list-style-type: none"> Disengage teeth by rot plunger 180 deg (black triangle down) Rotate shutoff knob such that FLOW points \perp to nozzle Install MLI tip cover 	<p>35. Give SSRMS GO to maneuver a -120 deg (cw) wrist roll</p> <p>36. On SSRMS GO: Pull lower right snare (#2) fully out into C-curve with gap gauge, apply force perpendicular to rod-end</p> <p>37. Prep grease gun</p> <p>38. Apply grease to rod-end/fork interface to lower left bearing (#3)</p> <p>39. Apply grease to rod-end/fork interface to lower right bearing (#2)</p> <p>40. Stow grease gun</p> <p>41. Exercise lower left bearing (#3) in x-axis using needle nose pliers [1 min/40 cycles]</p> <p>42. Report to IV/MCC-H: Noticeable change in bearing motion</p> <p>43. Exercise lower right bearing (#2) in x-axis using needle nose pliers [1 min/40 cycles]</p> <p>44. Report to IV/MCC-H: Noticeable change in bearing motion</p> <p>45. Push lower right snare (#2) into groove with needle nose pliers</p> <p>46. Give SSRMS GO to maneuver a -120 deg (cw) wrist roll</p> <p>47. On SSRMS GO: Pull lower right snare (#3) fully out into C-curve with gap gauge, apply force perpendicular to rod-end</p> <p>48. Prep grease gun</p> <p>49. Apply grease to rod-end/fork interface to lower left bearing (#1)</p> <p>50. Apply grease to rod-end/fork interface to lower right bearing (#6)</p> <p>51. Stow grease gun</p> <p>52. Exercise lower left bearing (#1) in x-axis using needle nose pliers [1 min/40 cycles]</p> <p>53. Report to IV/MCC-H: Noticeable change in bearing motion</p> <p>54. Exercise lower right bearing (#6) in x-axis using needle nose pliers [1 min/40 cycles]</p> <p>55. Report to IV/MCC-H: Noticeable change in bearing motion</p> <p>56. Push lower right snare (#3) into groove with needle nose pliers</p> <p>57. Use gap gauge to pack any excess grease into bearings, as reqd</p> <p>58. Clean tools as necessary with EVA wipe</p>  

EVA 3 LEE B REPAIR (01:45) (Cont)

IV/SSRMS	EV2 – Arnold (FF)		
<p>3. M1/M2: Receive GO from EV2 for Snare Checkout</p> <p>4. IV/MCC-H: Receive EV2 report on snare condition </p> <p>5. M1/M2: Receive EV2 report: LEE photos, obs complete</p> <p>6. M1/M2: On EV2 GO, maneuver SSRMS to LEE Lubrication Clearance position</p> <div data-bbox="117 646 762 1122" style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">Tool Inventory</p> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; vertical-align: top;"> <p style="text-align: center;"><u>MWS</u></p> <p><input type="checkbox"/> Small trash bag</p> <p><input type="checkbox"/> RET</p> <p><input type="checkbox"/> RETs w/PIP pin</p> <p><input type="checkbox"/> Adj tether</p> <p><input type="checkbox"/> Wire ties (2)</p> <p style="text-align: center;"><u>BRT</u></p> <p><input type="checkbox"/> Wire ties (2)</p> <p><input type="checkbox"/> RET</p> <p style="text-align: center;"><u>Swingarm</u></p> <p><input type="checkbox"/> Wire tie loop (holster)</p> <p style="padding-left: 20px;"><input type="checkbox"/> Grease gun</p> <p style="padding-left: 20px;"><input type="checkbox"/> EVA wipe</p> </td> <td style="width: 50%; vertical-align: top;"> <p style="text-align: center;"><u>Crewlock Bag</u></p> <p><input type="checkbox"/> Adj tether</p> <p><input type="checkbox"/> Adj tether</p> <p style="padding-left: 20px;"><input type="checkbox"/> EVA Wipes (2)</p> <p><input type="checkbox"/> EVA wipe w/ wire tie</p> <p><input type="checkbox"/> Needle nose pliers</p> <p><input type="checkbox"/> RCC Gap gauge</p> </td> </tr> </table> </div> <p>7. IV: Record APFR settings: [__, __, __, __] (S0 WIF 42)</p> <p>8. Receive glove check report from EV2</p>	<p style="text-align: center;"><u>MWS</u></p> <p><input type="checkbox"/> Small trash bag</p> <p><input type="checkbox"/> RET</p> <p><input type="checkbox"/> RETs w/PIP pin</p> <p><input type="checkbox"/> Adj tether</p> <p><input type="checkbox"/> Wire ties (2)</p> <p style="text-align: center;"><u>BRT</u></p> <p><input type="checkbox"/> Wire ties (2)</p> <p><input type="checkbox"/> RET</p> <p style="text-align: center;"><u>Swingarm</u></p> <p><input type="checkbox"/> Wire tie loop (holster)</p> <p style="padding-left: 20px;"><input type="checkbox"/> Grease gun</p> <p style="padding-left: 20px;"><input type="checkbox"/> EVA wipe</p>	<p style="text-align: center;"><u>Crewlock Bag</u></p> <p><input type="checkbox"/> Adj tether</p> <p><input type="checkbox"/> Adj tether</p> <p style="padding-left: 20px;"><input type="checkbox"/> EVA Wipes (2)</p> <p><input type="checkbox"/> EVA wipe w/ wire tie</p> <p><input type="checkbox"/> Needle nose pliers</p> <p><input type="checkbox"/> RCC Gap gauge</p>	<p><u>LEE B CLEANUP</u> (00:30)</p> <p>59. Give SSRMS GO for Snare Checkout (Close and Open Snares)</p> <p>60. Report to IV/MCC-H: Snare condition (in or out of groove)</p> <p>61. <input checked="" type="checkbox"/> Retrieve EVA Camera from Crewlock Bag. Take pictures of LEE:</p> <ul style="list-style-type: none"> • Bearings #1 & #2 • Bearings #3 & #4 • Bearings #5 & #6 • Overall view of LEE <p>62. Stow EVA Camera in LEE Lube Crewlock Bag #1</p> <p>63. Inform M1/M2, LEE photos and observation complete. Give SSRMS GO to maneuver SSRMS to LEE Lubrication Clearance position</p> <p>64. Adjust MWS up, as reqd</p> <p>65. Perform tool inventory</p> <p>66. Place EVA wipe over end of grease gun and secure with wire tie</p> <p>67. Stow grease gun on outside of Crewlock Bag using adj tether</p> <p>68. Egress APFR</p> <p>69. Stow APFR ingress aid</p> <p>70. Relocate APFR to S0 WIF 42 <input type="checkbox"/> √Blk-Blk, pull/twist test</p> <p>71. Adjust APFR to low-profile configuration and report settings to IV</p> <p>72. Inspect gloves/gauntlets. Report glove check to IV</p> <p>73. Translate to med ORU Bag (S0 HR 3528)</p> <p>74. Stow LEE Lube Crewlock Bag #1 near med ORU Bag location</p> <p>If EV2 performing P1 1A_A REMOVE/REPLACE:</p> <p>75. Retrieve PGT. Stow PGT on swing arm</p> <p>76. Go to P1 1A_A RPCM REMOVE/REPLACE</p>
<p style="text-align: center;"><u>MWS</u></p> <p><input type="checkbox"/> Small trash bag</p> <p><input type="checkbox"/> RET</p> <p><input type="checkbox"/> RETs w/PIP pin</p> <p><input type="checkbox"/> Adj tether</p> <p><input type="checkbox"/> Wire ties (2)</p> <p style="text-align: center;"><u>BRT</u></p> <p><input type="checkbox"/> Wire ties (2)</p> <p><input type="checkbox"/> RET</p> <p style="text-align: center;"><u>Swingarm</u></p> <p><input type="checkbox"/> Wire tie loop (holster)</p> <p style="padding-left: 20px;"><input type="checkbox"/> Grease gun</p> <p style="padding-left: 20px;"><input type="checkbox"/> EVA wipe</p>	<p style="text-align: center;"><u>Crewlock Bag</u></p> <p><input type="checkbox"/> Adj tether</p> <p><input type="checkbox"/> Adj tether</p> <p style="padding-left: 20px;"><input type="checkbox"/> EVA Wipes (2)</p> <p><input type="checkbox"/> EVA wipe w/ wire tie</p> <p><input type="checkbox"/> Needle nose pliers</p> <p><input type="checkbox"/> RCC Gap gauge</p>		

EVA 3 LEE B REPAIR – TASK DATA




Figure 1. LEE Face – Overview

EVA 3 LEE B REPAIR – TASK DATA (Cont)




Figure 2. LEE Face – Overview (Cont)

EVA 3 LEE B REPAIR – TASK DATA (Cont)




Figure 3. LEE Lubing Pattern

EVA 3 LEE B REPAIR – TASK DATA (Cont)




Figure 4. LEE Face

EVA 3 LEE B REPAIR – TASK DATA (Cont)

Estimated Task Duration:

	With SSRMS	Without SSRMS
One EV Crew	01:45	N/A
Two EV Crew	N/A	N/A

Tools:

EV3	
Crewlock Bag	RETs (2)
Gap gauge w/Kapton Tape	Grease Gun w/Straight Nozzle
Needle nose pliers w/ Kapton tape	EVA Wipes (5)
EVA Camera	

Foot Restraints:

Task	WIF	Y/P Setting	APFR Setting
LEE B SNARE REPAIR	S0 WIF 45		4, HH, F, 6

EVA Fasteners: N/A

EVA Connectors: N/A

LEE Mass = ~460 lb/209 kg

Notes:

- Grease should not extend more than ¼ inch from bearing

Cautions:

- Avoid inadvertent contact with LEE grounding springs, torsional springs, latch covers, shrouds, and camera
- Do not stress torsional spring more than 90 deg (rod-end perpendicular to LEE housing) when exercising bearing

Warnings:

- Avoid touching LEE curvic coupling, grounding springs, snares, and internal mechanisms inside LEE with gloved hand

Timeline Considerations:

- Photos shall be taken as best effort, noting that it is possible that the LEE may be in an eclipse
- Inhibits for SSRMS brakes and trigger-safe are controlled in Robotics procedures. SSRMS will give EV2 GO each time inhibits are in place and ready for EVA LEE work
- Time permitting, **MCC-H** may request additional cycles for sticky bearings

Grease Gun Steps:



Prep grease gun

- Engage teeth by rotating plunger 180 deg (black triangle up)
- Remove MLI; stow on gun in way to prevent contact with LEE
- Point tip away from LEE
- Rotate shutoff knob such that FLOW points toward nozzle

Stow grease gun

- Rotate shutoff knob such that FLOW points perpendicular to nozzle
- Disengage teeth by rotating plunger 180 deg (black triangle down)
- Install MLI tip cover

EVA 3 S1/S3 SSAS PANEL BBC RECONFIG (00:30)

IV	EV3 – Acaba (FF)
<p>1. Verify with MCC-H that inhibits are in place</p> <p>2. Give EV GO to perform connector swaps</p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">S1-S3 SSAS Panel BBC Inhibits (16)</p> <p>A. RPCM S13A G RPC 01 – Open, Close Cmd Inhibit RPC 02 – Open, Close Cmd Inhibit RPC 13 – Open, Close Cmd Inhibit RPC 14 – Open, Close Cmd Inhibit RPC 15 – Open, Close Cmd Inhibit</p> <p>B. RPCM S12B A RPC 05 – Open, Close Cmd Inhibit RPC 11 – Open, Close Cmd Inhibit RPC 13 – Open, Close Cmd Inhibit</p> <p>C. RPCM S14B G RPC 01 – Open, Close Cmd Inhibit RPC 05 – Open, Close Cmd Inhibit RPC 13 – Open, Close Cmd Inhibit RPC 14 – Open, Close Cmd Inhibit RPC 15 – Open, Close Cmd Inhibit</p> <p>D. RPCM S11A A RPC 03 – Open, Close Cmd Inhibit RPC 04 – Open, Close Cmd Inhibit RPC 13 – Open, Close Cmd Inhibit</p> </div> <p>If BRT used on oval HR:</p> <ol style="list-style-type: none"> 3. Request EV3 to perform inspection of oval HR, after BRT is released  4. Receive inspection report from EV3 5. Request EV3 to perform glove check 6. Receive glove check report from EV3 	<p><u>SSAS BBC CONNECTOR SWAPS</u> (00:30)</p> <ol style="list-style-type: none"> 1. On IV GO: Demate caps/connectors and swap with terminator caps <p style="text-align: center;"><u>NOTE</u></p> <p>√Connectors for straight pins, no FOD, EMI band intact, and good bend radius</p> <p>If BRT on oval HR is required, inspect contact area prior to attaching the BRT and again after the BRT is released</p> <p><u>Panel A102 (zenith):</u></p> <ol style="list-style-type: none"> 2. <input type="checkbox"/> Remove cap from J195 3. <input type="checkbox"/> Demate P116 from J116 4. <input type="checkbox"/> Install cap on J116 5. <input type="checkbox"/> Inspect and Mate P116 to J195 6. <input type="checkbox"/> Check good bend radius <p><u>Panel A103 (nadir):</u></p> <ol style="list-style-type: none"> 7. <input type="checkbox"/> Remove cap from J196 8. <input type="checkbox"/> Demate P121 from J121 9. <input type="checkbox"/> Install cap on J121 10. <input type="checkbox"/> Inspect and Mate P121 to J196 <input type="checkbox"/> Check good bend radius 11. If BRT used on oval HR, inspect HR for change at contact area  12. Perform glove check. Report status to IV 13. Translate to S1 – S3 Fluid Jumper Task/worksite

EVA 3 S1/S3 FLUID QD JUMPER INSTALL (00:35)

IV	EV3 – Acaba (FF)
<ol style="list-style-type: none"> 1. Verify with MCC-H that TRRJ inhibits are in place for translation to S1/S3 worksite 2. Give GO to EV3 to translate to S1/S3 <div data-bbox="107 459 636 589" style="border: 1px solid black; background-color: #e0ffe0; padding: 5px;"> <p>DEMATE QD</p> <ol style="list-style-type: none"> 1. √Forward white band visible, button up 2. Demate QD (pull back on release ring) </div> <div data-bbox="107 605 636 914" style="border: 1px solid black; background-color: #e0ffff; padding: 5px;"> <p>MATE QD</p> <ol style="list-style-type: none"> 1. Inspect QDs for FOD or damage 2. √Detent button is up 3. √Forward white band is NOT visible 4. Assess side loads 5. Mate QD. √Forward white band is visible 6. Perform snap back test (√Fwd white band is visible) 7. Perform pull test 8. Perform gap check (visual) </div> <div data-bbox="107 930 636 1109" style="border: 1px solid black; background-color: #ffe0ff; padding: 5px;"> <p>OPEN VALVE</p> <ol style="list-style-type: none"> 1. Press button, move bail forward (open valve) 2. √Aft white band visible, button up 3. Verify detent button can be depressed </div> <ol style="list-style-type: none"> 3. Receive glove check from EV3 	<p><u>S1/S3 FLUID JUMPER INSTALL (00:35)</u></p> <div data-bbox="953 358 1488 492" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION</p> <p>QDs exposed to direct sunlight can overtemp in 20 min. Shading by EMU or thermal shroud can lengthen acceptable time with bootie removed</p> </div> <p>On IV GO:</p> <ol style="list-style-type: none"> 1. Translate to S1/S3 Face 6 (nadir) interface 2. Open shroud on S1 nadir umbilical tray 3. Release TA clamps, as reqd 4. For QDs F56, perform DEMATE QD steps in the IV column 5. Open thermal bootie and remove QD cap from M3 on S1 Panel A503. Stow cap in trash bag 6. Open thermal bootie and remove QD cap from M1 on S3 panel A501. Stow cap in trash bag 7. Attach RET to jumper 8. For QDs F57, perform DEMATE QD steps in the IV column 9. BRT to HR 3010 10. Perform MATE QD steps in IV column to mate QD F57 to M3 on S1 panel A503 11. For QD F57, perform OPEN VALVE steps in IV column 12. Perform MATE QD steps in IV column to mate QD F56 to M1 on S3 panel A501 13. For QD F56, perform OPEN VALVE steps in IV column 14. Reinstall thermal booties (2) 15. Close TA clamps, as reqd 16. Perform WVS survey of jumper connections 17. Replace S1 nadir umbilical tray shroud 18. Inspect EMU gloves/gauntlets. Report glove status to IV 19. Translate to S1 for FHRC P-Clamp Release

EVA 3 S1 FHRC P-CLAMP RELEASE (01:05)

IV		EV3 – Acaba (FF)		
<p>S1 FHRC P-Clamps: Bay 11 Stinger (6) – diagram on next page Bay 13 Hose Box (6) – diagram on next page</p> <ol style="list-style-type: none"> Request EV3 tool inventory Receive EV3 tool inventory report Request EV3 to perform glove inspection Receive EV3 glove inspection report <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p style="text-align: center;">Tool Inventory</p> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; vertical-align: top;"> <p><u>MWS</u></p> <input type="checkbox"/> Sm Trash bag <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> RET <input type="checkbox"/> Wire ties (2) <p><u>Swing Arm</u></p> <input type="checkbox"/> PGT <input type="checkbox"/> 6-in wobble ext <input type="checkbox"/> RET </td> <td style="width: 50%; vertical-align: top;"> <p><u>Crewlock Bag</u></p> <input type="checkbox"/> Ratchet wrench <input type="checkbox"/> 2-in socket ext <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> 18-in socket ext <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> EVA Camera <input type="checkbox"/> RET </td> </tr> </table> </div>	<p><u>MWS</u></p> <input type="checkbox"/> Sm Trash bag <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> RET <input type="checkbox"/> Wire ties (2) <p><u>Swing Arm</u></p> <input type="checkbox"/> PGT <input type="checkbox"/> 6-in wobble ext <input type="checkbox"/> RET	<p><u>Crewlock Bag</u></p> <input type="checkbox"/> Ratchet wrench <input type="checkbox"/> 2-in socket ext <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> 18-in socket ext <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> EVA Camera <input type="checkbox"/> RET		<p><u>RELEASE FHRC P-CLAMPS</u></p> <p><u>Stinger (Inboard)</u> (00:30)</p> <ol style="list-style-type: none"> Retrieve 18-in ext from Crewlock Bag #3 and install on PGT PGT [A7 9.2 ft-lb, CCW2 30 rpm, MTL 30.5] – 7/16-18-in ext: Release Stinger P-Clamps (6), any order, ~7-12.5 turns Stow 7/16-18-in ext in Crewlock Bag #3 Install 6-in extension on PGT Retrieve ratchet w/2-in from Crewlock Bag #3 to MWS <p><u>Hose Box (Outboard)</u> (00:25)</p> <ol style="list-style-type: none"> PGT [A7 9.2 ft-lb, CCW2 30 rpm, MTL 30.5] – 7/16-6-in ext: Release Hose Box P-clamps (6). Start at end furthest from QD, ~7-12.5 turns Perform tool inventory Stow EVA Camera in Crewlock Bag #3 Inspect gloves/gauntlets. Report glove status to IV Retrieve S1 Tasks Crewlock Bag #3 and attach to BRT <p><u>FHRC P-CLAMP CLEANUP</u> (00:10)</p> <ol style="list-style-type: none"> Translate to med ORU Bag (S0 Face 2) Stow S1 Tasks Crewlock Bag #3 at med ORU Bag location Retrieve S0 1A_D RPCM Crewlock Bag #4 Attach S0 RPCM Crewlock Bag #4 to BRT On MCC-H GO, translate to S0 outboard for S0 1A_D RPCM REMOVE/REPLACE
<p><u>MWS</u></p> <input type="checkbox"/> Sm Trash bag <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> RET <input type="checkbox"/> Wire ties (2) <p><u>Swing Arm</u></p> <input type="checkbox"/> PGT <input type="checkbox"/> 6-in wobble ext <input type="checkbox"/> RET	<p><u>Crewlock Bag</u></p> <input type="checkbox"/> Ratchet wrench <input type="checkbox"/> 2-in socket ext <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> 18-in socket ext <input type="checkbox"/> RET w/PIP pin <input type="checkbox"/> EVA Camera <input type="checkbox"/> RET			

EVA 3 S1 FHRC P-CLAMP RELEASE – TASK DATA

FHRC P-Clamps – Hose Box (Outboard)

Legend:
 ○ = P-Clamp Location
 ⊗ = TA Clamp (not released)

Hose Box

	P-Clamp	Tool	Socket
<input type="checkbox"/>	1	PGT	6-in ext
<input type="checkbox"/>	2	PGT	6-in ext
<input type="checkbox"/>	3	Ratchet	2-in ext
<input type="checkbox"/>	4	PGT	6-in ext
<input type="checkbox"/>	5	PGT	6-in ext
<input type="checkbox"/>	6	Ratchet	2-in ext

QD: M3/F169
 QD: M4/F168
 QD: M5/F167
 QD: M6/F166

FHRC P-Clamps – Stinger (Inboard)

Legend:
 ○ = P-Clamp Location
 ⊗ = P-Clamp (not released)


Stinger

	P-Clamp	Tool	Socket
<input type="checkbox"/>	1	PGT	6- or 18-in ext
<input type="checkbox"/>	2	PGT	6- or 18-in ext
<input type="checkbox"/>	3	PGT	6- or 18-in ext
<input type="checkbox"/>	4	PGT	6- or 18-in ext
<input type="checkbox"/>	*5	PGT	18-in ext
<input type="checkbox"/>	^6	PGT	6- or 18-in ext



QD: M1/F165
 QD: M2/F164
 Torque Box Assy

*18-in required for this bolt
 ^18-in doable w/difficulty


EVA 3 S0 1A_D RPCM REMOVE/REPLACE (00:45)

IV	EV3 – ACABA (FF)	
<p style="text-align: center;"><u>NOTE</u> CETA lights will be turned off due to DDCU power-down</p>	<div style="border: 1px solid black; padding: 5px; margin-bottom: 10px; text-align: center;"> <p><u>CAUTION</u> Avoid contact to SPDA Radiator (Face 3) to prevent hardware damage</p> </div> <ol style="list-style-type: none"> 1. Translate to S0 RPCM location (HR 3490) (with S0 1A_D RPCM Crewlock Bag #4) 2. Temp stow S0 1A_D RPCM Crewlock Bag #4. Translate to S0 HR 3490 3. Slide port door open but don't open fully to avoid detents from catching 4. BRT to S0 HR 3484 <div style="border: 3px double black; padding: 5px; margin-bottom: 10px; text-align: center;"> <p><u>WARNING</u> Edges of RPCM housing may be sharp. Use caution while handling</p> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Failure to align and fully seat socket until lock springs have released can result in damage to RPCM Drive Screw Assembly</p> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p>Combined linear and rotational motion on the socket while inserting, can result in damage to RPCM Drive Screw Assembly</p> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p>Failure to use wobble socket, or socket with equivalent outer diameter, to release I lock springs can result in damage to the RPCM Drive Screw Assembly</p> </div> <div style="border: 1px solid black; padding: 5px;"> <p>Do not operate drive screw with scoop attached to microconical. The wobble socket feature will not extend thru the round scoop</p> </div>	<p style="text-align: center;"><u>NOTE</u> Equipment Hook shown in correct orientation for R&R</p> <p>Gate away from RPCM</p> 

EVA 3 S0 1A_D RPCM REMOVE/REPLACE (00:45) (Cont)

IV	EV3 – ACABA (FF)	
<p>MCC-H:</p> <ol style="list-style-type: none"> 1. Verify S0 RPCM Inhibits in place (√DDCU S01A Converter – Off), give EV GO for removal 2. Record Failed RPCM s/n _____ (expect s/n C024088) 3. Record Spare RPCM s/n _____ (expect s/n C235299) 4. IV record S0 1A_D RPCM Drive Screw Installation Data Turns: _____ Torque: _____  5. Receive glove check report from EV2 	<p>On IV GO, perform the following RPCM R&R steps:</p> <ol style="list-style-type: none"> 5. Verify failed RPCM 1A_D is s/n C024088 6. Tether to RPCM with gate pointing away from RPCM 7. PGT [A6 8.3 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16 <input type="checkbox"/> Release Drive Screw, push while turning, ~8 turns 8. √Status Indicator – UNLOCK 9. Install scoop, as reqd 10. Remove failed RPCM (slide off rail) 11. Stow failed RPCM 12. Inspect guide rail for debris/damage 13. Retrieve spare RPCM 14. Verify spare RPCM s/n (expect C235299) 15. Verify proper hook orientation on new RPCM (gate away from RPCM) 16. Install RPCM on guide rail and slide into soft dock 17. √Status Indicator not below UNLOCK 18. PGT [A2 3.8 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16 <input type="checkbox"/> Fasten Drive Screw, push while turning, 6-7 turns to hard stop 19. √Status Indicator – LOCK 20. EV3 report torque and turns 21. Slide door closed, verify door does not slide freely and √alignment mark 22. Close S0 1A_D RPCM Crewlock Bag #4. Attach S0 1A_D Crewlock Bag #4 to BRT 23. Inspect gloves/gauntlets. Report glove status to IV 24. Translate to med ORU Bag (S0 HR 3528) 25. Stow S0 1A_D RPCM Crewlock Bag #4 in med ORU Bag <p>If EV3 performing P1 1A_A RPCM R&R:</p> <ol style="list-style-type: none"> 26. Go to P1 1A_A RPCM R&R 	<p style="text-align: center;"><u>NOTE</u> Equipment Hook shown in correct orientation for R&R</p> <p style="text-align: center;">Gate away from RPCM</p> 

EVA 3 S0 1A_D RPCM REMOVE/REPLACE – TASK DATA



EVA 3 S0 1A_D RPCM REMOVE/REPLACE – TASK DATA (Cont)

SPDA Radiator – No Contact
(Face 3)





Figure X



EVA 3 S0 1A_D RPCM REMOVE/REPLACE – TASK DATA (Cont)

Tools:

EV3
PGT
7/16 Socket-9 ext
Round scoop
Russian Tie-down tether

EVA Fasteners:

Fastener Name	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
RPCM Drive Screw	7/16	1	5.5 (gnd) 3.8 (orbit)	4.5	18.6 (remove) 8.5 (install)	8 (remove) 6-7 (install)	30
SPDA Door Bolts	7/16	2	7.08 (gnd)	8.3	14.27	13	30

EVA Connectors: None

ORU Identification:

	Part Number	Serial Number
Spare RPCM	R077419-61	C235299
Failed RPCM	R077419-61	C024088

Notes:

1. The round scoop is removed for bolt driving operations to allow for visual verification of socket engagement on the drive screw
2. Installation of tether on RPCM tether point must be oriented such that the hook is facing the body of the RPCM. Otherwise, interference between the SPDA frame and the RPCM will not allow hook removal

Cautions:

1. Failure to use wobble socket, or socket with equivalent outer diameter, to release lock springs can result in damage to the RPCM Drive Screw Assembly
2. Do not operate drive screw with scoop attached to microconical. The wobble socket feature will not extend thru the round scoop
3. Failure to align and fully seat socket until lock springs have released can result in damage to RPCM Drive Screw Assembly
4. Combined linear and rotational motion on the socket while inserting, can result in damage to RPCM Drive Screw Assembly
5. If worksite is left unattended at any time with just Bolt 7 and the tether tie down, the tether must be cinched snug


Warnings:

1. RPCM may have sharp edges; use caution while handling




RPCM Tether Orientation



EVA 3 P1 1A_A RPCM REMOVE/REPLACE (00:45)

IV	EV2/EV3 (FF)	
<p style="text-align: center;"><u>NOTE</u> CETA lights will be turned off due to DDCU power-down</p> <p>1. Verify with MCC-H: P1 RPCM Inhibits in place (√DDCU S01A Converter – Off)</p> <p style="text-align: center;">or</p> <p>RPCM S01A_A RPC 01 Open, Close Inhibited), then: IV give EV2 GO for RPCM R&R</p>	<div style="border: 2px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Edges of RPCM housing may be sharp, use caution while handling</p> <p>Maintain minimum 1 ft clearance from P1 antenna (radomes) during translation</p> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Failure to align and fully seat socket until lock springs have released can result in damage to RPCM Drive Screw Assembly</p> <p>Combined linear and rotational motion on the socket while inserting, can result in damage to RPCM Drive Screw Assembly</p> <p>Failure to use wobble socket, or socket with equivalent outer diameter, to release I lock springs can result in damage to the RPCM Drive Screw Assembly</p> <p>Do not operate drive screw with scoop attached to microconical. The wobble socket feature will not extend thru the round scoop</p> </div> <ol style="list-style-type: none"> 1. Translate to med ORU Bag at S0 3528, as reqd 2. Retrieve P1 1A_A Crewlock Bag #2 and stow on BRT 3. Translate to 55-ft Safety Tether at S0 3545 4. Perform Safety Tether swap to 55-ft Safety Tether: <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Safety Tether Reel unlocked <input type="checkbox"/> Remove 85-ft Safety Tether and stow on S0 HR 3545 5. Translate to P1 1A_A RPCM worksite (access via Fwd Face – zenith) 6. Stow P1 1A_A Crewlock Bag #2 on P1 HR 3680 7. Attach BRT to P1 HR 3672 	<p style="text-align: center;"><u>NOTE</u> Equipment Hook shown in correct orientation for R&R</p> <p>Gate away from RPCM</p> <div style="text-align: center;">  </div>


EVA 3 P1 1A_A RPCM REMOVE/REPLACE (00:45) (Cont)

IV	EV2/EV3 (FF)	
<p>2. IV record Failed RPCM s/n _____ (expect s/n C235300)</p> <p>3. IV record Spare RPCM s/n _____ (expect C326597)</p> <p>4. IV record RPCM Drive Screw installation data: Turns= _____ Torque= _____</p> <p style="text-align: center;"><u>NOTE</u> CETA lights may turn on after power-up</p> <p>5. If S0 1A_D RPCM R&R complete: On EV2 GO: Inform MCC-H,  EV2 clear GO for DDCU S01A Converter power-up and RPCM checkout(s), as reqd</p>	<p><u>REMOVE FAILED RPCM</u> On IV GO (inhibits complete), perform the following RPCM removal steps:</p> <ol style="list-style-type: none"> 8. Verify failed P1 A_A RPCM is s/n C235300 9. Tether to failed RPCM tether point with gate pointed away from RPCM 10. PGT [A6 8.3 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16: Release RPCM drive screw, push slightly while turning, ~8 turns 11. ✓Status indicator – UNLOCK 12. Remove failed RPCM (slide off of rail) 13. Use scoop, as reqd 14. Stow failed RPCM in P1 A_A Crewlock Bag #2 <p><u>INSTALL RPCM</u></p> <ol style="list-style-type: none"> 15. Inspect guide rail for debris/damage 16. Remove spare RPCM from P1 1A_A Crewlock Bag #2 (leave RET connected) 17. Report spare RPCM s/n (expect C326597) 18. Verify proper hook orientation on new RPCM (gate away from RPCM) 19. Install scoop, as reqd 20. Install RPCM on guide rail, and slide into soft dock 21. ✓Status indicator – not below UNLOCK 22. PGT [A2 3.8 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16: Fasten RPCM drive screw, push slightly while turning, 6-7 turns to hard stop 23. ✓Status indicator – LOCK 24. EV2 report torque and turns to IV 25. Stow PGT on swing arm 26. EV2 inform IV when clear of worksite. (DDCU S01A Converter power-up and RPCM checkout)  27. Retrieve P1 1A_A RPCM Crewlock Bag #2 Attach P1 1A_A Crewlock Bag #2 to BRT 	<p style="text-align: center;"><u>NOTE</u> Equipment Hook shown in correct orientation for R&R</p> <p>Gate away from RPCM</p> 

EVA 3 P1 1A_A RPCM REMOVE/REPLACE (00:45) (Cont)

IV	EV2/EV3 (FF)	
<p>6. Receive glove check report from EV2</p>	<p>28. Inspect gloves/gauntlets. Report glove status to IV</p> <p>29. Perform tool inventory</p> <p>30. Translate to airlock Safety Tether temp stow location (S0 HR 3545)</p> <p>31. Perform Safety Tether swap to airlock 85-ft Safety Tether:</p> <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Safety Tether Reel unlocked <input type="checkbox"/> Remove 55-ft Safety Tether and stow on MWS <p>32. Perform CLEANUP</p>	

EVA 3 P1 1A_A RPCM REMOVE/REPLACE – TASK DATA



EVA 3 P1 1A_A RPCM REMOVE/REPLACE – TASK DATA (Cont)

Table 1. Tools

EV2/EV3
PGT
7/16 (wobble) Socket-6 ext
Round scoop

Table 2. EVA Fasteners

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
RPCM Drive Screw		7/16	1	5.5 (grnd) 3.8 (orbit)	4.5	18.6 (remove) 8.5 (install)	8 (remove) 6-7 (install)	30

* Fastener torque data is derived from INC-9 S0 RPCM R&R task.
It will be necessary to reverify data prior to performing this task.

Table 3. ORU Identification

	Part Number	Serial Number
Spare RPCM	R077419-61	C326597
Failed RPCM	R077419-61	C235300

RPCM Tether Orientation



EVA 3 CLEANUP (00:50)

IV	EV2 – Arnold (FF)	EV3 – Acaba (FF)
<p>1. Inform EV2/EV3 to begin cold soak, as reqd</p>	<p><u>CLEANUP</u> (00:50)</p> <ol style="list-style-type: none"> 1. Retrieve LEE Lube Crewlock Bag #1 and attach to BRT (LEE Lube Crewlock Bag #1 near med ORU Bag) 2. Adjust TCV to begin cold soak, as reqd 3. Translate to Airlock 	<p><u>CLEANUP</u> (00:25)</p> <ol style="list-style-type: none"> 1. Open med ORU Bag and stow the following items: <ul style="list-style-type: none"> <input type="checkbox"/> P1 1A_A RPCM Crewlock Bag #2 <input type="checkbox"/> S0 1A_D RPCM Crewlock Bag #4 <input type="checkbox"/> S1 Tasks Crewlock Bag #3 in the med ORU Bag 2. Close med ORU Bag and attach to BRT 3. Adjust TCV to begin cold soak, as reqd 4. Translate to Airlock 5. Stow med ORU Bag at airlock

EVA 3 A/L INGRESS (00:30)

IV	EV2 – Arnold (FF)	EV3 – Acaba (FF)
<p>1. Perform prior to ingress: WVS PWRDN (PHOTO/TV, <u>WVS CUE CARD</u>)</p>	<p><u>INGRESS</u> (00:30)</p> <ol style="list-style-type: none"> 1. Transfer LEE Lube Crewlock Bag #1 to EV3 2. On EV3 GO: Attach right waist tether to EV3 Safety Tether hook 3. On EV3 GO: Release EV3 Safety Tether <ul style="list-style-type: none"> <input type="checkbox"/> <input type="checkbox"/> √Gate closed (both hooks) <input type="checkbox"/> <input type="checkbox"/> √Hook locked (both hooks) 4. Release EV2 Safety Tether 5. Perform final tool inventory 6. Ingress Airlock 7. Close thermal cover, attach Velcro strap 8. Remove SCU from stowage pouch 9. Remove DCM cover; Velcro to DCM 10. Connect SCU to DCM; √SCU locked 11. WATER – OFF (fwd) (expect H2O off msg) <div style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px auto; width: fit-content;"> <p>CAUTION Do not close hatch until WATER is OFF at least 2 min</p> </div> <p>When WATER – OFF for 2 min:</p> <ol style="list-style-type: none"> 12. Verify hatch clear of hardware 13. EV handle – verify handle posn per hatch decal: Close and lock EV hatch <ol style="list-style-type: none"> 14. Go to PRE REPRESS portion of {CREWLOCK DEPRESS/REPRESS CUE CARD} (SODF: ISS EVA SYS: EVA PREP/POST) 	<p><u>INGRESS</u> (00:30)</p> <ol style="list-style-type: none"> 1. Open thermal cover 2. Ingress Airlock 3. Stow med ORU Bag in Airlock 4. Receive LEE Lube Crewlock Bag #1 from EV2 Stow Crewlock Bag in airlock 5. Attach right waist tether to airlock D-ring extender <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked 6. Give EV2 GO to attach EV2 right waist tether to EV3 Safety Tether 7. Give EV2 GO to release EV3 Safety Tether 8. Perform final tool inventory 9. Remove SCU from stowage pouch 10. Remove DCM cover; Velcro to DCM 11. Connect SCU to DCM; √SCU locked 12. WATER – OFF (fwd) (expect H2O off msg) <ol style="list-style-type: none"> 13. Go to PRE REPRESS portion of {CREWLOCK DEPRESS/REPRESS CUE CARD} (SODF: ISS EVA SYS: EVA PREP/POST)

This Page Intentionally Blank

NOTES

NOTES

EVA 4 SUMMARY TIMELINE

PET HR : MIN	IV/SSRMS	15A EVA 4 EV1 – Swanson	EV2 – Arnold	PET HR : MIN
00:00		<u>EVA 4 POST DEPRESS & EGRESS (00:25)</u>	<u>EVA 4 POST DEPRESS & EGRESS (00:25)</u>	00:00
		<u>JLP GPS ANTENNA B INSTALL (01:00)</u>	<u>S1/P1 RADIATOR IMAGING (01:30)</u>	
01:00				01:00
		<u>Z1 PATCH PANEL (00:30)</u>		
02:00		<u>S3 TASK SETUP (00:30)</u>	<u>S3 TASK SETUP (00:30)</u>	02:00
		<u>CP1 WETA INSTALL (00:40)</u>	<u>CP1 WETA INSTALL (00:40)</u>	
03:00		<u>S3 OUTBOARD/NADIR PAS (01:15)</u>	<u>S3 OUTBOARD/NADIR PAS (01:15)</u>	03:00
04:00		<u>S3 INBOARD/ZENITH PAS (01:15)</u>	<u>S3 INBOARD/ZENITH PAS (01:15)</u>	04:00
05:00		<u>EVA 4 CLEANUP & INGRESS (00:40)</u> • Cleanup (00:25) • Ingress (00:15)	<u>EVA 4 CLEANUP & INGRESS (00:40)</u> • Cleanup (00:25) • Ingress (00:15)	05:00
06:00	EVA 4 PET = 06:20 hr	<u>PRE-REPRESS (00:05)</u>	<u>PRE-REPRESS (00:05)</u>	06:00
-06:20				-06:20

EVA 4 INHIBIT PAD

USOS (1)

ALL EVAs	
PCU	<p style="text-align: center;"><u>NOTE</u></p> <p style="text-align: center;">PCUs may require up to a 1-hr warmup period before they are operational</p> <p>MCC-H 1. √PCUs (two) operational in discharge mode and one of the following:</p> <ol style="list-style-type: none"> a. CCS PCU EVA hazard control FDIR enabled b. No more than two arrays unshunted and oriented < 105° from velocity vector <p>If one or both PCUs failed</p> <p>2. No more than two arrays unshunted and oriented < 105° from velocity vector</p>
LOCATION DEPENDENT INHIBITS	
Mobile Transporter	<p>MCC-H 1. √MT latched</p>
Lab Window {JLP GPS Ant}	<p>IV When EV crew less than 10 ft from window or in window FOV, close window shutter</p>
KU-Band (SGANT) Antenna {On call, EV crew not expected to be in this area}	<p>MCC-H If EV crew < 3.3 ft from KU-BAND antenna</p> <ol style="list-style-type: none"> 1. Park KU-BAND: <ol style="list-style-type: none"> 1.1 Pointing Mode – Inhibit 1.2 PLC – Reset 1.3 Autotrack Continuous Retry – Inhibit

USOS (2)

LOCATION DEPENDENT INHIBITS	
S-Band (SASA) Antennas {On call, EV crew not expected to be in this area}	<p>MCC-H If EV crew < 3.6 ft from S1 SASA [P1 SASA]</p> <ol style="list-style-type: none"> 1. P1 SASA (S1 SASA) – Active 2. S1 SASA [P1 SASA] – Powered down
SARJ {S1/P1 Radiator Imagery & S3 PAS Deploys} (Stbd SARJ)	<p>MCC-H When EV crew working within 2 ft or outboard of stbd SARJ, truss struts removed, or in APFR on PMA1</p> <ol style="list-style-type: none"> 1. √DLA (1) – LOCKED 2. All motor setpoints set to zero 3. All motors deselected
{S1/P1 Radiator Imagery} (Port SARJ)	<p>MCC-H When EV crew in APFR on PMA1</p> <ol style="list-style-type: none"> 1. √DLA (1) – LOCKED 2. All motor setpoints set to zero 3. All motors deselected
TRRJ {WETA & S3 PAS Deploys}	<p>MCC-H When EV crew working or safety tether within 2 ft of S1 TRRJ rotation envelope</p> <ol style="list-style-type: none"> 1. √DLA (1) – LOCKED at -115 to -60 or 60 to 115
SSPTS {On call, EV crew not expected to be in this area}	<p>MCC-H If EV crew working within 2 ft of SSPTS cables</p> <ol style="list-style-type: none"> 1. RPCM LA1A4A D RPC 3 – Open, Close Cmd Inhibit 2. RPCM LA2A3B D RPC 1 – Open, Close Cmd Inhibit 3. RPCM Z14B A RPC 2 – Open, Close Cmd Inhibit 4. RPCM Z13B A RPC 2 – Open, Close Cmd Inhibit

EVA 4 INHIBIT PAD (Cont)

TASK SPECIFIC INHIBITS

Z1 Patch Panel

- MCC-H**
1. RPCM Z13B RPC 18 – Open, Close Cmd Inhibit
 2. RPCM S02B D RPC 17 – Open, Close Cmd Inhibit

WETA Inhibits, to be performed prior to WETA installation:

- MCC-H**
1. RPCM S31A_A RPC 15 – Open, Close Cmd Inhibit
RPCM S31A_A RPC 16 – Open, Close Cmd Inhibit
 2. RPCM S32B_A RPC 15 – Open, Close Cmd Inhibit
RPCM S32B_A RPC 16 – Open, Close Cmd Inhibit

Orbiter

ALL EVAs

TCS

- L12 1. \sqrt TCS POWER – OFF

KU-BAND ANTENNA

- MCC-H**
1. \sqrt KU-BAND Mask – active
 2. \sqrt KU-BAND EVA Protect Box – active

Ground

ALL EVAs

Ground Radar

- MCC-H** 1. \sqrt TOPO console, ground radar restrictions in place for EVA

COL

EuTEF

- COL-CC Verify PLEGPAY Power Status (ETF_PLEGPAY_Pwr_Stat) – OFF

JEM

JEMRMS

{JLP GPS Ant}

- SSIPC When EV crew working within vicinity of JEMRMS
1. RIP MA Brake – On
 2. MDP Main Mode – Stby Mode
- or
1. JEMRMS Rack – OFF

JPM PROX Antenna

{JLP GPS Ant}

- SSIPC When EV crew working within 0.3 ft JPM PROX Antenna
1. \sqrt TRX Power – OFF
 2. \sqrt TX Power – OFF
- or
1. JPM PROX Antennas – OFF

JPM Windows

{JLP GPS Ant}

- IV When EV crew translating on JPM port end cone, close window shutters

JLP GPS Antenna Install, to be performed prior to opening MLI

- SSIPC
1. PDB A2 RPC4 – OPEN
 2. PDB B1 RPC5 – OPEN

EVA 4 INHIBIT PAD (Cont)

RSOS (1)

ALL EVAs	
SM Antennas IV	<ol style="list-style-type: none">1. GTS – Deactivate2. ARISS (Ham Radio) – Deactivate or VHF (144-146 MHz) TX only
EVAs ON PMA1 OR RSOS (LOCATION DEPENDENT)	
FGB Thrusters MCC-M	<ol style="list-style-type: none">1. √FGB MCS unpowered2. √All FGB Attitude Control Thruster Valves (eighty) – closed3. √FGB Attitude Control Manifold Valves – closed KШK1, KШK2, KШK4, KШK5, KШK9, OKO3, OKГ3, OKO6, OKГ6, OKO7, OKГ7, OKO8, OKГ8
Soyuz Thrusters MCC-M	<ol style="list-style-type: none">1. √Soyuz manifolds (four) – closed ЭKO1, ЭKO2, ЭKГ1, ЭKГ22. √Soyuz MCS unpowered3. √Soyuz Attitude Control Thruster Valves (fifty-two) – closed4. √Soyuz Main Engine Valves (K1, K2, K3, K4, K5, K6) – closed
FGB Antennas MCC-M	<ol style="list-style-type: none">1. √FGB KURS P [KYPC P] – Deactivated
Soyuz Antennas MCC-M	<ol style="list-style-type: none">1. √Soyuz KURS A [KYPC A] – Deactivated

EVA 4 NOTES, CAUTIONS, AND WARNINGS

NOTES

1. Bolt install: Report torque and turns
2. Bolt release: Report torque and turns (if different from published range)
3. EVA connectors: After dis-connection and prior to connection; verify pin and EMI band integrity. Verify connector free of FOD
4. Inspect Fluid QDs for damage, prior to mating
5. Toolbox doors must be closed with one latch per door, when EV crew not in immediate vicinity
6. Avoid contact with OBSS striker bars (Vitrolube coating)

CAUTION

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture shafts (drylube)
 2. PIP pins
 3. EVA Crane [PMA1]
 4. TCS Reflectors [PMA2,PMA3]
 5. APAS hardware [PMA2,PMA3]
 6. CETA Lights (Z-93 paint) [LAB,S1,Node 1]
 7. Deployed MISSEs [Columbus EPF]
 8. Passive UMAs
 9. MBS/SSRMS/SPDM/JEMRMS taped radiative surfaces: VDU, ACU, JEU, LEU, MCU, CRPCMs, and Cameras
 10. Deployed TUS cable [Nadir CETA rail]
 11. S0 aft face Radiator
 12. GPS Antennas (S13 paint) [S0,JLP]
 13. UHF Antennas [LAB,P1]
 14. ETCS Radiator flexhoses and panels [S1,P1]
 15. EETCS/PV Radiator flexhoses, bellows and panels [P6,P4,S4,S6]
 16. SASA RF Group [S1,P1]
 17. Heat pipe radiators [Z1]
 18. PCU cathode and HCA ports [Z1]
 19. Ku-Band Antenna (SGANT) dish [Z1]
 20. CMG cover/shells [Z1]
 21. SPDM SJEU, EP, OTCM, LEU, and LEE VDU Radiator surfaces
 22. Open CBM petal covers, LAB window shutter, and JPM window shutter
 23. FPMU [S1]
 24. OTSD
 25. COL HAM radio antennas [COL-Nadir]
 26. JTVE Cameras [JEM]
 27. JEM A/L Target and Pins
 28. S0/Node 2 Fluid Tray Hardlines at Node 2 end are limited to 25 lb

CAUTION (Cont)

ISS Constraints (Cont)

- B. Electrical cables
1. Avoid bend radii < 10 times cable diameter
- C. Fiber optic cables
1. Avoid bend radii < 10 times cable diameter
 2. Avoid pulling on cable during mate/demate
- D. Fluid line flex hoses and QDs
1. Avoid bend radii < 5 in for hoses with diameter < 1 in on LAB, S0, S1, P1, and 10-in for hoses with diameter < 1 in on all other elements
 2. Avoid bend radii < 14 in for hoses with a diameter ≥ 1 in
 3. Additional care should be taken to not exceed bend radii when applying loads at the flexible hose to rigid tube stub interfaces
 4. Ensure fluid QD booties are fully closed prior to leaving worksite; wire tie if reqd
- E. For structural reasons
1. Avoid vigorous body motions, quick grabs and kickoffs against tether restraints
 2. Avoid performing shaking motions (sinusoidal functions) more than four cycles
 3. Avoid kicking S1/P1 radiator beam
If any of these occur, wait 2 to 5 min to allow structural response to dissipate

EVA 4 NOTES, CAUTIONS, AND WARNINGS (Cont)

CAUTION (Cont)

ISS Constraints (Cont)

F. Other

1. ITT Cannon connector: On demated connectors, do not rotate collar or manipulate cable/connector using collar or connector tool
2. **WIS Antennas: Do not use as handholds [Node 1,P6,Z1]**
3. Lubricant from Ku-Band SGANT gimbals [Z1], CMGs [Z1], and RTAS Ground Strap fasteners [P6,P4,S4] can contaminate EMU
4. **MLI handholds are not rated for crewmember translation loads**
5. CBM petal covers may not be used as handholds unless both launch restraint pins are engaged
6. Prevent inadvertent contact of the tether shuttle with ETRS when the P3/S3 Tether Shuttle Stop is raised away from the rail

CAUTION (Cont)

Shuttle Constraints

A. Avoid inadvertent contact with

1. OBSS and SRMS Composite Sections, Joint Torque Arms, Grapple Fixture Shafts, and Cable Harnesses
2. LCS (silver Teflon) and LDRI (silver Teflon) and ITVC (gold foil) [OBSS]
3. WVS Antenna [ODS Truss & PLB Sill]
4. Payload Bay and Camera wire harnesses, cables, cable guides, and connectors

B. No touch

1. LDRI diffuser [OBSS]
2. OBSS saddle contacts (when OBSS unberthed) [OBSS]
3. Monkey fur [PLB]
4. Cameras: Metallic surfaces [PLB]
5. Ku-Band Antenna black dish and gold thermal blankets [PLB]

EVA 4 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture targets and target pins
 2. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off
 3. Stay inboard of SARJ when active
 4. Stay 2 ft from S1/P1 radiator beam rotational envelope when beam is free to rotate
 5. Stay 5 ft from moving MT on face 1
 6. SOLAR and EuTEF [COL EPF]
- B. Handrails
1. Handrails previously used for MISSE attachment may not be used as a safety tether point [A/L endcone 564 & 566, A/L Tank 2 nad/fwd & port/fwd,P6 5389]
- C. Pinch
1. NZGL connector linkage. Use caution when mating/locking
 2. ITT Cannon Connector rotating housing
 3. EV side of IV Hatch during Hatch operation (also snag hazard) [A/L]
 4. LAB window shutter and CBM petal cover and JPM window shutter linkages during operation
 5. JEMRMS HRM capture latches
 6. JEM Cameras (JTVEs,EVE,WVE)
 7. JEM EFBM capture latches
- D. QDs
1. If QD is in FID when valve is opened (bail fwd), QD will leak and fluid line may whip
 2. Do not rotate if in mated/valve open config

WARNING (Cont)

ISS Constraints (Cont)

- E. RF radiation exposure
1. Stay 3.6 ft from S-Band (SASA) high gain Antenna when powered [S1,P1]
 2. Stay 1.3 ft from S-Band (SASA) low gain Antenna when powered [S1,P1]
 3. Stay 1 ft from UHF Antenna when powered [LAB,P1]
 4. Stay 0.3 ft from fwd/aft JPM PROX antenna
- F. Sharp Edges
1. Inner edges of WIF sockets
 2. APFR active WIF probes
 3. Mating surfaces of EVA connectors
Avoid side loads during connector mating
 4. Back side of MMOD shield fasteners
 5. Spring loaded captive EVA fasteners (e.g., 6B-boxes, BMRRM, RTAS, SARJ Covers); the end of the spring may protrude
 6. PMA umbilical launch restraints-exposed bolt threads
 7. Adjustable Fuse Tether (Fish Stringer) buckles stowed in Node Bag
 8. Nickel coated braided copper Ground Straps may contain frayed wires [P6,P4,S4,S6]
 9. SPDM OTCM gripper jaws

WARNING (Cont)

ISS Constraints (Cont)

- F. Sharp Edges (Cont)
10. Solar Array Blanket Box [P6,S6]
 11. Keep hands away from SSRMS LEE/POA/SPDM LEE/JEMRMS EE opening, snares, and PDGF curvic coupling (teeth)
 12. Fastener threads on back of Z1 U-jumper male FQD panel, if nutplate cap missing
 13. Outboard MT rail attachment lug near P6 handrail 5333 and gap spanner
 14. P2 connector on EWIS box TAA-06 [Zenith/Forward Corner 1 of P5 – SARJ at 0 deg]
 15. Port/Aft portion of A/L circular HR [HR 0506]
 16. Interior of JEMRMS HRMs
 17. JEM A/L hatch corners
- G. Thermal
1. EVA connectors with booties may become hot if left uncovered. Handling may need to be limited
 2. PMA handrails may be hot. Handling may need to be limited
 3. Turn off glove heaters when comfortable temp reached to prevent bladder damage. Do not pull fingers out of gloves when heaters are on
 4. Uncovered trunnion pins may be hot
 5. SSRMS/MBS/SPDM/JEMRMS/JTVE operating cameras and lights may radiate large amounts of heat

EVA 4 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING (Cont)

ISS Constraints (Cont)

G. Thermal (Cont)

6. Stay ≥ 1 ft away from PMAs and MMOD shields > 270 degF if EMU sun visor up; limit time to 15 min or less if > 300 degF
7. Stay at least 0.5 ft away from PMA and MMOD shields > 325 degF
8. Do not touch EMU protective visor if temp has been < -134 degF for > 15 min
9. No EMU TMG contact with PMAs and MMOD shields > 320 degF
10. No EMU boot contact with foot restraint when temp < -120 degF or > 200 degF
11. Columbus end cones may violate touch temperature constraints when $-75 \leq \beta \leq -60$ or $60 \leq \beta \leq 75$
12. PDGF surfaces may not meet touch temperature requirements for unlimited contact when $\beta \leq -70$ or $\beta \geq 70$
13. JPM port end cones and JLP port nadir may violate touch temperature constraints when $\beta > 60$ deg

WARNING (Cont)

ISS Constraints (Cont)

H. Electrical Shock

1. Stay ≥ 2 ft from ungrounded floating connectors if not unpowered
 - SSPTS connectors include NOD1 Stbd/Fwd HR 0130, Lab Stbd/Fwd HR 0273, PMA2 Stbd and Port
 - MBS Cross-Connect jumpers (translate past these using UMA handrails) Include S0 EVA Power Cables (inside S0 Bay 00 Face 4, Bay 01 Face 3) ESP2 jumper (inside S0 Bay 03 Face 4)
2. Do not touch SPDM CLPA 1 electrical connector prior to camera installation

WARNING (Cont)

Shuttle Constraints

A. Arcing/Molten Debris

1. Stay ≥ 2 ft from exposed EFGF connector when OBSS berthed, powered, and EFGF not grappled [PLB]
2. Stay ≥ 2 ft from exposed Stbd Fwd MPM contacts [PLB]
3. Stay above PLB sill when within 1 ft of powered ROEU connector [PLB]

B. Pinch

1. PRLA operation [PLB]

C. RF radiation exposure

1. Stay 3.28 ft from S-Band Antenna when powered
2. Stay 1 ft from top and side of UHF PLB Antenna radome surface when in high powered mode [ODS truss]
3. Stay 0.33 ft from top and side of UHF PLB Antenna radome surface when in low powered mode [ODS truss]
4. Remain below the level of the PLB door mold line for first 20 in Aft of Fwd bulkhead when S-Band Antenna powered [PLB]
5. Remain on the inboard side of the Stbd slidewire (sill handrails if slidewire not installed) for first 20 ft Aft of Fwd bulkhead when Ku-Band Antenna powered [PLB]

EVA 4 NOTES, CAUTIONS, AND WARNINGS (Cont)

WARNING (Cont)

Shuttle Constraints (Cont)

D. Sharp Edges

1. PRLA grounding wipers [PLB]
2. LDRI baffles (also an entrapment hazard) [OBSS]
3. Keep hands away from SRMS EE opening and snares
4. TCS connector backshells have exposed threads [ODS]

E. Thermal

1. Illuminated PLB lights; do not touch
2. OBSS grapple fixture shafts/cams may be hot. Limit handling if required
3. Stay 27 ft from PRCS when powered
4. Stay 3 ft from VRCS when powered
5. Stay 3 ft from APU when operating

F. Contamination

1. Stay out of the immediate vicinity of leaking jet or APU

G. Lasers

1. Do not look at LDRI diffuser or LCS laser aperture window

EVA 4 TOOL CONFIG

EV1

EMU D-rings

- Ext on left side
- Ext on right side
- Waist Tether [right D-ring extender]
- 85-ft Safety Tether [right D-ring extender]
- 85-ft Safety Tether [MWS]

MWS

- Small Trash Bag
 - Adj tether s/n _____
- 2 – Wire ties as tether loops
- RET (w/PIP pin)
- RET (sm-sm)
- Adj Tether
- RET (sm-sm) (WETA MLI)

- Swing Arm (right side)
 - PGT w/6-in ext s/n _____
 - RET (sm-sm)

- BRT (left side)
 - RET (sm-sm)
 - 2 – Wire ties

- SAFER

NOTE: Prior to use, inspect the following hardware:

- RET cords for fraying
- Safety Tether & Waist Tether load alleviating straps: No red visible
- Sm Trash Bag: Bristle deformation/damage, after stowing tools in trash bag

Use Blue RETs Only

Tether Count:	(used)	(total) ISS qty
RET (sm-sm)	11	16
RET (w/PIP pin)	2	5
RET (Lg-sm)	4	8
Adj Tethers (sm-sm)	7	10
Adj Tethers (Lg-sm)	0	2
D-ring Extenders	5	6

EV2

EMU D-rings

- Ext on left side
- Ext on right side
- Waist Tether [right D-ring extender]
- 85-ft Safety Tether [right D-ring extender]

MWS

- Small Trash Bag [left inside]
 - Adj tether
 - Gap Spanner, 72-in
 - Adj tether
- Small Trash Bag [right inside]
- 2 – Wire ties as tether loops
- RET (w/PIP pin)
- RET (sm-sm)

- Swing Arm (right side)
 - PGT w/6-in ext s/n _____
 - EVA Camera w/bracket & 50mm lens
 - RET (sm-sm)

- BRT (left side)
 - RET (sm-sm)
 - 2 – Wire ties

- SAFER

CREWLOCK

- RET (Lg-sm)
- IR Camera w/EHIP Bat

NOTE

Prior to egress, turn IR camera Master Switch ON. Wait until LED on back of camera is solid green (~45 sec). Hold enable switch UP for 5 sec, verify LED – OFF. Cover Master Switch with Kapton Tape.

Remove IVA covers from JLP GPS Antenna and WETA shown in section 18

Bag Color Key: 119 EVA Tools, Staging, Crewlock MWS

CREWLOCK (Cont)

- Tether Ext on A/L D-ring

 - RET (Lg-sm)
 - Med ORU Bag
 - Adj Tether (outside – tie down)
 - Adj Tether (outside – tie down)
 - 55-ft Safety Tether
 - RET (sm-sm) (to inside tether point)
 - Round Scoop
 - JLP GPS Antenna B
 - Fish Stringer
 - 2 – Connector Caps (GPS Ant)
 - 2 – Connector Caps (JLP)
 - MLI (JLP GPS)
 - Long Wiretie
-
- RET (Lg-sm)
 - Crewlock bag #3
 - Adj Tether (outside – tie down)
 - Dummy Box (WETA) (Int RET #1)
 - Round Scoop (WETA) (Int RET #2)
 - Adj Tether (Int RET #3)
 - MLI (WETA)
 - EVA Camera w/bracket & 28mm lens
 - RET (sm-sm)
-
- RET (Lg-sm) on Scoop
 - WETA (with MLI)
 - RET (sm-sm) on opposite tether point (right side when looking at Scoop)
 - Round Scoop
-
- RET (sm-sm) (On UIA D-ring)
 - PGT w/6-in ext
 - EVA Camera w/bracket & 50mm lens
-
- RET (sm-sm) (On UIA D-ring)
 - BRS Pin Tool w/Sheath

EVA 4 TOOL CONFIG (Cont)

CREWLOCK (Cont)

Staging Bag

- Fish Stringer #1
 - Wire Tie Caddy (hook #1)
 - 9 wire ties
 - Velcro/Tape Caddy (hook #2)
 - PGT (hook #3) s/n _____
 - PGT Battery s/n _____
 - 7/16-in (wobble) Socket – 6 ext
 - Vise Grips (hook #4)
 - Ratchet Wrench (hook #5)
 - 7/16-in (rigid) Socket – 9 ext
 - Cheater Bar (hook #6)
 - EVA Hammer (hook #7)
 - 55-ft Safety Tether (to strap)
- Fish Stringer #2
 - Connector Cleaner Tool Kit (Hook #1)
 - Pin Straightener Tool (Hook #2)
 - Probe (Hook #3)
 - Prybar (Hook #4)
 - Needle Nose Pliers (Hook #5)**
 - Torque Wrench w/bag (set to 31) (Hook #6)
 - Right Angle Drive (Hook #7)
 - Long-Duration Tie-Down Tether (to strap)
 - Long-Duration Tie-Down Tether (to strap)
 - MWS Key Strap Assy (on Wire Tie to strap)
- RET (Lg-sm)
 - Sm ORU Bag
 - Fish Stringer #3
 - Cnctr Insulating Sleeve Size 21/25 (Hook #1)
 - Cnctr Insulating Sleeve Size 21/25 (Hook #2)
 - Cnctr Insulating Sleeve Size 21/25 (Hook #3)
 - Cnctr Insulating Sleeve Size 21/25 (Hook #4)
 - Cnctr Insulating Sleeve Size 33/37 (Hook #5)
 - Cnctr Insulating Sleeve Size 33/37 (Hook #6)

CREWLOCK (Cont)

IV Bag

- 2 – Towel
- Contamination Detection Kit
- 2 – GP Caddy
 - Thermal Mittens (1 pair)
- RET (sm-sm) (Black)
 - Socket Caddy
 - 1/2-in (wobble) Socket – 8 ext
 - 7/16-in (wobble) Socket – 6 ext
- 2 – DCM Plug (SAFER Hardmount)
- 2 – RET (sm-sm, black)

- JLP GPS Antenna
 - Potential sharp edge exists on underside of GPS Antenna bracket
 - The plate nut retainers have sharp edges that have been taped over with Glass Tape P213 (BETA Cloth Tape)

- Review PGT ops
 - Report “green light” (for torque down ops)
 - Report torque and turns
 - Expect LOTORQ fault msg, Fault LED and Red LED for bolt release ops

EQUIPMENT LOCK

Crewlock Bag #1

- Empty

Crewlock Bag #2

- Failed RPCM (Int RET #1)

Crewlock Bag #4

- Failed RPCM (Int RET #1)

Mesh Bag #1 (119 EVA Tools)

- Ziplock w/Grease Gun Caps

Mesh Bag #2 (Done Tools)


- 5/8-7.8-in extension
- 5/8-7.8-in extension
- Round TM w/5/8-in Prd Socket
- Socket Caddy
- Torque Wrench bag
- Cannon Connector Tool
- Cannon Connector Tool
- Ratchet Wrench
 - 7/16-2-in rigid ext
- Cnctr Insulating Sleeve Size 33/37
- SPDM EP1 Cover**
- RCC Gap Gauge**
- WIF Adapter**
- Ziplock w/used EVA Wipes (4) & Wire Ties**
- Ziplock w/Grease Gun, Wipe, & Wire Tie**
- 7/16-18-in ext**

Mesh Bag #3 (Transfer to Shuttle)

- Locking Strut Aid
- Locking Strut Aid
- Locking Strut Aid
- Locking Strut Aid
- Torque Wrench (s/n 1007)

Bag Color Key: **119 EVA Tools**, **Staging**, **Crewlock** **MWS**




EVA 4 A/L EGRESS (00:20)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
 <div data-bbox="136 714 703 852" style="border: 1px solid black; padding: 5px;"> <p>2 – 85-ft A/L tether – EV1 > EMU 1 – 85-ft A/L tether – EV2 1 – 55-ft tether – EV1 Med ORU Bag</p> </div> <p style="text-align: center;"><u>NOTE</u> Sunrise/Sunset checks</p> <ul style="list-style-type: none"> • √Helmet lts, visor, as reqd • √Gloves • √Tool, MWS tethers • √MWS, BRT latches <p>IR Camera Warmup start: _____</p>	<p><u>INITIAL CONFIG</u></p> <p>Verify:</p> <ul style="list-style-type: none"> <input type="checkbox"/> EV1 right waist tether connected to EV2's 85-ft safety tether <input checked="" type="checkbox"/> √Gate closed (both hooks) <input checked="" type="checkbox"/> √Hook locked (both hooks) <p><u>EGRESS</u></p> <ol style="list-style-type: none"> 1. Open hatch thermal cover 2. Egress crewlock 3. Attach EV1 safety tether to fwd A/L D-ring <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked 4. Fairlead safety tether as reqd 5. Attach EV2s safety tether anchor end to aft A/L D-ring <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> Release EV1 waist tether 6. Give EV2 GO to release waist tether 7. Receive Med ORU bag and place on BRT 8. As EV2 egresses monitor IR camera clearance 	<p><u>INITIAL CONFIG</u></p> <p>Verify:</p> <ul style="list-style-type: none"> <input type="checkbox"/> EV2 right waist tether connected to Airlock D-ring extender <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked <p><u>EGRESS</u></p> <ol style="list-style-type: none"> 1. On EV1 GO, release waist tether from A/L D-ring 2. Hand Med ORU bag to EV1, Leave RET on A/L D-ring ext <p style="text-align: center;"><u>NOTE</u> IR Camera requires 5-min warm up after power up and prior to use</p> <ol style="list-style-type: none"> 3. √sw MASTER – ON, √LED – OFF 4. Press and release ENABLE switch to initiate camera warmup (IV start 5-min timer), √LED – ON 5. Place IR camera on BRT 6. Egress crewlock


EVA 4 A/L EGRESS (00:20) (Cont)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
<p>1. Post crew egress: WVS Software: Select page – RF Camera sel 'Advanced controls' S-Band level (two) – max (Required after A/L egress)</p>	<p>9. Verify EV2 SAFER Configuration: <input type="checkbox"/> √R Handle down (HCM door – Closed) <input type="checkbox"/> √L Handle down (MAN ISO Valve – Open)</p> <p>10. Translate to JEM HR 1111 for tether swap</p>	<p>7. Verify EV1 SAFER Configuration: <input type="checkbox"/> √R Handle down (HCM door – Closed) <input type="checkbox"/> √L Handle down (MAN ISO Valve – Open)</p> <p>8. Close hatch thermal cover</p> <p>9. Translate to PMA1 WIF 2</p>


EVA 4 S1/P1 RADIATOR IMAGING (01:30)

IV	EV2 – Arnold (FF)																
<table border="1" data-bbox="94 337 571 483"> <thead> <tr> <th>Radiator Side</th> <th>IR</th> <th>Digital</th> </tr> </thead> <tbody> <tr> <td>S1 RBVM</td> <td></td> <td></td> </tr> <tr> <td>S1 Non-RBVM</td> <td></td> <td></td> </tr> <tr> <td>P1 RBVM</td> <td></td> <td></td> </tr> <tr> <td>P1 Non-RBVM</td> <td></td> <td></td> </tr> </tbody> </table>   <p data-bbox="147 1169 504 1218">Panel numbers and movie sequence (pause 2-3 sec on each panel)</p> <p data-bbox="94 1274 504 1307">1. Give MCC-H GO for TRRJ rotation</p>	Radiator Side	IR	Digital	S1 RBVM			S1 Non-RBVM			P1 RBVM			P1 Non-RBVM			<p data-bbox="976 300 1050 324" style="text-align: center;"><u>NOTE</u></p> <p data-bbox="682 324 1333 349">IR Camera is set to auto stop a movie after 150 frames (75 sec).</p> <p data-bbox="682 373 1218 397">Each row of 8 panels should be roughly 50 frames</p> <ol data-bbox="609 430 1417 1412" style="list-style-type: none"> RET to APFR in PMA1 WIF2 Reconfigure APFR [6,KK,F,6] for S1 or [6,KK,F,12] for P1 <ul style="list-style-type: none"> <input type="checkbox"/> √Bik-Bik pull/twist test Ingress APFR; use Tool Stanchion as reqd (yaw handle) Lower MWS and position IR camera with BRT as reqd Remove camera lens cover <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Set camera focus on middle radiator panels 4 and 5 using arrow keys (can be done during warm up): <ol style="list-style-type: none"> a. Right arrow Course Focus (+) b. Left arrow Course Focus (-) c. Up arrow Fine Focus (+) d. Down arrow Fine Focus (-) Verify with IV 5-min camera warmup complete <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Perform Flat Field correction (Press and release F A button) <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Record 150-frame/75 sec movie of radiator: <ol style="list-style-type: none"> a. Press and release the S T button to start the movie b. Start with zenith radiator panels 1-8, then middle radiator panels 8-1, and finally nadir radiator panels 1-8 c. Pause for 2-3 sec centered on each radiator panel d. The movie will auto stop after 150 frames, or if complete with all panels prior to 150 frames press and release the S T button to stop the movie <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Transfer movie to flash card. (Press and hold S T button for 3 sec. Expect 75 sec to complete the transfer) Close lens cover <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> If daylight present, map radiators with EVA camera (15-20 photos per radiator set). (Take digital photos of radiator damage during rotation) Give IV GO for TRRJ rotation Repeat steps 5-13 for both sides of S1 and P1 radiators; yaw APFR [6,KK,F,6] for S1 or [6,KK,F,12] for P1 and Tool Stanchion as reqd 	 <p data-bbox="1669 1266 1753 1291" style="text-align: center;"><u>NOTE</u></p> <p data-bbox="1522 1291 1900 1372">Press and release for top function. Press and hold ~3 sec for bottom function</p>
Radiator Side	IR	Digital															
S1 RBVM																	
S1 Non-RBVM																	
P1 RBVM																	
P1 Non-RBVM																	



EVA 4 S1/P1 RADIATOR IMAGING (01:30) (Cont)

IV	EV2 – Arnold (FF)	
<p>2. Inform MCC-H EV crew ready for Port SARJ rotation</p>	<p>When complete with all IR imagery of both S1 and P1 radiators:</p> <ol style="list-style-type: none"> 15. Press and hold ENABLE switch for 5 sec to put IR Camera in Standby mode (display reads 'Shutting down...' and LED-OFF) 16. Close lens cover and LCD cover 17. Adjust BRT and MWS as reqd 18. Configure APFR [12,KK,F,6] (Original Settings) <ul style="list-style-type: none"> <input type="checkbox"/> √Blk-Blk pull/twist test 19. Check gloves 20. Inform IV when ready for Port SARJ rotation (after APFR Egress) 21. Translate to A/L 	 <p>The diagram shows a vertical assembly with several components labeled: <ul style="list-style-type: none"> TOOL BOARD LATCH ASSEMBLY: Located at the top left of the main structure. ORU TETHER: A line extending from the top assembly. TILT/ROTATE OVER CENTER LEVERS: Two levers on the left side of the upper assembly. HOOP BRACKET: A horizontal bracket at the top right. BAYONET FITTING RECEPTACLES (4 REQUIRED): Four receptacles on the right side of the upper assembly. HANDLING/INSTALLATION AID: A component on the vertical shaft. ARTICULATING PORTABLE FOOT RESTRAINT (APFR) INTERFACE: The bottom-most component. Dimensions are indicated: <ul style="list-style-type: none"> (28.50) a: Horizontal distance from the center of the tool board to the right edge of the hoop bracket. (64.11) b: Total vertical height of the assembly from the top of the hoop bracket to the bottom of the APFR interface. (20.00) c: Horizontal distance from the center of the APFR interface to the right edge of the hoop bracket. </p>

EVA 4 JLP GPS ANTENNA INSTALL (01:00)


IV	EV1 – Swanson (FF)
	<p>SETUP</p> <ol style="list-style-type: none"> Perform safety tether swap to 85-ft safety tether at JEM HR 1111 <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked Stow A/L safety tether on JEM HR 1111 <ul style="list-style-type: none"> <input type="checkbox"/> √Reel unlocked <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">CAUTION</p> <p style="text-align: center;">Avoid inadvertent contact with JEM airlock target and pins</p> </div> <div style="border: 3px double black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">WARNING</p> <p style="text-align: center;">Avoid inadvertent contact with JEM cameras and booms (Thermal & Pinch)</p> <p style="text-align: center;">JEM airlock hatch corners may be sharp</p> <p style="text-align: center;">Interior of JEMRMS HRMs may be sharp</p> <p style="text-align: center;">JEM EFBM capture latches are potential pinch points</p> </div> <ol style="list-style-type: none"> Translate to JEM port end cone Fairlead safety tether around JEM camera and boom If 55-ft safety tether used, perform safety tether swap to 55-ft safety tether at JLP HR _____, if reqd <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked If 55-ft safety tether used, stow 85-ft safety tether on JLP HR _____, if reqd <ul style="list-style-type: none"> <input type="checkbox"/> √Reel unlocked Look for JLP HR 1227 or HR 1228 and head zenith Fairlead Safety Tether out to center of JLP <p>GPS ANTENNA INSTALL</p> <ol style="list-style-type: none"> Stow Med ORU Bag with Adj tethers on JLP HR 1271 & 1272 with the lid on 1275 & 1276 Stow Fish Stringer between ORU bag and JLP HR 1274 Check gloves <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">CAUTION</p> <p style="text-align: center;">Avoid inadvertent contact with GPS Antenna (paint)</p> </div> <ol style="list-style-type: none"> BRT to JLP HR 1270 and attach MWS EE to 1274 Remove MLI cover for GPS Antenna B (stbd); stow on Fish Stringer Install GPS Antenna B onto dovetail; perform pull test Remove round scoop and stow in ORU bag

EVA 4 JLP GPS ANTENNA INSTALL (01:00) (Cont)


IV	EV1 – Swanson (FF)
<p>1. Verify with MCC-H JEM PROX GPS Antennas Inhibit Pad complete</p> <p style="padding-left: 40px;"><u>Med ORU Bag Inventory</u></p> <ul style="list-style-type: none"> <input type="checkbox"/> (2) – Adj Tethers <input type="checkbox"/> RET (sm-sm) <ul style="list-style-type: none"> <input type="checkbox"/> Round Scoop <input type="checkbox"/> 55-ft Safety Tether <input type="checkbox"/> Fish Stringer <ul style="list-style-type: none"> <input type="checkbox"/> (2) – Connector Caps (GPS Ant) <input type="checkbox"/> (2) – Connector Caps (JLP) <input type="checkbox"/> MLI (JLP GPS) <input type="checkbox"/> Long Wiretie 	<p>16. On IV GO: Open GPS Antenna connector MLI covers on JLP</p> <p>17. Remove dust caps (2) from JLP and stow on Fish Stringer</p> <p style="text-align: center;"><u>NOTE</u> √No FOD, No bent pins, Good EMI band</p> <p>18. Remove P7401 dust cap from cable; stow on Fish Stringer (wire tie is connected to a cap)</p> <p>19. Inspect and Mate connectors: <input type="checkbox"/> P7401→ ←J7401 (aft)</p> <p>20. Reattach MLI covers to P7401 grounding Velcro; black on black (cable to cover)</p> <p>21. Remove P7402 dust cap from cable; stow on Fish Stringer (wire tie is connected to a cap)</p> <p>22. Inspect and Mate connectors: <input type="checkbox"/> P7402→ ←J7402 (fwd)</p> <p>23. Reattach MLI covers to P7402 grounding Velcro; black on black (cable to cover)</p> <p>24.  WVS Survey of GPS Antenna B</p> <p>25. Give MCC-H GO to checkout GPS Antenna</p> <p>26. Perform tool inventory</p> <p>27. Stow Fish Stringer in Med ORU Bag</p> <p>28. Place Med ORU Bag on BRT</p> <p>29. If 55-ft safety tether used, perform safety tether swap to 85-ft safety tether at JLP HR _____, if reqd</p> <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked <p>30. If 55-ft safety tether used, stow 55-ft tether on Med ORU Bag, if reqd</p> <p>31. Translate to JEM HR 1111</p> <p>32. Perform safety tether swap to A/L safety tether at JEM HR 1111</p> <ul style="list-style-type: none"> <input type="checkbox"/> √Gate closed <input type="checkbox"/> √Hook locked <input type="checkbox"/> √Reel unlocked <p>33. Stow 85-ft tether on MWS</p> <p>34. Translate to A/L</p> <p>35. Open A/L thermal cover</p> <p>36. Stow spare 85-ft Safety Tether on Med ORU bag</p> <p>37. Stow Med ORU bag in A/L</p> <p>38. Retrieve BRS Pin Tool</p> <p>39. Close A/L thermal cover</p>

EVA 4 Z1 PATCH PANEL (00:30)

IV	EV1 – Swanson (FF)
<p>1. √MCC-H: Patch panel inhibits in place: √RPCM Z13B RPC 18 – Open, close cmd inh √RPCM S02B D RPC 17 – Open, close cmd inh</p> <p>2. Give EV GO for patch panel reconfig</p> <p>APFR Setting if reqd: Z1 WIF 04 [10,PP,B,12]</p> <p>Contingency Tool if reqd: Compound Cutters – Port A/L Toolbox Slot 1 behind Zenith door</p>	<ol style="list-style-type: none"> Verify EV1 SAFER Configuration: <ul style="list-style-type: none"> <input type="checkbox"/> √R Handle down (HCM door – Closed) <input type="checkbox"/> √L Handle down (MAN ISO Valve – Open) Check gloves Translate to Z1 Patch Panel <div data-bbox="730 444 1278 521" style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">CAUTION</p> <p style="text-align: center;">Avoid inadvertent contact with heat pipe radiators</p> </div> <p style="text-align: center;">NOTE</p> <p style="text-align: center;">√No FOD, No bent pins, Good EMI band</p> <ol style="list-style-type: none"> On IV GO on Front Panel: <ul style="list-style-type: none"> <input type="checkbox"/> Attempt to demate P2 from J4 <input type="checkbox"/> Remove dust cap from J2 If able to demate connector P2 from J4 on Front Panel: <ul style="list-style-type: none"> <input type="checkbox"/> Place dust cap on J4 <input type="checkbox"/> Inspect and Mate P2 to J2 If NO joy with connector P2: <ul style="list-style-type: none"> <input type="checkbox"/> Ensure bail on P2 is fully aft and dust cap is off <input type="checkbox"/> Move to Back Panel <input type="checkbox"/> Demate connector J2 from Upper Right receptacle <input type="checkbox"/> Demate connector J4 from Upper Middle receptacle <p style="text-align: center;">NOTE</p> <p style="text-align: center;">Connectors J2 and J4 are restrained by tie-wrap and may prevent mating of connectors. Tie-wrap may be cut if required</p> <ul style="list-style-type: none"> <input type="checkbox"/> Inspect and Mate J2 to Upper Middle receptacle (Back Panel) <input type="checkbox"/> Inspect and Mate J4 to Upper Right receptacle (Back Panel) <input type="checkbox"/> Push bail of P2 fwd to mate connector (Front Panel) <input type="checkbox"/> Install dust cap on J2 (Front Panel) <ol style="list-style-type: none"> Give GO to MCC-H for patch panel power up Open Stbd door of Port toolbox and stow Adj tether from trash bag on tool panel; close and lock toolbox door Check gloves Translate to A/L



CMG Patch Panel Front Side



CMG Patch Panel Back Side

EVA 4 S3 TASK SETUP (00:30)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
<p>1. Verify with MCC-H S1 TRRJ and S3/S4 SARJ locked</p>	<p><u>SETUP</u></p> <ol style="list-style-type: none"> 1. Receive C/L bag from EV2 and place on BRT 2. Hand BRS Pin Tool to EV2 3. Receive WETA and temp stow aft on A/L HR with RET (Lg-sm) 4. Reconfig safety tethers <ul style="list-style-type: none"> <input type="checkbox"/> On EV2 GO: Connect EV1 waist tether to EV2 safety tether (while EV2 safety tether anchor remains on HR) <input type="checkbox"/> On EV2 GO: Release EV2 safety tether A/L aft D-ring <input type="checkbox"/> <input checked="" type="checkbox"/> Gate closed (both hooks) <input type="checkbox"/> <input checked="" type="checkbox"/> Hook locked (both hooks) <input type="checkbox"/> Release EV1 safety tether from A/L fwd D-ring 5. On IV GO: Translate to S1 HR 3214 6. Set safety tether anchor (for both EV1/2): <ul style="list-style-type: none"> <input type="checkbox"/> Attach EV1 safety tether anchor to S1 HR (3214) <input type="checkbox"/> Gate closed <input type="checkbox"/> Hook locked <input type="checkbox"/> Reel unlocked <input type="checkbox"/> Attach EV2 safety tether anchor to S1 HR (3215) <input type="checkbox"/> Gate closed <input type="checkbox"/> Hook locked 7. Release EV1 waist tether from EV2 safety tether 8. Give EV2 GO to release EV2 waist tether from A/L D-ring 9. Translate to S3 aft side 	<p><u>SETUP</u></p> <ol style="list-style-type: none"> 1. Open hatch thermal cover 2. Stow IR Camera in A/L 3. Stow EVA camera in A/L 4. Hand C/L bag to EV1 5. Receive BRS Pin Tool and stow in A/L 6. RET to WETA 7. Hand WETA to EV1 (A/L RET stays with WETA) 8. Attach waist tether to A/L D-ring ext <ul style="list-style-type: none"> <input type="checkbox"/> Gate closed <input type="checkbox"/> Hook locked <input type="checkbox"/> Give EV1 GO to attach Waist Tether to EV2 safety tether <input type="checkbox"/> Give EV1 GO to release EV2 safety tether 9. Retrieve PGT and place on Swing Arm 10. Retrieve WETA and attach to BRT 11. Attach RET (Lg-sm) from WETA on A/L D-ring ext 12. Verify EV2 SAFER Configuration: <ul style="list-style-type: none"> <input type="checkbox"/> R Handle down (HCM door – Closed) <input type="checkbox"/> L Handle down (MAN ISO Valve – Open) 13. <input type="checkbox"/> Reel unlocked 14. On EV1 GO, release Waist Tether from A/L D-ring 15. Close hatch thermal cover 16. Translate to S3 fwd side
<div style="border: 2px solid black; padding: 5px;"> <p>WARNING 2-ft Keep-Out Zone for floating cables between MT and MBS. Stay on UMA handrails during translation underneath MT</p> </div>		



EVA 4 CP1 WETA INSTALL (00:40)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)						
<p>1. <input type="checkbox"/> MCC-H WETA inhibits in place:</p> <p>RPCM S31A_A RPC 15 – Open, Close Cmd Inh RPC 16 – Open, Close Cmd Inh</p> <p>RPCM S32B_A RPC 15 – Open, Close Cmd Inh RPC 16 – Open, Close Cmd Inh</p> <table border="1" data-bbox="109 1096 541 1252"> <thead> <tr> <th></th> <th>Torque</th> <th>Turns</th> </tr> </thead> <tbody> <tr> <td>WETA (Center)</td> <td></td> <td></td> </tr> </tbody> </table>		Torque	Turns	WETA (Center)			<p style="text-align: center;"><u>NOTE</u> Either crewmember may perform</p> <p><u>SETUP</u></p> <ol style="list-style-type: none"> Check gloves Temp stow C/L Bag on S3 Face 4 at HR 3029 and HR 3020 Temp stow camera w/RET at HR 3029 <p><u>DUMMY BOX REMOVAL</u></p> <ol style="list-style-type: none"> Tether to dummy box with C/L bag RET PGT [A5 7.0 ft-lb, CCW2, 30.5]-7/16-6-in ext <input type="checkbox"/> Release dummy box left and right captive fasteners 7-12 turns (bolt will pop up) PGT[A5 7.0 ft-lb, CCW2, 30.5]-7/16-6-in ext <input type="checkbox"/> Release center jack screw 24-30 turns Remove dummy box Hand dummy box to EV2 <p style="text-align: center;"><u>NOTE</u> √No FOD, No bent pins, Good EMI band</p> <p><u>WETA INSTALL</u></p> <ol style="list-style-type: none"> Set PGT [A7 9.2 ft-lb, CW2, 30.5]-7/16-6-in ext For WETA center jack bolt Receive WETA from EV2 Install WETA on the stanchion by sliding it along two guide pins into soft dock position RET to and Remove round scoop; stow on MWS or pass to EV2 for C/L bag stowage Push in and engage WETA center jack bolt to hardstop ~24-30 turns ← Report torque and turns Visually check for contact between WETA front wedge and support structure Release TA clamps <ol style="list-style-type: none"> Demate W8200 cable connectors P2, P3 and P4 from dummy panel A296 <ul style="list-style-type: none"> <input type="checkbox"/> P2 from J2 <input type="checkbox"/> P3 from J3 <input type="checkbox"/> P4 from J4 	<p style="text-align: center;"><u>NOTE</u> Either crewmember may perform</p> <p><u>SETUP</u></p> <ol style="list-style-type: none"> Check gloves <p><u>DUMMY BOX REMOVAL</u></p> <ol style="list-style-type: none"> Assist EV1 as required Receive dummy box from EV1 and stow in C/L bag <p><u>WETA INSTALL</u></p> <ol style="list-style-type: none"> Pass WETA to EV1 On IV GO: Demate deadface connectors and connector cap from panel A78 J2, J3 and J4; temp stow <ul style="list-style-type: none"> <input type="checkbox"/> J2 <input type="checkbox"/> J3 <input type="checkbox"/> J4 Inspect and Mate W8200 cable connectors to S3 panel A78 receptacles (any order) <ul style="list-style-type: none"> <input type="checkbox"/> P2 to J2 <input type="checkbox"/> P3 to J3 <input type="checkbox"/> P4 to J4
	Torque	Turns						
WETA (Center)								

EVA 4 CP1 WETA INSTALL (00:40) (Cont)

IV			EV1 – Swanson (FF)	EV2 – Arnold (FF)									
<table border="1"> <thead> <tr> <th></th> <th>Torque</th> <th>Turns</th> </tr> </thead> <tbody> <tr> <td>WETA (Outer – Left/stbd)</td> <td></td> <td></td> </tr> <tr> <td>WETA (Outer – Right/port)</td> <td></td> <td></td> </tr> </tbody> </table>				Torque	Turns	WETA (Outer – Left/stbd)			WETA (Outer – Right/port)			<p>17. Inspect and Mate deadface connectors (J2 & J3) and twist cap (J4) to A296 dummy panel</p> <ul style="list-style-type: none"> <input type="checkbox"/> P2 NZGL Cap (size 15) to J2 <input type="checkbox"/> P3 NZGL Cap (size 13) to J3 <input type="checkbox"/> P4 Twist Cap to J4 <p>18. PGT[A7 9.2 ft-lb, CW2, 30.5]-7/16-6-in ext Push in and engage left and right fasteners to hardstop ~7-12 turns ← Start both bolts before going to hardstop Report torque and turns</p> <p>19. Remove RET from WETA and stow on MWS</p> <p>20. RET to then remove thermal shroud from WETA; temp stow on outside of C/L bag</p> <p>21. Close TA clamps or Wire tie cables as necessary</p> <p>22. Stow dummy box in C/L bag, if reqd</p> <p>23. √Scoop in C/L bag</p> <p>24. Inspect gloves</p> <p>25. Translate to PAS Worksite</p>	<p>7. Inspect gloves</p> <p>8. Translate to PAS Worksite</p>
	Torque	Turns											
WETA (Outer – Left/stbd)													
WETA (Outer – Right/port)													
<p>2. Give MCC-H GO to power up WETA</p>													

EVA 4 CP1 WETA INSTALL – TASK DATA



EVA 4 CP1 WETA INSTALL – TASK DATA (Cont)

Estimated Task Duration:

	With SSRMS	Without SSRMS
One EV Crew	N/A	TBD
Two EV Crew	N/A	00:40

ORU Identification:

ORU	Part number	Serial Number
WETA	16103320-301	1003

ORU Specs:

ORU	Dimensions (in)	Mass (lb)
WETA	34x18x18	105.8

Tools:

EV1 (FF)	EV2 (FF)
PGT	PGT
7/16-6-in wobble	7/16-6-in wobble
Round Scoop (on WETA in A/L)	
Wire ties	

Foot Restraints: None

EVA Fasteners:

Fastener Name	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Dummy Box (Outer)	7/16	2	N/A	7.0	17.1	6.8-11.8	30
Dummy Box (Center)	7/16	1	N/A	7.0	17.1	24.4-30.4	30
WETA (Outer)	7/16	2	9.2	N/A	13.2	6.8-12.8	30
WETA (Center)	7/16	1	9.2	N/A	13.2	24.4-30.4	30

Electrical Connectors:

Harness	From	To	Size
Dead Face Connector	S3 J2	VSSA Dummy Panel	15
Dead Face Connector	S3 J3	VSSA Dummy Panel	13
Connector Cap	S3 J4	VSSA Dummy Panel	15
W8200-P2	VSSA Dummy Panel	S3 J2	15
W8200-P3	VSSA Dummy Panel	S3 J3	13
W8200-P4	VSSA Dummy Panel	S3 J4	15

Connector Inhibits:

1. RPCM S31A_A RPC 15 – Open, Close Cmd Inhibit
2. RPCM S31A_A RPC 16 – Open, Close Cmd Inhibit
3. RPCM S32B_A RPC 15 – Open, Close Cmd Inhibit
4. RPCM S32B_A RPC 16 – Open, Close Cmd Inhibit

Timeline Considerations:

1. WETA thermal clock is 9 hr with thermal cover and 4 hr with no thermal cover
2. WETA thermal cover must be removed before WETA heater activation

Notes:

1. Dummy panel A296 is on bottom of VSSA mounting plate ~4 ft from S3 face 4; S3 A78 is just inside S3 face 4

Cautions:

1. N/A

Warnings:

1. N/A

EVA 4 S3 OUTBOARD NADIR PAS DEPLOY (01:15)

IV	EV1/2										
<p>1. Verify S1 Lower Outboard Camera aimed at PAS</p> <p>Deploy Clevis Bracket Bolts Released</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="width: 20px;">1</th> <th style="width: 20px;">2</th> <th style="width: 20px;">3</th> <th style="width: 20px;">4</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		1	2	3	4	Bolt					<p>On IV GO: <u>S3 PAS DEPLOY – OUTBOARD NADIR</u></p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0; text-align: center;"> <p>CAUTION Avoid inadvertent contact with grapple fixture shafts and target pins</p> </div> <p><input type="checkbox"/> <u>Swivel Deploy Clevis Bracket/Release Pins</u> (EV1)</p> <ol style="list-style-type: none"> 1. RET to Deploy Clevis Bracket 2. Swivel Deploy Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext 3. Temp stow Deploy Clevis Bracket with RET on HR 3057 <p><input type="checkbox"/> <u>Install Gap Spanner</u> (EV2)</p> <ol style="list-style-type: none"> 4. Attach gap spanner to yoke 5. Attach Adj/Gap Spanner/Adj tether to hinge line HR 3051 <p style="margin-left: 40px;"><u>NOTE:</u> Route under braces and attach to outboard portion of yoke</p> <p><input type="checkbox"/> <u>Release Yoke ADP and PIP Pin</u> (EV1)</p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0; text-align: center;"> <p>CAUTION When attempting to remove the Yoke PIP pin and ADP, do not impart more than 10 lbf Yoke ADP does not have a stowage hole. Do not close ADP lock bracket when ADP is not inserted in a stowage/clevis hole</p> </div> <ol style="list-style-type: none"> 6. Release yoke PIP pin, secure using pre-installed wire tie → If unsuccessful go to step 8, else skip 8 7. Release yoke ADP, secure using pre-installed wire tie → If unsuccessful go to step 8, else skip 8 <p><input type="checkbox"/> <u>ADP/PIP Pin Contingency Removal</u></p> <ol style="list-style-type: none"> 8. Complete step 8 only if step 6 and/or 7 were NO joy: <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Stow Clevis Bracket bolts (4) <ul style="list-style-type: none"> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext, approx 4 turns each <input type="checkbox"/> Re-attempt removal of yoke PIP pin and/or yoke ADP, secure using pre-installed wire tie <p><input type="checkbox"/> <u>Hinge Line Prep</u> (EV2)</p> <ol style="list-style-type: none"> 9. Remove hinge line ADPs (2), insert in stowage hole (toward station forward), confirm ADP closed <ul style="list-style-type: none"> <input type="checkbox"/> Inboard <input type="checkbox"/> Outboard
	1	2	3	4							
Bolt											

EVA 4 S3 OUTBOARD NADIR PAS DEPLOY (01:15) (Cont)

IV	EV1/2															
<p>Stow Clevis Bracket Bolts Released</p> <table border="1"> <tr> <td></td> <td>5</td> <td>6</td> <td>7</td> <td>8</td> </tr> <tr> <td>Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>		5	6	7	8	Bolt					<p><input type="checkbox"/> <u>Reposition Braces</u> (EV2)</p> <ol style="list-style-type: none"> Release SARJ Launch Bolt by hand, approx 3 turns ccw necessary If reqd, PGT [B6 24.0 ft-lb, CCW2 30 RPM, 30.5] Release SARJ Brace (cup-cone bolt), stop on turns; 35 turns, do not exceed 37 turns <input type="checkbox"/> PGT [B6 24.0 ft-lb, CCW3 60 RPM, 30.5]-7/16-6-in ext (use A7, CCW2 if desired to go to hardstop) Attach SARJ Brace to Diagonal Strut, hand tighten SARJ Launch Bolt 1 turn cw Release Diagonal Brace (cup-cone bolt), stop on turns; 35 turns, do not exceed 37 turns <input type="checkbox"/> PGT [B6 24.0 ft-lb, CCW3 60 RPM, 30.5]-7/16-6-in ext (use A7, CCW2 if desired to go to hardstop) <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <ol style="list-style-type: none"> Guide Diagonal Brace and temp stow with tether to HR 3044 Swing yoke inside to provide room for removal of stow clevis bracket 					
		5	6	7	8											
	Bolt															
<p style="text-align: center;">**SYNC POINT**</p> <hr style="border-top: 2px dashed red;"/> <p style="text-align: center;">**SYNC POINT**</p>	<p><input type="checkbox"/> <u>Swivel Stow Clevis Bracket</u> (EV1)</p> <ol style="list-style-type: none"> RET to Stow Clevis Bracket Swivel Stow Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns <input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext Temp stow Stow Clevis Bracket on HR 3044 															
	<p><input type="checkbox"/> <u>Deploy PAS to Detent</u> (EV2)</p> <ol style="list-style-type: none"> Deploy PAS to detent, tend with Adj/Gap Spanner/Adj, lead with yoke – (10 deg past vertical) Reposition Adj/Gap Spanner/Adj at hinge end to take up slack to on HR 3060 															
<p>Record Torque and Turns of Stow Clevis Brackets:</p> <table border="1"> <tr> <td>Bolt #</td> <td>5</td> <td>6</td> <td>7</td> <td>8</td> </tr> <tr> <td>Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>	Bolt #	5	6	7	8	Initial Torque					Turns					<p><input type="checkbox"/> <u>Reinstall Stow Clevis Bracket</u> (EV1)</p> <p style="text-align: center;">** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <ol style="list-style-type: none"> Finger start Stow Clevis Bracket bolts (4), approx 1-2 turns Engage Stow Clevis Bracket bolts (4) to hard stop, expect 10 turns <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns Retrieve RET from bracket
Bolt #	5	6	7	8												
Initial Torque																
Turns																

EVA 4 S3 OUTBOARD NADIR PAS DEPLOY (01:15) (Cont)

IV	EV1/2																				
<p>Record Torque and Turns for the Brace Bolts:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Bolt</th> <th style="width: 15%;">SARJ Brace</th> <th style="width: 15%;">Diagonal</th> </tr> </thead> <tbody> <tr> <td>Torque</td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> </tr> </tbody> </table>	Bolt	SARJ Brace	Diagonal	Torque			Turns			<p><input type="checkbox"/> <u>Reposition Braces</u> (EV2)</p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <p>24. Move Diagonal Brace into position for re-installation</p> <p>25. Engage Diagonal Brace (cup-cone bolt) to hard stop, approx 35 turns <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns</p> <p>26. Release SARJ Brace via SARJ Launch Bolt by hand, approx 1 turn ccw necessary</p> <p>27. Engage SARJ Brace (Cup-Cone bolt) to hard stop, approx 38 turns <input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns</p> <p>28. <input type="checkbox"/> Re-engage SARJ Launch Bolt bolt for temp stow; hand tighten cw 2-3 turns</p> <p>29. Retrieve tether from brace temp stow location</p> <hr/> <p><input type="checkbox"/> <u>Re-Install Deploy Clevis Bracket</u> (EV1)</p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <p>30. Finger start Deploy Clevis Bracket bolts (4), approx 1-2 turns</p> <p>31. Engage Deploy Clevis Bracket bolts (4) to hard stop, expect 10 turns <input type="checkbox"/> PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext ← Report torque and turns</p> <p>32. Apply final Torque to Deploy Clevis Bracket bolts (4) in Ratchet Mode <input type="checkbox"/> PGT [RCW, 30.5]-7/16-6-in ext, two clicks each bolt ←</p> <p>33. Retrieve RET from bracket</p> <hr/> <p><input type="checkbox"/> <u>Move PAS from Detent to Final Deploy Position</u></p> <p>34. Disconnect Gap Spanner and Move platform from detent into install position, tend with Adj/Gap Spanner/Adj</p> <p>35. Install yoke into Deploy Clevis Bracket <input type="checkbox"/> Release wire tie securing PIP pin and ADP to yoke</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION When attempting to install the Yoke PIP pin and ADP, do not impart more than 10 lbf</p> </div> <p><input type="checkbox"/> Install yoke ADP, √lock bracket engaged → If unsuccessful go to step 36, else skip 36</p> <p><input type="checkbox"/> Install yoke PIP Pin → If unsuccessful go to step 36, else skip 36</p>											
Bolt	SARJ Brace	Diagonal																			
Torque																					
Turns																					
<p>Record Torque and Turns of Deploy Clevis Brackets:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Bolt #</th> <th style="width: 10%;">1</th> <th style="width: 10%;">2</th> <th style="width: 10%;">3</th> <th style="width: 10%;">4</th> </tr> </thead> <tbody> <tr> <td>Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Final Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Bolt #	1	2	3	4	Initial Torque					Turns					Final Torque					
Bolt #	1	2	3	4																	
Initial Torque																					
Turns																					
Final Torque																					

EVA 4 S3 OUTBOARD NADIR PAS DEPLOY (01:15) (Cont)

IV	EV1/2												
<p>IV: Obtain GO from MCC-H for RTL Checkout</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">RTL #</th> <th style="text-align: center;">1</th> <th style="text-align: center;">2</th> <th style="text-align: center;">3</th> </tr> </thead> <tbody> <tr> <td>PIP Pin</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Test Complete</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	RTL #	1	2	3	PIP Pin				Test Complete				<p><input type="checkbox"/> ADP/PIP Pin Contingency Install</p> <p>36. Complete step 36 only if step 35 was NO joy:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Deploy Clevis Bracket bolts (4), approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCCW, 30.5]-7/16-6-in ext <input type="checkbox"/> Re-attempt ADP Installation <input type="checkbox"/> Re-attempt PIP pin Installation <input type="checkbox"/> Engage Deploy Clevis Bracket bolts (4) to hard stop, approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require RAD (attempt w/fingers first): PGT [A7 9.2 ft-lb, CW2 30 RPM, 30.5]-RAD w/7/16-2-in ext (count turns at bolt head) <input type="checkbox"/> Remaining bolts, PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext <input type="checkbox"/> Apply final Torque <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCW, 30.5]-7/16-6-in ext <p><input type="checkbox"/> Cleanup/Prep PAS</p> <p>37. Release Adj/Gap Spanner/Adj</p> <p>38. Extend Gap Spanner to full length and stow with Adj in trash bag</p> <p>39. Translate under PAS UMA</p> <p>40. Tether to hitch pin from EVA OVERRIDE anti-rotation cap, remove hitch pin</p> <p>41. <input type="checkbox"/> Remove anti-rotation cap and stow in trash bag</p> <p>42. Translate to each Guide Vane (3) and perform:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Remove launch restraint PIP pin from guide vane, stow in trash bag <input type="checkbox"/> On MCC-H GO, depress and hold RTL lever for 15 sec, then release <input type="checkbox"/> Verify with MCC-H good checkout, move to next guide vane <p>43. Translate to EBCS Target and perform:</p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">CAUTION EBCS target has finished surface that is susceptible to damage by contact</p> </div> <ul style="list-style-type: none"> <input type="checkbox"/> Verify both EV crew are clear of target area <input type="checkbox"/> Remove target cover, stow on backside of target assembly <p>44. Check gloves</p>
RTL #	1	2	3										
PIP Pin													
Test Complete													

EVA 4 S3 INBOARD ZENITH PAS DEPLOY (01:15)

IV	EV1/2										
<p>1. Verify SSRMS Camera aimed at PAS</p> <p>Deploy Clevis Bracket Bolts Released</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="width: 25%;">1</th> <th style="width: 25%;">2</th> <th style="width: 25%;">3</th> <th style="width: 25%;">4</th> </tr> </thead> <tbody> <tr> <td>Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		1	2	3	4	Bolt					<p>On IV GO: <u>S3 PAS DEPLOY – INBOARD ZENITH</u></p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0; text-align: center;"> <p>CAUTION Avoid inadvertent contact with grapple fixture shafts and target pins</p> </div> <p><input type="checkbox"/> <u>Swivel Deploy Clevis Bracket/Release Pins</u> (EV1)</p> <ol style="list-style-type: none"> 1. RET to Deploy Clevis Bracket 2. Swivel Deploy Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext 3. Temp stow Deploy Clevis Bracket with RET on HR 3023 <p><input type="checkbox"/> <u>Install Gap Spanner</u> (EV2)</p> <ol style="list-style-type: none"> 4. Attach gap spanner to yoke 5. Attach Adj/Gap Spanner/Adj tether to hinge line HR 3013 <p style="margin-left: 40px;"><u>NOTE:</u> Route under braces and attach to outboard portion of yoke</p> <p><input type="checkbox"/> <u>Release Yoke ADP and PIP Pin</u> (EV1)</p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0; text-align: center;"> <p>CAUTION When attempting to remove the Yoke PIP pin and ADP, do not impart more than 10 lbf Yoke ADP does not have a stowage hole. Do not close ADP lock bracket when ADP is not inserted in a stowage/clevis hole</p> </div> <ol style="list-style-type: none"> 6. Release yoke PIP pin, secure using pre-installed wire tie → If unsuccessful go to step 8, else skip 8 7. Release yoke ADP, secure using pre-installed wire tie → If unsuccessful go to step 8, else skip 8 <p><input type="checkbox"/> <u>ADP/PIP Pin Contingency Removal</u></p> <ol style="list-style-type: none"> 8. Complete step 8 only if step 6 and/or 7 were NO joy: <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Stow Clevis Bracket bolts (4) <ul style="list-style-type: none"> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext, approx 4 turns each <input type="checkbox"/> Re-attempt removal of yoke PIP pin and/or yoke ADP, secure using pre-installed wire tie <p><input type="checkbox"/> <u>Hinge Line Prep</u> (EV2)</p> <ol style="list-style-type: none"> 9. Remove hinge line ADPs (2), insert in stowage hole (toward station forward), confirm ADP closed <ul style="list-style-type: none"> <input type="checkbox"/> Inboard <input type="checkbox"/> Outboard
	1	2	3	4							
Bolt											

EVA 4 S3 INBOARD ZENITH PAS DEPLOY (01:15) (Cont)

IV	EV1/2																															
<p>Stow Clevis Bracket Bolts Released</p> <table border="1"> <tr> <td></td> <td style="text-align: center;">5</td> <td style="text-align: center;">6</td> <td style="text-align: center;">7</td> <td style="text-align: center;">8</td> </tr> <tr> <td>Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </table> <p style="text-align: center;">**SYNC POINT** **SYNC POINT**</p> <p>Record Torque and Turns of Stow Clevis Brackets:</p> <table border="1"> <tr> <td>Bolt #</td> <td style="text-align: center;">5</td> <td style="text-align: center;">6</td> <td style="text-align: center;">7</td> <td style="text-align: center;">8</td> </tr> <tr> <td>Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> </table> <p>Record Torque and Turns for the Brace Bolt:</p> <table border="1"> <tr> <td>Bolt</td> <td>Diagonal</td> </tr> <tr> <td>Torque</td> <td></td> </tr> <tr> <td>Turns</td> <td></td> </tr> </table>		5	6	7	8	Bolt					Bolt #	5	6	7	8	Initial Torque					Turns					Bolt	Diagonal	Torque		Turns		<p><input type="checkbox"/> <u>Reposition Braces (EV2)</u></p> <p>10. Release Diagonal Brace (cup-cone bolt), stop on turns; 35 turns, do not exceed 37 turns</p> <p style="margin-left: 20px;"><input type="checkbox"/> PGT [B6 24.0 ft-lb, CCW3 60 RPM, 30.5]-7/16-6-in ext (use A7, CCW2 if desired to go to hardstop)</p> <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;">CAUTION</p> <p style="text-align: center;">Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <p>11. Guide Diagonal Brace and temp stow with tether to HR 3023 12. Swing yoke inside to provide room for removal of stow clevis bracket</p> <hr/> <p><input type="checkbox"/> <u>Swivel Stow Clevis Bracket (EV1)</u></p> <p>13. RET to Stow Clevis Bracket 14. Swivel Stow Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns</p> <p style="margin-left: 20px;"><input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext</p> <p>15. Temp stow Stow Clevis Bracket on HR 3023</p> <hr/> <p><input type="checkbox"/> <u>Deploy PAS to Detent (EV2)</u></p> <p>16. Deploy PAS to detent, tend with Adj/Gap Spanner/Adj, lead with yoke – (10 deg past vertical) 17. Reposition Adj/Gap Spanner/Adj at hinge end to take up slack to on HR 3003</p> <hr/> <p><input type="checkbox"/> <u>Reinstall Stow Clevis Bracket (EV1)</u></p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <p>18. Finger start Stow Clevis Bracket bolts (4), approx 1-2 turns 19. Engage Stow Clevis Bracket bolts (4) to hard stop, expect 10 turns</p> <p style="margin-left: 20px;"><input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext</p> <p style="margin-left: 20px;">← Report torque and turns</p> <p>20. Retrieve RET from bracket</p> <hr/> <p><input type="checkbox"/> <u>Reposition Braces (EV2)</u></p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;">CAUTION</p> <p style="text-align: center;">Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <p>21. Move Diagonal Brace into position for re-installation 22. Engage Diagonal Brace (cup-cone bolt) to hard stop, approx 35 turns</p> <p style="margin-left: 20px;"><input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext</p> <p style="margin-left: 20px;">← Report torque and turns</p> <p>23. Retrieve tether from brace temp stow location</p>
	5	6	7	8																												
Bolt																																
Bolt #	5	6	7	8																												
Initial Torque																																
Turns																																
Bolt	Diagonal																															
Torque																																
Turns																																


EVA 4 S3 INBOARD ZENITH PAS DEPLOY (01:15) (Cont)

IV	EV1/2																				
<p>Record Torque and Turns of Deploy Clevis Brackets:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">Bolt #</th> <th style="text-align: center;">1</th> <th style="text-align: center;">2</th> <th style="text-align: center;">3</th> <th style="text-align: center;">4</th> </tr> </thead> <tbody> <tr> <td>Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Final Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Bolt #	1	2	3	4	Initial Torque					Turns					Final Torque					<p><input type="checkbox"/> <u>Re-Install Deploy Clevis Bracket</u> (EV1)</p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <p>24. Finger start Deploy Clevis Bracket bolts (4), approx 1-2 turns 25. Engage Deploy Clevis Bracket bolts (4) to hard stop, expect 10 turns ← <input type="checkbox"/> PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext Report torque and turns</p> <p>26. Apply final Torque to Deploy Clevis Bracket bolts (4) in Ratchet Mode ← <input type="checkbox"/> PGT [RCW, 30.5]-7/16-6-in ext, two clicks each bolt</p> <p>27. Retrieve RET from bracket</p> <hr/> <p><input type="checkbox"/> <u>Move PAS from Detent to Final Deploy Position</u></p> <p>28. Disconnect Gap Spanner and Move platform from detent into install position, tend with Adj/Gap Spanner/Adj 29. Install yoke into Deploy Clevis Bracket <input type="checkbox"/> Release wire tie securing PIP pin and ADP to yoke</p> <div style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p>CAUTION When attempting to install the Yoke PIP pin and ADP, do not impart more than 10 lbf</p> </div> <p><input type="checkbox"/> Install yoke ADP, √lock bracket engaged → If unsuccessful go to step 30, else skip 30 <input type="checkbox"/> Install yoke PIP Pin → If unsuccessful go to step 30, else skip 30</p> <hr/> <p><input type="checkbox"/> <u>ADP/PIP Pin Contingency Install</u></p> <p>30. Complete step 30 only if step 29 was NO joy:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Deploy Clevis Bracket bolts (4), approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCCW, 30.5]-7/16-6-in ext <input type="checkbox"/> Re-attempt ADP Installation <input type="checkbox"/> Re-attempt PIP pin Installation <input type="checkbox"/> Engage Deploy Clevis Bracket bolts (4) to hard stop, approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require RAD (attempt w/fingers first): PGT [A7 9.2 ft-lb, CW2 30 RPM, 30.5]-RAD w/7/16-2-in ext (count turns at bolt head) <input type="checkbox"/> Remaining bolts, PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext <input type="checkbox"/> Apply final Torque <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCW, 30.5]-7/16-6-in ext
Bolt #	1	2	3	4																	
Initial Torque																					
Turns																					
Final Torque																					

EVA 4 S3 INBOARD ZENITH PAS DEPLOY (01:15) (Cont)

IV	EV1/2												
<p>IV: Obtain GO from MCC-H for RTL Checkout</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">RTL #</th> <th style="text-align: center;">1</th> <th style="text-align: center;">2</th> <th style="text-align: center;">3</th> </tr> </thead> <tbody> <tr> <td>PIP Pin</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Test Complete</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	RTL #	1	2	3	PIP Pin				Test Complete				<ul style="list-style-type: none"> <input type="checkbox"/> <u>Clean Up/Prep PAS</u> 31. Release Adj/Gap Spanner/Adj 32. Extend Gap Spanner to full length and stow with Adj in trash bag 33. Translate under PAS UMA 34. Tether to hitch pin from EVA OVERRIDE anti-rotation cap, remove hitch pin 35. <input type="checkbox"/> Remove anti-rotation cap and stow in trash bag 36. Translate to each Guide Vane (3) and perform: <ul style="list-style-type: none"> <input type="checkbox"/> Remove launch restraint PIP pin from guide vane, stow in trash bag <input type="checkbox"/> On MCC-H GO, depress and hold RTL lever for 15 sec, then release <input type="checkbox"/> Verify with MCC-H good checkout, move to next guide vane 37. Translate to EBCS Target and perform: <div style="border: 1px solid black; padding: 5px; margin: 10px 0; text-align: center;"> <p>CAUTION EBCS target has finished surface that is susceptible to damage by contact</p> </div> <ul style="list-style-type: none"> <input type="checkbox"/> Verify both EV crew are clear of target area <input type="checkbox"/> Remove target cover, stow on backside of target assembly 38. Check gloves
RTL #	1	2	3										
PIP Pin													
Test Complete													

EVA 4 S3 PAS DEPLOY – TASK DATA



DEPLOYED UCCAS

EVA 4 S3 PAS DEPLOY – TASK DATA (Cont)



HINGE LINE ADP ORIENTATION

EVA 4 S3 PAS DEPLOY – TASK DATA (Cont)

Estimated Task Duration:

	Without SSRMS
One EV Crew	N/A
Two EV Crew	01:15

Tools:

EV1	EV2
PGT	PGT
7/16-6-in socket ext	7/16-6-in socket ext
	Adj – 45-72-in Gap Spanner (Large) – Adj

EVA Fasteners:

Fastener Name	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns
SARJ Brace Launch Lock Bolt	7/16	1	16.0	24.0	32.3	
SARJ Brace cup/cone Bolt	7/16	1	16.0	24.0	14.0 and 31.6	37-40
Diagonal cup/cone bolt	7/16	1	16.0	24.0	14.0 and 31.6	37-40
Stowage Clevis	7/16	4	16.0	25.5	46.7	10
Deploy Clevis	7/16	4	30.5	25.5	106.6	10

Inhibits:

Inhibit
S3/S4 SARJ Locked

Notes:

1. UMA EVA Override anti-rotation cap must be removed prior to first use of UMA on PAS
2. EBCS target cover must be removed prior to cargo attachment to PAS. Protects target from MMOD and inadvertent contact. Remove as last activity
3. RAD drive may be needed for re-install of deployed clevis bracket. It will likely exceed RAD limits and need to be returned for refurb

Cautions:

1. Do not lift diagonal brace greater than 7 deg out of rotation plane when rotating to temp stowage location so as to not bend hinge end
2. Do not close ADP lock bracket when ADP is not inserted in a stowage/clevis hole. The pin can fall apart
3. EBCS target has finished surface that is susceptible to damage by contact

Warnings:

EVA 4 CLEANUP/INGRESS (00:40)

IV	EV1 – Swanson (FF)	EV2 – Arnold (FF)
<p>Prior to Ingress: 1. Perform WVS PWRDN (PHOTO/TV, <u>WVS CUE CARD</u>)</p>	<p><u>CLEANUP</u></p> <ol style="list-style-type: none"> 1. Stow EVA camera in C/L bag 2. Stow WETA MLI in C/L bag 3. Translate to S1 Safety Tether Anchor 4. Prepare Safety Tether for return to A/L <ul style="list-style-type: none"> <input type="checkbox"/> On EV2 GO: Connect EV1 Waist Tether to EV2 Safety Tether (while EV2 safety tether anchor remains on HR) <input type="checkbox"/> On EV2 GO: Release EV2 Safety Tether from S1 HR (3215) <input type="checkbox"/> <input type="checkbox"/> √Gate Closed (both hooks) <input type="checkbox"/> <input type="checkbox"/> √Hook Locked (both hooks) <input type="checkbox"/> Release EV1 Safety Tether from S1 HR (3214) 5. Adjust TCV to begin cold soak, as reqd 6. Translate to A/L 7. Ingress A/L 8. Remove SCU from stowage pouch 9. Remove DCM cover; Velcro to DCM 10. Connect SCU to DCM; √SCU Locked 11. WATER – OFF (fwd), expect H2O IS OFF msg 12. Close thermal cover; attach Velcro strap 13. √EV hatch clear of FOD and obstructions 14. Verify EV hatch handle position per hatch decal; close and lock <p>Go to PRE-REPRESS (<u>DEPRESS/REPRESS</u> Cue Card)</p>	<p><u>CLEANUP</u></p> <ol style="list-style-type: none"> 1. Place C/L bag on BRT 2. Adjust TCV to begin cold soak, as reqd 3. Translate to A/L 4. Open hatch thermal cover 5. Complete safety tether re-config to A/L <ul style="list-style-type: none"> <input type="checkbox"/> Connect EV2 waist tether to A/L D-ring ext <input type="checkbox"/> √Gate Closed <input type="checkbox"/> √Hook Locked 6. Give EV1 GO to attach Waist Tether to EV2 Safety Tether 7. Give GO to EV1 to release EV2 safety tether anchor 8. Stow CL bag in A/L 9. Ingress A/L 10. Remove SCU from stowage pouch 11. Remove DCM cover; Velcro to DCM 12. Connect SCU to DCM; √SCU Locked 13. WATER – OFF (fwd), expect H2O IS OFF msg
<p>CAUTION Do not close hatch until EMU Water OFF for 2 min. Verify outer hatch clear of hardware</p>		
		<p>Go to PRE-REPRESS (<u>DEPRESS/REPRESS</u> Cue Card)</p>

This Page Intentionally Blank

NOTES

NOTES

S3 INBOARD NADIR PAS DEPLOY (01:15)

IV	EV1/2										
1. Verify S3/S4 SARJ locked and S1 TRRJ locked 2. Verify S1 Lower Outboard Camera aimed at PAS Deploy Clevis Bracket Bolts Released <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="width: 20px;">1</th> <th style="width: 20px;">2</th> <th style="width: 20px;">3</th> <th style="width: 20px;">4</th> </tr> </thead> <tbody> <tr> <td>Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		1	2	3	4	Bolt					<p>On IV GO: <u>S3 PAS DEPLOY – INBOARD NADIR</u></p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Avoid inadvertent contact with grapple fixture shafts and target pins</p> </div> <p><input type="checkbox"/> <u>Swivel Deploy Clevis Bracket/Release Pins</u> (EV1)</p> <ol style="list-style-type: none"> 1. RET to Deploy Clevis Bracket 2. Swivel Deploy Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns <ul style="list-style-type: none"> <input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext 3. Temp stow Deploy Clevis Bracket with RET on HR 3025 <p><input type="checkbox"/> <u>Install Gap Spanner</u> (EV2)</p> <ol style="list-style-type: none"> 4. Attach gap spanner to yoke 5. Attach Adj/Gap Spanner/Adj tether to hinge line HR 3017 NOTE: Route under braces and attach to outboard portion of yoke <p><input type="checkbox"/> <u>Release Yoke ADP and PIP Pin</u> (EV1)</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION When attempting to remove the Yoke PIP pin and ADP, do not impart more than 10 lbf Yoke ADP does not have a stowage hole. Do not close ADP lock bracket when ADP is not inserted in a stowage/clevis hole</p> </div> <ol style="list-style-type: none"> 6. Release yoke PIP pin, secure using pre-installed wire tie → If unsuccessful go to step 8, else skip 8 7. Release yoke ADP, secure using pre-installed wire tie → If unsuccessful go to step 8, else skip 8 <p><input type="checkbox"/> <u>ADP/PIP Pin Contingency Removal</u></p> <ol style="list-style-type: none"> 8. Complete step 8 only if step 6 and/or 7 were NO joy: <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Stow Clevis Bracket bolts (4) PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext, approx 4 turns each <input type="checkbox"/> Re-attempt removal of yoke PIP pin and/or yoke ADP, secure using pre-installed wire tie <p><input type="checkbox"/> <u>Hinge Line Prep</u> (EV2)</p> <ol style="list-style-type: none"> 9. Remove hinge line ADPs (2), insert in stowage hole (toward station forward), confirm ADP closed <ul style="list-style-type: none"> <input type="checkbox"/> Inboard <input type="checkbox"/> Outboard
	1	2	3	4							
Bolt											

GET-AHEADS

S3 INBOARD NADIR PAS DEPLOY (01:15) (Cont)

IV	EV1/2																															
<p>Stow Clevis Bracket Bolts Released</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td></td> <td style="text-align: center;">5</td> <td style="text-align: center;">6</td> <td style="text-align: center;">7</td> <td style="text-align: center;">8</td> </tr> <tr> <td style="text-align: center;">Bolt</td> <td></td> <td></td> <td></td> <td></td> </tr> </table> <p style="text-align: center;">**SYNC POINT** **SYNC POINT**</p> <p>Record Torque and Turns of Stow Clevis Brackets:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">Bolt #</td> <td style="text-align: center;">5</td> <td style="text-align: center;">6</td> <td style="text-align: center;">7</td> <td style="text-align: center;">8</td> </tr> <tr> <td style="text-align: center;">Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> </table> <p>Record Torque and Turns for the Brace Bolt:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">Bolt</td> <td style="text-align: center;">Diagonal</td> </tr> <tr> <td style="text-align: center;">Torque</td> <td></td> </tr> <tr> <td style="text-align: center;">Turns</td> <td></td> </tr> </table>		5	6	7	8	Bolt					Bolt #	5	6	7	8	Initial Torque					Turns					Bolt	Diagonal	Torque		Turns		<p><input type="checkbox"/> <u>Reposition Braces (EV2)</u></p> <p>10. Release Diagonal Brace (cup-cone bolt), stop on turns; 35 turns, do not exceed 37 turns</p> <p style="margin-left: 20px;"><input type="checkbox"/> PGT [B6 24.0 ft-lb, CCW3 60 RPM, 30.5]-7/16-6-in ext (use A7, CCW2 if desired to go to hardstop)</p> <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center; margin: 0;">CAUTION</p> <p style="text-align: center; margin: 0;">Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <p>11. Guide Diagonal Brace and temp stow with tether to HR 3025</p> <p>12. Swing yoke inside to provide room for removal of stow clevis bracket</p> <hr/> <p><input type="checkbox"/> <u>Swivel Stow Clevis Bracket (EV1)</u></p> <p>13. RET to Stow Clevis Bracket</p> <p>14. Swivel Stow Clevis Bracket: (4 bolts) 10 turns on all bolts except pivot bolt, 8 turns</p> <p style="margin-left: 20px;"><input type="checkbox"/> PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5]-7/16-6-in ext</p> <p>15. Temp stow Stow Clevis Bracket on HR 3025</p> <hr/> <p><input type="checkbox"/> <u>Deploy PAS to Detent (EV2)</u></p> <p>16. Deploy PAS to detent, tend with Adj/Gap Spanner/Adj, lead with yoke (10 deg past vertical)</p> <p>17. Reposition Adj/Gap Spanner/Adj at hinge end to take up slack to on HR 3010</p> <hr style="border-top: 2px dashed red;"/> <p><input type="checkbox"/> <u>Reinstall Stow Clevis Bracket (EV1)</u></p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <p>18. Finger start Stow Clevis Bracket bolts (4), approx 1-2 turns</p> <p>19. Engage Stow Clevis Bracket bolts (4) to hard stop, expect 10 turns</p> <p style="margin-left: 20px;"><input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext</p> <p style="margin-left: 20px;">← Report torque and turns</p> <p>20. Retrieve RET from bracket</p> <hr/> <p><input type="checkbox"/> <u>Reposition Braces (EV2)</u></p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center; margin: 0;">CAUTION</p> <p style="text-align: center; margin: 0;">Do not lift diagonal brace more than ~7 deg out of rotation plane to prevent damage to hinge end</p> </div> <p>21. Move Diagonal Brace into position for re-installation</p> <p>22. Engage Diagonal Brace (cup-cone bolt) to hard stop, approx 35 turns</p> <p style="margin-left: 20px;"><input type="checkbox"/> PGT [B2 16.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext</p> <p style="margin-left: 20px;">← Report torque and turns</p> <p>23. Retrieve tether from brace temp stow location</p>
	5	6	7	8																												
Bolt																																
Bolt #	5	6	7	8																												
Initial Torque																																
Turns																																
Bolt	Diagonal																															
Torque																																
Turns																																



S3 INBOARD NADIR PAS DEPLOY (01:15) (Cont)

IV	EV1/2																				
<p>Record Torque and Turns of Deploy Clevis Brackets:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">Bolt #</th> <th style="text-align: center;">1</th> <th style="text-align: center;">2</th> <th style="text-align: center;">3</th> <th style="text-align: center;">4</th> </tr> </thead> <tbody> <tr> <td>Initial Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Turns</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Final Torque</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Bolt #	1	2	3	4	Initial Torque					Turns					Final Torque					<p><input type="checkbox"/> <u>Re-Install Deploy Clevis Bracket</u> (EV1)</p> <p>** THIS MUST BE DONE BEFORE PAS IS MOVED FROM DETENT TO FINAL DEPLOY**</p> <p>24. Finger start Deploy Clevis Bracket bolts (4), approx 1-2 turns 25. Engage Deploy Clevis Bracket bolts (4) to hard stop, expect 10 turns ← <input type="checkbox"/> PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext Report torque and turns</p> <p>26. Apply final Torque to Deploy Clevis Bracket bolts (4) in Ratchet Mode ← <input type="checkbox"/> PGT [RCW, 30.5]-7/16-6-in ext, two clicks each bolt</p> <p>27. Retrieve RET from bracket</p> <hr/> <p><input type="checkbox"/> <u>Move PAS from Detent to Final Deploy Position</u></p> <p>28. Disconnect Gap Spanner and Move platform from detent into install position, tend with Adj/Gap Spanner/Adj 29. Install yoke into Deploy Clevis Bracket <input type="checkbox"/> Release wire tie securing PIP pin and ADP to yoke</p> <div style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p>CAUTION When attempting to install the Yoke PIP pin and ADP, do not impart more than 10 lbf</p> </div> <p><input type="checkbox"/> Install yoke ADP, √lock bracket engaged → If unsuccessful go to step 30, else skip 30 <input type="checkbox"/> Install yoke PIP Pin → If unsuccessful go to step 30, else skip 30</p> <hr/> <p><input type="checkbox"/> <u>ADP/PIP Pin Contingency Install</u></p> <p>30. Complete step 30 only if step 29 was NO joy:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Loosen Deploy Clevis Bracket bolts (4), approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 31 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCCW, 30.5]-7/16-6-in ext <input type="checkbox"/> Re-attempt ADP Installation <input type="checkbox"/> Re-attempt PIP pin Installation <input type="checkbox"/> Engage Deploy Clevis Bracket bolts (4) to hard stop, approx 4-6 turns <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require RAD (attempt w/fingers first): PGT [A7 9.2 ft-lb, CW2 30 RPM, 30.5]-RAD w/7/16-2-in ext (count turns at bolt head) <input type="checkbox"/> Remaining bolts, PGT [B5 22.0 ft-lb, CW2 30 RPM, 30.5]-7/16-6-in ext <input type="checkbox"/> Apply final Torque <ul style="list-style-type: none"> <input type="checkbox"/> Some bolts will require Torque Wrench 2-in ext at 30.5 ft-lb <input type="checkbox"/> Remaining bolts, PGT [RCW, 30.5]-7/16-6-in ext
Bolt #	1	2	3	4																	
Initial Torque																					
Turns																					
Final Torque																					

S3 INBOARD NADIR PAS DEPLOY (01:15) (Cont)

IV	EV1/2												
<p>IV: Obtain GO from MCC-H for RTL Checkout</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: center;">RTL #</th> <th style="text-align: center;">1</th> <th style="text-align: center;">2</th> <th style="text-align: center;">3</th> </tr> </thead> <tbody> <tr> <td>PIP Pin</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Test Complete</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	RTL #	1	2	3	PIP Pin				Test Complete				<ul style="list-style-type: none"> <input type="checkbox"/> <u>Clean Up/Prep PAS</u> 31. Release Adj/Gap Spanner/Adj 32. Extend Gap Spanner to full length and stow with Adj in trash bag 33. Translate under PAS UMA 34. Tether to hitch pin from EVA OVERRIDE anti-rotation cap, remove hitch pin 35. <input type="checkbox"/> Remove anti-rotation cap and stow in trash bag 36. Translate to each Guide Vane (3) and perform: <ul style="list-style-type: none"> <input type="checkbox"/> Remove launch restraint PIP pin from guide vane, stow in trash bag <input type="checkbox"/> On MCC-H GO, depress and hold RTL lever for 15 sec, then release <input type="checkbox"/> Verify with MCC-H good checkout, move to next guide vane 37. Translate to EBCS Target and perform: <div style="border: 1px solid black; padding: 5px; margin: 10px 0; text-align: center;"> <p><u>CAUTION</u> EBCS target has finished surface that is susceptible to damage by contact</p> </div> <ul style="list-style-type: none"> <input type="checkbox"/> Verify both EV crew are clear of target area <input type="checkbox"/> Remove target cover, stow on backside of target assembly 38. Glove check
RTL #	1	2	3										
PIP Pin													
Test Complete													

CONNECTOR INSULATING SLEEVE – CHANNEL 1/4 (S0)

IV	EV (FF)
<p>1. IV/MCC-H: Verify Inhibits are in place: DDCU S0 1A</p> <p>Face 3 Shroud Door – Ingress Here</p>  <p>RPCM Worksite</p> <p>S0 Zenith – Looking Nadir</p>	<ol style="list-style-type: none"> 1. Retrieve 1 connector sleeve (sz 33/37) 2. On IV GO (Inhibits completed) 3. Translate to S0 Bay 0 Face 3 4. Ingress aft shroud door 5. Install Connector Sleeve over affected connector <ul style="list-style-type: none"> □ Install P333 (W4145)/J333A (W4148)  <p>FWD</p> <p>ZEN</p> <p>NAD</p> <p>W4148 S0 jumper P333A mated to A163 J333</p> <p>HR 3500</p> <p>TA clamp</p> <p>Face 3 entry</p> <p>W4145 P333 mated to W4148 S0 jumper J333A</p> <p>PANEL A163 (EVA 3) POST 12A.1</p> <p>Install sleeve on this connector</p>

CONNECTOR INSULATING SLEEVE – MBS



IV

1. IV/MCC-H: Verify Inhibits are in place:

Worksite Dependent

WS1: RPCM S3-4B_F
RPCM S3-3A_F


WS4: RPC S0-4B_A1
RPC S0-3A_A1




Nadir side of MT

EV (FF)


1. Retrieve 2 connector sleeves (sz 21/25)
2. On IV GO (Inhibits completed)
3. Translate to nadir side of MT/MBS
4. Install Connector Sleeves (2) over affected connectors
 - ❑ J2 (W9181)/P2 (A1W8031)
 - ❑ J2 (W9182)/P2 (A2W8031)




CONNECTOR INSULATING SLEEVE – SSPTS (NODE 1 FWD)

IV	EV (FF)
<p>1. IV/MCC-H: Verify Inhibits are in place: RPCM Z1 3B_A2 RPCM Z1 4B_A2</p>	<p>1. Retrieve 2 connector sleeves (sz 33/37) 2. On IV GO (Inhibits completed) 3. Translate to Node 1 Fwd (stbd, zenith) – HRs N1 0137 & N1 0130 4. Install Connector Sleeves (2) over affected connectors</p> <ul style="list-style-type: none">❑ P430/J430A❑ P440/J440A 


CONNECTOR INSULATING SLEEVE – SSPTS (LAB FWD)

IV	EV (FF)
<p>1. IV/MCC-H: Verify Inhibits are in place: RPCM Z1 3B_A2 RPCM Z1 4B_A2</p>	<p>1. Retrieve 2 connector sleeves (sz 21/25) 2. On IV GO (Inhibits completed) 3. Translate to Lab Fwd (stbd) – HR Lab 0273 4. Install Connector Sleeves (2) over affected connectors <input type="checkbox"/> P113/J113A <input type="checkbox"/> P114/J114A</p>  <p>The photograph shows a close-up view of the Lab Fwd (stbd) area. Several cables and connectors are visible. Labels with arrows point to specific components: J114A/P114 (top left), SSPTS (top right), 0273 (middle left), J113A/P113 (middle right), and 8A LTA Cable (bottom center). The background shows the metallic structure of the station with various cables and connectors.</p> <p>ISS014E13476</p>

CONNECTOR INSULATING SLEEVE – SSPTS (PMA2 PORT)

IV	EV (FF)
<p>1. IV/MCC-H: Verify Inhibits are in place: RPCM LA 1A4A_D3 RPCM Z1 4B_A2</p>	<p>1. Retrieve 1 connector sleeve (sz 21/25) 2. On IV GO (Inhibits completed) 3. Translate PMA2 port (midway) 4. Install Connector Sleeve over affected connector □ P3/J3A</p>  <p>The image is a 3D CAD model of a spacecraft component, likely a connector assembly. It shows a complex structure with various wires, cables, and mechanical parts. A white callout box with the text 'J3A/P3' is positioned in the lower right area of the model, with a white arrow pointing to a specific connector location on the side of the component. The model is rendered in a dark grey color with some yellow and orange highlights on the wires and connectors.</p>

CONNECTOR INSULATING SLEEVE – SSPTS (PMA2 STBD)

IV	EV (FF)
<p>1. IV/MCC-H: Verify Inhibits are in place: RPCM LA 2A3B_D1 RPCM Z1 3B_A2</p>	<p>1. Retrieve 1 connector sleeve (sz 21/25) 2. On IV GO (Inhibits completed) 3. Translate to PMA2 stbd (midway) – HR 0407 4. Install Connector Sleeve over affected connector □ P16/J16A</p>  <p>The diagram shows a detailed view of a spacecraft's internal connector assembly. Three specific components are highlighted with white boxes and black text labels: '0407' is located at the top center, pointing to a small yellow component; 'J16A/P16' is in the middle right, pointing to a large multi-pin connector; and 'W9303' is at the bottom left, pointing to a cylindrical component. Various colored wires (yellow, orange, green) and mechanical parts are visible throughout the assembly.</p>


TOOLS AND STOWAGE

HW TOOL STOWAGE ASSEMBLY (TSA)	TEMP FS 8-2	
PGT CHECKOUT	8-3	
PGSC-PGT CONNECTION (A31P AND 760XD)	8-4	
PROGRAM PGT SETTINGS	8-5	
DOWNLOAD/ERASE EVENT LOG	8-5	
PGT CONTINGENCIES.....	8-6	
PGT STANDARD SETTINGS.....	8-7	
TOOLBOX STOWAGE – STS-119/15A.....	FS 8-9	
APFR MANAGEMENT – STS-119/15A	FS 8-10	
SAFETY TETHERS – STS-119 (15A)	FS 8-11	
TOOLBOX PANEL AND SLOT LABELS	FS 8-12	
Z1 TOOLBOX INTERNAL LAYOUT	FS 8-13	
AIRLOCK TOOLBOX INTERNAL LAYOUT	FS 8-14	
APFR THERMAL SHIELD REMOVAL.....	FS 8-15	
GREASE GUN NOZZLE MLI MODIFICATION.....	FS 8-16	


TOOLS AND
STOWAGE

HW TOOL STORAGE ASSEMBLY (TSA)


I



TOOLS AND STOWAGE




FORWARD DRAWER STOWAGE




AFT DRAWER STOWAGE

HW TOOL STOWAGE ASSEMBLY (TSA) (Cont)



FORWARD COMPARTMENT STOWAGE CONFIGURATION
DOOR REMOVED FOR CLARITY



MISSION SPECIFIC COMPARTMENT

This Page Intentionally Blank

TOOLBOX STOWAGE – STS-119/15A

	Z1 PORT TOOLBOX (MMOD Damage – potential sharp edges) {all slots have sliders}	Z1 STBD TOOLBOX {all slots have sliders}	A/L TOOLBOX 1 (STBD)	A/L TOOLBOX 2 (PORT)
SLOT # 1	SQUARE TM BOARD {stbd door} SQ TORQUE MULTIPLIER 7/16" FLUSH SQ SOCKET 7/16" PROUD SQ SOCKET 7/16" RECESSED SQ SOCKET	SQUARE TM BOARD {stbd door} SQ TORQUE MULTIPLIER 7/16" FLUSH SQ SOCKET 7/16" PROUD SQ SOCKET 7/16" RECESSED SQ SOCKET	HAMMER BOARD {nadir door}	CABLE CUTTER BOARD COMPOUND CUTTERS (SM) SCISSORS {zenith door}
SLOT # 2		QD BAIL TOOL BOARD {stbd door} BMRRM LATCH TOOL QD BAIL DRIVE TOOL (1")	PLIERS BOARD {nadir door} NEEDLE NOSE PLIERS	
SLOT # 3	RATCHET BOARD {middle} 7/16" X 12" WOBBLE SOCKET 7/16" X 2" RIGID SOCKET	RATCHET BOARD {middle} 7/16" X 6" WOBBLE SOCKET	{only slot with slider}	{only slot with slider}
SLOT # 4				
SLOT # 5	ROUND TM BOARD {port door} RND TORQUE MULTIPLIER 5/8" PROUD RND SOCKET 7/16" FLUSH RND SOCKET 7/16" PROUD RND SOCKET	ROUND TM BOARD {port door} 7/16" FLUSH RND SOCKET 7/16" PROUD RND SOCKET	ADJ WRENCH BOARD FORCEPS WRENCH, ADJ {zenith door}	T-HANDLE TOOL BOARD 1-8" T-TOOLS {nadir door}
SLOT # 6	TRASH BAG BOARD {stbd door} SMALL TRASH BAG	TRASH BAG BOARD {stbd door}	HYDRAZINE BRUSH BOARD HYDRAZINE BRUSH {nadir door}	
SLOT # 7	SOCKET BOARD {port door} 5/32" BALL END ALLEN DR 1/2" X 8" WOBBLE SOCKET 5/16" X 7" RIGID SOCKET	SOCKET BOARD {port door} 5/32" BALL END ALLEN DR 1/2" X 8" WOBBLE SOCKET 5/16" X 7" RIGID SOCKET	PRD (Toolboard) {zenith door} PRD	PRD (Toolboard) {nadir door} PRD
PANEL # 8	CHEATER BAR PANEL {stbd door}	CHEATER BAR PANEL {stbd door} CHEATER BAR ADJ EQUIP TETHER	TOOL CADDY PANEL {nadir door} CADDY, ISS (BUNGEE)	
PANEL # 9	18" SOCKET PANEL {port door} 7/16" X 18" WOBBLE SOCKET	18" SOCKET PANEL {port door}	BOLT PULLER PANEL BOLT PULLER MECHANICAL FINGER {zenith door}	LARGE CUTTER PANEL {nadir door} Large Cutters (-303)
EXTERNAL	1 SQUARE SCOOP w/D-HANDLE (on zenith micro) (D-handle taped over repaired MMOD damage) 1 ROUND SCOOP D-HANDLE on port side of toolbox	1 SQUARE SCOOP NOTE D-Handle will not stow on the side of this toolbox due to an interference with the CMG MLI		

APFR MANAGEMENT – STS-119/15A

APFR DESIGNATOR	APFR 1 (8A, 13A.1 Pitch knob problem)	APFR 2 (US EVA 9 Pitch knob problem, 10A sticky locking collar)	APFR 3 s/n 1005 (no pitch knob prob 9A- inc12 suspected sharp edge on locking collar and possible sticky locking collar)	APFR 4 (TS, old ORU tether, heat shield)	APFR 5 (TS, old ORU tether, heat shield)	APFR 6 (heat shield removed on 12A.1 stage)	APFR 7 s/n 1008	IAPFR 1	IAPFR 2	CRANE (old ORU tether)	TS	ORU stanchion/ TERA headless	OTSD
Post STS-126	Lab WIF 7 [6,PP,F,12]	Lab WIF 4 [1,TT,C,11]	CETA 2 WIF 1 12, GG [6,II,F,6] ingress aid	Z1 WIF 08 [7,PP,B,6] TS at 4 o'clock	PMA1 WIF 2 [12,KK,F,6]	S1 WIF 1 [10,TT,L,12]	Lab WIF 11 [1,QQ,A,12]	Z1 WIF 1 [12,PP,F,12]	Z1 WIF 3 [6,PP,F,12]	PMA1 WIF 5	S0 port wedge face	S0 port wedge face	S0 WIF 7 CL=7
STS-119 EVA 1													
			CETA 2 WIF 4 12, GG [6,II,F,6] ingress aid										
STS-119 EVA 2													
	P6 WIF 30 [12,PP,F,12]	Relocating TS from APFR 4		IVA to remove heat shield			P6 WIF 10 [6,GG,E,6]						
STS-119 EVA 3													
			S0 WIF 42 [low-profile] ingress aid	A/L Starboard Toolbox WIF									
STS-119 EVA 4													
Post STS-119	P6 WIF 30 [12,PP,F,12]	Lab WIF 4 [1,MM,C,11] Tool Stanchion	S0 WIF 42 [low-profile] ingress aid	A/L Starboard Toolbox WIF	PMA1 WIF 2 [12,KK,F,6]	S1 WIF 1 [10,TT,L,12]	P6 WIF 10 [6,GG,E,6]	Z1 WIF 1 [12,PP,F,12]	Z1 WIF 3 [6,PP,F,12]	PMA1 WIF 5	S0 port wedge face	S0 port wedge face	S0 WIF 7 CL=7

SAFETY TETHERS – STS-119 (15A)

	55-ft tethers							85-ft tethers			
	#59 s/n 1007 Sm-sm	#71 s/n 1021 Lg-sm	#72 s/n 1022 Lg-sm (had 10A – retraction issues)	#73 s/n 1023 Lg-sm (AR written against this one) (1JA – slow retractor)	#60 s/n 1008 Lg-sm (has retracting issues)	#70 s/n 1020 Lg-sm	#66 s/n 1016 Sm-sm	#26 s/n 1002 Lg-sm	#28 s/n 1008 Lg-sm	#21 s/n 1001 (Shuttle safety tethers)	#24 s/n 1004 (Shuttle safety tethers)
Post 126 EVA 4	Returns on shuttle (MPLM)	INSIDE tether staging area	Returns on shuttle (MPLM)	INSIDE tether staging area	S0 HH 3539 or HH 3530 Tether on 3539 had retracting issues	S0 HH 3539 or HH 3530 Tether on 3539 had retracting issues	INSIDE tether staging area	INSIDE tether staging area	INSIDE tether staging area	Returned on shuttle	Returned on shuttle
126 Stage	-----same-----							-----same-----			
Post 119 EVA 4	Ground	INSIDE tether staging area	Ground	INSIDE tether staging area	S0 HH 3539 or HH 3530 Tether on 3539 had retracting issues	S0 HH 3539 or HH 3530 Tether on 3539 had retracting issues	INSIDE tether staging area	INSIDE tether staging area	INSIDE tether staging area	Returned on shuttle	Returned on shuttle


NOTE

During US EVA #8, EV2 reported that her 55-ft safety tether (P/N SEG33106674-307 s/n 1023, #73) was not retracting properly. EV2 attempted to perform the usual technique of pulling out some cable and then letting it reel in, but there came a point when EV2 was neither able to extend or retract the line with 6-8 ft of tether cable still extended. EV2 also cycled the tether from UNLOCK to LOCK and back to UNLOCK, with no joy. The tether was temp stowed as is until later (EV2 was attached to an 85-ft tether at this point.) During EVA cleanup, EV1 attempted to troubleshoot the tether, placing it in LOCK and extending quite a few more feet of cable from the tether. When the tether was placed back in UNLOCK it retracted completely, with a little bit of coaxing for the last couple feet of cable (typical behavior). The tether was brought inside. No further action required


TOOLBOX PANEL AND SLOT LABELS

NOTE


- A/L Toolbox: Slider feature located in center slot (#3)
- Z1/CETA Toolbox: Slider feature located in all slots



Z1 TOOLBOX INTERNAL LAYOUT



AIRLOCK TOOLBOX INTERNAL LAYOUT



APFR THERMAL SHIELD REMOVAL

I

1. Retrieve the following:
 - APFR
 - Dry Wipes
 - Ziplock Bag
 - Sharpie
 - Driver Handle, 3/8-in Drive – Drawer 2
 - #8 Long Torq Driver, 3/8-in Drive – Drawer 3




Figure 1. - Thermal Shield Location on APFR.

2. Remove APFR thermal shield non-captive screws (eight) (Driver, Handle, 3/8-in Drive; #8 Long Torq Driver, 3/8-in Drive). Expect a breaking torque of 10-30 in-lb
Refer to Figure 1
Stow screws in Ziplock Bag

CAUTION

Do not pry Thermal Shield off, damage could occur

3. Remove Thermal Shield; light tapping applied from side of Thermal Shield may be required (Driver Handle, 3/8-in Drive, blunt end)
Temp stow thermal shield in Ziplock Bag
4. Inspect bottom of APFR Load Limiter for sharp edges
5. Wipe off Vibratite from bottom of Load Limiter (Dry Wipes). Vibratite may not come completely off; it is not essential to remove all residue
6. Label Ziplock Bag "15A APFR Thermal Shield, GMT 2009/XXX" and stow (Sharpie)


GREASE GUN NOZZLE MLI MODIFICATION

Perform the following steps for the straight nozzle gun (Grease) prior to the EVA 3 PRE TOOL CONFIG

1. Retrieve the following items:

ITEM	QTY	LOCATION
EV/IV tie-wrap	2	Shuttle IFM locker Tray 1, MA16L
1"x1" square Velcro pile	1	Shuttle IFM locker Tray 1, MA16L
Kapton tape	1 strips	Shuttle IFM locker Tray 1, MA16L
Scissors	1	Half CTB S/N 1154, NOD1O4C1


2. Cut small slit (~1/8-in) in center of Velcro square
3. Remove adhesive backing from Velcro square; discard backing
4. Insert tie-wrap into Velcro square (head of tie-wrap against pile side)




5. Insert tie-wrap and Velcro through orifice in nozzle MLI (Velcro square inside of cover)



6. Snug tie-wrap and Velcro to inside of cap



7. Slide second tie-wrap onto first tie-wrap and snug tight



8. Perform pull test (~5-7 lb) on tie-wrap; verify it remains captive in MLI
9. Cut off ends of tie-wraps



10. Wrap exposed edges of tie-wrap with Kapton tape



This Page Intentionally Blank

EMU MAINT/RECHARGE

WATER RECHARGE.....	TEMP FS 10-2
EMU POWERUP.....	TEMP FS 10-2
WATER FILL.....	TEMP FS 10-2
WATER FILL VERIFICATION.....	TEMP FS 10-2
EMU LiOH CHANGEOUT.....	10-4
MIDDECK EMU BATTERY RECHARGE (STAND-ALONE).....	10-4a
MIDDECK EMU BATTERY RECHARGE/LiOH REPLACEMENT.....	10-5
INITIATE.....	10-5
TERMINATE.....	10-6
IN-SUIT EMU BATTERY RECHARGE/CHARGE VERIFICATION.....	10-7
INITIATE.....	10-7
TERMINATE.....	10-7
EMU POWERDOWN.....	10-7
HELMET LIGHT/PGT BATTERY RECHARGE.....	10-8
INITIATE.....	10-8
TERMINATE.....	10-9
REBA BATTERY INSTALLATION.....	10-9
EMU BATTERY REMOVAL/INSTALL.....	10-10
HELMET LIGHT BULB CHANGEOUT.....	10-11
REBA BATTERY RECHARGE.....	10-12
INITIATE.....	10-12
TERMINATE.....	10-13
CONSUMABLES TRACKING CUE CARD.....	FS CC 10-15
BATTERY RECHARGE/METOX REGEN CUE CARD.....	FS CC 10-16

WATER RECHARGE

IF EMU NOT ALREADY POWERED UP:

EMU POWERUP

- BOTH DCM 1. Retrieve, position SCUs; remove DCM covers
 2. Connect SCUs to DCM, √locked
 3. PWR – BATT

CAUTION

EMU must be on BATT pwr when
 airlock pwr supply is turned on

- AW18H 4. PWR/BATT CHGR EMU 1,2 MODE (two) – PWR
 BUS SEL (two) – MNA(MNB)
- MD(flir) 5. √EMU O2 ISOL VLV – OP
- AW82B 6. EV1,2 O2 vlv (two) – OP
- DCM 7. PWR – SCU

WATER FILL

- MO13Q 8. √ARLK H2O S/O VLV – OPEN (tb-OP)
- R11L 9. √SPLY H2O TKA OUTLET – CL (tb-CL)

SM 60 TABLE MAINT

- CRT 10. Use TKB quantity:
 PARAM ID – ITEM 1 +0 6 2 0 4 2 0 EXEC
11. Log value before recharge

Recharge #	H2O TKB %
1	
2	
3	
4	
5	

- AW82D 12. √EMU 1,2 H2O WASTE tb (two) – CL
 SPLY (two) – OP (tb-OP)
13. √H2O TKB quantity decreasing

NOTE

Full charge requires ~15 min

WATER FILL VERIFICATION

- DCM 14. √STATUS: H2O WP 8-15 psi and stable for ~30 sec (indicates charging complete)

SM 60 TABLE MAINT

- CRT 15. Use TKB quantity:
 PARAM ID – ITEM 1 +0 6 2 0 4 2 0 EXEC
16. Log value after recharge

Recharge #	H2O TKB %
1	
2	
3	
4	
5	

EMU MAINT/
 RECHARGE

Cont next page

TEMP FS 10-2

119

EVA/ALL/FIN A

TOP

**HOOK
VELCRO**

CONSUMABLES TRACKING CUE CARD

SAFER usage s/n 1004 & 1007				EVA 1 EMU TV: ID 16 (Sw) & 18 (An)			Dump CWC s/n 1059		
	EMU	LiOH (s/n) (B/C)	METOX (s/n) (B/C)	EMU Battery	REBA (s/n)	HL Battery (s/n)	PGT Battery (s/n)	PGT Battery Spare (s/n)	PWR (s/n)
Campout			0005/0022						
EVA 1	EV1 – Sw EMU 3017	2014	N/A	2068	1008	1022/1025	1008	1009	
	EV2 – An EMU 3006	2015	N/A	2069	1006	1026/1030	1006		
Post					Recharge	Recharge	Recharge	Recharge	1032
Between	Swap			Recharge					
Campout			0015/0016						
EVA 2	EV1 – Sw EMU 3017	N/A	0007 7802J	2076	1008	1028/1029	1008	1009	
	EV3 – Ac EMU 3005	N/A	0011 7792J	2037	1009	1031/1035	1006		
Post			Regen Campout		Recharge	Recharge	Recharge	Recharge	1032/1003
Between	Swap			Recharge 2076 only					
Campout			0015/0016						
EVA 3	EV2 – An EMU 3006	N/A	0012 (none)	2074	1006	1022/1025	1006	1009	
	EV3 – Ac EMU 3005	N/A	0013 7794J	2075	1009	1026/1030	1008		
Post			Regen Campout		Recharge	Recharge	Recharge	Recharge	1003
Between	Swap			Recharge					
Campout			0015/0016			IR Camera 1022			
EVA 4	EV1 – Sw EMU 3017	N/A	0017 7811J	2068	1008	1028/1029	1008	1009	
	EV2 – An EMU 3006	N/A	0021 7814J	2069	1006	1031/1035	1006		
Post									1003/1005
Return	EV1 – Sw EMU 3017	2014		2074					
	EV2 – An EMU 3004	2015		2075					
Return	Spare			2037					


EVA-6a/119/O/B

(reduced copy)

TOP
BACK OF 'CONSUMABLES TRACKING CUE CARD'

BATTERY RECHARGE/METOX REGEN CUE CARD

**HOOK
VELCRO**



EVA-6b/119/O/B

(reduced copy)

EMU CONTINGENCY PROCS

DISPLAY LOSS DURING POWER TRANSFER (WARM RESTART)..... TEMP FS 12-2
VACUUM H2O RECHARGE (MANNED)..... TEMP FS 12-2
LiOH REPLACEMENT (MANNED)..... 12-3
BATTERY REPLACEMENT (MANNED) 12-4
WATER DUMP 12-6
SCU SWAP (UNMANNED)..... 12-7
SCU SWAP (MANNED)..... 12-7
EMU COLD RESTART (MANNED) 12-7
12.1 STS EVA DECONTAMINATION..... 12-8
CONTAMINATION TEST..... 12-15
SAFER BATTERY CHANGEOUT 12-18
BENDS TREATMENT ADAPTER (BTA) INSTALLATION (IN-SUIT) 12-19
 BTA PREP 12-19
 BTA TREATMENT 12-19
BENDS TREATMENT ADAPTER (BTA) INSTALLATION (POST
SUIT DOFFING)..... 12-21
 BTA PREP 12-21
 BTA TREATMENT 12-21
EMU RESIZE 12-24
EMERGENCY UNDOCKING EVA TRANSFER FS CC 12-27
EXPEDITED SUIT DOFFING CUE CARD FS CC 12-28
STS-119 NOMINAL EMU SIZING FS 12-29
EMU CONTINGENCY RESIZE MATRIX (STS-119/15A)..... FS 12-32

DISPLAY LOSS DURING POWER TRANSFER (WARM RESTART)

- DCM If PWR – BATT and SCU connected:
- AW18H 1. √PWR/BATT CHGR EMU 1(2) BUS SEL – OFF
- DCM If PWR – SCU:
- 2. PWR – BATT
- AW18H 3. PWR/BATT CHGR EMU 1(2) BUS SEL – OFF

<p><u>WARNING</u></p> <p>Fan will be off from steps 4 to 9 during which time CO2 buildup is a concern</p>
--

NOTE

Affected EMU will be without comm after step 6. Steps 6 and 7 should be read together before step 6 is performed

- DCM 4. FAN – OFF (expect FAN SW OFF msg, DISP – PRO)
- IV 5. Inform affected EV crewmember of impending comm loss
- DCM 6. PWR – SCU (7 sec)
- 7. PWR – BATT
- When power restart complete:
- 8. √Display – O2 POS XX, expect FAN SW OFF msg, DISP – PRO
- 9. As reqd, FAN – ON
- If display blank or locked up:
- 10. Contact MCC
- If SCU power desired:
- 11. √SCU connected to DCM
- AW18H 12. PWR/BATT CHGR EMU 1(2) MODE – PWR
 BUS SEL – MNA(MNB)
- 13. √EMU INPUT 1(2) Volts = 18.0 – 20.0
- DCM 14. PWR – SCU
- DCM 15. √Display – O2 POS XX

VACUUM H2O RECHARGE (MANNED)

<p><u>WARNING</u></p> <p>Procedure should be used only if performing a contingency EVA</p>

- EV 1. Perform AIRLOCK INGRESS, Cuff C/L, 30 (Close hatch, partially engage latches)
- 2. √Helmet purge vlv – cl, locked
- DCM 3. √PURGE vlv – cl (dn)
- 4. √WATER – OFF
- IV MO13Q 5. √ARLK H2O S/O VLV – OPEN (tb-OP)
- MD(flr) 6. √EMU O2 ISOL VLV – OP
- ML86B:C 7. √cb MNC EXT ARLK HTR LINE ZN 1,2 (two) – op
- AW82B 8. √EV-1(EV-2) O2 vlv – OP
- EV AW18H 9. PWR/BATT CHGR EMU 1(2) BUS SEL – MNA(MNB)
- DCM 10. PWR – SCU (fwd), WARN TONE
- IV R11L If SPLY H2O XOVR VLV closed (tb-CL or bp) (water transfer config):
- 11. SPLY H2O TKA OUTLET – CL (tb-CL)
- If SPLY H2O XOVR VLV open (tb-OP) (nominal config):
- L1 12. √RAD CNTLR OUT TEMP – NORM
- 13. √FLASH EVAP CNTLR PRI A,B (two) – OFF
- ML31C 14. SPLY H2O TKD OUTLET – CL (tb-CL)
- R11L 15. SPLY H2O TKB OUTLET – CL (tb-CL)
- √TKA OUTLET – CL (tb-CL)
- TKC INLET – CL (tb-CL)
- TKC OUTLET – OP (tb-OP)

TOP

HOOK
VELCRO

EMERGENCY UNDOCKING EVA TRANSFER

Critical

- 2 EMUs: 3017 (Sw) & 3006 (An)/3004 (An)
 - Time permitting:
 - Remove: Helmet Lights, TV, REBA, METOX, ISS Tethers and MWS w/Tools
 - EMU 3004 preferred – reconfig per EVA Prep for Transfer to Shuttle
- ECOKS (Sw & An)
- CCAs (Sw & An)
- Gloves (Sw & An)
- LCVG (Sw & An)
- EMU Batteries (2) (s/n 2074, 2075 desirable)
- 85-ft Safety Tethers (2)

Desired

- Shuttle Airlock Floor Bag
- (1) EMU Servicing Kit, s/n 5005 preferred

EVA-5a/119/O/A

TOP
BACK OF 'EMERGENCY UNDOCKING EVA TRANSFER'

HOOK
VELCRO

EXPEDITED SUIT DOFFING CUE CARD

CAUTION


Verify EV crew is clear of hatch mechanism

- IV 1. When equalization complete: Open IV Hatch per decal
- DOFFING SAFER (5 min)
- SAFER 2. Remove latch covers
3. Latch → ENG
4. Latch ccw until release (~90 deg)
5. Doff SAFER
- SUIT DOFFING (10 min)
- DCM 6. O2 ACT → OFF
7. PURGE vlv → op (up)
- PLSS 8. sw REBA → OFF (toward left arm of suit)
9. Engage EMU in EDDA
- PLSS 10. EMU TV Power Cable ←|→ EMU EV
- DCM 11. √STATUS: SUIT P < 0.4
12. Gloves ←|→ EMU
13. Helmet ←|→ EMU
- DCM 14. sw FAN → OFF
15. Doff EMU
16. If taking EMUs to shuttle:
UIA sw PWR EV-1,2 (two) → OFF
√PWR EV-1,2 LEDs (four) – Off
- DCM SCU ←|→ DCM
LTA →|← HUT
Gloves →|← EMU
Helmet →|← EMU
- Go to the EMERGENCY UNDOCKING
EVA TRANSFER Cue Card
(opposite side)


EVA-5b/119/O/A

STS-119 NOMINAL EMU SIZING

Swanson (Sw) up



Swanson (Sw) down




	Croakie	Fresnel Lens	Valsalva	LCVG/BLVD	MAG	TCU Top	TCU Bottom	Comfort Gloves	Socks
Sw	None	None	-308	03/05 Thermal Slippers	-709 (Med)	Med	Med	Thick Spectra (L)	Tube

Blue – Items launched on Shuttle to remain on ISS


Green – Items returning from ISS

STS-119 NOMINAL EMU SIZING (Cont)

Arnold (An) up



Arnold (An) down




	Croakie	Fresnel Lens	Valsalva	LCVG/BLVD	MAG	TCU Top	TCU Bottom	Comfort Gloves	Socks
An	None	None	-309	06/07 Thermal Slippers	-711 (Large)	XL	XL	Thin Spectra (L)	Sock Liners (L)

Blue – Items launched on Shuttle to remain on ISS


Green – Items returning from ISS

STS-119 NOMINAL EMU SIZING (Cont)

Acaba (Ac) ISS EMU



EMU 3006 Config for ISS



	Croakie	Fresnel Lens	Valsalva	LCVG/BLVD	MAG	TCU Top	TCU Bottom	Comfort Gloves	Socks
Ac	None	None	-309	02/04	-709 (Med)	Med	Med	Thick Spectra (M)	Tube

Blue – Items launched on Shuttle to remain on ISS
 Green – Items returning from ISS
 Red – ISS items to remain on ISS

EMU CONTINGENCY RESIZE MATRIX (STS-119/15A)

FOR LOSS OF:	EV1 – Swanson	EV2 – Arnold	EV3 – Acaba
HUT/PLSS	<p>For EVA 1 or 4: Use EMU 3005, Medium (Ac)</p> <ol style="list-style-type: none"> 1. Remove glove/arm assys 2. Use primary arms, gloves 3. √Arm red connects to right, √locks, √cams 4. Use primary LTA 5. Swap EMU PLSS identifier stripes, national flag 6. Swap helmet, comm cap, LiOH/Metox, EMU battery, REBA <p>For EVA 2: Use EMU 3011, Large</p> <ol style="list-style-type: none"> 1a. Follow steps 1,3-6 listed above and remove arm rings 2a. Use -02 lower arms s/n 331/332 from ISS 3a. Adjust cams to L/L for prime gloves or S/L for BU gloves 	<p>Use EMU 3011, Large</p> <ol style="list-style-type: none"> 1. Remove ring/glove/arm assys 2. Use primary ring, arms, gloves 3. √Arm red connects to right, √locks, √cams 4. Use primary LTA 5. Swap EMU PLSS identifier stripes, national flag 6. Swap helmet, comm cap, LiOH/Metox, EMU battery, REBA 	<p>Use EMU 3017, Medium (Sw)</p> <ol style="list-style-type: none"> 1. Remove glove/arm assys 2. Use primary arms, gloves 3. √Arm red connects to right, √locks, √cams 4. Use primary LTA 5. Swap EMU PLSS identifier stripes, national flag 6. Swap helmet, comm cap, LiOH/Metox, EMU battery, REBA
CCA	Use size 04/327 s/n 1172 Location: Sw ECOK	Use size 06/327 CCA s/n 1191 Location: on ISS (Barratt BU)	Use size 03/323 s/n 1207 Location: Airlock Floor Bag
Lower Arm Segment	Med HUT: Use size 03 arm s/n 375/376 from ISS. Cams S/L (red = right, blue = left) 1. √Locks, √cams	Use size 03 arm s/n 375/376 from ISS. Cams S/L (red = right, blue = left) 1. √Locks, √cams	Use size 04 arm s/n 347/348 from Bag C. Cams S/S (red = right, blue = left) 1. √Locks, √cams
Gloves	Back-up: Use 6PZ gloves s/n 6279 1. Adjust arm cams to S/S	Back-up: Use 6PT gloves s/n 6230 1. Adjust arm cams S/S	Back-up: Use 6LA gloves s/n 6147 1. √Arm cams S/S
Waist Brief	Use size 01 waist brief s/n 2075 (029) from ISS. Cams S/L 1. Use primary legs, leg rings, and boots 2. √Locks, √cams 3. Swap EMU brief identifier stripes	Use size 01 waist brief s/n 2075 (029) from ISS. Cams L/S 1. Use prime legs and boots 2. √Locks, √cams 3. Swap EMU brief identifier stripes	Use size 01 waist brief s/n 2075 (029) from ISS. Cams S/S 1. Use prime legs and boots 2. √Locks, √cams 3. Swap EMU brief identifier stripes
Leg Segment	Use size 03 leg from ISS s/n 185 or 186. Cams S/L 1. √Locks, √cams	Use size 04 leg from ISS s/n 212. Cams S/L 1. √Locks, √cams	Use size 02 leg from ISS s/n 152. Cams S/L 1. √Locks, √cams
Boot	Use size 02 boots s/n 214 from ISS 1. √NO BSI or Toe Cap 2. √Locks	Use size 02 boots s/n 214 from ISS 1. √NO BSI or Toe Cap 2. √Locks	Use size 02 boots s/n 214 from ISS 1. Install 03 BSI and toe cap from prime boots 2. √Locks
Sizing Rings	• <u>0.5" Leg:</u> Use s/n 134 or 135 from ISS	• <u>0.5 arm:</u> Use s/n 167 or 168 from ISS	• (None)
LCVG	(03) 1. Use s/n 3172 Location: Bag C 2. Transfer biomed and dosimeter	(07) 1. Use s/n 3183 Location: ISS Airlock 2. Transfer biomed and dosimeter	(03) 1. Use s/n 3172 (Sw/Ac shared BU) Location: Bag C 2. Remove thermal slipper, cut 5 tack stitches 3. Transfer biomed and dosimeter

TPS REPAIR

The TPS Repair procedures listed below are not published in the hardcopy EVA Flight Supplement. These procedures will be uplinked realtime if they are required.

A PDF and a WORD version of the procedures can be found at:
<http://mod.jsc.nasa.gov/do3/FDF/FDFBooks/Status%20Sheets/index.html>.

Select the "As Flown" Status sheet for STS-119 and the link to the procedures can be found with the link to the EVA FS. The procedures can also be found on the FDF Books CD provided to the FAO console

BOOM TPS INSPECTION	
BOOM POINT INSPECTION SUMMARY TIMELINE	FS 13-3
BOOM POINT INSPECTION TOOL CONFIG.....	FS 13-4
BOOM POINT INSPECTION	FS 13-5
BOOM WLE MAPPING SUMMARY TIMELINE	FS 13-15
BOOM WLE MAPPING TOOL CONFIG	FS 13-17
BOOM WLE MAPPING	FS 13-18
EVA WLE MAPPING INSPECTION.....	FS 13-24
BOOM CONTINGENCY	
BOOM FRGF SHAFT RELEASE	FS 13-29
BOOM FRGF SHAFT INSTALLATION	FS 13-30
BOOM EFGF SHAFT RELEASE	FS 13-32
BOOM MPM STOW/DEPLOY.....	FS 13-34
BOOM ASSISTED LATCHING	FS 13-35
TILE REPAIR	
EMU PREP FOR TPS REPAIR.....	FS 13-36
POST TPS REPAIR DOFFING	FS 13-37
EWA MATERIAL MIXING	FS 13-38
EWA REF DATA	FS 13-39
EWA TILE REPAIR – DOCKED/ORM SUMMARY TIMELINE	FS 13-40
EWA TILE REPAIR – DOCKED/ORM TOOL CONFIG.....	FS 13-41
EWA TILE REPAIR – DOCKED/ORM	FS 13-42
SSRMS GAP FILLER REMOVAL SUMMARY TIMELINE	FS 13-50
BOOM GAP FILLER REMOVAL SUMMARY TIMELINE	FS 13-51
GAP FILLER REMOVAL.....	FS 13-52
RCC REPAIR	
RCC CRACK REPAIR BAG ASSEMBLY.....	FS 13-57
TEMP SENSOR DISASSEMBLY POST-EVA.....	FS 13-60
RCC CRACK REPAIR BAG DISASSEMBLY POST-EVA	FS 13-61
TEMPERATURE PROBE ASSEMBLY	FS 13-63
CRM APPLICATOR ASSEMBLY	FS 13-63
CRM APPLICATOR NOZZLE INSTALLATION (DAY OF EVA).....	FS 13-64
RCC CRACK REPAIR.....	FS 13-65
RCC PLUG TRANSFER BAG ASSEMBLY	FS 13-77
NOTES, CAUTIONS, WARNINGS	
EVA TPS INSPECTION/REPAIR INHIBIT PAD.....	FS 13-89
TPS REPAIR CAUTIONS AND WARNINGS	FS 13-92
TPS REPAIR NOTES.....	FS 13-93
BOOM OPERATIONAL WARNINGS	FS 13-94
BOOM OPERATIONAL NOTES	FS 13-95

TPS REF DATA	
PREFERRED EMU POSITIONING FOR TPS REPAIR.....	FS 13-96
EVA TPS REACH AND ACCESS	FS 13-97
POINT INSPECTION REACH AND ACCESS WHILE DOCKED.....	FS 13-98
WLE MAPPING INSPECTION WHILE DOCKED	FS 13-100
TILE LAYUP	FS 13-101
85-FOOT SAFETY TETHER.....	FS 13-102
PFR ATTACHMENT DEVICE (PAD)	FS 13-103
WIF EXTENDER	FS 13-104
EVA DIGITAL CAMERA.....	FS 13-105
EVA IR CAMERA	FS 13-107
OVERLAY TILE REPAIR SYSTEM (OTRS)	FS 13-109
OTRS MARKING TEMPLATE AND INSULATION BAGS	FS 13-110
AUGER HOUSING.....	FS 13-111
OTRS RELEASED CONFIGURATION	FS 13-112
ORU BAG INSERT FOR OTRS	FS 13-113
BOOM REF DATA	
RTF BOOM OVERVIEW	FS 13-114
BOOM TRANSITIONS WITH MLI	FS 13-115
BOOM BASE END AND MODIFIED EFGF	FS 13-116
BOOM BASE END EFGF ADAPTER PLATE	FS 13-117
EVA-ASSISTED EFGF CONNECTOR DEMATE	FS 13-118
BOOM BASE END SADDLE AND MPM.....	FS 13-119
BOOM MID SECTION AND MODIFIED FRGF.....	FS 13-120
BOOM MID SECTION FRGF ADAPTER PLATE.....	FS 13-121
BOOM TIP END AND SENSORS	FS 13-122
BOOM SENSOR DETAILS	FS 13-124
SENSOR PACKAGE 1 (SP1): LDRI/ITVC	FS 13-126
SENSOR PACKAGE 2 (SP2): LCS.....	FS 13-128
POSSIBLE PRD ROUTING FOR EVA ASSISTED LATCHING	
OF BOOM IN MPMS.....	FS 13-130
BOOM CONTINGENCIES	FS 13-131
GRAPPLE SHAFTS	FS 13-132
PDGF GRAPPLE SHAFT COVER.....	FS 13-133
BOOM FRGF FSE.....	FS 13-134

UNSCHEDULED/CONTINGENCY EVA TASKS

UNSCH/CONT
EVA TASKS

15A WORKAROUNDS CRIBSHEET

EVA 1	FS 16-3
EVA 2	FS 16-6
EVA 3	FS 16-6
EVA 4	FS 16-9
GENERIC	
APFR/IAPFR	FS 16-10
BALLSTACK	FS 16-10
BRT	FS 16-11
CANNON CONNECTOR	FS 16-11
EVA WRENCH (TORQUE AND RATCHET)	FS 16-11
FLUID QD OPS	FS 16-11
MUT EE	FS 16-14
MWS	FS 16-15
NZGL CONNECTORS	FS 16-15
PAD	FS 16-17
PGT	FS 16-17
SAFETY TETHER	FS 16-18
SCOOPS	FS 16-19
SOCKET CADDY	FS 16-19
TA CLAMP	FS 16-19
TETHER SHUTTLE	FS 16-19
TORQUE MULTIPLIER	FS 16-20
TSA (HW TSA)	FS 16-21
S5/S6 ATTACH	
16.1a RTAS GAP CLOSURE (CORNER 1 OR 2)	FS 16-22
16.1b RTAS GAP CLOSURE (CORNER 3 OR 4)	FS 16-24
CAPTURE BAR ROTATION	FS 16-25
ATTACH S6 TO S5 USING CONTINGENCY FASTENERS	FS 16-27
PRD S5-S6 OVERVIEW	FS 16-30
PRD RTAS CORNER 1 (PRIMARY)	FS 16-31
PRD RTAS CORNER 1 (PRIMARY) NBL	FS 16-32
PRD RTAS CORNER 2	FS 16-33
PRD RTAS CORNER 2 NBL	FS 16-34
PRD RTAS CORNER 3	FS 16-35
PRD RTAS CORNER 3 NBL (STRAP ROUTING)	FS 16-36
PRD RTAS CORNER 3 NBL	FS 16-38
PRD RTAS CORNER 4 (PRIMARY)	FS 16-39
PRD RTAS CORNER 4 (PRIMARY) NBL	FS 16-40
PRD RTAS CORNER 4 (PRIMARY) (STRAP ROUTING)	FS 16-41
PVR	
S6 RADIATOR MANUAL OVERRIDE TO DEPLOY/RETRACT	FS 16-43
SAW	
PRD 4-BAR ROUTING	FS 16-48
MANUAL OVERRIDE TO DISENGAGE BETA GIMBAL	
ANTI-ROTATION LATCH	FS 16-52
BMRRM ANTI-ROTATION LATCH TABLE	FS 16-53
MANUAL RELEASE OF SABB RESTRAINT PINS	FS 16-54
MANUAL OVERRIDE TO UNLATCH/LATCH (TENSION) SABB	FS 16-57
MANUAL OVERRIDE TO EXTEND/RETRACT MAST	FS 16-59
ASSISTED SOLAR ARRAY DEPLOY/RETRACT	FS 16-62
SABB SPOOL RE-TENSION	FS 16-68
MANUAL SAW JETTISON	FS 16-74

TIE-DOWN PLAN

GAP CHECK TOOL TIE-DOWN FS 16-80
 SABB LAUNCH RESTRAINT TIE-DOWN FS 16-81
 UCCAS/PAS TIE-DOWN FS 16-82
 RPCM TIE-DOWN..... FS 16-84
 WETA/DUMMY BOX TIE-DOWN..... FS 16-85

MISC

BMRRM REMOVE/REPLACE FS 16-89
 DCSU REMOVE AND REPLACE FS 16-94
 DDCU REMOVE AND REPLACE FS 16-99
 DLA REMOVE AND REPLACE FS 16-104
 MBSU REMOVE/REPLACE..... FS 16-112
 RJMC REMOVE AND REPLACE FS 16-119
 SSRMS JOINT DRIVE FS 16-120
 SARJ – TBA REMOVE/INSTALL FS 16-124
 BCDU REMOVE/REPLACE..... FS 16-130
 GENERIC EVA INHIBIT PAD..... FS 16-139
 GENERIC NOTES, CAUTIONS, & WARNINGS..... FS 16-144

15A WORKAROUNDS CRIBSHEET

EVA 1

S6 INSTALL ON S5

A. Pre-install inspection of S6 corners show that primary and/or contingency ball/nuts are not centered	When within reach, center ball/nut with gloved hand and report to MCC-H
B. Pre-install inspection of S5 corners 1, 2, 3 or 4 shows exposed threads on primary RTAS bolt	<ol style="list-style-type: none"> 1. Attempt to retract bolt tip to flush using gloved hand 2. If no joy, PGT: B1, CCW2
C. S5 CLA will not engage	<ol style="list-style-type: none"> 1. If limits out prior to capture bar contact, increase settings to A7, CW2 for 5 turns max, then back down to A6, CW2 (Do not make contact w/capture bar at A7) 2. If PGT torques out mid-travel, contact MCC-H 3. Refer to PRD RTAS for affected corner. Install PRDs on Corners 1 and 4 Verify: CMG control, desat request inhibited, SSRMS: Brakes on for PRD routing and in Limp mode for PRD ratcheting. EV1 and EV2 ratchet both PRDs simultaneously, verify SSRMS in good config after each ratchet throw. NOTE: Do not attach PRD to HR, use ISS structure only
D. S5/S6 gap check fails on one corner	<ol style="list-style-type: none"> 1. Verify gap is being checked in correct location (at ground strap installation location) 2. For corners 1 and 2 only, remove gap check tool (on corner 1) with PGT settings: A6, CCW2; 12-14 turns, check gap 3. If gap reading less than 0.6 line (shoulder of the tool), GO to press with nominal procedure 4. If tool hits at shoulder (reading greater than .6) for Corner 1 or 2, refer to 16.1a RTAS GAP CLOSURE 5. If tool hits at shoulder (reading greater than .6) on Corner 3 or 4, then proceed with Corner 1 and 2 install to initial torque PGT: B7, CW2; ~27 turns to HS 6. Perform gap check at Corners 3 and 4. If gap reading less than 0.6 line (shoulder of the tool), GO to press with nominal initial torque of Corners 3 and 4 7. If tool hits at shoulder (reading greater than .6) for Corner 3 or 4, refer to 16.1b RTAS GAP CLOSURE
E. S5/S6 gap check fails on more than one corner	Contact MCC-H (will consider releasing CLA and backing S6 off)
F. For any of the following S5 Primary Bolt contingencies: a. Does not achieve full torque b. Bolt shoulder has a gap (is not seated against nut)	Refer to ATTACH S6 TO S5 USING CONTINGENCY FASTENERS
G. Primary bolt free spins and does not advance into S6 nut (PGT does not "see" torque) (possible broken self-feeding nut)	If bolt free spins, push S5 bolt axially toward S6 while driving PGT until bolt threads begin to engage S6 nut (under load)
H. S5 gap check tool will not release from outboard corner 1	<ol style="list-style-type: none"> 1. Check worksite for FOD 2. If bolt did not turn, increase PGT setting to B7, CCW2 drive 1 turn only, then return to original PGT setting: A6, CCW2 3. Retrieve gap check tool from inboard corner 1
I. Once release from S6, Fairchild fastener on ground strap is missing washer	If positive control on bolt, press with install
J. S6 ground strap cross threads during install onto S5 lug	<ol style="list-style-type: none"> 1. Ensure EV crew begins installation manually 2. Back-off thread engagement and re-attempt

WORKAROUNDS CRIBSHEET

15A WORKAROUNDS CRIBSHEET (Cont)

K. S6 ground strap will not seat properly onto S5 lug (ground strap is not flush to surface or PGT stalls)	<ol style="list-style-type: none"> 1. Check ground strap alignment 2. Increase PGT torque setting to B1, CW2
--	--

S5 TO S6 ELECTRICAL CONNECTORS

A. Cable fails to release from S5	<ol style="list-style-type: none"> 1. Check for FOD, damage or misalignment 2. Verify cable routing not impeding connector rotation 3. Use cannon connector tool for more leverage 4. Verify P260 demated from S5 and mated to S6 prior to P259
B. Connector/Cap fails to softdock	<ol style="list-style-type: none"> 1. Verify collar unlocked – white on connector shell tip should align with white on receptacle backplate 2. Check for FOD or damage
C. Connector/Cap fails to lock	<ol style="list-style-type: none"> 1. Remove connector/cap, check for FOD or damage 2. Check alignment, remate, rock connectors back and forth as required (once locked, white on connector shell tip should align with black on receptacle backplate) 3. Use cannon connector tool for more leverage (NOTE: Can only use tool for part of the throw on P260 due to strut interference)
D. High cable stiffness prevents mating	<ol style="list-style-type: none"> 1. Verify all necessary TA clamps are released 2. Use two crewmembers/APFR
E. Connector/jack pin bent	<ol style="list-style-type: none"> 1. Report bent pin location to MCC-H 2. On MCC-H GO: Retrieve pin straightener from ISS A/L, Staging Bag; straighten pins
F. Connector/jack FOD	On MCC-H GO: Obtain Connector Cleaner Tool from ISS A/L, Staging Bag to remove FOD
G. Connector EMI band bent	On MCC-H GO: Obtain Needle Nose Pliers or Forceps to remove band

SABB LAUNCH RESTRAINT

A. SABB launch restraint will not release	<ol style="list-style-type: none"> 1. PGT[RCCW, MTL 30.5] RD TM w/5/8" PRD: Apply manual torque to fastener 2. 3/8-in Drive Ratchet – RD TM w/5/8" PRD: Apply ccw manual torque to fastener
---	---

S6 RADIATOR

A. Unable to break torque on cinch bolt	<ol style="list-style-type: none"> 1. Verify PGT socket is fully installed on bolt (depressing anti-rotation feature) 2. Take PGT to manual RCCW, 30.5. Break torque then resume release with PGT settings: B7, CCW2, 30.5 3. If no joy, retrieve ratchet wrench from crewlock bag and re-attempt to break torque then resume release with PGT settings: B7, CCW2, 30.5 4. If issue due to radiator expansion, ask for EV2's assistance to compress radiator
B. Unable to release cinch bolt after torque broken	<ol style="list-style-type: none"> 1. If issue due to radiator expansion, attempt to compress radiator solo 2. Verify bolt released full amount of turns (~14) 3. If single person compression not enough, ask for EV2's assistance to compress radiator
C. Cinch fails to stow in cinch clip	Wire tie cinch to adjacent handrail, verify not in radiator deployment envelope
D. PIP pin fails to release	Attach equipment tether hook to PIP pin loop to provide more leverage
E. Winch bar interferes with radiator deploy	Use adjustable tether or wire tie to secure winch bar out of deployment envelope

15A WORKAROUNDS CRIBSHEET (Cont)

ROTATE IEA KEEL PIN

A. IEA Keel Pin fastener will not release	<ol style="list-style-type: none"> 1. PGT[RCCW, MTL 30.5]-6 ext 7/16 Apply torque 2. PGT[RCCW, MTL 30.5]-SQ TM w/7/16 PRD: Apply torque 1 turn 3. On MCC GO, <div style="border: 2px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p>WARNING Sharp edge hazard, bolts have exposed threads</p> </div> <p>Remove keel pin nut plate:</p> <ol style="list-style-type: none"> a. PGT[B1 12 ft-lb, CCW1 10 RPM]-6 ext 7/16 b. Release non-captive fasteners (2) and stow in trash bag c. Unfasten hex nut with adjustable wrench and stow in trash d. Translate to inboard side of keel housing and remove keel pin fastener e. If jammed, use hammer to drive bolt out
B. IEA Keel Pin will not stay in hard dock	Attach adj equip tether between narrow rod on IEA keel pin nut plate and S6 HR #2067 stand-off. Tether can be retrieved and keel pin put back in launch position after BGA restraint bolt release and 4-bar deploy

RELEASE BGA RESTRAINTS

A. Beta Gimbal launch restraint will not release	<ol style="list-style-type: none"> 1. 3/8-in Drive Ratchet with 5/8: Apply ccw manual torque to fastener 2. 3/8-in Drive Ratchet – RD TM with 5/8: Apply ccw manual torque to fastener
B. 4-bar linkage does not deploy to the locked position	<ol style="list-style-type: none"> 1. Push on 4-bar linkage until latches engage 2. If required, install PRD between IEA and Beta Gimbal Assembly structure. Ratchet PRD to pull 4-bar into locked position. NOTE: Do not attach PRD to HR, use ISS structure only

SAW

A. SABB strut locking sleeve does not engage after SABB unstow	<ol style="list-style-type: none"> 1. Insert SABB PIP pin when the Pivot Locking Mechanism is in BOX UNSTOWED position. Apply manual force to engage locking sleeve over joint 2. If locking sleeve is reset to the STOW position, cycle SABB to LAUNCH position and then back to the UNSTOW position 3. Install Locking Strut Aid
B. Mast Tip Fittings will not release	<ol style="list-style-type: none"> 1. On MCC GO, PGT[B7 25.5 ft-lb, CCW2 30 RPM, MTL 30.5]-6 ext 7/16: Apply torque 1 turn, report release torque to MCC 2. If free spinning nut plate: <ol style="list-style-type: none"> a. Retrieve vise grips b. Attach vise grips to nut plate c. Turn bolt while restraining nut plate

IEA MMOD SHIELD

A. Bolt fails to release	<ol style="list-style-type: none"> 1. PGT[RCCW, MTL 30.5]-6 ext 7/16: Break torque 2. Ratchet Wrench-6 ext 7/16: Break torque
--------------------------	---

15A WORKAROUNDS CRIBSHEET (Cont)

EVA 2

P6 BATTERY PREP

A. APFR	See APFR section of GENERIC cribsheet
B. WIF Inspect: If WIF plate and fasteners fail initial inspection	<ol style="list-style-type: none"> 1. Use PGT [A1 CW2 30 RPM]-6 ext 7/16: to torque down bolt 2. Re-inspect WIF plate <p>NOTE: Although WIF plate bolt height is not to EVA requirements, attempt bolt tightening</p>

PAS/UCCAS DEPLOY

A. Deploy/Stow clevis bracket bolt fails to break torque	<ol style="list-style-type: none"> 1. Use PGT in manual ratchet mode [RCCW, 30.5 MTL] 2. Retrieve torque wrench from A/L staging bag. Set to 41 ft-lb and reattempt release
B. ADP does not release after loosening clevis bolts	Retrieve hammer from staging bag and with ADP in full open position, tap it in farther. Reattempt removal
C. Yoke PIP pin does not release after loosening clevis bolts	Retrieve hammer from staging bag and tap out PIP pin
D. SARJ launch bolt fails to break torque	Increase to PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5] for 1 turn, then return to original setting
E. Cup-cone bolt fails to break torque	Increase to PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5] . (Do not go to hard stop at this setting)
F. Strut cone cannot be removed from cup interface	<ol style="list-style-type: none"> 1. Inspect for clearance between cup and cone, if reqd, PGT[A7 9.2 ft-lb, CCW2 30 RPM]-6 ext 7/16: Release bolt to hardstop 2. Wiggle brace (worked during VITT deploys) 3. Retrieve hammer and tap brace
G. Clevis bracket bolt fails to achieve full torque and turns	Back out the bolts fully and reattempt installation
H. Yoke PIP pin does not install	<ol style="list-style-type: none"> 1. Open handle of Yoke ADP and reattempt installation. If joy, close ADP handle 2. If no joy, manipulate yoke to align PIP pin holes. If joy, close ADP handle

P1/P3 FLUID JUMPER

A. Fluid QDs	See Fluid QD section of GENERIC cribsheet
--------------	---

P1 FHRC P-CLAMPS

A. P-Clamp does not release	Increase to PGT [B1 12.0 ft-lb, CCW2 30 RPM, 30.5] for 1 turn, then return to original setting
-----------------------------	---

EVA 3


CETA CART

A. Wheel bogie fails to release from truss	<ol style="list-style-type: none"> 1. Verify brakes are fully released 2. Ensure trigger is being depressed while attempting to rotate handle 3. On MCC-H GO: Perform {6.100.125 CETA CART WHEEL BOGIE REMOVE AND REPLACE} (SODF: EVA TASK: CONTINENCY TASKS) <ul style="list-style-type: none"> – There is no spare wheel bogie on-orbit, so after the CETA cart is relocated the failed wheel bogie will be reinstalled
B. Wheel bogie fails to install on truss	<p>There is no spare wheel bogie on-orbit. 3 of 4 bogies are required. Real time call on whether MT couple or CETA cart tiedown required. For CETA cart tie down see block G. For wheel bogie tie up:</p> <ol style="list-style-type: none"> 1. Use Adj tether to restrain the wheel bogie so that it is rotated $\geq 25^\circ$ from rail 2. Rotate handle perpendicular to rail (locked position)

15A WORKAROUNDS CRIBSHEET (Cont)

C. Parking brake fails to engage	<ol style="list-style-type: none"> 1. Use parking brake handle on other side of CETA cart 2. Couple CETA cart to MT and utilize other WIF if possible
D. Parking brake fails to disengage	<ol style="list-style-type: none"> 1. Hold pedal down for brake release 2. Use pedal on other side of CETA cart to release parking brake
E. Dynamic brake fails to engage	Limit translation rates to allow manual stopping
F. CETA active coupler fails to capture or lock	<ol style="list-style-type: none"> 1. Cycle active coupler 2. Swap active coupler from MT with failed active coupler on CETA Cart 3. On MCC-H GO: Tie down CETA cart. See block G
G. CETA cart tiedown	<p>On MCC-H GO: Perform the following tiedown procedure (see figure)</p> <ol style="list-style-type: none"> a. Translate CETA cart to P3/S3 location (not over truss segment joint) b. Engage parking brake c. Retrieve 2 Long Duration TieDown (LDTD) tethers from Airlock Staging Bag or P6 AUX Bag (fwd face of Z1) d. Route 1 LDTD tether on stbd side of CETA cart as follows: <ol style="list-style-type: none"> (1) Attach 1 hook to zenith brake handle support tether point (2) Loop tether strap around CETA rail HR standoff (3) Attach second hook to nadir brake handle support tether point (4) Lightly cinch tether and close buckle (5) Close MLI flap over buckle and any excess strap e. Repeat on port side of CETA cart
H. Coupler knob fails to unlock	<ol style="list-style-type: none"> 1. On MCC-H GO: Release active coupler by removing wireties (2) (reinstall of wireties not required) and PIP pins (2) 2. On MCC-H GO: Release passive coupler via EVA bolt: <ul style="list-style-type: none"> PGT: [B7 (25.5), CCW2, 30.5], 7/16-6-ext 9 turns – Bolt is attached by lanyard

15A WORKAROUNDS CRIBSHEET (Cont)






RPCM R&R

A. RPCM jacking bolt will not release	<ol style="list-style-type: none"> 1. Verify socket is fully installed on the bolt (releases the anti-rotation locking tangs) 2. Increase PGT setting to: B1, CCW2, 30.5
B. Spare RPCM did not achieve full turns (6 turns)	<ol style="list-style-type: none"> 1. Verify RET hook installed correctly 2. Remove RPCM with PGT settings: A7, CCW2, 30.5, verify no FOD 3. Reattempt installation with PGT settings: A2, CW2, 30.5 4. If no joy, contact MCC-H
C. Status indicator did not travel to LOCK	As long as torque and turns achieved, no action – press with next task

15A WORKAROUNDS CRIBSHEET (Cont)

EVA 4

JLP GPS ANTENNA

<p>A. OIWIF cannot be locked on dovetail</p>	<ol style="list-style-type: none"> 1. Check for FOD and structural interference 2. Cycle soft dock pins and reattempt installation 3. Verify WIF is co-planar with dovetail 4. Tie down GPS antenna to HR 1268 with long duration tie-down tether 
<p>B. Taping patch came off from antenna bracket</p>  <p><u>Taping patch (3pl)</u></p>  <p><u>Sharp edge</u></p>	<div style="border: 2px solid black; padding: 5px; text-align: center;"> <p>WARNING</p> <p>Do not touch nut retainer on the backside of antenna bracket (sharp edge)</p> </div> <ol style="list-style-type: none"> 1. Inspect gloves 2. Check the backside of antenna bracket and report the location where taping patch is lost to MCC-H 3. Continue the antenna installation without touching the sharp edge 4. Stow the taping patch in small trash bag if possible
<p>C. Connector cap fails to demate</p>	<p>See NZGL section of GENERIC cribsheet</p>
<p>D. Connector fails to mate</p>	<p>See NZGL section of GENERIC cribsheet</p>
<p>E. Connector MLI peeled off from JLP due to MLI torn away from fastener</p>	<ol style="list-style-type: none"> 1. No action required if MLI can stay on JLP with Velcro only 2. After connector cable is installed, tie down the MLI to connector cable with wire tie

Z1 PATCH PANEL

<p>A. NZGL Connectors</p>	<p>See NZGL section of GENERIC cribsheet</p>
---------------------------	--

S1/P1 RADIATOR IMAGERY

<p>A. APFR</p>	<p>See APFR section of GENERIC cribsheet</p>
----------------	--

15A WORKAROUNDS CRIBSHEET (Cont)

WETA INSTALL

A. Dummy box outer bolt does not release	Increase to PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5] for 1 turn, then return to original setting
B. Dummy box center bolt does not release	1. Ensure outer bolts (2) are fully released 2. Increase to PGT [B7 25.5 ft-lb, CCW2 30 RPM, 30.5] for 1 turn, then return to original setting
C. WETA center bolt does not engage	Remove WETA; inspect stanchion interface for FOD or damage; reattempt installation
D. WETA center bolt does not achieve minimum turn count (24 turns)	Increase to PGT [B1 12 ft-lb, CCW2 30 RPM, 30.5]
E. WETA outer bolt does not engage	1. Engage opposite outer bolt; reattempt installation of failed bolt 2. Increase to PGT [B1 12 ft-lb, CCW2 30 RPM, 30.5]

S3 PAS DEPLOYS

A. PAS	See PAS section of EVA 2 cribsheet
--------	------------------------------------

GENERIC

APFR/IAPFR

A. APFR/IAPFR fails to install into WIF	1. Verify APFR collar in install position (black-on-black) 2. Check for FOD in WIF or structural interference 3. Attempt APFR install in alternate clocking 4. If no joy, attempt APFR install in alternate WIF 5. If no joy, APFR failure; use another APFR
B. Joint fails to actuate	1. Verify no load is applied to joint and/or jiggle APFR joint while actuating knob For pitch joint, push knob in during rotation (Class I pitch joints known to be stiff) 2. Increase force applied in order to free joint
C. Boot becomes stuck in APFR boot plate	1. Have other EV crewmember assist with getting boot out 2. Loosen 7/16-in EVA bolts (3) on heel clip using EVA ratchet or PGT: PGT: [B1 (12.0), CCW2, 30.5] 7/16-6-ext 3. Remove 7/16-in EVA bolts (3 – captive) on heel clip (non captive) using EVA ratchet or PGT: PGT: [B1 (12.0), CCW2, 30.5] 7/16-6-ext 5 turns
D. Boot becomes stuck in IAPFR boot plate	1. Have other EV crewmember assist with getting boot out 2. If wearing Small EMU boot, have other EV crewmember adjust boot sizing to Large 3. Loosen 7/16-in EVA bolts (2) on heel clip using EVA ratchet or PGT: PGT: [B2 (16.0), CCW2, 30.5] 7/16-6-ext 4. Remove 7/16-in EVA bolts (2) on heel clip using EVA ratchet or PGT: PGT: [B2 (16.0), CCW2, 30.5] 7/16-6-ext 4 turns

BALLSTACK

A. ECOM fails to release from ISS Structure	On MCC-H GO : Tether ballstack to handrail and leave outside
B. ECOM fails to release from MUT EE	Leave together and return inside
C. Ballstack fails to rigidize	On MCC-H GO : Use secondary tethers to assist in restraining payload

15A WORKAROUNDS CRIBSHEET (Cont)

BRT

A. BRT jaws fail to release	<ol style="list-style-type: none"> 1. Loosen rigidizing collar to relieve sideloads 2. Shake BRT while depressing paddles to alleviate sideloads from handrail 3. Detach BRT from suit and tether to structure
-----------------------------	---

CANNON CONNECTOR

A. Connector fails to release	<ol style="list-style-type: none"> 1. Check for FOD, damage or misalignment 2. Verify cable routing is not impeding connector rotation. (Release TA-clamps as required) 3. Use cannon connector tool for more leverage
B. Connector/Cap fails to softdock	<ol style="list-style-type: none"> 1. Verify collar unlocked (White on connector shell tip should align with white on receptacle backplate) 2. Check for FOD or damage
C. Connector/Cap fails to lock	<ol style="list-style-type: none"> 1. Remove connector/cap, check for FOD or damage 2. Check alignment, remate, rock connector back and forth as required. (Once locked, white on connector shell tip should align with black on receptacle backplate) 3. Use cannon connector tool for more leverage
D. High cable stiffness prevents mating	<ol style="list-style-type: none"> 1. Verify all TA-clamps are released 2. Use second crewmember 3. Use APFR
E. Connector/Jack pin bent	<ol style="list-style-type: none"> 1. Describe pin location and condition; obtain WVS view of interface if possible 2. On MCC-H GO: For 16, 20, or 22 gauge pins only, retrieve pin straightener and attempt pin repair 3. On MCC-H GO: Retrieve needle nose pliers and attempt pin repair MCC-H will verify pin size prior to retrieving tools
F. Connector/Jack FOD	On MCC-H GO: Obtain connector cleaner tool to remove FOD
G. Connector EMI band bent	On MCC-H GO: Obtain needle nose pliers or forceps to remove band

EVA WRENCH (TORQUE AND RATCHET)

A. Ratchet teeth slip	Ratchet to new set of teeth and reapply torque
B. Wrench does not ratchet	Hold the ratchet selector and socket in opposite hands and rotate in opposite directions

FLUID QD OPS – MATING OPS

NOTE

If troubleshooting requires the crew to leave the worksite, verify that female QDs are covered to prevent exposure to direct sunlight. For thermal clocks refer to flight rules

A. QD fails to mate	<ol style="list-style-type: none"> 1. Check for debris, damage, or crystals 2. Verify release ring is retracted. (Fwd white band is not visible) 3. Check alignment and verify no side loads
B. Release ring snap back test fails	<ol style="list-style-type: none"> 1. Push release ring forward. (Release ring will not slide fwd if QD is in FID) 2. QD is in FID; demate QD, verify fwd white band not visible, and remate QD
C. Gap check fails (visual or FID gauge)	Retract release ring, demate QD, verify fwd white band not visible, and remate QD

15A WORKAROUNDS CRIBSHEET (Cont)

FLUID QD OPS – VALVE OPS

<p>A. Detent button is partially unthreaded</p>	<p>Rethread detent button</p> <ol style="list-style-type: none"> a. Load bail handle (button will free spin if not loaded) <ul style="list-style-type: none"> – If valve is open, pull bail handle aft – If valve is closed, push bail handle fwd b. Rotate button CW (8 turns max)
<p>B. Detent button is missing</p> <p style="text-align: center;"><u>NOTE</u></p> <p>Detent button is only required for BDT ops and 1 in SPD ops</p>	<ol style="list-style-type: none"> 1. Use equipment hook to depress detent button shaft 2. Use tether strap around gloved finger to depress detent button shaft 3. Retrieve and use Beta Gimbal Antirotation Latch Tool to depress detent button shaft
<p>C. Bail fails to travel fwd</p>	<p>Check for debris, damage, or crystals</p>
<p>D. Bail fails to travel to full fwd (valve open) position (button does not pop up)</p>	<ol style="list-style-type: none"> 1. Neutralize sideloads 2. Apply greater opening force to QD bail handle
<p>E. Detent button fails to depress during valve closing</p> <div style="border: 2px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Bail may kick back and contact crew when button is depressed if a leaking primary seal allowed pressure build-up in spring cavity</p> </div>	<ol style="list-style-type: none"> 1. Push and hold bail handle fwd (to open) with significant force to relieve load on button while simultaneously depressing the detent button <ul style="list-style-type: none"> – If button depresses, vent by pulling bail aft until release ring covers aft white band – Push bail fwd to valve open and check button depresses 2. On MCC-H GO: Retrieve and install QD button depress tool (BDT)
<p>F. Bail fails to travel to full aft (valve closed) position (button does not pop up)</p>	<ol style="list-style-type: none"> 1. Inspect QD for retaining wire protrusion 2. Neutralize possible side loading 3. Depress button and increase force on bail

FLUID QD OPS – DEMATING OPS

<p>A. Female QD fails to demate</p>	<ol style="list-style-type: none"> 1. Verify release ring is fully retracted while attempting to demate 2. Verify TA or P clamps are released 3. Verify detent button is up 4. Neutralize sideloads or manipulate flexhose to relieve mating forces on female QD 5. Apply greater force to release ring and female QD
<p>B. Thermal bootie fails to remain securely closed</p>	<p>Install wire tie around bootie to keep QD fully covered</p>
<p>C. Cap will not demate</p>	<ol style="list-style-type: none"> 1. Verify pulling out on cap before rotating to ensure locking tab is disengaged 2. Wait for day pass if possible and reattempt cap removal 3. If force is too great for hand actuation or crystals visible around the QD, male may be leaking; notify MCC-H <ul style="list-style-type: none"> – Prepare for quick mate on MCC-H GO 4. Retrieve QD cap tool (either QD Bag on Airlock) <ul style="list-style-type: none"> – Use QD cap tool to turn stuck cap a maximum of 2 turns (cap vents at ~ 2 turns). Finish removal of cap by hand (~ 1 additional turn)

15A WORKAROUNDS CRIBSHEET (Cont)

FLUID QD OPS – LEAKS

A. Mated QD leaks in valve open position (bail fwd)	Close valve (bail aft)
B. Male QD leaks after cap removal	Reinstall cap; notify MCC-H – Prepare for quick QD mate on MCC-H GO
C. Female QD leaks during or after bail actuation to fwd position (valve open)	<ol style="list-style-type: none"> 1. Return bail to aft position (valve closed) 2. Perform release ring snap back test <ul style="list-style-type: none"> – If FID is observed, demate and remate QD – If no FID, neutralize sideloads and push bail to fwd position (valve open)
D. Female QD leaks after demate	Fully mate to destination male as quickly as possible
E. Male QD leaks after demate (male sleeve may be visibly stuck open)	<ol style="list-style-type: none"> 1. Remate female QD and cycle QD valve <ol style="list-style-type: none"> a. Depress button and use significant force to push bail forward; release button (valve open) b. With QD in open position (bail fwd) apply significant force to aft end of the female QD in back and forth, up and down directions c. Depress button and pull bail aft; release button (valve close) d. Demate QD and inspect 2. If applicable, close valve of appropriate QD in flowpath, verify detent button is up, and fwd white line is visible 3. Install cap
F. Leak detected by MCC-H after valve ops to close position (possible male sleeve stuck open)	<ol style="list-style-type: none"> 1. Cycle QD valve <ol style="list-style-type: none"> a. Depress button and use significant force to push bail forward; release button (valve open) b. With QD in valve open (bail fwd) position apply significant force to aft end of the female QD in back and forth, up and down directions c. Depress button and pull bail aft; release button (valve close) d. Demate QD and inspect 2. If applicable, close valve of appropriate QD in flowpath, verify detent button is up, and fwd white line is visible
G. Frozen NH3 present on female or male QD	<ol style="list-style-type: none"> 1. Leave QD exposed to vacuum; wait maximum of 5 min for sublimation (check periodically) 2. On MCC-H GO: Continue QD ops

15A WORKAROUNDS CRIBSHEET (Cont)

FLUID QD OPS – QD BLOCKS

MATE QD

1. Remove QD caps as required
2. Inspect male and female QD for debris or damage
3. Verify female QD ready to mate
 - √Detent button – up
 - √Fwd white band – not visible
4. Assess side load potential prior to mate
5. Mate QD
 - √Fwd white band – visible
6. Perform snapback test
 - √Fwd white band visible
7. Perform pull test (Stay clear of button and release ring)
8. Perform visual gap test
 - √For FID

OPEN VALVE

1. Assess side loads
2. Depress detent button
3. Push bail to forward position
4. √Aft white band visible
5. √Detent button – up

CLOSE VALVE, DEMATE QD

1. √Aft white band visible
2. √Detent button fully installed
3. √Detent button up
4. √Detent button can be depressed
5. Assess side loads prior to bail movement
6. Push bail toward open position with significant force while depressing detent button (unstick male sleeve seals)
7. Depress detent button, move bail aft (close valve)
8. √Fwd white band visible
9. √Detent button up
10. Assess side loads prior to demate
11. Pull back on release ring and demate QD
12. √Release ring – retracted (FWD white band not visible)
13. Inspect male and female QD for debris, damage, or anomalous conditions (ammonia crystals)
14. Install QD caps as required; verify lock tab engaged

MUT EE

A. MUT EE jaws fail to release

1. Verify locking collar fully released
2. Shake MUT EE while depressing paddles to alleviate sideloads from handrail
3. Release MUT EE ECOM socket and tether MUT EE to structure

15A WORKAROUNDS CRIBSHEET (Cont)

MWS

A. MWS EE is sticky	Known problem. Report degree of stickiness to MCC-H and any noted correlation with thermal environment. Post EVA, report s/n of affected unit (s/n located on "stem" of T-bar)
B. MWS EE cord fails to retract	<ol style="list-style-type: none"> 1. Verify MWS EE tether lock in unlock position 2. Cycle MWS EE tether lock 3. Check tether reel opening for FOD 4. Pull out small amount of tether and allow reel to retract while holding light tension on the tether
C. MWS T-bar fails to pivot	<ol style="list-style-type: none"> 1. Check sideloads on T-bar while depressing button 2. Slip T-bar clutch (40-60 lb force required)

NZGL CONNECTORS

A. Bail bar fails to slide over-center	<ol style="list-style-type: none"> 1. Inspect bail for FOD 2. Inspect bail linkage for damage and report to MCC-H 3. Check alignment and sideloads 4. Verify sufficient TA-clamps are open 5. Increase force on bail 6. Attach 2 hooks from adj tether to connector bail and use adj strap to pull bail into demated position 7. On MCC-H GO: Retrieve vise grips to help increase force on bail
B. Backshell fails to slide (after over-center mechanism has been overcome)	<ol style="list-style-type: none"> 1. Verify sufficient TA-clamps are open 2. Check for cable harness and hardware interference 3. Check alignment and sideloads 4. Inspect bail and connector for FOD 5. Inspect bail linkage for damage and report to MCC-H 6. Wiggle/jiggle connector while pushing or pulling on backshell 7. Attach 2 hooks from adj tether to connector bail and use adj strap to pull bail into demated position 8. On MCC-H GO: Retrieve vise grips to help increase force on bail
C. Connector fails to release from soft dock	<ol style="list-style-type: none"> 1. Verify bail fully thrown, undamaged, and backshell fully aft 2. If backshell springs forward, pull and hold in fully aft position (will have to overcome spring force, approx 5-10 lb) while attempting to demate connector 3. Verify sufficient TA-clamps are open 4. Check for cable harness and hardware interference 5. Check alignment and sideloads 6. Relieve compression on connector interface due to cable loads by pulling backshell away from jack 7. Push the plug towards the jack to compress the soft dock 8. Wiggle/jiggle connector. (Use slight rolling motion)
D. Connector fails to soft dock	<ol style="list-style-type: none"> 1. Verify correct plug and jack 2. Verify bail fully aft 3. Verify backshell fully aft and remains fully aft. If backshell not fully aft, pull and hold in fully aft position while attempting to soft dock connector 4. Inspect the following: <ul style="list-style-type: none"> - O-ring seal - FOD - Bend radius - Soft dock springs - Connector keying feature 5. Verify alignment (avoid excessive rolling or rocking the plug as this could unseat soft dock springs) <ul style="list-style-type: none"> - Connector should snap into soft dock with little force once half shells are aligned

15A WORKAROUNDS CRIBSHEET (Cont)

E. Connector fails to mate	<ol style="list-style-type: none"> 1. Verify half-shells are fully seated on both sides 2. Verify cable and backshell free to move (no clamps) 3. Push forward on connector backshell while actuating bail 4. Detach from soft dock and inspect: <ul style="list-style-type: none"> – Pins – FOD – EMI band – Bend radius – TA clamps – P clamps – Bail linkages and rivets – Soft dock springs – O-ring seal and main joint gasket – Connector keying feature 5. Cycle bail while disconnected (push forward on connector backshell for additional leverage)
F. Connector pin bent	<ol style="list-style-type: none"> 1. Rotate connector to bail up position and describe pin location and condition <ul style="list-style-type: none"> – Obtain WVS view of interface if possible 2. On MCC-H GO: For 16, 20, or 22 gauge pins only, retrieve pin straightener and attempt pin repair 3. On MCC-H GO: Retrieve needle nose pliers and attempt pin repair <ul style="list-style-type: none"> – MCC-H will verify pin size prior to retrieving tools 4. Inspect plug and jack prior to re-mating
G. Connector FOD	<ol style="list-style-type: none"> 1. On MCC-H GO: Retrieve connector cleaner tool <p style="text-align: center;"><u>NOTE</u></p> <p>One N2 cartridge is already captured in the tool (the other is lanyarded inside the caddy). In order to puncture the cartridge, it must be threaded into the tool until the indicator line passes out of sight under the collar of the tool.</p> <p>Puncture connector cleaner cartridge only when ready to perform actual cleaning.</p> <p>Use entire N2 cartridge prior to reentering airlock</p> 2. Attempt cleaning
H. Connector EMI band bent	<p>On MCC-H GO: Retrieve needle nose pliers or forceps to remove band</p> <ul style="list-style-type: none"> – Bail may need to be pushed forward while demated to expose EMI band for removal
I. Connector bail linkage failure	<ol style="list-style-type: none"> 1. On MCC-H GO: Re-attempt connector mate/demate with broken bail <ul style="list-style-type: none"> – Impart load through undamaged side of bail linkage – Assist bail motion with hand on backshell once bail linkage has passed over-center – May take multiple pushes on the bail to mate/demate connector 2. Tether hook or vise grips may be used for additional leverage
J. Connector soft dock spring bent	<p>On MCC-H GO: Retrieve needle nose pliers and remove bent spring</p>

15A WORKAROUNDS CRIBSHEET (Cont)

K. Connector O-ring or main joint gasket seal loose (seal and O-ring required in 1-G only)	<ol style="list-style-type: none"> 1. Remove seal with tether hook 2. On MCC-H GO: Retrieve additional tools to remove seal (i.e., wire tie, needle nose pliers, probe, loop pin puller)
L. Connector cap (twist) will not release	<ol style="list-style-type: none"> 1. Increase force 2. Use tether hook for additional leverage

PAD

A. Release knob fails to rotate open	<ol style="list-style-type: none"> 1. Verify knob in release position 2. Attempt to rotate knob using 7/16-in Ratchet on knob's 7/16-in hex stud 3. Release contingency release bar by rotating captive release bolts (2) 5 turns, PGT settings: A6, CCW2, 30.5
B. Release knob fails to rotate close	<ol style="list-style-type: none"> 1. Verify knob in release position 2. Stow PAD, retrieve backup PAD from crew bag NOTE: PAD in crew lock can't be left outside because of paint

PGT

A. No LEDs	<ol style="list-style-type: none"> 1. Perform LED test 2. Use display torque
B. LEDs and torque messages do not agree	Use torque message and notify MCC-H
C. Mode switch breaks	Retrieve spare PGT

LCD MESSAGES

D. BATTERY HITEMP	<ol style="list-style-type: none"> 1. Power off PGT 2. If alternate battery available; change battery 3. Retrieve spare PGT 4. Switch to ratchet mode
E. BATTERY LOTEMP (blinking)	<ol style="list-style-type: none"> 1. Drive tool with no load to increase battery temperature 2. If alternate battery available; power off and change battery 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
F. BATTERY LOVOLT (blinking)	<ol style="list-style-type: none"> 1. Continue using tool until unable to deliver sufficient torque 2. Retrieve spare PGT 3. Power off and switch to ratchet mode
G. CAL FAILED	<ol style="list-style-type: none"> 1. Press, release trigger to repeat calibration 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
H. COLLAR ERROR	<ol style="list-style-type: none"> 1. Cycle torque and speed collars to clear error 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
I. COMPAR ERROR	<ol style="list-style-type: none"> 1. Cycle torque collar and A/B mode switch 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
J. EEPROM WR ERR (blinking) HYBRID HITEMP OVER CURR SLFTST FAIL X	<ol style="list-style-type: none"> 1. Power cycle and calibrate 2. Retrieve spare PGT 3. Power off and switch to ratchet mode
K. HI TORQ	<ol style="list-style-type: none"> 1. Contact MCC-H and report torque (Real time engineering assessment required) 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode

15A WORKAROUNDS CRIBSHEET (Cont)

L. HICURR	<ol style="list-style-type: none"> 1. Reattempt operation <ul style="list-style-type: none"> – Can be caused by excessive rotation of the PGT body while torquing 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
M. LO TORQ (Expected during bolt release)	<ol style="list-style-type: none"> 1. Reattempt operation until desired torque is reached 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
N. LOCURR	<ol style="list-style-type: none"> 1. Reattempt operation 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
O. LOG IS FULL (blinking)	<ol style="list-style-type: none"> 1. Cycle torque and speed collars to clear message 2. Continue operation
P. MOTOR HITEMP	<ol style="list-style-type: none"> 1. Power off PGT 2. Retrieve spare PGT 3. Switch to ratchet mode


SAFETY TETHER

A. Safety tether fails to retract/tend	<ol style="list-style-type: none"> 1. Verify reel is unlocked 2. Verify tether reel and/or cable guide (for 85-ft tethers) is clear of FOD 3. Pull out small amount of cable and allow reel to retract while holding light tension on the cable 4. Tap side of reel housing during retraction 5. Report ID # of faulty tether to MCC-H and use alternate safety tether 6. Coil safety tether to bring inside 7. For 85-ft tether, on MCC-H GO: If coiling tether is not practical, release level wind mechanism bypass on back of safety tether (Red indicator will show around edge of bypass once released) <p style="text-align: center;"><u>NOTE</u></p> <p>Once level wind has been released, cable guide will likely be frozen in place. This will limit the amount of tether that can be successfully retracted into the tether housing and may require coiling of excess tether.</p> <p>Level wind release will require safety tether be returned for ground servicing.</p> <p>If tether fails to retract due to thermal issue, normal tether function may return after tether brought IVA</p>
B. Safety tether red stripe showing (any length)	<p>Safety tether cannot be used</p> <ul style="list-style-type: none"> – Report ID # of faulty tether to MCC-H – Use alternate safety tether
C. Crew hook fails	<ol style="list-style-type: none"> 1. On load alleviating end: Use waist tether to replace alleviating strap <ul style="list-style-type: none"> – Report ID # of faulty tether to MCC-H – Retrieve replacement safety tether 2. On anchor end: Report ID # of faulty tether to MCC-H and use an alternate safety tether

15A WORKAROUNDS CRIBSHEET (Cont)

SCOOPS

A. Scoop will not release from fitting	<ol style="list-style-type: none"> 1. If actuator will not pull back while in locked position, tap actuator with tool to release 2. On MCC-H GO: Leave scoop in place 3. On MCC-H GO: Remove non-captive contingency screws; 5 turns: PGT [A1 (7.0), CCW2, 30.5], 5/32 Allen drive – Round Scoop: 7 screws (see figure)
--	---



Round Scoop

SOCKET CADDY

A. Socket fails to release from socket caddy	<ol style="list-style-type: none"> 1. Verify PIP pin fully inserted into drop proof tether interface on socket 2. Reattempt using a different PIP pin
--	---


TA CLAMP

A. TA clamp fails to release	<ol style="list-style-type: none"> 1. With handle up, press down on top of rounded clamp 2. With handle up, use tether hook to pry drawhook from capture pin
------------------------------	--

TETHER SHUTTLE

A. Tether shuttle will not release from CETA/MT rail	<p>On MCC-H GO: Remove non-captive screws (2) at hingeline to release nadir section with slide lock (not captive) (see figure): PGT [A7 (9.2), CCW1, 30.5], 5/32 Allen drive</p>
--	---

15A WORKAROUNDS CRIBSHEET (Cont)




Tether Shuttle

TORQUE MULTIPLIER

D. TM will not release from fitting

1. Place TM anti-backlash in neutral, if unable:
PGT [RCW, 30.5]
– Apply cw torque while pushing anti-backlash button to neutral. Reattempt removal
2. If able to lift TM off of bolt, attempt to rock off of fitting (Square TM only)
3. On **MCC-H GO**: Release TM contingency release band pin 20 turns (do not exceed 28 turns):
PGT [A1 (7.0), CCW2, 30.5], 5/32 ball end driver
– When band springs open remove TM



Torque Multiplier

15A WORKAROUNDS CRIBSHEET (Cont)

TSA (HWTSA)

A. Latch fails to open	Release 7/16 EVA bolt on latch bracket; rotate bracket clear of latch PGT [A2 3.8 ft-lb, CCW2, 30.5]-6-ext 7/16 Loosen bolt 1-2 turns
B. Latch fails to close	Close remaining latches (1 of 2 required for landing)

S5/S6
ATTACH


16.1a RTAS GAP CLOSURE (CORNER 1 OR 2)

During ATTACH S6 to S5
Gap > 0.6 after CLA closure
Assumes CLA had ~126 turns
(127 total, one turn previously completed) and torqued to HS

As required, unbolt Gap Check Tool Bolt (2) (also called Contingency Spacer Lock Tool)

PGT, 7/16-6 in ext; A6, CCW2; 12-14 turns

Stow tool in C/L bag or trash bag after operations



① Gap = distance between passive and active RTAS housings. Gap must not be greater than 0.6 in prior to driving primary bolt. Gap must not be greater than 0.478 in after primary bolt is driven to allow for shear loading. Measuring tools: Small crew hook = 0.430 in; drop proof tether end of 7/16 in-6 in ext = 0.66 in; S5/P5 contingency spacer locking tool thickness range = 0.3 to 0.6 in

② Structure warped or hardware interference (hardware interference more likely)

③ S6 might 'rock' such that gap appears on different corner. If Corner 1 meets gap criteria and one other corner does not meet gap criteria, continue with nominal procedure for corner 1 and then re-assess affected corner

S5/S6 ATTACH

16.1a (Cont)

11

13

- Remove PRD
- SSRMS brakes ON
- Release corner 1 if required
PGT, 5/8-7.8 in ext: B7, CCW2; 27 turns, √2-7 threads visible
- Verify separation plane clear
- Open CLA fully
PGT, 7/16-6 in ext: A6, CCW3; 55 turns or as required to HS
- SSRMS drive S6 out to 30 cm or as required to allow EV crew to visually and tactilely assess S6 nuts/bearings
- EV crew assess whether primary bearing is centered and capable of sliding from sliding ~0.160" in all directions for corner 1 or side to side for corner 2. Center S6 bearing as required
- Verify no FOD between elements, in S6 nuts, in coarse alignment holes/cones
- Perform nominal GCA and bolting procedure and re-enter RTAS GAP CLOSURE as required

14

- If no joy, √MCC-H


16.1b RTAS GAP CLOSURE (CORNER 3 OR 4)

During ATTACH S6 to S5
Gap > 0.6 after CLA closure and corner 1, 2 successful install to initial torque

As required, unbolt Gap Check Tool Bolt (2) (also called Contingency Spacer Lock Tool)

PGT, 7/16-6 in ext; A6, CCW2; 12-14 turns.

Stow tool in C/L bag or trash bag after operations



1
Gap = distance between passive and active RTAS housings. Gap must not be greater than 0.6 in prior to driving primary bolt. Gap must not be greater than 0.478 in after primary bolt is driven to allow for shear loading. Measuring tools: Small crew hook = 0.430 in; drop proof tether end of 7/16 in-6 in ext = 0.66 in; S5/P5 contingency spacer locking tool thickness range = 0.3 to 0.6 in

2
Structure warped or hardware interference (hardware interference more likely)

CAPTURE BAR ROTATION (00:30)

IV	EV1	EV2
<p>1. √SSRMS grappled, brakes on</p>	<p><u>ROTATE S6 CAPTURE BAR</u></p> <ol style="list-style-type: none"> 1. Retrieve 7/16-18-in ext socket from Z1 port toolbox 2. Partially open S5 CLA (capture latch) PGT, 7/16-6-in ext: A6, CCW3; 75 turns <p style="text-align: center;"><u>NOTE</u></p> <p style="text-align: center;">EV may need to remove MWS to ingress long spacer.</p> <p style="text-align: center;">If APFR access required, check MCC for settings</p> <ol style="list-style-type: none"> 3. Open S6 thermal shroud flap to access capture bar if not done previously 4. Loosen capture bar disk clamp bolt PGT, 7/16-18-in ext; A7, CCW2; ~2.5-3 turns to HS 5. Manually turn capture bar disk center bolt PGT, 7/16-18-in ext; RCCW, turn until clamp bolt is at end of disc slot (rotating capture bar to re-engaged position; black on black) 6. Tighten capture bar disk clamp bolt PGT, 7/16-18-in ext; A5, CW2; ~2.5-3 turns to HS 7. Close S6 thermal shroud 8. Close S5 CLA (capture latch) per nominal procedure 	

CAPTURE BAR ROTATION – TASK DATA

EVA Tools:

EV1 (FF)	EV2 (FF)
PGT	N/A
7/16-18-in ext	
7/16-6-in ext	

EVA Fasteners:

Fastener	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Capture bar disk clamp bolt	7/16-in	1	7.0	9.2	13.1 (rel) 10.6 (inst)	2.5-3.0	30
Capture bar disk center bolt	7/16-in	1	N/A	30.5	116.8	.33	N/A

EVA Connectors: None

Foot Restraints:


Task	WIF	APFR Setting

Warnings:

Cautions:

Notes:

1. Crewmember may need to remove MWS to ingress long spacer




ATTACH S6 TO S5 USING CONTINGENCY FASTENERS

IV	EV1	EV2
<p>1. Initial RTAS gap: _____</p> <p>2. Circle which contingency sleeve used: Left or Right</p>	<p style="text-align: center;"><u>NOTE</u></p> <p>EVA worksite per nominal bolt engagement.</p> <p>Contingency Spacer Lock Tools are at S5 inboard and outboard RTAS corner 1.</p> <p>Only one Contingency Fastener is required</p> <ol style="list-style-type: none"> 1. Remove ground straps if required 2. Unbolt Gap Check Tool Bolt (2) (also called Contingency Spacer Lock Tool) PGT, 7/16-6-in ext; A6,CCW2; 12-14 turns 3. Measure RTAS gap, record gap <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Do not loosen S5 contingency spacer locking bolt more than 1 turn. Excessive turns of spacer locking bolt may cause guide washer to come out of slot and snap ring washer to bend</p> </div> <ol style="list-style-type: none"> 4. Loosen contingency spacer locking bolt PGT, 7/16-6-in ext; B2,CCW1; 1 turn only 5. Tighten spacer sleeve until snug against S6 spherical bearing (~10 turns cw) 6. Notify IV which contingency sleeve used ("Left" or "Right" when looking at corner number) 7. Verify spacer sleeve aligned within nut by jiggling back end of S6 contingency ball/nut <p style="text-align: center;"><u>NOTE</u></p> <p>Contingency spacer sleeve may need to be rotated to allow tool installation, prefer ccw rotation</p> <ol style="list-style-type: none"> 8. Install Contingency Spacer Lock Tool over contingency spacer sleeve (friction fit) 9. Fasten contingency spacer locking bolt PGT, 7/16-6-in ext; B2,CW1; 1 turn only 10. Tighten RTAS contingency bolt PGT, 7/16-6-in ext; B1,CW2; 7-9 turns. Bolt will come out of launch position and move ~2 in fwd 11. Push bolt ~0.5 in to contact nut 	

ATTACH S6 TO S5 USING CONTINGENCY FASTENERS (Cont)

IV	EV1	EV2
<p>3. Final RTAS gap: _____</p>	<ol style="list-style-type: none"> 12. Continue to tighten RTAS contingency bolt PGT, 7/16-6-in ext; B1,CW2; 9.5-11.5 turns to HS 13. Torque RTAS contingency bolt Torque Wrench, 7/16-6-in ext; 57 ft-lb 14. Remove Contingency Spacer Lock Tool from sleeve 15. Measure gap; report to MCC-H 16. Stow Contingency Spacer Lock Tool in trash bag 17. Remove spherical bearing locking plate bolt on S6 PGT, 7/16-6-in ext; A5,CCW2; 12-14 turns 18. Stow plate with wire tie to adjacent handrail 19. Install ground strap per nominal ATTACH S6 TO S5 procedure 	



ATTACH S6 TO S5 USING CONTINGENCY FASTENERS – TASK DATA

EVA Tools:

EV1 (FF)	EV2 (FF)
PGT	N/A
7/16-6-in ext	
Torque Wrench	

EVA Fasteners:

Fastener	Head Size	Qty	Ground Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Gap Check Tool bolt (Contingency spacer lock tool bolt)	7/16-in	2/Tool	~4	4.3	12.2	12-14	30
Contingency spacer locking bolt	7/16-in	1/RTAS	~7	16	31.1	1 turn max	N/A
RTAS contingency bolt	7/16-in	2/RTAS	57	N/A	115.2	7-9: Release from uplock 9.5-11.5: Install	30
Spherical bearing locking plate bolt	7/16-in	1/RTAS	~3.0	3.0	12.2	12-14	10

EVA Connectors: None

Foot Restraints: See nominal procedure

Warnings:


Cautions:

- Do not loosen S5 contingency spacer locking bolt more than 1 turn. Excessive turns of spacer locking bolt may cause guide washer to come out of slot and cause snap ring washer to bend

Notes:


- EVA worksite per nominal bolt engagement. Contingency spacer lock tool is at RTAS corner #1 on inboard and outboard of S5
- If contingency spacer sleeve needs to be rotated to allow tool installation, rotate ccw
- Contingency bolt will come out of launch position and move ~2 in fwd after 7 turns

PRD S5-S6 OVERVIEW




PRD RTAS CORNER 1 (PRIMARY)

PRD RTAS Corner 1





PRD RTAS CORNER 1 (PRIMARY) NBL




PRD RTAS CORNER 2

PRD RTAS Corner 2






PRD RTAS CORNER 3




PRD RTAS CORNER 3 NBL (STRAP ROUTING)



PRD RTAS CORNER 3 NBL (STRAP ROUTING) (Cont)




PRD RTAS CORNER 3 NBL




PRD RTAS CORNER 4 (PRIMARY)


PRD RTAS Corner 4



PRD RTAS CORNER 4 (PRIMARY) NBL



PRD RTAS CORNER 4 (PRIMARY) (STRAP ROUTING)




FS 16-41

EVA/119/FIN A

PVR

This Page Intentionally Blank

S6 RADIATOR MANUAL OVERRIDE TO DEPLOY/RETRACT

IV	EV1	EV2
<p>MCC-H 1. Verify PVR motor OFF</p> <p style="text-align: center;"><u>NOTE</u> Free Drift or CMG Control with Thrusters Disabled is required while radiator is being deployed/retracted. Applies only while mechanisms are in motion</p> <p>MCC-H 2. Configure ISS/Orbiter attitude control to CMG Control with thrusters disabled or Orbiter and ISS in free drift</p> <p>IV 3. Give EV crew GO for extend/retract radiator</p> <p>IV 4. On EV GO, cmd nominal attitude control</p> <div style="text-align: center;">  </div>	<p><u>MANUAL OVERRIDE TO EXTEND (RETRACT) RADIATOR</u></p> <ol style="list-style-type: none"> If required, APFR, set up and ingress (see Task Data for WIF position and APFR settings) On IV GO, release PVR MDA fastener H32 PGT, 7/16-6-in ext; B1 (12 ft-lb), CCW2 (CW2) 30 RPM, MTL 30.5; push to engage (5 lb) ~45 turns to HS If required to re-engage H32 locking collar PGT, 7/16-6-in ext; RCCW (RCW), MTL 30.5; ~1/6 turn until collar pops up completely and re-engages Report to IV, radiator deployment (retraction) complete <p>If retracting, re-install PVR cinches using the procedure below. Manual compression of the radiator panels may be required to install cinches (two crewmember operation):</p> <ul style="list-style-type: none"> <input type="checkbox"/> Cinch H11 <input type="checkbox"/> Cinch H13 <input type="checkbox"/> Cinch H15 	<p>If retracting, re-install PVR cinches using the procedure below. Manual compression of the radiator panels may be required to install cinches (two crewmember operation):</p> <ul style="list-style-type: none"> <input type="checkbox"/> Cinch H12 <input type="checkbox"/> Cinch H14 <input type="checkbox"/> Cinch H16

S6 RADIATOR MANUAL OVERRIDE TO DEPLOY/RETRACT (Cont)

IV	EV1	EV2
	<p>REINSTALL PVR CINCHES</p> <ol style="list-style-type: none"> Position for cinch H11 installation Verify cinch H11 bolt is engaged in last thread (to maximize clearance); verify fixed end pulled all the way out and seated properly in bracket Compress radiator panels and assess cinch H11 installation If EV1 and EV2 both GO for cinch install Give EV2 GO for cinch install, install cinch H11 Remove winch bar PIP pin (H33); align winch bar clevis to lug on radiator; re-install PIP pin If NO GO for cinch install, assess winch bar installation If GO for winch installation: <ol style="list-style-type: none"> Remove winch bar PIP pin (H33) Give EV2 GO for winch install, compress radiator panels, align winch bar clevis to lug on radiator, re-install PIP pin Remove FQDC shroud per steps below Retract winch per steps below Replace FQDC shroud per steps below If NO GO for winch install: <ol style="list-style-type: none"> Remove FQDC shroud per steps below Extend winch per steps below Remove winch bar PIP pin (H33) Give EV2 GO for winch install; align winch bar clevis to lug on radiator; re-install PIP pin Retract winch per steps below Replace FQDC shroud per steps below Install cinch H11 Tension cinch H11 PGT, 7/16-6-in ext; A3 (4.8 ft-lb), CW2 (30 RPM), MTL 30.5; push 5 lb, ~6-14 turns to HS Install and tension cinches H13 and H15 PGT, 7/16-6-in ext; A3 (4.8 ft-lb), CW2 (30 RPM), MTL 30.5; push 5 lb, ~6-14 turns to HS, each 	<p>REINSTALL PVR CINCHES</p> <ol style="list-style-type: none"> Position for cinch H12 installation Verify cinch H12 bolt is engaged in last thread (to maximize clearance); verify fixed end pulled all the way out and seated properly in bracket Compress radiator panels and assess cinch H12 installation If EV1 and EV2 GO for cinch install On GO from EV1, install cinch H12 Remove winch bar PIP pin (H34); align winch bar clevis to lug on radiator; re-install PIP pin If NO GO for cinch install, assess winch bar installation If GO for winch installation: <ol style="list-style-type: none"> Remove winch bar PIP pin (H34) On GO from EV1, compress radiator panels, align winch bar clevis to lug on radiator, re-install PIP pin If NO GO for winch install: <ol style="list-style-type: none"> Remove winch bar PIP pin (H34) On GO from EV1, compress radiator panels, align winch bar clevis to lug on radiator, re-install PIP pin Install cinch H12 Tension cinch H12 PGT, 7/16-6-in ext; A3 (4.8 ft-lb), CW2 (30 RPM), MTL 30.5; push 5 lb, ~6-14 turns to HS Install and tension cinches H14 and H16 PGT, 7/16-6-in ext; A3 (4.8 ft-lb), CW2 (30 RPM), MTL 30.5; push 5 lb, ~6-14 turns to HS, each
<p><u>Cinch (Initial Torque)</u> <u>Torque/Turns</u></p> <p>H11 / _____</p> <p>H12 / _____</p> <p>H13 / _____</p> <p>H14 / _____</p> <p>H15 / _____</p> <p>H16 / _____</p> <p><u>Cinch (Final Torque)</u> <u>Torque/Turns</u></p> <p>H11 / _____</p> <p>H12 / _____</p> <p>H13 / _____</p> <p>H14 / _____</p> <p>H15 / _____</p> <p>H16 / _____</p> <p><u>Cinch (Manual Torque)</u> <u>Turns</u></p> <p>H11 _____</p> <p>H12 _____</p> <p>H13 _____</p> <p>H14 _____</p> <p>H15 _____</p> <p>H16 _____</p>		

S6 RADIATOR MANUAL OVERRIDE TO DEPLOY/RETRACT (Cont)

IV	EV1	EV2
	<p>24. Tighten cinch H11 PGT, 7/16-6-in ext; A3 (4.8 ft-lb), CW2 (30 RPM), MTL 30.5; push 5 lb, turn to HS</p> <p>25. Tighten cinch H11 PGT, 7/16-6-in ext; RCW, MTL 30.5; 3/4 turn</p> <p>26. Verify anti-rotation device is up; if not, rotate bolt cw until up, max 60 deg</p> <p>27. Tighten cinches H13 and H15 PGT, 7/16-6-in ext; A3 (4.8 ft-lb), CW2 (30 RPM), MTL 30.5; push 5 lb, turn to HS</p> <p>28. Tighten cinches H13 and H15 PGT, 7/16-6-in ext; RCW, MTL 30.5; 3/8 turn</p> <p>29. Verify anti-rotation device is up; if not, rotate bolt cw until up, max 60 deg (x2)</p> <p><u>REMOVE FQDC SHROUD</u></p> <ol style="list-style-type: none"> 1. Stage RET for FQDC shroud restraint 2. Release FQDC shroud bolts (4) PGT, 7/16-6-in ext; A7 (9.2 ft-lb), CCW2 (30 RPM), MTL 30.5, 7 turns 3. Restrain FQDC shroud w/RET <p><u>EXTEND WINCH</u></p> <ol style="list-style-type: none"> 1. Actuate H10 bolt PGT, 7/16-6-in ext; A1 (2.5 ft-lb), CW1 (10 RPM), MTL 30.5; push 5 lb, extend winch bars until winch bar clevis aligns with radiator lug (=20 turns max) <p><u>RETRACT WINCH</u></p> <ol style="list-style-type: none"> 1. PGT[A1 2.5 ft-lb, CCW1 10 RPM, MTL 30.5]-6ext 7/16: Actuate H10 bolt, push 5 lb, fully retract winch bars (~25 turns max) <p><u>REPLACE FQDC SHROUD</u></p> <ol style="list-style-type: none"> 1. Retrieve FQDC Shroud 2. Engage FQDC shroud bolts (4) PGT, 7/16-6-in ext; A7 (9.2 ft-lb), CW2 (30 RPM), MTL 30.5, 7 turns to HS 3. Retrieve RET 	<p>17. Tighten cinch H12 PGT, 7/16-6-in ext; A3 (4.8 ft-lb), CW2 (30 RPM), MTL 30.5; push 5 lb, turn to HS</p> <p>18. Tighten cinch H12 PGT, 7/16-6-in ext; RCW, MTL 30.5; 3/4 turn</p> <p>19. Verify anti-rotation device is up; if not, rotate bolt cw until up, max 60 deg</p> <p>20. Tighten cinches H14 and H16 PGT, 7/16-6-in ext; A3 (4.8 ft-lb), CW2 (30 RPM), MTL 30.5; push 5 lb, turn to HS</p> <p>21. Tighten cinches H14 and H16 PGT, 7/16-6-in ext; RCW, MTL 30.5; 3/8 turn</p> <p>22. Verify anti-rotation device is up; if not, rotate bolt cw until up, max 60 deg (x2)</p>

S6 RADIATOR MANUAL OVERRIDE TO DEPLOY/RETRACT – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	00:30 (E)
Two EV Crew	N/A	01:30 I

Tools:

EV1	EV2
PGT	PGT
7/16-6-in ext	7/16-6-in ext
APFR	
RET	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Max Break Away Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
PVR MDA	H32	7/16-in	1	12.0	19.1*	25.2	45-50	30
Cinch bolts	H11-H12	7/16-in	2	4.8	15.8	35.7	8-14	30
Cinch bolts	H13-H16	7/16-in	4	4.8	24.6	39.7	8-14	30
FQDC Shroud bolts	H5, H6, H8, H9	7/16-in	4	9.2	6.7	21.2 I 18.1 (I)	7	30
Winch bolt	H10	7/16-in	1	2.5	4.4*	6.4	25 I 20 (I)	30

*Indicates Max On-Orbit Installation Torque

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting
PVR MDA worksite	S6 – 16	(5,PP,E,1)

Mass: N/A

Notes:


- Free drift or CMG Control with Thrusters Disabled is required while radiator is being deployed/retracted. Applies only while mechanisms are in motion

Cautions:

- Equipment damage. Avoid contact with radiator bellows
- Winch mechanism extension may fail due to excess slack if extended beyond 20 turns from launch state, or beyond 25 turns from fully retracted state
- Avoid putting high axial loads on winch bolt; retaining mechanism for locking device may fail. Still usable if failure occurs, but no locking capability


Warnings:

- Moving equipment. Avoid contact with panels and mechanisms during extension of radiator



PVR FQDC

S6 RADIATOR MANUAL OVERRIDE TO DEPLOY/RETRACT – TASK DATA (Cont)




PV Radiator – MDA H32 Fastener Located Near Ground Strap




PV Radiator MDA Fastener

PVR EVA Interfaces



PVR




FQDC Shroud

FQDC


- H5,6,9,8 = FQDC Shroud Fasteners
- H7 = FQDC Shroud Alignment Pin
- H10 = Winch Drive
- H11 - H16 = Cinches
- H17 = Grounding Strap
- H18 - H19 = FQDC Drive bolts
- H20 - H21 = Carrier Slider bolts
- H22 - H23 = Carrier to PVR Attach
- H24 - H25 = Carrier to IEA Attach
- H26 - H27 = Center Bolts
- H28 - H31 = Corner Bolts
- H32 = Manual Deploy/Retract
- H33-H34 = Winch PIP pins

SAW


PRD 4-BAR ROUTING




PRD 4-BAR ROUTING (Cont)



PRD 4-BAR ROUTING (Cont)



PRD 4-BAR ROUTING (Cont)



MANUAL OVERRIDE TO DISENGAGE BETA GIMBAL ANTI-ROTATION LATCH (01:00)

TIME (HR:MN)	IV/RMS	EV1	EV2
01:00	<p>MCC-H 1. BGA XX(YY) ANTI-ROTATION LATCH FAIL TO UNLATCH REMOTELY (ISS EPS GENERIC, <u>MALFUNCTION PROCEDURES</u>)</p> <p>IV PCS 2. Determine Anti-rotation latch posn S6: EPS: BGA XX(YY) <u>BGA XX(YY)</u></p> <p>'ECU XX(YY)' Verify Integ Cnt – Incrementing</p> <p>'BGA XX(YY)' Record Actual Angle = _____deg Motor State - _____ Latch 1 Pin Status - _____ Latch 2 Pin Status - _____</p> <p>Refer to BMRRM Anti-Rotation Latch Table to determine beta gimbal anti-rotation latch access hole: Anti-rotation latch posn = (Hole#)</p> <p>IV PCS 3. \sqrtAnti-rotation latch released S6: EPS: BGA 4B(2B) <u>BGA XX(YY)</u></p> <p>'ECU XX(YY)' Verify Integ Cnt – Incrementing</p> <p>'BGA XX(YY)' Verify: Latch 1 Pin Status – Unlatched Latch 2 Pin Status – Unlatched</p>	<p>Stbd Tool Box/QD BDT Board: Obtain BMRRM anti-rotation latch tool</p> <p>1. \sqrtMCC-H for APFR setting</p> <p>2. Insert tool into designated beta gimbal hole to depress and release anti-rotation latch. Use indicator mark on tool for correct insertion depth</p>	<p>S6 could be S4, P4, or P6 depending on failure</p>

BMRRM ANTI-ROTATION LATCH TABLE

Hole	Latch 1 Angle	Latch 2 Angle	Cable Restricts Access		
1	0	267.1875			
2	5.625	272.8125			
3	11.25	278.4375			
4	16.875	284.0625			
5	22.5	289.6875			
6	28.125	295.3125	J1 – Primary Power		
7	33.75	300.9375	J1 – Primary Power		
8	39.375	306.5625	J1 – Primary Power		
9	45	312.1875	J1 – Primary Power		
10	50.625	317.8125			
11	56.25	323.4375			
12	61.875	329.0625			
13	67.5	334.6875			
14	73.125	340.3125			
15	78.75	345.9375			
16	84.375	351.5625			
17	90	357.1875			
18	95.625	2.8125			
19	101.25	8.4375			
20	106.875	14.0625			
21	112.5	19.6875			
22	118.125	25.3125			
23	123.75	30.9375	J4 – 1553 Bus B		
24	129.375	36.5625	J4 – 1553 Bus B		
25	135	42.1875	J4 – 1553 Bus B		
26	140.625	47.8125			
27	146.25	53.4375			
28	151.875	59.0625			
29	157.5	64.6875			
30	163.125	70.3125			
31	168.75	75.9375			
32	174.375	81.5625			
33	180	87.1875			
34	185.625	92.8125			
35	191.25	98.4375			
36	196.875	104.0625			
37	202.5	109.6875			
38	208.125	115.3125			
39	213.75	120.9375			
40	219.375	126.5625			
41	225	132.1875			
42	230.625	137.8125	J2 – Secondary Pwr (RPCM XX A RPC 2)		
43	236.25	143.4375	J2 – Secondary Pwr (RPCM XX A RPC 2)		
44	241.875	149.0625	J2 – Secondary Pwr (RPCM XX A RPC 2)		
45	247.5	154.6875			
46	253.125	160.3125			
47	258.75	165.9375			
48	264.375	171.5625			
49	270	177.1875			
50	275.625	182.8125			
51	281.25	188.4375	J3 – 1553 Bus A and Sec Pwr (RPCM XX A RPC 1)		
52	286.875	194.0625	J3 – 1553 Bus A and Sec Pwr (RPCM XX A RPC 1)		
53	292.5	199.6875	J3 – 1553 Bus A and Sec Pwr (RPCM XX A RPC 1)		
54	298.125	205.3125			
55	303.75	210.9375			
56	309.375	216.5625			
57	315	222.1875			
58	320.625	227.8125			
59	326.25	233.4375			
60	331.875	239.0625			
61	337.5	244.6875			
62	343.125	250.3125			
63	348.75	255.9375			
64	354.375	261.5625			

MANUAL RELEASE OF SABB RESTRAINT PINS

IV	EV
<ol style="list-style-type: none">1. Position applicable BGA to angle per Task Data page2. Secure BGA3. Give EV crew GO to enter worksite	<div data-bbox="852 305 1577 518" style="border: 2px solid black; padding: 5px;"><p style="text-align: center;"><u>WARNING</u></p><p>Sharp edge/pinch point/entrapment hazard: Avoid contact with outboard underside of SABB due to exposed reels, guide-wire and tension mechanisms</p><p>Collision hazard: BRS Pin will extend ~1 inch from bottom of box when fired. Keep EMU and tools out of this area</p></div> <div data-bbox="852 553 1474 683" style="border: 1px solid black; padding: 5px;"><p style="text-align: center;"><u>CAUTION</u></p><p>Actuation of BRS trigger with probe tool should not require excessive force. Application of excessive force may damage the BRS pin tool</p></div> <ol style="list-style-type: none">1. Set up and ingress APFR (see Task Data page)2. Induce sharp rap(s) to side of BRS pin housing with the hammer to release3. If no joy, use the BRS pin release tool to actuate the trigger in the direction indicated by the arrow

MANUAL RELEASE OF SABB RESTRAINT PINS – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	01:00
Two EV Crew	N/A	N/A

Tools:

EV1	EV2
APFR	N/A
Ingress aid	
BRS Pin Contingency Tool	
Hammer	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
N/A								

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints, Right SABB settings are in ():

IEA Side	Task	WIF	APFR Setting	BGA Angle
Non-Keel	Left (Right) SABB BRS Pin #1	S4-26, S6-38	12,FF,F,1 (6,FF,G,3)	284 (53)
	Left (Right) SABB BRS Pin #2	S4-26, S6-38	12,FF,F,9 (12,FF,G,3)	265 (78)
	Left (Right) SABB BRS Pin #3	S4-15, S6-27	10,FF,D,9 (9,FF,G,4)	281 (90)
	Left (Right) SABB BRS Pin #4	S4-15, S6-23	3,FF,F,8 (9,GG,G,3)	281 (90)
	Left (Right) SABB BRS Pin #5	S4-15, S6-27	3,FF,F,8 (3,GG,G,3)	281 (90)
	Left (Right) SABB BRS Pin #6	S4-11, S6-23	5,II,F,6 (7,FF,E,10)	281 (95)
	Left (Right) SABB BRS Pin #7	S4-11, S6-23	9,JJ,E,7 (7,KK,F,5)	281 (101)
Keel	Left (Right) SABB BRS Pin #1	S4-25, S6-37	12,FF,F,1 (6,FF,G,3)	284 (53)
	Left (Right) SABB BRS Pin #2	S4-25, S6-37	12,FF,F,9 (12,FF,G,3)	265 (78)
	Left (Right) SABB BRS Pin #3	S4-13, S6-25	10,FF,D,9 (9,FF,G,4)	281 (90)
	Left (Right) SABB BRS Pin #4	S4-13, S6-21	3,FF,F,8 (9,GG,G,3)	281 (90)
	Left (Right) SABB BRS Pin #5	S4-13, S6-27	3,FF,F,8 (3,GG,G,3)	281 (90)
	Left (Right) SABB BRS Pin #6	S4-09, S6-21	5,II,F,6 (7,FF,E,10)	281 (95)
	Left (Right) SABB BRS Pin #7	S4-09, S6-21	9,JJ,E,7 (7,KK,F,5)	281 (101)

Notes:

- When the trigger is actuated, the slider will slide down and lock the trigger in the actuated position. If the slider has moved down, the BRS pin may be have not fired due to solar array panel side loads
- If trigger/slider is not in actuated position, trigger must be actuated manually with probe tool
- Arrows (←) indicate direction of trigger actuation
- All triggers are on the MDA side of BRS pin
- Pin 3 is a blind operation, and pins 4, 5 require bending metal for access
- Some APFR settings have a body position that is rather close to the lower blanket box; in these instances, the ingress aid may be used to control body positioning to avoid hitting the helmet against the SABB



Cautions:

- Actuation of BRS trigger with probe tool should not require excessive force. Application of excessive force may damage the BRS pin tool

Warnings:

- Sharp edge/pinch point/entrapment hazard: Avoid contact with outboard underside of SABB due to exposed reels, guide-wire and tension mechanisms
- Collision hazard: BRS Pin will extend ~1 inch from bottom of box when fired. Keep EMU and tools out of this area

MANUAL RELEASE OF SABB RESTRAINT PINS – TASK DATA (Cont)



MANUAL OVERRIDE TO UNLATCH/LATCH (TENSION) SABB

IV/RMS	EV
<p>Identify Affected Power Channel XX = _____</p> <p>IF UNLATCHING SABB MCC-H 1. Perform {3.190 SAW XX FAILURE TO UNLATCH SABB REMOTELY} (SODF: EPS: MALFUNCTION: PRIMARY POWER) IV 2. GO for EV crew ingress at worksite</p> <p>IF TENSIONING SABB MCC-H 1. Perform {3.193 SAW XX FAILURE TO LATCH (TENSION) SABB REMOTELY} SODF: EPS: MALFUNCTION: PRIMARY POWER</p> <p>THEN:</p> <p>IV 2. If required (see Task Data notes), Verify affected SABB positioned over the IEA and BGA latched PCS PVM: EPS: BGA XX <u>BGA XX</u> 'ECU XX' Verify: Integ Cnt – Incrementing 'BGA XX' Verify: Actual Angle, deg = 270.000 (± 0.5) (Left SABB) OR Actual Angle, deg = 90.000 (± 0.5) (Right SABB) Motor State – OFF Latch 1 Pin Status – Latched</p> <p>IV 3. GO for EV crew ingress at worksite <u>NOTE</u> Free Drift or CMG Control with Thrusters Disabled is required while SABB is being unlatched/latched. Applies only while mechanisms are in motion</p> <p>MCC-H 4. Configure ISS/Orbiter attitude control to CMG Control with thrusters disabled IV 5. When task complete, give MCC-H GO to resume nominal attitude control</p>	<div style="border: 3px double black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;">WARNING</p> <p>Sharp edge/pinch point/entrapment hazard – Avoid contact with outboard underside of SABB due to exposed reels, guide-wire and tension mechanisms Avoid contact with blanket box latches during manual override operation</p> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;">CAUTION</p> <p>Maintain a constant push force (3-10 lb) on the MDA fastener anti-rotation collar during fastener rotation</p> </div> <p>MANUAL OVERRIDE TO UNLATCH SABB</p> <ol style="list-style-type: none"> On IV GO (see IV column, Unlatching SABB, step 2) – Enter worksite area If required, APFR, setup and ingress (see Task Data for WIF position, APFR settings, and BGA angle) Release PIP pin from back-up position lever Move override lever to MANUAL position Insert PIP pin into lock lever position Drive MDA drive fastener PGT, 7/16-2-in ext; A6 (8.3 ft-lb), CCW2 (30 RPM), MTL 30.5; push to engage (3-10 lb), 48 ± 1 turns until visual indication of latch position or HS Release PIP pin from override positioning lever Move override lever to AUTOMATIC position Insert PIP pin into lock lever position Drive MDA drive fastener (opposite direction) PGT 7/16-2-in ext; RCW, MTL 30.5; Push to engage (3-10 lb), ¼ turn to engage clutch pins <p>MANUAL OVERRIDE TO TENSIONING SABB</p> <ol style="list-style-type: none"> On IV GO (see IV column, Tensioning SABB, step 3), Enter worksite area If required, APFR, setup and ingress (see Task Data for WIF position, APFR settings, and BGA angle) Release PIP pin from back-up position lever Move override lever to MANUAL position Insert PIP pin into lock lever position Drive MDA drive fastener PGT, 7/16-2-in ext; A6 (8.3 ft-lb), CW2 (30 RPM), MTL 30.5; push to engage (3-10 lb), 48 ± 1 turns until visual indication of latch position or HS. The latches along the blanket box are visible and will move to the engaged position Release PIP pin from override positioning lever Move override lever to AUTOMATIC position Insert PIP pin into lock lever position Drive MDA drive fastener (opposite direction) PGT 7/16-2-in ext; RCCW, MTL 30.5; Push to engage (3-10 lb), ¼ turn to engage clutch pins

MANUAL OVERRIDE TO UNLATCH/LATCH (TENSION) SABB – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	00:30
Two EV Crew	N/A	N/A

Tools:

EV1	EV2
PGT	N/A
7/16-2-in ext	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Max Break Away Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
SABB MDA Fastener	Yes	7/16-in	1 per	N/A	7.5	12	48	30

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting	BGA Angle
IEA Non-keel side – Right SABB	P4/S4-26; P6/S6-38	(12,FF,F,3)	90
IEA Non-keel side – Left SABB	P4/S4-26; P6/S6-38	(12,FF,E,9)	270
IEA Keel side – Right SABB	P4/S4-25; P6/S6-37	(12,FF,F,3)	90
IEA Keel side – Left SABB	P4/S4-25; P6/S6-37	(12,FF,E,9)	270

Mass: N/A

Notes:


1. It has been demonstrated in the NBL that the EVA crewmember can access the SABB Manual Override Fastener from a free floating position on the mast canister. If the EVA crew thinks they can actuate the SABB Manual Override Fastener from a free floating position on the mast canister, there is no need to position the BGA per IV step 2
2. Free Drift or CMG Control with Thrusters Disabled is required while SABB is being unlatched/latched. Applies only while mechanisms are in motion

Cautions:

1. Equipment damage – Maintain a constant push force (3-10 lb) on the MDA fastener anti-rotation collar during fastener rotation. Damage to the locking collar and/or the fastener could result if the collar is allowed to extend during fastener rotation
2. Equipment damage – Avoid contact with blanket box latches and mechanisms on underside of blanket box

Warnings:

1. Sharp edge/pinch point/entrapment hazard – Avoid contact with outboard underside of SABB due to exposed reels, guide-wire and tension mechanisms
2. Moving equipment. Avoid contact with blanket box latches during manual override operation



SABB MDA

MANUAL OVERRIDE TO EXTEND/RETRACT MAST

IV	EV
<p>Identify Affected Power Channel XX = _____</p> <p>MCC-H 1. Perform {3.191 SAW XX FAILURE TO EXTEND MAST REMOTELY} (SODF: EPS: MALFUNCTION: PRIMARY POWER)</p> <p>OR</p> <p>Perform {3.192 SAW XX FAILURE TO RETRACT MAST REMOTELY} (SODF: EPS: MALFUNCTION: PRIMARY POWER)</p> <p>IV PCS 2. Verify affected SABB positioned over the IEA and BGA latched PVM: EPS: BGA XX BGA XX 'ECU XX' Verify: Integ Cnt – Incrementing</p> <p>'BGA XX' Verify: Actual Angle, deg = 180.000 (+/- 0.5) Motor State – OFF Latch 1 Pin Status – Latched</p> <p>IV 3. GO FOR EV CREW INGRESS AT WORKSITE</p> <p style="text-align: center;"><u>NOTE</u></p> <p>Free Drift or CMG Control with Thrusters Disabled is required while solar array is being deployed/retracted. Applies only while mechanisms are in motion</p> <p>MCC-H 4. Configure ISS/Orbiter attitude control to CMG Control with thrusters disabled</p>	<div style="border: 2px solid black; padding: 5px; text-align: center;"> <p>WARNING</p> <p>Sharp edge/pinch point/entrapment hazard – Avoid contact with outboard underside of SABB due to exposed reels, guide-wire and tension mechanisms</p> <p>Avoid contact with blanket box latches during manual override operation</p> </div> <p style="text-align: center;"><u>MANUAL OVERRIDE TO EXTEND MAST</u></p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION</p> <p>If excessive blanket panel "stiction" occurs during mast deployment, perform contingency incremental deployment</p> </div> <ol style="list-style-type: none"> 1. On IV GO (see IV column, step 3), enter worksite area 2. Set up and ingress APFR (see Task Data page) 3. If reqd, Deploy MCHD PGT swing arm, install MCHD onto mast canister, zip nuts (4) 4. If reqd, secure MCHD fasteners (4) PGT, 7/16-2-in ext; A5 (7.0 ft-lb), CW2 (30 RPM), MTL 30.5; to HS 5. Rotate Manual Override Actuator Shaft on left side of MDA Ratchet, 7/16-2-in ext; cw; 180 deg to disengage MDA, indicator – MANUAL 6. If reqd, place PGT in MCHD PGT swing arm <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION</p> <p>Crew must monitor the tension bar. Stop SAW deployment if the tension bar rises more than 1.5 inches from the sill. Drive MDA EVA override fastener until tension bar returns to 1.5 inches from the sill: PGT, 7/16-2 in ext; A7 (9.2 ft-lb), CW3 (60 RPM), MTL 30.5. When panels release and tension bar returns to the sill, deployment can continue</p> </div> <p style="text-align: center;"><u>NOTE</u></p> <p>Insolation is not required for this task, unless needed for visual abort cues. As expected, the tension bar will rise 18 to 20 inches from the sill as the last half mast bay is deployed.</p> <p>Extension complete when: Visual observation of the last mast bay visual indicators (black/white, cross hatched). Hard stop, sharp rise in tool torque.</p> <p>If reqd, off-load drive shaft with IVA pipe wrench. Apply load from the right to the left above the torsion spring in the coupler. Switch to manual mode while holding torque on the coupler</p> <ol style="list-style-type: none"> 7. Drive MDA EVA override fastener PGT, 7/16-2-in ext; A7 (9.2 ft-lb), CCW3 (60 RPM), MTL 30.5; ~78 turns until 1 mast bay is deployed 8. Give MCC-H GO to place solar array blanket boxes in high tension

MANUAL OVERRIDE TO EXTEND/RETRACT MAST (Cont)

IV	EV
<p>MCC-H 5. On EV GO (see EV column, Extend Mast, step 8), place solar array blanket boxes in high tension, when complete, give EV GO to continue SAW deployment</p> <p>MCC-H 6. On EV GO – resume nominal attitude control</p>	<p>9. On MCC-H GO (see IV column, step 5), drive MDA EVA override fastener PGT, 7/16-2-in ext; A7 (9.2 ft-lb), CCW3 (60 RPM), MTL 30.5; 2382 turns (x1 PGT battery will actuate approx 1300 turns), PGT battery changeout expected</p> <p>10. While holding the PGT with 7/16-2-in ext on the backup drive fastener, Ratchet with 7/16-2-in ext – rotate Manual Override Actuator Shaft 180 to disengage MDA, indicator – AUTOMATIC</p> <p>11. Give MCC-H GO to resume nominal attitude control</p> <p>12. Egress worksite, if utilized, leave MCHD on mast canister</p> <p><u>MANUAL OVERRIDE TO RETRACT MAST</u></p> <p>1. On IV GO (see IV column, step 3), Enter worksite area</p> <p>2. Set up and ingress APFR (see Task Data page)</p> <p>3. If reqd, deploy MCHD PGT swing arm, install MCHD onto mast canister, zip nuts (4)</p> <p>4. If reqd, secure MCHD fasteners (4) PGT, 7/16-2-in ext; A5 (7.0 ft-lb), CW2 (30 RPM), MTL 30.5; to HS</p> <p>5. Rotate manual override actuator shaft on left side of MDA Ratchet, 7/16-2-in ext; cw; 180 deg to disengage MDA, indicator – MANUAL</p> <p>6. If reqd, place PGT in MCHD PGT swing arm</p> <p>7. Drive MDA EVA override fastener PGT, 7/16-2-in ext; A7 (9.2 ft-lb), CW3 (60 RPM), MTL 30.5; 2460 turns (x1 PGT battery will actuate approx 1300 turns), PGT battery changeout expected</p> <p>8. While holding the PGT with 7/16-2-in ext on the backup drive fastener, Ratchet with 7/16-2-in ext – rotate Manual Override Actuator Shaft 180 deg to disengage MDA, indicator – AUTOMATIC</p> <p>9. Give MCC-H GO to resume nominal attitude control</p> <p>10. Egress worksite, if utilized, leave MCHD on mast canister</p>

MANUAL OVERRIDE TO EXTEND/RETRACT MAST – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	02:00
Two EV Crew	N/A	N/A

Tools:

EV1	EV2
PGT with 7/16-2-in ext	N/A
Ratchet wrench with 7/16-2-in ext	
If reqd, MCHD	
APFR	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Max Break Away Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
MCHD Fasteners	N/A	7/16-in	4	7.0	8.1	11.0 (L) 12.2 (R)	Zip	10
Mast Canister Manual Override Actuator Shaft	Yes	7/16-in	2 per	N/A	2.5	10	0.5	10
Mast Canister MDA Fastener	Yes	7/16-in	1 per	N/A	9.0	19.3	2461	60

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting
IEA Keel Side	P6/S6-37, P4/S4-25	(12,FF,F,12)
IEA Non-keel side	P6/S6-38, P4/S4-26	(12,FF,F,12)

Mass: N/A

Notes:

- Insulation is not required for this task, unless needed for visual abort cues. As expected, the tension bar will rise 18 to 20 inches from the sill as the last half mast bay is deployed
- Extension complete when: Visual observation of the last mast bay visual indicators (black/white, cross hatched). Hard stop, sharp rise in tool torque
- The mast canister needs to be positioned such that the MDA faces the direction of the IEA. This will allow an EV crewmember to set up an APFR to access the MDA
- In order to release MCHD fasteners from zipnuts, inward force on each bolt must be minimized

Cautions:

- Crew must monitor the tension bar. Stop SAW deployment if the tension bar rises more than 1.5 inches from the sill. Drive MDA EVA override fastener until tension bar returns to 1.5 inches from the sill. When panels release and tension bar returns to the sill, deployment can continue
- Equipment damage – Avoid contact with blanket box latches and mechanisms on underside of blanket box
- If monitoring IVA notes excessive blanket panel "stiction", during mast deployment, abort deployment. Coordinate with IVA to perform contingency incremental deploy. Not applicable for retraction

Warnings:

- Sharp edge/pinch point/entrapment hazard – Avoid contact with outboard underside of SABB due to exposed reels, guide-wire and tension mechanisms
- Moving equipment. Avoid contact with blanket box latches during manual override operation



Mast Canister MDA

ASSISTED SOLAR ARRAY DEPLOY/RETRACT

WARNING

1. Sharp edges:
 - a. SABB (skirt, swing bolts)
 - b. Solar cells
 - c. Springs along tension bar
 - d. Panel hinges
 - e. Guide cable burrs or frays
 - f. Mast Canister roller guides
 - g. Braided cables
 - h. Fastener exposed threads
 - i. Exposed bolts in rib cavities on mast canister
2. Shock hazard:
 - a. Avoid EMU contact with FCC and Kapton part of solar array panels
 - b. EV crew will only contact energized surfaces with approved tools that have been insulated with Kapton tape to prevent molten metal and shock
 - c. Solar array to be manipulated will be shunted prior to EV crew entering worksite
3. Pinch:
 - a. Lower SABB exposed reels and pulleys (guide wire and tensioning mechanisms)
 - b. Solar array mast during deploy/retraction
4. Avoid inadvertent contact with:
 - a. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off

ASSISTED SOLAR ARRAY DEPLOY/RETRACT (Cont)

IV/SSRMS	EV1	EV2
Deploy Solar Array		<p style="text-align: center;"><u>ASSISTED DEPLOY</u></p> <ol style="list-style-type: none"> 1. Verify glove gauntlets cover wrist disconnects 2. Determine SAW problem (perform full <u>SAW SURVEY FOR DEPLOY</u> below as required) 3. Perform <u>SAW WORKAROUND</u> for problem seen 4. Layback below Mast Canister separation plane, and give GO for deploy 5. Monitor array, call ABORT if problem seen 6. Repeat steps 1 thru 5 as required, translating in or away as required <p style="text-align: center;"><u>SAW SURVEY FOR DEPLOY (IF REQD)</u></p> <ol style="list-style-type: none"> 1. Prior to deploy, perform SABB/SAW survey to verify the following: <ul style="list-style-type: none"> <input type="checkbox"/> Tension reels are spooled (2 per SABB) <input type="checkbox"/> No slack in tension cables (2 per SABB) <input type="checkbox"/> Center, outboard guide wires run through pulleys and reels (3 per SABB, but cannot check inboard guide wire due to cover) <input type="checkbox"/> Center, outboard guide wire not rubbing against power cable (3 per SABB, but cannot check inboard guide wire due to cover) <input type="checkbox"/> No slack in guide wires (3 per SABB)
Retract Solar Array Retract Solar Array		<p style="text-align: center;"><u>ASSISTED RETRACT</u></p> <ol style="list-style-type: none"> 1. Verify glove gauntlets cover wrist disconnects 2. Determine SAW problem (perform full <u>INITIAL SAW SURVEY PRIOR TO RETRACT</u> below as reqd) 3. Perform <u>SAW WORKAROUND</u> for problem seen 4. Layback below Mast Canister separation plane, and give GO for retract 5. Monitor array, call ABORT if problem seen 6. Repeat steps 1 thru 5 as reqd, until 1 bay out 7. Perform <u>1 BAY OUT SAW SURVEY DURING FINAL RETRACT</u> 8. Give IV GO for final bay retraction 9. Verify guide wires remain tight and grommets are not caught between panels 10. If latching to be performed, verify latches aligned and within reach of latch pins on upper blanket box <p style="text-align: center;"><u>INITIAL SAW SURVEY PRIOR TO RETRACT (IF REQD)</u></p> <ol style="list-style-type: none"> 1. Prior to retract, perform SABB/SAW survey to verify the following: <ul style="list-style-type: none"> <input type="checkbox"/> Y-guides (4 per SABB) should not be visible <input type="checkbox"/> Center, outboard guide wire not rubbing against power cable <input type="checkbox"/> Foam pads in SABB base (7 per SABB) not overlapping and appear seated in original location (look through leaders) <p style="text-align: center;"><u>1 BAY OUT SAW SURVEY DURING FINAL RETRACT</u></p> <ol style="list-style-type: none"> 1. Perform SABB/SAW survey to verify the following: <ul style="list-style-type: none"> <input type="checkbox"/> Blanket fully contained within blanket box <input type="checkbox"/> Outboard STE loops neatly stacked within goal posts <input type="checkbox"/> Upper blanket box cover guide pins/alignment tabs aligned with goal posts <input type="checkbox"/> Guide wires (3 per SABB) retracted with no slack

ASSISTED SOLAR ARRAY DEPLOY/RETRACT (Cont)

IV/SSRMS	EV1	EV2
	<p style="text-align: center;"><u>SAW WORKAROUND</u></p> <p>Over-center Hinge Reset: A. Use cheater bar to press metal panel hinge into normal configuration; avoid contact with guide wire</p> <p>Uneven Panel Distribution (causes stuck grommets during retract): B. Get as close as possible to lower blanket box near center guide wire on affected solar array C. Use TPS scraper or cheater bar to evenly distribute panel folds along array (fluff); avoid contact with guide wire</p> <p>Stuck Grommet:</p> <p style="text-align: center;">1. <u>NOTE</u></p> <p>Provided a fray is not causing the grommet fault, panel fluffing near center guide wire will likely clear problems at all three guide wires</p> <p>If guide wire fray NOT suspected: D. Get as close as possible to affected panel near center guide wire E. Use TPS scraper or cheater bar to evenly distribute panel folds (fluff); avoid contact with guide wire F. If no joy; perform steps as if guide wire fray suspected</p> <p>If guide wire fray is suspected: G. Use TPS scraper or cheater bar to free grommet; repeat as necessary for lower panel grommets as guide wire fray retracts</p> <p>If bunching of panels above ~11.5 bays is seen (known fray): H. IV retract to the '12 bays deployed' configuration</p> <p style="text-align: center;">2. <u>NOTE</u></p> <p>If grommets are difficult to see, grommets are located on all outward folds (relative to EV crew), so folds can be counted.</p> <p>Procedure assumes fray is between 16th and 17th grommet, although it is possible that fray is between 15th and 16th grommet</p> <p>I. Pull grommets down using TPS scraper (or other tool) until 16 grommets above fray, remainder below fray J. IV re-attempt deploy</p> <p>Guide Wire Slack Due to Reel/Pulley Jam:</p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Guide wire can jump out of pulley track, attempt cable manipulation from inside blanket box first. If guide wire must be handled from outside of blanket box, avoid pulling guide wire to side of pulley plane</p> </div> <p>K. Verify all grommets on affected guide wire are loose L. Use needle nose pliers to pull cable out of reel; allow cable to retract</p> <p>Out of Plane Panels or Guide Wire Slack after Retract: M. Perform steps for stuck grommet N. If no joy; GCA SSRMS (if available) to goal posts of affected blanket O. Use gloved hand to realign STE loops between goal posts; avoid contact with FCC</p> <p>Y-Guide Reset P. Verify SABB is unlatched (low tension) Q. Use BRS Pin Tool on short skirt stiffener to lift tension bar; TPS scraper can be used assist with tension bar manipulation R. Lower tension bar on to Y-guide</p> <p>Leader Disconnected from Tension Bar S. If spring not connected to leader, inspect tension bar for spring condition and determine if it will interfere with latching T. If spring still connected to leader, use needle nose pliers to retain loose piece and cut leader with EVA scissors; stow in trash U. If spring needs to be cut from tension bar, use needle nose pliers to retain loose piece and cut spring with compound cutters; stow in trash</p>	

ASSISTED SOLAR ARRAY DEPLOY/RETRACT – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	N/A
Two EV Crew	As long as it takes	As long as it takes

Tools:

EV1	EV2
APFR	Crewlock Bag
Cheater Bar with 1.5-in bail drive lever	Digital Camera
Needle Nose Pliers	BRT
Compound Cutters	
Loop Pin Puller	
TPS Scraper	
BRS Pin Tool	
EVA Scissors	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
N/A								

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting

Notes:

1. Provided a fray is not causing the grommet fault, panel fluffing near center guide wire will likely clear problems at all three guide wires


Cautions:

1. Guide wire can jump out of pulley track, attempt cable manipulation from inside blanket box first. If guide wire must be handled from outside of blanket box, avoid pulling guide wire to side of pulley plane

Warnings:

1. Sharp edge/pinch point/shock hazard: Avoid EMU contact with the following:
 - Lower SABB exposed reels and pulleys (guide wire and tensioning mechanisms)
 - SABB skirt
 - Swing bolts
 - Springs on tension bar
 - Panel hinges
 - Guide wire frays
 - Braided cables
 - Fastener exposed threads
 - Exposed bolts in rib cavities on mast canister
 - Mast roller guides
 - FCC and Kapton part of solar array panels

Y-guide





Leader


Spring

Tension Bar

ASSISTED SOLAR ARRAY DEPLOY/RETRACT – TASK DATA (Cont)



ASSISTED SOLAR ARRAY DEPLOY/RETRACT – TASK DATA (Cont)



SABB SPOOL RE-TENSION

IV/RMS	EV1	EV2
<p>Identify Affected Power Channel XX = _____ Which SABB needs re-tensioning _____ Which Tension Reel needs re-tensioning _____</p> <p>IV 1. Retract Affected SAW approx 1 mast bay only if Mast is fully deployed</p> <p>PCS PVM: EPS: SAW XX <input type="text" value="SAW"/> 'Mast' sel Mast Commands</p> <p><input type="text" value="SAW XX Mast"/></p> <p>cmd Mast – Retract Arm cmd Mast – Retract</p> <p>Wait approx 20 sec (~ 1 bay) cmd Mast – Abort</p> <p>√MDA Voltage, V < 10 (± 2.8)</p> <p>2. Unlatch affected SABB. If required: Perform {1.3.450 SAW XX SABB INITIAL UNLATCH} (SODF: EPS: ACTIVATION AND CHECKOUT: CHANNEL ACTIVATION), step 2 for LBB or step 3 for RBB (NOTE: BRS Pin visual checks can be ignored)</p> <p>MCC-H 3. Position and safe SAW for Tension Reel Task. Perform {2.101 PVM BGA XX ENGAGE ANTIROTATION LATCH} (SODF: EPS: NOMINAL: PRIMARY POWER), using the following values:</p> <p>If Right SABB (Inboard Reel) BGA XX Cmded Angle = 80.000 deg BGA XX Latch Select = 1</p> <p>If Right SABB (Outboard Reel) BGA XX Cmded Angle = 93.000 deg BGA XX Latch Select =</p> <p>If Left SABB (Inboard Reel) BGA XX Cmded Angle = 285.000 deg BGA XX Latch Select = 2</p> <p>If Left SABB (Outboard Reel) BGA XX Cmded Angle = 283.000 deg BGA XX Latch Select = 1</p>	<div style="border: 2px solid black; padding: 5px; margin: 10px auto; width: 80%;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Moving equipment hazard. Stay clear of SABB and capture latch mechanisms</p> <hr/> <p>Moving equipment hazard. Avoid contact with mast canister/beta gimbal during rotation of SAW</p> <hr/> <p>Sharp edges: Pulley shroud at machined edges Guide wire mechanism cover at machined edges Guide wire mechanism Guide wire pulley Guide wire Top flange of blanket box Protrusions (4) on tension reel housing</p> </div> <p><u>TENSION REEL TASK SETUP</u></p> <ol style="list-style-type: none"> Translate to S6 Set up APFR (see Task Data page) Ingress APFR 	<div style="border: 2px solid black; padding: 5px; margin: 10px auto; width: 80%;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Moving equipment hazard. Stay clear of SABB and capture latch mechanisms</p> <hr/> <p>Moving equipment hazard. Avoid contact with mast canister/beta gimbal during rotation of SAW</p> <hr/> <p>Sharp edges: Pulley shroud at machined edges Guide wire mechanism cover at machined edges Guide wire mechanism Guide wire pulley Guide wire Top flange of blanket box Protrusions (4) on tension reel housing</p> </div> <p><u>TENSION REEL TASK SETUP</u></p> <ol style="list-style-type: none"> Translate to S6 Set up APFR (see Task Data page) Ingress APFR using EV 1 ingress aid or EV 1 for assistance

SABB SPOOL RE-TENSION (Cont)

IV/RMS	EV1	EV2
<p>IV 4. SSRMS: SSRMS RECONFIGURATION FOR EVA SUPPORT (SODF: ROBO PROCEDURE REFERENCE)</p> <p>5. SRMS: SRMS RECONFIGURATION FOR EVA SUPPORT (FDF: PDRS PROCEDURE REFERENCE)</p> <p style="text-align: center;"><u>NOTE</u></p> <p>Free Drift or CMG Control with Thrusters Disabled is required while the EV crewmembers are handling the cable</p> <p>MCC-H 6. Configure ISS/Orbiter attitude control to CMG control with thrusters disabled</p> <p>IV 7. When task complete, give MCC-H GO to resume nominal attitude control</p>	<p><u>INSTALL CABLE ON OUTBOARD REEL</u></p> <p>1. Assist EV2 with cable as required</p> <p style="text-align: center;"><u>NOTE</u></p> <p>The reel will rotate a fraction of a turn without resistance. Some uneven tension and binding may be initially detected as internal mechanism seats. The 2.5 turn count begins when this minimal rotational resistance (approx 2-6 lb) is encountered. The tension reel housing will self tend back to initial position. Hand guidance is required to control rate</p> <p>2. Rotate tension reel ccw by hand approx 2.5-2.75 turns to hard stop</p> <p style="text-align: center;"><u>NOTE</u></p> <p>EV1 acts as the "clutch" on reel in case EV2 lets go. Tension reel housing will self tend back to initial position. Hand guidance is required to control rate of motion</p> <p>3. Maintain reel and help tend cable during EV2 alignment</p> <p>4. Inspect final cable routing on tension reel groves, through pulley, and clear of blanket box fasteners</p> <p>5. Take closeout photos</p> <p>6. Egress APFR</p> <p><u>INSTALL CABLE ON INBOARD REEL</u></p> <p>1. Set up APFR (see Task Data page)</p> <p>2. Ingress APFR</p> <p>3. Repeat <u>INSTALL CABLE ON OUTBOARD REEL</u> for the SABB inboard reel</p> <p>4. Give IV GO for solar array deploy</p>	<p><u>INSTALL CABLE ON OUTBOARD REEL</u></p> <p style="text-align: center;"><u>NOTE</u></p> <p>Pull cable on bottom side of blanket box running between pulley and tension reel. There will be approx 2 ft of cable slack. The tension bar will be pulled into position against blanket box</p> <p>1. Using the loop pin puller, pull slack on tension cable by pulling cable through pulley using light force (expect 5-10 lb pull force. If force is high, contact MCC)</p> <p>2. Align cable through pulley</p> <p>3. Maintain cable tension during reel rotation using loop pin puller</p> <p>4. Feed cable onto reel using loop pin puller as reel rotates back cw under it's own spring power</p> <p>5. Remove loop pin puller</p> <p>6. Egress APFR</p> <p><u>INSTALL CABLE ON INBOARD REEL</u></p> <p>1. Set up APFR (see Task Data page)</p> <p>2. Ingress APFR using EV1 ingress aid or EV1 for assistance</p> <p>3. Repeat <u>INSTALL CABLE ON OUTBOARD REEL</u> for the SABB inboard reel</p>

SABB SPOOL RE-TENSION (Cont)

IV/RMS	EV1	EV2
<p>MCC-H 8. Return SAW/BGA to Deploy Position. If reqd: Perform {2.101 PVM BGA XX ENGAGE ANTIROTATION LATCH} (SODF: EPS: NOMINAL: PRIMARY POWER)</p> <p>IV 9. Return to Nominal SAW Deploy Camera configuration (Truss Cameras, PLB Cameras, etc)</p> <p>10. SSRMS: SSRMS RECONFIGURATION FOR SAW VIEWING (SODF: ROBO PROCEDURE REFERENCE)</p> <p>11. SRMS: SRMS RECONFIGURATION FOR SAW VIEWING (FDF: PDRS PROCEDURE REFERENCE)</p> <p>MCC-H12. Re-Latch (Tension) Affected SABB If reqd: Perform {1.3.452 SAW XX DEPLOY} (SODF: EPS: ACTIVATION AND CHECKOUT: CHANNEL ACTIVATION) step 13 for LBB, or step 14 for RBB</p>	<p>IF REQD:</p> <p><u>TENSION REEL JAM CONTINGENCY</u></p> <ol style="list-style-type: none"> 1. If no rotational resistance or no hard stop (free spinning), call MCC 2. If excessive force (> 6 lb) or mechanism jam is encountered, go to <u>INSTALL CABLE ON INBOARD REEL</u> 3. EV guide tension reel back into initial position 4. IV Cycle SABB Latches. Perform {4.118 SAW XX RETRACT} (SODF: EPS: CORRECTIVE: PRIMARY POWER) steps 12 (13) for Unlatch OR steps 18 (19) for Latch 5. EV attempt outboard tension reel rotation 6. If smooth reel rotation, go to <u>INSTALL CABLE ON OUTBOARD REEL</u>, EV2, step 1 7. If jam or resistance encountered, repeat steps 4 and 5 8. If no joy, call MCC 	

SABB SPOOL RE-TENSION – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	N/A
Two EV Crew	N/A	01:00

Tools:

EV1	EV2
APFR	APFR
Ingress aid	Loop pin puller

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
N/A								

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
N/A					

Foot Restraints:

Task	WIF	APFR Setting	BGA Angle
IEA Non-keel side – SABB Outboard Reel EV1 access	P4/S4-11, P6/S6-23	(12,HH,F,6)	283, 93
IEA Non-keel side – SABB Outboard Reel EV2 access	P4/S4-15, P6/S6-27	(10,HH,G,1)	283, 93
IEA Non-keel side – SABB Inboard Reel EV1 access	P4/S4-26, P6/S6-38	(1,FF,E,2)	285, 80
IEA Non-keel side – SABB Inboard Reel EV2 access	P4/S4-19, P6/S6-31	(5,GG,F,7)	285, 80
IEA Keel side – SABB Outboard Reel EV1 access	P4/S4-09, P6/S6-21	(12,HH,F,6)	283, 93
IEA Keel side – SABB Outboard Reel EV2 access	P4/S4-13, P6/S6-25	(10,HH,G,1)	283, 93
IEA Keel side – SABB Inboard Reel EV1 access	P4/S4-25, P6/S6-37	(1,FF,E,2)	285, 80
IEA Keel side – SABB Inboard Reel EV2 access	P4/S4-17, P6/S6-29	(5,GG,F,7)	285, 80

Notes:

1. SABB Outboard Reel does not have a pulley shroud
2. Combination wrenches may be used if the tension reel fails to take up the tension cable slack


Cautions:

1. Equipment damage – Beware of close proximity to blanket box during ingress. Visually inspect cables prior to handling for fraying or jamming on structure or nearby cables
2. Do not allow uncontrolled cw rotation of tension reel
3. Do not manually wrap cable on reel housing

Warnings:

1. Sharp edges:
 - Pulley shroud at machined edges
 - Guide wire mechanism cover at machined edges
 - Guide wire mechanism
 - Guide wire pulley
 - Guide wire
 - Top flange of blanket box
 - Protrusions (4) on tension reel housing
2. Moving equipment hazard. Stay clear of SABB and capture latch mechanisms
3. Moving equipment hazard. Avoid contact with mast canister/beta gimbal during rotation of SAW

SABB SPOOL RE-TENSION – TASK DATA (Cont)



Tension
Bar

Outboard
TM


Inboard
TM

NOTE
No markings on these TMs, markings are not on S6.
Tension Bar in fully extended position

SABB SPOOL RE-TENSION – TASK DATA (Cont)



SABB Tensioning Reel Outboard – markings not on S6



SABB Tensioning Reel Inboard – markings not on S6

MANUAL SAW JETTISON

PRIOR TO EVA:

1. Unstow SSU cover and place in crewlock
2. If ECU removal is planned, stow Medium ORU bag in crewlock
3. Remove SSU shunt plug adapter J5A and J6A caps and tether to tether point on SSU shunt plug adapter
4. Remove SSU shunt plug caps and mate SSU shunt plugs to SSU shunt plug adapter J5A and J6A (shunt plugs can go on either adapter receptacle)
5. Remove caps from SSU shunt plug adapter ground service equipment connectors
6. Stow SSU shunt plug adapter/shunt plugs, Cannon connector tool in EVA crewlock bag
7. If available, stow size 37 Cannon connector plug cap in EVA crewlock bag; if not available, will need to retrieve one from Z1

IV/RMS	EV1	EV2
<p>Identify Affected Power Channel XX = _____ and opposite deck Power Channel YY = _____</p> <p>MCC-H 1. Mnv/orient ISS for SAW jettison</p> <p>MCC-H 2. Position and safe SAW for SSU Removal Perform {2.101 PVM BGA XX ENGAGE ANTIROTATION LATCH} (SODF: EPS: NOMINAL: PRIMARY POWER)</p> <p>MCC-H 3. Verify solar array positioned for EV crew access to SSU and BGA latched PCS PVM: EPS: BGA XX BGA XX 'ECU XX' Verify: Integ Cnt – Incrementing 'BGA XX' Verify: Actual Angle, deg = 270 Motor State – OFF Latch 1(2) Pin Status – Latched</p> <p>4. GO for EV ingress at SSU worksite</p> <p>MCC-H 5. Verify power connector inhibits in place before SSU Removal PCS PVM: EPS: DCSU XX DCSU XX 'DCSU XX' sel RBI 1 Verify: Cmdded Position – Op</p>	<div style="border: 2px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Voltage hazard exists at the connectors of the SSU. SSU must be safed before removal</p> <p>Electrical Shock Hazard. SSU Shunt Plug installation/removal and SSU removal/installation must occur during eclipse. STEPS DENOTED BY AN “E” MUST OCCUR DURING ECLIPSE. Crew must wait the specified wait periods for voltage drops to safe levels before proceeding. EV crew will need to move away from exposed electrical receptacles during day pass</p> <p>Protrusion Hazard. SSU alignment post protrudes beyond mast canister. Maintain clearances between structure and crewmember during SSU removal</p> <p>Collision Hazard. The solar array motion should be prevented by locking the BGA. This avoids a collision hazard with the EV crew if the EV crew is within 24 inches of the array rotational envelope</p> </div> <p><u>EVA SETUP</u></p> <ol style="list-style-type: none"> 1. If required, retrieve Sq TM with 7/16 Rec socket and square scoop from Z1 toolbox 2. If required, translate to Z1 forward face, demate Cannon connector cap from Z1 J259 or J260, stow in EVA crewlock bag 3. On MCC GO, translate to SSU worksite 4. Transfer tools and APFR with AIA to worksite 5. Set up APFR (see Task Data page) 	<div style="border: 2px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Voltage hazard exists at the connectors of the SSU. SSU must be safed before removal</p> <p>Electrical Shock Hazard. SSU Shunt Plug installation/removal and SSU removal/installation must occur during eclipse. STEPS DENOTED BY AN “E” MUST OCCUR DURING ECLIPSE. Crew must wait the specified wait periods for voltage drops to safe levels before proceeding. EV crew will need to move away from exposed electrical receptacles during day pass</p> <p>Protrusion Hazard. SSU alignment post protrudes beyond mast canister. Maintain clearances between structure and crewmember during SSU removal</p> <p>Collision Hazard. The solar array motion should be prevented by locking the BGA. This avoids a collision hazard with the EV crew if the EV crew is within 24 inches of the array rotational envelope</p> </div> <p><u>EVA SETUP</u></p> <ol style="list-style-type: none"> 1. Translate to Mast Canister/Aux bag (PMA1 stbd by Node bag) 2. Retrieve MCHD 3. On MCC GO, translate to worksite 4. Temp stow MCHD and SSU cover 5. Translate to BMRRM 6. Remove BMRRM thermal shroud (peels back)

MANUAL SAW JETTISON (Cont)

IV/RMS	EV1	EV2
<p>Close Cmd – Inh Voltage: -4.2 – 4.2 Current: -7.5 – 7.5</p> <p>PCS PVM: EPS: SSU XX SSU XX 'BCDU YY1' (YY= opposite channel on IEA) sel CP RBI</p> <p>BCDU XX CP RBIs 'YY1 CP RBI' (YY= opposite channel on IEA) Verify: YY1 CP RBI Posn – Op</p> <p>MCC-H 6. Turn off and off point video camera luminaries, rpcm open and closed inhibited</p> <p>MCC-H 7. Give GO for BMRRM J1 demate and SSU shunt plug installation</p> <p>MCC-H 8. Give GO for SSU removal during 2nd ECLIPSE ONLY</p>	<div data-bbox="877 316 1241 727" data-label="Image"> </div> <p>SSU shunt plugs and adapter installed on mast canister with shroud open</p> <p>E6. On MCC GO (2 min wait after transition from insolation to eclipse), remove mast canister ground test port caps (2) and place in EVA trash bag</p> <p>E7. Position MLI shroud as shown above or folded against shunt plugs</p> <p>E8. Install SSU shunt plug adapter with bails facing outward, not against mast canister</p> <p>9. Reinstall MLI shroud 10. Ingress APFR</p> <p><u>REMOVE FAILED SSU</u></p> <p>E1. Install Sq TM onto primary fastener, √anti-backlash neutral</p> <p>E2. On MCC GO (5 min wait after transition from insolation to eclipse), Release SSU fastener 1 turn PGT, Sq TM-7/16 Rec; B1 (12.0 ft-lb), CCW2 (30 RPM), MTL 30.5; 1 turn on bolt = 5 turns from PGT</p> <p>E3. Remove Sq TM</p> <p>E4. Install Sq Scoop on SSU</p> <p>E5. Release SSU fastener PGT, 7/16-6-in ext; B1 (12.0 ft-lb), CCW2 (30 RPM), MTL 30.5; 10 turns</p>	<p>E7. On MCC GO, demate connector from BMRRM J1</p> <p>E8. Mate Cannon connector cap on BMRRM J1</p> <p>9. If reqd, reinstall BMRRM thermal shroud</p> <p><u>REMOVE FAILED SSU</u></p>

MANUAL SAW JETTISON (Cont)

IV/RMS	EV1	EV2
<p>9. Position and safe SAW for ECU Removal (if required) and SAW jettison. Perform {2.101 PVM BGA XX ENGAGE ANTI-ROTATION LATCH} (SODF: EPS: NOMINAL: PRIMARY POWER) using the following values:</p> <p style="padding-left: 40px;">BGA XX Cmded Angle = 180 deg BGA XX Latch Select = 1</p> <p>10. GO for EV ingress at ECU worksite</p> <p>MCC-H 11. Remove ECU power PCS PVM: EPS: BGA XX BGA XX</p> <p style="padding-left: 40px;">sel RPCM YY A RPC 02 RPCM YY A RPC 02</p> <p style="padding-left: 40px;">cmd RPC Position – Open (Verify – Op)</p> <p style="padding-left: 40px;">(Expect Caution Message: BGA XX Loss of Comm)</p> <p>MCC-H 12. GO for ECU removal and BMRRM cable demate</p>	<p>E6. √Status indicator – UNLOCK E7. Remove SSU and hand to EV2</p> <p>2. Clear BGA rotation plane for BGA rotation and inform IV when clear</p> <div style="border: 2px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p>WARNING Moving equipment hazard: Avoid contact with mast canister/beta gimbal during rotation of SAW</p> </div> <p><u>REMOVE ECU (if reqd)</u></p> <ol style="list-style-type: none"> Set up and ingress APFR [see Task Data page] On MCC GO, release ECU fastener 1 turn PGT, Sq TM-7/16 Rec; B1 (12.0 ft-lb), CCW2 (30 RPM), MTL 30.5; 1 turn on bolt = 5 turns from PGT Remove Sq TM Install Square Scoop on ECU Release ECU fastener PGT, 7/16-6-in ext; B1 (12.0 ft-lb), CCW2 (30 RPM), MTL 30.5; 10 ± 2 turns √Status indicator – UNLOCK Remove ECU and stow in ORU transfer bag 	<ol style="list-style-type: none"> Receive SSU and stow on SSU cover Clear BGA rotation plane for BGA rotation and inform IV when clear <p><u>RELEASE BMRRM FASTENERS/CONNECTORS</u></p> <ol style="list-style-type: none"> If not done already, remove BMRRM thermal shroud and temp stow Release BMRRM center fastener PGT, 7/16-6-in ext; B6 (24.0 ft-lb), CCW2 (30 RPM), MTL 10.5; 17 turns On MCC GO, disconnect the following connectors from the BMRRM: Demate connector from J3 Demate connector from J2

MANUAL SAW JETTISON (Cont)

IV/RMS	EV1	EV2
<p>MCC-H 13. Give GO for MCHD installation</p> <p>MCC-H 14. Give GO for jettison</p>	<p><u>INSTALL MCHD</u></p> <ol style="list-style-type: none"> 1. On MCC GO, set up and ingress APFR (see Task Data page) 2. Deploy MCHD appendages 3. Install MCHD on mast canister 4. Fasten MCHD corner attach fasteners (4) PGT, 7/16-6-in ext; A5 (7.0 ft-lb), CW2 (30 RPM), MTL 30.5; to HS <p><u>MANUAL SAW JETTISON</u></p> <ol style="list-style-type: none"> 1. Using MCHD, move mast canister from beta gimbal at a velocity less than 1 ft/min. Move mast canister 2 ft from beta gimbal separation plane. Correct wing attitude as reqd to achieve stability 2. Release MCHD 3. Monitor SAW separation 4. When SAW is clear, egress worksite 	<p><u>MANUAL SAW JETTISON</u></p> <ol style="list-style-type: none"> 1. On MCC GO, release platform vice clamp fastener PGT, 7/16-6-in ext; B1 (12.0 ft-lb), CCW2 (30 RPM), MTL 10.5; 19 turns to HS 2. When complete, give EV1 GO for SAW motion 3. Call out separation distance until 2-ft separation achieved 4. Monitor SAW separation

MANUAL SAW JETTISON – TASK DATA

Estimated Task Duration:

	Without RMS
One EV Crew	N/A
Two EV Crew	03:00

Tools:

EV1	EV2
PGT	PGT
7/16-6-in ext	7/16-6-in ext
APFR/ingress aid	
Square TM with 7/16-in Recessed socket	
EVA crewlock bag	SSU cover
SSU shunt plug adapter	Mast Canister Handling Device
SSU shunt plugs (2)	
Size 33 Cannon conn plug cap	
Square scoop (2)	
Medium ORU bag (if reqd – for ECU)	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Max Break Away Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
SSU fastener	N/A	7/16-in	1	6.3	35.7	264 (R)	11 ± 2	30
ECU fastener	N/A	7/16-in	1	6.3	30.5	290.3 (R)	11 ± 2	30
BMRRM Center Fastener	N/A	7/16-in	1	N/A	16.0	54.0	17	30
MCHD Fasteners	N/A	7/16-in	4	7.0	8.1	11.0 (l)	ZIP	10
Vice Clamp	N/A	7/16-in	1	N/A	5.2	20.1	19	30

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
W05 P23 J3		BMRRM J3		25	ECU feed; SSU Control pwr; 1553B
W06 P22 J2		BMRRM J2		25	ECU cross feed
		BMRRM J1		37	Primary power

Foot Restraints:

Task	WIF	APFR Setting	BGA Angle
Access to SSU (IEA non-keel side 4A/3A SAW)	P4/S4-23	4, PP, G, 9	270
Access to SSU (IEA keel side 2A/1A SAW)	P4/S4-24	4, PP, G, 9	270
Access to BMRRM (IEA non-keel side 4A/3ASAW)	P4/S4-28	9, NN, G, 3	Any
Access to BMRRM (IEA keel side 2A/1A SAW)	P4/S4-27	9, NN, G, 3	Any
Install MCHD and 4A/3A SAW jettison position (IEA non-keel side SAW)	P4/S4-26	6, FF, F, 6	180
Install MCHD and 2A/1A SAW jettison position (IEA keel side SAW)	P4/S4-25	6, FF, F, 6	180
Access to 4A/3A ECU	P4/S4-26	8, OO, A, 3	180
Access to 2A/1A ECU	P4/S4-25	8, OO, A, 3	180
Access to SSU (IEA non-keel side)	S6/S6-35	4, PP, G, 9	270
Access to SSU (IEA keel side)	S6/S6-33	4, PP, G, 9	270
Access to BMRRM (IEA non-keel side)	S6/S6-39	9, NN, G, 3	Any
Access to BMRRM (IEA keel side)	S6/S6-40	9, NN, G, 3	Any
Install MCHD and SAW jettison position (IEA non-keel side)	S6/S6-38	12, FF, F, 12	180
Install MCHD and SAW jettison position (IEA keel side)	S6/S6-37	12, FF, F, 12	180
Access to ECU (IEA non-keel side)	S6/S6-38	8, OO, A, 3	180
Access to ECU (IEA keel side)	S6/S6-37	8, OO, A, 3	180

ORU Mass: SSU – 186 lb

ECU – 90 lb SAW – approx 2326 lb

MANUAL SAW JETTISON – TASK DATA (Cont)

Notes:


1. The MCHD has four deployable legs. Each leg has an EVA fastener which engages a zip nut on the mast canister hand rails. The MCHD also has a deployable PGT cradle assembly which is used to drive the mast canister MDA. The PGT cradle assembly is not required for the jettison procedure

Cautions:


None

Warnings:

1. Electrical Shock Hazard: Install SSU shunt plug adapter/SSU shunt plugs and remove SSU during orbital eclipse. Procedure specifies wait time before installing SSU shunt plug adapter/SSU shunt plugs and removing SSU to allow voltages to drop to safe levels
2. Protrusion Hazard: SSU alignment post protrudes beyond mast canister. Maintain clearances between structure and crewmember during SSU changeout
3. Voltage hazard may exist at connectors of the ECU and BMRRM. ECU and BMRRM must be safed before removal
4. Collision Hazard: The solar array motion should be inhibited to prevent a collision hazard with the EV crew because the EV crew may be within 24 inches of the array rotational envelope
5. Moving equipment hazard: Avoid contact with mast canister/beta gimbal during rotation of SAW
6. Mass handling – The crewmember will control the SAW mass with bent arms to avoid loading the EMU suit structure
7. Release mast canister with minimal tip-off rates




Mast Canister Handling Device (MCHD)



BMRRM connectors without BMRRM thermal cover

GAP CHECK TOOL TIE-DOWN


RTAS Gap Check Tool Contingency Tie Down. Tie-down taken from 12A.1 RTAS Gap Check Tool tether point to nearest handrail on S5. Can use wire tie from tether loop on gap check tool to handrail stanchion point nearest gap check tool



NOTE: Wire Tie process in approval,
use Adj tether unless contacted by
MCC-H with go on wire tie

SABB LAUNCH RESTRAINT TIE-DOWN

SABB Launch Restraint




This tether is a long duration tether. Total length is approx. 28.4". It goes from the tether loop on the SABB Launch restraint to SABB HR. The buckles are not a concern

NOTE: Approval process for 2 Adj tethers daisy chained instead of LDTDT is in work

UCCAS/PAS TIE-DOWN


Overall View of PAS
and UCCAS



NOTE
Wire Tie in approval process,
use Adj tether unless contacted
by **MCC-H** with GO on wire tie

UCCAS/PAS TIE-DOWN (Cont)

PAS and UCCAS Tether #1



Alternative, use wire tie between clevis bracket tether loops


This tether is an adjustable equipment tether (small/small hooks). Total length is approx. 22.5". It goes from the tether loop on the Deployed Bracket around P3 or S3 Structure and hooks back onto its own D-Ring

NOTE

Wire Tie in approval process, use Adj tether unless contacted by **MCC-H** with GO on wire tie


RPCM TIE-DOWN

RPCM S04B-C Contingency Tie-Down, taken from Inc 12 US EVA 4 Hazard Report. Different RPCM, but tie-down still applicable




NOTE
Wire Tie in approval process,
use Adj tether unless contacted
by **MCC-H** with GO on wire tie


ETVCG Tie-Down



Dummy Box secured to VSSA




Dummy Box secured to VSSA



Dummy Box secured to VSSA

Two Sm-Sm Adjustable Tethers




BMRRM REMOVE/REPLACE

IV/RMS	EV1	EV2
<p><u>NOTE:</u> S6 could be S4, P4, or P6 depending on failure</p> <p>IV: 1. Safe Channel B for EV2 terminator install and EV1 J2 and J4 demate Verify ISS perform S6 PREPARATION FOR XX BMRRM R&R steps 11 & 12 complete GO for EV1 step 5 and EV2 steps 2-3</p> <p>IV: 2. When EV2 steps 2-3 complete ISS perform S6 PREPARATION FOR XX BMRRM R&R steps 13 & 14</p> <p>IV: 3. Prior to eclipse, safe Primary Power for EV1 J1 demate ISS perform S6 PREPARATION FOR XX BMRRM R&R steps 15 & 16 GO for EV1 step 6</p> <p>IV: 4. If IV step 2 not successful, EV2 steps E5 and E6 required</p> <p>IV: 5. Safe Channel A for EV1 J3 demate ISS perform S6 PREPARATION FOR XX BMRRM R&R steps 17 & 18 GO for EV1 step E9</p>	<p><u>REMOVE OLD BMRRM</u></p> <ol style="list-style-type: none"> PGT[A5 7.0 ft-lb, CCW2 30RPM, MTL 10.5]-6ext 7/16: Unfasten BMRRM housing bolts (H6, H7, H8, H9) 8 +/- 1 turns, verify bolts spring up PGT[A5 7.0 ft-lb, CCW2 30RPM, MTL 10.5]-6ext 7/16: Drive dual latch bolts (H3, H2, H4) 15 turns PGT[A1 2.5 ft-lb, CCW2 30RPM, MTL 5.5]-6ext 7/16: Drive dual latch bolts (H4, H2, H3) to hard stop, 8 turns expected (23 ± 2 turns total expected) Release remaining T/A clamps On IV GO, demate connectors from BMRRM J4, J2 receptacles <ol style="list-style-type: none"> On IV GO, demate J1 receptacle Secure demated connectors clear of BMRRM removal area Notify IV when complete <div data-bbox="877 906 1268 1052" style="border: 2px solid black; padding: 5px; text-align: center;"> <p>WARNING Steps denoted by an "E" must occur during eclipse to prevent possible hot connector mate Old BMRRM has sharp edge hazard</p> </div> <ol style="list-style-type: none"> On IV GO, demate connector from the BMRRM J3 receptacles Secure demated connectors clear of BMRRM removal area PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 10.5]-6ext 7/16: Release BMRRM center bolt H1, 10 turns Remove old BMRRM from Beta Gimbal housing assembly Transfer old BMRRM to EV2 	<p><u>REMOVE OLD BMRRM</u></p> <ol style="list-style-type: none"> Verify dual latches engaged to mast canister platform On IV GO, demate W19 P1 from JBOX 6 J2 Mate 1553B terminator cap 10955J to JBOX 6 J2 Notify IV when complete <div data-bbox="1520 906 1911 1052" style="border: 2px solid black; padding: 5px; text-align: center;"> <p>WARNING Steps denoted by an "E" must occur during eclipse to prevent possible hot connector mate Old BMRRM has sharp edge hazard</p> </div> <ol style="list-style-type: none"> If reqd: On IV GO, demate W05 P1 from JBOX 4 J2 If reqd: Mate 1553B terminator cap 10956J to JBOX 4 J2 If reqd: Notify IV when E5 and E6 complete Translate to vice clamp worksite PGT[A4 6.3 ft-lb, CCW2 30RPM, MTL 10.5]-6ext 7/16: Unfasten vice clamp bolt, 19 ± 2 turns <ol style="list-style-type: none"> Receive old BMRRM from EV1 and stow on MUT EE/Ballstack/MUT EE

BMRRM REMOVE/REPLACE (Cont)

IV/RMS	EV1	EV2
<p>IV: 6. Notify ISS EV1 step E20 complete GO for ISS perform EPS RETURN TO NOMINAL CONFIG POST XX BMRRM R&R steps 1-4</p> <p>IV: 7. If Eclipse time permits, GO for EV1 step 21 Else, verify ISS perform EPS RETURN TO NOMINAL CONFIG POST XX BMRRM R&R steps 1-4 complete GO for EV1 step 21</p> <p>IV: 8. Verify ISS perform EPS RETURN TO NOMINAL CONFIG POST XX BMRRM R&R step 1 complete GO for EV2 steps 16 & 17</p> <p>IV: 9. Notify MCC-H EV1 step 21 and EV2 step 17 complete</p>	<p><u>INSTALL NEW BMRRM</u></p> <p>E14. PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 10.5]-6ext 7/16: Release new BMRRM center bolt H1, 10 turns, verify center bolt springs up</p> <p>E15. Remove new BMRRM from housing</p> <p>E16. Position new BMRRM for EV2 verification of lever latch position</p> <p>E17. Use alignment mark to clock BMRRM; Install new BMRRM in Beta Gimbal housing assembly</p> <p>E18. Push center bolt H1 to soft capture BMRRM to platform</p> <p>E19. PGT[A6 8.3 ft-lb, CW2 30RPM, MTL 10.5]-6ext 7/16: Fasten center bolt H1 to hard stop, notify EV2 center bolt hard stop, turns will vary due to zip nut feature</p> <p>E20. Mate J3 connector to the new BMRRM, notify IV when complete</p> <p>21. On IV GO, mate connectors to the new BMRRM J1, J2 and J4 receptacles, notify IV when complete</p> <p>22. PGT[A4 6.3 ft-lb, CW2 30RPM, MTL 5.5]-6ext 7/16: Start each bolt before driving to hard stop, fasten BMRRM housing bolts (H7, H9, H6, H8) 8 ± 1 turns</p> <p>23. PGT[A6 8.3 ft-lb, CW2 30RPM, MTL 10.5]-6ext 7/16: Drive dual latch bolts (H3, H2, H4) to hard stop, 23 ± 2 turns expected</p> <p>24. Receive old BMRRM from EV2</p> <p>25. Position old BMRRM for EV2 verification of lever latch position</p> <p>26. Using alignment pin to clock BMRRM, stow old BMRRM in housing</p> <p>27. Push in center bolt H1 to set soft capture</p> <p>28. Inspect old BMRRM for contaminants</p> <p>29. PGT[A6 8.3 ft-lb, CW2 30RPM, MTL 10.5]-6ext 7/16: Fasten center bolt H1 to hard stop on old BMRRM, turns will vary due to zip nut feature</p> <p>30. Install connector cover on old BMRRM</p> <p>31. Stow old BMRRM RET on old BMRRM</p>	<p><u>INSTALL NEW BMRRM</u></p> <p>E11. Verify lever latch in latched position on new BMRRM</p> <p>E12. Assist EV1 with alignment of new BMRRM into Beta Gimbal housing assembly</p> <p>E13. If reqd, On IV GO, Demate terminator cap 10956J from JBOX 4 J2</p> <p>E14. If reqd, Mate W05 P1 to JBOX 4 J2, notify IV when complete</p> <p>15. PGT[A3 5.0 ft-lb, CW2 30RPM, MTL 5.5]-6ext 7/16: Fasten vice clamp bolt, 19 ± 2 turns, verify locking collar engages, install vice clamp contingency tool with wire tie if reqd</p> <p>16. Verify dual latch blocks are still flush on platform</p> <p>17. On IV GO, Demate terminator cap 10955J from JBOX 6 J2</p> <p>18. Mate W19 P1 to JBOX 6 J2, notify IV when complete</p> <p>19. Stow terminator connector</p> <p>20. Verify dual latches released from mast canister platform</p> <p>21. Retrieve old BMRRM by releasing MUT from BGA HR</p> <p>22. Transfer old BMRRM to EV1</p> <p>23. Verify lever latch in latched position on old BMRRM</p>

BMRRM REMOVE/REPLACE (Cont)



BMRRM REMOVE/REPLACE – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	N/A
Two EV Crew	N/A	03:00

Tools:

EV1 (RMS)	EV2 (FF)
PGT	Crewlock bag
7/16-6-in ext	Vice clamp locking tool
Cannon connector tool	Cannon Connector tool
Round scoop	J23 Connector Cap
Ball stack (2)	JBOX 6 J2 terminator cap
MUT end effector (3)	JBOX 4 J2 terminator cap
APFR	

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque	Failure Torque	Turns	RPM
Dual Latches	H2, H3, H4	7/16-in	3	2.5 SAW Latch	8.3 BMRRM Latch	3.4 SAW Latch	47 BMRRM Latch	23 +/- 2	N/A
BMRRM Center Fastener	H1	7/16-in	1	8.3	10.5		51.6	10 +/- 2	N/A
BMRRM Housing Fasteners	H6, H7, H8, H9	7/16-in	4	5.5	7.0		15.5	8 +/- 1	N/A
Vice Clamp Fastener	None	7/16-in	1	2.5	5.0		8	19 +/- 2	N/A

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
W111 P11		XX BMRRM J1			Primary power
W03 P12		XX BMRRM J2			
W04 P13		XX BMRRM J3			
W12 P14		XX BMRRM J4			
W118 P21		YY BMRRM J1		37	Primary power
W118 P1		W18 J23		37	Primary power
W06 P22		YY BMRRM J2			ECU-XX cross feed
W05 P23		YY BMRRM J3		25	ECU-YY feed; SSU YY Control pwr; 1553B, Bus A
W05 P1		J2 (JBOX 4)		25	ECU-YY feed; SSU YY Control pwr; 1553B, Bus A
W19 P24		YY BMRRM J4		19	1553B, Bus B
W19 P1		J2 (JBOX 6)		19	1553B, Bus B

Foot Restraints:

Task	WIF	APFR Setting
Access to Stbd SAW BMRRM		
Access to Port SAW BMRRM		
BMRRM change-out support		
BMRRM change-out support		
Access to Stbd SAW SSU		
Access to Port SAW SSU		

ORU Mass: BMRRM = 142 lb Cover = 69 lb

BMRRM REMOVE/REPLACE – TASK DATA (Cont)

Notes:

1. Translation technique: The BMRRM within the ORU cover can be attached to the EVA crewmember via the BRT and Round Scoop. The EVA crewmember should attach an additional tether between themselves and the ORU cover to prevent uncontrolled motion
2. Fastener turn counts in the procedures are in reference to the bolt head
3. Recommend spare BMRRM temp stowage configuration: MUT end effector; ball stack, round scoop attached to cover microconical. A second tether should be tethered between the cover and structure
4. The three dual latches are used to latch the housing to the platform. Order of operation is not important
5. Three Dual Latches are equipped with locking collars. Collars must be pushed and held while rotating bolt heads
6. BMRRM center bolt is equipped with a spring and will pop out when fully unfastened
7. Vice Clamp Assembly actuating bolt is equipped with a locking collar. Collar must be pushed and held while rotating the bolt head
8. Four captive fasteners securing BMRRM to the housing are equipped with springs and will pop out when fully unfastened
9. Center bolt on the bottom of the platform assembly is a ZIP bolt. The number of turns to tighten to hard stop depends on how far the center bolt is pushed into the ZIP nut
10. BMRRM housing fasteners must be pushed lightly to start thread engagement
11. Vernier thrusters with CMG are allowed for attitude control during the BMRRM ORU changeout

Cautions:

1. FPP solar arrays, probes, and RF box are sensitive to impact loads. FPP (located in WIF S6-39) will interfere with BMRRM remove and replace procedure. FPP can be relocated to an alternate WIF. Grounding pin can be removed from grounding lug if necessary
2. Hardware Damage. The Vice clamp fastener may "back out" if the fastener locking collar does not engage after the spare BMRRM is installed. Vice clamp locking collar must be installed to prevent inadvertent rotation of Vice clamp bolt. Installation of Vice clamp collar locking tool will be required if vice clamp locking collar fails to engage
3. Minimize loads on Mast Platform when only Dual Latch Fasteners are engaged
4. Loss of ISS Hardware. Failure to engage the BMRRM Dual latches prior to failed BMRRM removal will result in SAW release

Warnings:

1. Excessive loads into the EMU: The EVA crewmember should translate at a rate no greater than 1.6 fps when the EVA crewmember is translating with the BMRRM attached to their BRT
2. Crew must remain 24 inches from rotating starboard SAW
3. Sharp Edge Hazard. The flange at the base of the failed BMRRM is sharp. Handle the BMRRM only by the EVA handle holds. Avoid contact with the end of the BMRRM opposite of the BMRRM face plate. The flange at the base of the replacement BMRRM is not sharp but should be avoided to avoid hardware damage
4. Umbilical mate/demate inhibits/constraints must be verified to avoid HOT connector mate/demate

DCSU REMOVE AND REPLACE

IV	EV1	EV2
<p>MCC-H 1. Verify SAW rotation inhibits complete 2. Verify Inhibits for spare DCSU complete; give EV GO for DCSU removal</p> <p>IV 3. Record s/n of failed DCSU: _____</p> <p>MCC-H 4. Verify electrical power inhibits complete; give EV GO for DCSU removal</p>	<p><u>REMOVE SPARE DCSU FROM ESP-1</u></p> <ol style="list-style-type: none"> Translate to ESP-1 worksite Ingress APFR Remove thermal cover Transfer thermal cover to EV2 <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Acme screws unfastened/fastened out of sequence could lead to jamming of DCSU Minimize force applied to H1 microfixture</p> </div> <ol style="list-style-type: none"> Install Sq TM onto H1, √anti-backlash neutral PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT 5 turns (1 turn at bolt) on H1 Remove Sq TM; Install on H2 fitting; √anti-backlash neutral PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT 5 turns (1 turn at bolt) on H2 Remove Sq TM PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-6 ext-7/16: Drive H1 minimum 5 turns √Status indicator – UNLOCK Install Square scoop on H2 PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-6 ext-7/16: Drive H2 minimum 16 turns √Status indicator – UNLOCK Remove DCSU from ESP-1 FSE Transfer spare DCSU to EV2 <p><u>REMOVE FAILED DCSU</u></p> <ol style="list-style-type: none"> Translate to IEA worksite Set up and ingress APFR (see Task Data sheet) Verify failed DCSU P/N and s/n to IV Install Sq TM onto H1, √anti-backlash neutral <ol style="list-style-type: none"> On MCC GO, PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT 5 turns (1 turn at bolt) on H1 	<p><u>REMOVE SPARE DCSU FROM ESP-1</u></p> <ol style="list-style-type: none"> Translate to ESP-1 worksite Set up WIF Extender and APFR (see Task Data sheet) Receive thermal cover from EV1 Temp stow thermal cover at worksite <p>5. Receive spare DCSU from EV1 and stow on BRT</p> <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Avoid contacting DCSU mating surface (electrical connectors and cooling fins) with structure during translation with DCSU</p> </div> <p><u>REMOVE FAILED DCSU</u></p> <ol style="list-style-type: none"> Translate to IEA worksite with spare DCSU

DCSU REMOVE AND REPLACE (Cont)

IV	EV1	EV2																		
<p>IV 5. Record spare DCSU bolt data</p> <table border="1" data-bbox="195 841 573 938"> <thead> <tr> <th>Bolt</th> <th>Turns</th> <th>Torque</th> </tr> </thead> <tbody> <tr> <td>H1</td> <td>_____</td> <td>_____</td> </tr> <tr> <td>H2</td> <td>_____</td> <td>_____</td> </tr> </tbody> </table> <p>IV 6. Record failed DCSU bolt data</p> <table border="1" data-bbox="195 1182 573 1279"> <thead> <tr> <th>Bolt</th> <th>Turns</th> <th>Torque</th> </tr> </thead> <tbody> <tr> <td>H1</td> <td>_____</td> <td>_____</td> </tr> <tr> <td>H2</td> <td>_____</td> <td>_____</td> </tr> </tbody> </table>	Bolt	Turns	Torque	H1	_____	_____	H2	_____	_____	Bolt	Turns	Torque	H1	_____	_____	H2	_____	_____	<ol style="list-style-type: none"> 6. Remove Sq TM; Install on H2 fitting; √anti-backlash neutral 7. PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-Sq TM-7/16: Drive PGT 5 turns (1 turn at bolt) on H2 8. Remove Sq TM 9. PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-6 ext-7/16: Drive H1 minimum 5 turns 10. √Status indicator – UNLOCK 11. Install Square scoop on H2 12. PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-6 ext-7/16: Drive H2 minimum 16 turns 13. √Status indicator – UNLOCK 14. Remove failed DCSU 15. Stow failed DCSU on BRT <p><u>INSTALL SPARE DCSU</u></p> <ol style="list-style-type: none"> 1. Receive spare DCSU from EV2 2. Install spare DCSU on IEA <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;"><u>CAUTION</u> Ensure ORU is level during installation to prevent damage to H2 status indicator probe</p> </div> <ol style="list-style-type: none"> 3. √Status indicator on H1 and H2 are in UNLOCK 4. PGT[A3 4.8 ft-lb, CW2 30RPM, MTL 30.5]-6 ext-7/16: Drive H2, 16-17 turns 5. √Status indicator – LOCK 6. PGT[A3 4.8 ft-lb, CW2 30RPM, MTL 30.5]-6 ext-7/16: Drive H1, 5-6 turns 7. √Status indicator – LOCK 8. Remove Square scoop from H2 fitting 9. Egress and remove APFR 10. Give MCC-H GO to restore power to DCSU <p><u>STOW FAILED DCSU ON ESP-1</u></p> <ol style="list-style-type: none"> 1. Translate to ESP1 worksite <ol style="list-style-type: none"> 2. Transfer failed DCSU to EV2 <p><u>STOW FAILED DCSU ON ESP-1</u></p> <ol style="list-style-type: none"> 3. Retrieve and transfer thermal cover to EV2 	<p><u>INSTALL SPARE DCSU</u></p> <ol style="list-style-type: none"> 1. Transfer spare DCSU to EV1 <p><u>STOW FAILED DCSU ON ESP-1</u></p> <ol style="list-style-type: none"> 1. Translate to ESP-1 worksite 2. Ingress APFR/WIF Extender 3. Receive failed DCSU from EV1 and install on ESP-1 4. √Status indicator on H1 and H2 are in UNLOCK 5. PGT[B3 18.4 ft-lb, CW2 30RPM, MTL 30.5]-6 ext-7/16: Drive H2, 16-17 turns 6. √Status indicator – LOCK 7. PGT[B3 18.4 ft-lb, CW2 30RPM, MTL 30.5]-6 ext-7/16: Drive H1, 5-6 turns 8. √Status indicator – LOCK 9. Remove Square scoop from H2 fitting 10. Receive thermal cover from EV1 11. Install thermal cover over DCSU 12. Remove APFR and WIF Extender
Bolt	Turns	Torque																		
H1	_____	_____																		
H2	_____	_____																		
Bolt	Turns	Torque																		
H1	_____	_____																		
H2	_____	_____																		

DCSU REMOVE AND REPLACE – TASK DATA

Estimated Task Duration:

Two EV Crew	2:30
-------------	------

Tools:

EV1 (RMS)	EV2 (FF)
PGT	PGT
6ext 7/16	6ext 7/16
Square TM w/7/16 in Rec Socket	Square TM w/7/16 in Rec Socket
Square scoop	Square scoop
APFR	APFR
	WIF Extender
BRT	BRT

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Fastener	H1	7/16	1	4.8	31.7	190.3 (R) 22.8 (I)	5-6	30
Fastener	H2	7/16	1	4.8	33.5	188.4 (R) 27.8 (I)	16-17	30

EVA Connectors:

Harness	From	To	Clamps (#)	Conn Size	Function
P3/J3	ESP1	FRAM	3		FSE Heater Power

Foot Restraints:

Task	WIF	APFR Setting	WIF Extender
P6 (S6) Non-keel side DCSU	P6-26 (S6-26)	12, PP, D, 12	N/A
P6 (S6) Keel side DCSU	P6-28 (S6-28)	12, PP, D, 12	N/A
P4 (S4) IEA Non-keel side DCSU	P4-14 (S4-14)	12, PP, D, 12	N/A
P4 (S4) IEA Keel side DCSU	P4-16 (S4-16)	12, PP, D, 12	N/A
Access to ESP1 DCSU (spare)	LAB 01-06	11, QQ, G, 12	6, B, 7

ORU Identification:

Task	Part Number	Serial Number
Spare DCSU	R072610	X830114
Failed DCSU	TBD	TBD

ORU Mass: DCSU = 217 lb, FSE = 154 lb

Notes:

1. Thermal conditioning of the spare DCSU before installation may be required (Preliminary LSAR time of 18 min)
2. DCSU will travel outward or inward as Acme screw H2 is unfastened or fastened
3. Lock SARJ when translating outboard of SARJ
4. A crewman on the RMS could also be used for ORU transfer to and from the worksite. This might also change the order of the task
5. If taking the FRAM with the DCSU, combined mass exceeds BRT capability
6. DO NOT USE the P6 IEA ORU placards. The label information is incorrect
7. There is no hard stop when releasing H1 and H2 bolts; upon release, they will free spin


Cautions:

1. Acme screws unfastened/fastened out of sequence could lead to jamming of DCSU during removal/installation. When unfastening Acme screws, H1 must be unfastened before H2. When fastening Acme screws, H2 must be fastened before H1
2. Avoid contacting DCSU mating surface (electrical connectors and cooling fins) with structure during translation with DCSU
3. Ensure ORU is maintained level and perpendicular to stanchion during installation. Failure to comply may damage H2 status indicator probe
4. Minimize force applied to H1 microfixture. It is not rated to withstand excessive loads


Warnings:

1. Depending on worksite proximity to SAW rotation, **MCC-H** may need to inhibit SAW rotation to avoid collision with the EVA crewmembers
2. Hazard voltage exists at the mating connectors to the failed DCSU. DCSU interface must be safed before removal
3. If taking the FRAM with the DCSU, inhibit may be different. Connector must be released

DCSU REMOVE AND REPLACE – TASK DATA (Cont)




DCSU installed on P6 IEA




H2 Status Indicator in Locked position

DCSU REMOVE AND REPLACE – TASK DATA (Cont)



P6 IEA DCSU (prior to installation)



P6 IEA DCSU lower deck location (prior to installation)

DDCU REMOVE AND REPLACE

Prior to EVA:

1. Verify part number of spare ORU (R076522-121) and record serial number on task data sheet. Report P/N and s/n of spare unit to **MCC-H**
2. Position DDCU-E in large ORU Transfer Bag and stow in airlock

IV/RMS	EV1	EV2
<p>MCC-H</p> <ol style="list-style-type: none"> 1. Verify electrical power inhibits complete. Give EV GO for DDCU removal 2. Verify P/N of failed ORU and record s/n on task data sheet. Report P/N and s/n to MCC-H <p style="text-align: center;"><u>NOTE</u> ORU is successfully installed if H1 and H2 screw torque and appropriate number of turns has been met.</p> <p>Removing DDCU from cold plate causes H1 status indicator to move from UNLOCK to LOCK</p>	<p><u>REMOVE FAILED DDCU</u></p> <ol style="list-style-type: none"> 1. Translate to P6 IEA worksite 2. Transfer tools and APFR to worksite 3. Setup and ingress APFR (see task data) 4. Report failed DDCU P/N and s/n to IV <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Acme screws unfastened/fastened out of sequence could lead to jamming of DDCU during removal. When unfastening Acme screws, H1 must be unfastened before H2</p> </div> <ol style="list-style-type: none"> 5. Install SqTM onto H1 fitting, √anti-backlash neutral 6. PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT, 5 turns 7. Remove SqTM and install on H2 fitting 8. √Anti-backlash neutral 9. Install 7/16 X 6-in socket 10. PGT[B7 25.5 ft-lb, CCW2 30RPM, MTL 30.5]-6 Ext 7/16: Drive H1, 8 turns 11. √Status indicator – UNLOCK 12. PGT[B1 12.0 ft-lb, CCW2 30RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT, 5 turns 13. Remove SqTm and stow 14. PGT[B7 25.5 ft-lb, CCW2 30RPM, MTL 30.5]-6 Ext 7/16: Drive H2, 18 turns 15. √Status indicator – UNLOCK <div style="border: 3px double black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Avoid contact with intermeshing fins of the DDCU-E and coldplate due to sharp edge concerns</p> </div> <ol style="list-style-type: none"> 16. Install Square scoop on H2 fitting 17. Remove failed DDCU (soft dock on H2 15-20 lb) 18. Hand off failed DDCU to EV2 	<p><u>REMOVE FAILED DDCU</u></p> <ol style="list-style-type: none"> 1. Translate to P6 IEA worksite 2. Transfer tools and spare DDCU to worksite <ol style="list-style-type: none"> 3. Receive failed DDCU from EV1 4. Temp stow failed DDCU

DDCU REMOVE AND REPLACE (Cont)

IV/RMS	EV1	EV2
	<p><u>INSTALL SPARE DDCU</u></p> <ol style="list-style-type: none"> 1. Inspect guide rails, connectors and coldplate fins for debris/damage 2. Receive spare DDCU from EV2 3. Install spare DDCU (soft dock on H2 15-20 lb) 4. √Status indicator on H1 is in UNLOCK <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;"><u>CAUTION</u></p> <p style="text-align: center;">There is a TBD thermal dwell time between the DDCU & coldplate. Wait TBD time prior to driving bolt</p> </div> <ol style="list-style-type: none"> 5. Remove Square Scoop from H2 fitting 6. PGT[A3 4.8 ft-lb, CW2 30RPM, MTL 30.5]-6Ext-7/16: Install primary bolt H2 to hard stop, approx 17 turns 7. √Visual indicator – LOCK 8. PGT[A3 4.8 ft-lb, CW2 30RPM, MTL 30.5]-6Ext-7/16: Install secondary bolt H1, approx 7 turns \pm 2 9. √Visual indicator – LOCK 10. Give MCC-H GO to restore power to DDCU 11. Place failed DDCU in ORU Transfer Bag 	<p><u>INSTALL SPARE DDCU</u></p> <ol style="list-style-type: none"> 1. Open ORU Transfer Bag, install Square Scoop on H2 2. Remove spare DDCU from ORU Transfer Bag 3. Inspect DDCU fins for debris/damage 4. Hand off spare DDCU to EV1 <p>5. Place failed DDCU in ORU Transfer Bag</p>

DDCU REMOVE AND REPLACE – TASK DATA

Estimated Task Duration:

Two EV Crew	1:00
--------------------	------

Tools:

EV1	EV2
PGT	PGT w/7/16 X 6-in socket
7/16 X 6-in socket	EVA Crewlock bag
Square TM w/7/16 in Rec Socket	Large ORU Transfer Bag
Square Scoop	Square Scoop

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Fastener	H1	7/16	1	4.8	31.7	190.3 (R) 22.8 (I)	5-6	30
Fastener	H2	7/16	1	4.8	33.5	188.4 (R) 27.8 (I)	16-17	30

Foot Restraints:

Task	WIF	CETA Position	Swing Arm Settings	APFR Setting
DDCU-E 2B (P6 IEA Non-keel side)	P6-18	N/A	N/A	9, PP, E, 12*
DDCU-E 4B (P6 IEA Keel side)	P6-17	N/A	N/A	2, PP, F, 12*

ORU Identification:

ORU	Part number	Serial Number
Spare DDCU	R076522-121	X650374
Failed DDCU	R076522-121	

Notes:

N/A


Cautions:

1. Acme screws unfastened/fastened out of sequence could lead to jamming of DDCU during removal. When unfastening Acme screws, H1 must be unfastened before H2
2. Avoid contacting DDCU electrical connector mating surfaces
3. Square Scoop should only be installed on H2 fitting for ORU handling. The H1 fitting may not support EVA handling loads

Warnings:

1. Hazard voltage exists at the mating connectors to the DDCU. DDCU interface must be safed before removal
2. Depending on worksite proximity to SAW rotation, **MCC-H** may need to inhibit SAW rotation to avoid collision with the EVA crewmembers
3. Avoid contact with intermeshing fins of the DDCU-E and coldplate due to sharp edge concerns

DDCU REMOVE AND REPLACE – TASK DATA (Cont)



DDCU REMOVE AND REPLACE – TASK DATA (Cont)



DLA REMOVE AND REPLACE

CAUTION

1. During reinstallation of MLI covers, do not reinstall swing bolts on the outboard SARJ race ring side. This will preclude SARJ rotation.
2. Avoid contact between MLI cover and surrounding hardware.
3. Avoid impacting the race ring with the DLA when the DLA is unconstrained.
4. During follower arm rotation (90 deg turn) when the DLA is unconstrained, interference with structure may occur. The DLA must be held against the outer side of the SARJ race ring for the follower arm to rotate fully, clearing obstruction.
5. The following precautions should be observed to prevent loss of inboard MLI cover fasteners during removal:
 - Limit turn count to minimum required for fastener release.
 - Minimize side loading bolt head.
 - Maintain axial force on fastener to compress spring during rotation.
6. If DLA rotation bolts 1B and 2B do not turn freely when attempting to stow the follower arms, there is still partial interference in the mechanism and additional adjustment to the draw bolts is required to prevent damage to the follower arm mechanism.

NOTE

1. Steps 1 to 3, ROTATE DLA DRAW BOLTS (1C AND 2C), are required to evenly release tension load on belleville stacks for bolts 1C and 2C.
2. Multiple iterations of DLA draw bolt adjustments may be required to allow follower arms to rotate.
3. The physical labels of the S3 DLAs do not match the logical names the software uses. To ensure that the appropriate DLA commands were sent to prepare for disengaging the DLA, two visual inspections are performed: the window on the DLA indicates "N" for neutral, and the DLA pinion gear teeth are no longer engaged on the SARJ race ring teeth.
4. The ratchet wrench is used to rotate the DLA follower arms to the stow position. This tool is utilized instead of the PGT to protect against damage to the follower arm mechanism.

DLA REMOVE AND REPLACE (Cont)

IV	EV1	EV2
<p>MCC-H 1. Verify failed DLA is in neutral position with no motors selected and motor setpoints set to zero. Verify active DLA is in locked position with no motors selected and motor setpoints set to zero.</p> <p>2. Give GO for EVA to enter SARJ worksite.</p>	<div data-bbox="646 240 1165 511" style="border: 2px solid black; padding: 5px;"> <p style="text-align: center; background-color: yellow;">CAUTION</p> <p>The following precautions should be observed to prevent loss of inboard MLI cover fasteners during removal:</p> <ul style="list-style-type: none"> Limit turn count to minimum required for fastener release. Minimize side loading bolt head. Maintain axial force on fastener to compress spring during rotation. </div> <p><u>REMOVE DLA MLI COVER</u></p> <ol style="list-style-type: none"> 1. PGT[A6 8.3 ft-lb, CCW2 30RPM, MTL 30.5]-6ext 7/16: Release inboard MLI cover fasteners (four), nine turns. 2. Remove MLI cover and temp stow. 3. On IV GO, install and ingress APFR (refer to Task Data for WIF position and APFR settings). <p><u>VERIFY DLA IN NEUTRAL</u></p> <ol style="list-style-type: none"> 1. Inspect window for neutral indicator, N. 2. Verify DLA pinion gear teeth are not engaged on the SARJ race ring teeth. <p><u>ROTATE DLA DRAW BOLTS (1C AND 2C)</u></p> <ol style="list-style-type: none"> 1. PGT[B7 25.5 ft-lb, CCW1 10RPM, MTL 30.5]-6ext 7/16: Rotate draw bolt 1C, one turn (release tension). 2. PGT[B7 25.5 ft-lb, CW1 10RPM, MTL 30.5]-6ext 7/16: Rotate draw bolt 2C, three turns (release tension). 3. PGT[B7 25.5 ft-lb, CCW1 10RPM, MTL 30.5]-6ext 7/16: Rotate draw bolt 1C, two turns (continue releasing tension). 4. PGT[A3 4.8 ft-lb, CCW2 30RPM, MTL 30.5]-6ext 7/16: Rotate draw bolt 1C, ~32 turns to hard stop. 	<div data-bbox="1197 316 1816 1023"> </div> <p style="text-align: center;">Figure 1.- DLA Bolts and Labels.</p>

DLA REMOVE AND REPLACE (Cont)

IV	EV1	EV2
	<p><u>ROTATE FOLLOWER ARMS (1B AND 2B)</u></p> <div data-bbox="646 297 1167 428" style="border: 1px solid black; padding: 5px;"><p style="text-align: center;">CAUTION</p><p>If DLA rotation bolts 1B and 2B do not turn freely, additional adjustment to the draw bolts is required.</p></div> <div data-bbox="690 472 1167 583" style="border: 1px solid black; padding: 5px;"><p style="text-align: center;"><u>NOTE</u></p><p>Multiple iterations of DLA draw bolt adjustments may be required to allow follower arms to rotate.</p></div> <ol style="list-style-type: none">1. Ratchet Wrench-6ext 7/16: Rotate draw bolt 1C, CW ~1/8 turn.2. Ratchet Wrench-6ext 7/16: Rotate follower arm rotation bolt 1B, CW ~5/8 turn to hardstop.3. If 1B bolt does not turn freely, repeat steps 1 and 2 until follower arm has rotated 90 deg.4. PGT[A3 4.8 ft-lb, CW2 30RPM, MTL 30.5]-6ext 7/16: Rotate follower arm draw bolt 2C, ~32 turns to hard stop.5. Ratchet Wrench-6ext 7/16: Rotate draw bolt 2C, CCW ~1/8 turn.6. Ratchet Wrench-6ext 7/16: Rotate follower arm rotation bolt 2B, CCW ~5/8 turn to hardstop.7. If 2B bolt does not turn freely, repeat steps 5 and 6 until follower arm has rotated 90 deg. <p><u>REPOSITION DLA</u></p> <ol style="list-style-type: none">1. Reposition DLA to launch position [approximately 1 inch away from race ring, then 0.375 inch inboard (toward S0), then 0.5 inch away from race ring]. <p><u>INSTALL THREE DLA LAUNCH RESTRAINT BOLTS (4A, 4B, AND 4C)</u></p> <ol style="list-style-type: none">1. PGT[B4 19.4 ft-lb, CW2 30RPM, MTL 30.5]-6ext 7/16: Engage launch restraint bolts 4A, 4B, and 4C, ~five to nine turns (attaches DLA frame to launch bracket). <p><u>PRELOAD FOLLOWER DRAW BOLTS (1C AND 2C) AND ENGAGE DLA LOCK BOLTS (1A AND 2A)</u></p> <ol style="list-style-type: none">1. PGT[A3 4.8 ft-lb, CCW2 30RPM, MTL 30.5]-6ext 7/16: Preload draw bolt 1C, ~zero to two turns to hardstop.2. PGT[A3 4.8 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16: Preload draw bolt 2C, ~zero to two turns to hardstop.	

DLA REMOVE AND REPLACE (Cont)

IV	EV1	EV2												
<p data-bbox="642 245 1743 326">3. PGT[A5 7.0 ft-lb, CW1 10RPM, MTL 30.5]-6ext 7/16: Engage lock bolts 1A and 2A fasteners (two), ~six turns (engage lock preload on follower arm with lock tip bolt).</p> <p data-bbox="642 354 989 378"><u>RELEASE DLA CONNECTORS</u></p> <p data-bbox="642 407 1020 431">1. Perform the following demates:</p> <table data-bbox="642 436 1094 516"><tr><td>DLA 2</td><td>DLA 1</td></tr><tr><td><input type="checkbox"/> P1 ← → J23</td><td><input type="checkbox"/> P1 ← → J21</td></tr><tr><td><input type="checkbox"/> P2 ← → J24</td><td><input type="checkbox"/> P2 ← → J22</td></tr></table> <p data-bbox="642 516 1146 540">2. Install dust caps on connectors, if available</p> <p data-bbox="642 570 963 594"><u>RELEASE BRACKET BOLTS</u></p> <p data-bbox="642 623 1812 704">1. PGT[B7 25.5 ft-lb, CCW2 30RPM, MTL 30.5]-6ext 7/16: Release 5A, 5B, and 5C in any order, 8-10 turns 2. Remove DLA, lift straight up away from race ring 3. Temp stow DLA on MUT EE/Ballstack on S3 HR 3060/TBD</p> <p data-bbox="642 734 1171 790"><u>PERFORM CLEANING/LUBING OF RACE RING</u> Clean and lube as required</p> <p data-bbox="642 820 953 844"><u>ENGAGE BRACKET BOLTS</u></p> <p data-bbox="642 849 1793 930">1. Retrieve DLA 2. Install DLA onto race ring 3. PGT[B7 25.5 ft-lb, CW2 30RPM, MTL 30.5]-6ext 7/16: Engage 5A, 5B, and 5C in any order, 8-10 turns</p> <p data-bbox="642 959 980 984"><u>ENGAGE DLA CONNECTORS</u></p> <p data-bbox="642 1013 1440 1037">4. Perform the following connector mates, stowing any dust caps as reqd:</p> <table data-bbox="642 1042 1104 1122"><tr><td>DLA 2</td><td>DLA 1</td></tr><tr><td><input type="checkbox"/> P1 → ← J23</td><td><input type="checkbox"/> P1 → ← TBD</td></tr><tr><td><input type="checkbox"/> P2 → ← J24</td><td><input type="checkbox"/> P2 → ← TBD</td></tr></table> <p data-bbox="642 1151 1110 1175"><u>ROTATE DLA DRAW BOLTS (1C AND 2C)</u></p> <p data-bbox="642 1180 1325 1205">(This decreases friction between pivot fork and follower bracket)</p> <p data-bbox="642 1209 1593 1260">5. PGT[A3 4.8 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16: Rotate draw bolt 1C, 2 turns 6. PGT[A3 4.8 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16: Rotate draw bolt 2C, 2 turns</p>			DLA 2	DLA 1	<input type="checkbox"/> P1 ← → J23	<input type="checkbox"/> P1 ← → J21	<input type="checkbox"/> P2 ← → J24	<input type="checkbox"/> P2 ← → J22	DLA 2	DLA 1	<input type="checkbox"/> P1 → ← J23	<input type="checkbox"/> P1 → ← TBD	<input type="checkbox"/> P2 → ← J24	<input type="checkbox"/> P2 → ← TBD
DLA 2	DLA 1													
<input type="checkbox"/> P1 ← → J23	<input type="checkbox"/> P1 ← → J21													
<input type="checkbox"/> P2 ← → J24	<input type="checkbox"/> P2 ← → J22													
DLA 2	DLA 1													
<input type="checkbox"/> P1 → ← J23	<input type="checkbox"/> P1 → ← TBD													
<input type="checkbox"/> P2 → ← J24	<input type="checkbox"/> P2 → ← TBD													

DLA REMOVE AND REPLACE (Cont)

IV	EV1	EV2
	<p><u>BACK OFF DLA LOCK BOLTS (1A AND 2A)</u> (Releases lock preload on follower arm, lock tip bolt retracted from follower bracket)</p> <p>7. PGT[A6 8.3 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16: Release lock bolts 1A and 2A fasteners (2), 6 turns</p> <p><u>RELEASE 3 DLA LAUNCH RESTRAINT BOLTS (4A, 4B, 4C)</u> (This allows the DLA frame to move relative to the launch bracket)</p> <p>8. PGT[B7 25.5 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16: Release launch restraint bolts 4A, 4B, 4C, ~8-10 turns – bolt pops up</p> <p><u>REPOSITION DLA AND ROTATE FOLLOWER ARMS</u></p> <p>9. Reconfigure PGT[A3 4.8 ft-lb, CCW1 10 RPM, MTL 30.5]-6ext 7/16: Reposition DLA onto race ring (approx 3/8 inch outboard, 1.5 inches radially in) Rotate follower arm rotation bolt 1B, ~5/8 turn to hardstop</p> <p>10. Verify follower arm has rotated 90 deg</p> <p>11. PGT[A3 4.8 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16: Rotate follower arm draw bolt 1C, ~32 turns to torque</p> <p>12. Verify follower bearings are in contact with race ring</p> <p>13. PGT[A3 4.8 ft-lb, CW1 10 RPM, MTL 30.5]-6ext 7/16: Rotate follower arm rotation bolt 2B, ~5/8 turn to hardstop</p> <p>14. Verify follower arm has rotated 90 deg</p> <p>15. PGT[A3 4.8 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16: Rotate follower arm draw bolt 2C, ~32 turns to torque</p> <p>16. Verify follower bearings are in contact with race ring</p> <p>17. PGT[B4 19.4 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16: Final installation torque on follower arm draw bolt 2C, ~4 turns to torque</p> <p>18. PGT[B4 19.4 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16: Final installation torque on follower arm draw bolt 1C, ~4 turns to torque</p> <p><u>INSPECT DLA</u></p> <p>19. On MCC GO, verify DLA pinion gear teeth fully engaged to SARJ race ring teeth</p> <p><u>REINSTALL DLA MLI COVER</u></p> <p>1. PGT[A1 2.5 ft-lb, CW2 30RPM, MTL 30.5]-6ext 7/16: Engage inboard MLI cover fasteners (four), ~nine turns.</p>	

DLA REMOVE AND REPLACE – TASK DATA

Table 1. Estimated Task Duration

	With SSRMS	Without SSRMS
One EV Crew	N/A	1:00
Two EV Crew	N/A	0:45

Table 2. Tools

EV1 (FF)	EV2 (FF)
PGT	PGT
6 Ext 7/16	6 Ext 7/16
APFR	
Round Scoop (optional)	

Table 3. EVA Fasteners

Fastener Name	Label	Head Size (in)	Qty	Install Torque (ft-lb)	Max Break Away Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
MLI Cover Inboard Fasteners	N/A	7/16	4 per cover	2.5	3.4	3.8 (Install) 13.7 (Release)	7 to 9	30
DLA 1A and 2A Lock Bolts	Yes	7/16	2	3.3 to 6.3	6.7	42.2	6	30
DLA 1C and 2C Draw Bolts	Yes	7/16	2	19.4 initial 4.8 final	25.7*	29.1 init 38.9 final	3 to 4 init 32 to 33 final	10 init 30 final
DLA 4A, 4B, and 4C Launch Restraint Bolts	Yes	7/16	3	24 to 26	25.0	50 - A and B 75 - C	4 to 6 - A and B 6 to 9 - C	30
DLA 1B and 2B Follower Arm Rotation Bolts	Yes	7/16	N/A	4.8	~1	10.6	5/8	10

*Max On-Orbit Installable Torque

DLA REMOVE AND REPLACE – TASK DATA (Cont)

Table 4. Foot Restraints

Task	WIF	APFR Setting	SARJ Angle
P3 Cover 5 DLA 1 Face 6	P3-31	7, PP, F, 12	NA
P3 Cover 20 DLA 2 Face 2	P4-04	6, PP, L, 1	180
S3 Cover 5 DLA 1 Face 2	S3-28	2, PP, F, 12	NA
S3 Cover 20 DLA 2 Face 6	S4-04	6, PP, L, 1	0

Table 5. DLA/RJMC Labeling

Location	Physical Label	Software/Logical Name
S3, Face 6	DLA 2	DLA 1
S3, Face 6	RJMC 2	RJMC 1
S3, Face 2	DLA 1	DLA 2
S3, Face 2	RJMC 1	RJMC 2
P3, Face 6	DLA 1	DLA 1
P3, Face 6	RJMC 1	RJMC 1
P3, Face 2	DLA 2	DLA 2
P3, Face 2	RJMC 2	RJMC 2

DLA REMOVE AND REPLACE – TASK DATA (Cont)




Figure 2.- DLA.





Figure 3.- DLA Window.

MBSU REMOVE/REPLACE

IV/SSRMS	EV1(SSRMS)	EV2 (FF)
<p>IV 1. Verify with MCC S0 inhibits in place (see Task Data)</p> <p>IV 2. Verify with MCC ESP2 inhibits in place – RPCM N1RS2-B RPC10 (open and close inhibited) – RPCM S04B F RPC 12 (open and close inhibited)</p> <p>SSRMS 3. At TBD APFR install posn</p> <p>IV 4. Verify SSRMS in standby prior to APFR install</p> <p>SSRMS 5. On EV GO – to APFR Ingress posn, as reqd</p> <p>SSRMS 6. On EV GO – to MBSU worksite</p> <p>IV 7. Record s/n of failed MBSU</p> <p>_____</p>	<p><u>S0 MBSU R&R SETUP</u></p> <ol style="list-style-type: none"> 1. Retrieve APFR from TBD location 2. Translate to SSRMS APFR install location 3. Install WIF adapter in SSRMS PFR socket, tether point toward EE 4. Install APFR (12,PP,F,6) in SSRMS WIF adapter (Toes away from EE) – Pull test – Verify APFR lock collar black on black 5. Safety tether swap to SSRMS, verify hook locked; attach A/L safety tether to nearby HR 6. GCA SSRMS for APFR ingress 7. Ingress SSRMS APFR 8. GCA SSRMS to MBSU worksite 	<p><u>S0 MBSU R&R SETUP</u></p> <ol style="list-style-type: none"> 1. Translate to ESP2; attach BRT to ESP2 HR 8003 (aft face, stbd side) 2. Remove MLI from spare MBSU (hinge is FWD) <ul style="list-style-type: none"> <input type="checkbox"/> Release Velcro tabs on front, side, and back corners of ORU base <input type="checkbox"/> Release integral strap from underside of fwd flap <input type="checkbox"/> Fold or roll cover toward back of MBSU, attach strap to Velcro mating swatch on back side of MLI <input type="checkbox"/> Using side straps from front of MLI, secure rest of MLI as reqd 3. Translate up CETA Spur to S0 Face 1 4. Translate to failed MBSU 5. Verify failed MBSU P/N and s/n to IV <div style="border: 2px solid black; background-color: yellow; text-align: center; padding: 2px;">CAUTION</div> <div style="border: 1px solid black; padding: 2px; text-align: center;">Minimize loads on H1 microfixture</div> <ol style="list-style-type: none"> 6. Install Sq TM on H1 fitting; √anti-backlash neutral

MBSU REMOVE/REPLACE (Cont)

IV/SSRMS	EV1(SSRMS)	EV2 (FF)
 <p>Jacking bolt, Scoop install location</p>	<p><u>MBSU REMOVAL</u></p> <div style="border: 2px solid black; background-color: yellow; padding: 5px; text-align: center; margin-bottom: 10px;">CAUTION</div> <p>Acme screws unfastened/fastened out of sequence could lead to jamming of MBSU</p> <p>On MCC GO:</p> <ol style="list-style-type: none"> 1. PGT [B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT 5 turns (1 turn at bolt) on H1 2. Remove Sq TM and install on H2 fitting; √anti-backlash neutral 3. PGT [B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT 5 turns (1 turn at bolt) on H2 4. Transfer TM to EV2 5. PGT [B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6 Ext 7/16: Drive H1 minimum 5 turns 6. √Status indicator – UNLOCK 7. Receive Sq Scoop from EV2; install on H2 8. PGT [B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6 Ext 7/16: Drive H2 minimum 16 turns 9. √Status indicator – UNLOCK 10. Stow PGT <div style="border: 2px solid black; background-color: red; color: white; padding: 5px; text-align: center; margin-bottom: 10px;">WARNING</div> <p>Avoid contact with intermeshing fins of the MBSU and coldplate</p> <ol style="list-style-type: none"> 11. Remove MBSU from coldplate (soft dock on H2 15-20 lb) 	<p><u>MBSU REMOVAL</u></p> <ol style="list-style-type: none"> 1. Receive Sq TM from EV1; stow on MWS 2. Transfer Sq Scoop to EV1

MBSU REMOVE/REPLACE (Cont)

IV/SSRMS	EV1(SSRMS)	EV2 (FF)									
<p>SSRMS 10. On EV GO – to MBSU worksite</p> <p>IV 11. Record spare MBSU installation turns and torque</p> <table border="1" data-bbox="109 961 480 1092"> <thead> <tr> <th>Bolt</th> <th>Turns</th> <th>Torque</th> </tr> </thead> <tbody> <tr> <td>H2</td> <td></td> <td></td> </tr> <tr> <td>H1</td> <td></td> <td></td> </tr> </tbody> </table> <p>SSRMS 12. On EV GO – to spare safety tether location</p>	Bolt	Turns	Torque	H2			H1			<p>18. PGT [B3 18.4 ft-lb, CW2 30 RPM, MTL 30.5]-6 Ext-7/16 Drive H1, 5-6 turns</p> <p>19. √H1 status indicator – LOCK</p> <p>20. Remove Sq Scoop; stow on MWS</p> <p>21. Install thermal cover on failed unit</p> <p>22. Receive spare MBSU</p> <p>23. GCA SSRMS to MBSU worksite</p> <p><u>INSTALL SPARE MBSU</u></p> <p>1. Orient MBSU such that blind-mate connectors and H2 are oriented correctly</p> <div data-bbox="627 717 1167 865" style="border: 2px solid black; padding: 5px; text-align: center;"> <p>CAUTION</p> <p>There is a TBD thermal dwell time between the MBSU & coldplate. Wait TBD time prior to driving bolt</p> </div> <p>2. Install spare MBSU (soft dock on H2 15-20 lbs)</p> <p>3. √Status indicator on H1 and H2 are in UNLOCK</p> <p>4. PGT [A3 4.8 ft-lb, CW2 30 RPM, MTL 30.5]-6 Ext-7/16 Drive H2, 16-17 turns</p> <p>5. √H2 status indicator – LOCK</p> <p>6. PGT [A3 4.8 ft-lb, CW2 30 RPM, MTL 30.5]-6 Ext-7/16 Drive H1, 5-6 turns</p> <p>7. √H1 status indicator – LOCK</p> <p>8. Give MCC-H GO to restore power to MBSU</p> <p><u>CLEANUP</u></p> <p>1. GCA SSRMS to spare safety tether anchor point</p> <p>2. Egress APFR; tether swap back to A/L safety tether, verify hook locked</p> <p>3. Remove APFR; stow in TBD location</p> <p>4. Remove WIF Adapter; stow in small trash bag</p>	<p>7. Transfer spare MBSU to EV1</p> <p><u>INSTALL SPARE MBSU</u></p> <p>1. Translate to worksite</p> <p>2. Inspect guide rails and connectors for debris/damage</p> <p>3. Assist EV1 with MBSU install</p> <p><u>CLEANUP</u></p> <p>1. Remove Sq scoop from MBSU</p>
Bolt	Turns	Torque									
H2											
H1											

MBSU REMOVE/REPLACE – TASK DATA

Estimated Task Duration:

	With SSRMS
One EV Crew	N/A
Two EV Crew	3:00

Tools:

EV1	EV2
Square scoop	EVA Crewlock bag (optional)
PGT – 6 Ext 7/16	Square Scoop
WIF Adapter	EVA Ratchet 3/8 drive – 6 Ext 7/16 (backup)
Safety Tether (SSRMS)	Sq TM 7/16 rec
APFR	MUT EE
	Ballstack

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Max Break Away Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
H1 (Secondary Bolt)	H1	7/16	1	4.8 (S0) 18.4 (FSE)	31.7	190.3 (R) 22.8 (I)	5-6	30
H2 (Primary Bolt)	H2	7/16	1	4.8 (S0) 18.4 (FSE)	33.5	188.4 (R) 27.8 (I)	16-17	30

Foot Restraints:

Task	WIF	Swing Arm Setting	APFR Setting
MBSU	SSRMS	N/A	12, PP, F, 6
MBSU 4A4B (CETA at Bay 02)	3	13, 12, GG	9, TT, F, 12
MBSU 1A1B (CETA at Bay 00)	3	13, 12, GG	9, TT, F, 12
MBSU 3A3B (CETA at Bay 00)	2	15, 12, GG	3, TT, F, 12
MBSU 2A2B (CETA at Bay 02)	2	15, 12, GG	3, TT, F, 12

ORU Data:

ORU	Part Number	Serial Number	Mass	Dimensions
MBSU 1A1B	R072591-41	X700385	236 lb	40" x 28" x 12"
MBSU 2A2B	R072591-41	X700386	236 lb	40" x 28" x 12"
MBSU 3A3B	R072591-41	C250636	236 lb	40" x 28" x 12"
MBSU 4A4B	R072591-41	C250637	236 lb	40" x 28" x 12"
Spare MBSU	R072591-41	X652064	236 lb	40" x 28" x 12"
Spare MBSU	R072591-41	TBD	236 lb	40" x 28" x 12"

Power Inhibits:

MBSU	DCSU Inhibits	MBSU Inhibits
MBSU 1A1B	DCSU 1A RBI 6 open DCSU 1B RBI 6 open	MBSU 4 RBI 6 open MBSU 4 RBI 7 open MBSU 2 RBI 14 open
MBSU 2A2B	DCSU 2A RBI 6 open DCSU 2B RBI 6 open	MBSU 1 RBI 6 open MBSU 3 RBI 7 open MBSU 1 RBI 14 open
MBSU 3A3B	DCSU 3A RBI 6 open DCSU 3B RBI 6 open	MBSU 2 RBI 6 open MBSU 2 RBI 7 open MBSU 4 RBI 14 open
MBSU 4A4B	DCSU 4A RBI 6 open DCSU 4B RBI 6 open	MBSU 3 RBI 6 open MBSU 1 RBI 7 open MBSU 3 RBI 14 open

Notes:

- H1 is secondary bolt, H2 is primary bolt
- NO ACTION is required when Acme screw torque and appropriate number of turns has been met and the status indicator is not at the LOCKED position. Report anomaly
- Removing MBSU from coldplate causes H1 status indicator to move from UNLOCK to LOCK
- There is no hard stop when releasing H1 and H2 bolts; upon release, they will free spin
- Primary stanchion (H2) has ~15-20 lb soft dock force to overcome during MBSU removal and installation from/to FSE & coldplate
- H1 and H2 status indicators are not identical, see drawing below

Cautions:

- Acme screws unfastened/fastened out of sequence could lead to jamming of MBSU during removal. When unfastening Acme screws, H1 must be unfastened before H2. When fastening Acme screws, H2 must be fastened before H1
- Ensure ORU is maintained level and perpendicular to the tiedown stanchions during installation. Failure to comply may damage H2 status indicator probe
- Minimize force applied to H1 microfixture. It is not rated to withstand excessive loads
- There is a TBD thermal dwell time between the MBSU and coldplate. Wait TBD time, prior to driving bolts


Warnings:

- Hazard voltage exists at the connectors of the MBSU. MBSU must be safed before removal
- Avoid contact with intermeshing fins of the MBSU and coldplate due to sharp edge concerns

MBSU REMOVE/REPLACE – TASK DATA (Cont)


MBSU locations

Spare
MBSU




MBSU REMOVE/REPLACE – TASK DATA (Cont)

H2 Status Indicator



Positional Criteria
(Adhered to in accordance with torque and turns specified in LSAR procedure.)



Locked, Nominal: The lock/unlock slot should be centered in relation to the silver mark.



Unlocked, Nominal: The lock/unlock slot should be centered in relation to the silver mark.



Locked, Tolerance: The lock/unlock slot can be left or right of nominal by a distance no greater than the width of the black stripe.




Unlocked, Tolerance: The lock/unlock slot can be left or right of nominal by a distance no greater than the width of the black stripe.



LOG-1010-01

H1 Status Indicator



Positional Criteria
(Adhered to in accordance with torque and turns specified in LSAR procedure.)

Unlocked, Nominal: The unlock slot should be centered in relation to the silver mark.



Locked, Nominal: The right edge of the lock slot should be flush with the right edge of the silver mark.



Unlocked, Tolerance: The unlock slot can be left or right of nominal by a distance no greater than the width of the black stripe.



Locked, Tolerance: The lock slot can be left of nominal by a distance no greater than the width of the black stripe.



LOG-1009-01



Spare MBSU w/MLI attached to FRAM on ESP-2



MBSU at worksite

RJMC REMOVE AND REPLACE

IV/SSRMS	EV2												
<p>1. Receive GO from MCC for RJMC R&R (inhibits in place)</p> <table border="1" data-bbox="121 495 556 657"> <thead> <tr> <th>Bolt</th> <th>Torque</th> <th>Turns</th> </tr> </thead> <tbody> <tr> <td>Center</td> <td></td> <td></td> </tr> <tr> <td>Outer (fwd)</td> <td></td> <td></td> </tr> <tr> <td>Outer (aft)</td> <td></td> <td></td> </tr> </tbody> </table>	Bolt	Torque	Turns	Center			Outer (fwd)			Outer (aft)			<p><u>RJMC R&R</u></p> <ol style="list-style-type: none"> 1. Translate to S3 RJMC 2. PGT[B7 25.5 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16: Release outer bolts (2) to hardstop, ~13 turns 3. PGT[B7 25.5 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16: Release center jack bolt to hardstop, ~28 turns 4. Remove RJMC; temp stow 5. Inspect ISS guide rails and connector receptacles 6. Retrieve new RJMC from Large ORU Bag 7. Install RJMC along guide pins into soft dock position 8. PGT[B2 16.0 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16: Engage center jack bolt to hardstop, 28 turns 9. PGT[B1 12.0 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16: Engage outer bolts (2) to hard stop, 13 turns 10. Stow old RJMC in Large ORU Bag 11. Perform Final Bag and Tool Inventory 12. Perform Glove Inspection
Bolt	Torque	Turns											
Center													
Outer (fwd)													
Outer (aft)													

SSRMS JOINT DRIVE

CAUTION

Avoid contact with:

- ACU radiator surface: Silver Teflon film (white in color)
- CLA and CLPA radiator surface: Silver Teflon film (white in color)
- VDU radiator surface: Silver Teflon film (white in color)
- JEU radiator surface: Z93 paint

NOTE

Gear ratio: 3.26 EVA drive turns/1 deg of joint movement.

cw input to EVA drive will produce ccw motion of joint.


Starting from LEE, order of joints: Roll, yaw, pitch.

Signs of logical (indicated on RWS or PCS) and physical (indicated on EVA scale) angles are reversed for the shoulder roll, shoulder yaw, and wrist roll joint (i.e., +73.2 logical = -73.2 physical) regardless of which end is base


Scale and Ambiguity Switch

- ❑ Since SSRMS joints can be rotated more than 360 deg, there is an ambiguity switch that tells the crewmember whether to use positive or negative scale
- ❑ Crew reads scale using black triangle on fixed side of joint. Located to side of black triangle (~90 deg around the circumference of the joint) is the ambiguity switch. Switch has a pointer that indicates “+” or “-” to tell crew which side of scale to read. If ambiguity switch points to “+”, then crew should read off yellow scale (black text on yellow background). If switch points to “-”, then crew should read off black scale (yellow text on black background)
- ❑ EVA drive handle is on back side of joint (away from LEE), and scale triangle is across from it towards LEE side

SSRMS JOINT DRIVE (Cont)

IV/RMS	EV1	REFERENCE
<p>SSRMS 1. <u>EVA JOINT DRIVE POSITION</u></p> <p>IV 2. Record ambiguity sensor reading and joint angle: _____ Monitor SSRMS joint angle Report position to EV1 Give EV1 STOP when joint angle is at desired position</p> <div data-bbox="115 722 609 1209">  <p>Joint Scale and Black Triangle</p> <p>Ambiguity Switch</p> <p>EVA Drive Handle (@ motor posn)</p> <p>Ambiguity Switch</p> <p>12:00</p> <p>3:00</p> <p>Back Side of Joint</p> </div>		

SSRMS JOINT DRIVE (Cont)



Task Data:

Table 1. Tools

EV1 (FF)
PGT
7/16 (wobble) Socket-6 ext
BRT
Square Scoop

Table 2. EVA Fasteners

Fastener Name	Label	Head Size	Qty	Min Drive Torque (ft-lb)	Max Drive Torque (ft-lb)	Failure Torque (ft-lb)	RPM
EVA Drive		7/16-in	1	1.25	2.5		30

Foot Restraints: N/A

SSRMS JOINT DRIVE (Cont)





Figure 1.- Roll/Pitch Joint ORU.

SARJ – TBA REMOVE/INSTALL

Remove

WARNING

Potential exists for sharp edge hazards on the bearing package and mount. Attempt to limit contact to tether points only

1. Verify failed TBA serial number
2. Demate TBA connector P1 from inboard receptacle on SARJ ring
3. Install SARJ dust cap on receptacle
4. Install TBA dust cap on TBA connector
5. Tether to bearing package
6. Tether to mount

CAUTION

Two TBAs cannot be out at the same time unless the two TBAs are 90, 120, or 180 deg apart from each other

7. **PGT [B7 25.5 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16:**
Break torque on TBA bolts (3), 1 turn each
8. **PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16:**
Loosen bolt 3 (mount bolt), 1 turn
9. **PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16:**
Loosen bolt 1 (bearing preload bolt), 6 turns
10. **PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16:**
Release bolt 2 (draw bolt), 12 turns until preload arm swings open (into SARJ bearing package will also move away from SARJ and mount)
11. Verify TBA bag in open position
12. Stow bearing package in TBA bag

NOTE

Do not push in while turning mount bolt 3; will cause mount clamping leg to side load bolt 3 and increase torque


13. **PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6ext 7/16:**
Release bolt 3 (mount bolt), 4 turns
14. Engage mount bolt 3 with PGT and press to open mount clamping leg
15. Remove mount from race ring
16. Stow mount in TBA Bag
17. Secure bag closed, stow in ORU Bag
18. Clean and Lube Race Ring as required

Install

NOTE

Limit force to engage mount bolt 3; too much force opens mount clamping leg

1. Retrieve new mount package from bag; report serial number
2. Verify mount clamping leg is open
3. Engage mount onto race ring, aligning mount boss with slot in race ring
4. Close mount clamping leg
5. **PGT[A2 3.8 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16:** Engage bolt 3 (mount bolt), 2 turns
6. Retrieve bearing package; report serial number
7. Engage bearing package onto race ring, guiding bearing arm through race ring
8. **PGT[A3 4.8 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16:** Engage bolt 2 (draw bolt), ~10.5-13 turns to torque until preload arm engages race ring (bearing package will also move toward SARJ and mount package)
9. **PGT[A5 7.0* ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16:** (*for Flight TBA)
Engage bolt 1 (bearing preload bolt), ~5-7 turns to torque
10. **PGT[A2 3.8 ft-lb, CW2 30 RPM, MTL 30.5]-6ext 7/16:**
Tighten bolt 3 (mount bolt), ~2-4 turns to torque
11. Remove dust cap on inboard receptacle; stow in TBA bag
12. Remove TBA connector dust cap; stow in TBA bag



NOTE

Verify pin and EMI band integrity; connector free of FOD

13. Mate connector to inboard receptacle on SARJ race ring
14. WVS Survey of work area; clean up work area; reinstall MLI cover

Outboard ← → Inboard

TBA	s/n	Bolt 2		Bolt 1		Bolt 3	
		Turns (~10.5-13)	Torque (4.8)	Turns (~5-7)	Torque (7.0)	Turns (~2-4)	Final Torque (3.8)

SARJ – TBA INSTALL – TASK DATA

Estimated Task Duration:

	With RMS	Without RMS
One EVA Crew	N/A	
Two EVA Crew	N/A	

Tools:

EV1	EV2
PGT w/6" ext-7/16	PGT w/6" ext-7/16
Large ORU Bag	Fish Stringer
Fish Stringer	Crewlock Bag
Crewlock Bag	Grease Gun – Straight Nozzle
Grease Gun – Straight Nozzle	Grease Gun – J Nozzle
Grease Gun – J Nozzle	EVA Wipe Caddy
EVA Wipe Caddy	EVA Wipes (dry)
EVA Wipes (dry)	EVA Greased Wipes (wet)
EVA Greased Wipes (wet)	Scraper Debris Container
Scraper Debris Container	Scraper
Scraper	Large Trash Bag
Large Trash Bag	Camera
Camera w/Flash	

EVA Fasteners:

Fastener Name	Label	Qty	Head Size	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
TBA Bearing Preload Bolt	1	1	7/16"	STA: 12.0 Flight: 7.0	18.4	Remv: 21.2 Install: STA: 13.2 Flight: 8.3	5-7	30
TBA Draw Bolt	2	1	7/16"	4.8	18.4	Remv: 21.2 Install: 6.6	10.5-13	30
TBA Mount Bolt	3	1	7/16"	3.8	12.0	Remv: 14.6 Install: 5.1	4-6	30

EVA Connectors:

Harness	From	To	Conn Size	Function
TBA electrical harness P1	Hardwired to TBA	SARJ connector J__ (see TBA Reference Info)	15	Power and data to TBA



Figure 1. TBA Bag

SARJ – TBA INSTALL – TASK DATA (Cont)

TBA Reference Info:

TBA #	S3 TBA Serial Number	S3 Inboard SARJ Label
1	TBA-1032	J9
2	TBA-1029	J10
3	TBA-1033	J11
4	TBA-1035	J12
5	TBA-1026	J13
6	TBA-1017	J14
7	TBA-1036	J15
8	TBA-1031	J16
9	TBA-1030	J17
10	TBA-1037	J18
11	TBA-1023	J19
12	TBA-1034	J20




Figure 2. Trundle Bearing Assembly – Labeled



Figure 3. Fairchild Fastener

Notes:

- Each TBA ORU consists of a bearing package and a mount assembly, which are a matched drilled set. They are always removed and replaced together, but must be separated to do so
- The mount bolt (Bolt 3) is springloaded. When depressed with enough force (approximately 2 lb), the bolt end pushes against the threaded interface, overcoming the two ball detents that hold the clamping leg in the closed position. The clamping leg will then spring open, freeing the mount from the race ring. In order to engage the threads during TBA installation, rotation of the bolt must begin prior to pressing in on the fastener to preclude inadvertent opening of the clamping leg
- The mount bolt (Bolt 3) must be partially released during bearing installation and removal to increase tolerance between the bearing and mount interface
- Tether hook must be removed from mount during bearing package installation and removal due to interference
- Clamping leg closure is accomplished by placing gloved hand through gap in the two race rings and pressing clamp against ring
- The spare SARJ dust cap tether point is top mounted; the SARJ dust cap tether point on the outboard receptacles are side mounted
- EVA Wipe Caddy O-rings may fail during extreme cold conditions such that EVA wipes cannot be retrieved from the caddy; such thermal extremes should not be reached during EVAs on STS-126/ULF-2
- STA TBA Install Torque on Bolt 1 is B1 (12.0 ft-lb). Setting listed in procedure is for a Flight TBA only
- This procedure was taken from STS-126/ULF-2. The only changes made were from STA TBA to Flight TBA and deletion of cleaning/lubing references

Cautions:

- To prevent loss of inboard MLI cover fasteners during removal:
Limit turn count to minimum required for fastener release
Minimize side loading bolt head
Maintain axial force on fastener to compress spring during rotation
- SARJ Race Ring is not tolerant to nicks and scratches. Exercise care within the vicinity of the Race Ring while handling components
- Two TBAs cannot be out at the same time unless the two TBAs are 90, 120, or 180 deg apart from each other
- The port SARJ must be locked for EVA ops outboard of the starboard AJIS struts

SARJ – TBA INSTALL – TASK DATA (Cont)

Warnings:

1. Potential exists for sharp edge hazards on the TBA bearing package and mount. Attempt to limit contact to tether points only
2. Verify SARJ is locked (one DLA locked, one DLA engaged) to prevent rotation while EV crew is in vicinity of rotational plane plus 2 feet




Figure 4. Bearing Package Assembly



Figure 5. Mount Assembly




Figure 6. Trundle Bearing Assembly




Figure 7. Slot in Race Ring to Align Mount



Figure 8. Mount Assy on Race Ring, mount leg clamp open (initial position)



Figure 9. Mount Assy on Race Ring, mount leg clamp closed (final position)

SARJ – TBA INSTALL – TASK DATA (Cont)




Figure 10. TBA Roller Bearings




Figure 11. Roller Bearing Close-Up




Figure 12. Bearing Package Cable




Figure 13. Bearing Package Cable – Open View

SARJ – TBA INSTALL – TASK DATA (Cont)




Figure 14. TBA Install Sequence

BCDU REMOVE/REPLACE

WARNING

1. Depending on worksite proximity to SAW rotation, **MCC-H** may need to inhibit SAW rotation to avoid collision with the EVA crewmembers.
2. Hazardous voltage exists at the mating connectors to the failed BCDU. BCDU interface must be safed before removal.

CAUTION

1. Acme screws unfastened/fastened out of sequence could lead to jamming of BCDU during removal/installation. When unfastening Acme screws, H1 must be unfastened before H2. When fastening Acme screws, H2 must be fastened before H1.
2. Avoid contacting BCDU mating surface (electrical connectors and cooling fins) with structure during translation with BCDU.
3. Ensure ORU is maintained level and perpendicular to stanchion during installation. Failure to comply may damage H2 status indicator probe.
4. Minimize force applied to H1 microfixture. It is not rated to withstand excessive loads.

NOTE

1. Thermal conditioning of the spare BCDU before installation may be required
2. BCDU will travel outward or inward as Acme screw H2 is unfastened or fastened.
3. Lock SARJ when translating outboard of SARJ.
4. There is no hard stop when releasing H1 and H2 bolts; upon release, they will free spin.

BCDU REMOVE/REPLACE (Cont)

IV	EV1	EV2
<p>MCC-H</p> <ol style="list-style-type: none"> 1. Verify SARJ locked 2. Verify BGAs locked 3. Verify Inhibits for spare BCDU complete. <p>Give EV GO for spare BCDU removal.</p>	<p><u>REMOVE SPARE BCDU FROM S6</u></p> <ol style="list-style-type: none"> 1. Translate to S6 spare BCDUs. 2. Ingress APFR. 3. Open thermal cover and tether as reqd. <div data-bbox="678 508 1283 610" style="border: 1px solid black; background-color: yellow; padding: 5px;"> <p align="center">CAUTION</p> <p>Acme screws unfastened/fastened out of sequence could lead to jamming of BCDU.</p> </div> <ol style="list-style-type: none"> 5. Install Sq TM onto H1. √Anti-backlash – neutral 6. PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT five turns (one turn at bolt) on H1. 7. Remove Sq TM; install on H2 fitting. √Anti-backlash – neutral 8. PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT five turns (one turn at bolt) on H2. 9. Remove Sq TM. 10. PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6 ext 7/16: Drive H1 minimum five turns. 11. √Status indicator – UNLOCK 12. Install Square Scoop on H2. 13. PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6 ext 7/16: Drive H2 minimum 16 turns. 14. √Status indicator – UNLOCK 15. Remove BCDU from S6 FSE. 16. Transfer spare BCDU to EV2. 	<p><u>REMOVE SPARE BCDU FROM S6</u></p> <ol style="list-style-type: none"> 1. Translate to S6 spare BCDUs. 2. Set up APFR (refer to Task Data). <div data-bbox="1356 889 1961 1101" style="border: 1px solid black; background-color: yellow; padding: 5px;"> <p align="center">CAUTION</p> <p>Avoid contacting BCDU mating surface (electrical connectors and cooling fins) with structure during translation with BCDU.</p> <p>Minimize force applied to H1 microfixture. It is not rated to withstand excessive loads.</p> </div> <ol style="list-style-type: none"> 3. Receive spare BCDU from EV1 and stow on BRT.

BCDU REMOVE/REPLACE (Cont)

IV	EV1	EV2
<p>IV</p> <p>3. Record S/N of failed BCDU: _____</p> <p>MCC-H</p> <p>4. Verify electrical power inhibits for failed BCDU complete. Give EV GO for failed BCDU removal.</p>	<p><u>REMOVE FAILED BCDU</u></p> <ol style="list-style-type: none"> 1. Translate to IEA worksite. 2. Set up and ingress APFR (refer to Task Data). 3. Verify failed BCDU P/N and S/N to IV. 4. Install Sq TM onto H1. √Anti-backlash – neutral 5. On MCC-H GO, PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-Sq TM-7/16Rec: Drive PGT five turns (one turn at bolt) on H1. 6. Remove Sq TM; Install on H2 fitting. √Anti-backlash – neutral 7. PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-Sq TM-7/16: Drive PGT five turns (one turn at bolt) on H2. 8. Remove Sq TM. 9. PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6 ext 7/16: Drive H1 minimum five turns. 10. √Status indicator – UNLOCK 11. Install Square Scoop on H2. 12. PGT[B1 12.0 ft-lb, CCW2 30 RPM, MTL 30.5]-6 ext 7/16: Drive H2 minimum 16 turns. 13. √Status indicator – UNLOCK 14. Remove failed BCDU. 15. Stow failed BCDU on BRT. <div style="border: 2px solid black; padding: 5px; margin-top: 10px;"> <p style="text-align: center; background-color: yellow;">CAUTION</p> <p>Ensure ORU is maintained level and perpendicular to stanchion during installation. Failure to comply may damage H2 status indicator probe.</p> </div>	<p><u>REMOVE FAILED BCDU</u></p> <ol style="list-style-type: none"> 1. Translate to IEA worksite with spare BCDU.

BCDU REMOVE/REPLACE (Cont)

IV	EV1	EV2									
<p>IV 5. Record spare BCDU bolt data.</p> <table border="0"> <thead> <tr> <th>Bolt</th> <th>Turns</th> <th>Torque</th> </tr> </thead> <tbody> <tr> <td>H2</td> <td>_____</td> <td>_____</td> </tr> <tr> <td>H1</td> <td>_____</td> <td>_____</td> </tr> </tbody> </table>	Bolt	Turns	Torque	H2	_____	_____	H1	_____	_____	<p><u>INSTALL SPARE BCDU</u></p> <ol style="list-style-type: none"> 1. Receive spare BCDU from EV2. 2. Install spare BCDU on IEA. 3. ✓Status indicators on H1 and H2 – UNLOCK 4. PGT[A3 4.8 ft-lb, CW2 30 RPM, MTL 30.5]-6 ext-7/16: Drive H2, 16 to 17 turns. 5. ✓Status indicator – LOCK 6. PGT[A3 4.8 ft-lb, CW2 30 RPM, MTL 30.5]-6 ext-7/16: Drive H1, five to six turns. 7. ✓Status indicator – LOCK 8. Remove Square Scoop from H2 fitting. <ol style="list-style-type: none"> 9. Egress and remove APFR. 10. Give MCC-H GO to restore power to BCDU. <p><u>STOW FAILED BCDU ON S6</u></p> <ol style="list-style-type: none"> 1. Translate to S6 spare BCDUs. 	<p><u>INSTALL SPARE BCDU</u></p> <ol style="list-style-type: none"> 1. Transfer spare BCDU to EV1. <p><u>STOW FAILED BCDU ON S6</u></p> <ol style="list-style-type: none"> 1. Translate to S6 spare BCDUs. 2. Ingress APFR. 3. Receive failed BCDU from EV1 and install on S6. 4. ✓Status indicators on H1 and H2 – UNLOCK 5. PGT[B3 18.4 ft-lb, CW2 30 RPM, MTL 30.5]-6 ext-7/16: Drive H2, 16 to 17 turns. 6. ✓Status indicator – LOCK 7. PGT[B3 18.4 ft-lb, CW2 30 RPM, MTL 30.5]-6 ext-7/16: Drive H1, five to six turns. 8. ✓Status indicator – LOCK 9. Remove Square Scoop from H2 fitting. 10. Close thermal cover over BCDU. 11. Remove APFR.
Bolt	Turns	Torque									
H2	_____	_____									
H1	_____	_____									
<p>IV 6. Record failed BCDU bolt data.</p> <table border="0"> <thead> <tr> <th>Bolt</th> <th>Turns</th> <th>Torque</th> </tr> </thead> <tbody> <tr> <td>H2</td> <td>_____</td> <td>_____</td> </tr> <tr> <td>H1</td> <td>_____</td> <td>_____</td> </tr> </tbody> </table>	Bolt	Turns	Torque	H2	_____	_____	H1	_____	_____	<ol style="list-style-type: none"> 2. Transfer failed BCDU to EV2. 	
Bolt	Turns	Torque									
H2	_____	_____									
H1	_____	_____									

BCDU REMOVE/REPLACE – TASK DATA

Estimated Task Duration

Two EV Crew	~2:30
-------------	-------

Tools

EV1 (RMS)	EV2 (FF)
PGT	PGT
6 ext 7/16	6 ext 7/16
Square TM with 7/16 in Rec Socket	Square TM with 7/16 in Rec Socket
Square Scoop	Square Scoop
APFR	APFR
BRT	BRT

EVA Fasteners

Fastener Name	Label	Head Size (in)	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Fasteners	H1	7/16	1	4.8	31.7	190.3 (Release) 22.8 (Install)	5 to 6	30
Fasteners	H2	7/16	1	4.8	33.5	188.4 (Release) 27.8 (Install)	16 to 17	30

BCDU REMOVE/REPLACE – TASK DATA (Cont)

Foot Restraints

Task	Fitting	WIF	WIF Extender	APFR Setting
Access to S6 Spare BCDU		S6 – 19		10, OO, G, 12
		S6 – 19		10, OO, F, 12
Access to IEA BCDU 2B1 (1B1)	H1	P6/S6 – 26		12, QQ, K, 12
	H2	P6/S6 – 38		9, QQ, J, 12
Access to IEA BCDU 2B2 (1B2)	H1	P6/S6 – 18		10, QQ, G, 12
	H2	P6/S6 – 22		9, QQ, E, 12
Access to IEA BCDU 2B3 (1B3)	H1	P6/S6 – 22		5, QQ, L, 12
	H2	P6/S6 – 26		3, QQ, G, 12
Access to IEA BCDU 4B1 (3B1)	H1	P6/S6 – 25		12, QQ, B, 12
	H2	P6/S6 – 21		3, QQ, G, 12
Access to IEA BCDU 4B2 (3B2)	H1	P6/S6 – 17		2, QQ, E, 12
	H2	P6/S6 – 37		3, QQ, B, 12
Access to IEA BCDU 4B3 (3B3)	H1	P6/S6 – 21		7, QQ, A, 12
	H2	P6/S6 – 25		9, QQ, E, 12
Access to IEA BCDU 2A1 (1A1)	H1	P4/S4 - 09	9, A, 1	12, QQ, G, 12
	H2	P4/S4 - 09		3, QQ, G, 12
Access to IEA BCDU 2A2 (1A2)	H1	P4/S4 - 05		2, QQ, E, 12
	H2	P4/S4 - 25		3, QQ, B, 12
Access to IEA BCDU 2A3 (1A3)	H1	P4/S4 - 09		7, QQ, A, 12
	H2	P4/S4 - 13		9, QQ, E, 12
Access to IEA BCDU 4A1 (3A1)	H1	P4/S4 - 06		10, QQ, G, 12
	H2	P4/S4 - 26	11, A, 1	3, QQ, F, 12
Access to IEA BCDU 4A2 (3A2)	H1	P4/S4 - 10	3, A, 3	3, QQ, L, 12
	H2	P4/S4 - 10		9, QQ, E, 12
Access to IEA BCDU 4A3 (3A3)	H1	P4/S4 - 14	9, A, 3	9, QQ, A, 12
	H2	P4/S4 - 14		3, QQ, G, 12


ORU Mass: 234 lbs

BCDU REMOVE/REPLACE – TASK DATA (Cont)


Inhibits

BCDU	Inhibits	BCDU	Inhibits
2B1 (P6)	DCSU 2B RBI 2 Op, CI Inh BCDU 4B1 CP RBI Op, CI Inh	2A1 (P4)	DCSU 2A RBI 2 Op, CI Inh BCDU 4A1 CP RBI Op
2B2 (P6)	DCSU 2B RBI 3 Op, CI Inh BCDU 4B2 CP RBI Op, CI Inh	2A2 (P4)	DCSU 2A RBI 3 Op, CI Inh BCDU 4A2 CP RBI Op
2B3 (P6)	DCSU 2B RBI 4 Op, CI Inh BCDU 4B3 CP RBI Op, CI Inh	2A3 (P4)	DCSU 2A RBI 4 Op, CI Inh BCDU 4A3 CP RBI Op
4B1 (P6)	DCSU 4B RBI 2 Op, CI Inh BCDU 2B1 CP RBI Op, CI Inh	4A1 (P4)	DCSU 4A RBI 2 Op, CI Inh BCDU 2A1 CP RBI Op
4B2 (P6)	DCSU 4B RBI 3 Op, CI Inh BCDU 2B2 CP RBI Op, CI Inh	4A2 (P4)	DCSU 4A RBI 3 Op, CI Inh BCDU 2A2 CP RBI Op
4B3 (P6)	DCSU 4B RBI 4 Op, CI Inh BCDU 2B3 CP RBI Op, CI Inh	4A3 (P4)	DCSU 4A RBI 4 Op, CI Inh BCDU 2A3 CP RBI Op
1B1 (S6)	DCSU 1B RBI 2 Op, CI Inh BCDU 3B1 CP RBI Op, CI Inh	1A1 (S4)	DCSU 1A RBI 2 Op, CI Inh BCDU 3A1 CP RBI Op
1B2 (S6)	DCSU 1B RBI 3 Op, CI Inh BCDU 3B2 CP RBI Op, CI Inh	1A2 (S4)	DCSU 1A RBI 3 Op, CI Inh BCDU 3A2 CP RBI Op
1B3 (S6)	DCSU 1B RBI 4 Op, CI Inh BCDU 3B3 CP RBI Op, CI Inh	1A3 (S4)	DCSU 1A RBI 4 Op, CI Inh BCDU 3A3 CP RBI Op
3B1 (S6)	DCSU 3B RBI 2 Op, CI Inh BCDU 1B1 CP RBI Op, CI Inh	3A1 (S4)	DCSU 3A RBI 2 Op, CI Inh BCDU 1A1 CP RBI Op
3B2 (S6)	DCSU 3B RBI 3 Op, CI Inh BCDU 1B2 CP RBI Op, CI Inh	3A2 (S4)	DCSU 3A RBI 3 Op, CI Inh BCDU 1A2 CP RBI Op
3B3 (S6)	DCSU 3B RBI 4 Op, CI Inh BCDU 1B3 CP RBI Op, CI Inh	3A3 (S4)	DCSU 3A RBI 4 Op, CI Inh BCDU 1A3 CP RBI Op


BCDU REMOVE/REPLACE – TASK DATA (Cont)



BCDU REMOVE/REPLACE – TASK DATA (Cont)



H2 Primary Fastener.



H1 Secondary Fastener.

GENERIC EVA INHIBIT PAD

Orbiter (1)

ALL EVAs	
TCS L12	1. √TCS POWER – OFF
KU-Band Antenna MCC-H	
	1. √KU-BAND Mask – active 2. √KU-BAND EVA Protect Box – active
RCS	
IV O14,15,16	If EV crew < 27 feet from FRCS 1. √DAP: VERN, FREE, LO Z (flt specific check with GNC) 2. √RJDF F1, F2, F3, F4 MANF DRIVER (four) – OFF LOGIC (four) – OFF
MCC-H IV	3. √Above RCS config 4. √RCS F – ITEM 1 EXEC (*) √JET DES F1U – ITEM 17 (*) F3U – ITEM 19 (*) F2U – ITEM 21 (*)

Ground

ALL EVAs	
Ground Radar MCC-H	1. √TOPO console, ground radar restrictions in place for EVA

LOCATION DEPENDENT INHIBITS

OBSS - LDRI

TO INHIBIT LASER FIRING BUT LEAVE HEATER POWER ON:

NOTE

This procedure works best when performed during orbital night, and OBSS must be positioned such that its diffuser window is visible in the Camera B view.

- | | |
|----------|--|
| R12(VPU) | 1. √Green Jumper – LDRI/ITVC |
| A7U | 2. VIDEO OUT MON2 pb – push
IN B pb – push
OUT MON1 pb – push
IN PL2(VPU) pb – push |
| | 3. Center Cam B (ITVC) in the view of LDRI/ITVC |
| | 4. VIDEO OUT MON2 pb – push |
| | 5. Center LDRI/ITVC diffuser in the view of Cam B (ITVC) |
| | 6. CAMR CMD ZOOM – IN (FULL) |
| | 7. VIDEO OUT MUX 1 L pb – push
IN MIDDECK pb – push |

NOTE

The following step will power off the LDRI laser. Observe the LDRI diffuser in the Camera B view and verify the laser turns off. Report observation to **MCC-H**.

- | | |
|-----------|--|
| | 8. LDRI MODE 1 pb – push |
| | 9. VIDEO IN as desired (not MIDDECK) |
| | <u>POINT PTU/LDRI AWAY FROM EV CREW</u> |
| A7U | 10. VIDEO OUT MON1 pb – push
IN PL2(VPU) pb – push |
| | 11. CAMR CMD PAN/TILT – HI RATE
PAN – L (to hard stop)
TILT – UP (to hard stop)
PAN/TILT – RESET
PAN/TILT – HI RATE (LO within 10°)
PAN: TBD
TILT: TBD |
| R12(OBSS) | 12. ITVC ENA – OFF |

GENERIC EVA INHIBIT PAD (Cont)

Orbiter (2)

LOCATION DEPENDENT INHIBITS (Cont)

OBSS - LCS

TO INHIBIT LASER FIRING BUT LEAVE HEATER POWER ON:

- IV 1. Perform LCC DEACTIVATION step 1 (FDF P/TV CUE CARD, LCS).

To shut down and remove all power to LCS (and ROEU if flown)

NOTE

These steps remove all power from LCS sensor and start a 105-minute thermal clock.

- IV 2. Perform LCH DEACTIVATION (FDF P/TV CUE CARD, LCS).
 R1 3. √PRI PL MNC – OFF (tb-OFF)
 A6U 4. √PL RETEN PL SEL – 1

EFGF Connector

NOTE

These steps remove all power from both OBSS sensors and start a 90-minute thermal clock.

- IV 1. √DEACTIVATION complete (FDF P/TV CUE CARD, LDR/I/TVC)
 2. √LCC DEACTIVATION complete (FDF P/TV CUE CARD, LCS)
 3. √LCH DEACTIVATION complete (FDF P/TV CUE CARD, LCS)

S-Band Antennas

NOTE

Possible loss of comm when forced LL FWD antenna.

- IV If EV crew < 2 feet from S-Band antenna
 A1R 1. S-BAND FM ANT – XMIT LOWER/RCVR UPPER
 2. √**MCC**, lower antenna selected
 If no comm, or **On MCC GO**
 C3 3. S-BAND PM ANT – LL FWD
 When EVA crewmember at least 2 feet away from all S-Band upper antennas
 C3 4. S-BAND PM ANT – GPC

USOS (1)

ALL EVAs

PCU

NOTE

PCUs may require up to a 1-hour warmup period before they are operational.

- MCC-H** 1. √PCUs (two) operational in discharge mode and one of the following:
 a. CCS PCU EVA hazard control FDIR enabled.
 b. No more than two arrays unshunted and oriented <105° from velocity vector.
 If one or both PCUs failed
 2. No more than two arrays unshunted and oriented <105° from velocity vector.

LOCATION DEPENDENT INHIBITS

Lab Window

- IV If EV crew less than 10 feet from window or in window FOV, close window shutter

KU-Band (SGANT Antenna)_

- MCC-H** If EV crew < 3.3 feet from KU-BAND antenna
 1. Park KU-BAND
 1.1 Pointing Mode – Inhibit
 1.2 PLC – Reset
 1.3 Autotrack Continuous Retry – Inhibit

S-Band (SASA) Antennas

- MCC-H** If EV crew < 3.6 feet from S1 SASA [P1 SASA]
 1. P1 SASA (S1 SASA) – Active
 2. S1 SASA [P1 SASA] – Powered down

Mobile Transporter

- MCC-H** If EV crew <1.5 meters from MT
 1. √MT latched

GENERIC EVA INHIBIT PAD (Cont)

USOS (2)

LOCATION DEPENDENT INHIBITS

SARJ
MCC-H If EV crew working within 2 feet or outboard of SARJ
 1. √DLA (1) – LOCKED
 2. All motor setpoints set to zero.
 3. All motors deselected.

TRRJ
MCC-H If EV crew working within 2 feet of P1 TRRJ rotation envelope
 1. √DLA (1) – LOCKED
MCC-H If EV crew working within 2 feet of S1 TRRJ rotation envelope
 1. √DLA (1) – LOCKED

FPMU
MCC-H If EV crew working within 5 feet of Floating Potential Measurement Unit
 1. FPMU power – Off

SSPTS
MCC-H If EV crew working within 2 ft of SSPTS cables
 1. RPCM LA1A4A D RPC 3 – Open, Close Cmd Inhibit
 2. RPCM LA2A3B D RPC 1 – Open, Close Cmd Inhibit
 3. RPCM Z14B A RPC 2 – Open, Close Cmd Inhibit
 4. RPCM Z13B A RPC 2 – Open, Close Cmd Inhibit

COL (1)

ALL EVAs

EuTEF
COL-CC 1. √PLEGpay Power Status (ETF_PLEGPAY_Pwr_Stat) – OFF

LOCATION DEPENDENT INHIBITS

EuTEF
COL-CC If EV crew expected to contact EuTEF verify FEEDER 1 Power – OFF 40 minutes prior to contact

JEM (1)

LOCATION DEPENDENT INHIBITS

JPM Windows
 IV If EV crew translating on JPM port end cone, window shutters.

JEMRMS
SSIPC If EV crew working within vicinity of JEMRMS
 1. RIP MA Brake – ON
 2. MDP Main Mode – Stby Mode
 or
 1. JEMRMS Rack – OFF

JPM PROX Antenna
SSIPC If EV crew working within 0.3 ft. JPM PROX Antenna
 1. TRX Power – OFF
 2. TX Power – OFF
 or
 1. JPM PROX Antennas – OFF

GENERIC EVA INHIBIT PAD (Cont)

RSOS (1)

ALL EVAs

SM Antennas

- IV
1. GTS – Deactivate
 2. ARISS (Ham Radio) – Deactivate or VHF (144-146 MHz) TX only

EVAS ON PMA 1 OR RSOS (LOCATION DEPENDENT)

FGB Thrusters

- MCC-M**
1. √FGB MCS unpowered
 2. √All FGB Attitude Control Thruster Valves (eighty) – closed
 3. √FGB Attitude Control Manifold Valves – closed
КШК1, КШК2, КШК4, КШК5, КШК9, OKO3, OKГ3, OKO6, OKГ6,
OKO7, OKГ 7, OKO8, OKГ8

Soyuz Thrusters

- MCC-M**
1. √Soyuz manifolds (four) – closed
ЭКО1, ЭКО2, ЭКГ1, ЭКГ2
 2. √Soyuz MCS unpowered
 3. √Soyuz Attitude Control Thruster Valves (fifty-two) – closed
 4. √Soyuz Main Engine Valves (K1, K2, K3, K4, K5, K6) – closed

FGB Antennas

- MCC-M**
1. √FGB KURS P [КУРС P] – Deactivated

Soyuz Antennas

- MCC-M**
1. √Soyuz KURS A [КУРС A] – Deactivated

GENERIC EVA INHIBIT PAD (Cont)

RSOS (2)

ADDITIONAL ANTENNA INHIBITS FOR EVAS ON RSOS (LOCATION DEPENDENT)

FGB Antennas

MCC-M	1. √TORU [ТОРУ]	– Deactivated
	2. √TV System [ТВС]	– Deactivated
	3. √KURS A [КУРС А]	– Deactivated
	4. Radiotelemetry [БР-9ЦУ-8]	– Deactivate
	5. √TV System [КЛ-108А]	– Deactivated
	6. √CNPMS [СИТНП]	– Deactivated
	7. √КОМРАУС [КИС]	– Deactivated
	8. √Sirius (VHF Ham Radio)	– Deactivated

IV

SM Antennas

MCC-M	1. VHF-1, VHF-2 [СТТС]	– Deactivate
	2. BITS [БИТС2-12]	– Deactivate
	3. √TV System [ТВС]	– Deactivated
	4. REGUL [РЕГУЛ]	– Deactivate
	5. √LIRA [ОА]	– Deactivated
	6. √Orbit Radio Tracking System [PKO]	– Deactivated
	7. √Kurs P [КУРС P]	– Deactivated
	8. ARISS VHF (Ham Radio)	– Deactivate

IV

Soyuz Antennas

MCC-M	1. √Teleoperator	– Deactivated
	2. √Telemetry	– Deactivated
	3. √TV	– Deactivated
	4. √Tracking	– Deactivated
	5. √Command (OMNI)	– Deactivated

Progress Antennas

MCC-M	1. √Teleoperator	– Deactivated
	2. √Telemetry	– Deactivated
	3. √TV	– Deactivated
	4. √Tracking	– Deactivated
	5. √Command (OMNI)	– Deactivated
	6. √KURS A [КУРС А]	– Deactivated

ADDITIONAL THRUSTER INHIBITS FOR EVAS ON RSOS (LOCATION DEPENDENT)

SM Thrusters

MCC-M	1. √SM MCS – INDICATOR MODE or CMGTA with Thrusters Disabled
	2. √SM Manifold valves (four) closed ККГ1, ККГ2, ККО1, ККО2
	3. √SM Attitude Control Thruster Valves (sixty-four) – closed
	4. √SM Main Engine Thruster Valves (four) – closed
	5. √SM Reboost manifold valves (four) – closed КМГ1, КМГ2, КМО1, КМО2

Progress Thrusters

MCC-M	1. √Progress Manifold Valves (four) – closed ЭКО1, ЭКО2, ЭКГ1, ЭКГ2
	2. √Progress Attitude Control Thruster Valves (fifty-six) – closed
	3. √Progress Main Engine Valves (K1, K2, K3, K4, K5, K6) – closed

GENERIC NOTES, CAUTIONS, & WARNINGS

NOTES

1. Bolt install: Report torque and turns
2. Bolt release: Report torque and turns if different from published range
3. EVA connectors: After disconnection and prior to connection; verify pin and EMI band integrity; verify connector free of FOD
4. Inspect QDs for damage prior to mating
5. Toolbox doors must be closed with one latch per door when EV crew not in immediate vicinity
6. Avoid contact with OBSS striker bars (Vitrolube coating)

CAUTION

ISS Constraints

- A. Avoid inadvertent contact with
 1. Grapple fixture shafts (drylube)
 2. PIP pins
 3. EVA Crane [PMA1]
 4. TCS Reflectors [PMA2,PMA3]
 5. APAS hardware [PMA2,PMA3]
 6. CETA Lights (Z-93 paint) [LAB,S1,Node 1]
 7. Deployed MISSEs [Columbus EPF]
 8. Passive UMAs
 9. MBS/SSRMS/SPDM/JEMRMS taped radiative surfaces: VDU, ACU, JEU, LEU, MCU, CRPCMs, and Cameras
 10. Deployed TUS cable [Nadir CETA rail]
 11. S0 aft face Radiator
 12. GPS Antennas (S13 paint) [S0,JLP]
 13. UHF Antennas [LAB,P1]
 14. ETCS Radiator flexhoses and panels [S1,P1]
 15. EETCS/PV Radiator flexhoses, bellows and panels [P6,P4,S4,S6]
 16. SASA RF Group [S1,P1]
 17. Heat pipe radiators [Z1]
 18. PCU cathode and HCA ports [Z1]
 19. Ku-Band Antenna (SGANT) dish [Z1]
 20. CMG cover/shells [Z1]
 21. SPDM SJEU, EP, OTCM, LEU, and LEE VDU Radiator surfaces
 22. Open CBM petal covers, LAB window shutter, and JPM window shutter
 23. FPMU [S1]
 24. OTSD
 25. COL HAM radio antennas [COL-Nadir]
 26. JTVE Cameras [JEM]
 27. JEM A/L Target and Pins
 28. S0/Node 2 Fluid Tray Hardlines at Node 2 end are limited to 25 lb

CAUTION

ISS Constraints (Cont)

- B. Electrical cables
 1. Avoid bend radii < 10 times cable diameter
- C. Fiber optic cables
 1. Avoid bend radii < 10 times cable diameter
 2. Avoid pulling on cable during mate/demate
- D. Fluid line flex hoses and QDs
 1. Avoid bend radii < 5 in for hoses with diameter < 1 in on LAB, S0, S1, P1, and 10 in for hoses with diameter < 1 in on all other elements
 2. Avoid bend radii < 14 in for hoses with a diameter \geq 1 in
 3. Additional care should be taken to not exceed bend radii when applying loads at the flexible hose to rigid tube stub interfaces
 4. Ensure fluid QD booties are fully closed prior to leaving worksite; wire tie if reqd
- E. For structural reasons
 1. Avoid vigorous body motions, quick grabs and kickoffs against tether restraints
 2. Avoid performing shaking motions (sinusoidal functions) more than four cycles
 3. Avoid kicking S1/P1 radiator beam. If any of these occur, wait 2 to 5 min to allow structural response to dissipate

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

CAUTION

ISS Constraints (Cont)

F. Other

1. ITT Cannon connector: On demated connectors, do not rotate collar or manipulate cable/connector using collar or connector tool
2. WIS Antennas: Do not use as handholds [Node 1,Lab,P6,Z1]
3. Lubricant from Ku-Band SGANT gimbals [Z1], CMGs [Z1], and RTAS Ground Strap fasteners [P6,P4,S4,S6] can contaminate EMU
4. MLI handholds are not rated for crewmember translation loads
5. CBM petal covers may not be used as handholds unless both launch restraint pins are engaged
6. Prevent inadvertent contact of the tether shuttle with ETRS when the P3 Tether Shuttle Stop is raised away from the rail

CAUTION

Shuttle Constraints

G. Avoid inadvertent contact with

1. OBSS and SRMS Composite Sections Joint Torque Arms, Grapple Fixture Shafts, and Cable Harnesses
2. LCS (silver Teflon) and LDRI (silver Teflon) and ITVC (gold foil) [OBSS]
3. WVS Antenna [ODS Truss & PLB Sill]
4. Payload Bay and Camera wire harnesses, cables, cable guides, and connectors

H. No touch

1. LDRI diffuser [OBSS]
2. OBSS saddle contacts (when OBSS unberthed) [OBSS]
3. Monkey fur [PLB]
4. Cameras: Metallic surfaces [PLB]
5. Ku-Band Antenna black dish and gold thermal blankets [PLB]

CAUTION

HTV/HTV EP Constraints

A. Avoid inadvertent contact with

1. EVA Cover [HTV] (does not meet EVA kick loads)
2. Wheel guide [HTV] (snag hazard)
3. HBCS (berthing camera) [HTV EP]
4. HCSM (solid lubricant) [HTV EP]
5. HCAM (solid lubricant) [HTV EP]
6. EP PIU (solid lubricant and Black/White Paint) [HTV EP]

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

WARNING

ISS Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture targets and target pins
 2. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off
 3. Stay inboard of SARJ when active
 4. Stay 2 ft from S1/P1 radiator beam rotational envelope when beam is free to rotate
 5. Stay 5 ft from moving MT on face 1
 6. SOLAR and EuTEF [COL EPF]
- B. Handrails
1. Handrails previously used for MISSE attachment may not be used as a safety tether point [A/L endcone 564 & 566, A/L Tank 2 nad/fwd & port/fwd, P6 5389]
- C. Pinch
1. NZGL connector linkage. Use caution when mating/locking
 2. ITT Cannon Connector rotating housing
 3. EV side of IV Hatch during Hatch operation (also snag hazard) [A/L]
 4. LAB window shutter and CBM petal cover and JPM window shutter linkages during operation
 5. JEMRMS HRM capture latches
 6. JEM Cameras (JVTEs, EVE, WVE)
 7. JEM EFBM capture latches
- D. QDs
1. If QD is in FID when valve is opened (bail fwd), QD will leak and fluid line may whip
 2. Do not rotate if in mated/valve open config

WARNING

ISS Constraints (Cont)

- E. RF radiation exposure
1. Stay 3.6 ft from S-Band (SASA) high gain Antenna when powered [S1,P1]
 2. Stay 1.3 ft from S-Band (SASA) low gain Antenna when powered [S1,P1]
 3. Stay 1 ft from UHF Antenna when powered [LAB,P1]
 4. Stay 0.3 ft from fwd/aft JPM PROX antenna
- F. Sharp Edges
1. Inner edges of WIF sockets
 2. APFR active WIF probes
 3. Mating surfaces of EVA connectors
Avoid side loads during connector mating
 4. Back side of MMOD shield fasteners
Spring loaded captive EVA fasteners (e.g., 6B-boxes, BMRRM, RTAS, SARJ Covers); the end of the spring may protrude
 5. PMA umbilical launch restraints-exposed bolt threads
 6. Adjustable Fuse Tether (Fish Stringer) buckles stowed in Node Bag
 7. Nickel coated braided copper Ground Straps may contain frayed wires [P6,P4,S4,S6]
 8. SPDM OTCM gripper jaws

WARNING

ISS Constraints (Cont)

- F. Sharp Edges (Cont)
9. Solar Array Blanket Box [P6,S6]
 10. Keep hands away from SSRMS LEE/POA/SPDM LEE/JEMRMS EE opening, snares, and PDGF curvic coupling (teeth)
 11. Fastener threads on back of Z1 U-jumper male FQD panel, if nutplate cap missing
 12. Outboard MT rail attachment lug near P6 handrail 5333 and gap spanner
 13. P2 connector on EWIS box TAA-06 [Zenith/Forward Corner 1 of P5 – SARJ at 0 deg]
 14. Port/Aft portion of A/L circular HR [HR 0506]
 15. Interior of JEMRMS HRMs
 16. JEM A/L hatch corners
- G. Thermal
1. EVA connectors with booties may become hot if left uncovered. Handling may need to be limited
 2. PMA handrails may be hot. Handling may need to be limited
 3. Turn off glove heaters when comfortable temp reached to prevent bladder damage. Do not pull fingers out of gloves when heaters are on
 4. Uncovered trunnion pins may be hot
 5. SSRMS/MBS/SPDM/JEMRMS/JTVE operating cameras and lights may radiate large amounts of heat

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

WARNING

ISS Constraints (Cont)

G. Thermal (Cont)

6. Stay ≥ 1 ft away from PMAs and MMOD shields > 270 degF if EMU sun visor up; limit time to 15 min or less if > 300 degF
7. Stay at least 0.5 ft away from PMA and MMOD shields > 325 degF
8. Do not touch EMU protective visor if temp has been < -134 degF for > 15 min
9. No EMU TMG contact with PMAs and MMOD shields > 320 degF
10. No EMU boot contact with foot restraint when temp < -120 degF or > 200 degF
11. Columbus end cones may violate touch temperature constraints when $-75 \leq \beta \leq -60$ or $60 \leq \beta \leq 75$ V
12. PDGF surfaces may not meet touch temperature requirements for unlimited contact when $\beta \leq -70$ or $\beta \geq 70$
13. JPM port end cones and JLP port nadir may violate touch temperature constraints when $\beta > 60$ deg

H. Electrical Shock

1. Stay ≥ 2 ft from ungrounded floating connectors if not unpowered
 - SSPTS connectors include NOD1 Stbd/Fwd HR 0130, LAB Stbd/Fwd HR 0273, PMA2 Stbd and Port

WARNING

ISS Constraints (Cont)

H. Electrical Shock (Cont)

- MBS Cross-Connect jumpers (translate past these using UMA handrails) include S0 EVA Power Cables (inside S0 Bay 00 Face 4, Bay 01 Face 3) ESP2 jumper (inside S0 Bay 03 Face 4)
2. Do not touch SPDM CLPA 1 electrical connector prior to camera installation

WARNING

Shuttle Constraints

A. Arcing/Molten Debris

1. Stay ≥ 2 ft from exposed EFGF connector when OBSS berthed, powered, and EFGF not grappled [PLB]
2. Stay ≥ 2 ft from exposed Stbd Fwd MPM contacts [PLB]
3. Stay above PLB sill when within 1 ft of powered ROEU connector [PLB]

B. Pinch

1. PRLA operation [PLB]

C. RF radiation exposure

1. Stay 3.28 ft from S-Band Antenna when powered
2. Stay 1 ft from top and side of UHF PLB Antenna radome surface when in high powered mode [ODS truss]
3. Stay 0.33 ft from top and side of UHF PLB Antenna radome surface when in low powered mode [ODS truss]
4. Remain below the level of the PLB door mold line for first 20 in Aft of Fwd bulkhead when S-Band Antenna powered [PLB]
5. Remain on the inboard side of the Stbd slidewire (sill handrails if slidewire not installed) for first 20 ft Aft of Fwd bulkhead when Ku-Band Antenna powered [PLB]

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

WARNING

Shuttle Constraints (Cont)

D. Sharp Edges

1. PRLA grounding wipers [PLB]
2. LDRI baffles (also an entrapment hazard) [OBSS]
3. Keep hands away from SRMS EE opening and snares
4. TCS connector backshells have exposed threads [ODS]

E. Thermal

1. Illuminated PLB lights; do not touch
2. OBSS grapple fixture shafts/cams may be hot. Limit handling if required
3. Stay 27 ft from PRCS when powered
4. Stay 3 ft from VRCS when powered
5. Stay 3 ft from APU when operating

F. Contamination

1. Stay out of the immediate vicinity of leaking jet or APU

G. Lasers

1. Do not look at LDRI diffuser or LCS laser aperture window

WARNING

HTV/HTV EP Constraints

A. Avoid inadvertent contact with

1. HTV solar array panels (kick loads can shatter panel and generate sharp edges) [HTV]
2. HTV fwd RCS thrusters [HTV]

B. Pinch

1. HSM connector moving parts (pinch hazard and dry film lube) [HTV EP]
2. EP wheels (pinch point) [HTV EP]

C. RF radiation exposure

1. Stay 0.7 ft from IOS-N antenna [HTV]
2. Stay 0.7 ft from IOS-Z antenna [HTV]
3. Stay 0.3 ft from PLS-Z antenna [HTV]

FLIGHT SPECIFIC EVA REFERENCE

PAYLOAD BAY CONFIGURATION..... FS 18-3

S6

- S6 OVERVIEW..... FS 18-4
- S6 LONG SPACER..... FS 18-5
- S6 IEA (NON-KEEL SIDE) AND NON-PVR SIDE FS 18-8
- S6 IEA (KEEL SIDE) AND NON-PVR SIDE..... FS 18-9
- S6 IEA (KEEL SIDE) AND PVR SIDE..... FS 18-10
- S6 STARBOARD, NON-KEEL UP FS 18-11
- S6 STARBOARD, KEEL UP FS 18-12
- GAP CHECK TOOL FS 18-13
- S5 CAPTURE LATCH ASSEMBLY (CLA) FS 18-14
- S6 SSU SHROUD MLI FOLDING SEQUENCE..... FS 18-15

SAW

- BGA PRIMARY POWER CABLE CLAMPS FS 18-16
- RELEASE BETA GIMBAL LAUNCH RESTRAINTS FS 18-17
- FOUR BAR IN LOCKED POSITION FS 18-18
- SABB UNSTOW..... FS 18-19
- 4-BAR STOWED AND DEPLOYED CONFIGURATIONS FS 18-22
- MAST CANISTER MDA FS 18-23

CETA CART

- CETA CART – TOP VIEW FS 18-24
- CETA CART – SWING ARMS AND WIF MARKINGS FS 18-25
- CETA CART – COUPLERS FS 18-26
- CETA CART – WHEEL BOGIES FS 18-27

SPDM/SSRMS

- SPDM ASSY FS 18-28
- SPDM CAMERA LIGHT ASSY (CLA)..... FS 18-29
- SPDM CAMERA LIGHT PAN TILT ASSY (CLPA)..... FS 18-31
- SPDM ORU TOOL CHANGEOUT MECHANISM (OTCM) FS 18-33
- SPDM ELECTRONICS PLATFORM (EP) #1..... FS 18-35
- SPDM ELECTRONICS PLATFORM 1 (EP1) COVER..... FS 18-37
- LEE SNARE REPAIR..... FS 18-38

UCCAS/PAS

- UCCAS/PAS DEPLOY FS 18-40

JLP

- JLP GPS ANTENNA WITH COVER FS 18-43
- JLP GPS ANTENNA OVERVIEW FS 18-44
- JLP GPS ANTENNA CABLE/CONNECTOR LOCATION AND ID..... FS 18-46

WETA

- WETA ASSY AND S3 CP1 INSTALL BRACKET..... FS 18-47
- CP1 WETA INSTALL FS 18-48
- ETVCG DUMMY BOX..... FS 18-49


MISC

- S0 1A_D RPCM FS 18-50
- CONNECTOR GROUNDING SLEEVES FS 18-51
- ORU CONTINGENCY TIE-DOWN DEFINITIONS..... FS 18-52


FLIGHT SPECIFIC
EVA REFERENCE

This Page Intentionally Blank


PAYLOAD BAY CONFIGURATION




S6 OVERVIEW



S6 LONG SPACER



S6 LONG SPACER (Cont)





S6 LONG SPACER (STBD, LOWER VIEW)

Keel side

FS 18-6



EVA/119/FIN A

S6 LONG SPACER (Cont)




S6 LONG SPACER (PORT, LOWER VIEW)

S6 IEA (NON-KEEL SIDE) AND NON-PVR SIDE





S6 IEA (STBD, UPPER VIEW)

S6 IEA (KEEL SIDE) AND NON-PVR SIDE



S6 IEA (STBD, LOWER VIEW)


S6 IEA (KEEL SIDE) AND PVR SIDE



S6 IEA (STBD, LOWER VIEW)


NOTE: PVR removed for clarity

S6 STARBOARD, NON-KEEL UP






S6 IEA (STBD, UPPER VIEW)

S6 STARBOARD, KEEL UP



S6 IEA (STBD, LOWER VIEW)


GAP CHECK TOOL



LAUNCH POSITION
(RTAS corner #1)




TOOL REMOVED



TOOL INSTALLED ON
RTAS CONTINGENCY SPACER SLEEVE

S5 CAPTURE LATCH ASSEMBLY (CLA)



S6 SSU SHROUD MLI FOLDING SEQUENCE



1. Remove shroud



2. Fold in sewn short side



3. Fold in long sides



3. Fold in long sides




4. Fold shroud in half




5. Stow short straps inside bundle
6. Secure Velcro

BGA PRIMARY POWER CABLE CLAMPS



RELEASE BGA POWER CABLE FROM CLAMPS
PRIOR TO FOUR BAR DEPLOYMENT

FOUR BAR
LOWER SAA
(R075800)




VIEW T


BGA POWER
CABLE CLAMPS
(R078501)

FOUR BAR
LOWER SAA
(R075800)


RELEASE BETA GIMBAL LAUNCH RESTRAINTS



REMOVE PIP PIN (R03095-112)
 PRIOR TO BREAKING TORQUE
 REPLACE PIP PIN (2X)
 AFTER COMPLETING OPERATION




LAUNCH




DEPLOYED

View G

FOUR BAR IN LOCKED POSITION




LAUNCH



DEPLOYED

View T


SABB UNSTOW



DISENGAGE PIP PINS FROM PIVOT LID
LMMS (5851426-001)

SABB shown in stowed configuration


SABB UNSTOW (Cont)




SABB shown in deployed configuration

SABB UNSTOW (Cont)

TIP FITTING LMMS (5843517-003). TURN COUNTERCLOCKWISE TO BREAK GROUND SET TORQUE Ⓢ F6. FASTENERS WILL POP UP WHEN DISENGAGED.



View W




View AF

TIP FITTING INSTALLED
3 PLACES EACH MAST CANISTER


TIP FITTING DEPLOYED
3 PLACES EACH MAST CANISTER

VERIFY LOCKING SLEEVE LMMS (581331-001) IS IN LOCKED POSITION SHOWN. TYP UPPER AND LOWER BLANKET BOXES



SOLAR ARRAY LOCKING ARMS


4-BAR STOWED AND DEPLOYED CONFIGURATIONS




**Stowed
(Launch Configuration)**

**Deployed
(On-Orbit Configuration)**


MAST CANISTER MDA




CETA CART – TOP VIEW




CETA CART – SWING ARMS AND WIF MARKINGS



CETA CART – COUPLERS




Wire ties required for launch only. Removed for coupler R+R




BOTTOM VIEW

Compliance in indicated direction to allow for misalignment. Centering spring nominally constrains motion




TOP VIEW










PASSIVE COUPLER

Contingency bolt removed if latch failed closed




SIDE VIEW


CETA CART – WHEEL BOGIES




SPDM ASSY




SPDM CAMERA LIGHT ASSY (CLA)




SPDM CAMERA LIGHT ASSY (CLA) (Cont)




SPDM CAMERA LIGHT PAN TILT ASSY (CLPA)




SPDM CAMERA LIGHT PAN TILT ASSY (CLPA) (Cont)




SPDM ORU TOOL CHANGEOUT MECHANISM (OTCM)




ORU TOOL CHANGEOUT MECHANISM (OTCM) (Cont)



SPDM ELECTRONICS PLATFORM (EP) #1



SPDM ELECTRONICS PLATFORM (EP) #1 (Cont)




EP #1 installed on Upper Body Structure


NOTE: Temporary radiator surface protection will be removed before launch

SPDM ELECTRONICS PLATFORM 1 (EP1) COVER


Aluminum Ground Tabs and Flaps Locations



LEE SNARE REPAIR



LEE SNARE REPAIR (Cont)




FS 18-39

EVA/119/FIN A

UCCAS/PAS

UCCAS/PAS

UCCAS/PAS DEPLOY




DEPLOYED UCCAS

UCCAS/PAS DEPLOY (Cont)




HINGE LINE ADP ORIENTATION


UCCAS/PAS DEPLOY (Cont)




Active UMA EVA Override with Anti-Rotation Cap



Guide Vane and RTL lever




EBCS Target with Cover



Deployed and Stowed Clevis Brackets (looking from zenith)

JLP GPS ANTENNA WITH COVER





FS 18-43

EVA/119/FIN A



JLP

JLP

JLP GPS ANTENNA OVERVIEW




JLP GPS ANTENNA OVERVIEW (Cont)



S126E010957

JLP GPS ANTENNA CABLE/CONNECTOR LOCATION AND ID



Cable ID

- ① "PROX GPS Ant Cable-A-01"
- ② "PROX GPS Ant Cable-A-02"
- ③ "PROX GPS Ant Cable-B-01"
- ④ "PROX GPS Ant Cable-B-02"

Connector ID

JEM Power Line	GPS Ant-A	GPS Ant-B
A-string	Cable ① (JLP side) P7301⇔J7301 (Ant side) P7351⇔J1	Cable ③ (JLP side) P7401⇔J7401 (Ant side) P7451⇔J1
B-string	Cable ② (JLP side) P7302⇔J7302 (Ant side) P7352⇔J2	Cable ④ (JLP side) P7402⇔J7402 (Ant side) P7452⇔J2

(P:Plug, J:Jack)

WETA ASSY AND S3 CP1 INSTALL BRACKET

Remove before
EVA




FS 18-47

EVA/119/FIN A

WETA


WETA

CP1 WETA INSTALL




WETA (Connector End)
***NOTE:** Connector
Cover Installed

Remove before EVA



WETA (Blind-Mate Connector)

ETVCG DUMMY BOX




FS 18-49



EVA/119/FIN A

MISC

S0 1A_D RPCM



CONNECTOR GROUNDING SLEEVES




FS 18-51


EVA/119/FIN A

ORU CONTINGENCY TIE-DOWN DEFINITIONS


Adjustable Tether (16-26")




Adjustable Tether End To End Configuration (32-52")




Long Duration Tie Down Tether (24-84")



Long Duration Tie Down Tether End To End Configuration (48-168")





EVA CHECKLIST

STS
119