

EVA Checklist

STS-135 Flight Supplement

**Mission Operations Directorate
EVA, Robotics, and Crew Systems
Operations Division**

**Final
June 1, 2011**

NOTE

This supplement is to be integrated into the generic edition to provide a complete document for the specific flight. Some pages in the generic edition may be replaced with supplemental pages identified as 'TEMP'. These generic pages, if any, must be retained for use on future flights.

National Aeronautics and
Space Administration

Lyndon B. Johnson Space Center
Houston, Texas



EVA CHECKLIST STS-135 FLT SUPPL

FINAL (June 1, 2011)

PCN-1 (June 24, 2011) Sheet 1 of 1

List of Implemented Change Requests (482s):

EVA FS-00424
EVA FS-00425
EVA FS-00426
EVA FS-00427
EVA FS-00428
EVA FS-00429


Incorporate the following:


1. Replace FS v thru FS xiv
2. Replace section 2 (18 pages)
3. Replace TEMP FS 3-1 and TEMP FS 3-2
After 3-12, add FS 3-13 thru FS 3-22
4. Replace section 7 (68 pages)
5. Replace FS 8-9 and FS 8-10, FS 8-15 thru FS 8-18
6. Replace TEMP FS 10-1 and TEMP FS 10-2, FS CC 10-15 and FS CC 10-16
7. Replace FS 16-3 thru FS 16-8, FS 16-17 and FS 16-18
After FS 16-18, add FS 16-18a and FS 16-18b
Replace FS 16-19 and FS 16-20, FS 16-51 and FS 16-52, FS 16-65 and FS 16-66

Prepared by:



Book Manager

Approved by:


Lead, EVA Systems Group


Lead, EVA Task Group for Zeb Scaville

Accepted by:


Chief, EVA and Crew Systems
Operations Branch


Encl: 134 pages

File this PCN immediately behind the front cover as a permanent record




MISSION OPERATIONS DIRECTORATE

**EVA CHECKLIST
STS-135 FLIGHT SUPPLEMENT**FINAL
June 1, 2011

PREPARED BY:

Lawrence D. Welsh
Book Manager

APPROVED BY:

Tomas L. Gonzalez-Torres
Lead, EVA Systems GroupZebulon L. Scoville
Lead, EVA Task GroupMunish P. Patel
Chief, EVA Operations Branch

This document is under the configuration control of the Crew Procedures Control Board (CPCB). All proposed changes must be submitted via Change Request Workflow (CRW) to DO3/FDF Manager.

Additional distribution of this book, for official use only, may be requested in writing to DO3/PMO Administrator. The request must include justification and requester's name, organization, position, and phone number. Contractor requests are made through the NASA or DOD organization supported. Deletions, reduction in quantity, or change of address may be submitted to DO3/FDF Management Office, 281-244-1184.

Incorporates the following:		
482#:	EVA FS-00394	EVA FS-00419
	EVA FS-00406A	EVA FS-00420
	EVA FS-00416	EVA FS-00421
	EVA FS-00417	EVA FS-00422
	EVA FS-00418	EVA FS-00423

AREAS OF TECHNICAL RESPONSIBILITY

Book Manager

DX32/L. Welsh

281-244-1058

EVA CHECKLIST
STS-135 FLIGHT SUPPLEMENT

LIST OF EFFECTIVE PAGES

FINAL 06/01/11
PCN-1 06/24/11

Sign Off	*	135/FIN	3-3	generic
FS ii	*	135/FIN	3-4	generic
iii	*	generic	3-5	generic
iv	*	generic	3-6	generic
FS v	*	135/FIN 1	3-7	generic
FS vi	*	135/FIN 1	3-8	generic
FS vii	*	135/FIN 1	3-8a	generic
FS viii	*	135/FIN 1	3-8b	generic
FS ix	*	135/FIN 1	3-9	generic
FS x	*	135/FIN	CC 3-10	generic
FS xi		135/FIN 1	CC 3-11	generic
FS xii		135/FIN 1	3-12	generic
FS xiii		135/FIN 1	FS 3-13	135/FIN 1
FS xiv		135/FIN	FS 3-14	135/FIN 1
FS xv		135/FIN	FS 3-15	135/FIN 1
FS xvi		135/FIN	FS 3-16	135/FIN 1
1-1		generic	FS 3-17	135/FIN 1
1-2		generic	FS 3-18	135/FIN 1
1-3		generic	FS 3-19	135/FIN 1
1-4		generic	FS 3-20	135/FIN 1
1-5		generic	FS 3-21	⊗ 135/FIN 1
1-6		generic	FS 3-22	⊗ 135/FIN 1
1-7		generic	4-1	generic
1-8		generic	4-2	generic
1-9		generic	4-3	generic
1-10		generic	4-4	generic
TEMP FS 2-1		135/FIN 1	4-5	generic
TEMP FS 2-2		ALL/FIN	4-6	generic
TEMP FS 2-3		135/FIN 1	4-7	generic
TEMP FS 2-4		135/FIN	4-8	generic
TEMP FS 2-5		135/FIN 1	4-9	generic
TEMP FS 2-6		ALL/FIN	4-10	generic
FS 2-7		135/FIN 1	4-11	generic
FS 2-8		135/FIN 1	4-12	generic
FS 2-9		135/FIN 1	5-1	generic
FS 2-10		135/FIN 1	5-2	generic
FS 2-11		135/FIN 1	5-3	generic
FS 2-12	⊗	135/FIN 1	5-4	generic
FS 2-13	⊗	135/FIN 1	A6-1	generic
FS 2-14		135/FIN 1	CC A6-2	generic
FS 2-15		135/FIN 1	6-3	generic
FS 2-16		135/FIN 1	CC 6-4	generic
FS 2-17	⊗	135/FIN 1	FS 7-1	135/FIN 1
FS 2-18	⊗	135/FIN 1	FS 7-2	135/FIN
TEMP FS 3-1		135/FIN 1	FS 7-3	135/FIN 1
TEMP FS 3-2		ALL/FIN 1	FS 7-4	⊗ 135/FIN 1

* – Omit from flight book

⊗ – Flight copies of this page contain color

FS 7-5	⊗	135/FIN 1	FS 7-59		135/FIN 1
FS 7-6		135/FIN 1	FS 7-60		135/FIN
FS 7-7		135/FIN 1	FS 7-61	⊗	135/FIN
FS 7-8		135/FIN 1	FS 7-62	⊗	135/FIN
FS 7-9		135/FIN 1	FS 7-63	⊗	135/FIN
FS 7-10	⊗	135/FIN 1	FS 7-64	⊗	135/FIN
FS 7-11	⊗	135/FIN 1	FS 7-65	⊗	135/FIN
FS 7-12	⊗	135/FIN	FS 7-66	⊗	135/FIN
FS 7-13	⊗	135/FIN 1	TEMP FS 8-1		135/FIN
FS 7-14	⊗	135/FIN	TEMP FS 8-2	⊗	135/FIN
FS 7-15	⊗	135/FIN 1	8-3		generic
FS 7-16	⊗	135/FIN	8-4		generic
FS 7-17	⊗	135/FIN 1	8-5		generic
FS 7-18	⊗	135/FIN	8-6		generic
FS 7-19		135/FIN 1	8-7		generic
FS 7-20		135/FIN 1	8-8		generic
FS 7-21	⊗	135/FIN 1	FS 8-9	⊗	135/FIN 1
FS 7-22		135/FIN 1	FS 8-10		135/FIN 1
FS 7-23		135/FIN 1	FS 8-11	⊗	135/FIN
FS 7-24	⊗	135/FIN 1	FS 8-12		135/FIN
FS 7-25		135/FIN 1	FS 8-13		135/FIN
FS 7-26		135/FIN 1	FS 8-14		135/FIN
FS 7-27		135/FIN 1	FS 8-15		135/FIN
FS 7-28	⊗	135/FIN 1	FS 8-16	⊗	135/FIN 1
FS 7-28a	⊗	135/FIN 1	FS 8-17	⊗	135/FIN 1
FS 7-28b	⊗	135/FIN 1	FS 8-18	⊗	135/FIN 1
FS 7-29	⊗	135/FIN 1	FS 8-19		135/FIN
FS 7-30		135/FIN 1	FS 8-20	⊗	135/FIN
FS 7-31		135/FIN 1	FS 8-21	⊗	135/FIN
FS 7-32	⊗	135/FIN 1	FS 8-22	⊗	135/FIN
FS 7-33	⊗	135/FIN 1	FS 8-23	⊗	135/FIN
FS 7-34	⊗	135/FIN 1	FS 8-24	⊗	135/FIN
FS 7-35	⊗	135/FIN 1	FS 8-25		135/FIN
FS 7-36	⊗	135/FIN 1	FS 8-26	⊗	135/FIN
FS 7-37	⊗	135/FIN 1	FS 8-27		135/FIN
FS 7-38	⊗	135/FIN 1	FS 8-28		135/FIN
FS 7-39	⊗	135/FIN 1	FS 8-29	⊗	135/FIN
FS 7-40	⊗	135/FIN 1	FS 8-30	⊗	135/FIN
FS 7-41	⊗	135/FIN 1	FS 8-31	⊗	135/FIN
FS 7-42	⊗	135/FIN 1	FS 8-32	⊗	135/FIN
FS 7-43		135/FIN 1	FS 8-33	⊗	135/FIN
FS 7-44	⊗	135/FIN 1	FS 8-34		135/FIN
FS 7-45		135/FIN 1	FS 8-35	⊗	135/FIN
FS 7-46		135/FIN 1	FS 8-36		135/FIN
FS 7-47	⊗	135/FIN 1	FS 8-37		135/FIN
FS 7-48	⊗	135/FIN 1	FS 8-38		135/FIN
FS 7-49	⊗	135/FIN 1	FS 8-39		135/FIN
FS 7-50	⊗	135/FIN 1	FS 8-40		135/FIN
FS 7-51	⊗	135/FIN 1	9-1		generic
FS 7-52		135/FIN 1	9-2		generic
FS 7-53		135/FIN 1	9-3		generic
FS 7-54		135/FIN 1	9-4		generic
FS 7-55	⊗	135/FIN	9-5		generic
FS 7-56		135/FIN	9-6		generic
FS 7-57	⊗	135/FIN	TEMP FS 10-1		135/FIN 1
FS 7-58	⊗	135/FIN	TEMP FS 10-2		ALL/FIN

⊗ – Flight copies of this page contain color

10-3	generic	FS 13-1	135/FIN
10-4	generic	FS 13-2	135/FIN
10-4a	generic	14-1	generic
10-4b	generic	14-2	generic
10-5	generic	14-3	generic
10-6	generic	14-4	generic
10-7	generic	14-5	generic
10-8	generic	14-6	generic
10-9	generic	14-7	generic
10-10	generic	14-8	generic
10-11	generic	14-9	generic
10-12	generic	14-10	generic
10-13	generic	14-11	generic
10-14	generic	14-12	generic
FS CC 10-15	135/FIN 1	14-13	generic
FS CC 10-16	135/FIN 1	14-14	generic
11-1	generic	14-15	generic
11-2	generic	14-16	generic
11-3	generic	14-17	generic
11-4	generic	14-18	generic
12-i	generic	14-19	generic
12-ii	generic	14-20	generic
TEMP FS 12-1	135/FIN	14-21	generic
TEMP FS 12-2	ALL/FIN	14-22	generic
12-3	generic	15-1	generic
12-4	generic	15-2	generic
12-5	generic	15-3	generic
12-6	generic	15-4	generic
12-7	generic	15-5	generic
12-8	generic	15-6	generic
12-9	generic	15-7	generic
12-10	generic	15-8	generic
12-11	generic	15-9	generic
12-12	generic	15-10	generic
12-13	generic	15-11	generic
12-14	generic	15-12	generic
12-15	generic	15-13	generic
12-16	generic	15-14	generic
12-17	generic	16-i	generic
12-18	generic	16-ii	generic
12-19	generic	TEMP FS 16-1	135/FIN
12-20	generic	TEMP FS 16-2	135/FIN
12-21	generic	FS 16-3	135/FIN 1
12-22	generic	FS 16-4	135/FIN 1
12-23	generic	FS 16-5	135/FIN 1
12-24	generic	FS 16-6	135/FIN 1
12-24a	generic	FS 16-7	135/FIN 1
12-24b	generic	FS 16-8	135/FIN
12-25	generic	FS 16-9	135/FIN
12-26	generic	FS 16-10	135/FIN
FS CC 12-27	⊗ 135/FIN	FS 16-11	⊗ 135/FIN
FS CC 12-28	⊗ 135/FIN	FS 16-12	135/FIN
FS 12-29	⊗ 135/FIN	FS 16-13	⊗ 135/FIN
FS 12-30	⊗ 135/FIN	FS 16-14	135/FIN
FS 12-31	135/FIN	FS 16-15	⊗ 135/FIN
FS 12-32	135/FIN	FS 16-16	135/FIN

⊗ – Flight copies of this page contain color

FS 16-17	135/FIN	FS 18-3.....	135/FIN
FS 16-18	135/FIN 1	FS 18-4.....	135/FIN
FS 16-18a.....	135/FIN 1	FS 18-5.....	135/FIN
FS 16-18b.....	135/FIN 1	FS 18-6.....	135/FIN
FS 16-19	135/FIN 1	FS 18-7.....	135/FIN
FS 16-20.....	⊗ 135/FIN	FS 18-8.....	135/FIN
FS 16-21.....	⊗ 135/FIN	FS 18-9.....	135/FIN
FS 16-22.....	⊗ 135/FIN	FS 18-10.....	135/FIN
FS 16-23.....	135/FIN	FS 18-11.....	135/FIN
FS 16-24.....	⊗ 135/FIN	FS 18-12.....	135/FIN
FS 16-25.....	⊗ 135/FIN	FS 18-13.....	135/FIN
FS 16-26.....	135/FIN	FS 18-14.....	135/FIN
FS 16-27.....	135/FIN	FS 18-15.....	135/FIN
FS 16-28.....	135/FIN	FS 18-16.....	135/FIN
FS 16-29.....	135/FIN	FS 18-17.....	⊗ 135/FIN
FS 16-30.....	135/FIN	FS 18-18.....	⊗ 135/FIN
FS 16-31.....	135/FIN	FS 18-19.....	⊗ 135/FIN
FS 16-32.....	135/FIN	FS 18-20.....	⊗ 135/FIN
FS 16-33.....	135/FIN	FS 18-21.....	⊗ 135/FIN
FS 16-34.....	135/FIN	FS 18-22.....	⊗ 135/FIN
FS 16-35.....	135/FIN	FS 18-23.....	135/FIN
FS 16-36.....	135/FIN	FS 18-24.....	⊗ 135/FIN
FS 16-37.....	135/FIN	FS 18-25.....	⊗ 135/FIN
FS 16-38.....	135/FIN	FS 18-26.....	⊗ 135/FIN
FS 16-39.....	135/FIN	FS 18-27.....	⊗ 135/FIN
FS 16-40.....	135/FIN	FS 18-28.....	⊗ 135/FIN
FS 16-41.....	135/FIN	FS 18-29.....	⊗ 135/FIN
FS 16-42.....	135/FIN	FS 18-30.....	⊗ 135/FIN
FS 16-43.....	135/FIN	FS 18-31.....	⊗ 135/FIN
FS 16-44.....	⊗ 135/FIN	FS 18-32.....	⊗ 135/FIN
FS 16-45.....	⊗ 135/FIN	FS 18-33.....	⊗ 135/FIN
FS 16-46.....	135/FIN	FS 18-34.....	⊗ 135/FIN
FS 16-47.....	⊗ 135/FIN	FS 18-35.....	⊗ 135/FIN
FS 16-48.....	⊗ 135/FIN	FS 18-36.....	⊗ 135/FIN
FS 16-49.....	135/FIN	FS 18-37.....	⊗ 135/FIN
FS 16-50.....	135/FIN	FS 18-38.....	⊗ 135/FIN
FS 16-51.....	135/FIN	FS 18-39.....	⊗ 135/FIN
FS 16-52.....	135/FIN 1	FS 18-40.....	⊗ 135/FIN
FS 16-53.....	135/FIN	FS 18-41.....	⊗ 135/FIN
FS 16-54.....	135/FIN	FS 18-42.....	⊗ 135/FIN
FS 16-55.....	135/FIN	FS 18-43.....	⊗ 135/FIN
FS 16-56.....	135/FIN	FS 18-44.....	⊗ 135/FIN
FS 16-57.....	135/FIN	FS 18-45.....	135/FIN
FS 16-58.....	135/FIN	FS 18-46.....	⊗ 135/FIN
FS 16-59.....	135/FIN	FS 18-47.....	⊗ 135/FIN
FS 16-60.....	135/FIN	FS 18-48.....	⊗ 135/FIN
FS 16-61.....	135/FIN	FS 18-49.....	⊗ 135/FIN
FS 16-62.....	135/FIN	FS 18-50.....	⊗ 135/FIN
FS 16-63.....	⊗ 135/FIN	FS 18-51.....	⊗ 135/FIN
FS 16-64.....	⊗ 135/FIN	FS 18-52.....	⊗ 135/FIN
FS 16-65.....	⊗ 135/FIN 1	FS 18-53.....	⊗ 135/FIN
FS 16-66.....	⊗ 135/FIN	FS 18-54.....	⊗ 135/FIN
17-1.....	* generic	FS 18-55.....	⊗ 135/FIN
17-2.....	* generic	FS 18-56.....	⊗ 135/FIN
FS 18-1	135/FIN	FS 18-57.....	⊗ 135/FIN
FS 18-2	135/FIN	FS 18-58.....	⊗ 135/FIN

⊗ – Flight copies of this page contain color

* – Omit from flight book

FS 18-59	⊗	135/FIN	FS 18-87		135/FIN
FS 18-60	⊗	135/FIN	FS 18-88	⊗	135/FIN
FS 18-61	⊗	135/FIN	FS 18-89		135/FIN
FS 18-62	⊗	135/FIN	FS 18-90		135/FIN
FS 18-63	⊗	135/FIN	FS 18-91		135/FIN
FS 18-64	⊗	135/FIN	FS 18-92		135/FIN
FS 18-65		135/FIN	FS 18-93	⊗	135/FIN
FS 18-66	⊗	135/FIN	FS 18-94	⊗	135/FIN
FS 18-67	⊗	135/FIN	19-i		generic
FS 18-68	⊗	135/FIN	19-ii		generic
FS 18-69	⊗	135/FIN	19-1		generic
FS 18-70	⊗	135/FIN	19-2		generic
FS 18-71	⊗	135/FIN	19-3		generic
FS 18-72	⊗	135/FIN	19-4		generic
FS 18-73	⊗	135/FIN	19-5		generic
FS 18-74	⊗	135/FIN	19-6		generic
FS 18-75	⊗	135/FIN	19-7		generic
FS 18-76	⊗	135/FIN	19-8		generic
FS 18-77		135/FIN	19-9		generic
FS 18-78	⊗	135/FIN	19-10		generic
FS 18-79	⊗	135/FIN	19-11		generic
FS 18-80	⊗	135/FIN	19-12		generic
FS 18-81	⊗	135/FIN	19-13		generic
FS 18-82	⊗	135/FIN	19-14		generic
FS 18-83	⊗	135/FIN	20-1	*	generic
FS 18-84	⊗	135/FIN	20-2	*	generic
FS 18-85	⊗	135/FIN			
FS 18-86	⊗	135/FIN			

EVA CUE CARDS

<u>Title</u>	<u>Ref. Page</u>	<u>Card No.</u>
SAFER CHECKOUT RESULTS (Front).....	CC 3-10	generic
SAFER STATUS TROUBLESHOOTING (Back)	CC 3-11	generic
DEPRESS/REPRESS (NOM A/L) (Front).....	CC A6-2	generic
FAILED LEAK CHECK (Back of DEPRESS/REPRESS)	CC 6-4	generic
STS-135 CONSUMABLES TRACKING CUE CARD		
(Front)	FS CC 10-15	EVA-4a/135/O/B
(Back).....	FS CC 10-16	EVA-4b/135/O/B
EMERGENCY UNDOCKING EVA TRANSFER (Front)...	FS CC 12-27	EVA-5a/135/O/A
EXPEDITED SUIT DOFFING CUE CARD (Back)	FS CC 12-28	EVA-5b/135/O/A

⊗ – Flight copies of this page contain color

* – Omit from flight book

This Page Intentionally Blank

CONTENTS

PAGE

10.2 PSI CABIN	1-1
MASK PREBREATHE INITIATE	1-2
PREP FOR 10.2 PSI CABIN	1-3
CABIN DEPRESS TO 10.2 PSI.....	1-4
10.2 PSIA DEPRESS CHART	1-5
10.2 PSI CABIN CONFIG.....	1-6
MASK PREBREATHE TERMINATE	1-6
10.2 PSI MAINTENANCE.....	1-7
CABIN REPRESS TO 14.7 PSI.....	1-8
14.7 PSI CABIN CONFIG.....	1-9
AIRLOCK CONFIG.....	TEMP FS 2-1
AIRLOCK PREP	TEMP FS 2-2
AIRLOCK PREP FOR DOCKING.....	TEMP FS 2-3
BOOSTER FAN DEACTIVATION/REMOVAL.....	TEMP FS 2-4
BOOSTER FAN INSTALLATION/ACTIVATION.....	TEMP FS 2-4
EMU REMOVAL	TEMP FS 2-4
EMU INSTALLATION.....	TEMP FS 2-4
EMU CHECKOUT PREP.....	TEMP FS 2-5
ISS EMU CHECKOUT PREP	TEMP FS 2-5
LTA RESTRAINT STRAP REMOVAL	TEMP FS 2-6
LTA RESTRAINT STRAP INSTALLATION	TEMP FS 2-6
EVA PREP FOR TRANSFER TO ISS.....	FS 2-7
POST DOCKING EVA TRANSFER AND RECONFIG.....	FS 2-9
POST-EVA EMU RESIZE	FS 2-10
POST EVA RECONFIG AND TRANSFER TO SHUTTLE	FS 2-14
EVA UNPACK AND STOW	FS 2-16
EMU PLSS TAB INSTALL.....	FS 2-17
CHECKOUTS.....	3-1
EMU CHECKOUT	TEMP FS 3-2
EMU POWERUP AND COMM CHECK.....	TEMP FS 3-2
PRIMARY REGULATOR/FAN/PUMP CHECK.....	3-4
SOP CHECK.....	3-5
BATTERY CHARGE CHECK INIT.....	3-6
BATTERY CHARGE CHECK TERM.....	3-6
EMU SWAP DURING CHECKOUT	3-7
POST EMU C/O RECONFIG.....	3-7
SAFER CHECKOUT	3-8
SELF TEST SEQUENCE	3-9
SAFER CHECKOUT RESULTS.....	CC 3-10
SAFER STATUS TROUBLESHOOTING	CC 3-11
REBA POWERED HARDWARE CHECKOUT	3-12
ISS EMU CHECKOUT.....	FS 3-13
EVA PREP	4-1
MIDDECK PREP	4-2
EVA PREP.....	4-3
PREP FOR DONNING.....	4-3
EMU DONNING.....	4-5
EMU CHECK	4-7
EMU PURGE.....	4-7
EMU PREBREATHE	4-8
SAFER DONNING.....	4-8
EVA COMM CONFIG.....	4-10
EVA COMM DECONFIG	4-10
APPROVED NON-EMU HARDWARE MATRIX.....	4-11
EMU STATUS	5-1
EMU STATUS	5-2

DEPRESS/REPRESS	A6-1
DEPRESS/REPRESS (NOM A/L)	CC A6-2
FAILED LEAK CHECK	6-3
FAILED LEAK CHECK (5 PSI)	CC 6-4
FAILED LEAK CHECK (14.7/10.2 PSI)	CC 6-4
 TIMELINES	 FS 7-1
EVA 1	
EVA 1 SUMMARY TIMELINE	FS 7-3
EVA 1 TOOL CONFIG	FS 7-4
EVA 1 BRIEFING CARD	FS 7-6
EVA 1 INHIBIT PAD	FS 7-7
EVA 1 NOTES/CAUTIONS/WARNINGS	FS 7-10
EVA 1 EGRESS/SETUP	FS 7-17
REMOVE PM FRAM FROM ESP-2	FS 7-20
TRANSFER PM FRAM TO PLB	FS 7-21
INSTALL PM FRAM ON LMC	FS 7-22
REMOVE RRM FRAM FROM LMC	FS 7-23
TRANSFER RRM FRAM TO EOTP	FS 7-24
INSTALL RRM FRAM ON EOTP	FS 7-25
MISSE 8 ORMATE III R/W INSTALL ON ELC-2	FS 7-26
SSRMS CLEANUP	FS 7-28
FGB PDGF TROUBLESHOOTING	FS 7-28a
PMA3 COVER INSTALL	FS 7-29
EVA 1 CLEANUP/INGRESS	FS 7-30
EVA 1 TASK DATA – PM TRANSFER	FS 7-31
EVA 1 TASK DATA – RRM TRANSFER	FS 7-33
EVA 1 TASK DATA – MISSE 8 ORMATE III	FS 7-38
EVA 1 TASK DATA – FGB PDGF TROUBLESHOOTING	FS 7-39
EVA 1 TASK DATA – PMA3 COVER INSTALL	FS 7-43
GET-AHEADS	
STS-135 GET-AHEADS	FS 7-45
FGB PDGF 1553 DATA CABLE INSTALL	FS 7-46
FGB PDGF 1553 DATA CABLE INSTALL – TASK DATA	FS 7-48
PORT CETA CART RECONFIG	FS 7-51
SSRMS BASE B ELBOW CLPA R&R	FS 7-53
SSRMS BASE B ELBOW CLPA R&R – TASK DATA	FS 7-55
S1 FHRC P-CLAMP RELEASE	FS 7-56
S1 FHRC P-CLAMP RELEASE – TASK DATA	FS 7-57
TOOL RECONFIGURATION	FS 7-59
GAP SPANNER INSTALL	FS 7-66
 TOOLS AND STOWAGE	 TEMP FS 8-1
STARBOARD LIGHTWEIGHT TOOL STOWAGE ASSEMBLY (TSA) ...	TEMP FS 8-2
PGT CHECKOUT	8-3
PGSC-PGT CONNECTION (A31P AND 760XD)	8-4
PROGRAM PGT SETTINGS	8-5
DOWNLOAD/ERASE EVENT LOG	8-5
PGT CONTINGENCIES	8-6
PGT STANDARD SETTINGS	8-7
SAFETY TETHERS – STS-135 (ULF7)	FS 8-9
APFR MANAGEMENT – STS-135 (ULF7)	FS 8-10
CETA CART WIF AND SWINGARM MANAGEMENT TABLE – STS-135/ULF7 ..	FS 8-11
TOOLBOX STOWAGE – STS-135 (ULF7)	FS 8-12
TOOLBOX PANEL AND SLOT LABELS	FS 8-13
Z1 TOOLBOX INTERNAL LAYOUT	FS 8-14
AIRLOCK TOOLBOX INTERNAL LAYOUT	FS 8-15

FLUID QD BAG LAYOUT	FS 8-16
CREW TETHER INSPECTIONS	FS 8-19
CLPA IVA UNPACKING	FS 8-26
CLPA CONFIGURE AND PACK FOR STOWAGE	FS 8-29
MISSE 8 ORMATE III R/W PREP FOR EVA	FS 8-39
MISSE 8 ORMATE III R/W POST EVA COVER STOWAGE	FS 8-40
POST EVA	9-1
POST EVA	9-2
SUIT DOFFING	9-2
SAFER DOFFING	9-2
EMU WATER RECHARGE	9-3
SAFER STOW	9-3
SUIT DRYING/SEAL WIPE	9-4
OXYGEN RECHARGE VERIFICATION	9-4
WATER FILL VERIFICATION	9-4
EMU POWERDOWN/OVERNIGHT STOW	9-5
EMU MAINT/RECHARGE	TEMP FS 10-1
WATER RECHARGE	TEMP FS 10-2
EMU POWERUP	TEMP FS 10-2
WATER FILL	TEMP FS 10-2
WATER FILL VERIFICATION	TEMP FS 10-2
EMU LiOH CHANGEOUT	10-4
MIDDECK EMU BATTERY RECHARGE (STAND-ALONE)	10-4a
MIDDECK EMU BATTERY RECHARGE/LiOH REPLACEMENT	10-5
INITIATE	10-5
TERMINATE	10-6
IN-SUIT EMU BATTERY RECHARGE/CHARGE VERIFICATION	10-7
INITIATE	10-7
TERMINATE	10-7
EMU POWERDOWN	10-7
HELMET LIGHT/PGT BATTERY RECHARGE	10-8
INITIATE	10-8
TERMINATE	10-9
REBA BATTERY INSTALLATION	10-9
EMU BATTERY REMOVAL/INSTALL	10-10
HELMET LIGHT BULB CHANGEOUT	10-11
REBA BATTERY RECHARGE	10-12
INITIATE	10-12
TERMINATE	10-13
STS-135 CONSUMABLES TRACKING CUE CARD	FS CC 10-15
POST EVA ENTRY PREP	11-1
POST EVA ENTRY PREP	11-2
SAFER ENTRY STOW	11-2
POST ISS EVA ENTRY PREP	11-3
<u>OFF-NOMINAL PROCEDURES</u>	12-i
EMU CONTINGENCY PROCS	TEMP FS 12-1
DISPLAY LOSS DURING POWER TRANSFER (WARM RESTART) ...	TEMP FS 12-2
VACUUM H2O RECHARGE (MANNED)	TEMP FS 12-2
LiOH REPLACEMENT (MANNED)	12-3
BATTERY REPLACEMENT (MANNED)	12-4
WATER DUMP	12-6

SCU SWAP (UNMANNED)	12-7
SCU SWAP (MANNED)	12-7
EMU COLD RESTART (MANNED).....	12-7
12.1 STS EVA DECONTAMINATION	12-8
CONTAMINATION TEST	12-15
SAFER BATTERY CHANGEOUT	12-18
BENDS TREATMENT ADAPTER (BTA) INSTALLATION (IN-SUIT).....	12-19
BTA PREP	12-19
BTA TREATMENT	12-20
BENDS TREATMENT ADAPTER (BTA) INSTALLATION (POST SUIT DOFFING)...	12-21
BTA PREP	12-21
BTA TREATMENT	12-22
EMU RESIZE.....	12-25
EMERGENCY UNDOCKING EVA TRANSFER	FS CC 12-27
EXPEDITED SUIT DOFFING CUE CARD	FS CC 12-28
STS-135 NOMINAL EMU SIZING	FS 12-29
EMU CONTINGENCY RESIZE MATRIX (STS-135/ULF7)	FS 12-31
TPS REPAIR.....	FS 13-1
ORBITER CONTINGENCY EVA.....	14-1
PAYLOAD BAY EVA NOMENCLATURE	14-2
RMS/PRLA CONTINGENCY EVA	14-3
96 BOLT PRE-EVA TOOL CONFIG.....	14-13
96 BOLT EVA TIMELINE	14-14
CAPTURE LATCH MANUAL RELEASE (ODS/PMA)	14-19
96 BOLT EVA LAYOUT.....	14-21
PLBD LATCH TOOL PLACEMENT WITH DUAL LATCH GANG FAILURES.....	14-22
EVA CUFF CHECKLIST (CIL)	15-1
NORMAL EVA STATUS.....	15-2
DCM CONFIGURATION	15-2
EMU MALFUNCTION INDEX.....	15-2
DECOMPRESSION SICKNESS (DCS)	15-3
DECOMPRESSION SICKNESS (DCS) (CONT).....	15-3
ABORT EVA.....	15-3
TERMINATE EVA.....	15-3
SUIT P EMERG	15-4
SOP O2 ON.....	15-4
BATT AMPS HIGH	15-4
BATT V DECAY OR BATT VDC LOW	15-4
SUIT P LOW	15-5
SUIT P HIGH.....	15-5
SOP P LOW	15-5
O2 USE HIGH	15-5
SUBLM PRESS.....	15-6
H2O GP LOW.....	15-6
RESRV H2O ON	15-6
H2O WP HIGH	15-6
NO VENT FLOW	15-7
CO2 HIGH OR MONITOR CO2	15-7
CO2 SNSR BAD.....	15-7
COMM FAILURE.....	15-7
AIR FLOW CONTAMINATION	15-8
LOSS OF COOLING	15-8
RLF V FAIL.....	15-8
MISC MSGS 1	15-8
MISC MSGS (CONT)/TIME LF.....	15-9
AIRLOCK LATCH DISCONNECT	15-9
AIRLOCK INGRESS.....	15-9

FOLLOWING PAGES NOT IN EV CUFF

RADIATOR ACTUATOR DISCONNECT	15-9
PLBD DRIVE CUT	15-10
DOOR DRIVE RESTRAINT	15-10
DOOR DRIVE DISCONNECT	15-10
WINCH OPERATIONS	15-10
WINCH OPERATIONS (CONT)	15-11
3-PT TOOL INSTALLATION	15-11
CL LATCH TOOL	15-11
RMS JOINT ALIGN	15-11
MPM STOW/DEPLOY	15-12
RMS TIEDOWN	15-12
RMS FLIGHT RELEASABLE GRAPPLE FIXTURE RELEASE	15-12
PRLA OPEN/CLOSE	15-12
PRLA OPEN/CLOSE (CONT)	15-13
KU ANTENNA STOW	15-13
KU ANTENNA STOW (CONT)	15-13
AIRLOCK EGRESS	15-13
<u>FLIGHT SPECIFIC REFERENCE</u>	16-i
UNSCHEDULED/CONTINGENCY EVA TASKS	TEMP FS 16-1
STS-135/ULF7 WORKAROUNDS CRIBSHEET	TEMP FS 16-2
EVA 1 CONTINGENCIES	TEMP FS 16-2
GET-AHEAD CONTINGENCIES	FS 16-6
GENERIC CONTINGENCIES	FS 16-8
ROEU CONTINGENCIES	
RELEASE ROEU LATCHES	FS 16-31
LATCH ROEU LATCHES	FS 16-34
STOW ROEU ARM	FS 16-38
MATE ROEU ARM	FS 16-41
ROEU OVERVIEW	FS 16-43
SSRMS JOINT DRIVE	FS 16-44
GENERIC EVA INHIBIT PAD	FS 16-49
GENERIC NOTES, CAUTIONS, & WARNINGS	FS 16-56
TIE-DOWN PLANS	
MISSE 8 ORMATE III R/W TIE-DOWN	FS 16-63
CP7 ETVCG TIE-DOWN	FS 16-64
SSRMS BASE B BOOM CLPA TIE-DOWN	FS 16-65
CP13 ETVCG LIGHT TIE-DOWN	FS 16-66
 GENERIC EVA REFERENCE	 17-1
 FLIGHT SPECIFIC EVA REFERENCE	 FS 18-1
ORBITER	
PAYLOAD BAY OVERVIEW	FS 18-3
LMC	FS 18-9
ROEU	FS 18-21
PRLA	FS 18-23
EVA 1	
PM	FS 18-24
COLT	FS 18-35
RRM	FS 18-38
FRAM	FS 18-45
MISSE 8 ORMATE III R/W	FS 18-62
SPDM	FS 18-69
SPDM EOTP	FS 18-70

GET-AHEADS	
ETVCG	FS 18-75
ETVCG LIGHT (VLA).....	FS 18-79
SSRMS BASE B CLPA.....	FS 18-81
CP13.....	FS 18-85
S1 FHRC P-CLAMP RELEASE	FS 18-86
PMA3 COVER (TBD).....	FS 18-87
LAB GAP SPANNER	FS 18-88
GENERIC ISS	
CETA CART OVERVIEW	FS 18-89
<u>EVA EMERGENCY</u>	19-i
EMERGENCY PROCEDURES.....	19-1
EMERGENCY AIRLOCK REPRESS	19-3
EMERGENCY AIRLOCK REPRESS.....	19-4
POST EMERGENCY AIRLOCK REPRESS	19-4
SAFER RESCUE.....	19-5
SAFER RESCUE	19-6
DAP/EVA RESCUE/RETRIEVE	19-7
EVA ORBITER CONFIG.....	19-7
EVA RESCUE/RETRIEVE.....	19-9
19.1 DCS TREATMENT	19-10
CONTINGENCY SHUTTLE AIRLOCK INGRESS FROM ISS	19-13
CUE CARD CONFIGURATION	20-1

AIRLOCK CONFIG

AIRLOCK PREP TEMP FS 2-2
AIRLOCK PREP FOR DOCKING TEMP FS 2-3
BOOSTER FAN DEACTIVATION/REMOVAL TEMP FS 2-4
BOOSTER FAN INSTALLATION/ACTIVATION TEMP FS 2-4
EMU REMOVAL TEMP FS 2-4
EMU INSTALLATION TEMP FS 2-4
EMU CHECKOUT PREP TEMP FS 2-5
ISS EMU CHECKOUT PREP TEMP FS 2-5
LTA RESTRAINT STRAP REMOVAL TEMP FS 2-6
LTA RESTRAINT STRAP INSTALLATION TEMP FS 2-6
EVA PREP FOR TRANSFER TO ISS FS 2-7
POST DOCKING EVA TRANSFER AND RECONFIG FS 2-9
POST-EVA EMU RESIZE FS 2-10
POST EVA RECONFIG AND TRANSFER TO SHUTTLE FS 2-14
EVA UNPACK AND STOW FS 2-16
EMU PLSS TAB INSTALL FS 2-17

AIRLOCK
CONFIG

AIRLOCK PREP (50 min)

	Retrieve or unstow following equipment:
MF28G	3/8-in breaker bar, 4-in ext w/3/8-in drive
IFM Tool Kit	1/2-in socket w/3/8-in drive
Vol H	EMU Equipment Bag – attach to middeck wall
	Helmet Lights
	EVA Bag
	Contamination Detection Kit (location flight specific)
<hr/> FDF Locker	Cuff Checklists (2) – stow in EMU Equipment Bag
	<u>DEPRESS/REPRESS</u> Cue Card

- AW18A
1. ✓ Inner hatch Equal vlv (two) – OFF
 2. LTG FLOOD (four) – ON
 3. Remove from airlock, as reqd:
 - Airlock Stowage Bag
 - Airlock Floor Pallet using 3/8-in breaker bar, 4-in ext w/3/8-in drive, and 1/2-in socket w/3/8-in drive
 4. Stow Vol H Bags in Vol H
 5. Transfer to airlock:
 - EVA Bag – install on airlock wall
 - DEPRESS/REPRESS Cue Card
 - Helmet Lights
 - Contamination Detection Kit – install on airlock wall
 6. Install IVA foot restraint, as reqd
 7. Unbuckle SCU straps, Velcro SCU to wall
 8. Install EMU lights on helmets (EMU 1, EMU 2) and perform pull test to verify latches fully seated in helmet brackets
 9. Disconnect helmets from Airlock EMUs, temp stow
 10. Remove comm caps from LTA Restraint Bags and connect to electrical harnesses
 11. Install helmets (not reqd if proceeding directly to EMU Checkout)
 12. Remove LTA Restraint Bags
 13. Disconnect waist rings; remove and stow any equipment stowed in HUT/LTA
 14. Stow LTA Restraint Bags on AAPs
 15. ✓ Thermal cover clear of waist ring
 16. Waist ring – engage posn
 17. Connect LTA to HUT, lock
 18. Remove 20-g Crash Bag from middeck EMU, as reqd

AIRLOCK PREP FOR DOCKING (30 min)


- AW18A
1. √Inner hatch Equal vlv (two) – OFF
 2. LTG FLOOD (four) – ON

NOTE

Removing EMU from AAP will make it easier to install LTA Restraint Bag

BOTH EMUs/
DCM

3. Release LTA Spring hooks (four) from AAP
4. Release EMU from AAP so back of PLSS can be accessed
5. Remove LTA Restraint Bags from the lower AAP Bar and transfer to LTA Restraint strap D-rings (ref: figure below)
6. Attach LTA spring hooks (four) to SAFER mount brackets
7. √PWR – SCU
8. √PURGE vlv – op (up)
9. √WATER – OFF, switch guard installed
10. √O2 ACT – OFF
11. Stow EMU, as required (in Middeck or on AAP)



NOTE

French hooks should be attached to SAFER mount brackets for launch and landing

BOOSTER FAN DEACTIVATION/REMOVAL (15 min)

- MO13Q 1. ARLK FAN A,B (two) – OFF
MA73C:G 2. cb AC1,2 ARLK TNL FAN A,B (six) – op
EXT A/L 3. Disconnect flex duct from booster fan muffler inlet, direct airflow into airlock, temp secure
4. Disconnect vent duct from booster fan outlet and external airlock duct inlet; temp stow in middeck
If booster fan to be removed:
5. Disconnect flex duct from booster fan inlet; rotate and stow in launch bracket
6. Demate booster fan electrical connectors from J1,J2 (two) on tunnel extension wall; loosen cable harnesses (two) from Velcro strips (four)
7. Stow electrical connectors (two) on booster fan dummy fittings, secure cable harnesses with Velcro strips
8. Loosen booster fan fasteners (four)
9. Remove booster fan assy, temp stow in middeck

BOOSTER FAN INSTALLATION/ACTIVATION (15 min)

- If booster fan to be installed:
MA73C:G 1. √cb AC1,2 ARLK TNL FAN A,B (six) – op
MO13Q 2. √ARLK FAN A,B (two) – OFF
EXT A/L 3. Install booster fan assy, secure fasteners (four)
4. Demate electrical connectors (two) from booster fan dummy fittings and Velcro strips
5. Mate booster fan electrical connectors J1,J2 (two) on tunnel extension wall; secure cable harnesses (two) with Velcro strips (four)
6. Unstow/connect flex duct from launch bracket to booster fan inlet
7. Unstow/connect vent duct to external airlock duct inlet and booster fan outlet
8. Unstow/connect flex duct from middeck to fan muffler inlet
MA73C:G 9. cb AC1,2 ARLK TNL FAN A,B (six) – cl
MO13Q 10. ARLK FAN A(B) – ON
11. Check for airflow at top of external airlock halo

EMU REMOVAL (15 min)

1. As reqd, install gloves
2. As reqd, perform LTA RESTRAINT STRAP INSTALLATION
3. As reqd, relocate LTA spring hooks (four) from AAP rings to SAFER mount brackets
4. Disconnect EMUs from AAPs, stow in middeck

EMU INSTALLATION (30 min)

1. Transfer EMUs to A/L, connect to AAPs
2. Remove LTA Restraint strap from D-rings on LTA Restraint Strap and transfer to lower AAP Bar
3. Relocate LTA spring hooks (four) from SAFER mount brackets to AAP rings

EMU CHECKOUT PREP (30 min)

NOTE

For use with Shuttle A/L related EVA

- Airlock
1. LTG FLOOD (four) – on
 2. Remove Airlock Floor Bag from Airlock, as required
 3. Unbuckle SCU straps, Velcro SCU to wall
 4. Disconnect helmets from EMUs, temp stow
 5. √DIDB Restraint Bags installed
 6. Remove comm caps (3) from LTA Restraint Bags (kangaroo pouches)
For EMU 3015 – Starboard Side (Wh)
Connect comm cap Wh1 to EMU electrical harness
Temp stow comm cap Wh2 (for Wh ECOK, step 9)
For EMU 3006 – Port Side (Mg)
Connect comm cap Mg 1 to EMU electrical harness
 7. Disconnect LTA Restraint Bag from EMUs; temp stow on bottom of AAP
 8. Disconnect waist rings; remove Wh, Mg ECOKs and LCVGs
 9. Stow comm caps: Wh2 in Wh ECOK
 10. Temp stow LCVGs for EMU checkout
 11. √Thermal cover clear of waist rings
 12. Waist rings – engage position
 13. Connect LTAs to HUTs, lock
- Middeck
Vol H
(MD23R)
14. Unstow from Volume H Bags:
EVA 1 INBD Bag:
EMU Servicing Kit s/n 5004 – Temp Stow
 15. Restow Volume H Bags
 16. If performing EMU checkout on shuttle, assemble EMU Equipment Bag and temp stow in Middeck. Will be used for EMU checkout

ISS EMU CHECKOUT PREP (30 min)

- ISS A/L
1. Remove EMUs s/n 3010 (Fs) and 3009 (Ga) from EDDAs and temp stow in Crewlock
 2. Install EMU s/n 3015 in Aft EDDA (Wh)
 3. Install EMU s/n 3006 in FWD EDDA (Mg)
 4. Remove prime comm caps (Wh1 and Mg1) from LTA Restraint Bags (kangaroo pouches)
 5. Remove LTA restraint bags to allow access to waist ring
 6. Disconnect waist rings; remove Wh, Mg ECOKs and LCVGs
 7. Temp stow ECOKs for EMU checkout
 8. Disconnect helmets from EMUs, temp stow. (Will remain off until ISS EMU checkout)
 9. √DIDB Restraint Bags installed
 10. For EMU 3015 – Aft EDDA (Wh)
Connect comm cap Wh1 to EMU electrical harness
For EMU 3006 – Fwd EDDA (Mg)
Connect comm cap Mg1 to EMU electrical harness
 11. √Thermal cover clear of waist rings
 12. Waist rings – engage position
 13. Connect LTAs to HUTs, lock

LTA RESTRAINT STRAP REMOVAL (15 min)

NOTE

May be performed on EMU 1 and 2 simultaneously.
Perform steps as reqd for current EMU config


1. As reqd, remove comm cap from LTA Restraint Bag; temp stow
2. Remove EMU from AAP
3. Disconnect all restraint attachments from SAFER mount brackets (two)
4. Loosen cinch strap mechanism, remove SAFER mount brackets
5. Remove strap from PLSS
6. Stow strap in LTA Restraint Bag Pouch with D-rings (three) connected
7. Engage EMU in AAP
8. Stow LTA Restraint Bag/strap

LTA RESTRAINT STRAP INSTALLATION (15 min)

NOTE

May be performed on EMU 1 and 2 simultaneously. Perform steps as reqd for current EMU config. Procedure written to install in Launch/Landing config shown below

1. Unstow LTA Restraint Bag/strap
2. Remove EMU from AAP
3. Install SAFER mount brackets (two)
4. Install elastic band of strap around SOP
5. Tighten cinch strap mechanism
6. Attach strap French hooks (two) to SAFER mount brackets
7. Engage EMU in AAP
8. Stow LTA, suit arms inside LTA Restraint Bag
9. Connect upper spring hooks (two) over suit shoulders to upper AAP attachment rings (two)
10. Connect lower spring hooks (two) around suit arms to SAFER mount brackets (two)
11. Tighten all LTA bag straps with bag as high as possible on EMU



NOTE

French hooks should be attached to SAFER mount brackets for launch and landing

EVA PREP FOR TRANSFER TO ISS (30 min)

- Bag D
1. Retrieve Fs and Ga combined ECOK from Bag D, remove EVA Sys Xfer Bags 1 & 2 from inside combined ECOK
 2. Retrieve PMA3 cover from Bag D
 3. Place combined ECOK in EVA Sys Xfer Bag 1
- Airlock/
4. Retrieve the following: Middeck

EVA Sys Xfer Bag 1 (w/combined ECOK)
EVA Sys Xfer Bag 2
PMA3 Cover

5. Retrieve spare EXPEDITED SUIT DOFFING/EMERGENCY UNDOCKING EVA TRANSFER CUE CARD from FDF/SODF Locker MF57K and stow with EMU 3006 (Mg)
6. Verify/configure items according to tables below:

EMU 3015 (Wh)	EMU 3006 (Mg)
<input type="checkbox"/> LTA Restraint Bag installed	<input type="checkbox"/> LTA Restraint Bag installed
<input type="checkbox"/> Helmet (√sun shade down, cover installed)	<input type="checkbox"/> Helmet (√sun shade down, cover installed)
<input type="checkbox"/> EMU Gloves (Wh1)	<input type="checkbox"/> EMU Gloves (Mg1)
<input type="checkbox"/> Comm Caps (Wh1 and Wh2) in LTA Restraint Pouch	<input type="checkbox"/> Comm Cap (Mg1) in LTA Restraint Pouch

EVA SYS XFER BAG 1	FROM
<input type="checkbox"/> ISS EVA Systems Checklist (1) with Red Stripe (Green remains in locker for IV) <input type="checkbox"/> ISS EVA Systems Checklist (1) with no stripe (Not to use during STS-135/ULF7) <input type="checkbox"/> FDF: EVA Checklist STS-135 (1) with Red Stripe currently in use (Green remains in locker for IV) <input type="checkbox"/> EVA Ziplock <input type="checkbox"/> <u>STS-135 CONSUMABLES TRACKING CUE CARD</u> <input type="checkbox"/> <u>EXPEDITED SUIT DOFFING/EMERGENCY UNDOCKING EVA TRANSFER CUE CARD</u> <input type="checkbox"/> <u>ISLE EVA PREBREATHE CUE CARD</u> <input type="checkbox"/> <u>CREWLOCK DEPRESS/REPRESS CUE CARD</u> <input type="checkbox"/> <u>AMMONIA CONTAMINATION TEST/HYDRAZINE CONTAMINATION TEST CUE CARD</u> <input type="checkbox"/> <u>JOINT EXPEDITED EGRESS CUE CARD</u> <input type="checkbox"/> <u>CEVIS EXERCISE PREBREATHE CUE CARD</u> <input type="checkbox"/> <u>CREWLOCK DEPRESS/REPRESS CUE CARD WITHOUT IV</u>	FDF/SODF Locker MF57K
<input type="checkbox"/> Contingency Operation LAPA Tool (COLT) (2) s/n 1001 and 1002 <input type="checkbox"/> COLT Caps (2) s/n 1001 and 1003 <input type="checkbox"/> D-ring Extender s/n 1003 <input type="checkbox"/> Gap Spanner s/n 1096	Bag D
<input type="checkbox"/> LiOH (CCC) (2) (s/n 2014 & 2025)	Airlock Floor Bag – Bag I
<input type="checkbox"/> PBA Mask Assembly (2)	Bag B
<input type="checkbox"/> Nikon 10.5mm Lens (marked for EVA use)	Still Camera Bag, Locker A17
<input type="checkbox"/> EVA Camera Thermal Blanket (s/n 1012) <input type="checkbox"/> Lens Cap Assembly, 28mm, 35mm, 50mm (s/n 1035)	DTV Bag, Locker A16

EVA PREP FOR TRANSFER TO ISS (30 min) (Cont)

EVA SYS XFER BAG 2	FROM
<input type="checkbox"/> EMU Servicing Kit (s/n 5004) <input type="checkbox"/> SOP Checkout Fixture (SCOF) s/n 1012 <input type="checkbox"/> SOP Checkout Fixture (SCOF) s/n 1014	Volume H – EMU Equipment Bag
<input type="checkbox"/> Bends Treatment Adapter w/wrench s/n 1003 <input type="checkbox"/> DIDBs unused (2) <input type="checkbox"/> 85-ft Safety Tether #25 <input type="checkbox"/> 85-ft Safety Tether #27	Airlock Floor Bag – Bag I

Fs and Ga Combined ECOKs (Reference only, no need to verify) FROM BAG D	
<input type="checkbox"/> ECOK (Fs) <ul style="list-style-type: none"> <input type="checkbox"/> Fs EVA 1 Ziplock Bags <ul style="list-style-type: none"> • MAGs (2 w/Ziplock Bags) • TCUs (top, bottom) • Socks • Wristlets • Comfort Gloves, Spectra • EV identifier stripes (EV1) • Fresnel Lens (2) • Elastic Glasses Retention Device • Moleskin • Mission patch • US flag 	<input type="checkbox"/> ECOK (Ga) <ul style="list-style-type: none"> <input type="checkbox"/> Ga EVA 1 Ziplock Bags <ul style="list-style-type: none"> • MAGs (2 w/Ziplock Bags) • TCUs (top, bottom) • Socks • Wristlets • Comfort Gloves, Manzella • EV identifier stripes (EV2) • Moleskin • Mission patch • US flag

POST DOCKING EVA TRANSFER AND RECONFIG (35 min)

I

NOTE

This procedure assumes that transfer items were preconfigured per EVA PREP FOR TRANSFER TO ISS

1. Transfer the following EVA equipment to ISS:

Item	Final Destination	Xfer Status
EVA Sys Xfer Bag 1	E-Lk	
EVA Sys Xfer Bag 2	Node 1 (Deck 1)	
PMA3 Cover	Crew Lock	

EVA Sys
Xfer Bag 1

2. Unstow (Fs/Ga) combined ECOK and temp stow in E-Lk
3. Unstow following items and position in E-Lk Xfer Bag 1

From EVA Sys Xfer Bag 1:

- ISS EVA Sys Checklist with Red Stripe
- STS-135 FDF EVA Checklist with Red Stripe
- STS-135 CONSUMABLES TRACKING CUE CARD
- EXPEDITED SUIT DOFFING/EMERGENCY UNDOCKING EVA TRANSFER CUE CARD
- JOINT EXPEDITED EGRESS CUE CARD
- ISLE EVA PREBREATHE CUE CARD
- CREWLOCK DEPRESS/REPRESS CUE CARD (Deploy/replace in Crewlock)
- AMMONIA CONTAMINATION TEST/HYDRAZINE CONTAMINATION TEST CUE CARD (Deploy/replace in Crewlock IV Bag)

EVA Sys
Xfer Bag 1

4. Stow the following cue cards from EVA Sys Xfer Bag 1 into the large top pocket of the EMU Equipment Bag:
 - CEVIS EXERCISE PREBREATHE CUE CARD
 - CREWLOCK DEPRESS/REPRESS CUE CARD WITHOUT IV
5. Unstow LiOH canisters (s/n 2014 & 2025). Holding LiOH cartridge with aluminum plate serial number facing self, remove caps (right first) inspect O-rings for damage and verify O-rings are seated properly in grooves. Remove Vent Port Plugs and install LiOH s/n 2014 in EMU 3010 (Fs) and LiOH s/n 2025 in EMU 3009 (Ga). Stow LiOH Caps and Vent Port Plugs in EMU Equipment Bag
6. Unstow PBA Mask Assemblies (2) and change out with PHA side pocket PBAs assemblies. Check **MCC-H** for stowage location of old mask
7. Unstow COLT (2), COLT Caps (2). RET to Crewlock Bag per EVA 1 TOOL CONFIG
8. Unstow Gap Spanner and PMA Cover; stow in Medium ORU bag per EVA 1 TOOL CONFIG
9. Unstow Nikon 10.5mm Lens, Thermal Blanket and Lens Cap Assembly and configure per EVA P/TV Setup
10. Gather old ISS EVA Sys Checklist, Ammonia CC & Depress/Repress CC from Airlock and stow in EVA Sys Xfer Bag 1
11. Stow EVA Sys Xfer Bag 2 in the NOD1 D1. Items in this bag will not be used during the EVA and will be deployed post EVA
12. Report transfer status to **MCC-H** as time permits

EVA Sys
Xfer Bag 2

POST-EVA EMU RESIZE (120 min)

I

OBJECTIVE

This procedure will swap Garan's EMU 3009 and Walheim EMU 3015 HUTs. This will configure EMU 3015 to leave on ISS and EMU 3009 for Walheim return. Figures 1 and 2 contain final sizing information. To complete this activity, all components will be removed from one HUT and installed on the other HUT

NOTE

Reference 1.550 EMU RESIZE (SODF: ISS EVA SYS: EMU MAINTENANCE) for component changeout steps

CAUTION

Remove rings and other jewelry before exposing EMU bladder

√All seals are clean and free of debris before making connections

- EMU 3006 (Mg) 1. Remove EMU 3006 (Mg) from FWD EDDA and stow in Crewlock
- EMU 3009 (Ga) 2. Retrieve EMU 3009 (Ga) and install on FWD EDDA
3. Remove Helmet (s/n 1080) and Comm Cap; temp stow. Remove DIDB and stow in wet trash (leave restraint in EMU)
- EMU 3015 (Wh)/ 4. Remove Helmet (s/n 1077) and install on EMU 3009 (Ga)
3009 (Ga) Install Helmet and Comm Cap from EMU 3009 (Ga) on EMU 3015 (Wh)
5. Install protective cover on helmets
- Swap Lower Arms of EMUs 3015 (Wh) to 3009 (Ga)**
- EMU 3009 (Ga) 6. Disconnect Lower Arm Power Harness ←|→ Upper Arm Power Cable (2)
Remove Lower Arms (s/n 380/379) w/gloves (Ga) attached; temp stow
- EMU 3015 (Wh)/ 7. Disconnect Lower Arm Power Harness ←|→ Upper Arm Power Cable (2)
3009 (Ga) Remove Lower Arms (s/n 419/420) w/gloves (Wh) attached and install on EMU 3009 (Ga)
- EMU 3015 (Wh) 8. Install Lower Arms (s/n 380/379) w/gloves (Ga) on EMU 3015 (Wh)
9. Verify Both EMUs:
Red disconnect is right arm, blue disconnect is left arm
Cams (8) are Short/Long for each EMU
Check lock tab 1 engaged for each arm
Lower Arm Power Harness →|← Upper Arm Power Cable (2)
- Swap Lower LTA Assembly of EMUs 3015 (Wh) to 3009 (Ga)**
- EMU 3009 (Ga) 10. Remove LTA Assembly (waist brief s/n 052) and temp stow
- EMU 3015 (Wh) 11. Remove LTA Assembly and ECOK (Wh) from EMU 3015 (Wh)
- EMU 3009 (Ga) 12. Stow ECOK (Wh) inside of EMU 3009 (Ga) and install LTA Assembly
(waist brief s/n 039) on EMU 3009 (Ga)
- EMU 3015 13. Install LTA Assembly (s/n 052) on EMU 3015

POST EVA EMU RESIZE (60 min) (Cont)

Swap LiOHs and Mission Patches of EMUs 3009 (Ga) to 3015 (Wh)

- | | |
|-------------------|--|
| EMU 3009 | 14. Remove LiOH from EMU 3009 (Ga) (expended), install caps from EMU Equipment Bag and stow in EVA Sys Xfer Bag 1 |
| | 15. Remove EMU Battery and stow in 0.5 CTB (1025) inside M-O2 Bag 1038 |
| EMU 3015/
3009 | 16. Remove LiOH and Battery from EMU 3015 (Wh) and install in EMU 3009 (Ga). Install Vent Port Plugs from EMU Equipment Bag in EMU 3015 (Wh) Reference <u>1.515 EMU METOX/LiOH/BATTERY REPLACEMENT</u> (SODF: ISS EVA SYS: EMU MAINTENANCE) as necessary |
| EMU 3009 | 17. Install LTA Restraint Bag and Restraint Strap from EMU 3015 and install on EMU 3009 for transfer back to shuttle (Wh) return suit |
| | 18. Swap mission patches and stripes |
| | 19. Stow shuttle EMUs (s/n 3006 and 3009) per crew preference |

POST EVA EMU RESIZE (60 min) (Cont)




Figure 1.- EMU 3009 sized Walheim final configuration.

Blue Font – Indicates components that come from EMU 3015

Black Font – Indicates hardware already installed on EMU 3009

POST EVA EMU RESIZE (60 min) (Cont)




Figure 2.- EMU 3015 sized for Garan ISS.

Red Font – Indicates components that come from EMU 3009

Black Font – Indicated hardware already installed on EMU 3015

POST EVA RECONFIG AND TRANSFER TO SHUTTLE (30 min)

I

NOTE

This procedure assumes [1.240 POST EVA](#)
(SODF: ISS EVA SYS: EVA PREP/POST)
has been completed following the EVA

- EMU 3010 (Fs)
1. Install EMU 3010 in FWD EDDA and remove LiOH and install vent port plugs from the EMU Equipment Bag. Remove EMU LIB Battery and stow in 0.5 CTB (s/n 1025) inside M-O2 Bag (s/n 1038). Stow expended LiOH in EVA Sys Xfer Bag 1
 2. Gather COLT Caps (2) from EMU s/n 3010 trash bag and stow in EVA Sys Xfer Bag 2
 3. Gather Nikon 10.5mm Lens (used during EVA), EVA Camera Thermal Blanket (s/n 1007) and Lens Cap Assembly, 28mm, 35mm, 50mm (s/n 1037) stow in EVA Sys Xfer Bag 1
- EMU 3006/3009
4. Verify Installed and connected:
 - Gloves
 - Helmets
 - DIDB Restraint Bag
 - ECOKS stowed inside of HUT
 - LTAs
 - LTA Restraint Bag for transfer
 - Comm Caps (Wh (2) and Mg (1)) stowed in LTA Restraint Bag Pouch
 5. ✓Helmet sun shades down, cover installed
- Deploy items from EVA Sys Xfer Bag 2
6. Remove EMU Servicing Kit s/n 5004 from EVA Sys Xfer Bag 2 and deploy in E-Lk
 7. Gather EMU Servicing Kit s/n 5002 and stow in EVA Sys Xfer Bag 2
 8. Remove SCOFs s/n 1012 and 1014 and stow in EMU Equipment Bag
 9. Gather SCOFs s/n 1011 and 1013 and stow in EVA Sys Xfer Bag 2
 10. Remove BTA Assembly s/n 1003 from EVA Sys Xfer Bag 2 and stow in the outside pocket of MO-2 bag 1038
 11. Gather BTA Assembly s/n 1004 and stow in EVA Sys Xfer Bag 2
 12. Remove 85-ft Safety Tethers #25 and #27 and D-ring Extender s/n 1003 and deploy on Tether Staging area
 13. Gather 85-ft Safety Tethers #22 and #21 and stow in EVA Sys Xfer Bag 2
 14. Remove DIDBs unused (2) and stow in A/L1D1_B2
 15. Gather SODF/FDF Cue Cards from ISS airlock per EVA Sys Xfer Bag 1 table below
 16. Config/verify items listed below are in specified bags
Transfer bags and EMUs to shuttle

POST EVA RECONFIG AND TRANSFER TO SHUTTLE (30 min) (Cont)

<u>EMU 3009 (Wh)</u>	<u>EMU 3006 (Mg)</u>
<input type="checkbox"/> DIDB Restraint Bag	<input type="checkbox"/> DIDB Restraint Bag
<input type="checkbox"/> ECOK	<input type="checkbox"/> ECOK
<input type="checkbox"/> LCVG (Wh)	<input type="checkbox"/> LCVG (Mg)
<input type="checkbox"/> Helmet (√sun shade down, cover installed)	Helmet (√sun shade down, cover installed)
<input type="checkbox"/> Valsalva	<input type="checkbox"/> Valsalva
<input type="checkbox"/> EMU Gloves (Wh1)	<input type="checkbox"/> EMU Gloves (Mg1)
<input type="checkbox"/> EMU Battery (s/n 2099)	<input type="checkbox"/> EMU Battery (s/n 2100)
<input type="checkbox"/> LiOH (2002)	<input type="checkbox"/> LiOH (2012)
<input type="checkbox"/> LTA	<input type="checkbox"/> LTA
<input type="checkbox"/> 2 Comm Caps	<input type="checkbox"/> 1 Comm Cap

EVA SYS XFER BAG 1
<input type="checkbox"/> <input type="checkbox"/> LiOH (CCC) (2) (expended from EVA 1) s/n 2014 & 2025
<input type="checkbox"/> ISS EVA Systems Checklist (2) with Red Stripe and No Stripe (Old ISS Checklist)
<input type="checkbox"/> FDF: EVA Checklist STS-135 (1) with Red Stripe
<input type="checkbox"/> EVA Ziplock
<input type="checkbox"/> <u>STS-135 CONSUMABLES TRACKING CUE CARD</u>
<input type="checkbox"/> <input type="checkbox"/> <u>EXPEDITED SUIT DOFFING/EMERGENCY UNDOCKING EVA TRANSFER CUE CARD</u>
<input type="checkbox"/> <u>ISLE PREBREATHE CUE CARD (Old ISS CC)</u>
<input type="checkbox"/> <u>AMMONIA CONTAMINATION TEST CUE CARD</u>
<input type="checkbox"/> <u>EXERCISE PREBREATHE CUE CARD (Old ISS CC)</u>
<input type="checkbox"/> <u>CREWLOCK DEPRESS/REPRESS CUE CARD (Old ISS CC)</u>
<input type="checkbox"/> <u>CREWLOCK DEPRESS/REPRESS CUE CARD WITHOUT IV (Old ISS CC)</u>
<input type="checkbox"/> <u>JOINT EXPEDITED EGRESS CUE CARD</u>
<input type="checkbox"/> Nikon 10.5mm Lens (used during EVA)
<input type="checkbox"/> EVA Camera Thermal Blanket (s/n 1007)
<input type="checkbox"/> Lens Cap Assembly, 28mm, 35mm, 50mm (s/n 1037)

EVA SYS XFER BAG 2
<input type="checkbox"/> EMU Servicing Kit (s/n 5002)
<input type="checkbox"/> SOP Checkout Fixture (SCOF) s/n 1011
<input type="checkbox"/> SOP Checkout Fixture (SCOF) s/n 1013
<input type="checkbox"/> 85-ft Safety Tether #22
<input type="checkbox"/> 85-ft Safety Tether #21
<input type="checkbox"/> Bends Treatment Adapter w/wrench s/n 1004
<input type="checkbox"/> <input type="checkbox"/> COLT Caps (2) s/n 1001 and 1003

17. Report to **MCC-H** when transfer complete

Item	Destination	Xfer Status
EMU s/n 3006	Middeck	
EMU s/n 3009	Middeck	
EVA Sys Xfer Bag 1	Middeck	
EVA Sys Xfer Bag 2	Middeck	

EVA UNPACK AND STOW (60 min)

NOTE

This procedure assumes that transfer items were preconfigured per EVA PREP FOR TRANSFER TO SHUTTLE

1. Unpack and stow items per table below; report status to **MCC-H** when complete:

Item	Initial Location (After Transfer)	Final Destination (On Shuttle)	Transfer Status
<input type="checkbox"/> EMU 3009 (Wh)		Stbd – AAP	
<input type="checkbox"/> EMU 3006 (Mg)		Port – AAP	
<input type="checkbox"/> SOP Checkout Fixture (SCOF) s/n 1011 <input type="checkbox"/> SOP Checkout Fixture (SCOF) s/n 1013	EVA Sys Xfer Bag 2	Vol H (MD23R) EMU Equipment Bag main compartment	
<input type="checkbox"/> EMU Servicing Kit s/n 5002	EVA Sys Xfer Bag 2	Vol H (MD23R) EVA 1 INBD Bag	
<input type="checkbox"/> ISS EVA Systems Checklist (2) <input type="checkbox"/> FDF: EVA Checklist <input type="checkbox"/> <u>STS-135 CONSUMABLES TRACKING CUE CARD</u> <input type="checkbox"/> <u>EXPEDITED SUIT DOFFING/EMERGENCY UNDOCKING EVA TRANSFER CUE CARD (2)</u> <input type="checkbox"/> <u>ISLE PREBREATHE CUE CARD</u> <input type="checkbox"/> <u>EXERCISE PREBREATHE CUE CARD</u> <input type="checkbox"/> <u>CREWLOCK DEPRESS/REPRESS CUE CARD</u> <input type="checkbox"/> <u>CREWLOCK DEPRESS/REPRESS CUE CARD WITHOUT IV</u> <input type="checkbox"/> <u>AMMONIA CONTAMINATION TEST CUE CARD</u> <input type="checkbox"/> <u>JOINT EXPEDITED EGRESS CUE CARD</u>	EVA Sys Xfer Bag 1	SODF Locker (MF57K)	
<input type="checkbox"/> Nikon 10.5mm Lens (marked for EVA use)	EVA Sys Xfer Bag 1	Still Camera Bag, Locker A17	
<input type="checkbox"/> EVA Camera Thermal Blanket (s/n 1007) <input type="checkbox"/> Lens Cap Assembly, 28mm, 35mm, 50mm (s/n 1035)	EVA Sys Xfer Bag 1	DTV Bag, Locker A16	
<input type="checkbox"/> 85-ft Safety Tethers (2) <input type="checkbox"/> Bends Treatment Adapter w/wrench 1004	EVA Sys Xfer Bag 2	A/L Floor Bag	
<input type="checkbox"/> LiOH s/n 2014 <input type="checkbox"/> LiOH s/n 2025	EVA Sys Xfer Bag 1	Bag D	
<input type="checkbox"/> <input type="checkbox"/> COLT Caps (2) s/n 1001 and 1003	EVA Sys Xfer Bag 2	Bag D	
<input type="checkbox"/> <input type="checkbox"/> EVA Systems Xfer Bags 1 & 2 (2)	Middeck	A/L Floor Bag	

EMU PLSS TAB INSTALL (10 min)

OBJECTIVE:

To assemble Kapton lanyard for PLSS zippers. This procedure allows crewmembers to easily unzip PLSS with gloved hands in case of a Metox canister changeout

NOTE: Tape will be installed on EMUs 3006 and 3015 prior to launch

MATERIALS:

Kapton Tape – NOD1O4_B1 .5 CTB 1178 (1 inch width)

TOOLS:

Scissors – EMU Servicing Kit, E-Lk Deployed

1. Gather Kapton tape and scissors
2. Cut 8-in piece of Kapton tape
3. Fold tape lengthwise over onto itself in half, twice



Figure 1.- Fold tape.

4. Smooth out creases to make flat surface
NOTE: Tape does not have to be completely flat



Figure 2.- Creasing tape.

EMU PLSS TAB INSTALL (10 min) (Cont)

5. Hold one end of tape and fold over the tip lengthwise, then thread it through hole on the zipper




Figure 3.- Threading tape.

6. Pull through zipper hole doubling the tape, making lanyard tails
7. Wrap a second piece of tape onto the lanyard tails starting at the tail end with adhesive side down



Figure 4.- Wrapping lanyard.

8. Continue wrapping tape in a corkscrew pattern
9. Tuck Kapton lanyard under TMG and Velcro down

CHECKOUTS

EMU CHECKOUT TEMP FS 3-2
 EMU POWERUP AND COMM CHECK TEMP FS 3-2
 PRIMARY REGULATOR/FAN/PUMP CHECK 3-4
 SOP CHECK 3-5
 BATTERY CHARGE CHECK INIT 3-6
 BATTERY CHARGE CHECK TERM..... 3-6
 EMU SWAP DURING CHECKOUT 3-7
 POST EMU C/O RECONFIG 3-7
SAFER CHECKOUT 3-8
SELF TEST SEQUENCE..... 3-9
SAFER CHECKOUT RESULTS CC 3-10
SAFER STATUS TROUBLESHOOTING..... CC 3-11
REBA POWERED HARDWARE CHECKOUT 3-12
ISS EMU CHECKOUT FS 3-13

EMU CHECKOUT

NOTE

Procedures are written for simultaneous C/O of EMUs #_____ (stbd) and #_____ (port) in airlock. An additional C/O of EMU(s) #_____ uses same procedure after performing EMU SWAP during C/O

X: SM 60 SM TABLE MAINT

- 1. Contact MCC for uplink of SM ALERT TMBU (if desired)
Changes enclosed in

Param Name	Param ID	Lower Limit	Upper Limit
EXT A/L H2O LINE T			
EXT A/L H2O SPLY ZN 1 T	0640181	43	<input type="checkbox"/> 100
EXT A/L LCG 2 SPLY ZN 1 T	0640182	<input type="checkbox"/> 36	<input type="checkbox"/> 85
EXT A/L H2O LINE T 2			
EXT A/L H2O SPLY ZN 2 T	0640184	48	<input type="checkbox"/> 100
EXT A/L LCG 2 SPLY ZN 2 T	0640185	<input type="checkbox"/> 36	<input type="checkbox"/> 82
EXT A/L O2 LN T			
EXT A/L O2 SPLY ZN 2 T	0640186	OSL	<input type="checkbox"/> 80
EXT A/L BATT CHARGER			
VOLTS EMU 1	0640210	OSL	<input type="checkbox"/> OSH
VOLTS EMU 2	0640213	OSL	<input type="checkbox"/> OSH

EMU POWERUP AND COMM CHECK (15 min)

NOTE

If procedure is being repeated for 3rd EMU #_____ only, other previously checked EMU #_____ is reqd in airlock to perform EMU POWERUP and COMM CHECK procedures to verify EMU-to-EMU comm.

PWR RESTART msg and BITE light should be illuminated whenever EMU power is cycled. Display and tone tests only occur during cold restarts

- BOTH DCM 2. Retrieve, position SCUs; remove DCM covers
- 3. Connect SCUs to DCM, locked
- 4. PWR – BATT

CAUTION

EMU must be on BATT pwr when airlock power supply is turned on

- AW18H 5. PWR/BATT CHGR EMU 1,2 MODE (two) – PWR
BUS SEL (two) – MNA(MNB)
- 6. EMU INPUT 1,2 volts = 18.0-20.0
- EV AW18D 7. AIRLK AUD PWR – OFF
- BOTH DCM 8. COMM mode – ALT
- 9. Comm FREQ – LOW
- IV A1R 10. AUD CTR UHF A/G 1,2 (two) – OFF
A/A – T/R
- R14:C 11. MNA UHF EVA – cl
 MNC UHF EVA – cl

CHECKOUTS

ISS EMU CHECKOUT (105 min)

OBJECTIVE:

Verify all systems on the Extravehicular Mobility Unit (EMU) are functional prior to use. Shuttle EMUs will remain in ISS A/L after checkout until post Resize. LTA Restraint Bags will be unbuttoned and left attached to the LTA Strap D-Rings for reinstallation.

NOTE

1. Procedure is written for simultaneous checkout of two EMUs.
2. **PWR RESTART** message occurs and BITE light is illuminated whenever EMU power is cycled. Display and tone tests only occur during cold restarts.

- | | |
|--------------|--|
| EMU | 1. √Helmet ← → HUT |
| | 2. √Comm cap → ← electrical harness |
| | 3. √LTA installed |
| | 4. √LiOH Canister installed |
| | √Battery installed |
| UIA | 5. √OXYGEN EMU 1,2 vlv (two) – CLOSE |
| | 6. CONFIGURING O2 SYSTEM |
| MCC-H | Airlock: ECLSS: O2 Hi Pressure Supply Valve
AL O2 Hi Pressure Supply Valve |
| | cmd Open (√Actual Position – Open) |
| | <u>POWERING UP EMUs/CHECKING HARDLINE COMM</u> |
| UIA | 7. √sw PWR EV-1,2 (two) – OFF |
| | √PWR EV-1,2 LEDs (four) – Off |
| | √EMU O2 SUPPLY PRESS gauge: 850 to 950 |
| C-Lk wall | 8. Remove SCU from stowage straps and pouches. |
| | Transfer SCU to E-Lk. |
| DCM | 9. Remove DCM Cover and affix with Velcro to DCM. |
| | 10. SCU → ← DCM |
| | √SCU locked |
| | 11. sw POWER → BATT |

ISS EMU CHECKOUT (105 min) (Cont)

CAUTION

EMU must be on BATT power when UIA suit power is turned on.

- | | | | |
|---------|------------|--|---|
| PSA | 12. | √sw SUIT SELECT (two) – OFF
√sw EMU MODE EMU 1,2 (two) – PWR | |
| | 13. | sw MAIN POWER → ON
√MAIN POWER LED – On | |
| | 14. | sw SUIT SELECT (two) → EMU 1,2
√EMU 1,2 LEDs (two) – On
√EMU 1,2 Volts: 18.0 to 19.0 | |
| UIA | 15. | sw PWR EV-1,2 (two) → ON
√PWR EV-1,2 EMU LEDs (two) – On | |
| ATU 4,5 | 16. | √EACP Y-cable → ← ATUs | |
| EACP | 17. | √EACP Y-cable → ← EACP
sw PWR → ON
√EMU 1,2 mode sel (two) – DUAL | |
| IV | ATU 6 | 18. | Connect headset. |
| | ATUs 4,5,6 | 19. | pb PTT → Press
pb 5 → Press
√Display – ' 5T ' and other loops, as required
√Display – ' DUAL ' |
| EV1,2 | | 20. | Don Comm Caps |
| DCM | | 21. | sw COMM mode → HL |

NOTE

After the next step, be prepared to verify no missing segments on display and that all tones are audible.

22. sw POWER → SCU
23. Verify no missing segments during display test.
Verify BITE light extinguishes.

ISS EMU CHECKOUT (105 min) (Cont)

Verify status (continuous) tone and warble tone are audible.

Report any anomalies to **MCC-H**.

24. Perform IV/EV comm check. (Any ATU with Loop **5T** called up)
- IV ATU 4,5,6 25. pb HANG UP → Press
pb 5 → Press
- EACP 26. sw PWR → OFF
27. [CONFIGURING FOR CONTINUOUS EMU DATA](#)
- DCM sw DISP → STATUS, until **DATA?COMBO** displayed
sw DISP → YES (hold for 2 seconds)
sw DISP → STATUS, until **DATA EMU?** displayed
sw DISP → YES (hold for 2 seconds)
Verify **DATA?EMU** displayed

[CHECKING EMU RADIOS/417.1 MHZ](#)

- IV ATU 6 28. pb 1 → PRESS
- √Display – '1TG' and other loops, as required
- √Display – 'DUAL'

NOTE

The EMUs will be hot mic to **MCC-H** on Public 1 once the COMM modes are taken out of hardline (HL) and the Comm FREQs are in LOW.

- EV1,2 DCM 29 sw COMM mode → PRI
30. sw Comm FREQ → HIGH

NOTE

The Big Loop will be disabled while ISS UHF is in high frequency. (Steps 31 - 37)

31. Inform Shuttle crew that the Big Loop will be disabled while in High Frequency ~ 10 mins.

ISS EMU CHECKOUT (105 min) (Cont)

MCC-H

32. [Switching UHF 2 to High Frequency](#)

C&T: UHF: Configuration

UHF Configuration

'Frequency'

cmd High Freq

√Pending Frequency: 417.1 MHz

'Set Actual Configuration'

cmd Set Actual

Verify no lighted boxes in the Miscompare columns.

√Actual Frequency: 417.1 MHz

EV1,2

33. Perform IV/EV/**MCC-H** comm check.

EV1,2 DCM

34. sw COMM mode → ALT

35. Perform IV/EV comm check.

CHECKING EMU RADIOS/414.2 MHZ

EV1,2 DCM

36. sw Comm FREQ → LOW

MCC-H

37. [Switching UHF 2 to Low Frequency](#)

C&T: UHF: Configuration

UHF Configuration

'Frequency'

cmd Low Freq

√Pending Frequency: 414.2 MHz

'Set Actual Configuration'

cmd Set Actual

Verify no lighted boxes in the Miscompare columns.

√Actual Frequency: 414.2 MHz

EV1,2

38. Perform IV/EV comm check.

EV1,2 DCM

39. sw COMM mode → PRI

40. Perform IV/EV comm check.

41. Doff comm caps.
Stow in left suit arm.

ISS EMU CHECKOUT (105 min) (Cont)

DCM 42. √STATUS: **O2 P**: 800 to 950

EMU	1	2	3
O2 P: 800 to 950 psi	_____	_____	_____

UIA 43. OXYGEN EMU 1,2 vlv (two) → OPEN

44. Install Helmet, lock.

45. √Suit arms aligned

√Gloves locked

√Helmet purge vlv – cl, locked

DCM 46. PURGE vlv → cl (dn)

47. O2 ACT → IV

48. √STATUS: **SUIT P**: 0.4 to 1.4 and stable (compare with gauge)

EMU	1	2	3
SUIT P (IV): 0.4 to 1.4	_____	_____	_____

49. O2 ACT → PRESS

50. √STATUS: **SUIT P**: 4.2 to 4.4 and stable (compare with gauge)

√STATUS: **H2O GP**: 14.0 to 16.0

√STATUS: **H2O WP**: 14.0 to 16.0

EMU	1	2	3
SUIT P (PRESS): 4.2 to 4.4	_____	_____	_____
H2O GP: 14.0 to 16.0	_____	_____	_____
H2O WP: 14.0 to 16.0	_____	_____	_____

51. sw DISP → STATUS, until **LEAK CHECK?** displayed

sw DISP → YES (hold for 2 seconds)

ISS EMU CHECKOUT (105 min) (Cont)

Follow displayed instructions.

EMU	1	2	3
SUIT ΔP: ≤ 0.3 psi	_____	_____	_____

*
*
*

If LEAKAGE/HI SUIT P msg occurs

Perform [2.115 FAILED LEAK CHECK \(14.7/10.2 PSIA\)](#)
(SODF: ISS EVA SYS: EMU CONTINGENCY), then:

- 52. O2 ACT → OFF
- 53. PURGE vlv → op (up)
- 54. √STATUS: SUIT P < 0.4 (compare with gauge)
- 55. To completely equalize EMU ΔP
 - 55.1 Glove ←|→ EMU
 - 55.2 Glove →|← EMU
- 56. Helmet ←|→ HUT
 - Stow Helmet
- 57. Waist ring ←|→ HUT
 - Secure LTA.
 - Remove Multiple Water Connector cover.
- 58. Cooling loop jumper →|← Multiple Water Connector
- 59. √Multiple Water Connector locked
- DCM 60. √Temp control vlv – Max C

NOTE
Steps 61 - 75 operations will be completed serially.

CAUTION
Minimize fan operation with O2 ACT → OFF (~2 minutes).

ISS EMU CHECKOUT (105 min) (Cont)

- DCM 61. sw POWER → BATT
- UIA 62. sw PWR EV-1,2 (two) → OFF
 - √PWR EV-1,2 LEDs (four) – Off
 - √PWR EV-1,2 VOLTS: ~00.0

NOTE

The SCU will be disconnected so that SCU water will not be circulated through the suit during fan on activities.

- DCM 63. SCU ←|→ DCM
- 64. Install DCM cover.
- C-Lk wall 65. Insert SCU in stowage pouch.
- 66. sw FAN → ON
 - Expect BAT AMPS HI message
 - Sw DISP → PRO
 - Verify flow at neck ring vent port.

- DCM 67. √STATUS: BAT AMPS: 2.4 to 6.5

EMU	1	2	3
BATT AMPS: 2.4 to 6.5	_____	_____	_____

- EMU 68. Install SCOF, lock.

NOTE

To ensure good pump flow verify bubbles moving in the cooling loop jumper after the O2 Act taken to IV mode. The bubbles may dissipate quickly after flow started.

- 69. O2 ACT → IV (Possible O2 USE HI message)
 - Expect NO VENT FLOW message, sw DISP → PRO
 - Verify Flow in Cooling Loop Jumper (LCVG).

* If no flow in Cooling Loop Jumper

* ↓ Depress and hold pump priming valve on back of EMU,

* while slowly cycling TCV between 7 and Max C (30 seconds minimum).

↑

ISS EMU CHECKOUT (105 min) (Cont)

DCM

70. √STATUS: **BAT VDC** ≥ 16.8

√STATUS: **BAT AMPS**: 2.4 to 4.0 (decrease from step 67)

√STATUS: **RPM**: 19.0 to 20.0 K

EMU	1	2	3
BAT VDC: ≥ 16.5	_____	_____	_____
BAT AMPS: 2.4 to 4.0	_____	_____	_____
RPM: 19.0 to 20.0k	_____	_____	_____

71. √Fan noise steady

72. O2 ACT → OFF (expect **O2 IS OFF** message)

73. sw FAN → OFF

74. sw POWER → SCU (wait 10 seconds)

75. sw POWER → BATT (to reset X-State)

NOTE

Steps 76 - 86 operations will be completed serially.

CHECKING SOP (2 MINUTES/EMU)

76. CONFIGURING FOR CONTINUOUS EMU DATA

DCM

sw DISP → STATUS, until **DATA?COMBO** displayed

sw DISP → YES (hold for 2 seconds)

sw DISP → STATUS, until **DATA EMU?** displayed

sw DISP → YES (hold for 2 seconds)

Verify **DATA?EMU** displayed

ISS EMU CHECKOUT (105 min) (Cont)

77. ✓STATUS: **SOP P**: 5410 to 6800

EMU	1	2	3
SOP P: 5410 to 6800	_____	_____	_____

SOP

78. ✓SOP gauge 5400 to 6800 (reference Figure 1)

Note SOP interstage gauge.

EMU	1	2	3
SOP GAUGE: 5400 to 6800	_____	_____	_____
INT GAUGE: 0 to 600	_____	_____	_____




Figure 1.- SOP Gauges and Manual Override Lever.

PCS

79. ✓**MCC-H** if Cabin Temp required

Airlock: ECLSS
Airlock ECLSS
 'Equipment Lock'

✓Cab Temp

CAB TEMP	_____
----------	-------

DCM

80. sw DISP → STATUS until **SUIT P** displayed

sw DISP → YES (hold for 2 seconds) to lock parameter

NOTE

Minimize the duration of pressing down on the manual override to conserve SOP pressure.

81. While pressing down on the SOP manual override (30 seconds
 ↓ maximum)

SOP

✓SOP interstage gauge < 600

ISS EMU CHECKOUT (105 min) (Cont)

DCM

√STATUS: **SUIT P**: 3.4 to 3.9 and stable

EMU	1	2	3
INT GAUGE: < 600	_____	_____	_____
SUIT P: 3.4 to 3.9	_____	_____	_____

↑

82. √STATUS: **SOP P**: 5410 to 6800

EMU	1	2	3
SOP P: 5410 to 6800	_____	_____	_____

83. Remove SCOF, stow in EMU Equipment Bag.

84. sw COMM mode → OFF

85. √sw Comm FREQ → LOW

86. sw POWER → SCU

87. LCVG (cooling loop jumper) ←|→ Multiple Water Connector

Stow LCVG in HUT.

Install Multiple Water Connector cover.

88. Remove Comm Caps and stow in LTA Restraint Bag pouch.

Install Helmet →|← HUT

Re-stow ECOKs inside EMUs.

Install LTA →|← HUT

Bundle suit up, install LTA Restraint Bag on EMU 3006 (Mg) only.

UIA

89. OXYGEN EMU 1,2 vlv (two) → CLOSE

PSA

90. sw SUIT SELECT (two) → OFF

√SUIT SELECT LEDs (four) – Off

91. sw MAIN POWER → OFF

√MAIN POWER LED – Off

92. Check **MCC-H** if data reporting required.

MCC-H

93. [RECONFIGURING O2 SYSTEM](#)

Airlock: ECLSS: O2 Hi Pressure Supply Valve

AL O2 Hi Pressure Supply Valve

cmd Close (√Actual Position – Closed)

TIMELINES

EVA 1

EVA 1 SUMMARY TIMELINE	FS 7-3
EVA 1 TOOL CONFIG	FS 7-4
EVA 1 BRIEFING CARD	FS 7-6
EVA 1 INHIBIT PAD	FS 7-7
EVA 1 NOTES/CAUTIONS/WARNINGS	FS 7-10
EVA 1 EGRESS/SETUP	FS 7-17
REMOVE PM FRAM FROM ESP-2	FS 7-20
TRANSFER PM FRAM TO PLB.....	FS 7-21
INSTALL PM FRAM ON LMC	FS 7-22
REMOVE RRM FRAM FROM LMC	FS 7-23
TRANSFER RRM FRAM TO EOTP	FS 7-24
INSTALL RRM FRAM ON EOTP	FS 7-25
MISSE 8 ORMATE III R/W INSTALL ON ELC-2.....	FS 7-26
SSRMS CLEANUP.....	FS 7-28
FGB PDGF TROUBLESHOOTING.....	FS 7-28a
PMA3 COVER INSTALL	FS 7-29
EVA 1 CLEANUP/INGRESS	FS 7-30
EVA 1 TASK DATA – PM TRANSFER	FS 7-31
EVA 1 TASK DATA – RRM TRANSFER.....	FS 7-33
EVA 1 TASK DATA – MISSE 8 ORMATE III.....	FS 7-38
EVA 1 TASK DATA – FGB PDGF TROUBLESHOOTING.....	FS 7-39
EVA 1 TASK DATA – PMA3 COVER INSTALL	FS 7-43

GET-AHEADS

STS-135 GET-AHEADS.....	FS 7-45
FGB PDGF 1553 DATA CABLE INSTALL.....	FS 7-46
FGB PDGF 1553 DATA CABLE INSTALL – TASK DATA	FS 7-48
PORT CETA CART RECONFIG	FS 7-51
SSRMS BASE B ELBOW CLPA R&R.....	FS 7-53
SSRMS BASE B ELBOW CLPA R&R – TASK DATA.....	FS 7-55
S1 FHRC P-CLAMP RELEASE	FS 7-56
S1 FHRC P-CLAMP RELEASE – TASK DATA	FS 7-57
TOOL RECONFIGURATION	FS 7-59
GAP SPANNER INSTALL.....	FS 7-66

TIMELINES

This Page Intentionally Blank

EVA 1 SUMMARY TIMELINE

PET HR : MIN	IV/SSRMS	EV1	EV2	
00:00	<ul style="list-style-type: none"> SSRMS at ST install position near ESP-2 	<u>EGRESS/SETUP (01:00)</u> <ul style="list-style-type: none"> Post Depress and Egress Install COLTs 	<u>EGRESS/SETUP (01:00)</u> <ul style="list-style-type: none"> Post Depress and Egress SSRMS Setup 	00:00
01:00	<ul style="list-style-type: none"> SSRMS Maneuver to PM FRAM release ESP-2 PM FRAM inhibits in place 	<u>REMOVE PM FRAM FROM ESP-2 (00:30)</u>	<u>REMOVE PM FRAM FROM ESP-2 (00:30)</u> <ul style="list-style-type: none"> Rotate PM 	01:00
	<ul style="list-style-type: none"> SSRMS Maneuver to ESP-2 clearance (~00:30 to PLB) 	<u>TRANSFER PM FRAM TO PLB (00:30)</u>	<u>TRANSFER PM FRAM TO PLB (00:30)</u>	
02:00		<u>INSTALL PM FRAM ON LMC (00:30)</u>	<u>INSTALL PM FRAM ON LMC (00:30)</u>	02:00
	<ul style="list-style-type: none"> LMC RRM FRAM inhibits in place 	<ul style="list-style-type: none"> Swap Crew on SSRMS <u>REMOVE RRM FRAM FROM LMC (00:20)</u>	<ul style="list-style-type: none"> Swap Crew on SSRMS <u>REMOVE RRM FRAM FROM LMC (00:20)</u>	
03:00	<ul style="list-style-type: none"> SSRMS Maneuver to EOTP (~00:30) 	<u>TRANSFER RRM FRAM TO EOTP (00:30)</u>	<u>TRANSFER RRM FRAM TO EOTP (00:30)</u>	03:00
	<ul style="list-style-type: none"> EOTP RRM FRAM inhibits in place 	<u>INSTALL RRM FRAM ON EOTP (00:20)</u>	<u>INSTALL RRM FRAM ON EOTP (00:20)</u>	
04:00	<ul style="list-style-type: none"> SSRMS Maneuver to ESP-2 egress position (~00:15) ELC-2 MISSE 8 inhibits in place 	<u>SSRMS CLEANUP (00:45)</u>	<u>MISSE 8 ORMATE-III R/W INSTALL ON ELC-2 (01:20)</u>	04:00
	<ul style="list-style-type: none"> SSRMS Maneuver to park position SSRMS RWS in Backup 	<u>FGB PDGF TROUBLESHOOTING (00:35)</u>		
05:00		<u>PMA3 COVER INSTALL (00:45)</u>	<u>PMA3 COVER INSTALL (00:45)</u>	05:00
06:00		<u>CLEANUP/INGRESS (00:45)</u> <ul style="list-style-type: none"> Cleanup (00:15) Ingress and Pre-Repress (00:30) 	<u>CLEANUP/INGRESS (00:45)</u> <ul style="list-style-type: none"> Cleanup (00:15) Ingress and Pre-Repress (00:30) 	06:00
06:30				06:30

EVA 1 TOOL CONFIG

EV1

- MWS
 - BRT (L)
 - RET (sm-sm)
 - Wire Tie (2 short, 2 long)
 - T-Bar
 - Wire Tie (3)
 - RET (sm-sm)
 - WIF Adapter (w/PIP Pin)
 - RET w/PIP Pin
 - RET (sm-sm) (from COLT & gap spanner stow)
 - Adj Equip Tether (sm-sm) (behind MWS)
 - Adj Equip Tether (sm-sm) (behind MWS)
 - Adj Equip Tether (sm-sm) (Left D-ring)
 - Adj Equip Tether (sm-sm) (Right D-ring)
 - Small ISS Trash Bag
 - (Left/Outer short wire tied – 3 twists)
 - COLT Cap
 - COLT Cap
 - Swing Arm (R)
 - RET (sm-sm)
 - PGT [A4 6.3 ft-lb, CAL, MTL 30.5] s/n _____
 - PGT Battery s/n _____
 - 7/16 (wobble) Socket-6 ext
 - D-ring Extender (2, R & L D-ring)
 - ST Pack (85-ft + 85-ft to R D-ring Ext)
 - Waist Tether (L on D-ring Ext)
 - Waist Tether (R on D-ring, to Crew ST reel)
 - SAFER
 - WVS

NOTE: Prior to use, inspect the following hardware:

- RET cords for fraying
- Inspect Load Alleviating Straps and D-ring Extenders; ref CREW TETHER INSPECTIONS, ISS EVA Tasks Checklist:
 1. MMOD/general damage
 2. Discoloration
 3. Tack Stitching
 4. Red Band
- ISS Trash Bag: Zipper closed
Bristle deformation/damage, after having stowed tools
- BRT joint screws not loose
- COLT sliders in OPEN position
- COLT unlock caps installed, with Velcro & RET

Highlighted items are transferred from Shuttle

Tether Counts: **GREEN RETS**
 RETs (sm-sm) = 16/16 RETs (PIP Pin) = 4/5
 RETs (Lg-sm) = 5/8 Adj Eq Tethers = 10/10 sm; 2/2 Lg

EV2

- MWS
 - BRT (L)
 - RET (sm-sm)
 - Wire Tie (2 short, 2 long)
 - T-Bar
 - Wire Tie (3)
 - RET (sm-sm)
 - RET w/PIP Pin
 - Adj Equip Tether (sm-sm) (behind MWS)
 - Adj Equip Tether (sm-sm) (Fairlead)
 - Adj Equip Tether (sm-sm) (Fairlead)
 - Small ISS Trash Bag
 - (Left/Outer short wire tied – 3 twists)
 - RET w/PIP Pin
 - WIF Adapter (w/PIP Pin)
 - Swing Arm (R)
 - RET (sm-sm)
 - PGT [A4 6.3 ft-lb, CAL, MTL 30.5] s/n _____
 - PGT Battery s/n _____
 - 7/16 (wobble) Socket-6 ext
 - D-ring Extender (2, R & L D-ring)
 - 85-ft Safety Tether (R D-ring Ext) (Anchor – A/L)
 - 85-ft Safety Tether (R D-ring Ext) (Crew – SSRMS)
 - Waist Tether (L on D-ring Ext)
 - Waist Tether (R on D-ring, to Anchor ST reel)
 - SAFER
 - WVS
- RET (Lg-sm) (stays in A/L)
- Adj Equip Tethers (sm-sm) (stays on ORU Bag)
 - Medium ORU Bag (PMA3 Cover)**
 - Gap Spanner (fully extend) (on int tethers) (-307/42"-72")**
 - RET (sm-sm)
 - PMA3 Cover (Cover key near bag flap hinge)**
 - EVA Camera (w/bracket and Int RET)
 - RET (sm-sm)
 - Needle Nose Pliers
- RET (Lg-sm) (stays in A/L)
 - Medium ORU Bag (CLPA)**
 - RET (sm-sm)
 - Square Scoop
 - CLPA
 - RET (sm-sm)
 - Square Scoop (on top, for failed CLPA)

- Adj Equip Tether (sm-sm)
- RET (Lg-sm) (stays in A/L)
 - Crewlock Bag (COLT)**
 - Wire Ties (2 long – 3 twists)
 - COLT (short/aft, used second)**
 - Int RET 1
 - Wire tied closest to bag, along external HR
 - RET (sm-sm) (Cap to COLT)
 - COLT Cap (installed on COLT)**
 - COLT (long/fwd, used first)**
 - Int RET 2
 - Wire tied 2nd to bag, along external HR
 - RET (sm-sm) (Cap to COLT)**
 - (used for gap spanner stow)
 - COLT Cap (installed on COLT)**
 - ERAD w/7/16" socket 2" ext (Int RET 3)
 - (for RRM FRAM contingency bolt down)
 - RET (sm-sm)
 - EVA Camera (w/bracket and int RET)
 - RET (sm-sm)
 - Fisheye Camera (w/bracket and int RET)
 - Adj Equip Tether (sm-sm)
 - RET (Lg-sm) (Stays in A/L)
 - Crewlock Bag (MISSE/Get-ahead)**
 - Wire Ties (1 short, 1 long – 3 twists)
 - Adj Equip Tether (sm-sm) (from internal D-ring around MISSE to HR)
 - MISSE 8 ORMATE (Int RET 1; wire tied to back of bag; configure during pre-breathe)
 - Ratchet w/7/16" socket 2" ext (Int RET 2)
 - RET (sm-sm)
 - EVA Camera (w/bracket and Int RET)
 - Wire Tie Caddy (Int RET 3) (3 short; 6 long)
 - Socket Caddy (Int RET 4)
 - RET (sm-sm)
 - EVA Fisheye Camera (w/bracket and Int RET)
 - RET (Lg-sm) (stays in A/L)
 - Adj Equip Tether (Lg-sm)
 - Adj Equip Tether (Lg-sm)
 - 1553 Data Cable Bag**
 - 1553 Cable
 - Fish Stringer
 - Node 3 Terminator MLI
 - Node 3 Terminator MLI
 - Node 3 Terminator Cap
 - Node 3 Terminator Cap
 - 1553 P1 cap
 - 1553 P2 cap



EVA 1 TOOL CONFIG (Cont)

IV Bag

- Towels (2)
- Contamination Detection Kit
- RET (sm-sm, Black)
 - GP Caddy
 - Adjustable Thermal Mittens (2)
 - GP Caddy
 - Adjustable Thermal Mittens (2)
- RET (sm-sm, Black)
 - Socket Caddy (hatch contingencies)
 - 1/2 Socket-8 ext
 - 7/16 (wobble) Socket-6 ext (spare)
- RET (sm-sm, Black)
 - DCM Plug (SAFER Hardmount) (2)

Staging Bag

- Fish Stringer Tether #1
 - Wire Tie Caddy (6 short; 3 long)
 - Velcro/Tape Caddy
 - PGT s/n _____
 - PGT Battery s/n _____
 - 7/16 (wobble) Socket-6 ext
 - Ratchet Wrench
 - Spare WIF Adapter (w/PIP Pin)
 - Long Duration Tie-Down Tether
 - Long Duration Tie-Down Tether
 - Spare 85-ft Safety Tether
- Fish Stringer Tether #2 (inside tether)
 - Connector Cleaner Tool Kit
 - Pry Bar
 - MWS Key Strap Assy (on wire tie, to strap)
- Crewlock Bag (Tool Relocations) (hook to outside of Staging Bag)**
 - Vise Grips (stbd toolbox) (Int RET 1)
 - Probe (stbd toolbox) (Int RET 2)
 - Pin Straightener Assy (port toolbox) (Int RET 3)
 - Adj Equip Tether (sm-sm) (Int RET 4)
 - Short MMOD T-Handle Tool (port toolbox)
 - Short MMOD T-Handle Tool (port toolbox)
 - RET w/PIP Pin
 - 1" QD Cap Tool (stbd QD Bag)
 - General Purpose Cutters (Large Cutters) (from port toolbox)



EVA 1 BRIEFING CARD

EVA Prep

- Review Morning Timeline/Plan/Tethers
- Work With a Purpose
- Pure O2 Protocol
- Suit Donning Plan – special requests, boot bladder manipulation
- Safer, MWS, Tools, CL, Bag Stowage in A/L
- Airlock Depress Review

Procedure Review

- Egress Plan (tethers)
- Order of Tasks (summary timeline)
- Translation Paths, Fairleads
- Hazards (no touch, no damage, keep outs, notes, cautions, warnings)
 - Opened MISSE PECs – no touch; PEC hinges – pinch point
- Contingencies – section 16
- Task Constraints, Potential Get-aheads
- Ingress Plan

Post EVA

- Suit Doffing
- Tool Reconfig Plan

Emergencies

- Comm Fail (hand signals, Term EVA, Abort EVA)
- EMU Malfunctions
- Lost Tools/Crewmember (velocity and direction)
- DCS
- Safer Ops
- Crew Rescue

Reminders/Top Ten

- Gate Closed, Slider Locked, Tether Reel Unlocked
- Pins Straight, No FOD, Good EMI
- PGT Read-back, Turns and Torque with light
- Worksite Departure – tethers and tools clear
- Move Slow – no hopping (slower is faster)
- Body Position is Everything (use space)
- Tether Awareness – all of them
- Suit/Tool Awareness – BRT/PGT/ORU Stowage
- Suit MAL – read down DCM messages
- Discipline and Attention to detail until the end
- Day/Night Checks (Settings, tools, tethers)

Contingency

I

EVA 1 INHIBIT PAD

Orbiter

ALL EVAs	
TCS (<i>Prior to Egress – Crew</i>) IV L12	1. √TCS POWER – OFF 2. Install Switch Guard to remain in place through EVA
TriDAR (<i>Prior to Egress – Crew</i>) IV L12L (SSP2)	1. √TriDAR POWER – OFF (tb-bp)
KU-Band Antenna (<i>Prior to Egress – INCO</i>) MCC-H	1. √KU-BAND Mask – active 2. √KU-BAND EVA Protect Box – active
RCS (<i>Prior to translation into payload bay – Crew/PROP/GNC</i>) If EV crew < 27 ft from FRCS	
IV O14,15,16	1. √DAP: VERN, FREE, LO Z 2. √RJDF F1, F2, F3, F4 MANF DRIVER (four) – OFF LOGIC (four) – OFF
MCC-H IV	3. √Above RCS config 4. √RCS F – ITEM 1 EXEC (*) √JET DES F1U – ITEM 17 (*) F3U – ITEM 19 (*) F2U – ITEM 21 (*)
LOCATION DEPENDENT INHIBITS	
S-Band Antennas (<i>Prior to translation into payload bay – Crew</i>)	
	NOTE Possible loss of comm when forced LL FWD antenna
IV A1R	If EV crew < 2 ft from S-Band antenna 1. S-BAND FM ANT – XMIT LOWER/RCVR UPPER 2. √ MCC , lower antenna selected
C3	If no comm, or on MCC GO 3. S-BAND PM ANT – LL FWD
C3	When EVA crewmember at least 2 ft away from all S-Band upper antennas 4. S-BAND PM ANT – GPC
TASK SPECIFIC INHIBITS	
Failed PM Install on LMC (<i>Prior to Egress</i>) (No inhibits required)	
RRM Removal from LMC (<i>Prior to Egress – Crew</i>) IV	R1 PL AFT MNC – OFF

USOS (1)

ALL EVAs	
PCU (<i>Prior to Egress – PHALCON</i>)	
	NOTE PCUs may require up to a 1-hr warmup period before they are operational
MCC-H	1. √PCUs (two) operational in discharge mode and one of the following: a. CCS PCU EVA hazard control FDIR enabled b. Only allowed arrays unshunted and oriented < 105° from velocity vector If one or both PCUs failed 2. Only allowed arrays unshunted and oriented < 105° from velocity vector
CUCU (<i>Prior to Egress – Crew</i>) IV – (LAB1O4)	
	1. √cb POWER A, B [two] – OPEN 2. √cb LINK 1,2 [two] – OPEN
MISSE 8 (<i>Prior to Egress – POD</i>) POIC Prior to EV Hatch Open	
	1. ELC-2 ExPA-2 Discrete Channel 6 – Disabled

Ground

ALL EVAs	
Ground Radar (<i>Prior to Egress – TOPO</i>)	
MCC-H	1. √TOPO console, ground radar restrictions in place for EVA

EVA 1 INHIBIT PAD (Cont)

RSOS

ALL EVAs

SM Antennas (*Prior to Egress – RIO*)

- IV
- MCC-M**
1. ARISS (Ham Radio) – Deactivate
 2. GTS – Deactivate
 3. Napor (PCПИ) – Deactivate

JEM

ALL EVAs

ICS-EF Antenna (*Prior to Egress – SSIPC*)

- SSIPC**
1. ICS MOD – OFF
 2. ICS UPC – OFF
 3. ICS HPA – OFF
 4. HPA ON and UPC ON commands are cleared (not present) in the ICS stored command queue

COL

ALL EVAs

HAM Radio (*Prior to Egress – Crew*)

- IV
1. HAM Radio – Deactivate

USOS (2)

LOCATION DEPENDENT INHIBITS

Lab Window (*Prior to Egress – Crew*)

- IV
- If EV crew less than 10 ft from window or in window FOV, close window shutter

Cupola Windows (*Prior to Starting Task – PMA3 Cover Install – Crew*)

- IV
- If EV crew less than 10 ft from window, coordinate shutter opening/closing with EV crew and minimize time shutter is open

Bluetooth Stethoscope (*Prior to Egress – SSIPC*)

- SSIPC**
- If EV crew translating on JEM
1. Electronic Stethoscope – OFF
 2. JEM Medical Laptop – Bluetooth Disabled

Mobile Transporter (*Prior to Egress – ROBO*)

- MCC-H**
- If EV crew < 1.5 meters from MT
1. √MT latched

SPDM (*Prior to Egress – ROBO*)

- MCC-H**
- If EV crew translating or working on SPDM
1. √SPDM in Keep Alive configuration
 2. √PSU – Operational
 3. √SACU1(2) – Operational
 4. √Body Prime(Redundant) – Keep Alive or Off
 5. √SPDM Arm 1(2) – Keep Alive

SSPTS (*Prior to Egress – PHALCON*)

- MCC-H**
- If EV crew working within 2 ft of SSPTS cables
1. RPCM LA2A3B D RPC 1 – Open, Close Cmd Inhibit
 2. RPCM Z14B A RPC 2 – Open, Close Cmd Inhibit
 3. RPCM Z13B A RPC 2 – Open, Close Cmd Inhibit

TASK SPECIFIC INHIBITS

Failed PM Removal from ESP-2 (*Prior to Task – PHALCON*)

- MCC-H**
- RPCM S04B_F RPC 10 Open/Close Inh – PM Heater 1 Pwr
RPCM N1RS2_B RPC 6 Open/Close Inh – PM Heater 2 Pwr

RRM Install on SPDM EOTP (*Prior to Egress – ROBO*)

- MCC-H**
- Verify SPDM PSU Output Bank A(B) Port #7 – OFF (two)

EVA 1 INHIBIT PAD (Cont)

GET-AHEADS

LOCATION DEPENDENT INHIBITS

Starboard TRRJ (*Prior to Egress – ORMatE III Install & FHRC P-Clamps – THOR*)

- MCC-H** If EV crew working within 2 ft of S1 TRRJ rotation envelope
(Includes ELC 4)
1. √DLA 1(2) – LOCKED 0°
 2. √DLA 2(1) – ENGAGED

Port TRRJ (*Prior to EVA – PMA3 Cover Install – THOR*)

- MCC-H** If EV crew working within 2 ft of P1 TRRJ rotation envelope
(Includes Node 3 Port Endcone and PMA3)
1. √DLA 1(2) – LOCKED -45°
 2. √DLA 2(1) – ENGAGED

SSRMS Base B Elbow CLPA (*Prior to Starting Task – ROBO*)

- MCC-H** RPCM S04B C RPC 4 – Open, Close Cmd Inhibit
RPCM S03A C RPC 2 – Open, Close Cmd Inhibit

RSOS (2)

EVA's ON PMA1 OR RSOS (LOCATION DEPENDENT)

RSOS and RSOS Visiting Vehicle Antennas (Includes FGB, SM, DC-1, MRM-1, MRM-2, Progress)

- MCC-M**
1. √KURS P [KYPC P] – Deactivated
 2. √KURS A [KYPC A] – Deactivated

USOS (3)

TASK SPECIFIC INHIBITS (2)

MISSE 8 (*Prior to Starting Task – ORMatE III Install on ELC-2 – POD*)

- POIC** If EV crew working zenith of plane of MISSE 8
1. MISSE-8 PASCAL solar cells – Zero voltage bias
 2. ELC-2 ExPA-2 Discrete Channel 1 – Disabled
 3. ELC-2 ExPA-2 28V Operational Power – Disabled

Starboard SARJ (*Prior to Egress – ORMatE III Install – PHALCON*)

- MCC-H** If EV crew working within 2 ft, outboard of SARJ or reqd per loads
FR (Includes Outboard faces of Outboard ELCs/ESPs)
1. √DLA (1) – LOCKED at 225°
 2. All motor setpoints set to zero
 3. All motors deselected

MCS Configuration (*PM xfer, RRM xfer, ORMatE-III Install – ADCO*)

- MCC-H** When EV on SSRMS w/PM or RRM < 2 ft from structure;
when EV on ELC-2 for ORMatE-III Install
1. √Desat Request – Inh
 2. √Auto Att Control handover to RS – Inh (MOD)

Node 3 J1 FGB and J2 FGB 1553 (*Once SSRMS at Park position and prior to 1553 Get-ahead – ROBO*)

- MCC-H** If any RWS active, cmd 'Active Assert Backup'

FGB PDGF Power (*Prior to 1553 or PDGF Get-ahead – RIO*)

- MCC-M**
1. √RACU-6 – OFF
 2. √RACU-5 – OFF

System power panel (ППС) 313

- RS Crew**
1. √БК Cable 77KM-7228-110-01 – Demated
 2. √БК Cable 77KM-7228-110 – Demated

RSOS (3)

ADDITIONAL ANTENNA INHIBITS FOR EVA's ON RSOS (LOCATION DEPENDENT)

FGB Antennas

- MCC-M**
1. √TORU [ТОРУ] – Deactivated
 2. √TV System [ТВС] – Deactivated
 3. Radiotelemetry [БР-9ЦУ-8] – Deactivate
 4. √TV System [КЛ-108А] – Deactivated
 5. √CNPMS [СИТНП] – Deactivated
 6. √КОМПАРУС [КИС] – Deactivated

EVA 1 NOTES/CAUTIONS/WARNINGS

NOTES

1. Bolt install: Report torque and turns
2. Bolt release: Report torque and turns if different from published range
3. EVA connectors: After disconnection and prior to connection; verify pin and EMI band integrity; verify connector free of FOD
4. Inspect QDs for damage prior to mating
5. Toolbox doors must be closed with one latch per door when EV crew not in immediate vicinity
6. 85-ft safety tether retract force may affect body positioning
7. CETA Cart brake handle wire ties must be replaced after crew loading
8. For HTV N/C/W refer to 6.100.180 HTV NOTES, CAUTIONS, & WARNINGS (SODF: EVA TASK)

CAUTION

ISS Generic Constraints

- A. Avoid inadvertent contact with
 1. Grapple fixture shafts (drylube)
 2. PIP pins
 3. Passive UMAs
 4. MBS/SSRMS/SPDM taped radiative surfaces: VDU, ACU, JEU, LEU, MCU, CRPCMs, and Cameras
 5. SPDM SJEU, EP, OTCM, LEU, and LEE VDU radiator surfaces
 6. OTSD
- B. Electrical cables
 1. Avoid bend radii < 10 times cable diameter
- C. Fiber optic cables
 1. Avoid bend radii < 10 times cable diameter
 2. Avoid pulling on cable during mate/demate
- D. Fluid line flex hoses and QDs
 1. Avoid bend radii < 14 in for hoses with a diameter \geq 1 in
 2. Additional care should be taken to not exceed bend radii when applying loads at the flexible hose to rigid tube stub interfaces
 3. Ensure fluid QD booties are fully closed prior to leaving worksite; wire tie if reqd
 4. Avoid bend radii < 5 in for hoses with diameter < 1 in on LAB, S0, S1, P1, and 10 in for hoses with diameter < 1 in on all other elements

CAUTION

ISS Generic Constraints (Cont)

- E. For structural reasons
 1. Avoid vigorous body motions, quick grabs and kickoffs against tether restraints
 2. Avoid performing shaking motions (sinusoidal functions) more than four cycles
- F. Other
 1. ITT Cannon connector: On demated connectors, do not rotate collar or manipulate cable/connector using collar or connector tool
 2. MLI handholds are not rated for crewmember translation loads

EVA 1 NOTES/CAUTIONS/WARNINGS (Cont)

CAUTION

ISS Truss Constraints

A. Avoid inadvertent contact with

1. CETA lights (Z-93 paint) [LAB,S1,S3,NODE 1]
2. Deployed TUS cable [Zenith and Nadir CETA rails]
3. S0 aft face radiator
4. GPS antennas (S13 paint) [S0,JLP]
5. UHF antennas [LAB,P1]
6. ETCS radiator flexhoses and panels [S1,P1]
7. EETCS/PV radiator flexhoses, bellows and panels [P6,P4,S4,S6]
8. SASA RF group [S1,P1]
9. Heat pipe radiators [Z1]
10. PCU cathode and HCA ports [Z1]
11. Ku-Band antenna (SGANT) dish [Z1]
12. CMG cover/shells [Z1]
13. FPMU [P1]
14. SASA high and low gain antennas and radiator surfaces [Z1]
15. Deployed MISSEs
16. OTP on HAB Tray [S0]
17. OBSS composite sections, striker bars, grapple fixture shafts, and cable harnesses

B. For structural reasons

1. Avoid kicking S1/P1 radiator beam. If any of these occur, wait 2 to 5 min to allow structural response to dissipate

CAUTION

ISS Truss Constraints (Cont)

C. Other

1. WIS antennas: Do not use as handholds [NODE 1,LAB,P6,Z1]
2. Lubricant from Ku-Band SGANT gimbals [Z1], CMGs [Z1], and RTAS ground strap fasteners [P6,P4,S4,S6] can contaminate EMU
3. Prevent inadvertent contact of the tether shuttle with ETRS when the S3/P3 tether shuttle stop is raised away from the rail

CAUTION

ISS U.S. Pressurized Elements Constraints

A. Avoid inadvertent contact with

1. EVA crane [PMA1]
2. TCS reflectors [PMA2,PMA3]
3. APAS hardware [PMA2,PMA3]
4. CETA lights (Z-93 paint) [LAB,S1,S3,NODE 1]
5. UHF antennas [LAB,P1]
6. Open CBM petal covers, LAB and Cupola window shutters
7. S0/NODE 2 fluid tray hardlines at NODE 2 end, which are limited to 25 lb

B. Other

1. WIS antennas: Do not use as handholds [NODE 1,LAB,P6,Z1]
2. CBM petal covers may not be used as handholds unless both launch restraint pins are engaged

EVA 1 NOTES/CAUTIONS/WARNINGS (Cont)

CAUTION

ISS I.P. Elements Constraints

COL

- A. Avoid inadvertent contact with
1. COL ARISS and AIS antennas [COL-Nadir]

JEM

- A. Avoid inadvertent contact with
1. GPS antennas (S13 paint) [S0,JLP]
 2. Open JPM window shutter
 3. JTVE, WVE/EVE, JEF VE cameras
 4. JEMRMS taped radiative surfaces [JEU,EE,Cameras]
 5. JEM A/L target and pins
 6. JEF ORUs and EFUs (paint and lubricant)
 7. MAXI front and top panel (paint)
 8. SEDA-AP sensors (HIT, SDOM, and AOM)
 9. Trunnions and UCMs (paint and lubricant) [JEF Payloads]
 10. RAIDS covers on end of HREP
 11. ICS-EF Ka-Band antenna dish
 12. Small Fine Arm (SFA) (paint, coating and lubricant)
- B. For structural reasons
1. Avoid kicking MMOD shields between JLP and JPM
 2. Avoid tool impact on ICS-EF sensor

CAUTION

Shuttle Constraints

- A. Avoid inadvertent contact with
1. OBSS and SRMS composite sections joint torque arms, grapple fixture shafts, and cable harnesses
 2. LCS (silver Teflon) and LDRI (silver Teflon) and ITVC (gold foil) [OBSS]
 3. WVS antenna [ODS truss and PLB sill]
 4. Payload bay and camera wire harnesses, cables, cable guides, and connectors
 5. OBSS striker bars (drylube)
- B. No touch
1. LDRI diffuser [OBSS]
 2. OBSS saddle contacts (when OBSS unberthed) [OBSS]
 3. Monkey fur [PLB]
 4. Cameras: Metallic surfaces [PLB]
 5. Ku-Band antenna black dish and gold thermal blankets [PLB]

EVA 1 NOTES/CAUTIONS/WARNINGS (Cont)

WARNING

ISS Generic Constraints

- A. Avoid inadvertent contact with
1. Grapple fixture targets and target pins
- B. Pinch
1. NZGL connector linkage. Use caution when mating/locking
 2. ITT Cannon connector rotating housing
 3. PDGF connector doors
- C. QDs
1. If QD is in FID when valve is opened (bail fwd), QD will leak and fluid line may whip
 2. Do not rotate if in mated/valve open configuration
 3. Bail may kick back suddenly when detent button is depressed if pressure has built up in spring cavity
- D. Sharp Edges
1. Inner edges of WIF sockets
 2. APFR active WIF probes
 3. Mating surfaces of EVA connectors
Avoid side loads during connector mating
 4. Back side of MMOD shield fasteners
 5. Spring loaded captive EVA fasteners (e.g., 6B-boxes, BMRRM, RTAS, SARJ Covers); the end of the spring may protrude
 6. SPDM OTCM gripper jaws
 7. Keep hands away from SSRMS LEE/POA/SPDM LEE opening, snares, and PDGF curvic coupling (teeth)
 8. MMOD strikes on ISS exterior

WARNING

ISS Generic Constraints (Cont)

- E. Thermal
1. EVA connectors with booties may become hot if left uncovered.
Handling may need to be limited
 2. Turn off glove heaters when comfortable temperature reached to prevent bladder damage. Do not pull fingers out of gloves when heaters are on
 3. Uncovered trunnion pins may be hot
 4. SSRMS/MBS/SPDM operating cameras and lights may radiate large amounts of heat
 5. Do not touch EMU protective visor if temperature has been < -134 degF for > 15 min
 6. No EMU boot contact with foot restraint when temperature < -120 degF or > 200 degF
 7. PDGF surfaces may not meet touch temperature requirements for unlimited contact when $\beta \leq -70$ or $\beta \geq 70$

WARNING

ISS Truss Constraints

- A. Avoid inadvertent contact
1. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off
 2. Stay inboard of SARJ when active
 3. Stay 2 ft from S1/P1 radiator beam rotational envelope when beam is free to rotate
 4. Stay 5 ft from moving MT on face 1
 5. Stay 3.3 ft from Ku-Band (SGANT antenna) when powered
 6. Stay 1 ft from top of STP-H3 (ELC-3)
 7. Deployed MISSEs and ORMatE-III R/W
- B. RF Radiation Exposure
1. Stay 3.8 ft from S-Band (SASA) high gain antenna when powered [S1,P1]
 2. Stay 1.3 ft from S-Band (SASA) low gain antenna when powered [S1,P1]
 3. Stay 1 ft from UHF antenna when powered [LAB,P1]
- C. Sharp Edges
1. Solar array blanket box [P6,S6]
 2. Fastener threads on back of Z1 U-jumper male FQD panel, if nutplate cap missing
 3. Outboard MT rail attachment lug near P6 handrail 5333 and gap spanner
 4. P2 connector on EWIS box TAA-06 [Zenith/Forward Corner 1 of P5 – SARJ at 0 deg]

EVA 1 NOTES/CAUTIONS/WARNINGS (Cont)

WARNING

ISS Truss Constraints (Cont)

C. Sharp Edges (Cont)

5. Nickel coated braided copper ground straps may contain frayed wires [P6,P4,S4,S6]
6. MMOD strikes on Z1 toolboxes
7. POA FSE (CSA Logo below MBS Mast Camera)
8. AMS Star Trackers

D. Electrical Shock

1. Stay \geq 2 ft from ungrounded floating connectors if powered
S0 EVA power cables (inside S0 Bay 00 Face 4, Bay 01 Face 3)
ESP-2 jumper (inside S0 Bay 03 Face 4)

E. Thermal

1. ELC may exceed touch temperatures when $\beta > 75$ deg

WARNING

ISS U.S. Pressurized Elements Constraints

A. Handrails

1. Handrails previously used for MISSE attachment may not be used as a safety tether point [A/L endcone 564 and 566, A/L Tank 2 Nad/Fwd and Port/Fwd, P6 5389]

B. Pinch

1. EV side of IV Hatch during Hatch operation (also snag hazard) [A/L]
2. LAB and Cupola window shutters and CBM petal cover linkages during operation

C. RF Radiation Exposure

1. Stay 1 ft from UHF antenna when powered [LAB,P1]

D. Sharp Edges

1. PMA umbilical launch restraints – exposed bolt threads
2. Adjustable fuse tether (Fish Stringer) buckles stowed in Node bag
3. Port/Aft portion of A/L circular HR [HR 0506]
4. A/L HR 0537 (Eq Lock Zenith)
5. ESP-2 HR 8012
6. PMM ROEU and ROFU panels (zenith endcone)

E. Thermal

1. PMA handrails may be hot. Handling may need to be limited.
2. Stay \geq 1 ft away from PMAs and MMOD shields > 270 degF if EMU sun visor up; limit time to 15 min or less if > 300 degF

WARNING

ISS U.S. Pressurized Elements Constraints (Cont)

E. Thermal (Cont)

3. Stay at least 0.5 ft away from PMA and MMOD shields > 325 degF
4. No EMU TMG contact with PMAs and MMOD shields > 320 degF

F. Electrical Shock

1. Stay \geq 2 ft from ungrounded floating connectors if powered. SSPTS connectors include NOD1 Stbd/Fwd HR 0130, LAB Stbd/Fwd HR 0273, PMA2 Stbd

G. Fluid QDs

1. Do not translate on gap spanners restraining NODE 3 – LAB NH3 jumpers

EVA 1 NOTES/CAUTIONS/WARNINGS (Cont)

WARNING

ISS I.P. Elements Constraints

COL

- A. Avoid inadvertent contact with
1. SOLAR [COL EPF]

B. Thermal

1. Columbus end cones may violate touch temperature constraints when $-75 \leq \beta \leq -60$ or $60 \leq \beta \leq 75$

JEM

- A. Avoid inadvertent contact with
1. ICS-EF sensors

B. Pinch

1. JPM window shutter linkages during operation
2. JEM cameras (JVTEs, EVE, WVE, and JEF VEs)
3. JEM EFU latching arms
4. JEF SSE latch
5. ICS-EF antenna boom
6. SEDA-AP mast
7. SMILES antenna rotating area
8. HREP hinge sides and RAIDS pinch areas
9. JEMRMS EE
10. JEMRMS Small Fine Arm (SFA) joints and booms

WARNING

ISS I.P. Elements Constraints (Cont)

JEM (Cont)

C. Sharp Edges

1. Interior of JEMRMS HRMs
2. JEMRMS EE opening and snares
3. JEM A/L hatch corners
4. ICS-EF AHM gears
5. MAXI visual star camera
6. SMILES baffles (two), baffle base bare bolts, and Cold Sky Terminator (CST)
7. HREP baffles (four) [Star tracker aperture Zenith and three instrument baffles Aft]
8. SFA Electro-Mechanical GF (EMGF)

D. RF Radiation Exposure

1. Stay 0.3 ft from Fwd/Aft JPM PROX antenna

E. Thermal

1. JPM Port End Cones and JLP Port Nadir may violate touch temperature constraints when $\beta > 60$ deg
2. JEMRMS/JTVE/JEFVE operating cameras and lights may radiate large amounts of heat

WARNING

Shuttle Constraints

A. Arcing/Molten Debris

1. Stay ≥ 2 ft from exposed EFGF connector when OBSS berthed, powered, and EFGF not grappled [PLB]
2. Stay ≥ 2 ft from exposed Stbd Fwd MPM contacts [PLB]
3. Stay above PLB sill when within 1 ft of powered ROEU connector [PLB]

B. Pinch

1. PRLA operation [PLB]

C. RF Radiation Exposure

1. Stay 3.28 ft from S-Band antenna when powered
2. Stay 1 ft from top and side of UHF PLB antenna radome surface when in high powered mode [ODS truss]
3. Stay 0.33 ft from top and side of UHF PLB antenna radome surface when in low powered mode [ODS truss]
4. Remain below the level of the PLB door mold line for first 20 in Aft of Fwd bulkhead when S-Band antenna powered [PLB]
5. Remain on the inboard side of the Stbd slidewire (sill handrails if slidewire not installed) for first 20 ft Aft of Fwd bulkhead when Ku-Band antenna powered [PLB]

EVA 1 NOTES/CAUTIONS/WARNINGS (Cont)

WARNING

Shuttle Constraints (Cont)

D. Sharp Edges

1. PRLA grounding wipers [PLB]
2. LDRI baffles (also an entrapment hazard) [OBSS]
3. Keep hands away from SRMS EE opening and snares
4. TCS connector backshells have exposed threads [ODS]

E. Thermal

1. Illuminated PLB lights; do not touch
2. OBSS grapple fixture shafts/cams may be hot. Limit handling if required
3. Stay 27 ft from PRCS when powered
4. Stay 3 ft from VRCS when powered
5. Stay 3 ft from APU when operating


F. Contamination

1. Stay out of the immediate vicinity of leaking jet or APU




G. Lasers

1. Do not look at LDRI diffuser or LCS laser aperture window

EVA 1 EGRESS/SETUP (01:00)

IV/SSRMS	EV1	EV2
 <p>1. Start Hatch Thermal Cover clock PET (30 min) ___ : ___</p> <p>2. Post crew egress: WVS Software: Select page – RF camera Sel ‘Advanced Controls’ S-Band Level (two) – Max</p> <p>3. Stop Hatch Thermal Cover clock PET (30 min) ___ : ___</p>	<p>Initial Configuration:</p> <ol style="list-style-type: none"> √All gates closed & hooks locked <ul style="list-style-type: none"> <input type="checkbox"/> L Waist Tether to A/L internal D-ring extender <input type="checkbox"/> L Waist Tether to D-ring extender <input type="checkbox"/> R Waist Tether to crew tether reel <input type="checkbox"/> R Waist Tether to D-ring <input type="checkbox"/> Green hook to crew ST reel <input type="checkbox"/> Anchor hook to MWS <input type="checkbox"/> Red hook to R D-ring extender <input type="checkbox"/> Yellow hook to anchor tether reel <p><u>EGRESS</u> (00:15)</p> <ol style="list-style-type: none"> ← Open hatch thermal cover Egress A/L Attach EV1 anchor hook to aft external D-ring <ul style="list-style-type: none"> <input type="checkbox"/> √Bail closed, slider locked, double locked, reel unlocked Release Waist Tether from internal D-ring extender Temp stow COLT Crewlock Bag on BRT Attach EV2 anchor hook to fwd external D-ring <ul style="list-style-type: none"> <input type="checkbox"/> √Bail closed, slider locked, double locked, reel unlocked Verify SAFER config <ul style="list-style-type: none"> <input type="checkbox"/> √L handle down (MAN ISOL Vlv – Open) <input type="checkbox"/> √R handle down, door closed (HCM – Closed) √WVS – green LED Perform translation adaptation 	<p>Initial Configuration:</p> <ol style="list-style-type: none"> √All gates closed & hooks locked <ul style="list-style-type: none"> <input type="checkbox"/> L Waist Tether to UIA fwd D-ring <input type="checkbox"/> L Waist Tether to D-ring extender <input type="checkbox"/> R Waist Tether to A/L tether reel <input type="checkbox"/> R Waist Tether to D-ring <input type="checkbox"/> Green hook to R D-ring extender <input type="checkbox"/> A/L 85-ft ST anchor hook to COLT C/L Bag <input type="checkbox"/> Red hook to R D-ring extender <input type="checkbox"/> Yellow hook to MWS <input type="checkbox"/> Lg-sm RET to UIA aft D-ring (<i>for COLT Crewlock Bag upon ingress</i>) <p><u>EGRESS</u> (00:15)</p> <ol style="list-style-type: none"> Transfer COLT Crewlock Bag with anchor hook attached to EV1 Release Waist Tether from UIA D-ring; egress A/L Verify SAFER config <ul style="list-style-type: none"> <input type="checkbox"/> √L handle down (MAN ISOL Vlv – Open) <input type="checkbox"/> √R handle down, door closed (HCM – Closed) √WVS – green LED ← Close hatch thermal cover Perform translation adaptation

EVA 1 EGRESS/SETUP (01:00) (Cont)

IV/SSRMS	EV1	EV2
<div data-bbox="191 313 583 367" style="border: 1px solid black; padding: 2px; margin-bottom: 5px;">Both "U" brackets engage HR</div>  <p data-bbox="100 630 621 695">4. SSRMS: GCA as required for ST install</p> <div data-bbox="107 699 615 753" style="border: 1px solid black; padding: 2px; margin-bottom: 5px;">Two lines visible after slider installation</div>  <div data-bbox="107 951 615 1005" style="border: 1px solid black; padding: 2px; margin-bottom: 5px;">Both slider paddles popped up</div> <p data-bbox="100 1005 621 1070">5. SSRMS: Maneuver to APFR Install position</p> <p data-bbox="100 1070 621 1151">6. SSRMS: Notify EV: Brakes on, ready for APFR install</p> <div data-bbox="107 1151 615 1425">  <div data-bbox="432 1151 615 1317" style="border: 1px solid black; padding: 2px; margin-left: 5px;">Washer flush w/end of contingency pin housing</div> </div>	<div data-bbox="701 272 1213 415" style="border: 3px double black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>WARNING</u></p> <p style="text-align: center;">Stay 1 ft from UHF Antenna</p> <hr style="border: 0.5px solid black;"/> <p style="text-align: center;">Avoid contact with sharp edge on ESP-2 HR 8012</p> </div> <p data-bbox="621 448 1304 480"><u>INSTALL COLTS</u> (00:45)</p> <ol style="list-style-type: none"> <li data-bbox="621 480 1304 513">1. Translate to ESP-2 aft/port (low road) <li data-bbox="621 513 1304 578">2. Stow Crewlock Bag on ESP-2 HR 8015 (aft/port/zenith) <li data-bbox="621 578 1304 643">3. Release gap spanner between Lab and ESP-2, stow with RET <li data-bbox="621 643 1304 675">4. Retrieve long COLT from Crewlock Bag <li data-bbox="621 691 1304 886">5. Install Long COLT onto FRAM (ISS fwd) <ul style="list-style-type: none"> <li data-bbox="684 724 1304 756"><input type="checkbox"/> √Both "U" brackets engage HR <li data-bbox="684 756 1304 789"><input type="checkbox"/> √Two lines visible after slider installation <li data-bbox="684 789 1304 821"><input type="checkbox"/> √Both slider paddles popped up <li data-bbox="684 821 1304 886"><input type="checkbox"/> √Washer flush w/end of contingency pin housing (gap < washer thickness OK) <li data-bbox="621 1000 1304 1032">6. Remove COLT cap, stow in trash bag <li data-bbox="621 1032 1304 1065">7. Retrieve RET from COLT cap, stow on MWS <li data-bbox="621 1097 1304 1325">8. Retrieve short COLT from C/L Bag; install onto FRAM (ISS aft) <ul style="list-style-type: none"> <li data-bbox="684 1162 1304 1195"><input type="checkbox"/> √Both "U" brackets engage HR <li data-bbox="684 1195 1304 1227"><input type="checkbox"/> √Two lines visible after slider installation <li data-bbox="684 1227 1304 1260"><input type="checkbox"/> √Both slider paddles popped up <li data-bbox="684 1260 1304 1325"><input type="checkbox"/> √Washer flush w/end of contingency pin housing (gap < washer thickness OK) <li data-bbox="621 1341 1304 1373">9. Remove COLT cap, stow in trash bag <li data-bbox="621 1373 1304 1406">10. Retrieve RET from COLT cap, stow in Crewlock Bag 	<div data-bbox="1381 272 1894 415" style="border: 3px double black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>WARNING</u></p> <p style="text-align: center;">Stay 1 ft from UHF Antenna</p> <hr style="border: 0.5px solid black;"/> <p style="text-align: center;">Avoid contact with sharp edge on ESP-2 HR 8012</p> </div> <p data-bbox="1304 448 1999 480"><u>SSRMS SETUP</u> (00:45)</p> <ol style="list-style-type: none"> <li data-bbox="1304 480 1999 513">1. Translate to ESP-2 fwd (high road) <li data-bbox="1304 626 1999 659">2. GCA SSRMS as required for ST install <div data-bbox="1381 691 1894 756" style="border: 1px solid black; padding: 2px; margin: 5px 0;"> <p style="text-align: center;"><u>NOTE</u></p> <p style="text-align: center;">Monitor clearance to AGB on FHRC</p> </div> <ol style="list-style-type: none"> <li data-bbox="1304 789 1999 886">3. Safety Tether swap to SSRMS LEE HR <ul style="list-style-type: none"> <li data-bbox="1381 821 1999 886"><input type="checkbox"/> √Bail closed, slider locked, double locked, reel unlocked <li data-bbox="1304 886 1999 919">4. Attach green hook onto ESP-2 HR 8011 _____ <li data-bbox="1304 1000 1999 1065">5. Give SSRMS GO for maneuver to APFR Install position <li data-bbox="1304 1097 1999 1195">6. On SSRMS GO, install WIF Adapter into SSRMS PFR socket with tether point toward LEE (PIP Pin required; not hitch pin)

EVA 1 EGRESS/SETUP (01:00) (Cont)





IV/SSRMS	EV1	EV2
<p>7. SSRMS: Maneuver to APFR ingress position</p> <p>8. SSRMS: Notify EV: Brakes on, ready for APFR ingress</p> <p>9. SSRMS: Maneuver to PM FRAM release</p> <p>10. <input checked="" type="checkbox"/> MCC-H – ESP-2 PM FRAM inhibits in place</p> <p>11. Start MBSU thermal clock PET (8-hr) ____ : ____</p>	<p>11. Verify PM clear of structure for release and SSRMS maneuver (port & aft sides)</p> <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> Fwd COLT clear of gap spanner <input type="checkbox"/> <input checked="" type="checkbox"/> Aft COLT clear of ESP-2 bracket <p>12. <input checked="" type="checkbox"/> EV2 heels engaged in APFR</p>	<p>7. Retrieve APFR from ESP-2 WIF 6 (fwd by PM)</p> <p>8. Install APFR into WIF Adapter [12, NN, F, 6]</p> <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> Locking collar black-on-black, pull & twist test <p>9. Extend and lock APFR Ingress Aid handle</p> <div style="border: 2px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">WARNING</p> <p style="text-align: center;">Extended APFR Ingress Aid handle may exceed EVA touch temperature limits</p> </div> <p>10. Give SSRMS GO for maneuver to APFR ingress position</p> <p>11. On SSRMS GO, attach local tether and ingress APFR</p> <p>12. Check Ingress Aid snug against body; PM clear for release</p> <p>13. Give SSRMS GO for maneuver to PM FRAM release</p> <p>14. Inspect gloves</p>

REMOVE PM FRAM FROM ESP-2 (00:30)

|

IV/SSRMS	EV1	EV2
<ol style="list-style-type: none"> 1. SSRMS: Maneuver to PM yaw position 2. SSRMS: Notify EV: Ready for AFRAM 90° yaw 3. SSRMS: Maneuver to ESP-2 clearance (~00:30 to PLB) 4. SSRMS: Notify EV: Ready to roll AFRAM 180° 5. SSRMS: Continue maneuver to PLB 	<p><u>REMOVE PM FRAM FROM ESP-2 (00:30)</u></p> <ol style="list-style-type: none"> 1. Translate to PM FRAM primary bolt 2. Engage PGT socket into both forward contingency pins on PM FRAM and verify anti-rotation device can be defeated 3. Position for driving primary bolt; BRT on HR 8018; local tether on 8023 4. Assist EV2 with attaching RET to AFRAM 5. Verify PM clear of structure for release and SSRMS maneuver (stbd & fwd sides) 6. Configure PGT <ul style="list-style-type: none"> ☐ [A4-TBD, CCW2, 30.5], 6" ext 7/16" 7. On EV2 GO, release FRAM primary bolt, expect 11.1 turns to hard stop (Push ~10 lb to release locking tabs) 8. ✓Status indicator "in" 9. Stow PGT 10. Visually verify AFRAM is clear; assist EV2 with maneuver to ESP-2 stbd 11. Monitor clearance of PM to ESP-2 ORUs 12. Assist EV2 with AFRAM rotation 13. Retrieve COLT Crewlock Bag from ESP-2 HR 8015, stow on BRT 14. Inspect gloves 	<p><u>REMOVE PM FRAM FROM ESP-2 (00:30)</u></p> <ol style="list-style-type: none"> 1. Attach two RETs in series to AFRAM handrail (near primary bolt); keep lock box near EV2 2. Configure PGT (<i>for install at LMC</i>) <ul style="list-style-type: none"> ☐ [A4-TBD, CW2, 30.5], 6" ext 7/16" 3. Stow PGT 4. Open PM MLI for access to PM handrails 5. Configure for maneuver (visor, cooling, glove heaters) 6. Hold AFRAM handrails and give EV1 GO to release 7. Lift AFRAM from PFRAM 8. Give SSRMS GO for maneuver to PM yaw position 9. On SSRMS GO, rotate AFRAM 90° yaw for SSRMS maneuver 10. Lock one of RETs in series to AFRAM 11. Give SSRMS GO for maneuver to ESP-2 clearance 12. On SSRMS GO, roll AFRAM 180° (PM near legs) 13. Give SSRMS GO to continue to PLB

TRANSFER PM FRAM TO PLB (00:30)

IV/SSRMS	EV1
<p>1. ✓MCC-H – Put Orbiter S-band inhibits in place (before EV1 translates onto Node 2 forward)</p>  	<p><u>TRANSLATE TO PLB (00:30)</u></p> <ol style="list-style-type: none"> 1. Translate forward along HR path just starboard of window, past window to Lab HR 265, then to HR 297 (EWIS antenna) 2. Translate port between SPDM and SSRMS base LEE to gap spanner between Lab and Node 2 HR 364 3. Translate forward along Node 2 between JEM endcone and MPLM to Node 2 forward endcone HR 308 4. Translate down Node 2 HR 323 to Node 2 HR 306 5. Attach green hook onto Node 2 HR 306 _____ <input type="checkbox"/> ✓Bail closed, slider locked, double locked, reel unlocked 6. Translate to port TSA; attach Adjustable Tether fairlead <div style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p>CAUTION Avoid contact with Payload Bay cameras</p> </div> <ol style="list-style-type: none"> 7. Translate aft to LMC; attach Adjustable Tether fairlead on LMC port/fwd HR 8. Translate to support position for PM install (clearance calls on aft bulkhead, specifically watch for WVS receiver antenna cable)
<p>2. ✓MCC-H – Reconfigure Orbiter S-band inhibits (after EV1 translates past PMA1)</p> 	

INSTALL PM FRAM ON LMC (00:30)


IV/SSRMS	EV1	EV2				
<p style="text-align: center;"><u>NOTE</u> No inhibits required for PM installation onto LMC</p> <p>1. SSRMS: GCA as required to PM install position</p> <p>2. Record PM FRAM bolt data:</p> <table border="1" data-bbox="163 446 535 511"> <thead> <tr> <th>Turns</th> <th>Torque (ft-lb)</th> </tr> </thead> <tbody> <tr> <td>(11.2)</td> <td>(6.3)</td> </tr> </tbody> </table> <p>3. IV: <input checked="" type="checkbox"/> WVS close-out imagery of PM on LMC</p> <p>4. SSRMS: Maneuver to crew swap</p> <p>5. SSRMS: Notify EV: Brakes on, ready for APFR egress/ingress</p>	Turns	Torque (ft-lb)	(11.2)	(6.3)	<p><u>INSTALL PM FRAM ON LMC (00:30)</u></p> <p>1. Assist EV2 with AFRAM rotation and installation</p> <p>2. GCA SSRMS as required to PM install position</p> <p>3. When aligned and seated on PFRAM, give EV2 GO to drive primary AFRAM bolt</p> <p>4. Verify PM MLI is configured for return</p> <p>5. Verify COLTs are configured for return</p> <p>6. Inspect gloves</p> <p>7. Translate to starboard side of EV2</p> <div style="border: 3px double black; padding: 5px; text-align: center; margin: 10px 0;"> <p>WARNING Only the two handrails on LMC zenith near PM are certified for safety tethering (handrails on fwd edge are not certified)</p> </div> <p>8. Attach Waist Tether to stbd/top LMC HR <input type="checkbox"/> <input checked="" type="checkbox"/> Large hook – Bail closed, slider locked <input type="checkbox"/> <input checked="" type="checkbox"/> Small hook – Bail closed, slider locked</p> <p>9. Move EV1 ST (red hook) to EV2 R D-ring extender (EV2 now on ST Pack) <input type="checkbox"/> <input checked="" type="checkbox"/> Bail closed, slider locked, double locked, reel unlocked</p> <p>10. Retrieve EV2 red hook and attach to EV1 R D-ring extender (EV1 ST now on SSRMS) <input type="checkbox"/> <input checked="" type="checkbox"/> Bail closed, slider locked, double locked, reel unlocked</p> <p>11. Retrieve Waist Tether</p>	<p><u>INSTALL PM FRAM ON LMC (00:30)</u></p> <p>1. Position AFRAM for installation on PFRAM</p> <p>2. Verify PGT settings: <input type="checkbox"/> [A4-TBD, CW2, 30.5]</p> <p>3. On EV1 GO, engage primary AFRAM bolt, expect 11.2 turns to hard stop (Push ~10 lb to release locking tabs)</p> <p>4. <input checked="" type="checkbox"/> Status indicator “out”</p> <p>5. Perform pull test on AFRAM</p> <p>6. Retrieve two RETs from AFRAM</p> <p>7. Verify PM MLI is configured for return</p> <p>8. Inspect gloves</p> <p>9. <input checked="" type="checkbox"/> WVS close-out imagery of PM in return config</p> <p>10. After attaching EV1 ST to EV2, provide EV1 with EV2 red hook</p> <p>11. Give SSRMS GO for maneuver to crew swap</p> <p>12. On SSRMS GO, egress SSRMS</p>
Turns	Torque (ft-lb)					
(11.2)	(6.3)					

REMOVE RRM FRAM FROM LMC (00:20)



IV/SSRMS	EV1	EV2
<p>1. <input checked="" type="checkbox"/> MCC-H – LMC RRM FRAM inhibits in place</p> <p>2. SSRMS: Maneuver to RRM FRAM release</p> <p>3. SSRMS: Maneuver to LMC back away</p> <p>4. SSRMS: Maneuver to EOTP (~00:30)</p>	<p><u>REMOVE RRM FRAM FROM LMC (00:20)</u></p> <div data-bbox="703 300 1243 441" style="border: 3px double black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>WARNING</u></p> <p>To avoid sharp edges, entrapments, and sensitive hardware, limit contact to FRAM, EVA handrails, and microfixtures</p> </div> <div data-bbox="703 479 1201 604" style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Do not touch Z-93 paint on RRM back radiator and avoid kicking top, front, and left faces (relative to FRAM primary bolt)</p> </div> <ol style="list-style-type: none"> 1. Attach local tether and ingress SSRMS APFR 2. Check Ingress Aid snug against body 3. Give SSRMS GO for maneuver to RRM FRAM release 4. Attach two RETs in series to AFRAM handrail, lock one RET 5. Configure PGT <ul style="list-style-type: none"> <input type="checkbox"/> [A4-TBD, CCW2, 30.5], 6" ext 7/16" 6. On EV2 GO, release FRAM primary bolt, expect 11 turns to hard stop (Push ~10 lb to release locking tabs) 7. <input checked="" type="checkbox"/> Status indicator "in" 8. Configure PGT (<i>for install at EOTP</i>) <ul style="list-style-type: none"> <input type="checkbox"/> [A4-TBD, CW2, 30.5], 6" ext 7/16" 9. Stow PGT 10. Configure for maneuver (visor, cooling, glove heaters, BRT) 11. Lift AFRAM from PFRAM 	<p><u>REMOVE RRM FRAM FROM LMC (00:20)</u></p> <div data-bbox="1390 300 1929 441" style="border: 3px double black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>WARNING</u></p> <p>To avoid sharp edges, entrapments, and sensitive hardware, limit contact to FRAM, EVA handrails, and microfixtures</p> </div> <div data-bbox="1390 479 1887 604" style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Do not touch Z-93 paint on RRM back radiator and avoid kicking top, front, and left faces (relative to FRAM primary bolt)</p> </div> <ol style="list-style-type: none"> 1. <input checked="" type="checkbox"/> EV1 heels engaged in APFR 2. Translate into position (port) to support RRM FRAM removal <div data-bbox="1381 755 1894 820" style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;"><u>CAUTION</u></p> <p style="text-align: center;">Avoid contact with Payload Bay cameras</p> </div> <ol style="list-style-type: none"> 3. Hold AFRAM handrails and give EV1 GO to release 4. Visually verify AFRAM is clear <ul style="list-style-type: none"> <input type="checkbox"/> <input checked="" type="checkbox"/> Safety Tether routing 5. Give SSRMS GO for maneuver to LMC back away 6. Inspect gloves

TRANSFER RRM FRAM TO EOTP (00:30)

I

IV/SSRMS	EV2
<ol style="list-style-type: none">1. <input checked="" type="checkbox"/> MCC-H – Put Orbiter S-band inhibits in place (before EV1 translates onto ODS)2. IV: Tool Inventory3. <input checked="" type="checkbox"/> MCC-H – Reconfigure Orbiter S-band inhibits (after EV1 translates past Node 2 forward)	<p><u>TRANSLATE TO EOTP (00:30)</u></p> <ol style="list-style-type: none">1. Retrieve both Adjustable Tether fairleads<ul style="list-style-type: none"><input type="checkbox"/> LMC<input type="checkbox"/> Port TSA2. Tool Inventory3. Translate to Node 2 HR 3064. Retrieve green hook; attach to crew tether<ul style="list-style-type: none"><input type="checkbox"/> <input checked="" type="checkbox"/> Bail closed, slider locked, double locked, reel unlocked5. Inspect gloves6. Translate port along Node 2 between JEM endcone and MPLM to Node 2 aft endcone HR 364 (with gap spanner)7. Position to support RRM install onto EOTP zenith PFRAM<ul style="list-style-type: none"><input type="checkbox"/> <input checked="" type="checkbox"/> Clearance of RRM to Lab
	

INSTALL RRM FRAM ON EOTP (00:20)


IV/SSRMS	EV1	EV2				
<p>1. ✓ MCC-H – EOTP RRM FRAM inhibits in place</p> <p>2. SSRMS: Notify EV: Ready to roll AFRAM 180°</p> <p>3. SSRMS: Maneuver to RRM install position</p> <p>4. Record PM FRAM bolt data:</p> <table border="1" data-bbox="163 634 537 699"> <thead> <tr> <th>Turns</th> <th>Torque (ft-lb)</th> </tr> </thead> <tbody> <tr> <td>(11.2)</td> <td>(6.3)</td> </tr> </tbody> </table> <p>5. On EV2 GO: Give MCC-H GO for EOTP RRM FRAM heater power</p> <p>6. IV: ✓  WVS close-out imagery of RRM on EOTP</p> <p>7. SSRMS: Maneuver clear of EOTP</p>	Turns	Torque (ft-lb)	(11.2)	(6.3)	<p><u>INSTALL RRM FRAM ON EOTP</u> (00:20)</p> <p>1. On SSRMS GO, rotate AFRAM 180° roll for installation on EOTP</p> <p>2. ✓ Ingress Aid position</p> <p>3. Give SSRMS GO for maneuver to RRM install position</p> <p>4. Position AFRAM on EOTP</p> <p>5. Verify PGT settings: <input type="checkbox"/> [A4-TBD, CW2, 30.5]</p> <p>6. On EV2 GO, engage primary AFRAM bolt, expect 11 turns to hard stop (Push ~10 lb to release locking tabs)</p> <p>7. ✓ Status indicator “out”</p> <p>8. Perform pull test on AFRAM</p> <p>9. Retrieve two RETs from AFRAM</p> <p>10. Transfer COLT Bag to EV2</p> <p>11. Give IV GO when clear of EOTP <input type="checkbox"/> ✓ All tethers and tools are clear of RRM before SSRMS maneuver</p> <p>12.  WVS close-out imagery of RRM on EOTP</p> <p>13. Inspect gloves</p> <p>14. Give SSRMS GO to maneuver clear of EOTP</p>	<p><u>INSTALL RRM FRAM ON EOTP</u> (00:20)</p> <p>1. Assist EV1 with AFRAM rotation and installation</p> <p>2. Provide clearance calls for <input type="checkbox"/> RRM to Lab <input type="checkbox"/> RRM to EOTP “goal posts”</p> <p>3. When aligned and seated on PFRAM, give EV1 GO to drive primary AFRAM bolt</p> <p>4. Receive COLT Bag from EV1; stow on BRT</p> <p>5. Inspect gloves</p> <p>6. Translate to A/L</p>
Turns	Torque (ft-lb)					
(11.2)	(6.3)					

MISSE 8 ORMATE III R/W INSTALL ON ELC-2 (01:20)

I


IV	EV2
<p><u>PLANNED PET 03:40</u></p> <ol style="list-style-type: none"> 1. Start Hatch Thermal Cover clock PET (30 min) ___ : ___ 2. Stop Hatch Thermal Cover clock PET (30 min) ___ : ___ 3. Give MCC-H GO to put MISSE 8 inhibits in place 4. Start MISSE 8 thermal clock PET (2-hr) ___ : ___ 	<p><u>MISSE 8 ORMATE III R/W INSTALL ON ELC-2 (01:20)</u></p> <ol style="list-style-type: none"> 1. ← Open hatch thermal cover 2. Transfer EVA Camera from COLT Bag into PMA3 Cover Bag 3. Transfer Fisheye Camera from COLT Bag into MISSE/Get-ahead C/L Bag; stow COLT Bag in A/L 4. Stow PMA3 Cover Bag onto A/L circular HR 5. Retrieve MISSE/Get-ahead C/L Bag; stow on BRT 6. ← Close hatch thermal cover <p style="text-align: center;"><u>NOTE</u></p> <p style="text-align: center;">Avoid contacting the CETA Cart brake handles during translation to avoid reconfiguring wire ties</p> <ol style="list-style-type: none"> 7. Translate up CETA Spur to S1 face 6 – HR 3292, then starboard along “low road” forward around CETA light to HR 3246 (half-way between CETA light and S1 lower outboard ETVCG) 8. Attach green hook onto S1 HR 3246 _____ <input type="checkbox"/> √Bail closed, slider locked, double locked, reel unlocked 9. Translate along face 1 CETA rail to mid S3 (bay 19 label) 10. Translate zenith to S3 HR 3038 (just inside bay 19 face 1 zenith) 11. Attach Adjustable Tether fairlead at S3 HR 3038 12. Translate zenith to ELC-2 fwd/nadir trunnion and HR 8604 (on inboard side of trunnion) 13. Temp stow C/L Bag on CTC FRAM HR _____ 14. Tether to ORMATE tether point near probe (captures both ORMATE and cover) 15. Release ORMATE from C/L Bag; stow on MWS <div style="border: 2px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p><u>WARNING</u> Avoid sharp edge on AMS star trackers</p> </div> <div style="border: 1px solid black; padding: 5px; text-align: center; margin: 10px 0;"> <p><u>CAUTION</u> Avoid inadvertent contact with deployed MISSE PECs, which have shatterable materials, and the silver avionics boxes atop the ExPA</p> </div> <ol style="list-style-type: none"> 16. Translate zenith along ELC-2 forward/inboard edge and CTC to ELC-2 fwd/zenith trunnion and HR 8603 17. BRT to HR 8603 or CTC FRAM HR 18. Release PIP pins (2) on MISSE ExPA forward socket 19. Install ORMATE into socket (RAM side to ISS velocity vector, bayonet probe away) <input type="checkbox"/> √Alignment marks match up 20. Install PIP pins (2) <input type="checkbox"/> Verify PIP pins fully engaged, loops out of the way 21. Use second RET to tether to ORMATE cover (tether point away from probe)


MISSE 8 ORMATE III R/W INSTALL ON ELC-2 (01:20) (Cont)

IV	EV2
<p>5. IV: Tool Inventory</p> <p>6. When EV1 is clear of ELC-2, give MCC-H GO to power up MISSE 8 (except for MISSE 8 WVS inhibit)</p> <p>7. Stop MISSE 8 thermal clock PET (2-hr) ____ : ____</p> <p>8. $\sqrt{\text{MCC-H}}$ – Timing for FHRC P-Clamps Release get-ahead</p>	<p>22. Remove RET from ORMATE near probe</p> <p>23. Release Velcro strap and remove protective cover from ORMATE</p> <p>24. Translate nadir to Crewlock Bag</p> <p>25. Stow cover on Crewlock Bag using RET and Adjustable Equipment Tether (wire tie only if necessary)</p> <p>26. Retrieve camera from Crewlock Bag</p> <div data-bbox="701 451 1350 516" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Avoid contact with FRGF grapple shaft and target pin</p> </div> <p>27.  Photograph MISSE 8 Required ORMATE <input type="checkbox"/> Fwd – Translate zenith along ELC-2 forward edge to HR 8603 <input type="checkbox"/> Aft – Translate nadir around CTC on inboard face, then zenith If time allows PEC 8 <input type="checkbox"/> Zenith – From inboard face, aft of CTC, translate zenith to zenith edge of ELC-2 <input type="checkbox"/> Nadir – Translate nadir, near CTC Overview of ExPA (<input type="checkbox"/><input type="checkbox"/> 2 angles)</p> <p>28. Translate to Crewlock Bag on ELC-2 HR 8604</p> <p>29. Stow camera in Crewlock Bag</p> <p>30. Tool Inventory</p> <p>31. Stow Crewlock Bag on BRT</p> <p>32. When clear of ELC-2, give IV GO for MISSE 8 power up</p> <p>33. Translate nadir to S3 HR 3038</p> <p>34. Retrieve Adjustable Tether fairlead at S3 HR 3038</p> <p>35. Glove Check</p> <p>36. Translate inboard to S1 HR 3246</p> <p>37. Retrieve green hook from S1 HR 3246 <input type="checkbox"/> $\sqrt{\text{Bail}}$ closed, slider locked, double locked, reel unlocked</p>







SSRMS CLEANUP (00:45)

I




IV/SSRMS	EV1
<ol style="list-style-type: none"> SSRMS: Maneuver to ESP-2 egress position (~00:15 from EOTP) SSRMS: Notify EV: Brakes on, ready for APFR egress SSRMS: Maneuver to APFR retrieval position SSRMS: Notify EV: Brakes on, ready for APFR retrieval  <ol style="list-style-type: none"> SSRMS: Maneuver to park position 	<p><u>SSRMS CLEANUP</u> (00:45)</p> <ol style="list-style-type: none"> On SSRMS GO, egress APFR Give SSRMS GO for maneuver to APFR retrieval position Locate anchor ST (green hook) on ESP-2 HR 8011 _____ On SSRMS GO, Safety Tether swap to anchor ST, retrieve crew ST from SSRMS <ul style="list-style-type: none"> <input type="checkbox"/> √Bail closed, slider locked, double locked, reel unlocked <input type="checkbox"/> Optional: Configure to ST Pack per diagram Retrieve APFR; stow in ESP-2 WIF 5 [low profile] <ul style="list-style-type: none"> <input type="checkbox"/> √Locking collar black-on-black, pull and twist test Report APFR settings Stow Ingress Aid and configure against boot plate Retrieve WIF Adapter; stow on MWS Give SSRMS GO to maneuver to park position Inspect gloves Translate to ESP-2 forward Reconfigure Gap Spanner between Lab HR 293 and ESP-2 HR 8013 (buckle can rotate 90°) Retrieve RET from Gap Spanner Translate to A/L

IV/SSRMS	EV1
<p>1. √RSOS inhibits in place</p> 	<p>FGB PDGF TROUBLESHOOTING (00:35)</p> <ol style="list-style-type: none"> Retrieve PMA3 Cover Bag; stow on BRT Translate from A/L via nadir route along Lab aft end cone (port between ESP-2 and A/L around high pressure gas tank, equipment lock to Lab gap spanner, then nadir under Lab to gap spanner 231-232) <div data-bbox="1121 444 1696 509" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Do not use Node 3 jumpers as a translation aid</p> </div> <ol style="list-style-type: none"> OPTIONAL – Install Gap Spanner <ol style="list-style-type: none"> Attach one end of gap spanner to forward stanchion of Lab HR 239 Translate to Lab HR 201 (OK to use WIF 4) Attach other end of gap spanner to fwd stanchion of Lab HR 201 <ul style="list-style-type: none"> <input type="checkbox"/> Tighten gap spanner until buckle can twist 90° Translate zenith around Node 3 jumpers to Node 3 stbd, then nadir under Node 3 to Node 1 aft Stow PMA3 Cover Bag onto Node 1 HR 107 _____ <div data-bbox="1113 867 1860 1010" style="border: 3px double black; padding: 5px; text-align: center;"> <p>WARNING Avoid inadvertent contact with grapple fixture target, target pin, connector doors, and PDGF curvic coupling (teeth) Avoid contact with FGB sun sensors (possible sharp edges)</p> </div> <div data-bbox="1117 1042 1856 1133" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Avoid inadvertent contact with zenith PMA1 MDM and above 22" of EVA crane</p> </div> <ol style="list-style-type: none"> Translate zenith to Node 1 HR 105, aft to PMA1 HR 6, then via PMA1 HR 11 & 12 to PDGF <div data-bbox="1125 1256 1722 1318" style="text-align: center;"> <p>NOTE VSC cover should not be used as a translation aid</p> </div>

FGB PDGF TROUBLESHOOTING (00:35) (Cont)

IV/SSRMS	EV1
	<ol style="list-style-type: none"> 7. Position head zenith, feet nadir; BRT to PAMA HR, MWS EE to PDGF tether point 8. Insert large crew hook in nadir/fwd electrical connector doors, near umbilical connectors, to hold open – orient hook perpendicular to doors so hook cannot damage pins 9. Inspect grounding wire attachment point and grounding wire routing for damage or potential snag concerns for wire slack removal 10. Open nadir/forward PDGF MLI 11. Pull grounding wire slack out of PDGF housing 12. Loop and tuck grounding wire slack between PDGF housing and MLI, close PDGF MLI and secure Velcro
<p>2. IV:  WVS close-out imagery</p>	<ol style="list-style-type: none"> 13. Insert large crew hook in nadir/fwd electrical connector doors, near umbilical connectors, to hold open – orient hook perpendicular to doors so hook cannot damage pins 14.  WVS close-out imagery and crew inspection inside PDGF connector door
	<ol style="list-style-type: none"> 15. Translate zenith of PDGF and rotate to position head nadir, feet zenith; BRT to PAMA HR, MWS EE to PDGF tether point 16. Insert large crew hook in zenith/fwd electrical connector doors, near umbilical connectors, to hold open – orient hook perpendicular to doors so hook cannot damage pins 17. Inspect grounding wire attachment point and grounding wire routing for damage or potential snag concerns for wire slack removal 18. Open zenith/forward PDGF MLI 19. Pull grounding wire slack out of PDGF housing 20. Loop and tuck grounding wire slack between PDGF housing and MLI, close PDGF MLI and secure Velcro
<p>3. IV:  WVS close-out imagery</p>	<ol style="list-style-type: none"> 21. Insert large crew hook in zenith/fwd electrical connector doors, near umbilical connectors, to hold open – orient hook perpendicular to doors so hook cannot damage pins
<p>4. Perform EV Final Tool Inventory</p>	<ol style="list-style-type: none"> 22.  WVS close-out imagery and crew inspection inside PDGF connector door
	<ol style="list-style-type: none"> 23. If time allows, inspect remaining two connector doors
	<ol style="list-style-type: none"> 24. Glove Check
	<ol style="list-style-type: none"> 25. Perform MWS Tool Inventory

PMA3 COVER INSTALL (00:45)

IV/SSRMS	EV1	EV2
<p>1. ✓ MCC-H – Inhibits in place (Port TRRJ & Cupola Windows)</p> <p>2. ✓ MCC-H – Time for 1553 Data Cable Install get-ahead</p> 	<p>PMA3 COVER INSTALL (00:45)</p> <ol style="list-style-type: none"> Translate to Node 1 Retrieve PMA3 Cover Bag from Node 1 HR 107; stow on BRT Translate nadir on Node 3 end cone to Node 3 fwd <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Do not use Node 3 jumpers as a translation aid</p> </div> <ol style="list-style-type: none"> Translate zenith between ESP-1 and Node 3 to Node 3 HR 663, then on HR 600 path port to PMA3 <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>WARNING Avoid contact with APAS mating surface and reflector</p> </div> <ol style="list-style-type: none"> Temp stow PMA3 Cover Bag on PMA3 zenith; hinge line stbd Secure ORU Bag lid straps to HRs 1605 and 1606 <ol style="list-style-type: none"> EV1 work from fwd side of PMA Remove PMA3 cover from ORU Bag without unfolding; PMA3 cover label on top Align “key” cutout with PMA reflector Attach Velcro strap to HR 1614. (Start with straps loose, then come back to tighten) Continue to unfold PMA3 cover, while attaching Velcro straps on fwd circumferential HRs <ul style="list-style-type: none"> <input type="checkbox"/> 1615 <input type="checkbox"/> 1618 <input type="checkbox"/> 1616 <input type="checkbox"/> 1617 Work back zenith toward bag, retightening straps as required  WVS close-out imagery of PMA3 cover Inspect gloves Retrieve PMA3 Cover Bag, stow on BRT 	<p>PMA3 COVER INSTALL (00:45)</p> <ol style="list-style-type: none"> Translate to A/L Stow MISSE Bag outside A/L If time allows for 1553 Data Cable Install get-ahead, retrieve 1553 Data Cable Bag, stow on BRT Translate aft and port on equipment lock along trunnion pins to Node 1 Translate port to Node 1 HR 104 <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>CAUTION Avoid inadvertent contact with zenith PMA1 MDM and above 22" of EVA crane</p> </div> <ol style="list-style-type: none"> Stow 1553 Data Cable Bag onto PMA1 HR 6 Translate back onto Node 1, then nadir to gap spanner onto Node 3 Translate port to PMA3 <div style="border: 1px solid black; padding: 5px; text-align: center;"> <p>WARNING Avoid contact with APAS mating surface and reflector</p> </div> <ol style="list-style-type: none"> Assist EV1 from aft side of PMA3 Attach Velcro strap to HR 1613. (Start with straps loose, then come back to tighten) Continue to unfold PMA3 cover, while attaching Velcro straps on aft circumferential HRs <ul style="list-style-type: none"> <input type="checkbox"/> 1612 <input type="checkbox"/> 1611 <input type="checkbox"/> 1610 Work back zenith toward bag, retightening straps as required  WVS close-out imagery of PMA3 cover Inspect gloves

EVA 1 CLEANUP/INGRESS (00:45)

IV/SSRMS	EV1	EV2
<ol style="list-style-type: none"> 1. IV: Perform WVS PWRDWN (PHOTO/TV, <u>WVS CUE CARD</u>) 2. Give MCC-H GO to release ESP-2 inhibits 3. Stop MBSU thermal clock PET (8-hr) ___ : ___ 4. Start Hatch Thermal Cover clock PET (30 min) ___ : ___ 5. Stop Hatch Thermal Cover clock PET (30 min) ___ : ___ 	<p><u>CLEANUP</u> (00:15)</p> <ol style="list-style-type: none"> 1. Final Tool Inventory 2. Translate to A/L <p><u>INGRESS AND PRE-REPRESS</u> (00:30)</p> <ol style="list-style-type: none"> 3. On EV2 GO, release EV2 ST anchor hook 4. On EV2 GO, ingress A/L 5. Attach L Waist Tether to A/L Internal D-ring extender <input type="checkbox"/> √Bail closed, slider locked 6. Retrieve EV1 anchor hook, attach to MWS 7. Remove SCU from stowage pouch 8. Remove DCM cover; Velcro to DCM 9. Connect SCU to DCM √SCU locked <p style="text-align: center;"><u>NOTE</u> A TCV setting 8 – Max C minimizes time for SCU cooling</p> <ol style="list-style-type: none"> 10. WATER – OFF (fwd), expect 'H2O IS OFF' msg 11. ← Close hatch thermal cover; attach Velcro strap <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: fit-content;"> <p style="text-align: center;"><u>CAUTION</u> Do not close hatch until EMU water OFF for 2 min</p> </div> <ol style="list-style-type: none"> 12. Verify outer hatch clear of hardware 13. Verify handle position per hatch decal 14. Close and lock hatch <p>Go to PRE-REPRESS (<u>DEPRESS/REPRESS</u> Cue Card)</p>	<p><u>CLEANUP</u> (00:15)</p> <ol style="list-style-type: none"> 1. Final Tool Inventory 2. Translate to A/L <p><u>INGRESS AND PRE-REPRESS</u> (00:30)</p> <ol style="list-style-type: none"> 3. ← Open hatch thermal cover 4. Stow bags in A/L (Crewlock and ORU) 5. Attach L Waist Tether to UIA fwd D-ring <input type="checkbox"/> √Bail closed, slider locked 6. Retrieve EV2 anchor hook, attach to MWS 7. Ingress Airlock 8. Give EV1 GO to ingress 9. Remove SCU from stowage pouch 10. Remove DCM cover; Velcro to DCM 11. Connect SCU to DCM √SCU locked <p style="text-align: center;"><u>NOTE</u> A TCV setting 8 – Max C minimizes time for SCU cooling</p> <ol style="list-style-type: none"> 12. WATER – OFF (fwd), expect 'H2O IS OFF' msg <p>Go to PRE-REPRESS (<u>DEPRESS/REPRESS</u> Cue Card)</p>

EVA 1 TASK DATA – PM TRANSFER

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew		
Two EV Crew		

Tools:

EV1	EV2
PGT w/7/16" socket	PGT w/7/16" socket

EVA Fasteners:

Fastener Name	Head Size	Qty	Nominal Install Torque (ft-lb)	Nominal Release Torque (ft-lb)	Max Expected Break Away Torque (ft-lb)	Max On-Orbit Install Torque (ft-lb)	Min On-Orbit Install Torque (ft-lb)	Max Torque not to exceed (ft-lb)	Turns	RPM
FRAM Primary Bolt	7/16"	1	6.3 (A4)	6.3 (A4)	13.3 (Release) 11.6 (Install)	10	2.5	21	11.1	30
FRAM Contingency Pin (Forward)	7/16"	4	6.3 (A4)		8.9	10	2.5	34	14.11	30
FRAM Contingency Pin (Aft)	7/16"	4	6.3 (A4)		8.9	10	2.5	34	16.858	30

ORUs:

Item	Mass (lb)	Dimensions (in)
Pump Module (w/10 lb of NH3) on AFRAM	1393	62 x 72 x 56

Foot Restraints:

Task	WIF	APFR Setting
PM Transfer	SSRMS	12, NN, F, 6

Notes:

- COLT Assembly, Pin 3 – SEG33122635-301 (long/fwd)
- COLT Assembly, Pin 4 – SEG33122635-302 (short/aft)

Cautions:



- Minimize loads into PM MLI handholds. It is possible that handholds may tear off

Timeline Considerations:

- 8-hour thermal clock

TASK DATA

EVA 1 TASK DATA – PM TRANSFER (Cont)



EVA 1 TASK DATA – RRM TRANSFER

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew		
Two EV Crew		

Tools:

EV1	EV2
PGT w/7/16" socket	PGT w/7/16" socket
Square Scoop (optional)	

EVA Fasteners:

Fastener Name	Head Size	Qty	Nominal Install Torque (ft-lb)	Nominal Release Torque (ft-lb)	Max Expected Break Away Torque (ft-lb)	Max On-Orbit Install Torque (ft-lb)	Min On-Orbit Install Torque (ft-lb)	Max Torque not to exceed (ft-lb)	Turns	RPM
FRAM Primary Bolt	7/16"	1	6.3 (A4)	6.3 (A4)	13.3 (Release) 11.6 (Install)	10	2.5	21	11.1	30
FRAM Contingency Pin (Forward)	7/16"	4	6.3 (A4)		8.9	10	2.5	34	14.11	30
FRAM Contingency Pin (Aft)	7/16"	4	12.0 (B1)	12.0 (B1)	7.2	12.5	8.4	29.8 (Release) 23.6 (Install)	2.6	30

ORUs:

Item	Mass (lb)	Dimensions (in)
RRM	820 lb with FRAM	45 x 33 x 43

Foot Restraints:


Task	WIF	APFR Setting
RRM Transfer	SSRMS	12, NN, F, 6

Notes:

- 1.
- 2.
- 3.
- 4.
- 5.


Timeline Considerations:

1. 12-hour thermal clock (LMC heater off to EOTP heater on)




RRM on LMC


EVA 1 TASK DATA – RRM TRANSFER (Cont)




EVA 1 TASK DATA – RRM TRANSFER (Cont)



EVA 1 TASK DATA – RRM TRANSFER (Cont)



EVA 1 TASK DATA – RRM TRANSFER (Cont)



EVA 1 TASK DATA – MISSE 8 ORMATE III

Estimated Task Duration:

	With RMS	Without RMS
One EV Crew	N/A	01:20
Two EV Crew	N/A	N/A

Tools:

EV1
Hammer (contingency only)
Pry Bar (contingency only)
BMRRM Tool (contingency only)

ORUs:

Item	Mass (lb)	Dimensions (in)
ORMatE III R/W	12.9 (experiment), 6.0 (cover)	19.92" x 10.83" x 3.62"

Notes:

1. Avoid contacting the CETA Cart brake handles during translation to avoid reconfiguring wire ties
2. 2-hr thermal clock when power is removed from MISSE 8

Cautions:


1. Avoid inadvertent contact with deployed MISSE PECs, which have shatterable materials, and the silver avionics boxes atop the ExPA
2. Avoid contact with FRGF grapple shaft and target pin

Warnings:


1. Avoid sharp edge on AMS star trackers

Timeline Considerations:

- 1.



EVA 1 TASK DATA – FGB PDGF TROUBLESHOOTING




EVA 1 TASK DATA – FGB PDGF TROUBLESHOOTING (Cont)




Avoid contact with curvic coupling teeth

Peeling back MLI tab




Pinch hazard of connector doors

Peeling back MLI to expose grounding wire




Attachment point

Inspecting grounding tab attachment point



Large crew hook inserted into electrical connector housing to hold open doors. Grounding wire slack being pulled out of PDGF housing

EVA 1 TASK DATA – FGB PDGF TROUBLESHOOTING (Cont)




Grounding wire slack being stowed so that Velcro will hold it in place when MLI closed



Closing MLI




Closing MLI tab




Pins in electrical connector

EVA 1 TASK DATA – FGB PDGF TROUBLESHOOTING (Cont)

Grapple fixture cover removed on STS-134



Grounding wire protruding from forward/nadir electrical connector doors



Grounding wire possibly visible through connector doors on forward/zenith electrical connector housing

EVA 1 TASK DATA – PMA3 COVER INSTALL

Estimated Task Duration:

Without RMS	
Two EV Crew	00:45

Tools:

EV1
PMA3 Cover



Notes:

- 1.


Timeline Considerations:

1. Gap spanner installation can be skipped to gain ~5 min



PMA3 Cover Storage Plan (accordion fold in quarters, straps inward)



PMA3 Cover Storage Plan (tri-folded with cutout and tether point on front face)



EVA 1 TASK DATA – PMA3 COVER INSTALL (Cont)



STS-135 GET-AHEADS

|

EVA Get-ahead Tasks (Order indicates priority)	Duration	Crew	Tools/Bags	Inhibits	Bingo Time
FGB PDGF 1553 Data Cable Install	00:45 (post PMA3 Cover Install); 01:15 (from A/L)	2	1553 Data Cable Bag	1. All RWS – Active Assert Backup 2. √RACU-5 – OFF 3. √RACU-6 – OFF 4. √KURS A [КУРС А] – Deactivated 5. √KURS P [КУРС Р] – Deactivated 6. √TORU [ТОРУ] – Deactivated 7. √TV System [ТВС] – Deactivated 8. Radiotelemetry [БР-9ЦУ-8] – Deactivate 9. √TV System [КЛ-108А] – Deactivated 10. √CNPMS [СИТНП] – Deactivated 11. √КОМПАРУС [КИС] – Deactivated	05:00 PET (from PMA3; 04:30 from A/L)
Port CETA Cart Reconfig	00:30	1	2 Long Wire Ties	MT Latched	
SSRMS Base B Elbow CLPA R&R	01:15	1	CLPA ORU Bag, 2 Square Scoops, PGT w/7/16" x 6"	1. RPCs – Open, Close Cmd Inhibit a. S04B C RPC 4 b. S03A C RPC 2	04:30 PET (SSRMS powered up and maneuvering to position for task)
S1 FHRC P-Clamp Release	00:45	1	MISSE/Get-ahead C/L Bag Ratchet w/7/16" x 2"; 7/16" x 18" socket (from Z1 Tool Box)	Stbd TRRJ Locked at 0°	
Tool Reconfiguration	00:30	1	Tool Relocations C/L Bag (in Staging Bag)	None	
Gap Spanner Install	00:20	1	45"-72" Gap Spanner (-307) (in PMA3 Cover Bag)	None	

GET-AHEADS


FGB PDGF 1553 DATA CABLE INSTALL (00:45 from PMA3 Cover Task; 01:15 from A/L)

IV/SSRMS	EV1	EV2
	<div data-bbox="821 245 1797 386" style="border: 2px solid black; padding: 5px; margin-bottom: 10px;"> <p style="text-align: center;"><u>WARNING</u></p> <p>Avoid inadvertent contact with grapple fixture target, target pin, connector doors, and PDGF curvic coupling (teeth) Avoid contact with FGB sun sensors (possible sharp edges)</p> </div> <div data-bbox="821 407 1772 467" style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Avoid inadvertent contact with zenith PMA1 MDM and above 22" of EVA crane</p> </div> <p data-bbox="632 500 1220 526"><u>FGB PDGF 1553 DATA CABLE INSTALL (00:45)</u></p> <ol data-bbox="632 532 1283 1170" style="list-style-type: none"> 1. Translate to Node 3 HR 667 (fwd/stbd); stow PMA3 Cover Bag 2. Translate nadir under Node 3 to Node 1 aft 3. Translate to FGB 4. Retrieve 1553 cable and fish stringer from bag <ul style="list-style-type: none"> <input type="checkbox"/> RET to connector bail or cable 5. Untwist taped wire tie to release Node 3 end 6. Attach taped wire tie (FGB end) to PMA1 HR 0011 7. Translate nadir/port to Node 3 connector panel (along Node 1 HR 0118), reel out 1553 cable as required 8. Temp stow fish stringer near Node 3 connector panel (add RET if extra length needed) 9. Remove Node 3 terminator MLI (2); stow on fish stringer <ul style="list-style-type: none"> <input type="checkbox"/> J1 FGB <input type="checkbox"/> J2 FGB 	<p data-bbox="1318 500 1913 526"><u>FGB PDGF 1553 DATA CABLE INSTALL (00:45)</u></p> <ol data-bbox="1318 532 1976 1138" style="list-style-type: none"> 1. ** If starting at A/L, retrieve 1553 Data Cable Bag and translate via Node 1 HR 104 (aft/zenith) to PMA1 HR 6; stow bag onto HR 6 2. Translate to FGB 3. Translate to PAMA/PDGF forward between foot 2 and 3 4. Release wire tie from PDGF for the 1553 cables 5. Route PDGF harness cables toward PMA1 HR 0011 <ul style="list-style-type: none"> <input type="checkbox"/> Verify ST routed over the cables 6. On IV GO: Remove caps (4); verify caps are securely wire tied to cables <p data-bbox="1598 1170 1682 1196" style="text-align: center;"><u>NOTE</u></p> <p data-bbox="1402 1203 1759 1229">Russian connectors reminder:</p> <ul data-bbox="1430 1229 1871 1414" style="list-style-type: none"> - Verify lock is in Open position - Align arrows on connector shells - Push connectors together - Rotate connectors ~1/4 turn - Verify arrow on plug points to white mark on socket - Slide lock closed

FGB PDGF 1553 DATA CABLE INSTALL (01:10) (Cont)

IV/SSRMS	EV1	EV2
<div data-bbox="107 418 604 771" data-label="Image"> </div> <p data-bbox="107 787 604 836">3. Give MCC-H GO to check both data channels</p> <p data-bbox="107 1112 604 1144">4. Perform EV Tool Inventory</p>	<p data-bbox="632 381 1306 503">10. On IV GO: Remove Node 3 terminator caps (2) from aft avionics panel; stow on fish stringer</p> <ul style="list-style-type: none"> <li data-bbox="688 446 1165 479">❑ Terminator cap ← → Node 3 J1 FGB <li data-bbox="688 479 1165 503">❑ Terminator cap ← → Node 3 J2 FGB <p data-bbox="632 535 1306 592">11. Remove cap from 1553 P1 cable; stow on fish stringer</p> <p data-bbox="632 625 1306 714">12. Mate 1553 cable P1 to Node 3 J1 FGB</p> <ul style="list-style-type: none"> <li data-bbox="688 657 1113 682">❑ √Good pins & EMI band; no FOD <li data-bbox="688 690 1186 714">❑ 1553 cable P1 → ← J1 FGB (Node 3) <p data-bbox="632 747 1306 771">13. Remove cap from 1553 P2 cable; stow on fish stringer</p> <p data-bbox="632 771 1306 868">14. Mate 1553 cable P2 to Node 3 J2 FGB</p> <ul style="list-style-type: none"> <li data-bbox="688 812 1113 836">❑ √Good pins & EMI band; no FOD <li data-bbox="688 844 1186 868">❑ 1553 cable P2 → ← J2 FGB (Node 3) <p data-bbox="632 868 1306 893">15. Retrieve fish stringer</p> <p data-bbox="632 901 1306 958">16. Wire tie 1553 cable and any slack to Node 1 HR 0118 (low profile wire tie) and PMA1 HR 0006</p> <p data-bbox="632 958 1306 1015">17. Translate to Node 3 bag; stow fish stringer in Node 3 bag</p> <p data-bbox="632 1088 1306 1112">18. Glove Check</p> <p data-bbox="632 1120 1306 1144">19. Perform MWS Tool Inventory</p> <p data-bbox="632 1153 1306 1177">20. Translate to Node 3 HR 667 (fwd/stbd)</p> <p data-bbox="632 1185 1306 1209">21. Retrieve PMA3 Cable bag; stow on BRT</p> <p data-bbox="632 1218 1306 1242">22. Translate to A/L</p>	<p data-bbox="1318 235 1992 381">7. Mate 1553 cable connectors to PDGF harness and lock connector:</p> <ul style="list-style-type: none"> <li data-bbox="1375 300 1648 324">❑ √Good pins; no FOD <li data-bbox="1375 332 1942 357">❑ PDGF harness 1800-X54 → ← J54 (Bus A) <li data-bbox="1375 365 1942 389">❑ PDGF harness 1800-X53 → ← J53 (Bus B) <p data-bbox="1318 446 1992 503">8. Secure FPP booties around 1553/PDGF harness connections; adjust wire ties as required</p> <p data-bbox="1318 933 1992 990">9. Wire tie any slack to PMA1 HR 0011 using integrated PDGF harness wire tie</p> <p data-bbox="1318 1031 1992 1055">10. Retrieve 1553 Data Cable Bag, stow on BRT</p> <p data-bbox="1318 1088 1992 1112">10. Glove Check</p> <p data-bbox="1318 1120 1992 1144">11. Perform MWS Tool Inventory</p> <p data-bbox="1318 1209 1992 1234">12. Translate to A/L</p>

FGB PDGF 1553 DATA CABLE INSTALL – TASK DATA



1553 Bus B
Data Cable


1553 Bus A
Data Cable

J53 of 1553
Bus B Data
Cable
(W4497)

J54 of 1553
Bus A Data
Cable
(W4495)

Insulating
Sleeves

FGB PDGF 1553 DATA CABLE INSTALL – TASK DATA (Cont)




FGB PDGF 1553 DATA CABLE INSTALL – TASK DATA (Cont)



J2 FGB on Node 3

Handrail 0672

1553 Bus B Terminator Cap MLI



HR 0619

Node 3

HR 0619



W4497/PDGF Ch B

W4495/PDGF Ch A

1553 Bus B Data Cable

HR 0672

PORT CETA CART RECONFIG (00:30)

IV/SSRMS	EV
<p>Tools Required:</p> <ul style="list-style-type: none"> <input type="checkbox"/> 2 long wire ties, 1 short (optional) <p>Inhibits Required: Mobile Transporter</p> <p>MCC-H EV crew expected < 1.5 meters from MT (ROBO) 1. <input checked="" type="checkbox"/> MT latched</p>  <p style="text-align: center;">NOTE TFR is at 0 in this graphic, but should be fully deployed to 30 on ISS</p>	<p>PORT CETA CART RECONFIG (00:30)</p> <ol style="list-style-type: none"> 1. Retrieve at least two long wire ties 2. Translate to Port CETA Cart 3. <input checked="" type="checkbox"/> Port TFR nadir 180 deg full nadir (position 30) 4. If not <ul style="list-style-type: none"> <input type="checkbox"/> Release Port nadir TFR swing arm, move to position 30 <input type="checkbox"/> Lock TFR swing arm 5. Attach Waist Tether to WIF 1 tether pt 6. Rotate Port brake handles forward and tie down (one long wire tie per handle) <ul style="list-style-type: none"> <input type="checkbox"/> Nadir brake handle to zenith TFR Toe Clip <input type="checkbox"/> Zenith brake handle to Sq Grid H (port/nadir corner) <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Three twists at each end of wire ties <input checked="" type="checkbox"/> Brake handles bent at elbow and secured together with wire tie (optional) 7. <input checked="" type="checkbox"/> Outboard WIFs pitched inboard at least 45° <ul style="list-style-type: none"> <input type="checkbox"/> WIF 4 <input type="checkbox"/> WIF 5 8. <input checked="" type="checkbox"/> Perform WVS survey of CETA Cart 9. Glove Check 

This Page Intentionally Blank

SSRMS BASE B ELBOW CLPA R&R (01:15)

IV/SSRMS	EV1
<p>1. SSRMS: Maneuver to CLPA Setup position (~00:10)</p> <p>2. Start Hatch Thermal Cover clock PET (30 min) ___ : ___</p> <p>3. Stop Hatch Thermal Cover clock PET (30 min) ___ : ___</p> <p>4. SSRMS: Maneuver to CLPA R&R position</p> <p>5. SSRMS: On EV GO, safe SSRMS</p> <p>6. SSRMS: Inform MCC-H SSRMS safed, ready for SSRMS power down</p> <p>7. <input checked="" type="checkbox"/> MCC-H – CLPA inhibits in place</p>	<p><u>SSRMS BASE B ELBOW CLPA R&R (01:15)</u></p> <p>1. ← Retrieve CLPA Bag from A/L</p> <p>2. ← Close A/L hatch thermal cover</p> <p>3. Temp stow CLPA Bag onto APFR (w/Ingress Aid, from ESP-2 WIF 5)</p> <p>4. Retrieve APFR; stow on BRT</p> <p>5. Translate nadir to Lab HR 231 (one with nadir gap spanner), then translate forward past window to Lab WIF 9</p> <div style="border: 3px double black; padding: 5px; text-align: center; margin: 10px 0;"> <p>WARNING Stay 1 ft from UHF Antenna</p> </div> <p>6. Install APFR into Lab WIF 9 [11, KK, F, 5]</p> <p>7. Stow CLPA Bag onto BRT</p> <p>8. Extend Ingress Aid</p> <p>9. Attach local tether to Ingress Aid</p> <p>10. Ingress APFR</p> <p>11. Position CLPA Bag on BRT for easy access</p> <p>12. Give SSRMS GO for maneuver and GCA into position for CLPA R&R <input checked="" type="checkbox"/> Access to CLPA micro-square and VDU (Texas) tether point (for temp stow of failed CLPA) <input checked="" type="checkbox"/> Lean back assessment for CLPA R&R Adjust APFR roll, if necessary</p> <p>13. Give SSRMS GO for safing</p> <p>14. Retrieve Square Scoop from CLPA Bag (on BRT)</p> <p>15. Install Square Scoop onto CLPA</p> <p>16. Transfer Square Scoop RET from bag to VDU (Texas) tether point (to right of CLPA, on “top” of VDU)</p> <p>17. Configure PGT <input type="checkbox"/> [B7, CCW2, 30.5], 6" ext 7/16"</p>

SSRMS BASE B ELBOW CLPA R&R (01:15) (Cont)

IV/SSRMS		EV1						
8. Record failed CLPA bolt data:	<table border="1"> <thead> <tr> <th>Bolt</th> <th>Turns</th> </tr> </thead> <tbody> <tr> <td>Primary</td> <td>(22)</td> </tr> </tbody> </table>	Bolt	Turns	Primary	(22)	18. On MCC-H GO , release CLPA bolt 22 turns – do NOT drive to hard stop (CLPA will come loose at 14 turns, continue driving to retract exposed bolt threads) 19. Remove failed CLPA (~5 lb soft-dock force); temp stow via RET to VDU (Texas) 20. Retrieve spare CLPA from CLPA Bag (on BRT); install into soft dock 21. Configure PGT <input type="checkbox"/> [B2, CW2, 30.5], 6" ext 7/16"		
Bolt	Turns							
Primary	(22)							
9. Record new CLPA bolt data:	<table border="1"> <thead> <tr> <th>Bolt</th> <th>Turns</th> <th>Torque</th> </tr> </thead> <tbody> <tr> <td>Primary</td> <td>(22)</td> <td>(16.0)</td> </tr> </tbody> </table>	Bolt	Turns	Torque	Primary	(22)	(16.0)	22. Drive CLPA bolt to torque (expect 22-23 turns) 23. Stow PGT 24. Verify lens cover is fully installed 25. Release Square Scoop from spare CLPA; stow in CLPA Bag 26. ✓Pop-up indicator fully "in" (only visible with scoop removed) 27. Stow failed CLPA in CLPA Bag; retrieve RET from VDU (Texas) 28. ✓All tethers and equipment clear of SSRMS 29. Egress APFR 30. Stow Ingress Aid and lay against boot plate 31. Temp stow CLPA Bag onto APFR 32. Retrieve APFR and Bag bundle
Bolt	Turns	Torque						
Primary	(22)	(16.0)						
10. Give MCC-H GO to power up SSRMS		33. When clear of SSRMS, give MCC-H GO to power up SSRMS 34. Translate to ESP-2 forward edge 35. Stow APFR in ESP-2 WIF 5, low profile settings 36. Report APFR settings 37. Retrieve CLPA Bag						
11. Start Hatch Thermal Cover clock PET (30 min) ___ : ___		38. ← Stow CLPA Bag in A/L						
12. Stop Hatch Thermal Cover clock PET (30 min) ___ : ___		39. ← Close A/L hatch thermal cover						
		40. Inspect gloves						

SSRMS BASE B ELBOW CLPA R&R – TASK DATA

Estimated Task Duration:

	With APFR	Without APFR
One EV Crew		
Two EV Crew	N/A	N/A

Tools:

EV1
CLPA ORU Bag (w/spare)
2 Square Scoops
PGT w/7/16" socket 6" extension

EVA Fasteners:


Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
CLPA Tie-Down Bolt	None	7/16"	1	10.8-16.7	25.5	43.0	23-25	30

ORUs:

Item	P/N	Base B s/n	Spare s/n	Mass (lb)	Dimensions (in)
CLPA	51612-3004-1	202	208	50.59 lb	16.82" x 22.47" x 17.00"

Foot Restraints:

Task	WIF	APFR Setting
SSRMS Base B Elbow CLPA R&R	Lab WIF 9	11, KK, F, 5




Notes:

1. Bolt is not free spinning. Drive to turn count, not hard stops
2. 20 turns provides structural integrity
3. 22 turns achieves electrical connectivity
4. Pop-up indicator indicates when CLPA is fully installed

Timeline Considerations:

1. EV2 may assist in setup/cleanup of this task by carrying CLPA ORU Bag to and from worksite while EV2 transports the APFR



S1 FHRC P-CLAMP RELEASE (00:45)

IV/SSRMS	EV																																																																
<p>1. Record P-clamps:</p> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th colspan="4" style="text-align: center;">Hose Box S1 Bay 13</th> </tr> <tr> <th></th> <th style="text-align: center;">P-clamp</th> <th style="text-align: center;">Tool</th> <th style="text-align: center;">Socket</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">1 (N)</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6-in ext</td> </tr> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">2 (N)</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6-in ext</td> </tr> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">3 (N)</td> <td style="text-align: center;">Ratchet</td> <td style="text-align: center;">2-in ext</td> </tr> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">1 (Z)</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6-in ext</td> </tr> <tr> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td style="text-align: center;">2 (Z)</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6-in ext</td> </tr> <tr> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td style="text-align: center;">3 (Z)</td> <td style="text-align: center;">Ratchet</td> <td style="text-align: center;">2-in ext</td> </tr> </tbody> </table> <p>2. Verify inhibits in place √Stbd TRRJ locked at 0 deg</p> <p>3. Record P-clamps:</p> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th colspan="4" style="text-align: center;">Stinger S1 Bay 11</th> </tr> <tr> <th></th> <th style="text-align: center;">P-clamp</th> <th style="text-align: center;">Tool</th> <th style="text-align: center;">Socket</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">1</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6- or 18-in ext</td> </tr> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">2</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">18-in ext</td> </tr> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">3</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6-in ext</td> </tr> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">4</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6- or 18-in ext</td> </tr> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">5</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6- or 18-in ext</td> </tr> <tr> <td style="text-align: center;"><input type="checkbox"/></td> <td style="text-align: center;">6</td> <td style="text-align: center;">PGT</td> <td style="text-align: center;">6* or 18-in ext</td> </tr> </tbody> </table> <p>*wobble reqd w/6-in</p>	Hose Box S1 Bay 13					P-clamp	Tool	Socket	<input type="checkbox"/>	1 (N)	PGT	6-in ext	<input type="checkbox"/>	2 (N)	PGT	6-in ext	<input type="checkbox"/>	3 (N)	Ratchet	2-in ext	<input type="checkbox"/>	1 (Z)	PGT	6-in ext	<input checked="" type="checkbox"/>	2 (Z)	PGT	6-in ext	<input checked="" type="checkbox"/>	3 (Z)	Ratchet	2-in ext	Stinger S1 Bay 11					P-clamp	Tool	Socket	<input type="checkbox"/>	1	PGT	6- or 18-in ext	<input type="checkbox"/>	2	PGT	18-in ext	<input type="checkbox"/>	3	PGT	6-in ext	<input type="checkbox"/>	4	PGT	6- or 18-in ext	<input type="checkbox"/>	5	PGT	6- or 18-in ext	<input type="checkbox"/>	6	PGT	6* or 18-in ext	<p>S1 FHRC HOSE BOX P-CLAMP RELEASE – BAY 13 (00:20)</p> <ol style="list-style-type: none"> √Ratchet w/7/16" socket 2" ext in MISSE/Get-ahead Bag is with you <ul style="list-style-type: none"> <input type="checkbox"/> Consider translation to Z1 stbd Tool Box to pick up 18" socket Translate to S1 FHRC Bay 13 <div style="border: 1px solid black; padding: 5px; margin: 10px 0; text-align: center;"> <p>CAUTION Do not impart loads greater than 15 lb into FHRC Hose Box fluid lines</p> </div> <ol style="list-style-type: none"> Configure PGT: [A7 (9.2), CCW2, 30.5] 7/16 socket 6 ext Release Hose Box P-clamps (4) [P-clamp #3N requires ratchet] ~6-12.5 turns Egress Bay 13 Verify SAFER handles: <ul style="list-style-type: none"> <input type="checkbox"/> √R Handle down (HCM door – Closed) <input type="checkbox"/> √L Handle down (MAN ISO Valve – Open) <p>S1 FHRC STINGER P-CLAMPS – BAY 11 (00:25)</p> <ol style="list-style-type: none"> Translate S1 FHRC Bay 11 Configure PGT [A7 (9.2), CCW2, 30.5] 7/16 socket 6 ext Release Stinger P-clamps (5) [P-clamp #2 requires 18 in ext] ~7-12.5 turns Do not release P-clamp on hardline P-clamps are not numbered Release 3 P-clamps closest to QD Egress Bay 11 Verify SAFER handles: <ul style="list-style-type: none"> <input type="checkbox"/> √R Handle down (HCM door – Closed) <input type="checkbox"/> √L Handle down (MAN ISO Valve – Open) Glove Check
Hose Box S1 Bay 13																																																																	
	P-clamp	Tool	Socket																																																														
<input type="checkbox"/>	1 (N)	PGT	6-in ext																																																														
<input type="checkbox"/>	2 (N)	PGT	6-in ext																																																														
<input type="checkbox"/>	3 (N)	Ratchet	2-in ext																																																														
<input type="checkbox"/>	1 (Z)	PGT	6-in ext																																																														
<input checked="" type="checkbox"/>	2 (Z)	PGT	6-in ext																																																														
<input checked="" type="checkbox"/>	3 (Z)	Ratchet	2-in ext																																																														
Stinger S1 Bay 11																																																																	
	P-clamp	Tool	Socket																																																														
<input type="checkbox"/>	1	PGT	6- or 18-in ext																																																														
<input type="checkbox"/>	2	PGT	18-in ext																																																														
<input type="checkbox"/>	3	PGT	6-in ext																																																														
<input type="checkbox"/>	4	PGT	6- or 18-in ext																																																														
<input type="checkbox"/>	5	PGT	6- or 18-in ext																																																														
<input type="checkbox"/>	6	PGT	6* or 18-in ext																																																														

S1 FHRC P-CLAMP RELEASE – TASK DATA

FHRC P-clamps – Hose Box (Outboard)

Legend:
 ○ = P-clamp Location
 ⊗ = TA-clamp (not released)

Hose Box S1 Bay 13

	P-clamp	Tool	Socket
<input type="checkbox"/>	1 (N)	PGT	6-in ext
<input type="checkbox"/>	2 (N)	PGT	6-in ext
<input type="checkbox"/>	3 (N)	Ratchet	2-in ext
<input type="checkbox"/>	1 (Z)	PGT	6-in ext
<input checked="" type="checkbox"/>	2 (Z)	PGT	6-in ext
<input checked="" type="checkbox"/>	3 (Z)	Ratchet	2-in ext

QD: M3/F40
 QD: M4/F41
 QD: M5/F42
 QD: M6/F43

FHRC P-clamps – Stinger (Inboard)

Legend:
 ○ = P-clamp Location
 ⊗ = P-clamp (not released)

Stinger S1 Bay 11

	P-clamp	Tool	Socket
<input type="checkbox"/>	1	PGT	6- or 18-in ext
<input type="checkbox"/>	2	PGT	18-in ext
<input type="checkbox"/>	3	PGT	6-in ext
<input type="checkbox"/>	4	PGT	6- or 18-in ext
<input type="checkbox"/>	5	PGT	6- or 18-in ext
<input type="checkbox"/>	6	PGT	6* or 18-in ext

*wobble reqd w/6-in

QD: M1
 QD: M2

S1 FHRC P-CLAMP RELEASE – TASK DATA (Cont)

Estimated Task Duration:

	With SSRMS	Without SSRMS
One EV Crew	N/A	N/A
Two EV Crew	N/A	00:45

Tools:

EV1
PGT w/7/16 (wobble) Socket-6 ext
Ratchet wrench w/7/16-2 in ext

EVA Fasteners:

Fastener Name	Label	Head Size	Qty	Install Torque (ft-lb)	Release Torque (ft-lb)	Failure Torque (ft-lb)	Turns	RPM
Hosebox P-clamp bolts	1,2,3	7/16	6	N/A	6.0	12.6	6-12.5	30
Stinger P-clamp bolts	Arrow	7/16	6	N/A	6.0	12.6	7-12.5	30

Inhibits:


ORU/Task	Location	Inhibit
S1 P-clamps	Prior to translation to S1	Stbd TRRJ √DLA (1) – LOCKED (0 deg)

Caution:

- Do not impart more than 15 lbf load into the hose box fluid lines



Hose box P-clamps have labels with bolt numbers



Stinger P-clamps have arrow labels for bolts

TOOL RECONFIGURATION (00:30)

I

IV/SSRMS	EV1
<ol style="list-style-type: none"> 1. Start Hatch Thermal Cover clock PET (30 min) ___ : ___ 2. Stop Hatch Thermal Cover clock PET (30 min) ___ : ___ 	<ol style="list-style-type: none"> 1. ← Retrieve Tool Relocate Bag from A/L Staging bag 2. ← Close A/L hatch thermal cover 3. Translate to A/L Toolboxes <p style="text-align: center;"><u>NOTE</u> Tether to toolboard prior to removal for tool stow</p> <ol style="list-style-type: none"> 4. Stow following tools in the Port A/L Toolbox (figure 3): <ul style="list-style-type: none"> <input type="checkbox"/> Behind Zenith Door – Slot 1 (figure 4) <ul style="list-style-type: none"> <input type="checkbox"/> Pin Straightener <input type="checkbox"/> Behind Nadir Door – Slot 5 (figures 5-8) <ul style="list-style-type: none"> <input type="checkbox"/> Short MMOD T-handle tool (tether point aligned with angled slot) <input type="checkbox"/> Short MMOD T-handle tool (tether point aligned with angled slot) 5. Retrieve Large Cutters from Port A/L Toolbox behind Nadir Door (figure 3) 6. Close both doors <ul style="list-style-type: none"> <input type="checkbox"/> Verify at least one lever in lock position for each door 7. Stow following tools in Starboard A/L Toolbox (figure 2): <ul style="list-style-type: none"> <input type="checkbox"/> Inside Zenith Door – Panel 9 (figure 9) <ul style="list-style-type: none"> <input type="checkbox"/> Probe <input type="checkbox"/> Behind Zenith Door – Slot 5 (figure 10) <ul style="list-style-type: none"> <input type="checkbox"/> Vise Grips 8. Close both doors <ul style="list-style-type: none"> <input type="checkbox"/> Verify at least one lever in lock position for each door 9. Translate to A/L zenith, QD Tool Bag #1 (stbd) 10. Stow 1" QD Cap Tool in 1" Cap Tool pocket 11. Retrieve Tool Relocate Bag; stow in A/L 12. Inspect gloves

TOOL RECONFIGURATION (00:30) (Cont)




Figure 1.- A/L Toolbox Panel and Slot Labels.

TOOL RECONFIGURATION (00:30) (Cont)




Figure 2.- A/L Toolbox 1 Stbd.

TOOL RECONFIGURATION (00:30) (Cont)





Figure 3.- A/L Toolbox 2 Port.

TOOL RECONFIGURATION (00:30) (Cont)



Pin Straightener Tool

Figure 4.- Small Cutter Board.






Figure 5.- T-Handle Tool Board.

TOOL RECONFIGURATION (00:30) (Cont)



Figures 6-7.- T-Handle Tool Board Operation.






Figure 8.- T-Handle Tools Stowed on Tool Board.

TOOL RECONFIGURATION (00:30) (Cont)



Probe


Figure 9.- Bolt Puller Panel.



Vise Grips

Figure 10.- Adjustable Wrench Board.


GAP SPANNER INSTALL (00:20)

IV/SSRMS	EV1
 <p>LAB</p> <p>NOD3</p> <p>202</p> <p>201</p> <p>200</p> <p>New gap spanner</p> <p>Not a translation aid</p> <p>WIF 04</p> <p>245</p> <p>239</p> <p>232</p> <p>Existing gap spanner (HR 231-232)</p> <p>PMM</p> <p>Zenith</p> <p>Port</p> <p>Nadir</p> <p>STBD</p>	<p>GAP SPANNER INSTALL (00:20)</p> <ol style="list-style-type: none">1. Retrieve Gap Spanner <div data-bbox="1522 332 1864 425" style="border: 1px solid black; padding: 5px; text-align: center;"><p>CAUTION Do not use Node 3 jumpers as a translation aid</p></div> <ol style="list-style-type: none">2. Translate to nadir to Lab HR 239 via existing gap spanner3. Attach local tether4. Attach one end of gap spanner to forward stanchion of Lab HR 2395. Translate to Lab HR 201 (okay to use WIF 4)6. Attach second end of gap spanner to forward stanchion of Lab HR 2017. Tighten gap spanner until buckle can twist 90°


TOOLS AND STOWAGE

STARBOARD LIGHTWEIGHT TOOL STOWAGE ASSEMBLY (TSA).....	TEMP FS 8-2
PGT CHECKOUT	8-3
PGSC-PGT CONNECTION (A31P AND 760XD)	8-4
PROGRAM PGT SETTINGS	8-5
DOWNLOAD/ERASE EVENT LOG	8-5
PGT CONTINGENCIES.....	8-6
PGT STANDARD SETTINGS.....	8-7
SAFETY TETHERS – STS-135 (ULF7).....	FS 8-9
APFR MANAGEMENT – STS-135 (ULF7)	FS 8-10
CETA CART WIF AND SWINGARM MANAGEMENT TABLE – STS-135/ULF7	FS 8-11
TOOLBOX STOWAGE – STS-135 (ULF7).....	FS 8-12
TOOLBOX PANEL AND SLOT LABELS	FS 8-13
Z1 TOOLBOX INTERNAL LAYOUT	FS 8-14
AIRLOCK TOOLBOX INTERNAL LAYOUT	FS 8-15
FLUID QD BAG LAYOUT	FS 8-16
CREW TETHER INSPECTIONS	FS 8-19
CLPA IVA UNPACKING	FS 8-26
CLPA CONFIGURE AND PACK FOR STOWAGE.....	FS 8-29
MISSE 8 ORMATE III R/W PREP FOR EVA.....	FS 8-39
MISSE 8 ORMATE III R/W POST EVA COVER STOWAGE	FS 8-40


STARBOARD LIGHTWEIGHT TOOL STORAGE ASSEMBLY (TSA)



Aft Tray Layout and Labels



Forward Tray Layout and Labels



TOOLS AND STOWAGE

SAFETY TETHERS – STS-135 (ULF7)

55-FT SAFETY TETHERS

	#67 s/n 1017 Lg-sm	#68 s/n 1018 Lg-sm (retracting issues – ULF4)	#69 s/n 1019 Lg-sm	#72 s/n 1022 Lg-sm
ULF6 Stage	INSIDE: Tether staging area	INSIDE: Tether staging area	INSIDE: Tether staging area	INSIDE: Tether staging area
Post EVA 1	INSIDE: Tether staging area	INSIDE: Tether staging area	INSIDE: Tether staging area	INSIDE: Tether staging area

STP = Safety Tether Pack

85-FT SAFETY TETHERS

	#21 s/n 1001 Lg-sm (GMT201 Tether Inspect – only 1 through tack stitch)	#22 s/n 1002 Lg-sm (2 J/A – retracting issue)	#24 s/n 1004 Lg-sm	#23 s/n 1003 Lg-sm	#26 s/n 1006 Lg-sm	#29 s/n 1009 Lg-sm	#25 s/n 1005 Lg-sm	#27 s/n 1007 Lg-sm
ULF6 Stage	INSIDE: Tether staging area	INSIDE: C/L deployed in STP	INSIDE: C/L deployed in STP	INSIDE: C/L deployed in STP	INSIDE: C/L deployed in STP	INSIDE: Tether staging area		
ULF7 EVA 1	INSIDE: Tether staging area	Used in STP w/#24	Used in STP w/#22	Used in STP w/#26	Used in STP w/#23	Spare in Staging Bag	STS-135/ULF7 Middeck	STS-135/ULF7 Middeck
ULF7 Stage	RETURNED: STS-135/ULF7 Middeck	RETURNED: STS-135/ULF7 Middeck	INSIDE: Tether staging area	INSIDE: Tether staging area	INSIDE: Tether staging area	INSIDE: Tether staging area	INSIDE: Tether staging area	INSIDE: Tether staging area

APFR MANAGEMENT – STS-135 (ULF7)

APFR DESIGNATOR	APFR 1 s/n 1004 (sticky pitch knob – 8A, 13A.1, 1JA)	APFR 2 s/n 1006 (sticky pitch knob – US 7 & 9, sticky locking collar – 10A)	APFR 3 s/n 1005 (suspected sharp edge on locking collar and possible sticky locking collar – US 7)	APFR 4 s/n 1002 (heat shield removed on ULF5)	APFR 5 s/n 1003 (sticky pitch knob – ULF4; heat shield removed on ULF3)	APFR 6 s/n 1007 (sticky pitch knob – 20A; heat shield removed on 12A.1 stage)	APFR 7 s/n 1008 (possible sticky locking collar – ULF4)	IAPFR 1	IAPFR 2	OTSD	WIF Extender
ULF6 Stage	Z1 WIF 13 [3,QQ,F,12] TS	P1 WIF 3 [6,PP,F,11] TS	ESP-2 WIF 06 [10,FF,A,3] Ingress Aid	Stbd CETA Cart WIF 4 [12,GG] [9,PP,F,6]	Port CETA Cart WIF 2 [6,GG] [12,TT,F,6]	COL WIF 3 [6,NN,F,6] Ingress Aid	P6 WIF 12 [3,OO,F,12] Ingress Aid	Z1 WIF 5 [12,PP,F,12]	Z1 WIF 3 [6,PP,F,12]	S0 WIF 7 CL=7	ESP-2 WIF 3 [3,A,1]
ULF7 EVA 1	Z1 WIF 13 [3,QQ,F,12] TS	P1 WIF 3 [6,PP,F,11] TS	SSRMS [12,NN,F,6] Ingress Aid	Stbd CETA Cart WIF 4 [12,GG] [9,PP,F,6]	Port CETA Cart WIF 2 [6,GG] [12,TT,F,6]	COL WIF 3 [6,NN,F,6] Ingress Aid	P6 WIF 12 [3,OO,F,12] Ingress Aid	Z1 WIF 5 [12,PP,F,12]	Z1 WIF 3 [6,PP,F,12]	S0 WIF 7 CL=7	ESP-2 WIF 3 [3,A,1]
ULF7 Stage	Z1 WIF 13 [3,QQ,F,12] TS	P1 WIF 3 [6,PP,F,11] TS	ESP-2 WIF 05 [low profile] Ingress Aid	Stbd CETA Cart WIF 4 [12,GG] [9,PP,F,6]	Port CETA Cart WIF 2 [6,GG] [12,TT,F,6]	COL WIF 3 [6,NN,F,6] Ingress Aid	P6 WIF 12 [3,OO,F,12] Ingress Aid	Z1 WIF 5 [12,PP,F,12]	Z1 WIF 3 [6,PP,F,12]	S0 WIF 7 CL=7	ESP-2 WIF 3 [3,A,1]

Crane (old ORU tether)	ORU Stanchion/TERA Headless	APFR 2 Tool Stanchion	APFR 1 Tool Stanchion	Tool Stanchion
PMA1 WIF 5	S0 port wedge face	Hex pointed ISS zenith, tool head pointed ISS stbd, and oriented ISS Zenith/Nadir	Tool stanchion port, pointed zenith	S0 port wedge face

CETA CART WIF AND SWINGARM MANAGEMENT TABLE – STS-135/ULF7

WIF Designator	CETA 1 (port) WIF 1 Port-nadir	CETA 1 (port) WIF 2 Stbd-nadir	CETA 1 (port) WIF 3 Stbd-zenith	CETA 1 (port) WIF 4 Port-zenith	CETA 1 (port) WIF 5 Port-middle	CETA 2 (stbd) WIF 1 Port-nadir	CETA 2 (stbd) WIF 2 Stbd-nadir ULF4: Pitch setting stuck in FF	CETA 2 (stbd) WIF 3 Stbd-zenith	CETA 2 (stbd) WIF 4 Port-zenith	CETA 2 (stbd) WIF 5 Port-middle
Post STS 133	[30,1,LL]	[0,6,GG]	[1,12,GG]	[12,DD]	[12,DD]	[0,12,GG]	[0,12,FF]	[1,12,GG]	[12,GG]	[12,GG]
Post STS 135

CETA 1 (port) Port Brake Handles	CETA 1 (port) Stbd Brake Handles	CETA 2 (Stbd) Port Brake Handles	CETA 2 (Stbd) Stbd Brake Handles
Folded over and wire tied to each other Handles FWD and NOT wire tied to cart	Straight and Locked No Wire Ties	Straight and Locked No Wire Ties	Straight and Locked No Wire Ties

NOTE

- Settings highlighted red are unconfirmed. This table was created during STS-132/ULF4. All WIFs and swingarms not used on ULF4 are assumed unconfirmed
- PORT CETA cart is NOT configured for translation to WS 8 unless the SARJ is parked for the duration
- STBD CETA cart is NOT configured for translation to WS 1 unless the SARJ is parked for the duration


TOOLBOX STOWAGE – STS-135 (ULF7)

	Z1 PORT TOOLBOX (MMOD Damage – potential sharp edges) {all slots have sliders}	Z1 STBD TOOLBOX (MMOD Damage – potential sharp edges) {all slots have sliders}	A/L TOOLBOX 1 (STBD)	A/L TOOLBOX 2 (PORT)
SLOT # 1	SQUARE TM BOARD {stbd door} SQ TORQUE MULTIPLIER 7/16" FLUSH SQ SOCKET 7/16" PROUD SQ SOCKET 7/16" RECESSED SQ SOCKET		HAMMER BOARD {nadir door} HAMMER	CABLE CUTTER BOARD {zenith door} COMPOUND CUTTERS (SM) SCISSORS
SLOT # 2		QD BAIL TOOL BOARD {stbd door} BMRRM LATCH TOOL QD BAIL DRIVE TOOL (1")	PLIERS BOARD {nadir door} NEEDLE NOSE PLIERS	
SLOT # 3	RATCHET BOARD {middle} 7/16" X 12" WOBBLE SOCKET 7/16" X 2" RIGID SOCKET	RATCHET BOARD {middle} 7/16" X 6" WOBBLE SOCKET 7/16" X 12" WOBBLE SOCKET RATCHET WRENCH RIGHT ANGLE DRIVE	{only slot with slider}	{only slot with slider}
SLOT # 4				
SLOT # 5	ROUND TM BOARD {port door} RND TORQUE MULTIPLIER 5/8" PROUD RND SOCKET 7/16" FLUSH RND SOCKET 7/16" PROUD RND SOCKET		ADJ WRENCH BOARD {zenith door} FORCEPS WRENCH, ADJ	T-HANDLE TOOL BOARD {nadir door} 1-8" T-TOOLS
SLOT # 6	TRASH BAG BOARD {stbd door} SMALL TRASH BAG	TRASH BAG BOARD {stbd door}	HYDRAZINE BRUSH BOARD { nadir door} HYDRAZINE BRUSH	
SLOT # 7	SOCKET BOARD {port door} 5/32" BALL END ALLEN DR 1/2" X 8" WOBBLE SOCKET 5/16" X 7" RIGID SOCKET	SOCKET BOARD {port door} 5/32" BALL END ALLEN DR 1/2" X 8" WOBBLE SOCKET 5/16" X 7" RIGID SOCKET	PRD (Toolboard) {zenith door} PRD	PRD (Toolboard) {nadir door} PRD
PANEL # 8	CHEATER BAR PANEL {stbd door} CHEATER BAR GP CADDY CANNON CONNECTOR TOOLS (2)	CHEATER BAR PANEL {stbd door} CHEATER BAR ADJ EQUIP TETHER	TOOL CADDY PANEL {nadir door}	
PANEL # 9	18" SOCKET PANEL {port door} 7/16" X 18" WOBBLE SOCKET	18" SOCKET PANEL {port door} 7/16" X 18" WOBBLE SOCKET	BOLT PULLER PANEL {zenith door} BOLT PULLER MECHANICAL FINGER	LARGE CUTTER PANEL {nadir door} LARGE CUTTERS (-303)
EXTERNAL	1 ROUND SCOOP w/D-HANDLE (on zenith micro) (D-handle taped over repaired MMOD damage) D-HANDLE on port side of toolbox	<u>NOTE</u> D-Handle will not stow on the side of this toolbox due to an interference with the CMG MLI		


TOOLBOX PANEL AND SLOT LABELS

NOTE

- A/L Toolbox: Slider feature located in center slot only (#3)
- Z1/CETA Toolbox: Slider feature located in all slots




Z1 TOOLBOX INTERNAL LAYOUT



DOORS SHOWN REMOVED AND ROTATED 180°
FROM CLOSED POSITION FOR CLARITY.


AIRLOCK TOOLBOX INTERNAL LAYOUT



FLUID QD BAG LAYOUT

QD TOOL BAG #1, STBD (SEG33114667-301/1001)			
#	TOOL	PART#/SERIAL #	LOCATION IN BAG
1.	¼" CAP TOOL	GD2043725	¼" Cap Tool Pkt
2.	½" CAP TOOL	GD2043730	½" Cap Tool Pkt
3.	1" CAP TOOL	GD2043325	ISS A/L Internal
4.	¾" & 1' QD BAIL DRIVE LEVER	SDG33113838-703	¾" & 1" QD Bail Drive Lever Pouch on Lid
5.	1.5" QD BAIL DRIVE LEVER	SDG33113837-701	1.5" QD Bail Drive Lever Pouch on Lid
6.	1.5" NH3/N2 VENT TOOL – F	1F9859-1/01	Pkt F: 1.5" NH3/N2
7.	1" H2O/N2 VENT TOOL – F	1F98593-1/01	Pkt E: 1" H2O/N2
8.	¾" NH3/N2 VENT TOOL – F	1F98597-1/01	Pkt D: ¾" NH3/N2
9.	1" NH3/N2 VENT TOOL – F	1F98589-1/T	Pkt A: 1" NH3/N2
10.	1" NH3/N2 VENT TOOL – M	1F98596-1/01	Pkt B: 1" NH3/N2 (male tool)
11.	¼" NH3/N2 VENT TOOL – F	1F98592-1/01	Pkt C: ¼" NH3/N2
12.	1.5" QRT & FID GAUGE	SEG33114617-701	Pkt FID/Gauge
13.	¾" & 1" QRT & FID GAUGE	SEG33114616-701	Pkt FID/Gauge

- Ensure cap tools (3) are friction fitted
- Close all QRT tool flaps (2)
- Close all vent tool flaps (6)



- Close bail drive lever flaps (2)
- Internal bag straps (2) should be stowed in pouches



FLUID QD BAG LAYOUT (Cont)

QD TOOL BAG #2, PORT (SEG33114667-301/1002)			
#	TOOL	PART #/SERIAL #	LOCATION IN BAG
1.	¼" Cap Tool	GD2043725	¼" Cap Tool Pkt
2.	½" Cap Tool	GD2043730	½" Cap Tool Pkt
3.	1.5" NH3/N2 Vent Tool – F	1F9859-1/02	Pkt F: 1.5" NH3/N2
4.	1" H2O/N2 Vent Tool – F	1F98593-1/02	Pkt E: H2O/N2
5.	¾" NH3/N2 Vent Tool – F	1F98597-1/02	Pkt D: ¾" NH3/N2
6.	¼" NH3/N2 Vent Tool – F	1F98592-1/02	Pkt C: ¼" NH3/N2
7.	¼" BDT	SEG33114984-301/001	Pkt C: ¼" NH3/N2 w/adj tether
8.	¾" BDT	SEG33114986-301/001	Pkt C: ¼" NH3/N2 w/adj tether
9.	¾" AKT	SEG33114983-301/1001	Pkt FID/Gauge: Stowed w/Adj tether to int loop
10.	Vent Tool Adapter	SEG33119079-301	Pkt FID/Gauge: Stowed w/Adj tether to int loop

¾" BDT is tethered to internal bag loop using integral tool tether

¾" AKT stowed with VTAs in QRT/FID pouch

¼" and ¾" BDTs are stowed on top of ¼" vent tool



Vent Tool Adapters (2) are stowed in QRT/FID gauge pockets and need adj tethers

Only 1 currently in QD bag

VENT TOOL ADAPTER STOWAGE

FLUID QD BAG LAYOUT (Cont)

VENT TOOL EXTENSION BAG (SEG33119100-301/1001)			
	TOOL	PART#	LOCATION POST ULF5
1.	Vent Tool Extension	SEG33119090-301	VTEB with VTE plug
2.	MUT EE		VTEB Connected to VTE L-bracket
3.	Vent Tool Adapter	SEG33119079-301	VTEB
4.	1" NH3/N2 Vent Tool – F	1F98589-1	VTEB
5.	Vent Tool Extension Plug		VTEB Mated to VTE – french hook to VTE



S116E06137

PUMP MODULE JUMPER BAG (SEG33119100-301)			
#	TOOL	PART #	LOCATION IN BAG
1.	PUMP MODULE JUMPER ASSY	1F15818	<input type="checkbox"/> TETHERED BY 1 INTEGRAL TETHER TO HR ON JUMPER

CREW TETHER INSPECTIONS

OBJECTIVE:

Inspect Load Alleviating Strap (LAS) on Safety Tethers, Waist Tethers and soft strap on D-Ring extenders. Prior to each set of EVAs (shuttle or ISS), all on-board tethers are to be inspected. Between each EVA, only those tethers used during the previous EVA require inspection.

DURATION:

1 hour 30 minutes (Parts 1 and 2 on six waist tethers, six D-Ring extenders, and eight safety tethers)

Additional 30 minutes required to perform Part 3 on two tethers.

NOTE

Standard tool config prep times only protect for performing Part 1 between EVAs on tethers used during the previous EVA.

ITEMS REQUIRED (PART 2 OR 3):

MATERIALS:

Sharpie

Ziplock Bag

TOOLS:

Camera

IS IVA Toolbox:

Drawer 5:

 Tape Measure

Tape Pantry

EVA Tape (1" Permacel Glass Cloth Tape) P/N P-213

PART 1: PRIOR TO EACH EVA

1. Prior to EVA use, soft goods on each safety tether (LAS), waist tether (LAS) and D-Ring extender (strap) for that EVA must be inspected.

1.1 MMOD Inspection

Inspect the soft goods (LAS) of the Waist Tether and ERCM/Safety Tether and soft strap of the D-Ring extender for MMOD damage and discoloration, manipulating the sheath as needed to inspect between folds. The damage may appear as small or large holes in the LAS or as a tear/rip in the sheath. The MMOD damage may also appear in small concentrated areas of excessive fraying (as would be expected to be found in the vicinity of a hole). Soft goods should be white to yellow or tan in appearance. Soft goods showing a burnt brown or black discoloration should not be used. Refer to Figures 1, 2, 3.

CREW TETHER INSPECTIONS (Cont)

1.2 D-Ring Extender

Inspect the soft strap of the D-Ring extender for MMOD damage, excessive wear and fraying.

Refer to Figures 1, 2, 3.




Figure 1. Damage Masked by Folds in LAS Sheath Exposed When Unbunched. (Note: Photo of ground-created damage.)




Figure 2. Picture Showing MMOD Damage Found in Flight AET.



Figure 3. Frayed D-Ring Extender; No-GO for Use.

1.3 LAS Base Inspection

Inspect base of LAS where strap attaches to ERCM D-Ring for any damage. Refer to Figure 4.

1.3.1 Smudging is acceptable.

CREW TETHER INSPECTIONS (Cont)

- 1.3.2 If safety tether anchor hook is taped, inspect tape for wear or damage.



Figure 4. LAS Attachment to ERCM D-Ring.

1.4 Tack Stitching Inspection

Verify two surface and two through tack stitches still present on each LAS (waist tether and safety tether).

- 1.4.1 Verify through stitches still intact by gently moving sheath away from hook to expose threads through Nomex. Refer to Figures 5 and 6. Once verified, gently replace sheath over red indicator.

- 1.4.2 Visually verify surface stitches on nonseam side of tether

1.5 Red Indicator Inspection

If red showing and all tack stitches present

- 1.5.1 Gently pull the sheath back to cover red indicator. Due to tolerances, some red may still show (tether is GO as long as tack stitching still present.)
- 1.5.2 Note width of any remaining red showing.
- 1.5.3 Report S/N of any tethers with red still showing to **MCC-H**.




Figure 5. Top View (Non-Seam Side) and Bottom View (Seam Side).

CREW TETHER INSPECTIONS (Cont)




Figure 6. Cross-Section of Tack Stitching.

2. Report serial numbers to **MCC-H** with inspection results.
3. For any tethers with MMOD/other damage, fraying or missing tack stitching, proceed to Part 2.
4. Restow remaining tethers.

PART 2: MMOD DAMAGE/MISSING TACK STITCHING EVALUATION

5. Retrieve Camera and Ziplock Bag(s).
6. If MMOD damage is found on LAS
 - 6.1 Smooth out the sheath at the damage location and take detailed photos of damage (with serial number in photo if possible). Refer to Figures 7 and 8. Note if any damage to the underlying Nomex strap is visible.
 - 6.2 Remove tether from usable inventory. Place tether in Ziplock Bag labeled, "No-GO for use". Report location and S/N to **MCC-H**.
 - 6.3 Report results to **MCC-H**.



Refer to Figure 8 for correct label location. For Waist Tethers, ensure label says Waist Tether Assy.

Figure 7. Photo of Partial Red Indicator Showing with Serial Number.

CREW TETHER INSPECTIONS (Cont)




Figure 8. Serial Number References.

7. If tack stitches are broken
 - 7.1 Take detailed photos of tack stitches (with serial number in photo) for further engineering evaluation. Refer to Figure 7.
 - 7.2 Stow tethers per Table 1.

Table 1. Tether GO/No-GO Criteria

Broken Stitch	Action
One or both surface stitches broken	Gently smooth sheath away from hook so only a single layer covers the red indicator area. Return tether to usable inventory.
One through stitch broken, one through stitch intact and zero to two surface tack stitches intact	Return tether to usable inventory.
Two through stitches broken	Remove tether from usable inventory. Place tether in Ziplock Bag labeled "No-GO for use." Report location to MCC-H .

- 7.3 Report results to **MCC-H**.
8. If fraying or MMOD damage is found on D-Ring extender
 - 8.1 Take detailed photos of damage showing S/N of extender (if possible). Refer to Figure 9.
 - 8.2 Remove tether from usable inventory. Place tether in Ziplock Bag labeled "No-GO for use." Report location and S/N to **MCC-H**.

CREW TETHER INSPECTIONS (Cont)

- 8.3 Report results to **MCC-H**.



Figure 9. D-Ring Extender Showing Serial Number.

9. If damage found on LAS base
- 9.1 Take detailed photos of damage with at least one photo showing tether number.
 - 9.2 Swap tether for spare.
 - 9.3 Remove tether from usable inventory.
Place tether in Ziplock Bag labeled "No-GO for use."
Report location and S/N to **MCC-H**.
 - 9.4 If tape damaged/worn on anchor hook, take detailed photos.
Replace tape as necessary using EVA tape.
 - 9.5 Report results to **MCC-H**.

PART 3: MEASURE LAS LENGTH (ON MCC-H GO)

- 10. Retrieve quarantined tethers, tape measure, Sharpie, and Camera.
- 11. Mark the desired length on a stable surface.
Refer to Figures 10 and 11 for required lengths.
- 12. Measure quarantined tether against markings.
Photograph results.
- 13. Report findings to **MCC-H**.
- 14. Stow tethers per **MCC-H** direction.




Figure 10. Waist Tether.

CREW TETHER INSPECTIONS (Cont)




Figure 11. Safety Tether.

Table 2. Inspection Results

Tether Type	Tether S/N	Damage Description	Tether Location

CLPA IVA UNPACKING

CAUTION

Extreme care should be exercised to avoid touching the white thermal paint on the camera, as it is easily removed. Scuffing the paint may reduce the CLPA life due to overheating, or it may reduce the allowed operational timelines to prevent overheating

The electrical grounding tabs and the connectors at the base of the unit should not be touched

The unit has an awkward center of mass, making it uncomfortable to handle. When possible, it is recommended to hold the unit from the tether point and micro fixture

1. Retrieve CLPA Protective Case
2. Release belts, pull-tabs, and beta cloth cover (in order); fold beta cloth cover on itself
3. Open two shells to expose mounted CLPA on base plate and ORU interface (fig 1)
4. Using a ratchet wrench w/7/16-in socket, drive EVA bolt ccw, ~22-23 turns
NOTE: Running torque should not exceed 75 in-lb (fig 2)
5. Verify EVA bolt driven out to hard stop
6. CLPA should slide freely from the base plate. It may be necessary to loosen four nuts on top of alignment guides (fig 3)
7. Visually verify blindmate connector cover removed
8. Retrieve MSS camera cover (P/N 51612-4968-551) (1.0 CTB 1078)
9. Rotate locking lever to open/unlocked position (lever perpendicular to plane of lens)
10. Install MSS camera cover onto CLPA by inserting spring loaded flange to depress spring
11. Rotate cover to seat against camera bracket for full installation
12. Rotate locking lever to closed/locked position (lever parallel to plane of lens)
13. Perform pull test
14. Install Sq scoop and place CLPA in ORU bag per tool config
15. Close shells on base. Secure Velcro straps, belts, and beta cloth cover
16. Stow CLPA Protective Case and MSS camera cover case (in mesh bag for use post EVA 1)



CLPA IVA UNPACKING (Cont)




Figure 1




Figure 2

CLPA IVA UNPACKING (Cont)




Figure 3




Figure 4

CLPA CONFIGURE AND PACK FOR STOWAGE

OBJECTIVE:

Rotate the CLPA Camera Joints (Yaw and Pitch) into position then pack in protective gear for stowage and return.

LOCATION:

US Lab

DURATION:

If no Star Block (18.1 thru 18.11) required
30 mins / 1 crew

If Star Block (18.1 thru 18.11) required
1hr 15 min / 1 crew

PARTS:

CLPA Camera

MSS Camera Cover

MSS Camera Cover Bag

3.0 CTB S/N 1088, B/C 006745J, Label: CAMERA LIGHT AND PAN/A
ASSEMBLY

1.0 CTB S/N 1078, B/C 004072J

MATERIALS:

MWA Utility Kit

Seat Track Restraints (2)

ORU Clamps (2)

TOOLS REQUIRED:

Drawer 2:

Ratchet, 3/8" Drive;

7/16" Deep Socket, 3/8" Drive

(40-200 in-lbs) Trq Wrench, 3/8" Drive

7/16" EVA Socket, 3/8" Drive

REFERENCED PROCEDURE(S):

A.2.6 MAINTENANCE WORK AREA (MWA) INSTALLATION

CAUTION

KEEP OUT ZONES - Do not touch the area of the Camera Lens, Light Lens, Cables, grounding tabs and connectors. Touching them may contaminate a ground analysis of space environment degradation or may damage connector for future use.

CLPA CONFIGURE AND PACK FOR STOWAGE (Cont)

SECURE CAMERA TO SEAT TRACK




Figure 1: MWA Track Restraints with ORU Clamps




Figure 2: Initial Position of Camera: Installed on Rack Seat Track using MWA Track Restraints with ORU Clamps

1. Remove Sq scoop and stow in EVA done mesh bag
2. Install 'bottom' MWA Track Restraint with ORU Clamp onto Rack seat track (reference A.2.6 MAINTENANCE WORK AREA (MWA) INSTALLATION) as shown in Figures 1 and 2.

CLPA CONFIGURE AND PACK FOR STOWAGE (Cont)

3. On Camera Base, turn EVA Microconical Tie Down Bolt counter clockwise (loosen) to hardstop to ensure bolt is fully retracted [Ratchet, 3/8" Drive; 7/16" EVA Socket, 3/8" Drive].
4. Place Camera Soft Dock Magnet Plate onto 'bottom' MWA Track Restraint with ORU Clamp and secure Camera using 'top' MWA Track Restraint with ORU Clamp as shown in Figures 1 and 2.

ROTATE CAMERA INTO STOWAGE CONFIGURATION

NOTE

Torque required to overcome motor gearing and begin rotational motion is estimated to be 20 to 30 foot pounds. Once rotation begins, it is estimated to take 5 to 10 foot pounds to continue rotational motion.




Figure 3: Rotate Mast Axis (Yaw) to Horizontal

5. Rotate the camera and light around Mast Axis (Camera Yaw) approximately 20 degrees until aligned horizontally as shown in Figure 3.

CLPA CONFIGURE AND PACK FOR STOWAGE (Cont)





Figure 4: Final Position - Rotate Camera Pitch Axis 90 degrees Clockwise

6. Rotate the camera and light around the Camera Axis (Camera Pitch) approximately 90 degrees until aligned as shown in Figure 4.

STOW CAMERA


7. Remove Camera from the MWA Track Restraints with ORU Clamps and temp stow.
8. Install 1/2" Thick Baseplate with Delrin Blocks inbetween the MWA Track Restraints with ORU Clamps. Move MWA Track Restraints on Seat Track as required.

CLPA CONFIGURE AND PACK FOR STOWAGE (Cont)



Secure 1/2" thick baseplate to Rack Seat Track using MWA Track Restraints with ORU Clamps.

Figure 5: Camera Installation onto 1/2" Thick Baseplate



Delrin Block "A" - one each side

Delrin Blocks "B" - two each side

Figure 6: Detail: 1/2" Thick Baseplate and Delrin Blocks "A" and "B" interface

CLPA CONFIGURE AND PACK FOR STOWAGE (Cont)

9. Loosen but do not remove base plate nuts (four) on each Delrin Block "A" [Ratchet, 3/8" Drive; 7/16" Deep Socket, 3/8" Drive]. Reference Figures 5 and 6.
10. Slide each block "A" outward.
11. Align and install Camera on the 1/2" Thick Baseplate and slide each Delrin Block "A" against the Camera guides. Tighten base plate nuts (four) on each Delrin Block "A" [Ratchet, 3/8" Drive; 7/16" Deep Socket, 3/8" Drive].
12. Torque base plate nuts (four) on each Delrin Block "A" to 50 in-lbs. [(40-200 in-lbs) Trq Wrench, 3/8" Drive; 7/16" Deep Socket, 3/8" Drive].
13. Rotate locking lever of CLPA MSS camera cover to the open/unlocked position (lever perpendicular to plane of lens)
14. Remove MSS camera cover from CLPA by depressing spring and rotating cover
15. Rotate locking lever to the closed/locked position (lever parallel to plane of lens)
16. Stow MSS camera cover into camera cover bag
17. Stow cover and bag into 1.0 CTB 1078

CLPA CONFIGURE AND PACK FOR STORAGE (Cont)




Figure 7: Camera Packaging Exploded View

18. Assemble the two Protective Shells around the Camera, reference Figure 7. Ensure interlocking side feature and interlocking feature to baseplate is engaged and closed completely.

CLPA CONFIGURE AND PACK FOR STOWAGE (Cont)

*
* If Protective Shell interlocking side feature or interlocking baseplate feature
* does not engage correctly, adjust Camera on Baseplate as follows:

*
* 18.1 Remove Protective Shells

*
* 18.2 Loosen but do not remove base plate nuts (eight) on each Delrin
* Block "A" and each Delrin Block "B" [Ratchet, 3/8" Drive; 7/16"
* Deep Socket, 3/8" Drive]. Reference Figures 5 and 6

*
* 18.3 Slide all six Delrin Blocks outboard.

*
* 18.4 Center Camera within the loosened Delrin Blocks, slide all six
* Delrin Blocks against the Camera guide, then by hand tighten
* lightly base plate nuts (eight) on each Delrin Block "A" and each
* Delrin Block "B".

NOTE
Since Camera is not tight, it should self-center as the closed shells locate the camera to the correct position within its internal clamps. Adjust sliding blocks (A and B) on the base plate as required to allow camera to center between the Protective Shells.

*
* 18.5 Assemble the two Protective Shells around the Camera such that
* they are centered on the base plate, reference Figure 7. Ensure
* interlocking side feature and interlocking feature to baseplate is
* engaged and closed completely.

*
* 18.6 Remove Protective Shells without moving Camera on the base
* plate.

*
* 18.7 Without moving the Camera, slide one of the Delrin Block 'A' away
* from the Camera. Ensure one corner for each of the Delrin Blocks
* "B" (two) is now pressed against the Camera base and adjust as
* required. Torque baseplate nuts (two) on Delrin Block "B" to 50 in-
* lbs. [(40-200 in-lbs) Trq Wrench, 3/8" Drive; 7/16" Deep Socket,
* 3/8" Drive].

*
* 18.8 Repeat adjustment and torquing for the opposite side of Delrin
* Blocks "B".

*
* 18.9 Verify that the Camera can move out of plane with the base plate
* and that it realigns to base plate such that only one position is
* possible. Repeat Delrin Block B adjustment as required to obtain
* this alignment. After final positioning, install Camera onto
* baseplate.

*
*
*
*
*
*
*
*
*
*
*

CLPA CONFIGURE AND PACK FOR STORAGE (Cont)

- 18.10 Slide Delrin Block "A" into position over Camera guide and torque base plate nuts (four) on each Delrin Block "A" to 50 in-lbs. [(40-200 in-lbs) Trq Wrench, 3/8" Drive; 7/16" Deep Socket, 3/8" Drive].
- * *
- * 18.11 Assemble the two Protective Shells around the Camera, reference Figure 7. Ensure interlocking side feature and interlocking feature to baseplate is engaged and closed completely.
- * *




Figure 8: Final Packaging in 3.0 CTB

- 19. Secure Protective Shell Velcro ensuring case is closed. Install Beta cloth blanket cover on side cut out. Secure base plate Velcro. Reference Figure 8.
- 20. Install Shorter Velcro belt tightly around Protective Shells and over baseplate Velcros.
- 21. Install Longer Velcro belt by passing it under the baseplate.

CLPA CONFIGURE AND PACK FOR STOWAGE (Cont)

22. Install Foam Pads as shown in Figures 7 and 8.

23. Photo document Camera package.

24. Transfer camera package to Shuttle for return.

POST MAINTENANCE

25. Update IMS with stowage location of stowed Camera

26. Inform MCC-H of task completion

27. Stow tools, materials, equipment --

MISSE 8 ORMATE III R/W PREP FOR EVA

1. Retrieve MISSE 8 ORMATE III R/W
2. Remove MISSE 8 ORMATE III R/W from bag
3. Verify Velcro strap holding cover is secure
4. Configure MISSE 8 ORMATE III R/W per EVA Tool Config
5. Fold bag opening over and tape closed to prevent FOD from contaminating bag.
(Type of tape does not matter)
6. Stow bag in Equipment Lock for use post EVA

MISSE 8 ORMATE III R/W POST EVA COVER STOWAGE

1. Retrieve MISSE 8 ORMATE III R/W cover from Crew Lock
2. Stow cover in protective bag (stowed in Equipment Lock for EVA)
3. Fold bag opening over and tape closed to prevent FOD from contaminating bag.
(Type of tape does not matter)
4. Stow bag in mesh bag labeled "Done Tools"

EMU MAINT/RECHARGE

WATER RECHARGE..... TEMP FS 10-2
 EMU POWERUP..... TEMP FS 10-2
 WATER FILL TEMP FS 10-2
 WATER FILL VERIFICATION TEMP FS 10-2
EMU LiOH CHANGEOUT 10-4
MIDDECK EMU BATTERY RECHARGE (STAND-ALONE)..... 10-4a
MIDDECK EMU BATTERY RECHARGE/LiOH REPLACEMENT 10-5
 INITIATE 10-5
 TERMINATE..... 10-6
IN-SUIT EMU BATTERY RECHARGE/CHARGE VERIFICATION..... 10-7
 INITIATE 10-7
 TERMINATE..... 10-7
EMU POWERDOWN 10-7
HELMET LIGHT/PGT BATTERY RECHARGE 10-8
 INITIATE 10-8
 TERMINATE..... 10-9
REBA BATTERY INSTALLATION 10-9
EMU BATTERY REMOVAL/INSTALL 10-10
HELMET LIGHT BULB CHANGEOUT 10-11
REBA BATTERY RECHARGE 10-12
 INITIATE 10-12
 TERMINATE..... 10-13
STS-135 CONSUMABLES TRACKING CUE CARD FS CC 10-15

WATER RECHARGE

IF EMU NOT ALREADY POWERED UP:

EMU POWERUP

- BOTH DCM 1. Retrieve, position SCUs; remove DCM covers
 2. Connect SCUs to DCM, √locked
 3. PWR – BATT

CAUTION

EMU must be on BATT pwr when
 airlock pwr supply is turned on

- AW18H 4. PWR/BATT CHGR EMU 1,2 MODE (two) – PWR
 BUS SEL (two) – MNA(MNB)
 MD(flir) 5. √EMU O2 ISOL VLV – OP
 AW82B 6. EV1,2 O2 vlv (two) – OP
 DCM 7. PWR – SCU

WATER FILL

- MO13Q 8. √ARLK H2O S/O VLV – OPEN (tb-OP)
 R11L 9. √SPLY H2O TKA OUTLET – CL (tb-CL)

SM 60 TABLE MAINT

- CRT 10. Use TKB quantity:
 PARAM ID – ITEM 1 +0 6 2 0 4 2 0 EXEC
 11. Log value before recharge

Recharge #	H2O TKB %
1	
2	
3	
4	
5	

- AW82D 12. √EMU 1,2 H2O WASTE tb (two) – CL
 SPLY (two) – OP (tb-OP)
 13. √H2O TKB quantity decreasing

NOTE

Full charge requires ~15 min

WATER FILL VERIFICATION

- DCM 14. √STATUS: **H2O WP** 8-15 psi and stable for ~30 sec (indicates charging complete)

SM 60 TABLE MAINT

- CRT 15. Use TKB quantity:
 PARAM ID – ITEM 1 +0 6 2 0 4 2 0 EXEC
 16. Log value after recharge

Recharge #	H2O TKB %
1	
2	
3	
4	
5	

EMU MAINT/
 RECHARGE

Cont next page

TEMP FS 10-2

TOP

HOOK
VELCRO

STS-135 CONSUMABLES TRACKING CUE CARD

		EVA 1
METOX for CO2 Removal in A/L	Serial Numbers	07, 11

PWR Usage: 1015 as required

Dump CWC: 1059 as required

	EV	EMU	LiOH (s/n)	EMU LIB Batt (s/n)	REBA (s/n)	EHIP (HL) Batts (s/n)	ERCA (address)	SAFER (s/n)	PGT Batt (s/n)	PGT Batt Spare (s/n)
EVA 1	EV1 Fs	3010	2014	3004	1008	1022 1025	20	1005	1005	1008
	EV2 Ga	3009	2025	3005	1012	1026 1028	18	1007	1006	

EVA-4a/135/O/B |

(reduced copy)

TOP
BACK OF 'STS-135 CONSUMABLES TRACKING CUE CARD'

**HOOK
VELCRO**

EVA-4b/135/O/B

(reduced copy)

FS CC 10-16

EVA/135/FIN 1

EMU CONTINGENCY PROCS

DISPLAY LOSS DURING POWER TRANSFER (WARM RESTART)..... TEMP FS 12-2
VACUUM H2O RECHARGE (MANNED)..... TEMP FS 12-2
LiOH REPLACEMENT (MANNED)..... 12-3
BATTERY REPLACEMENT (MANNED) 12-4
WATER DUMP 12-6
SCU SWAP (UNMANNED)..... 12-7
SCU SWAP (MANNED)..... 12-7
EMU COLD RESTART (MANNED) 12-7
12.1 STS EVA DECONTAMINATION..... 12-8
CONTAMINATION TEST..... 12-15
SAFER BATTERY CHANGEOUT 12-18
BENDS TREATMENT ADAPTER (BTA) INSTALLATION (IN-SUIT) 12-19
 BTA PREP 12-19
 BTA TREATMENT 12-20
BENDS TREATMENT ADAPTER (BTA) INSTALLATION (POST SUIT DOFFING) 12-21
 BTA PREP 12-21
 BTA TREATMENT 12-22
EMU RESIZE 12-25
EMERGENCY UNDOCKING EVA TRANSFER FS CC 12-27
EXPEDITED SUIT DOFFING CUE CARD FS CC 12-28
STS-135 NOMINAL EMU SIZING FS 12-29
EMU CONTINGENCY RESIZE MATRIX (STS-135/ULF7) FS 12-31

DISPLAY LOSS DURING POWER TRANSFER (WARM RESTART)

- DCM If PWR – BATT and SCU connected:
 AW18H 1. √PWR/BATT CHGR EMU 1(2) BUS SEL – OFF
 DCM If PWR – SCU:
 2. PWR – BATT
 AW18H 3. PWR/BATT CHGR EMU 1(2) BUS SEL – OFF

WARNING
 Fan will be off from steps 4 to 9 during which time CO2 buildup is a concern

NOTE

Affected EMU will be without comm after step 6. Steps 6 and 7 should be read together before step 6 is performed

- DCM 4. FAN – OFF (expect FAN SW OFF msg, DISP – PRO)
 IV 5. Inform affected EV crewmember of impending comm loss
 DCM 6. PWR – SCU (7 sec)
 7. PWR – BATT
 When power restart complete:
 8. √Display – O2 POS XX, expect FAN SW OFF msg, DISP – PRO
 9. As reqd, FAN – ON
 If display blank or locked up:
 10. Contact MCC
 If SCU power desired:
 11. √SCU connected to DCM
 AW18H 12. PWR/BATT CHGR EMU 1(2) MODE – PWR
BUS SEL – MNA(MNB)
 13. √EMU INPUT 1(2) Volts = 18.0 – 20.0
 DCM 14. PWR – SCU
 DCM 15. √Display – O2 POS XX

VACUUM H2O RECHARGE (MANNED)

WARNING
 Procedure should be used only if performing a contingency EVA

- EV 1. Perform AIRLOCK INGRESS, Cuff C/L, 30 (Close hatch, partially engage latches)
 2. √Helmet purge vlv – cl, locked
 DCM 3. √PURGE vlv – cl (dn)
 4. √WATER – OFF
 IV MO13Q 5. √ARLK H2O S/O VLV – OPEN (tb-OP)
 MD(flr) 6. √EMU O2 ISOL VLV – OP
 ML86B:C 7. √cb MNC EXT ARLK HTR LINE ZN 1,2 (two) – op
 AW82B 8. √EV-1(EV-2) O2 vlv – OP
 EV AW18H 9. PWR/BATT CHGR EMU 1(2) BUS SEL – MNA(MNB)
 DCM 10. PWR – SCU (fwd), WARN TONE
 IV R11L If SPLY H2O XOVR VLV closed (tb-CL or bp) (water transfer config):
 | 11. SPLY H2O TKA OUTLET – CL (tb-CL)
 If SPLY H2O XOVR VLV open (tb-OP) (nominal config):
 L1 12. √RAD CNTLR OUT TEMP – NORM
 13. √FLASH EVAP CNTLR PRI A,B (two) – OFF
 ML31C 14. SPLY H2O TKD OUTLET – CL (tb-CL)
 R11L 15. SPLY H2O TKB OUTLET – CL (tb-CL)
√TKA OUTLET – CL (tb-CL)
TKC INLET – CL (tb-CL)
TKC OUTLET – OP (tb-OP)

TOP

HOOK
VELCRO

EMERGENCY UNDOCKING EVA TRANSFER

Critical

- Wh & Mg
 - EMUs
 - CCAs
 - Batteries
 - Gloves
 - LCVGs
- EVA SYS XFER BAG 2

Desired (rotate items below)

- EVA SYS XFER BAG 2
 - 85-ft Safety Tethers, prefer #22 & #21
 - SCOFs, prefer s/n 1011 & 1013
 - BTA Assembly, prefer s/n 1004
 - EMU Servicing Kit, prefer s/n 5002

EVA-5a/135/O/A

(reduced copy)

FS CC 12-27

EVA/135/FIN

TOP
BACK OF 'EMERGENCY UNDOCKING EVA TRANSFER'

HOOK
VELCRO

EXPEDITED SUIT DOFFING CUE CARD

CAUTION

Verify EV crew is clear of hatch mechanism


- IV When equalization complete:
1. Open IV Hatch per decal
- DCM SUIT DOFFING
2. O2 ACT → OFF
3. PURGE vlv → op (up)
4. sw REBA → OFF (toward left arm of suit)
5. EMU TV Power Cable ←|→ EMU TV
6. √STATUS: **SUIT P** < 0.4 (compare with gauge)
7. Glove ←|→ EMU (leave donned, disconnected)
8. Helmet ←|→ EMU
- DCM 9. sw FAN → OFF
- SAFER SAFER DOFFING
10. Latch → ENG
11. Latch ↷ until release (~90 deg)
12. PLSS ←|→ Thruster Towers
- PLSS SUIT DOFFING (Cont)
13. Engage EMU in EDDA
14. Lower Arm Cables ←|→ Gloves
15. Gloves ←|→ EMU
16. Comm Mode → OFF
17. Disconnect CCA, MWC, and Biomed
18. Doff EMU
- UIA If taking EMUs to shuttle:
19. sw PWR EV-1,2 (two) → OFF
√PWR EV-1,2 LEDs (four) – Off
- DCM 20. SCU ←|→ DCM
21. LTA →|← HUT
22. Gloves →|← EMU
23. Helmet →|← EMU
24. Go to **EMERGENCY UNDOCKING
EVA TRANSFER** on reverse side

EVA-5b/135/O/A


(reduced copy)

STS-135 NOMINAL EMU SIZING

Fossum (Fs) – ISS




Garan (Ga) – ISS




	Croakie	Fresnel	Valsalva	LCVG/BLVD	MAG	TCU Top	TCU Bottom	Comfort Gloves	Socks
Fs	-002 [M]	-011 & -019	309	3240/315		Med	L	Spectra LG Thick	Crew 10-13
Mg	Mod M	N/A	309	3222/282		Lg	XL	Med Manzella	Crew 9-11

STS-135 NOMINAL EMU SIZING (Cont)

Walheim (Wh) – Up/Dn



Magnus (MG) – Up/Dn



	Croakie	Fresnel	Valsalva	LCVG/BLVD	MAG	TCU Top	TCU Bottom	Comfort Gloves	Socks
Wh	N/A	1.0 and 1.5 Diopter	309	3252/337	709	M	M	Spectra LG Thin	Thermax – Lg
Mg	S GRD	N/A	309	3198/288	709	S	M	Spectra MG	Woodsman – M

EMU CONTINGENCY RESIZE MATRIX (STS-135/ULF7)

FOR LOSS OF:	EV1 – Fossum	EV2 – Garan	EV – Walheim
HUT/PLSS	EMU 3011, M 1. Remove glove/arm assys 2. Use primary arms, gloves 3. √Arm red connects to right, √locks, √cams 4. Use primary LTA 5. Swap EMU PLSS identifier stripes, national flag 6. Swap helmet, comm cap, LiOH/Metox, EMU battery, REBA	EMU 3011, M 1. Remove ring/glove/arm assys 2. Use primary ring, arms, gloves 3. √Arm red connects to right, √locks, √cams 4. Use primary LTA 5. Swap EMU PLSS identifier stripes, national flag 6. Swap helmet, comm cap, LiOH/Metox, EMU battery, REBA	EMU 3011, M 1. Remove ring/glove/arm assys 2. Use primary ring, arms, gloves 3. √Arm red connects to right, √locks, √cams 4. Use primary LTA 5. Swap EMU PLSS identifier stripes, national flag 6. Swap helmet, comm cap, LiOH/Metox, EMU battery, REBA
CCA	Size 04/327 s/n 1198/1070 Location: ECOK (Fs)	Size 03/327 CCA s/n 1178/1055 Location: ECOK (Ga)	Size 04/323 CCA s/n 1181/5019 Location: ECOK (Wh)
Lower Arm Segment	Size 03 arm s/n 422/421 Location: A/L1D2 CTB 1078. Cams S/S (red = right, blue = left) 1. √Locks, √cams	Size 04 arm s/n 409/410 Location: A/L1O1 M-02 Bag 1010. Cams S/L (red = right, blue = left) 1. √Locks, √cams	Size 03 arm s/n 422/421 Location: A/L1O1 M-02 Bag 1010. Cams S/L (red = right, blue = left) 1. √Locks, √cams
Gloves	6BB gloves s/n 6231 Location: ECOK (Fs) Swap Arm Cams to S/L	6NO gloves s/n 6328 Location: ECOK (Ga) Arm Cams remain S/L	6FG gloves s/n 6330 Location: ECOK (Wh) Arm Cams remain S/L
Waist Brief	Size 01 waist brief s/n 2076/045 from EMU 3010. Cams S/S 1. Use prime legs, leg rings, and boots 2. √Locks, √cams 3. Swap EMU brief identifier stripes	Size 01 waist brief s/n 2076/045 from EMU 3010 Cams S/S 1. Use prime legs, leg rings, and boots 2. √Locks, √cams 3. Swap EMU brief identifier stripes	Size 01 waist brief s/n 2076/045 from EMU 3010. Cams S/S 1. Use prime legs, leg rings, and boots 2. √Locks, √cams 3. Swap EMU brief identifier stripes
Leg Segment	Use size 03 leg s/n 243/244 Location: TBD Cams L/L √Locks, √cams	Use size 03 leg s/n 243/244 Location: TBD Cams S/L √Locks, √cams Or Use size 02 leg s/n 249/250 Location EMU 3005 Cams L/L √Locks, √cams 0.5" thigh rings s/n 145/146 1.5" Leg sizing rings s/n 141/142 Location A/L1O1 CTB 1010	Use size 03 leg s/n 243/244 Location: TBD Cams S/L √Locks, √cams
Boot	Use size 02 boots s/n 232 from EMU 3010 1. No BSI & Toe Cap 2. √Locks	Use size 02 boots s/n 232 EMU 3010 1. No BSI & Toe Cap 2. √Locks	Use size 02 boots s/n 232 EMU 3010 1. No BSI & Toe Cap 2. √Locks
Sizing Rings	<ul style="list-style-type: none"> 0.5" Arm: Use s/n 145/146 from EMU 3005 1.5" Leg: Use s/n 121/122 Location: A/L1O1 M-02 1010 	1.5" Leg: Use s/n 121/122 Location: A/L1O1 M-02 1010	1.5" Leg: Use s/n 121/122 Location: A/L1O1 M-02 1010
LCVG	(04/05) 1. Use s/n 3195 Location: Bag "C" 2. Transfer biomed and dosimeter	(04/05) 1. Use s/n 3195 Location: Bag "C" 2. Transfer biomed and dosimeter	(04/05) 1. Use s/n 3202 Location: Bag "C" 2. Transfer biomed and dosimeter

This Page Intentionally Blank

TPS REPAIR

The TPS Repair procedures listed below are not published in the hardcopy EVA Flight Supplement. These procedures will be uplinked realtime if they are required.

A PDF and a WORD version of the procedures can be found at:
<http://mod.jsc.nasa.gov/do3/FDF/FDFBooks/Status%20Sheets/index.html>.

Select the "As Flown" Status sheet for STS-134 and the link to the procedures can be found with the link to the EVA FS. The procedures can also be found on the FDF Books CD provided to the FAO console

BOOM TPS INSPECTION	
BOOM POINT INSPECTION SUMMARY TIMELINE	FS 13-3
BOOM POINT INSPECTION TOOL CONFIG.....	FS 13-4
BOOM POINT INSPECTION	FS 13-5
BOOM WLE MAPPING SUMMARY TIMELINE	FS 13-15
BOOM WLE MAPPING TOOL CONFIG	FS 13-17
BOOM WLE MAPPING	FS 13-18
EVA WLE MAPPING INSPECTION.....	FS 13-24
BOOM CONTINGENCY	
BOOM FRGF SHAFT RELEASE	FS 13-29
BOOM FRGF SHAFT INSTALLATION	FS 13-30
BOOM EFGF SHAFT RELEASE	FS 13-32
BOOM MPM STOW/DEPLOY.....	FS 13-34
BOOM ASSISTED LATCHING	FS 13-35
TILE REPAIR	
EMU PREP FOR TPS REPAIR.....	FS 13-36
POST TPS REPAIR DOFFING	FS 13-37
EWA MATERIAL MIXING	FS 13-38
EWA REF DATA	FS 13-39
EWA TILE REPAIR – DOCKED/ORM SUMMARY TIMELINE	FS 13-40
EWA TILE REPAIR – DOCKED/ORM TOOL CONFIG.....	FS 13-41
EWA TILE REPAIR – DOCKED/ORM	FS 13-42
SSRMS GAP FILLER REMOVAL SUMMARY TIMELINE	FS 13-50
BOOM GAP FILLER REMOVAL SUMMARY TIMELINE	FS 13-51
GAP FILLER REMOVAL.....	FS 13-52
RCC REPAIR	
RCC CRACK REPAIR BAG ASSEMBLY.....	FS 13-57
TEMP SENSOR DISASSEMBLY POST-EVA.....	FS 13-60
RCC CRACK REPAIR BAG DISASSEMBLY POST-EVA	FS 13-61
TEMPERATURE PROBE ASSEMBLY	FS 13-63
CRM APPLICATOR ASSEMBLY	FS 13-63
CRM APPLICATOR NOZZLE INSTALLATION (DAY OF EVA).....	FS 13-64
RCC CRACK REPAIR.....	FS 13-65
RCC PLUG TRANSFER BAG ASSEMBLY	FS 13-77
RCC UNDOCKED CRACK REPAIR	FS 13-89
RULER PROTUBERANCE GAUGE TAPING.....	FS 13-120
NOTES, CAUTIONS, WARNINGS	
EVA TPS INSPECTION/REPAIR INHIBIT PAD.....	FS 13-122
TPS REPAIR CAUTIONS AND WARNINGS.....	FS 13-125
TPS REPAIR NOTES.....	FS 13-126
BOOM OPERATIONAL WARNINGS	FS 13-127
BOOM OPERATIONAL NOTES	FS 13-128

TPS REF DATA	
PREFERRED EMU POSITIONING FOR TPS REPAIR.....	FS 13-129
EVA TPS REACH AND ACCESS	FS 13-130
POINT INSPECTION REACH AND ACCESS WHILE DOCKED.....	FS 13-131
WLE MAPPING INSPECTION WHILE DOCKED	FS 13-133
TILE LAYUP	FS 13-134
85-FOOT SAFETY TETHER.....	FS 13-135
PFR ATTACHMENT DEVICE (PAD)	FS 13-136
WIF EXTENDER	FS 13-137
EVA DIGITAL CAMERA.....	FS 13-138
EVA IR CAMERA	FS 13-140
OVERLAY TILE REPAIR SYSTEM (OTRS)	FS 13-142
OTRS MARKING TEMPLATE AND INSULATION BAGS	FS 13-143
AUGER HOUSING.....	FS 13-144
OTRS RELEASED CONFIGURATION	FS 13-145
ORU BAG INSERT FOR OTRS	FS 13-146
RCC NOAX REPAIR REFERENCE.....	FS 13-147
BOOM REF DATA	
RTF BOOM OVERVIEW	FS 13-176
BOOM TRANSITIONS WITH MLI	FS 13-177
BOOM BASE END AND MODIFIED EFGF	FS 13-178
BOOM BASE END EFGF ADAPTER PLATE	FS 13-179
EVA-ASSISTED EFGF CONNECTOR DEMATE	FS 13-180
BOOM BASE END SADDLE AND MPM.....	FS 13-181
BOOM MID SECTION AND MODIFIED FRGF	FS 13-182
BOOM MID SECTION FRGF ADAPTER PLATE.....	FS 13-183
BOOM TIP END AND SENSORS	FS 13-184
BOOM SENSOR DETAILS	FS 13-186
SENSOR PACKAGE 1 (SP1): LDRI/ITVC	FS 13-188
SENSOR PACKAGE 2 (SP2): LCS.....	FS 13-190
POSSIBLE PRD ROUTING FOR EVA ASSISTED LATCHING	
OF BOOM IN MPMS.....	FS 13-192
BOOM CONTINGENCIES	FS 13-193
GRAPPLE SHAFTS	FS 13-194
PDGF GRAPPLE SHAFT COVER.....	FS 13-195
BOOM FRGF FSE.....	FS 13-196

UNSCHEDULED/CONTINGENCY EVA TASKS

STS-135/ULF7 WORKAROUNDS CRIBSHEET	TEMP FS 16-2
EVA 1 CONTINGENCIES	TEMP FS 16-2
GET-AHEAD CONTINGENCIES.....	FS 16-6
GENERIC CONTINGENCIES	FS 16-8
ROEU CONTINGENCIES	
RELEASE ROEU LATCHES	FS 16-31
LATCH ROEU LATCHES.....	FS 16-34
STOW ROEU ARM	FS 16-38
MATE ROEU ARM	FS 16-41
ROEU OVERVIEW.....	FS 16-43
SSRMS JOINT DRIVE.....	FS 16-44
GENERIC EVA INHIBIT PAD	FS 16-49
GENERIC NOTES, CAUTIONS, & WARNINGS	FS 16-56
TIE-DOWN PLANS	
MISSE 8 ORMATE III R/W TIE-DOWN.....	FS 16-63
CP7 ETVCG TIE-DOWN.....	FS 16-64
SSRMS BASE B BOOM CLPA TIE-DOWN	FS 16-65
CP13 ETVCG LIGHT TIE-DOWN	FS 16-66

UNSCH/CONT
EVA TASKS

STS-135/ULF7 WORKAROUNDS CRIBSHEET

EVA 1 CONTINGENCIES

TASK	FAILURE	ACTION
COLT Install	A. COLT will not engage contingency pin housing	Check for geometry conflicts and check with MCC-H
	B. COLT will not rotate with socket engaged on contingency pin	<ol style="list-style-type: none"> 1. Verify cap is installed 2. Test COLT with socket: <ol style="list-style-type: none"> a. Remove COLT from contingency pin housing b. Remove cap from COLT c. Insert socket into COLT to disengage anti-rotation device d. Turn socket and verify both ends of COLT rotate 3. With COLT removed from cont. pin housing, verify screw on contingency pin housing is at 12 o'clock (zenith) position as expected
	C. Both "U" brackets fail to engage handrail	<ol style="list-style-type: none"> 1. Verify slider in open position 2. Disengage COLT from contingency pin housing and reattempt installation and rotation. Ensure pressure (~10 lbf) against contingency pin housing during installation and rotation 3. Verify soft dock latch can be depressed 4. Check for geometry conflicts and check with MCC-H
	D. Slider will not move to closed position	<ol style="list-style-type: none"> 1. Verify both paddles are depressed 2. Check for FOD or tethers in slider path
	E. Two lines not visible after slider installation	One line is acceptable if slider captures handrail stanchion and paddles are popped out. Perform pull test on slider and wiggle test on COLT
	F. Slider paddle will not pop up	<ol style="list-style-type: none"> 1. Depress stuck paddle and push slider to closed position 2. Push slider to closed position with force 3. Contact MCC-H for options to tap slider
	G. Gap between washer & end of contingency pin housing > washer thickness	<ol style="list-style-type: none"> 1. Test COLT spring-loaded socket: <ol style="list-style-type: none"> a. Remove COLT b. Use tool (not glove) to depress and cycle COLT spring-loaded socket (~10 lbf) c. Report movement to MCC-H. Attempt to reinstall. (Perform all checks again) 2. With COLT installed, report to MCC-H: <ol style="list-style-type: none"> a. Position of pin on opposite side of housing from spring-loaded socket (recessed, flush, protruding) b. Position of washer relative to window
	H. Cap cannot be removed	<ol style="list-style-type: none"> 1. Attach large crew hook to cap tether point for improved handling 2. Contact MCC-H for options to pry cap loose

UNSC/CONT
EVA TASKS

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

EVA 1 CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
PM FRAM Transfer	<p>A. Primary FRAM bolt fails to release</p> <p>NOTE 3 of 4 contingency pins reqd for On-Orbit stowage.</p> <p>FRAM electrical connectivity fully lost at 0.95 turns on primary bolt.</p> <p>Partial electrical connectivity lost at 0.45 turns on primary bolt</p> <p>Minimum mechanical configuration is maintained with less than 2.2 turns on primary bolt (but pins highly desired time permitting)</p> <p>NOTE for Removal: For primary drive turn count of 2.2-4.7 turns, go for install of rear contingency pins due to uncertainty in PGT/Turn count. Failure to engage rear contingency pin to INSTALL location confirms turn count is 4.7 or less. Rear Contingency Pins, aft contingency pins can only be installed if the primary bolt turn count is 4.7 turns or more. With less than 4.7 turns on the primary bolt, the contingency pins are not needed and cannot be installed</p>	<ol style="list-style-type: none"> 1. Confirm socket fully engaged to release anti-rotation mechanism 2. Increase PGT setting: PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A4 (6.3) for full run-out of bolt 3. On MCC-H GO: Increase PGT setting: PGT: [B4 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A4 (6.3) for full run-out of bolt 4. Reattempt engagement of primary drive with nominal PGT settings 5. Engage contingency pins: <ul style="list-style-type: none"> – Front pins (all FRAMs) PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext 0.11 + (1.25 * Turns on Primary Bolt) turns – Aft pins PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext If Primary Drive disengaged more than 8.8 turns: <ul style="list-style-type: none"> – Insert Contingency Pins to hardstop at 13.8 turns If the Primary Drive disengaged less than 8.8 turns use the following equation for turns needed: $2.858 + (1.25 * \text{Turns on Primary Bolt}) = \# \text{ of total turns needed}$ [Stop on torque, verify turns]
	<p>B. Active FRAM fails to seat on passive FRAM</p>	<ol style="list-style-type: none"> 1. Check for FOD in mechanism 2. Check alignment. (Engage 2 forward shear pins first to ensure connector door is not jamming)
	<p>C. Primary FRAM bolt fails to engage</p> <p>NOTE 2 front and 1 of 2 aft contingency pins reqd for Shuttle PLB return.</p> <p>FRAM electrical connectivity begins at 10.25 turns on the primary bolt.</p> <p>Complete electrical mate is expected between 10.5-10.75 turns</p> <p>Minimum mechanical configuration is 9 turns on primary bolt, to not need contingency pins (but pins highly desired time permitting)</p>	<ol style="list-style-type: none"> 1. Verify FRAM seated 2. Check for FOD 3. Back out primary bolt fully at nominal setting. If removal isn't successful at nominal setting Increase PGT setting for disengagement: PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A4 (6.3) for full run-out of bolt On MCC-H GO: Increase PGT setting: PGT: [B4 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A4 (6.3) for full run-out of bolt 4. Reattempt engagement PGT: [A7 (9.2), CW2, 30.5], 7/16 - 6-ext Increase PGT setting: PGT: [B2 (16.0), CW2, 30.5], 7/16 - 6-ext On MCC-H GO: Increase PGT setting: PGT: [B4 (19.4), CW2, 30.5], 7/16 - 6-ext 5. Consider hold for thermal stabilization between active and passive FRAM

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

EVA 1 CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	<p>C. Primary FRAM bolt fails to engage (Cont)</p> <p><u>NOTE for Engage:</u> For primary drive turn count of 6.5-9 turns, go for install of rear contingency pins due to uncertainty in PGT/Turn count. Failure to engage rear contingency pin to INSTALL location confirms turn count is 6.5 or more. Aft contingency pins can only be installed if the primary bolt turn count is 6.5 turns or less. With greater than 6.5 turns on the primary bolt, the contingency pins are not needed and cannot be installed</p>	<p>6. Engage contingency pins:</p> <ul style="list-style-type: none"> - Front pins PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext 14.11 - (1.25 * Turns on Primary Bolt) turns - Aft pins PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext If Primary Drive inserted less than 2.4 turns: - Insert Contingency Pins to hardstop at 13.8 turns If the Primary Drive inserted greater than 2.4 turns use the following equation for turns needed: $16.858 - (1.25 * \text{Turns on Primary Bolt}) = \#$ of total turns needed [Stop on torque, verify turns]
<p>RRM FRAM Transfer</p>	<p>A. Primary FRAM bolt fails to release</p> <p><u>NOTE</u> 4 of 4 contingency pins reqd for Shuttle PLB return.</p> <p>FRAM electrical connectivity fully lost at 0.95 turns on primary bolt.</p> <p>Partial electrical connectivity lost at 0.45 turns on primary bolt</p> <p>Minimum mechanical configuration is maintained with less than 2.2 turns on primary bolt (but pins highly desired time permitting)</p> <p><u>NOTE for Removal:</u> For primary drive turn count of 2.2-4.7 turns, go for install of rear contingency pins due to uncertainty in PGT/Turn count. Failure to engage rear contingency pin to INSTALL location confirms turn count is 4.7 or less. Rear Contingency Pins, aft contingency pins can only be installed if the primary bolt turn count is 4.7 turns or more. With less than 4.7 turns on the primary bolt, the contingency pins are not needed and cannot be installed</p>	<ol style="list-style-type: none"> 1. Confirm socket fully engaged to release anti-rotation mechanism 2. Increase PGT setting: PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A7 (9.2) for full run-out of bolt 3. On MCC-H GO: Increase PGT setting: PGT: [B4 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A7 (9.2) for full run-out of bolt 4. Reattempt engagement of primary drive with nominal PGT settings 5. Engage contingency pins: <ul style="list-style-type: none"> - Front pins PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext 0.11 + (1.25 * Turns on Primary Bolt) turns - Aft pins for LMC FRAMs <ul style="list-style-type: none"> - Prep CPK by disengaging J-hook on locking mechanism; ensure J-hook fully seated in unlock position - Slide T-handle until contingency pin contact primary FRAM pin (# on locking mechanism counter – # of turns on primary FRAM bolt) - Engage J-hook lock (will “pop” into place if not precisely aligned with numbered slot); ensure J-hook fully seated in lock position
	<p>B. Active FRAM fails to seat on passive FRAM</p>	<ol style="list-style-type: none"> 1. Check for FOD in mechanism 2. Check alignment (engage 2 forward shear pins first to ensure connector door is not jamming)





STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

EVA 1 CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	<p>C. Primary FRAM bolt fails to engage</p> <p style="text-align: center;"><u>NOTE</u> 3 of 4 contingency pins reqd for On-Orbit stowage. FRAM electrical connectivity begins at 10.25 turns on the primary bolt. Complete electrical mate is expected between 10.5-10.75 turns</p> <p>Minimum mechanical configuration is 9 turns on primary bolt, to not need contingency pins (but pins highly desired time permitting)</p> <p><u>NOTE for Engage:</u> For primary drive turn count of 6.5-9 turns, go for install of rear contingency pins due to uncertainty in PGT/Turn count. Failure to engage rear contingency pin to INSTALL location confirms turn count is 6.5 or more. Aft contingency pins can only be installed if the primary bolt turn count is 6.5 turns or less. With greater than 6.5 turns on the primary bolt, the contingency pins are not needed and cannot be installed</p>	<ol style="list-style-type: none"> 1. Verify FRAM seated 2. Check for FOD 3. Back out primary bolt fully at nominal setting. If removal isn't successful at nominal setting Increase PGT setting for disengagement: PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A7 (9.2) for full run-out of bolt. On MCC-H GO: Increase PGT setting: PGT: [B4 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A7 (9.2) for full run-out of bolt. 4. Reattempt engagement PGT: [A7 (9.2), CW2, 30.5], 7/16 - 6-ext Increase PGT setting: PGT: [B2 (16.0), CW2, 30.5], 7/16 - 6-ext On MCC-H GO: Increase PGT setting: PGT: [B4 (19.4), CW2, 30.5], 7/16 - 6-ext 5. Consider hold for thermal stabilization between active and passive FRAM 6. Engage contingency pins: <ul style="list-style-type: none"> – Front pins PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext 14.11 - (1.25 * Turns on Primary Bolt) turns – Aft pins <ul style="list-style-type: none"> - Remove bolt from STOW location and engage in INSTALL location - Manually turn bolt as far as possible - PGT: [B1 (12.0), CW2, 30.5], 7/16 - 6-ext
<p>MISSE 8 ORMATE III R/W Install</p>	<p>A. ExPA Socket PIP pin will not release</p>	<ol style="list-style-type: none"> 1. Push PIP pin button and increase force on pull ring; stop if deformation occurs 2. If no joy, assess side loads on PIP pin 3. If no joy, tap detent end of PIP pin with hook 4. If no joy, retrieve hammer (stbd A/L toolbox), pry bar (Staging Bag), and BMRRM tool (stbd Z1 toolbox, slot 2) 5. Tap detent end of PIP pin with hammer; 6" max stroke; use metal side of hammer; reattempt step 1 6. If no joy, place edge of pry bar along the detent end of PIP pins, tap with hammer; 6" max stroke; use metal side of hammer; reattempt step 1 7. If no joy, insert BMRRM tool axially into detent end of PIP pin, tap with hammer; 4" max stroke; use metal side of hammer; reattempt step 1
	<p>B. ExPA Socket PIP pin will not engage</p>	<ol style="list-style-type: none"> 1. Verify ball detents can be depressed 2. Check alignment of ORMATE 3. Wiggle ORMATE to offload any misalignments while installing PIP pin 4. Install other PIP pin, if not already, and reattempt **One PIP pin is sufficient to hold ORMATE in ExPA socket

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GET-AHEAD CONTINGENCIES

TASK	FAILURE	ACTION
1553 CABLE INSTALL	A. NZGL Connectors B. Russian connectors will not mate	See Generic Section of Cribsheet 1. Verify connector alignment: Wide keypin should align with ball on the exterior housing of the connector housing  <p>Russian connector socket</p>
		2. If connector not aligned: <ol style="list-style-type: none"> Turn connector cap around to use keypin groove  <p>Russian connector cap</p> Place cap on connector so keypin enters groove on cap  <p>Russian socket and cap</p> Rotate cap until ball on connector housing aligns with groove on cap (may feel "detent" in rotation)  <p>Russian connector properly aligned</p> Remove cap and verify keypin aligns with ball on connector housing Reattempt connector mate

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GET-AHEAD CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
SSRMS BOOM B CLPA R&R	A. Failed CLPA bolt does not release	<ol style="list-style-type: none"> 1. Apply higher torque (using MTL): <ol style="list-style-type: none"> a. Turn PGT – Off, set to manual CCW ratchet (RCCW) with MTL setting of 30.5 b. After breaking torque, reset PGT to nominal settings for task (B7)
	B. CLPA fails to soft dock	<ol style="list-style-type: none"> 1. Inspect for FOD or damage 2. Wiggle CLPA into V-guide
	C. Bolt fails to engage fully (> 20 turns)	Increase torque PGT: [B7 (25.5), CW2, 30.5] <ul style="list-style-type: none"> • Minimum number of turns for electrical connectivity is 22 • Max installation torque is 43.0 ft-lb
	D. Bolt fails to engage fully (< 20 turns)	<ol style="list-style-type: none"> 1. Release bolt using PGT setting [B7 (25.5 ft-lb), CCW2 (30 rpm), 30.5 MTL] 2. Check for FOD or damage in interface 3. Reinstall CLPA using maximum torque settings, PGT: [B7 25.5 ft-lb), CW2 (30 rpm), 30.5 MTL] 4. If no joy with max torque, remove camera and bring both cameras back to A/L
FHRC P-Clamp Release	A. Bolt fails to release	Increase torque PGT: [B1 (12.0), CCW2, 30.5] for 1 turn then return to nominal setting PGT: [A7 (9.2), CCW2, 30.5]
Tool Relocations	A. Toolbox door will not open	<ol style="list-style-type: none"> 1. Verify both door locks are in open position (on either side of door panel) <ul style="list-style-type: none"> • If necessary, remove launch restraint PIP pin, place in stowage bracket, and open lock 2. Ingress APFR/IAPFR for better worksite access
	B. Toolbox door will not close	<ol style="list-style-type: none"> 1. Verify no FOD or interference in door hinge 2. Verify door hinge in travel in groove
	C. Toolbox door lock stuck	<ol style="list-style-type: none"> 1. Verify no FOD or interference 2. Use crew hook to apply additional force in desired direction 3. If door lock is stuck open, leave in open position and close door lock on the other side of door panel
	D. Toolboard tab will not open	<ol style="list-style-type: none"> 1. Verify no FOD or interference in tab 2. Use equipment hook to tap toolboard tab into open position 3. If appropriate, utilize alternate tab (TB vs SL) to gain access to toolboard
	E. Toolboard tab will not close	<ol style="list-style-type: none"> 1. Verify toolboard is fully seated in guide rail, reattempt 2. Verify no FOD or interference in tab 3. Stow toolboard in alternate location (mission specific): <ol style="list-style-type: none"> a. Alternate slot in same toolbox b. Alternate slot in alternate toolbox c. Return toolboard to Airlock for internal stowage

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES

TASK	FAILURE	ACTION
I. Generic	AGB	
	A. Bolt fails to release	<ol style="list-style-type: none"> Increase torque PGT: [B1 (12.0), CCW2, 30.5], 7/16 - 6-ext (2-in required for ESP-2 FHRC) If no joy, increase torque PGT: [B7 (25.5), CCW2, 30.5], 7/16 - 6-ext (2-in required for ESP-2 FHRC)
	B. Bolt jams during AGB release due to PGT dimensions (on ESP-2 FHRC)	Use ratchet wrench <ol style="list-style-type: none"> Drive bolt back in PGT: [A2 (3.8), CW2, 30.5], 7/16 - 2-ext Retrieve ratchet wrench to perform release
	C. T-handle fails to unlock (release)	<ol style="list-style-type: none"> Check interface for FOD or damage Increase force and reattempt Use prybar as lever to release T-handle
	D. AGB fails to release from soft dock	Use bolt puller or prybar to pry the AGB from the PM near sticky plungers
	E. T-handle fails to engage into alignment hole	<ol style="list-style-type: none"> Slide AGB single pin side in and out a few inches while tapping T-handle into position Install tether to hold 2 pin side to restraint engaged on ORU and push in single pin side. Then reattempt step 1
	F. AGB fails to soft dock	<ol style="list-style-type: none"> Check for FOD Exercise plungers with bolt puller or prybar
	G. Slider mechanism overcomes soft-dock	<ol style="list-style-type: none"> Verify T-handle fully out – 2 white lines Install tether to hold 2 pin side to restraint engaged on ORU and push in single pin side. Then slide AGB single pin side in and out a few inches while tapping T-handle into position
	H. Bolt fails to engage fully	<ol style="list-style-type: none"> Check interface for FOD or damage Back out bolt PGT: [A2 (3.8), CCW2, 30.5], 7/16 - 6-ext (2-in required for ESP-2 FHRC) and reattempt installation at nominal setting [A2 (3.8), CW2, 30.5], 7/16 - 6-ext (2-in required for ESP-2 FHRC) If green light achieved check with MCC-H if turn count is acceptable
	I. PGT interferes during AGB install (on ESP-2 FHRC)	Attempt turns by hand or with ratchet wrench palm wheel cw until bolt seated; do not put preload on bolt with ratchet
	APFR/IAPFR	
	A. APFR/IAPFR fails to install into WIF	<ol style="list-style-type: none"> Verify APFR collar in install position (black-on-black) Check for FOD in WIF or structural interference Attempt APFR install in alternate clocking Attempt APFR install in alternate WIF APFR failure <ul style="list-style-type: none"> Use another APFR
	B. Joint fails to actuate	<ol style="list-style-type: none"> Verify no load is applied to joint and/or jiggle APFR joint while actuating <ul style="list-style-type: none"> For pitch joint, push knob in during rotation. (Class I pitch joints known to be stiff) Increase force applied in order to free joint
	C. Boot becomes stuck in APFR boot plate	<ol style="list-style-type: none"> Have other EV crewmember assist with getting boot out Loosen 7/16-in EVA bolts (3) on heel clip using EVA ratchet or PGT: PGT: [B1 (12.0), CCW2, 30.5], 7/16 - 6-ext Remove 7/16-in EVA bolts (3 – captive) on heel clip (non captive) using EVA ratchet or PGT: PGT: [B1 (12.0), CCW2, 30.5], 7/16 - 6-ext 5 turns total

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	D. Boot becomes stuck in IAPFR boot plate	<ol style="list-style-type: none"> 1. Have other EV crewmember assist with getting boot out 2. If wearing Small EMU boot, have other EV crewmember adjust boot sizing to Large 3. Loosen 7/16-in EVA bolts (2) on heel clip using EVA ratchet or PGT: PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 4. Remove 7/16-in EVA bolts (2) on heel clip using EVA ratchet or PGT: PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 4 turns total
Ballstack		
	A. ECOM fails to release from ISS Structure	On MCC-H GO : Tether ballstack to handrail and leave outside
	B. ECOM fails to release from MUT EE	Leave together and return inside
	C. Ballstack fails to rigidize	On MCC-H GO : Use secondary tethers to assist in restraining payload
BRT		
	A. BRT jaws fail to release	<ol style="list-style-type: none"> 1. Loosen rigidizing collar to relieve sideloads 2. Shake BRT while depressing paddles to alleviate sideloads from handrail 3. Detach BRT from suit and tether to structure
Cannon Connector		
	A. Connector fails to release	<ol style="list-style-type: none"> 1. Check for FOD, damage or misalignment 2. Verify cable routing is not impeding connector rotation. (Release TA-clamps as required) 3. Use cannon connector tool for more leverage
	B. Connector/Cap fails to softdock	<ol style="list-style-type: none"> 1. Verify collar unlocked. (White on connector shell tip should align with white on receptacle backplate) 2. Check for FOD or damage
	C. Connector/Cap fails to lock	<ol style="list-style-type: none"> 1. Remove connector/cap, check for FOD or damage 2. Check alignment, remate, rock connector back and forth as required. (Once locked, white on connector shell tip should align with black on receptacle backplate) 3. Use cannon connector tool for more leverage
	D. High cable stiffness prevents mating	<ol style="list-style-type: none"> 1. Verify all TA-clamps are released 2. Use second crewmember 3. Use APFR
	E. Connector/Jack pin bent	<ol style="list-style-type: none"> 1. Describe pin location and condition <ul style="list-style-type: none"> • Obtain WVS view of interface if possible 2. On MCC-H GO: For 16, 20, or 22 gauge pins only, retrieve pin straightener and attempt pin repair 3. On MCC-H GO: Retrieve needle nose pliers and attempt pin repair <ul style="list-style-type: none"> • MCC-H will verify pin size prior to retrieving tools
	F. Connector/Jack FOD	On MCC-H GO : Obtain connector cleaner tool to remove FOD
	G. Connector EMI band bent	On MCC-H GO : Obtain needle nose pliers or forceps to remove band
CETA Cart		
	A. Wheel bogie fails to release from truss	<ol style="list-style-type: none"> 1. Verify brakes are fully released 2. Ensure trigger is being depressed while attempting to rotate handle 3. On MCC-H GO: Perform <u>6.100.125 CETA CART WHEEL BOGIE R&R</u> <ul style="list-style-type: none"> • There is no spare wheel bogie on-orbit, so after the CETA cart is relocated the failed wheel bogie will be reinstalled





STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	B. Wheel bogie fails to install on truss	There is no spare wheel bogie on-orbit. 4 of 4 bogies are required. Real time call on whether MT couple or CETA cart tiedown required. For tiedown, see block G
	C. Parking brake fails to engage	<ol style="list-style-type: none"> 1. Use parking brake handle on other side of CETA cart 2. Couple CETA cart to MT and utilize other WIF if possible
	D. Parking brake fails to disengage	<ol style="list-style-type: none"> 1. Hold pedal down for brake release 2. Use pedal on other side of CETA cart to release parking brake
	E. Dynamic brake fails to engage	Limit translation rates to allow manual stopping
	F. CETA active coupler fails to capture or lock	<ol style="list-style-type: none"> 1. Cycle active coupler 2. On MCC-H GO: Swap active couplers by removing PIP pins (2 on each coupler). (Port CETA Cart has short coupler.) (MT Coupler PIP pins restrained by lanyard which must be cut to remove PIP pins. Stbd Cart Coupler PIP pins restrained by wire tie. Wire tie does not need to be reinstalled) 3. On MCC-H GO: Tie down CETA cart. See block G
	G. CETA cart tiedown	<p>On MCC-H GO: Perform the following tiedown procedure (see figure 1)</p> <ol style="list-style-type: none"> a. Translate CETA cart to TBD location (not over truss segment joint) b. Engage parking brake c. Retrieve 2 Long Duration TieDown (LDTD) tethers d. Route 1 LDTD tether on stbd side of CETA cart as follows: <ol style="list-style-type: none"> 1. Attach 1 hook to zenith brake handle support tether point 2. Loop tether strap around CETA rail HR standoff 3. Attach second hook to nadir brake handle support tether point 4. Lightly cinch tether and close buckle 5. Close MLI flap over buckle and any excess strap e. Repeat on port side of CETA cart
	H. Coupler knob fails to unlock	<ol style="list-style-type: none"> 1. On MCC-H GO: Release active coupler by removing PIP pins (2). (MT Coupler PIP pins restrained by lanyard which must be cut to remove PIP pins. Stbd Cart Coupler PIP pins restrained by wire tie. Wire tie does not need to be reinstalled) 2. On MCC-H GO: Release passive coupler via EVA bolt: PGT: [B7 (25.5), CCW2, 30.5], 7/16 - 6-ext 9 turns <ul style="list-style-type: none"> • Bolt is attached by lanyard
	I. Swing arm fails to deploy	Use alternate swing arm or WIF
	J. Swing arm fails to stow	On MCC-H GO : Remove swing arm via EVA bolts (4): PGT: [B7 (25.5), CCW2, 30.5], 7/16 - 6-ext TBD turns (Captive bolts?)
	K. Swing arm fails to lock	Restrain in stowed position with wire ties

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	 <p>Starboard LDTDT Config. (port side LDTDT - similar)</p>  	
EVA Wrench (Torque & Ratchet)		
A. Ratchet teeth slip		Ratchet to new set of teeth and reapply torque
B. Wrench does not ratchet		Hold the ratchet selector and socket in opposite hands and rotate in opposite directions
Expandable Diameter Fasteners (EDFs)		
A. EDF does not release with recommended torque		<ol style="list-style-type: none"> 1. Increase torque to PGT: [B7 (25.5), CCW2, 30.5] for one turn only. Continue release at nominal setting 2. Increase torque to PGT: [RCCW, 30.5] for one turn only. Continue release at nominal setting 3. Use Ratchet Wrench (ccw) 4. Remove EDF with prybar (only if head not free spinning)

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)


GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	B. EDF cannot be removed from lug/clevis after untorqued	<ol style="list-style-type: none"> 1. Twist outer washer (lanyard washer) back and forth while pulling outward 2. Verify lanyard not snagged 3. Drive EDF ccw 2 turns. (Start EDF by hand when re-installing) 4. Gently tap along EDF major axis with back of equipment hook or hammer (EDF head must not be free spinning), and pull outward with lanyards 5. Use equipment hook over EDF bolt head to remove (EDF head must not be free spinning) 6. Use EVA prybar (EDF head must not be free spinning)
	C. Cannot insert EDF into lug/clevis interface	<ol style="list-style-type: none"> 1. Verify lug/clevis fully seated 2. Twist EDF bolt head by hand to seat on tip hex head 3. Drive EDF 2 addl turns ccw, retry insertion, verify head not free spinning 4. Remove EDF and verify collets not expanded 5. Cut EDF lanyards and replace failed EDF with spare EDF
	D. EDF is not captive after all EDFs at final torque	<ol style="list-style-type: none"> 1. Increase torque to PGT: [B7 (25.5), CW2, 30.5], ensure fully seated 2. Increase torque to PGT: [RCW, 30.5], ensure fully seated 3. Pull EDF and re-insert (loosen collets as reqd), ensure fully seated, retry 4. Increase torque on all EDFs to PGT: [RCW, 30.5], ensure fully seated 5. Cut EDF lanyards and replace failed EDF with spare EDF
Fluid QD Ops		
<u>NOTE</u>		
<p>Troubleshooting steps outlined in this cribsheet are a generic starting point. Flight specific situations may require different actions.</p> <p>If troubleshooting requires the crew to leave the worksite, verify that female QDs are covered to prevent exposure to direct sunlight. For thermal clocks refer to flight rules</p>		
Mating Ops		
	A. QD fails to mate	<ol style="list-style-type: none"> 1. Check alignment and verify side loads are counteracted 2. Verify fwd white band is not visible (release ring is retracted) 3. Inspect male and female QD for debris, damage, or NH3 4. Leave female QD engaged with male. (NH3 may sublimate between QDs) 5. Change body orientation for better access
	B. Release ring snap back test fails	<ol style="list-style-type: none"> 1. Push release ring forward. (Release ring will not slide fwd if QD is in FID) 2. QD is in FID <ol style="list-style-type: none"> a. Demate QD b. Pull back on release ring c. Verify fwd white band not visible (release ring is retracted) d. Assess and counteract sideloads and remate QD

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	C. Gap check fails (visual or FID gauge)	QD is in FID a. Demate QD b. Pull back on release ring c. Verify fwd white band not visible (release ring is retracted) d. Assess and counteract sideloads and remate QD
	D. Pull test fails	1. Verify fwd white band is not visible (release ring is retracted) 2. Assess and counteract sideloads and mate QD
Valve Ops		
	E. Detent button is partially unthreaded	Rethread detent button a. Load bail handle (button will free spin if not loaded) <ul style="list-style-type: none"> If valve is open (bail fwd), pull bail handle aft If valve is closed (bail aft), push bail handle fwd b. Rotate button cw to hardstop (8 turns max)
	F. Detent button is missing <p style="text-align: center;"><u>NOTE</u> Detent button is only required for BDT ops and 1 in SPD ops</p>	1. Use equipment hook to depress detent button shaft 2. Use tether strap around gloved finger to depress detent button shaft 3. Retrieve and use Beta Gimbal Antirotation Latch Tool to depress detent button shaft 4. On MCC-H GO : Install spare detent button. (Buttons are stowed IVA and must be configured prior to EVA use)
	G. Bail fails to travel to fwd (valve open) position (button does not pop up if attempting to go to full fwd)	1. Assess and counteract sideloads 2. Apply greater opening force to QD bail handle in fwd direction 3. Retrieve and use QD bail drive lever (3/4, 1, & 1.5 in only) 4. If applicable, retrieve and install SPD; notify MCC-H
	H. Detent button fails to depress in preparation for valve closing <div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p style="text-align: center;"><u>WARNING</u> Bail may kick back and contact crew when a stuck button is forcibly depressed due to pressure build-up in spring cavity</p> </div>	1. Verify locking collar unlocked (1/2, 3/4, & 1 in only) 2. Push and hold bail handle fwd (to open) with significant force to relieve load on button while simultaneously depressing the detent button <ul style="list-style-type: none"> If button depresses, vent by allowing bail aft until aft white band no longer visible 3. Twist bail handle/Rock QD from side-to-side and fwd/aft while depressing button to allow internal QD components to align 4. Retrieve QD bail drive lever and repeat step 2 (3/4, 1, & 1.5 in only) 5. Contact MCC to reduce NH3 pressure, if possible 6. On MCC-H GO : Retrieve and install QD button depress tool (BDT) (1/4, 3/4, & 1 in only) 7. On MCC-H GO : Retrieve hammer and tap center of button (Use plastic side of hammer) (Inspect tool and QD)
	I. Bail fails to travel to full aft (valve closed) position (button does not pop up)	1. Assess and counteract sideloads 2. Increase force on bail while depressing button 3. Retrieve and use QD bail drive lever (3/4, 1, & 1.5 in only) 4. Inspect QD for retaining wire protrusion




STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	Demating Ops	
	J. Female QD fails to demate	<ol style="list-style-type: none"> 1. Assess and counteract sideloads or manipulate flexhose to relieve mating forces on female QD 2. Verify release ring is fully retracted while attempting to demate 3. Verify TA or P clamps are released 4. Verify detent button is up (locking collar can be rotated under button) 5. Verify trigger linkage is still attached to release ring (1.5 in only) 6. Apply greater force to release ring and female QD 7. Retrieve and use QD release tool (QRT) to apply greater force (3/4, 1, & 1.5 in only) 8. On MCC-H GO: Shake QD vigorously while attempting to demate
	K. Thermal bootie fails to remain securely closed	Install wire tie around bootie to keep QD fully covered
	L. Cap will not demate	<ol style="list-style-type: none"> 1. Verify pulling out on cap before rotating to ensure locking tab is disengaged 2. Wait for opposite thermal conditions if possible and reattempt cap removal 3. Retrieve QD cap tool (1/4, 1/2, & 1 in only) <ol style="list-style-type: none"> a. PGT: [A4 (6.3), CCW1, 30.5] with QD cap tool to turn stuck cap a maximum of 2 turns (cap vents at ~ 2 turns) b. Once venting is complete, finish removal of cap by hand (~ 1 additional turn) <ul style="list-style-type: none"> • If venting does not stop or cap cannot be removed by hand, notify MCC-H (Male QD may be leaking)
	M. Partial fwd white band visible after QD demate	<ol style="list-style-type: none"> 1. Pull back on release ring to verify QD is not in FID 2. Verify detent button is up 3. If fwd white band is still partially visible this is likely a tolerance stackup; notify MCC-H and press with QD ops
	Leaks	
	<p>CAUTION</p> <p>Do not fully open a leaking QD. Fully opening a leaking QD could trap NH3 and prevent depressing the button in the future. For 1.5 in QDs, insert fwd SPD spacer prior to opening valve</p>	
	N. Mated QD leaks in valve open position (bail fwd)	<ol style="list-style-type: none"> 1. Cycle valve <ol style="list-style-type: none"> a. Remove SPD if present (aft spacer only for 1.5 in) and fully close valve (bail aft); wait for ice crystals to dissipate b. Open valve halfway (bail fwd). (For 1.5 in, verify fwd SPD spacer installed prior to opening valve) c. Describe leak size and if leak rate is changing 2. If leak has stopped, on MCC-H GO: Complete valve open steps; else: Repeat step 1 3. On MCC-H GO: Remove SPD if in place; push bail full fwd to engage secondary seal, verify detent button is up and aft white band is visible 4. Close valve; notify MCC-H 5. If applicable, close valve of appropriate QD in flowpath, verify detent button is up, and fwd white band is visible

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	O. Female QD leaks due to FID	<ol style="list-style-type: none"> Return bail to aft position (valve closed) Perform release ring snap back test <ul style="list-style-type: none"> If FID is observed, demate and remate QD
	P. Male QD leaks after cap removal	<ol style="list-style-type: none"> If leak small, mate female QD; continue ops Reinstall cap; notify MCC-H <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p style="text-align: center;">CAUTION</p> <p>Do not fully open a leaking QD. Fully opening a leaking QD could trap NH3 and prevent depressing the button in the future. For 1.5 in QDs, insert fwd SPD spacer prior to opening valve</p> </div>
	Q. QD leaks after valve close operation <div style="border: 2px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">WARNING</p> <p>Bail may kick back and contact crew when a stuck button is forcibly depressed due to pressure build-up in spring cavity</p> </div>	<ol style="list-style-type: none"> Cycle Valve <ol style="list-style-type: none"> Open valve halfway (bail fwd). (For 1.5 in, install fwd SPD spacer prior to opening valve) Contact MCC-H; describe leak size and if leak rate is changing; wait for ice crystals to dissipate On MCC-H GO, re-close QD; inform MCC-H if leak still present and quantify leak If still leaking, contact MCC-H to determine if male leaking. (THOR will monitor pressure drop) On MCC-H GO, demate QD and inspect If still leaking, contact MCC-H for direction. Depending on the situation further direction could include: Living with the leak, using a QD extender, additional cycles of the QD, apply radial force to tube stub with valve open or other real-time decisions
	R. Female QD leaks after demate	<ol style="list-style-type: none"> Contact MCC-H: Describe leak size and if leak rate is changing Depending on the situation, MCC-H could recommend the following actions: Continuing ops, using a QD extender, or other real-time decisions
	S. Male QD leaks after demate (male sleeve may be visibly stuck open) 	<ol style="list-style-type: none"> Contact MCC-H: Describe leak size and if leak rate is changing If leak is small and dissipating and does not interfere with EVA: Press with operations on MCC-H GO If leak is large: Remate female QD and open valve (bail fwd) <ol style="list-style-type: none"> Depress button and use significant force to push bail forward; release button With QD in open position (bail fwd) apply significant force to aft end of the female QD in side-to-side & up and down directions (radially from tube stub) Attempt to close valve (bail aft) Demate QD and inspect If applicable, close valve of appropriate QD in flowpath, verify detent button is up, and fwd white line is visible On MCC-H GO: Install cap
	T. Frozen NH3 present on female or male QD	<ol style="list-style-type: none"> Leave QD exposed to vacuum; wait maximum of 5 min for sublimation (check periodically) On MCC-H GO: Continue QD ops. (NH3 may sublimate during QD mating)

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	SPD	
	U. ½ in SPD cannot be installed	<ol style="list-style-type: none"> 1. If aft portion of SPD not fully seated, move bail fwd slightly to allow SPD to fully seat 2. After bail secured in slot on slider, wire tie in place
	V. ½ in SPD cannot be removed	Increase force on SPD slider (1/2 in SPD sliders can be sticky)
	W. 1.5 in aft SPD spacer cannot be installed	<ol style="list-style-type: none"> 1. Install fwd SPD spacer; ensure bail against fwd SPD 2. Wire tie bail to keep it against SPD; restrain aft SPD with wire tie, if reqd
	X. 1.5 in fwd SPD spacer cannot be installed	<ol style="list-style-type: none"> 1. Install aft SPD spacer; ensure bail against aft SPD 2. Wire tie bail to keep it against SPD; restrain fwd SPD with wire tie, if reqd
	Vent Tool	
	Y. Tip of vent tool does not pass black mark during alignment check	Slide equipment hook further away from vent tool nozzle end
	Z. Vent tool cannot be mated to Vent Tool Extender	Hold VTE adapter in sunlight to warm it up. (Known tolerance issue between cold VTE adapter and vent tool nozzle)

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
<p><u>Mate QD</u></p> <ol style="list-style-type: none"> 1. Remove QD caps as required 2. Inspect male and female QD for debris or damage 3. Verify female QD ready to mate <ul style="list-style-type: none"> √Detent button – up √Locking collar – locked position √Fwd white band – not visible 4. Assess and counteract side loads prior to mate 5. Mate QD <ul style="list-style-type: none"> √Fwd white band – visible 6. Perform snapback test <ul style="list-style-type: none"> √Fwd white band visible 7. Perform pull test (Stay clear of button and release ring) 8. Perform visual gap test 	<p><u>Demate QD</u></p> <ol style="list-style-type: none"> 1. Assess and counteract side loads prior to demate 2. Pull back on release ring and demate QD 3. √Release ring – retracted (FWD white band not visible) 4. Inspect male and female QD for debris, damage, or anomalous conditions (ammonia crystals) 5. If complete with QD ops: Rotate locking collar to locked position (1/2, 3/4, & 1 in only) 6. Install QD caps as required; verify lock tab engaged 	
<p><u>Open Valve (1/4 inch)</u></p> <ol style="list-style-type: none"> 1. Prior and during bail movement assess and counteract side loads 2. Depress detent button 3. Push bail to forward position 4. √Aft white band visible 5. √Detent button – up 	<p><u>Close Valve</u></p> <p style="text-align: center;">CAUTION</p> <p>Do not fully open a leaking QD. Fully opening a leaking QD could trap NH3 and prevent depressing the button in the future. For 1.5 in QDs, insert fwd SPD spacer prior to opening valve</p> <ol style="list-style-type: none"> 1. If present, remove SPD 2. Rotate locking collar to unlocked position (1/2, 3/4, & 1 in only) 3. √Aft white band visible 4. √Detent button fully installed 5. √Detent button up 6. √Detent button can be depressed 7. Prior and during bail movement assess and counteract side loads 8. Push bail toward open position with significant force while depressing detent button (unstick male sleeve seals) 9. Depress detent button, move bail aft (close valve) 10. √Fwd white band visible 11. √Detent button up 12. If complete with QD ops: Rotate locking collar to locked position (1/2, 3/4, & 1 in only) 	
<p><u>Open Valve (1/2 inch)</u></p> <ol style="list-style-type: none"> 1. Prior and during bail movement assess and counteract side loads 2. Rotate locking collar to unlocked position 3. Depress detent button 4. Push bail fwd, so aft white band just begins to show 5. Pull lock knob up on SPD 6. Slide SPD slider aft 7. Install SPD 8. Slide SPD slider fwd to engage bail handle 9. Push bail toward closed position up against slider 10. Push lock knob down on SPD; perform pull test on SPD 	<p><u>Open Valve (3/4 inch)</u></p> <ol style="list-style-type: none"> 1. Prior and during bail movement assess and counteract side loads 2. Rotate locking collar to unlocked position 3. Depress detent button 4. Push bail to forward position 5. √Aft white band visible 6. √Detent button – up 7. Rotate locking collar to locked position 	
<p><u>Open Valve (1 inch)</u></p> <ol style="list-style-type: none"> 1. Prior and during bail movement assess and counteract side loads 2. Rotate locking collar to unlocked position 3. Depress detent button 4. Push bail to forward position 5. √Aft white band visible 6. √Detent button – up 7. Install 1 in SPD if present; verify locking tabs engage; perform pull test 8. Rotate locking collar to locked position, if present and no SPD 	<p><u>Open Valve (1.5 inch)</u></p> <ol style="list-style-type: none"> 1. Install forward SPD spacer aft of release ring 2. Prior and during bail movement assess and counteract side loads 3. Depress detent button 4. Push bail against fwd SPD spacer 5. Install aft SPD spacer 	

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	<p>FRAM</p> <p>A. Primary FRAM bolt fails to release</p> <p style="text-align: center;"><u>NOTE</u></p> <p>4 of 4 contingency pins reqd for Shuttle PLB return.</p> <p>3 of 4 contingency pins reqd for On-Orbit stowage.</p> <p>FRAM electrical connectivity fully lost at 0.95 turns on primary bolt.</p> <p>Partial electrical connectivity lost at 0.45 turns on primary bolt.</p> <p>Minimum mechanical configuration is maintained with less 2.2 turns on primary bolt (but pins highly desired time permitting)</p> <p><u>NOTE for Removal:</u> For LWAPA, SAPA, CEPA, and EXPA: For primary drive turn count of 2.2-4.7 turns, go for install of rear contingency pins due to uncertainty in PGT/Turn count. Failure to engage rear contingency pin to INSTALL location confirms turn count is 4.7 or less. Rear Contingency Pins, aft contingency pins can only be installed if the primary bolt turn count is 4.7 turns or more. With less than 4.7 turns on the primary bolt, the contingency pins are not needed and cannot be installed</p>	<ol style="list-style-type: none"> 1. Confirm socket fully engaged to release anti-rotation mechanism 2. Increase PGT setting: SAPA, MAPA, LAPA, LWAPA PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A4 (6.3) for full run-out of bolt CEPA and ExPA PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A7 (9.2) for full run-out of bolt 3. On MCC-H GO: Increase PGT setting: SAPA, MAPA, LAPA, LWAPA PGT: [B4 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A4 (6.3) for full run-out of bolt CEPA and ExPA PGT: [B4 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A7 (9.2) for full run-out of bolt 4. Reattempt engagement of primary drive with nominal PGT settings 5. Engage contingency pins: <ul style="list-style-type: none"> - Front pins (all FRAMs) PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext 0.11 + (1.25 * Turns on Primary Bolt) turns - Aft pins for MAPA and LAPA PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext If Primary Drive disengaged more than 8.8 turns: <ul style="list-style-type: none"> - Insert Contingency Pins to hardstop at 13.8 turns If the Primary Drive disengaged less than 8.8 turns use the following equation for turns needed: $2.858 + (1.25 * \text{Turns on Primary Bolt}) = \# \text{ of total turns needed}$ <p style="text-align: center;">[Stop on torque, verify turns]</p> - Aft pins for LWAPA, SAPA, CEPA, and ExPA <ul style="list-style-type: none"> - Remove bolt from STOW location and engage in INSTALL location - Manually turn bolt as far as possible - PGT: [B1 (12.0), CW2, 30.5], 7/16 - 6-ext - Aft pins for LMC FRAMs <ul style="list-style-type: none"> - Prep CPK by disengaging J-hook on locking mechanism; ensure J-hook fully seated in unlock position - Slide T-handle until contingency pin contact primary FRAM pin (# on locking mechanism counter – # of turns on primary FRAM bolt) - Engage J-hook lock (will “pop” into place if not precisely aligned with numbered slot); ensure J-hook fully seated in lock position
	<p>B. Active FRAM fails to seat on passive FRAM</p>	<ol style="list-style-type: none"> 1. Check for FOD in mechanism 2. Check alignment (engage 2 forward shear pins first to ensure connector door is not jamming)

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	<p>C. Primary FRAM bolt fails to engage</p> <p>NOTE 4 of 4 contingency pins reqd for PLB shuttle return. 3 of 4 contingency pins reqd for On-Orbit stowage. FRAM electrical connectivity begins at 10.25 turns on the primary bolt. Complete electrical mate is expected between 10.5-10.75 turns. Minimum mechanical configuration is 9 turns on primary bolt, to not need contingency pins (but pins highly desired time permitting)</p> <p>NOTE for Engage: For LWAPA, SAPA, CEPA, and EXPA: For primary drive turn count of 6.5-9 turns, go for install of rear contingency pins due to uncertainty in PGT/Turn count. Failure to engage rear contingency pin to INSTALL location confirms turn count is 6.5 or more. Aft contingency pins can only be installed if the primary bolt turn count is 6.5 turns or less. With greater than 6.5 turns on the primary bolt, the contingency pins are not needed and cannot be installed</p>	<ol style="list-style-type: none"> 1. Verify FRAM 2. Check for FOD 3. Back out primary bolt fully at nominal setting. If removal isn't successful at nominal setting Increase PGT setting for disengagement: SAPA, MAPA, LAPA, LWAPA PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A4 (6.3) for full run-out of bolt CEPA and ExPA PGT: [B2 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A7 (9.2) for full run-out of bolt On MCC-H GO: Increase PGT setting: SAPA, MAPA, LAPA, LWAPA PGT: [B4 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A4 (6.3) for full run-out of bolt CEPA and ExPA PGT: [B4 (16.0), CCW2, 30.5], 7/16 - 6-ext 1 turn only to break torque; reset PGT to A7 (9.2) for full run-out of bolt 4. Reattempt engagement SAPA, MAPA, LAPA, LWAPA, CEPA and ExPA PGT: [A7 (9.2), CW2, 30.5], 7/16 - 6-ext Increase PGT setting: SAPA, MAPA, LAPA, LWAPA, CEPA and ExPA PGT: [B2 (16.0), CW2, 30.5], 7/16 - 6-ext On MCC-H GO: Increase PGT setting: PGT: [B4 (19.4), CW2, 30.5], 7/16 - 6-ext 5. Consider hold for thermal stabilization between active and passive FRAM 6. Engage contingency pins: <ul style="list-style-type: none"> - Front pins (all FRAMs) PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext 14.11 – (1.25 * Turns on Primary Bolt) turns - Aft pins for MAPA and LAPA PGT: [A4 (6.3), CW2, 30.5], 7/16 - 6-ext If Primary Drive inserted less than 2.4 turns: - Insert Contingency Pins to hardstop at 13.8 turns If the Primary Drive inserted greater than 2.4 turns, use the following equation for turns needed: $16.858 - (1.25 * \text{Turns on Primary Bolt}) = \# \text{ of total turns needed}$ [Stop on torque, verify turns] - Aft pins for LWAPA, SAPA, CEPA, and ExPA - Remove bolt from STOW location and engage in INSTALL location - Manually turn bolt as far as possible - PGT: [B1 (12.0), CW2, 30.5], 7/16 - 6-ext - Aft pins for LMC FRAMs - Prep CPK by disengaging J-hook on locking mechanism; ensure J-hook fully seated in unlock position - Slide T-handle until contingency pin contact primary FRAM pin (# on locking mechanism counter – # of turns on primary FRAM bolt) - Engage J-hook lock (will "pop" into place if not precisely aligned with numbered slot); ensure J-hook fully seated in lock position

This Page Intentionally Blank

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	D. Rotating Latches fail to retract during FRAM removal from Square Grid Interface	<ol style="list-style-type: none"> 1. Lift FRAM so that rotating latches contact square grid 2. Cycle primary drive bolt
	E. Rotating Latches not retracted prior to installation onto Square Grid Interface	Push rotating latches to retracted position with tool or tether hook
MMOD Shield		
	A. MMOD shield Dzus fastener fails to release <div style="border: 3px double black; padding: 5px; width: fit-content;"> <p style="text-align: center;">WARNING</p> <p>Do not touch back side of MMOD shield or handle fastener fragments due to sharp edges</p> <p>Fastener and shield/tool interface must be covered to avoid potential projectiles</p> </div>	On MCC-H GO : Use pry bar to release <ol style="list-style-type: none"> a. Retrieve pry bar and emptied med ORU bag b. Release other Dzus fasteners c. Assess clearance between MMOD shield and tools d. If possible, rotate fastener to position tangs off of tools e. Place med ORU bag over failed fastener f. Insert pry bar under MMOD shield by failed fastener and pry shield away from structure
	B. MMOD shield Dzus fastener fails to engage	<ol style="list-style-type: none"> 1. Verify center fastener is engaged first 2. Check Dzus fastener aligned with bracket (floating receptacles on endcones) 3. Verify fastener clocking correct per alignment mark 4. Push firmly and rotate 5. Engage other fasteners: 2 out of 3 required 6. If 2 of 3 not achieved: <ul style="list-style-type: none"> • Option 1 (Wire Tie) (See figures 2-4): 1 properly secured wire tie = 1 Dzus fastener; Using a long wire tie, squish the loop on one end, feed it through the bracket on structure (may need to push floating receptacle inboard to get it out of way), secure wire tie w/3 twists. Feed one end of wire tie around Dzus head (on outside of shield) and secure with 3 twists. If HR nearby can also secure wire tie to HR. (Goal is for the wire tie to push shield in toward body of structure and toward center if endcone shield) • Option 2 (LDTDT): Use 1 adj. (Attach to tether point on T tool and to structure HR) and 1 LDTDT across shield to hold shield in position
	C. T-handle tool fails to engage shield	Remove adjacent fasteners and attempt reinstallation
	D. MLI grounding strap Dzus fails to release	On MCC-H GO : Cut ground wire near Dzus fastener

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)




TASK	FAILURE	ACTION
		<p data-bbox="1149 373 1382 527">Will "squish" loop together a little Pre-EVA for easier access through nutplate</p> <p data-bbox="1203 674 1409 793">Floating receptacle shifted towards center of Shield</p> <p data-bbox="1187 947 1409 1037">Wire Tie Inserted Thru "Window" on receptacle bracket</p>

Figure 2 - MMOD Shield Wire Tie Option


STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	 <p data-bbox="435 367 760 493">Install shield with wire tie ends sticking out across adjacent shield</p>	 <p data-bbox="1144 1291 1412 1396">After threading wire tie through nutplate, twist 3 times</p> <p data-bbox="565 1617 1166 1680">Figure 3 - MMOD Shield Wire Tie Option (Cont)</p>

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
 <p data-bbox="488 951 878 1152">Wrap wire tie around Dzus head; one full wrap (shown here) or wrap & twist method Then twist loose wire tie ends to create a loop</p> <p data-bbox="592 1203 1200 1262">Figure 4 - MMOD Shield Wire Tie Option (Cont)</p>		
MUT EE		
A. MUT EE jaws fail to release	<ol style="list-style-type: none"> 1. Verify locking collar fully released 2. Shake MUT EE while depressing paddles to alleviate sideloads from handrail 3. Release MUT EE ECOM socket and tether MUT EE to structure 	
MWS		
A. MWS EE is sticky	Known problem. Report degree of stickiness to MCC-H and any noted correlation with thermal environment. Post EVA, report s/n of affected unit (s/n located on "stem" of T-bar)	
B. MWS EE cord fails to retract	<ol style="list-style-type: none"> 1. Verify MWS EE tether lock in unlock position 2. Cycle MWS EE tether lock 3. Check tether reel opening for FOD 4. Pull out small amount of tether and allow reel to retract while holding light tension on the tether 	
C. MWS T-bar fails to pivot	<ol style="list-style-type: none"> 1. Check sideloads on T-bar while depressing button 2. Slip T-bar clutch (40-60 lb force required) 	


STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	NZGL Connectors	
	A. Bail bar fails to slide over-center	<ol style="list-style-type: none"> 1. Inspect bail for FOD 2. Inspect bail linkage for damage and report to MCC-H 3. Check alignment and sideloads 4. Verify sufficient TA-clamps are open 5. Increase force on bail 6. Attach 2 hooks from adj tether to connector bail and use adj strap to pull bail into demated position 7. On MCC-H GO: Retrieve vise grips to help increase force on bail
	B. Backshell fails to slide (after over-center mechanism has been overcome)	<ol style="list-style-type: none"> 1. Verify sufficient TA-clamps are open 2. Check for cable harness and hardware interference 3. Check alignment and sideloads 4. Inspect bail and connector for FOD 5. Inspect bail linkage for damage and report to MCC-H 6. Wiggle/jiggle connector while pushing or pulling on backshell 7. Attach 2 hooks from adj tether to connector bail and use adj strap to pull bail into demated position 8. On MCC-H GO: Retrieve vise grips to help increase force on bail
	C. Connector fails to release from soft dock	<ol style="list-style-type: none"> 1. Verify bail fully thrown, undamaged, and backshell fully aft 2. If backshell springs forward, pull and hold in fully aft position (will have to overcome spring force, approx. 5-10 lb) while attempting to demate connector 3. Verify sufficient TA-clamps are open 4. Check for cable harness and hardware interference 5. Check alignment and sideloads 6. Relieve compression on connector interface due to cable loads by pulling backshell away from jack 7. Push the plug towards the jack to compress the soft dock 8. Wiggle/jiggle connector. (Use slight rolling motion)
	D. Connector fails to soft dock	<ol style="list-style-type: none"> 1. Verify correct plug and jack 2. Verify bail fully aft 3. Verify backshell fully aft and remains fully aft. If backshell not fully aft, pull and hold in fully aft position while attempting to soft dock connector 4. Inspect the following: <ul style="list-style-type: none"> • O-ring seal • FOD • Bend radius • Soft dock springs • Connector keying feature 5. Verify alignment. (Avoid excessive rolling or rocking the plug as this could unseat soft dock springs) <ul style="list-style-type: none"> • Connector should snap into soft dock with little force once half shells are aligned


STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	E. Connector fails to mate	<ol style="list-style-type: none"> 1. Verify half-shells are fully seated on both sides 2. Verify cable and backshell free to move (no clamps) 3. Push forward on connector backshell while actuating bail 4. Detach from soft dock and inspect: <ul style="list-style-type: none"> • Pins • FOD • EMI band • Bend radius • TA clamps • P clamps • Bail linkages and rivets • Soft dock springs • O-ring seal and main joint gasket • Connector keying feature 5. Cycle bail while disconnected (push forward on connector backshell for additional leverage)
	F. Connector pin bent	<ol style="list-style-type: none"> 1. Rotate connector to bail up position and describe pin location and condition <ul style="list-style-type: none"> • Obtain WVS view of interface if possible 2. On MCC-H GO: For 16, 20, or 22 gauge pins only, retrieve pin straightener and attempt pin repair <ul style="list-style-type: none"> • MCC-H will verify pin size prior to retrieving tools 3. On MCC-H GO: Retrieve needle nose pliers and attempt pin repair 4. Inspect plug and jack prior to re-mating
	G. Connector FOD	<ol style="list-style-type: none"> 1. On MCC-H GO: Remove FOD with connector cleaner tool <ol style="list-style-type: none"> a. Retrieve connector cleaner tool <p style="text-align: center;"><u>NOTE</u></p> <p>One N2 cartridge is already captured in the tool (the other is lanyarded inside the caddy). In order to puncture the cartridge, it must be threaded into the tool until the indicator line passes out of sight under the collar of the tool.</p> <p>Puncture connector cleaner cartridge only when ready to perform actual cleaning.</p> <p>Use entire N2 cartridge prior to reentering airlock</p> <ol style="list-style-type: none"> b. Attempt cleaning
	H. Connector EMI band bent	<p>On MCC-H GO: Retrieve needle nose pliers or forceps to remove band</p> <ul style="list-style-type: none"> • Bail may need to be pushed forward while demated to expose EMI band for removal
		
	I. Connector bail linkage failure	<ol style="list-style-type: none"> 1. On MCC-H GO: Re-attempt connector mate/demate with broken bail <ul style="list-style-type: none"> • Impart load through undamaged side of bail linkage • Assist bail motion with hand on backshell once bail linkage has passed over-center • May take multiple pushes on the bail to mate/demate connector 2. Tether hook or vise grips may be used for additional leverage

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	<p>J. Connector soft dock spring bent</p> 	<p>On MCC-H GO: Retrieve needle nose pliers and remove bent spring</p>
	<p>K. Connector O-ring or main joint gasket seal loose (seal and O-ring required in 1-G only)</p>	<ol style="list-style-type: none"> 1. Remove seal with tether hook 2. On MCC-H GO: Retrieve additional tools to remove seal. (Ex., wire tie, needle nose pliers, probe, loop pin puller)
	<p>L. Connector cap (Twist) will not release</p>	<ol style="list-style-type: none"> 1. Increase force 2. Use tether hook for additional leverage 3. On MCC-H GO: Attach equip hook to cap tether point and use strap of adj tether to release cap
On-Orbit Installed HR		
	<p>A. HR will not install in seat track or fails to soft dock</p>	<ol style="list-style-type: none"> 1. Verify HR installed in correct direction per arrow on underside of HR 2. Verify HR shoes are completely released and soft dock armed 3. Check for FOD on HR and seat track 4. Verify HR bolt completely released: PGT [A1 (2.5), CCW2, 30.5], 7/16 - 6-ext 5. If HR in seat track but soft dock will not engage, attempt to drive HR bolts 6. On MCC-H GO: Depending on HR priority, attempt to install 180 out or a different HR at this location
	<p>B. HR bolt fails to fully engage</p>	<ol style="list-style-type: none"> 1. If torqued, remove HR: PGT [A2 (3.8), CCW2, 30.5], 7/16 - 6-ext <ul style="list-style-type: none"> • To break torque PGT [A1 (2.5), CCW2, 30.5], 7/16 - 6-ext <ul style="list-style-type: none"> • For removal: Check for FOD on HR and seat track and reinstall using original torque 2. Increase PGT setting: PGT [A3 (4.8), CW2, 30.5], 7/16 - 6-ext 3. On MCC-H GO: Depending on HR priority, attempt to install 180 out or a different HR at this location
On-Orbit Installed WIF		
	<p>A. WIF fails to soft dock</p>	<ol style="list-style-type: none"> 1. Check for FOD and structural interference, cycle soft dock pins; reattempt installation 2. Verify WIF is co-planar to structure 3. Install a different WIF at this location 4. On MCC-H GO: Attempt installation of WIF in a different location 5. Return WIF inside
PAD		
	<p>A. Release knob fails to rotate open</p>	<ol style="list-style-type: none"> 1. Verify knob in release position (J-hook not locked) 2. Attempt to rotate knob using ratchet on knob's 7/16 in hex stud 3. Release contingency release bar captive bolts (2) PGT [A6 (8.3), CCW2, 30.5], 7/16 - 6 ext 5 turns (Verify hook released from striker bar)
PGT		
	<p>A. No LEDs</p>	<ol style="list-style-type: none"> 1. Perform LED test 2. Use display torque
	<p>B. LEDs and torque messages do not agree</p>	<p>Use torque message and notify MCC-H</p>
	<p>C. Mode switch breaks</p>	<p>Retrieve spare PGT</p>

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	D. NEED TO CAL displayed during PGT operation after calibration complete	<ol style="list-style-type: none"> 1. Power cycle and calibrate 2. Retrieve spare PGT 3. Power off and switch to ratchet mode
	E. TRIG TO CAL displayed with Mode collar set to MTR (Display should nominally read NEED TO CAL)	<ol style="list-style-type: none"> 1. Set Mode collar to RCW or RCCW <ol style="list-style-type: none"> a. Depress Trigger; Verify CAL PASSED b. Set Mode collar to MTR c. Verify good LED Test 2. Power Off <ol style="list-style-type: none"> a. Set Mode collar to RCW or RCCW b. Verify Speed collar in CAL c. Power On d. Verify TRIG TO CAL on display e. Complete calibration; Continue Ops 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
	F. PGT fails to drive with Mode collar set to MTR	<ol style="list-style-type: none"> 1. Power cycle and calibrate 2. Set Mode collar to RCW or RCCW <ol style="list-style-type: none"> a. Depress Trigger; Verify CAL PASSED b. Set Mode collar to MTR c. Verify good LED Test 3. Power Off <ol style="list-style-type: none"> a. Set Mode collar to RCW or RCCW b. Verify Speed collar in CAL c. Power On d. Verify TRIG TO CAL on display e. Complete calibration; Continue Ops 4. Retrieve spare PGT 5. Power off and switch to ratchet mode
LCD Messages		
	G. BATTERY HITEMP	<ol style="list-style-type: none"> 1. Power off PGT 2. If alternate battery available; change battery 3. Retrieve spare PGT 4. Switch to ratchet mode
	H. BATTERY LOTEMP (blinking)	<ol style="list-style-type: none"> 1. Drive tool with no load to increase battery temperature 2. If alternate battery available; power off and change battery 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
	I. BATTERY LOVOLT (blinking)	<ol style="list-style-type: none"> 1. Continue using tool until unable to deliver sufficient torque 2. Retrieve spare PGT 3. Power off and switch to ratchet mode
	J. CAL FAILED	<ol style="list-style-type: none"> 1. Press, release trigger to repeat calibration 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
	K. COLLAR ERROR	<ol style="list-style-type: none"> 1. Cycle torque and speed collars to clear error 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
	L. COMPAR ERROR	<ol style="list-style-type: none"> 1. Cycle torque collar and A/B mode switch 2. Power cycle and calibrate 3. Retrieve spare PGT 4. Power off and switch to ratchet mode
	M. EEPROM WR ERR (blinking) HYBRID HITEMP OVER CURR SLFTST FAIL X	<ol style="list-style-type: none"> 1. Power cycle and calibrate 2. Retrieve spare PGT 3. Power off and switch to ratchet mode


STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	N. HI TORQ	<ol style="list-style-type: none"> Contact MCC-H and report torque (Real time engineering assessment required) On MCC-H GO: Power cycle and calibrate Retrieve spare PGT Power off and switch to ratchet mode
	O. HICURR	<ol style="list-style-type: none"> Reattempt operation <ul style="list-style-type: none"> Can be caused by excessive rotation of the PGT body while torquing Power cycle and calibrate Retrieve spare PGT Power off and switch to ratchet mode
	P. LO TORQ (Expected during bolt release)	<ol style="list-style-type: none"> Reattempt operation until desired torque is reached Power cycle and calibrate Retrieve spare PGT Power off and switch to ratchet mode
	Q. LOCURR	<ol style="list-style-type: none"> Reattempt operation Power cycle and calibrate Retrieve spare PGT Power off and switch to ratchet mode
	R. LOG IS FULL (blinking)	<ol style="list-style-type: none"> Cycle torque and speed collars to clear message Continue operation
	S. MOTOR HITEMP	<ol style="list-style-type: none"> Power off PGT Retrieve spare PGT Switch to ratchet mode
Safety Tether		
	A. Safety tether fails to retract/tend	<ol style="list-style-type: none"> Verify reel is unlocked Verify tether reel and/or cable guide (for 85-ft tethers) is clear of FOD Pull out small amount of cable and allow reel to retract while holding light tension on the cable Tap side of reel housing during retraction Report ID # of faulty tether to MCC-H and use alternate safety tether Coil safety tether to bring inside For 85-ft tether. On MCC-H GO: If coiling tether is not practical, release level wind mechanism bypass on back of safety tether. (Red indicator will show around edge of bypass once released) <p style="text-align: center;">NOTE</p> <p>Once level wind has been released cable guide will likely be frozen in place. This will limit the amount of tether that can be successfully retracted into the tether housing and may require coiling of excess tether.</p> <p>Level wind release will require safety tether be returned for ground servicing.</p> <p>If tether fails to retract due to thermal issue, normal tether function may return after tether brought IVA</p>


STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
	B. Safety tether red stripe showing (any length)	<ol style="list-style-type: none"> 1. Use alternate safety tether 2. Connect waist tether to ERCM body as alternative load alleviation (Double Tether) 3. Inspect "Through" tack stitches. Tether NO-GO until tack stitching inspected. (Reference Crew Tether Inspection procedure) <ol style="list-style-type: none"> a. 1 of 2 stitches is required for tether to be GO for use b. If both "Through" stitches are broken, safety tether NO-GO for use <ul style="list-style-type: none"> • Report ID # of faulty tether to MCC-H • Use alternate safety tether
	C. Crew hook fails	<ol style="list-style-type: none"> 1. On load alleviating end: Use waist tether to replace alleviating strap <ul style="list-style-type: none"> • Report ID # of faulty tether to MCC-H • Retrieve replacement safety tether 2. On anchor end: Report ID # of faulty tether to MCC-H and use an alternate safety tether
Scoops		
	A. Scoop will not release from fitting	<ol style="list-style-type: none"> 1. If actuator will not pull back while in locked position, tap actuator with tool to release 2. On MCC-H GO: Leave scoop in place 3. On MCC-H GO: Remove non-captive contingency screws; 5 turns. Stow in trash bag PGT [A1 (2.5), CCW2, 30.5], 5/32 Allen drive <ul style="list-style-type: none"> • Square Scoop: 4 screws (figure 5) • Round Scoop: 7 screws (figure 6)
<div style="text-align: center;">  <p data-bbox="496 1541 776 1604">Contingency Release Fasteners (X4)</p> <div style="border: 1px solid black; padding: 5px; display: inline-block;"> <p data-bbox="824 1675 1117 1707">Figure 5 - Square Scoop</p> </div> </div>		





STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
 <p style="text-align: center; border: 1px solid black; display: inline-block; padding: 2px;">Figure 6 - Round Scoop</p>		
Socket Caddy		
A.	Socket fails to release from socket caddy	<ol style="list-style-type: none"> 1. Verify PIP pin fully inserted into drop proof tether interface on socket 2. Reattempt using a different PIP pin
TA Clamp		
A.	TA clamp fails to release	<ol style="list-style-type: none"> 1. With handle up, press down on top of rounded clamp 2. With handle up, use tether hook to pry drawhook from capture pin
Tether Shuttle		
A.	Tether shuttle will not release from CETA/MT rail	<ol style="list-style-type: none"> 1. Verify slider in unlock and no obstructions to paddle actuation 2. Verify safety tethered to structure and safety tether removed from tether shuttle anchor point 3. On MCC-H GO: Remove non-captive screws (2) at hingeline to release nadir section with slide lock (not captive) (figure 7). TBD turns. Stow screws in trash bag PGT [A1 (2.5), CCW1, 30.5], 5/32 Allen drive

STS-135/ULF7 WORKAROUNDS CRIBSHEET (Cont)

GENERIC CONTINGENCIES (Cont)

TASK	FAILURE	ACTION
		
Torque Multiplier		
A. TM will not release from fitting		<ol style="list-style-type: none"> 1. Place TM anti-backlash in neutral, if unable: PGT [RCW, 30.5] <ul style="list-style-type: none"> • Apply cw torque while pushing anti-backlash button to neutral. Reattempt removal 2. If able to lift TM off of bolt, attempt to rock off of fitting (Square TM only) 3. On MCC-H GO: Release TM contingency release band pin 20 turns (do not exceed 28 turns) (figure 8): PGT [A1 (2.5), CCW2, 30.5], 5/32 ball end driver <ul style="list-style-type: none"> • When band springs open remove TM
		
Figure 8 - Torque Multiplier		
TSA		
A. Latch fails to open		Release 7/16 EVA bolt on latch bracket; rotate bracket clear of latch PGT [A2 (3.8), CCW2, 30.5], 7/16 - 6 ext 1-2 turns
B. Latch fails to close		Close remaining latches arrow to arrow (3 of 4 required for landing)

RELEASE ROEU LATCHES

IV	EV
<p>1. <u>DEADFACE ROEU</u></p> <div data-bbox="327 331 961 456" style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;"><u>CAUTION</u></p> <p>Deactivating APCU 2 will remove critical keep-alive power to LCH and IDC. Power must be reapplied within 105 min</p> </div> <p style="text-align: center;"><u>NOTE</u></p> <p>With following steps expect: 'S200 APCU 1(2) VOLT LMT' msgs 'S200 APCU 1(2) TRIP' msgs</p> <p>SSP1 √APCU 1 CONV – OFF √OUTPUT RLY – OP (tb-bp) APCU 2 CONV – OFF (tb-bp) OUTPUT RLY – OP (tb-bp)</p> <p> √MPLM CHAN 1,2 HTR PWR (two) – OFF (tb-bp)</p> <p>R1 PL PRI MNC – OFF (tb-OFF)</p> <p>2. <u>ROEU SAFING</u></p> <p>R13L √PL BAY MECH PWR SYS 1,2 (two) – OFF A6U √RETEN LOGIC PWR SYS 1,SYS 2 (two) – OFF PL SEL – 1</p> <p style="text-align: center;">Give EV GO to release ROEU</p>	<p>Tools reqd: Ratchet with 3-in Ext (Airlock)</p> <div data-bbox="1125 367 1780 480" style="border: 3px double black; padding: 5px;"> <p style="text-align: center;"><u>WARNING</u></p> <p>For release, do not close access cover until ROEU stowed. Latches may not snap back to closed posn</p> </div> <p>1. On IV GO, open latch drive access cover: Break safety cord, release access cover (3/4 turn ccw) Open access cover (~120°) Manual drive to RELEASE: Rotate control lever to RELEASE Rotate latch drive cw (~9 ft-lb) to hard stop (~3/4 turn) Remove drive ratchet, clear worksite</p>

RELEASE ROEU LATCHES (Cont)

IV	EV
<p>3. <u>VERIFY TALKBACKS</u> Install <u>ROEU A6U PANEL OVERLAY</u></p> <p>PL RETEN PL SEL – 2</p> <div style="text-align: center;"> </div> <p>R13L A6U</p> <p>PL BAY MECH PWR SYS 1,2 (two) – ON PL RETEN LOGIC PWR SYS 1,SYS 2 (two) – ON</p> <p>Note single motor time (> 18 sec)</p> <p>DEMATE/MATE – DEMATE (tb-REL), 36 sec max – OFF</p> <div style="text-align: center;"> </div> <p>PL RETEN LOGIC PWR SYS 1, SYS 2 (two) – OFF PL SEL – 1</p> <p>R13L</p> <p>PL BAY MECH PWR SYS 1,2 (two) – OFF</p>	<div style="border: 3px double black; padding: 10px; text-align: center;"> <p><u>WARNING</u></p> <p>For release, remain clear of latches during access cover closing. Latches may snap back to closed posn</p> </div>

RELEASE ROEU LATCHES (Cont)

IV	EV
<p>R1</p> <p>4. <u>ENABLE POWER</u> PL PRI MNC – ON (tb-ON)</p> <p>Perform LCH ACTIVATION (LCS Cue Card, PHOTO/TV) Perform LCC ACTIVATION, step 2 (LCS Cue Card, PHOTO/TV) Perform LCC DEACTIVATION, step 1 (LCS Cue Card, PHOTO/TV) Notify MCC: “LCC Cue Card steps are complete”</p>	<p>2. Reengage latch actuator: Rotate control lever to neutral posn Close, secure access cover (3/4 turn cw) Clear worksite</p>

LATCH ROEU LATCHES (Cont)

IV	EV
<p>A6U R13L</p> <p>3. <u>MATE ROEU</u> PL RETEN LOGIC PWR SYS 1,2 (two) – ON BAY MECH PWR SYS 1,2 (two) – ON</p> <p>Note single motor time (> 30 sec)</p> <p>A6U</p> <p>DEMATE/MATE – MATE (tb-LAT), 60 sec max – OFF</p> <div style="text-align: center;"> <p>ELEC CONT</p> <p>RELAX DEMATE RELEASE</p> <p>✓ </p> <p> MATE LATCH</p> </div> <p>R13L A6U</p> <p>4. <u>ROEU SAFING</u> PL BAY MECH PWR SYS 1,2 (two) – OFF RETEN LOGIC PWR SYS 1, SYS 2 (two) – OFF PL SEL – 1</p> <p>Give EV GO to latch ROEU</p>	<p>1. On IV GO, open latch drive access cover: Break safety cord, release access cover (3/4 turn ccw) Open access cover (~120°) Manual drive to LATCH: Rotate control lever to LATCH Rotate latch drive ccw (~9 ft-lb) to hard stop (~3/4 turn) Remove drive ratchet, clear worksite</p>


LATCH ROEU LATCHES (Cont)

IV	EV
<p>A6U 5. <u>VERIFY TALKBACKS</u> PL RETEN PL SEL – 2</p> <div style="text-align: center;"> <p style="text-align: center;">ELEC CONT ✓ <input type="checkbox"/></p> <p>RELAX DEMATE RELEASE ✓ <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> LAT MATE LAT LATCH</p> </div> <p>R13L 6. <u>RELAX ROEU</u> A6U PL BAY MECH PWR SYS 1,2 (two) – ON RETEN LOGIC PWR SYS 1,SYS 2 (two) – ON</p> <p style="text-align: center;"><u>NOTE</u> Monitor PL SEL 2 LATCH 1 REL SYS msws on SPEC 97</p> <p>Note single motor time (> 12 sec)</p> <p>RELAX – RELAX (tb-REL), 24 sec max</p> <p>When LATCH 1 REL A(B) msw changes to 1: RELAX – OFF</p> <div style="text-align: center;"> <p style="text-align: center;">ELEC CONT <input type="checkbox"/></p> <p>RELAX DEMATE RELEASE ✓ <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> REL MATE LAT LATCH</p> </div> <p>R13L PL RETEN LOGIC PWR SYS 1,2 (two) – OFF BAY MECH PWR SYS 1,2 (two) – OFF</p>	<p>2. Reengage latch actuator: Rotate control lever to neutral posn Close, secure access cover (3/4 turn cw) Clear worksite</p>


LATCH ROEU LATCHES (Cont)

IV	EV
<p>R1</p> <p>7. <u>ENABLE POWER</u> PL PRI MNC – ON (tb-ON)</p> <p>Perform LCH ACTIVATION (LCS Cue Card, PHOTO/TV) Perform LCC ACTIVATION, step 2 (LCS Cue Card, PHOTO/TV) Perform LCC DEACTIVATION, step 1 (LCS Cue Card, PHOTO/TV) Notify MCC: “LCC Cue Card steps are complete”</p>	

STOW ROEU ARM (Cont)

	IV	EV
<p>R13L</p> <p>2. <u>RELEASE LATCHES</u> PL RETEN LOGIC PWR SYS 1,2 (two) – ON BAY MECH PWR SYS 1,2 (two) – ON</p> <p>Note single motor time (> 20 sec)</p> <p>RELEASE/LATCH – REL (tb-REL), 40 sec max – OFF</p> <div style="text-align: center;">  <p>The diagram shows a control panel with five buttons. From left to right: 'RELAX REL' (with a checkmark to its left), 'DEMATE MATE' (with a checkmark above it), 'RELEASE REL LATCH' (with a checkmark above it), and 'ELEC CONT' (with a checkmark above it). Each button is represented by a square with a diagonal hatching pattern.</p> </div> <p>R13L A6U</p> <p>3. <u>ROEU SAFING</u> PL BAY MECH PWR SYS 1,2 (two) – OFF RETEN LOGIC PWR SYS 1, SYS 2 (two) – OFF PL SEL – 1</p> <p>Give EV GO to stow ROEU</p>	<p>1. On IV GO, open arm drive access cover: Break safety cord, release access cover (3/4 turn ccw) Open access cover (~120°)</p> <p>Manual drive to STOW: Rotate control lever to STOW Rotate arm drive ccw (~23 ft-lb) to hard stop and pull arm inboard to verify Remove drive ratchet</p>	

STOW ROEU ARM (Cont)

	IV	EV
<p>A6U</p> <p>4. <u>VERIFY TALKBACKS</u> PL RETEN PL SEL – 2</p> <div style="text-align: center;">  <p>The diagram shows a control panel layout. At the top center is the label 'ELEC CONT' above a square button with diagonal hatching. Below it are three columns of buttons. The first column has 'RELAX' above a 'REL' button, with a checkmark to its left. The second column has 'DEMATE' above a 'REL' button, with 'MATE' centered below it. The third column has 'RELEASE' above a 'REL' button, with 'LATCH' centered below it.</p> </div> <p>R1</p> <p>5. <u>ENABLE POWER</u> PL PRI MNC – ON (tb-ON)</p> <p>Perform LCH ACTIVATION (LCS Cue Card, PHOTO/TV) Perform LCC ACTIVATION, step 2 (LCS Cue Card, PHOTO/TV) Perform LCC DEACTIVATION, step 1 (LCS Cue Card, PHOTO/TV) Notify MCC: “LCC Cue Card steps are complete”</p>	<p>2. Reengage arm actuator: Rotate control lever to neutral posn Close, secure access cover (3/4 turn cw) Clear worksite</p>	


MATE ROEU ARM

IV	EV
<p>1. <u>DEADFACE ROEU</u></p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p style="text-align: center;">CAUTION</p> <p>Deactivating APCU 2 will remove critical keep-alive power to LCH and IDC. Power must be reapplied within 105 min</p> </div> <p style="text-align: center;">NOTE</p> <p>With following steps expect: 'S200 APCU 1(2) VOLT LMT' msgs 'S200 APCU 1(2) TRIP' msgs</p> <p>SSP1 √APCU 1 CONV – OFF √OUTPUT RLY – OP (tb-bp) APCU 2 CONV – OFF (tb-bp) OUTPUT RLY – OP (tb-bp)</p> <p> √MPLM CHAN 1,2 HTR PWR (two) – OFF (tb-bp)</p> <p>R1 PL PRI MNC – OFF (tb-OFF)</p> <p>A6U 2. <u>CONFIGURE ROEU</u> Install <u>ROEU A6U PANEL OVERLAY</u></p> <p>A6U 3. <u>VERIFY TALKBACKS</u> PL RETEN PL SEL – 2</p> <div style="text-align: center; margin-top: 20px;"> <p>ELEC CONT</p> </div>	<p>Tools reqd: Ratchet with 3-in Ext (Airlock)</p> <p>1. On IV GO, open arm drive access cover: Break safety cord, release access cover (3/4 turn ccw) Open access cover (~120°) Manual drive to MATE: Rotate control lever to MATE Ratchet arm drive cw (~25 ft-lb) until "READY TO LATCH" posn indicated on interface guide Remove drive ratchet Clear worksite (for latching)</p>

MATE ROEU ARM (Cont)

	IV	EV
<p>R13L A6U</p> <p>4. <u>LATCH LATCHES</u> PL BAY MECH PWR SYS 1,2 (two) – ON RETEN LOGIC PWR SYS 1,SYS 2 (two) – ON</p> <p>Note single motor time (> 20 sec)</p> <p>RELEASE/LATCH – LATCH (tb-LAT), 40 sec max – OFF</p> <div data-bbox="294 535 735 763" style="text-align: center;"> <p>The diagram shows a control panel with the following elements: - A checkmark to the left of a button labeled 'RELAX' which has diagonal hatching. - A button labeled 'DEMATE' with 'LAT' written below it. - A button labeled 'RELEASE' with 'LAT' written below it. - A button labeled 'ELEC CONT' with a checkmark above it. - A button labeled 'MATE' below 'DEMATE'. - A button labeled 'LATCH' below 'RELEASE'.</p> </div>		
<p>R13L</p> <p>PL RETEN LOGIC PWR SYS 1,SYS 2 (two) – OFF BAY MECH PWR SYS 1,2 (two) – OFF</p> <p>5. <u>RELAX ROEU (EVA)</u> Monitor PL RETEN LAT 1 tb</p> <p>Give EV GO to STOW arm, halt once RELAX tb – REL</p>	<p>2. <u>RELAX ROEU (EVA)</u> On IV GO, rotate control lever to STOW: Ratchet arm drive ccw until IV receives RELAX 1 tb – REL Remove drive ratchet</p> <p>3. Reengage arm actuator: Rotate control lever to neutral posn Close, secure access cover (3/4 turn cw) Clear worksite</p>	
<p>R1</p> <p>6. <u>ENABLE POWER</u> PL PRI MNC – ON (tb-ON)</p> <p>Perform LCH ACTIVATION (LCS Cue Card, PHOTO/TV) Perform LCC ACTIVATION, step 2 (LCS Cue Card, PHOTO/TV) Perform LCC DEACTIVATION, step 1 (LCS Cue Card, PHOTO/TV) Notify MCC: “LCC Cue Card steps are complete”</p>		

ROEU OVERVIEW



SSRMS JOINT DRIVE

CAUTION	
Avoid contact with the following:	
1.	ACU radiator surface [silver Teflon film (white in color)].
2.	CLA and CLPA radiator surface [silver Teflon film (white in color)].
3.	VDU radiator surface [silver Teflon film (white in color)].
4.	JEU radiator surface (Z93 paint).






NOTE


1. Gear ratio: 3.26 EVA Drive turns/1 degree of joint movement.
2. CW input to the EVA drive will produce CCW motion of the joint.
3. Starting from LEE, the order of the joints: roll, yaw, pitch.
4. The signs of the logical (indicated on RWS or PCS) and physical (indicated on EVA scale) angles are reversed for the shoulder roll, shoulder yaw, and wrist roll joint (i.e., +73.2 logical = -73.2 physical) regardless of which end is base.
5. Scale and Ambiguity Switch: Since the SSRMS joints can be rotated more than 360 degrees, there is an ambiguity switch that tells the crewmember whether to use the positive or negative scale.

The crew reads the scale using the black triangle on the fixed side of the joint. Located to the side of the black triangle (~90 degrees around the circumference of the joint) is the ambiguity switch. The switch has a pointer that indicates "+" or "-" to tell the crew which side of the scale to read. If the ambiguity switch points to "+", the crew should read off the yellow scale (black text on yellow background). If the switch points to "-", the crew should read off the black scale (yellow text on black background).

EVA Drive handle is on back side of joint (away from LEE), and scale triangle is across from it towards the LEE side.

SSRMS JOINT DRIVE (Cont)

IV/RMS	EV1	REFERENCE
<p>SSRMS EVA JOINT DRIVE POSITION</p> <p>IV</p> <ol style="list-style-type: none"> Record ambiguity sensor reading and joint angle: _____ Monitor SSRMS joint angle. Report position to EV1. Give EV1 STOP when joint angle is at desired position. <div data-bbox="142 716 640 1209">  <p>Joint Scale and Black Triangle</p>  <p>Ambiguity Switch</p>  <p>Back Side of Joint</p> <p>EVA Drive Handle (at motor position)</p> <p>Ambiguity Switch</p> </div>	<ol style="list-style-type: none"> Translate to failed joint. If required for body stabilization, install square scoop on joint micro fitting and attach BRT. <p>INITIAL POSITION VERIFICATION</p> <ol style="list-style-type: none"> Verify initial joint position using the following: <ul style="list-style-type: none"> <input type="checkbox"/> Black triangle on fixed side of failed joint <input type="checkbox"/> Ambiguity sensor (90 degrees CW from EVA drive, toward front side of joint) <p>JOINT EVA DRIVE</p> <ol style="list-style-type: none"> Press button and move EVA Drive Handle to EVA. <div data-bbox="709 699 1199 756" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>NOTE Joint will rotate in opposite direction of PGT.</p> </div> <ol style="list-style-type: none"> PGT[A1 2.5 ft-lb, CW2 or CCW2 30 RPM (as required), MTL 2.5]-6 ext 7/16: Drive EVA bolt in ± direction _____ turns to specified position. Verify joint angle using scale and ambiguity sensor. If possible, verify joint angle with IV. If necessary, fine position joint using PGT in manual ratchet mode. Press button and move EVA Drive Handle to MOTOR. If used, retrieve square scoop. 	<div data-bbox="1241 293 1885 716">  </div> <div data-bbox="1241 727 1885 1209">  <p>EVA DRIVE HANDLE</p> <p>EVA DRIVE BOLT</p> </div>



SSRMS JOINT DRIVE (Cont)

TASK DATA

Table 1. Tools

EV1 (FF)
PGT
7/16 (wobble) Socket-6 ext
BRT
Square Scoop

Table 2. EVA Fasteners

Fastener Name	Label	Head Size	Qty	Min Drive Torque (ft-lb)	Max Drive Torque (ft-lb)	Failure Torque (ft-lb)	RPM
EVA Drive		7/16	1	1.25	2.5		30

Foot Restraints: N/A

SSRMS JOINT DRIVE (Cont)





Figure 1.- Roll/Pitch Joint ORU.

SSRMS JOINT DRIVE (Cont)




Figure 2.- YAW Joint ORU.

GENERIC EVA INHIBIT PAD

Orbiter (1)

ALL EVAs	
TCS L12	1. √TCS POWER – OFF
KU-Band Antenna	
MCC-H	1. √KU-BAND Mask – active 2. √KU-BAND EVA Protect Box – active
RCS	
	If EV crew < 27 feet from FRCS
IV O14,15,16	1. √DAP: VERN, FREE, LO Z (flt specific check with GNC) 2. √RJDF F1, F2, F3, F4 MANF DRIVER (four) – OFF LOGIC (four) – OFF
MCC-H	3. √Above RCS config
IV	4. √RCS F – ITEM 1 EXEC (*) √JET DES F1U – ITEM 17 (*) F3U – ITEM 19 (*) F2U – ITEM 21 (*)

Ground

ALL EVAs	
Ground Radar	
MCC-H	1. √TOPO console, ground radar restrictions in place for EVA

Orbiter (2)

LOCATION DEPENDENT INHIBITS	
OBSS - LDRI TO INHIBIT LASER FIRING BUT LEAVE HEATER POWER ON	
<u>NOTE</u>	
This procedure works best when performed during orbital night, and OBSS must be positioned such that its diffuser window is visible in the Camera B view.	
R12(VPU) A7U	1. √Green Jumper – LDRI/ITVC 2. VIDEO OUT MON2 pb – push IN B pb – push OUT MON1 pb – push IN PL2(VPU) pb – push 3. Center Cam B (ITVC) in the view of LDRI/ITVC 4. VIDEO OUT MON2 pb – push 5. Center LDRI/ITVC diffuser in the view of Cam B (ITVC) 6. CAMR CMD ZOOM – IN (FULL) 7. VIDEO OUT MUX 1 L pb – push IN MIDDECK pb – push
<u>NOTE</u>	
The following step will power off the LDRI laser. Observe the LDRI diffuser in the Camera B view and verify the laser turns off. Report observation to MCC-H .	
	8. LDRI MODE 1 pb – push 9. VIDEO IN as desired (not MIDDECK)
<u>POINT PTU/LDRI AWAY FROM EV CREW</u>	
A7U	10. VIDEO OUT MON1 pb – push IN PL2(VPU) pb – push 11. CAMR CMD PAN/TILT – HI RATE PAN – L (to hard stop) TILT – UP (to hard stop) PAN/TILT – RESET PAN/TILT – HI RATE (LO within 10°) PAN: TBD TILT: TBD
R12(OBSS)	12. ITVC ENA – OFF

GENERIC EVA INHIBIT PAD (Cont)

Orbiter (3)

LOCATION DEPENDENT INHIBITS (Cont)

OBSS - LCS

TO INHIBIT LASER FIRING BUT LEAVE HEATER POWER ON

- IV 1. Perform LCC DEACTIVATION step 1 (FDF P/TV CUE CARD, LCS), then:

To shut down and remove all power to LCS (and ROEU if flown)

NOTE

These steps remove all power from LCS sensor and start a 105-minute thermal clock.

- IV 2. Perform LCH DEACTIVATION (FDF P/TV CUE CARD, LCS), then:

R1 3. √PRI PL MNC – OFF (tb-OFF)

A6U 4. √PL RETEN PL SEL – 1

EFGF Connector

NOTE

These steps remove all power from both OBSS sensors and start a 90-minute thermal clock.

- IV 1. √DEACTIVATION complete (FDF P/TV CUE CARD, LDRI/ITVC)
 2. √LCC DEACTIVATION complete (FDF P/TV CUE CARD, LCS)
 3. √LCH DEACTIVATION complete (FDF P/TV CUE CARD, LCS)

S-Band Antennas

NOTE

Possible loss of comm when forced LL FWD antenna.

- IV If EV crew < 2 feet from S-Band antenna
 A1R 1. S-BAND FM ANT – XMIT LOWER/RCVR UPPER
 2. √MCC, lower antenna selected
 If no comm, or **On MCC GO**
 C3 3. S-BAND PM ANT – LL FWD
 When EVA crewmember at least 2 feet away from all S-Band upper antennas
 C3 4. S-BAND PM ANT – GPC

USOS (1)

ALL EVAs

PCU

NOTE

PCUs may require up to a 1-hour warmup period before they are operational.

- MCC-H** 1. √PCUs (two) operational in discharge mode and one of the following:
 a. CCS PCU EVA hazard control FDIR enabled.
 b. No more than two arrays unshunted and oriented <105° from velocity vector.
 If one or both PCUs failed
 2. No more than two arrays unshunted and oriented <105° from velocity vector.

CUCU

IV - (LAB1O4)

1. √cb POWER A, B (two) – OPEN
 2. √cb LINK 1,2 (two) – OPEN

MISSE 8

POIC

Prior to EV Hatch Open

1. ELC-2 ExPA-2 Discrete Channel 6 – Disabled

GENERIC EVA INHIBIT PAD (Cont)

LOCATION DEPENDENT INHIBITS

Lab Window

IV If EV crew less than 10 feet from window or in window FOV, close window shutter.

Cupola Windows

IV If EV crew less than 10 feet from window, coordinate shutter opening/closing with EV crew and minimize time shutter is open.

KU-Band (SGANT Antenna)

MCC-H If EV crew < 3.3 feet from KU-BAND antenna

1. Park KU-BAND
 - 1.1 Pointing Mode – Inhibit
 - 1.2 PLC – Reset
 - 1.3 Autotrack Continuous Retry – Inhibit

S-Band (SASA) Antennas

MCC-H If EV crew < 3.8 feet from S1 SASA [P1 SASA]

1. P1 SASA (S1 SASA) – Active
2. S1 SASA (P1 SASA) – Powered down and unavailable to FDIR

Mobile Transporter

MCC-H If EV crew < 1.5 meters from MT

1. √MT latched

MISSE 8

POIC If EV crew zenith of the plane of MISSE 8
(Includes ELC-2, ELC-3, and SSRMS)

1. MISSE-8 PASCAL solar cells – Zero voltage bias
2. ELC-2 ExPA-2 Discrete Channel 1 – Disabled
3. ELC-2 ExPA-2 28V Operational Power – Disabled

EV Crew If EV crew on ELC-2 in the vicinity of MISSE 8

4. MISSE 8 PEC – Closed
5. ORMATE-III RW – Cover Installed

SPDM

MCC-H If EV crew translating or working on SPDM

1. √SPDM in Keep Alive configuration
or
2. SPDM brakes on.

GENERIC EVA INHIBIT PAD (Cont)

USOS (2)

LOCATION DEPENDENT INHIBITS	
SARJ MCC-H	If EV crew working within 2 feet, outboard of SARJ or reqd per loads FR (Includes Outboard faces of Outboard ELCs/ESPs) <ol style="list-style-type: none"> √DLA (1) – LOCKED All motor setpoints set to zero. All motors deselected.
TRRJ MCC-H	If EV crew working within 2 feet of P1 TRRJ rotation envelope (Includes Node 3 Port Endcone and PMA 3) <ol style="list-style-type: none"> √DLA 1(2) – LOCKED √DLA 2(1) – ENGAGED
MCC-H	If EV crew working within 2 feet of S1 TRRJ rotation envelope (Includes ELC 4) <ol style="list-style-type: none"> √DLA 1(2) – LOCKED √DLA 2(1) – ENGAGED
FPMU MCC-H	If EV crew on Port truss (P1 - P6) or working within 5 feet of Floating Potential Measurement Unit <ol style="list-style-type: none"> RPCM P11A_B RPC 13 Open/Close Cmd Inhibit
SSPTS MCC-H	If EV crew working within 2 feet of SSPTS cables <ol style="list-style-type: none"> RPCM LA2A3B D RPC 1 – Open, Close Cmd Inhibit RPCM Z14B A RPC 2 – Open, Close Cmd Inhibit RPCM Z13B A RPC 2 – Open, Close Cmd Inhibit
CBM MCC-H	If EV crew working within circumference of CBM <ol style="list-style-type: none"> Verify CBM deactivated. Petals Closed unless performing CBM component R&R.
Bluetooth Stethoscope IV	If EV crew translating on JEM <ol style="list-style-type: none"> Electronic Stethoscope – OFF JEM Medical Laptop – Bluetooth Disabled

ALL EVAs

ICS-EF Antenna SSIPC	<ol style="list-style-type: none"> ICS MOD – OFF ICS UPC – OFF ICS HPA – OFF HPA ON and UPC ON commands are cleared (not present) in the ICS stored command queue.
HTV SSIPC	When HTV docked to ISS, refer to <u>6.100.210 HTV INHIBIT PAD</u> (SODF: EVA TASK: CONTINGENCY TASKS).

GENERIC EVA INHIBIT PAD (Cont)

JEM (1)

LOCATION DEPENDENT INHIBITS	
JPM Windows	
IV	If EV crew translating on JPM port end cone, close window shutters.
JEMRMS	
SSIPC	If EV crew working within 5 feet of JEMRMS <ol style="list-style-type: none"> 1. RIP MA Brake – ON 2. MDP Main Mode – Stby Mode or <ol style="list-style-type: none"> 1. JEMRMS Rack – OFF
JEMRMS EE, WVE and EVE	
SSIPC	If EV crew working in vicinity of EE opening <ol style="list-style-type: none"> 1. EE Enable 1 – Off 2. EE Enable 2 – Off
SSIPC	If EV crew working within 2 ft of WVE <ol style="list-style-type: none"> 1. VCU_b TVC WVE Sig Stat – No Signal 2. PDB RMS Ext4 Vout: 0.0 V 3. VLU EE Pwr – Off
SSIPC	If EV crew working within 2 ft of EVE <ol style="list-style-type: none"> 1. VCU_b TVC EVE Sig Stat – No Signal
JPM PROX Antenna	
SSIPC	If EV crew working within 0.3 feet JPM PROX Antenna <ol style="list-style-type: none"> 1. TRX Power – OFF 2. TX Power – OFF or <ol style="list-style-type: none"> 1. JPM PROX Antennas – OFF
JPM JTVE	
SSIPC	If EV crew working within 2 feet of Fwd JPM JTVE <ol style="list-style-type: none"> 1. PDB WS RPC 8 – Open (for CPB a)
SSIPC	If EV crew working within 2 feet of Aft JPM JTVE <ol style="list-style-type: none"> 1. PDB b2 RPC 4 – Open (for CPB b)
JEF VE	
SSIPC	If EV crew working within 2 feet of Fwd JEF VE <ol style="list-style-type: none"> 1. JEF PDB b RPC 22 – Open (for DCU/TVC/PTU Fwd)
SSIPC	If EV crew working within 2 feet of Aft JEF VE <ol style="list-style-type: none"> 1. JEF PDB a RPC 5 – Open (for DCU/TVC/PTU Aft)

SEDA-AP Mast and PLAM-S

SSIPC

If EV crew working within the SEDA-AP mast extension envelope

1. Mast Actuator – Off
2. PLAM-S – Off

GENERIC EVA INHIBIT PAD (Cont)

JEM (2)

LOCATION DEPENDENT INHIBITS	
EFU SSIPC	If EV crew working within 2 feet of EFU <ol style="list-style-type: none"> 1. JEF PDB a RPC 03 – Open (for EDU a) 2. JEF PDB b RPC 20 – Open (for EDU b) 3. EFU[X] Sel Status – not selected [X=1 to 12] 4. EEU Mode – EFU stop
SSE SLM SSIPC	If SFA is not on SSE and EV crew working in the vicinity of the SSE SLM <ol style="list-style-type: none"> 1. SSE SLM Ops Ena/Inh Status 1 – Inhibit 2. SSE SLM Ops Ena/Inh Status 2 – Inhibit
SMILES SSIPC	If EV crew working in the vicinity of open end of SMILES <ol style="list-style-type: none"> 1. Antenna Main Reflector – Stop between 0 deg and -40 deg 2. ADE – Off 3. JEF PDB a RPC 15 – Open (for EFU3)
HREP POIC SSIPC	If EV crew working in the vicinity of open end of HREP <ol style="list-style-type: none"> 1. RAIDS scanhead – Closed (0 deg rot) and unpowered 2. JEF PDB b RPC 31 – Open (for EFU6)
ICS-EF SSIPC	If EV crew working within the ICS-EF antenna dynamic envelope <ol style="list-style-type: none"> 1. ICS DM/DLM Pwr Status – Off 2. ICS DM Ena/Dis – Disable 3. ICS DM Step Sig – Stopped 4. ICS APM Pwr Status – Off 5. ICS APM X Ena Valid – Inhibit 6. ICS APM Y Ena Valid – Inhibit 7. ICS APM X Step Sig – Stopped 8. ICS APM Y Step Sig – Stopped

COL (1)

ALL EVAs	
HAM Radio IV	1. HAM Radio – Deactivate

RSOS (1)

ALL EVAs	
SM Antennas IV	1. ARISS (Ham Radio) – Deactivate
MCC-M	2. GTS – Deactivate
	3. Napor (PCПИ) – Deactivate

EVAS ON PMA 1 OR RSOS (LOCATION DEPENDENT)

Soyuz Thrusters MCC-M	1. Inhibited
RSOS and RSOS Visiting Vehicle Antennas (Includes FGB, SM, DC-1, MRM-1, MRM-2, Soyuz, Progress, and ATV)	
MCC-M	1. √KURS P (КУРС P) – Deactivated
	2. √KURS A (КУРС A) – Deactivated

GENERIC EVA INHIBIT PAD (Cont)

RSOS (2)

ADDITIONAL ANTENNA INHIBITS FOR EVAS ON RSOS (LOCATION DEPENDENT)

FGB Antennas

- MCC-M**
1. √TORU (ТОРУ) – Deactivated
 2. √TV System (ТВС) – Deactivated
 3. Radiotelemetry (БР-9ЦУ-8) – Deactivate
 4. √TV System (КЛ-108А) – Deactivated
 5. √СNPMS (СИТНП) – Deactivated
 6. √КОМРАРУS (КИС) – Deactivated

SM Antennas

- MCC-M**
1. VHF-1, VHF-2 (СТТС) – Deactivate
 2. BITS (БИТС2-12) – Deactivate
 3. √TV System (ТВС) – Deactivated
 4. REGUL (РЕГУЛ) – Deactivate
 5. √LIRA (ОА) – Deactivated
 6. √Orbit Radio Tracking System (PKO) – Deactivated
- IV
7. ARISS VHF (Ham Radio) – Deactivate

Soyuz Antennas

- MCC-M**
1. √Teleoperator – Deactivated
 2. √Telemetry – Deactivated
 3. √TV – Deactivated
 4. √Tracking – Deactivated
 5. √Command (OMNI) – Deactivated

Progress Antennas

- MCC-M**
1. √Teleoperator – Deactivated
 2. √Telemetry – Deactivated
 3. √TV – Deactivated
 4. √Tracking – Deactivated
 5. √Command (OMNI) – Deactivated

ADDITIONAL THRUSTER INHIBITS FOR EVAS ON RSOS (LOCATION DEPENDENT)

SM Thrusters

- MCC-M**
1. Inhibited

Progress Thrusters

- MCC-M**
1. Inhibited

ATV INHIBITS for EVAS ON RSOS (LOCATION DEPENDENT)

ATV Antennas

ATV-CC

1. √TDRS/ARTEMIS – Deactivated
2. √PROXimity Link – Deactivated
3. √KURS A: KMTA 1&2 – Deactivated
4. √TV – Deactivated

ATV Thrusters

ATV-CC

1. √ATV Attitude Control Thruster Valves (56) – Closed
2. √Progress Main Engine Thruster Valves (8) – Closed

ATV Other Equipment (Lasers)

ATV-CC

1. √Telegoniometer – Deactivated
2. √Videometer – Deactivated

GENERIC NOTES, CAUTIONS, & WARNINGS

NOTES

1. Bolt install: report torque and turns
2. Bolt release: report torque and turns if different from published range
3. EVA connectors: after disconnection and prior to connection; verify pin and EMI band integrity; verify connector free of FOD
4. Inspect QDs for damage prior to mating
5. Toolbox doors must be closed with one latch per door when EV crew not in immediate vicinity
6. 85 ft safety tether retract force may affect body positioning
7. CETA Cart brake handle wire ties must be replaced after crew loading
8. For HTV N/C/W, refer to 6.100.180 HTV NOTES, CAUTIONS, & WARNINGS (SODF: EVA TASK: CONTINGENCY TASKS)

CAUTION

ISS Generic Constraints

- A. Avoid inadvertent contact with
 1. Grapple fixture shafts (drylube)
 2. PIP Pins
 3. Passive UMAs
 4. MBS/SSRMS/SPDM taped radiative surfaces: VDU, ACU, JEU, LEU, MCU, CRPCMs, and Cameras
 5. SPDM SJEU, EP, OTCM, LEU, and LEE VDU radiator surfaces
 6. OTSD
- B. Electrical cables
 1. Avoid bend radii < 10 times cable diameter
- C. Fiber optic cables
 1. Avoid bend radii < 10 times cable diameter
 2. Avoid pulling on cable during mate/demate
- D. Fluid line flex hoses and QDs
 1. Avoid bend radii < 14 in for hoses with a diameter ≥ 1 in
 2. Additional care should be taken to not exceed bend radii when applying loads at the flexible hose to rigid tube stub interfaces
 3. Ensure fluid QD booties are fully closed prior to leaving worksite; wire tie if required
 4. Avoid bend radii < 5 in for hoses with diameter < 1 in on LAB, S0, S1, P1, and 10 in for hoses with diameter < 1 in on all other elements

CAUTION

ISS Generic Constraints (Cont)

- E. For structural reasons
 1. Avoid vigorous body motions, quick grabs and kickoffs against tether restraints
 2. Avoid performing shaking motions (sinusoidal functions) more than four cycles
- F. Other
 1. ITT Cannon connector: on demated connectors, do not rotate collar or manipulate cable/connector using collar or connector tool
 2. MLI handholds are not rated for crewmember translation loads

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

CAUTION

ISS Truss Constraints

- A. Avoid inadvertent contact with
1. CETA lights (Z-93 paint) [LAB,S1,S3, P3 Node 1]
 2. Deployed TUS cable [Zenith and Nadir CETA rails]
 3. S0 aft face radiator
 4. GPS antennas (S13 paint) [S0,JLP]
 5. UHF antennas [LAB,P1]
 6. ETCS radiator flexhoses and panels [S1,P1]
 7. EETCS/PV radiator flexhoses, bellows and panels [P6,P4,S4,S6]
 8. SASA RF group [S1,P1]
 9. Heat pipe radiators [Z1]
 10. PCU cathode and HCA ports [Z1]
 11. Ku-Band antenna (SGANT) dish [Z1]
 12. CMG cover/shells [Z1]
 13. FPMU [P1]
 14. SASA high and low gain antennas and radiator surfaces [Z1]
 15. Deployed MISSEs
 16. OTP on HAB Tray [S0]
 17. OBSS composite sections, striker bars, grapple fixture shafts, and cable harnesses
- B. For structural reasons
1. Avoid kicking S1/P1 radiator beam.
If any of these occur, wait 2 to 5 min to allow structural response to dissipate

CAUTION

ISS Truss Constraints (Cont)

- C. Other
1. WIS Antennas: do not use as handholds [Node 1,LAB,P6,Z1]
 2. Lubricant from Ku-Band SGANT gimbals [Z1], CMGs [Z1], and RTAS ground strap fasteners [P6,P4,S4,S6] can contaminate EMU
 3. Prevent inadvertent contact of the tether shuttle with ETRS when the S3/P3 tether shuttle stop is raised away from the rail

CAUTION

ISS U.S. Pressurized Elements Constraints

- A. Avoid inadvertent contact with
1. EVA crane [PMA1]
 2. TCS reflectors [PMA2,PMA3]
 3. APAS hardware [PMA2,PMA3]
 4. CETA lights (Z-93 paint) [LAB,S1,S3, P3,Node 1]
 5. UHF antennas [LAB,P1]
 6. Open CBM petal covers, LAB and Cupola window shutters
 7. S0/Node 2 fluid tray hardlines at Node 2 end, which are limited to 25 lb
- B. Other
1. WIS antennas: do not use as handholds [Node 1,LAB,P6,Z1]
 2. CBM petal covers may not be used as handholds unless both launch restraint pins are engaged

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

CAUTION

ISS I.P. Elements Constraints

COL

- A. Avoid inadvertent contact with
1. COL ARISS and AIS antennas [COL-Nadir]

JEM

- A. Avoid inadvertent contact with
1. GPS antennas (S13 paint) [S0,JLP]
 2. Open JPM window shutter
 3. JTVE, WVE/EVE, JEF VE cameras
 4. JEMRMS taped radiative surfaces [JEU,EE,Cameras]
 5. JEM A/L target and pins
 6. JEF ORUs and EFUs (paint and lubricant)
 7. MAXI front and top panel (paint)
 8. SEDA-AP sensors (HIT,SDOM, and AOM)
 9. Trunnions and UCMs (paint and lubricant) [JEF Payloads]
 10. RAIDS covers on end of HREP
 11. ICS-EF Ka-Band antenna dish
 12. Small Fine Arm (SFA) (paint, coating and lubricant)

B. For structural reasons

1. Avoid kicking MMOD shields between JLP and JPM
2. Avoid tool impact on ICS-EF sensor

CAUTION

Shuttle Constraints

- A. Avoid inadvertent contact with
1. OBSS and SRMS composite sections joint torque arms, grapple fixture shafts, and cable harnesses
 2. LCS (silver Teflon) and LDRI (silver Teflon) and ITVC (gold foil) [OBSS]
 3. WVS antenna [ODS truss and PLB sill]
 4. Payload bay and camera wire harnesses, cables, cable guides, and connectors
 5. OBSS striker bars (drylube)
- B. No touch
1. LDRI diffuser [OBSS]
 2. OBSS saddle contacts (when OBSS unberthed) [OBSS]
 3. Monkey fur [PLB]
 4. Cameras: metallic surfaces [PLB]
 5. Ku-Band antenna black dish and gold thermal blankets [PLB]

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

WARNING

ISS Generic Constraints

- A. Avoid inadvertent contact with
 - 1. Grapple fixture targets and target pins
- B. Pinch
 - 1. NZGL connector linkage. Use caution when mating/locking
 - 2. ITT Cannon connector rotating housing
 - 3. PDGF connector doors
- C. QDs
 - 1. If QD is in FID when valve is opened (bail fwd), QD will leak and fluid line may whip
 - 2. Do not rotate if in mated/valve open configuration
 - 3. Bail may kick back suddenly when detent button is depressed if pressure has built up in spring cavity
- D. Sharp Edges
 - 1. Inner edges of WIF sockets
 - 2. APFR active WIF probes
 - 3. Mating surfaces of EVA connectors
Avoid side loads during connector mating
 - 4. Back side of MMOD shield fasteners
 - 5. Spring loaded captive EVA fasteners (e.g., 6B-boxes, BMRRM, RTAS, SARJ Covers); the end of the spring may protrude
 - 6. SPDM OTCM gripper jaws
 - 7. Keep hands away from SSRMS LEE/POA/SPDM LEE opening, snares, and PDGF curvic coupling (teeth)
 - 8. MMOD strikes on ISS exterior

WARNING

ISS Generic Constraints (Cont)

- E. Thermal
 - 1. EVA connectors with booties may become hot if left uncovered. Handling may need to be limited
 - 2. Turn off glove heaters when comfortable temperature reached to prevent bladder damage. Do not pull fingers out of gloves when heaters are on
 - 3. Uncovered trunnion pins may be hot
 - 4. SSRMS/MBS/SPDM operating cameras and lights may radiate large amounts of heat
 - 5. Do not touch EMU protective visor if temperature has been < -134 degF for > 15 min
 - 6. No EMU boot contact with foot restraint when temperature < -120 degF or > 200 degF
 - 7. PDGF surfaces may not meet touch temperature requirements for unlimited contact when $\beta \leq -70$ or $\beta \geq 70$

WARNING

ISS Truss Constraints

- A. Avoid inadvertent contact
 - 1. SSU, ECU, beta gimbal platform, mast canister, SAW blanket boxes unless the beta gimbal is locked and the motor is turned off
 - 2. Stay inboard of SARJ when active
 - 3. Stay 2 ft from S1/P1 radiator beam rotational envelope when beam is free to rotate
 - 4. Stay 5 ft from moving MT on face 1
 - 5. Stay 3.3 ft from Ku-Band (SGANT Antenna) when powered
 - 6. Stay 1 ft from top of STP-H3 (ELC-3)
 - 7. Deployed MISSEs and ORMatE-III R/W (ELC-2)
 - 8. RRM (ELC-4)
- B. RF radiation exposure
 - 1. Stay 3.8 ft from S-Band (SASA) high gain Antenna when powered [S1,P1]
 - 2. Stay 1.3 ft from S-Band (SASA) low gain Antenna when powered [S1,P1]
 - 3. Stay 1 ft from UHF Antenna when powered [LAB,P1]
- C. Sharp Edges
 - 1. Solar array blanket box [P6,S6]
 - 2. Fastener threads on back of Z1 U-jumper male FQD panel, if nutplate cap missing
 - 3. Outboard MT rail attachment lug near P6 handrail 5333 and gap spanner
 - 4. P2 connector on EWIS box TAA-06 [Zenith/Forward Corner 1 of P5-SARJ at 0 deg]

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

WARNING

ISS Truss Constraints (Cont)

C. Sharp Edges (cont)

5. Nickel coated braided copper ground straps may contain frayed wires [P6,P4,S4,S6]
6. MMOD strikes on Z1 toolboxes
7. MMOD strike on POA FSE (on CSA Logo below MBS Mast Camera)
8. AMS Star Trackers Baffles (2)

D. Electrical Shock

1. Stay ≥ 2 ft from ungrounded floating connectors if powered
S0 EVA power cables (inside S0 Bay 00 Face 4, Bay 01 Face 3)
ESP2 jumper (inside S0 Bay 03 Face 4)

E. Thermal

1. ELC may exceed touch temperatures when $\beta > 75$ deg

WARNING

ISS U.S. Pressurized Elements Constraints

A. Handrails

1. Handrails previously used for MISSE attachment may not be used as a safety tether point [A/L endcone 564 and 566, A/L Tank 2 Nad/Fwd and Port/Fwd, P6 5389]

B. Pinch

1. EV side of IV Hatch during Hatch operation (also snag hazard) [A/L]
2. LAB and Cupola window shutters and CBM petal cover linkages during operation

C. RF radiation exposure

1. Stay 1 ft from UHF antenna when powered [LAB,P1]

D. Sharp Edges

1. PMA umbilical launch restraints - exposed bolt threads
2. Adjustable fuse tether (Fish Stringer) buckles stowed in Node bag
3. Port/Aft portion of A/L circular HR [HR 0506]
4. A/L HR 0537 (Eq Lock Zenith)
5. ESP-2 HR 8012
6. PMM ROEU and ROFU panels (Zenith endcone)

E. Thermal

1. PMA handrails may be hot. Handling may need to be limited
2. Stay ≥ 1 ft away from PMAs and MMOD shields > 270 degF if EMU sun visor up; limit time to 15 min or less if > 300 degF

WARNING

ISS U.S. Pressurized Elements Constraints (Cont)

E. Thermal (Cont)

3. Stay at least 0.5 ft away from PMA and MMOD shields > 325 degF
4. No EMU TMG contact with PMAs and MMOD shields > 320 degF

F. Electrical Shock

1. Stay ≥ 2 ft from ungrounded floating connectors if powered
SSPTS connectors include NOD1 Stbd/Fwd HR 0130, LAB Stbd/Fwd HR 0273, PMA2 Stbd

G. Fluid QDs

1. Do not translate on gap spanners restraining NODE 3 - LAB NH3 jumpers

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

WARNING

ISS I.P. Elements Constraints

COL

- A. Avoid inadvertent contact with
1. SOLAR [COL EPF]

B. Thermal

1. Columbus end cones may violate touch temperature constraints when $-75 \leq \beta \leq -60$ or $60 \leq \beta \leq 75$

JEM

- A. Avoid inadvertent contact with
1. ICS-EF sensors

B. Pinch

1. JPM window shutter linkages during operation
2. JEM cameras (JVTEs, EVE, WVE, and JEF VEs)
3. JEM EFU latching arms
4. JEF SSE latch
5. ICS-EF antenna boom
6. SEDA-AP mast
7. SMILES antenna rotating area
8. HREP hinge sides and RAIDS pinch areas
9. JEMRMS EE
10. JEMRMS Small Fine Arm (SFA) joints and booms

WARNING

ISS I.P. Elements Constraints (Cont)

JEM (Cont)

C. Sharp Edges

1. Interior of JEMRMS HRMs
2. JEMRMS EE opening and snares
3. JEM A/L hatch corners
4. ICS-EF AHM gears
5. MAXI visual star camera
6. SMILES baffles (two), baffle base bare bolts, and Cold Sky Terminator (CST)
7. HREP baffles (four) [Star tracker aperture Zenith and three instrument baffles Aft]
8. SFA's Electro-Mechanical GF(EMGF)

D. RF radiation exposure

1. Stay 0.3 ft from Fwd/Aft JPM PROX antenna

E. Thermal

1. JPM Port End Cones and JLP Port Nadir may violate touch temperature constraints when $\beta > 60$ deg
2. JEMRMS/JTVE/JEFVE operating cameras and lights may radiate large amounts of heat

WARNING

Shuttle Constraints

A. Arcing/Molten Debris

1. Stay ≥ 2 ft from exposed EFGF connector when OBSS berthed, powered, and EFGF not grappled [PLB]
2. Stay ≥ 2 ft from exposed Stbd Fwd MPM contacts [PLB]
3. Stay above PLB sill when within 1 ft of powered ROEU connector [PLB]

B. Pinch

1. PRLA operation [PLB]

C. RF radiation exposure

1. Stay 3.28 ft from S-Band Antenna when powered
2. Stay 1 ft from top and side of UHF PLB Antenna radome surface when in high powered mode [ODS truss]
3. Stay 0.33 ft from top and side of UHF PLB Antenna radome surface when in low powered mode [ODS truss]
4. Remain below the level of the PLB door mold line for first 20 in Aft of Fwd bulkhead when S-Band Antenna powered [PLB]
5. Remain on the inboard side of the Stbd slidewire (sill handrails if slidewire not installed) for first 20 ft Aft of Fwd bulkhead when Ku-Band Antenna powered [PLB]

GENERIC NOTES, CAUTIONS, & WARNINGS (Cont)

WARNING

Shuttle Constraints (Cont)

D. Sharp Edges

1. PRLA grounding wipers [PLB]
2. LDRI baffles (also an entrapment hazard) [OBSS]
3. Keep hands away from SRMS EE opening and snares
4. TCS connector backshells have exposed threads [ODS]

E. Thermal

1. Illuminated PLB lights; do not touch
2. OBSS grapple fixture shafts/cams may be hot. Limit handling if required
3. Stay 27 ft from PRCS when powered
4. Stay 3 ft from VRCS when powered
5. Stay 3 ft from APU when operating


F. Contamination

1. Stay out of the immediate vicinity of leaking jet or APU


G. Lasers

1. Do not look at LDRI diffuser or LCS laser aperture window

MISSE 8 ORMATE III R/W TIE-DOWN





CP7 ETVCG TIE-DOWN



Tether 1 is actually 2 adjustable equipment tethers (small/small hooks) hooked end-to-end. Total length is approx 42". It goes from the tether loop on the stanchion - up and around the camera base (green part) and back down to the D-ring on the first tether. The two tethers will hook together approx around the camera base. The buckles are not a concern


Tether 2 is an adjustable equipment tether (small/small hooks). Total length is approx 21". It goes from the tether loop on the stanchion to the tether loop on the MCF Round Scoop handle. The buckles are not a concern

SSRMS BASE B BOOM CLPA TIE-DOWN



CP13 ETVCG LIGHT TIE-DOWN

Requires two LDTD tethers
hook to hook due to length



FLIGHT SPECIFIC EVA REFERENCE

ORBITER
PAYLOAD BAY OVERVIEW..... FS 18-3
LMC..... FS 18-9
ROEU..... FS 18-21
PRLA..... FS 18-23

EVA 1
PM..... FS 18-24
COLT..... FS 18-35
RRM..... FS 18-38
FRAM..... FS 18-45
MISSE 8 ORMATE III R/W..... FS 18-62
SPDM..... FS 18-69
SPDM EOTP..... FS 18-70


GET-AHEADS
ETVCG..... FS 18-75
ETVCG LIGHT (VLA)..... FS 18-79
SSRMS BASE B CLPA..... FS 18-81
CP13..... FS 18-85
S1 FHRC P-CLAMP RELEASE..... FS 18-86
PMA3 COVER (TBD)..... FS 18-87
LAB GAP SPANNER..... FS 18-88

GENERIC ISS
CETA CART OVERVIEW..... FS 18-89


FLIGHT SPECIFIC
EVA REFERENCE

This Page Intentionally Blank

PAYLOAD BAY OVERVIEW




ATTACH LOCATIONS




ORBITER

PAYLOAD BAY OVERVIEW (Cont)


CARGO ARRANGEMENT STS-135 OV-104, FLIGHT 33



PAYLOAD BAY OVERVIEW (Cont)




PLAN VIEW
PAYLOAD BAY DOORS AND DRIVE MECHANISMS REMOVED FOR CLARITY




SIDE VIEW
PORT SIDE OF ORBITER MIDBODY REMOVED FOR CLARITY
STBD PAYLOAD BAY DOOR SHOWN IN CLOSED POSITION

PAYLOAD BAY OVERVIEW (Cont)




PAYLOAD BAY OVERVIEW (Cont)




SECTION H-H [20A]
 LOOKING AFT AT MPLM
 FROM Xo 919.00 TO Xo 1235.86

SECTION L-L [B3F]
 ROTATED 11.61° CW
 SHOWING CLEARANCE TO MANIPULATOR POSITIONING MECHANISM (MPM)


PAYLOAD BAY OVERVIEW (Cont)





LMC





LMC (Cont)





LMC (Cont)



LMC (Cont)




LMC (Cont)




ORIENTATION VIEW
LANDING CONFIGURATION


LMC (Cont)




VIEW LOOKING AFT
LANDING CONFIGURATION



LMC (Cont)




VIEW LOOKING DOWN
LANDING CONFIGURATION




LANDING CONFIGURATION VIEW LOOKING DOWN
SELECT ORBITER HARDWARE OMITTED FOR CLARITY

LMC (Cont)




VIEW LOOKING INBOARD
LANDING CONFIGURATION



LANDING CONFIGURATION VIEW LOOKING INBOARD
SELECT ORBITER HARDWARE OMITTED FOR CLARITY

LMC (Cont)




Y-link
Attaches with two bolts,
2 nuts, 4 washers

Aft passive latch


Power cable bond wire

↑
FWD
STBD side

LMC (Cont)



**Passive latch w/torque multiplier
and reaction adapter tool**




Y-lug

Bay 13 STBD
LMC aft passive latch


← FWD

LMC (Cont)



VIEW K-K
SECTION VIEW OF Y-LUG
AND Y-LINK ASSEMBLY


Y-link Assembly



Cable Mates




Orbiter side



Payload Side


ROEU




FS 18-21

EVA/135/FIN

ROEU (Cont)




In-board end of shaft has yellow marks.
Not aligned indicates motor disengaged



LWLL/MWLL/SMWLL

LIGHTWEIGHT LONGERON LATCH/
MIDDLEWEIGHT LONGERON LATCH/
SUPER MIDDLEWEIGHT LONGERON LATCH




MMWL


MODIFIED MIDDLEWEIGHT LATCH

EVA RELEASABLE PAYLOAD RETENTION LATCHES


Pump Module – Integrated Assembly (683-96501)



LAPA (683-96504)




PM-IA on LMC




NOTE: Cable trays, aft winch, and WVS antenna not present on STS-135

Dimensions from PM-IA to PLB Hardware




NOTE: Cable trays, aft winch, and WVS antenna not present on STS-135


Dimensions from Pins





Section Through Contingency Pin



Distance from Contingency Pin and Bottom of Handrail




PFRAM Centered on Modified ATA LMC Adapter Plate




PFRAM Fitting centered in ATA Adapter Plate machined pocket
Alignment Guide overhangs Adapter Plate

PFRAM Centered on Modified ATA LMC Adapter Plate




Modified ATA LMC Adapter Plate - Iso View



Modified ATA LMC Adapter Plate - Exploded View


PFRAM Centered on Modified ATA LMC Adapter Plate – Bulkhead Envelope




NOTE: Cable trays, aft winch, and WVS antenna not present on STS-135

PM (Cont)

PFRAM Centered on Modified ATA LMC Adapter Plate – Bulkhead Envelope




COLT




**COLT Assembly, Pin 3
P/N SEG33122635-301
(LONG)**


**COLT Assembly, Pin 4
P/N SEG33122635-302
(SHORT)**

COLT (Cont)



COLT (Cont)





A. COOLANT VALVE TASK

- A. Coolant Valve Panel
 - A. Cut wire on T-valve & Ambient Cap
 - B. Remove T-valve & stow; remove ambient cap & stow, manipulate ambient plug

B. REFUELING TASK (practice and demo)

- A. Fill/Drain valves
 - A. Cut wires – 3 places (FDV2, FDV4, PV1)
 - B. Remove tertiary & safety caps, stow
 - C. Open PV1 actuation nut, transfer ethanol, vent ethanol

C. MLI MANIPULATION TASK

- A. 3 MLI Flaps: MLI-1, MLI-2, TPP
- B. Cut Kapton tape, peel MLI, hold flaps open with magnets

D. #10 TORQUE SET TASK

- A. Disengage #10 captive fasteners – 2 (no cage)
- B. Disengage #10 non-captive fasteners – 4 (with cage)


E. VISION TASK BOARDS

- A. Vision Processing
 - Marmon clamp, HST door latch and J-hook, bolt hole, #10 TS, SMA


F. SMA CAP REMOVAL TASK

- A. SMA caps; remove 4 of 9, stow


RRM (Cont)




RRM (Cont)





RRM (Cont)



RRM (Cont)




RRM (Cont)




RRM (Cont)




FRAM



FRAM (Cont)




BOTTOM VIEW OF ACTIVE FRAM – W/O COVER




FRAM (Cont)


To avoid interference with the electrical connector flapper door, the AFRAM can be angled forward (shown at 7 deg)




Even if the AFRAM is biased aft, the rough alignment guide will guide the AFRAM back forward enough so that the PFRAM door will properly contact the stiffener on the AFRAM. At this point, the FRAM can be rocked back into a parallel position relative to the PFRAM for successful installation



FRAM Mechanism Turn Count Table



FRAM (Cont)



FS 18-50

EVA/135/FIN


FRAM (Cont)




FS 18-51

EVA/135/FIN


FRAM (Cont)




FRAM (Cont)



FRAM (Cont)





FRAM (Cont)




FS 18-55

EVA/135/FIN

FRAM (Cont)




FRAM (Cont)




FS 18-57

EVA/135/FIN

FRAM (Cont)



FRAM (Cont)



FRAM (Cont)



FRAM (Cont)



MISSE 8 ORMATE III R/W



MISSE 8 ORMATE III R/W (Cont)




FS 18-63

EVA/135/FIN

MISSE 8 ORMATE III R/W (Cont)




MISSE 8 ORMATE III R/W (Cont)



ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	FT-TA-8210-01	ORMate-III R/W Tray Assembly	1
2	FT-TA-8220-01	ORMate-III R/W Cover Assembly	1
3	419991-1	MISSE PEC Inner Bag	4


MISSE 8 ORMATE III R/W (Cont)




MISSE 8 ORMATE III R/W (Cont)




ELC-2 MISSE ExPA



MISSE 8 ORMATE III R/W (Cont)



SPDM



SPDM EOTP

EOTP to SPDM
Power Connector


EOTP Fuse
Connectors

BJU Input
Drive


SPDM outrigger

BJU Main Body


EOTP stand-off leg and
retention tether (used
for SPDM service
position)



SPDM EOTP (Cont)




SPDM EOTP (Cont)




SPDM EOTP (Cont)



SPDM EOTP (Cont)



ETVCG



FS 18-75


EVA/135/FIN

GET-AHEADS


ETVCG (Cont)



ETVCG (Cont)



ETVCG (Cont)



ETVCG LIGHT (VLA)



ETVCG LIGHT (VLA) (Cont)




SSRMS BASE B CLPA




S108E5107 2001:12:07 19:43:30



SSRMS BASE B CLPA (Cont)



SSRMS BASE B CLPA (Cont)




SSRMS BASE B CLPA (Cont)



Uninstalled



Installed (only white tip visible)



CP13




FS 18-85


EVA/135/FIN

S1 FHRC P-CLAMP RELEASE

FHRC P-clamps – Hose Box (Outboard)




FHRC P-clamps – Stinger (Inboard)




PMA3 COVER (TBD)


LAB GAP SPANNER




CETA CART OVERVIEW




CETA CART OVERVIEW (Cont)



CETA CART OVERVIEW (Cont)




Wire ties required for launch only. Removed for coupler R+R




BOTTOM VIEW

Compliance in indicated direction to allow for misalignment. Centering spring nominally constrains motion




TOP VIEW










PASSIVE COUPLER

Contingency bolt removed if latch failed closed




SIDE VIEW

CETA CART OVERVIEW (Cont)



CETA CART OVERVIEW (Cont)




Zenith Port brake handle



Nadir Port brake handle

CETA CART OVERVIEW (Cont)





EVA CHECKLIST

STS
135