

SPACE SHUTTLE PROGRAM Flight Software Office NASA Johnson Space Center, Houston, Texas



Flight Software Office (FSO) STS-126 In-Flight Anomaly Review

SR 4363

David Rutishauser/MS4 SICB Dec. 9, 2008 PRCB Dec. 11, 2008





Presenter D. RUTISHAUSER
Date 12/9/2008 Page 2

Tracking #	Description
STS-126-I-001	SM GPC Failure to Send GCIL Commands
(MER-08, AR 3595, AR 3596, CHIT 006660)	





FSO STS-126 IFA Review Discussion

D. RUTISHAUSER

Date

- STS-126-I-001, SM GPC Failure to Send GCIL Commands :
 - On FD1, the MPLM environment checks could not be completed, because the PSP could not be configured properly. The system management software command to configure the PSP failed, but a ground-initiated command worked correctly.
 - Failure of automatic handover of antenna management to Ku-Band from S-band, and vice-versa
 - Cause isolated to an inadvertent data shift affecting PSP port moding and Ku automatic handover commanding only (pre-OI-33 capabilities), introduced by an unrelated change in OI-33
 - OI-33 SCR 93122 "PSP Reject Indicator Fix to DR 122444" inserted data item into COMPOOL shared by affected commanding data
 - Inserted data caused shift in subsequent data that rendered three downstream commands inaccessible by the I/O processor (IOP)
 - Issues were addressed during the mission via ops workarounds
 - Ku-auto handover: Reverted to INCO procedures used before capability added in OI-27 (1997)
 - PSP port moding: Accomplished with ground commanding (MPLM checks completed)
 - FSW team mission support included
 - Verification and isolation of cause of command failure through analysis and SPF testing
 - Complete audit of OI-33 COMPOOL changes; Verified no other erroneous data shifts present



- IFA Status and forward plan:
 - Corrective action:
 - FSW DR126366 dispositioned by SASCB 12/4/08
 - Authorizes patch to STS-119 and STS-127 OI-33 systems
 - Patch is small, not complex, only impacts the affected functions, and is fully testable
 - Patch scheduled for release 12/15/08, SAIL testing complete 1/9/08
 - Source mod to OI-34 systems
 - Will audit all OI-34 COMPOOL changes for proper data alignment
 - Preventative action:
 - Team engaged in full root cause analysis
 - Examining all levels of inspection/review/verification
 - Verification procedures/philosophies/scope
 - Facility capabilities/limitations
 - Missed opportunities to have exposed problem
 - NESC Software Fellow engaged in reviews



 All analysis results and preventative action plan scheduled to be reported to SICB/PRCB January 13/15th, per MMT action 126-MMT-001

• Hazard Report Impacts

- IFA currently tracked as integrated due to potential impacts to IFSW-01 "FLIGHT SOFTWARE PROBLEMS CAN CAUSE LOSS OF VEHICLE COMMAND AND CONTROL"
- Impacts under investigation pending completion of root cause analysis









Presenter D. RUTISHAUSER Date 12/9/2008 Page 6

Backup



Date


- Key findings to date: ٠
 - Condition (maintenance trap) was introduced in OI-20 (June 1989)
 - Existing programming standards/methods to force output data alignment not used
 - Warnings to maintain alignment placed in code via comments
 - Subsequent changes to COMPOOL increased size to point that comments were well removed from location OI-33 data was inserted
 - Since the OI-33 changes functioned correctly, regression (system health) tests of nonrelated functions most likely verification step where problem could have been uncovered
 - Limitations exist in verification and training facilities for exercising the affected functions
 - No GCIL or PSP models in SPF, but output data stream can be logged and inspected
 - No SPF models to compute Ku-band signal strength for exercising handover function in a closed loop test, but functionality can be exercised with manual intervention
 - SMS uses simplified model of GCIL hardware interface which did not expose handover problem





Date 12/9/2008 Page 8


- Key findings to date, cont:
 - Opportunities still existed to uncover the error in verification:
 - SAIL uses GCIL and PSP hardware for verification
 - Ku auto-handover test performed, but was successful due to test sequence and the initial state of the hardware
 - Handover exercised again as the result of a configuration change in the test procedure and failed, but it was not identified or noticed because this transition was not a test requirement
 - PSP port moding still under investigation
 - PSP port moding rejected command identified in ODRC data from SMS development run, but was not a test requirement and was not identified at the time
 - KSC did not exercise PSP port moding functions during STS-126 vehicle processing
 - Not typically done for station flights



Space Shuttle Program

Flight Software Office NASA Johnson Space Center, Houston, Texas





DR NUMBER: 126366

DR TITLE: IFA STS-126-1-001, SM GPC Failure to Send GCIL Commands

FOUND BY:STS-126 ASSIGNED TO:PASS SEVERITY CODE:2N LOG DATE:11/17/08

DESCRIPTION OF PROBLEM:

The OI-33 software change for SCR 93122 "PSP Reject Indicator Fix to DR 122444" added a data parameter to an SM compool which inadvertently caused the PSP port moding and the Ku-band/S-band auto handover GCIL command data to shift to an odd memory address. The Input/Output Processor (IOP) only functions with output data that is on an even Memory address. The result of the shifted data causes the IOP to issue GCIL commands using the preceding (incorrect) halfword location. For PSP port moding, both the reset command (which should result in an ALL ZERO command state) and the set (DATA) commands are in error. For Kuband/S-band auto handover, only the reset command is in error.

HOW USER SEES EFFECTS:

The GCIL will not respond to a set command that is not preceded by a reset command. INCO controllers observed this behavior during the STS-126 mission. Workaround procedures are required to manually command Ku-band/S-band handovers (with the FSW automatic handover function inhibited). PSP automatic port mode switching will not function and separate GCIL uplink commands are required to switch between RF and umbilical PSP configurations.

REQUIREMENT (REQ VIOLATED/INADEQUACY): SS-P-0002-580, Sections 4.9.4.2 and 6.4 SS-P-0002-550, Section 4.27

DISPOSITIONS:

FLT	SYSTEM	CLOSURE	CLOSURE CODE DEFINITION	ACTIONEE
STS-126	OI33	4 A	Waiver Required	USA/PASS
STS-119	OI33	2B	Patch To Mass Memory	USA/PASS
STS-127	OI33	2B		
	OI34	2A	Source Mod Via Flight Build	USA/PASS

RATIONALE FOR DISPOSITIONS:

A waiver will retroactively apply to STS-126, the first OI-33 mission. A fix will be made via MM patch or source mod to all remaining missions until the end of the Shuttle Program. These dispositions represent no significant increase in risk.

CONTACT: S. Brooker 281-282-4501 SRE: D. Rutishauser

PERSONS CONSULTED:

D. Matthews (USA FCOD) 281-244-7535 D. Graham (NASA MOD) 281-483-4382 S. Sides (USA INCO) 281-483-4593 S. Peters (USA PASS) 281-282-3218 W. Wilkinson (USA PASS) 281-282-3120 B. Royer (USA PASS) 281-282-3473 C. Driskill (USA PASS) 281-282-4195 M. Banks (USA PASS) 281-282-3124 A. Romero (NASA GCIL) 281-483-0159 D. Johnson (NASA NSE) 281-483-5245 J. McDonald (NASA DPS) 281-483-0793 L. Wood (Boeing DPS) 281-226-4521

to detatuente 12/01/08 DATE

12/01/08

ASD CONCURRENCE

APPROVED BY:

Day

SASCB CHAIRMAN