



Flight Software Office (FSO) STS-132 In-Flight Anomaly Review SR 4780

David Rutishauser/MS4 SICB June 15, 2010 PRCB June 17, 2010

Flight Software Office NASA Johnson Space Center, Houston, Texas



STS-132 FSW Issues Overview

Presenter D. RUTISHAUSER Date Page 2 6/17/2010

Tracking #	Description	IFA?	IIFA?
STS-132-S-001, (MER-04, AR 4771)	Onboard Printer Problems	Y	N
STS-132-S-002, (MER-05, AR 4780)	STS4 PGSC Screen Cracked (RPOP1)	Y	N
STS-132-S-003	WLES_startup.bat file was missing from the STS13203 software load	Y	N

Flight Software Office

NASA Johnson Space Center, Houston, Texas



FSO STS-132 IFA Review Discussion

- STS-132-S-001, (MER-04, AR 4771), Onboard Printer Problems
 - Multiple instances of partial-page printing occurred over the course of Flight Days 2,3, and 5. Ground testing during mission failed to reproduce problem.
 - IFA? Yes
 - IIFA? No, does not impact integrated hazards or multiple elements (per NSTS 08126)
 - **Post flight activities** Post-flight testing scheduled for week of June 14th. As-flown hardware and software will include full PGSC network and printer.

Flight Software Office

NASA Johnson Space Center, Houston, Texas



FSO STS-132 IFA Review Discussion

Presenter D. RUTISHAUSER			
Date	6/17/2010	Page 4	

- STS-132-S-002, (MER-05, AR 4780) STS4 PGSC Screen Cracked (RPOP1)
 - On Flight Day 8 the crew reported that the screen on the RPOP (STS4) PGSC was cracked and the display was unusable. The PGSC network was reconfigured per the STS-132 PGSC Backup Plan.
 - IFA? Yes
 - IIFA? No, does not impact integrated hazards or multiple elements (per NSTS 08126)
 - **Post flight activities** Crew debrief occurred June 10th. Laptop power connector cover tethered to power cable floated between screen and keyboard when laptop closed. Broken laptop to be pulled from flight hardware inventory.

Flight Software Office

NASA Johnson Space Center, Houston, Texas



FSO STS-132 IFA Review Discussion

Presenter D	D. RUTISHAUSER			
Date	6/17/2010	Page 5		

STS-132-S-003, WLES_startup.bat file was missing from the STS13203 software load

- On Flight Day 1, the crew informed the ground which PGSC was being used for WLES operations. The ground operator searched for but didn't find the pop-up file in the expected location on the PGSC. The pop-up reminder file was subsequently uplinked. No WLES operations were impacted.
- After a few failures to restart the WLES application after reboot on prior missions, a pop-up reminder was added to the WLES PGSC and displays whenever the PGSC is restarted.
 - Initial procedure was to uplink pop-up batch file after the crew informs the ground which PGSC configured for WLES operations.
 - After a couple of flights, ground operators requested to make the pop-up a part of the standard preflight PGSC configuration.
 - PGSC and WLES engineers agreed to the request but subsequently failed to add it to the official PGSC and WLES configuration.
- IFA? Yes
- IIFA? No, does not impact integrated hazards or multiple elements (per NSTS 08126)
- Post flight activities The pop-up .bat file has formally been added to the WLES application delivery and PGSC load.