

MIT/IL SOFTWARE ANOMALY REPORT

SEC REPORT NO. LNY - 12
PROGRAM LUMINARY
PROGRAM REVISION 51

1.1 ORIGINATOR: D. A. Pettit	1.2 ORGANIZATION: GAEC	1.3 DATE: 10/22/68	1.4 ORIGINATOR CONTROL NO. LM-LUM-12
---------------------------------	---------------------------	-----------------------	---

1.5 DESCRIPTION OF ANOMALY:
When the V97NXX is flashing from the engine fail routine (R40), a short duration verb 06 flash appeared intermittently.

CONTINUED ON PAGE

1.6 DESCRIPTION OF RUN:

CONTINUED ON PAGE

- MIT ANALYSIS -

2.1 CAUSE:
Not an anomaly. The V06 occurs momentarily if the phasing of T4RUPT is such that a DSKY update is made before the "pasting" process is complete. This should be a program note.

CONTINUED ON PAGE

2.2 RECOGNITION:

CONTINUED ON PAGE

2.3 MISSION EFFECT:

CONTINUED ON PAGE

2.4 AVOIDANCE PROCEDURE:

CONTINUED ON PAGE

2.5 RECOVERY PROCEDURE:

CONTINUED ON PAGE

2.6 PROGRAM CORRECTION:

CONTINUED ON PAGE

2.7 RECOMMENDED DISPOSITION (Fix, Work-around, etc):

Make Program Note.

CONTINUED ON PAGE

2.8 RECOMMENDED RE-TESTING:

CONTINUED ON PAGE

2.9 MIT/IL SIGNATURE:	2.10 DATE:
-----------------------	------------

3.1 NASA DIRECTION:	4.1 CLOSING ACTION TAKEN:
---------------------	---------------------------

CONTINUED ON PAGE

CONTINUED ON PAGE

3.2 NASA MSC SIGNATURE:	3.3 ORGANIZATION	3.4 DATE:	4.2 SIGNATURE: <i>[Signature]</i>	4.3 ORGANIZATION: MIT	4.4 DATE: 12-3-68
-------------------------	------------------	-----------	--------------------------------------	--------------------------	----------------------