

SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-128 Integrated Launch Site Requirements Review

Presenter Kenneth Nowak

Date 08-14-08

Program Freeze Point

PRCB Presentation

S115128



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-128 Integrated Launch Site Requirements Review

Presenter K	enneth Nowak
Date 08-	14-08

Baseline the STS-128 Mission Specific Requirements and Flow Plans. This CR and the associated Data Package were reviewed at the 08-11-08 FRWG.

Flight Management MO3/USA-PI **Orbiter Engineering*** Requesting Approval **USA-OE Orbiter GFE** MV5 **Status in BackUp KSC Integration*** MK-SIO Flight Software **USA-FSW** XA **EVA** Payload/Cargo Engineering **USA-PI Baseline at LSFR SSME MP21**

*Backup Material





STS-128/17A

Launch Site Requirements Review (LSRR)

Flight Requirements Status

PRCB August 14, 2008

Shelby Lawson, STS-128 MIM
Frank Richmond, USA Flight Mgr.
Adam Richards/Boeing Mass Properties



SPACE SHUTTLE PROGRAM Space Shuttle Flight Operations and Integration Office NASA Johnson Space Center, Houston, Texas




STS-128 LAUNCH SITE REQUIREMENTS REVIEW

Shelby Lawson/MO3

Date 08/14/08

Page 2





SPACE SHUTTLE PROGRAM

Space Shuttle Flight Operations and Integration OfficeNASA Johnson Space Center, Houston, Texas



STS-128 LAUNCH SITE REQUIREMENTS **REVIEW**

Presenter Shelby Lawson/MO3

Date 08/14/08 Page 3

LAUNCH

07/30/09

39A/ MLP 2 (proposed)

CREW SIZE: 7UP/7DN (One crew

rotation)

ORBIT

51.6 DEG 122 NM

DIRECT INSERTION

(190 NM altitude)

DURATION: 11 + 1 + 2 DAYS (2 EVAs)

CONFIGURATION

OV-104 (31)

LP04;RP01

ET-132

BI-139

RSRM-107

(1) TBD (2) TBD (3) TBD

OI-34

SRMS, OBSS, ODS

CONSUMABLES

CRYO TANK SETS

5 (FULL) **GN2 TANKS** 5 (FULL)

FWD RCS

1912# (OFFLOAD)

4970# (FULL) **AFT RCS**

22760# (FULL) - COPV offload **OMS**

PAYLOAD

ISS-17A ISS-17A MPLM MAUI **LMC** SEITE

MISSE 6

TriDAR AR&D Sensor DTO-701A

LANDING

SITE **KSC**

TAL ZARAGOZA

ALT. TAL **MORON & ISTRES**

SCA **TBD**

- Rescue Flight for STS-127
- FDRD UPDATE REQUIRED TO IDENTIFY MLP#2



SPACE SHUTTLE PROGRAM

Space Shuttle Flight Operations and Integration Office NASA Johnson Space Center, Houston, Texas



STS-128 LAUNCH SITE REQUIREMENTS REVIEW

Presente	Shelby Lawson/MO3	
Date	08/14/08	Page 4

PERFORMANCE MARGIN

	PERFORMANCE MARG	<u>///N</u>	
•	SIMULATION MARGIN (SPLCSAPM)		+1257
•	WEIGHT CHANGES SINCE SIMULATION		
	• PAYLOAD	+2095	
	• OPERATOR	-1185	
	ORBITER	-178	
	• SSME	-141	
	• NPC	-34	
	CREW COMPARTMENT	+726	
	• OMS	-1340	
	• RCS	-4	
	MPS PROP (NOT INERT)	-93	
	• ET	<u>-163</u>	
	TOTAL WEIGHT CHANGES	-317	+317
•	OTHER PERFORMANCE PROJECTIONS		
	PROTECTION FOR DOL DISPERSIONS		-700
	 07/30/09 LAUNCH DATE (PMBT & ATMOS) 		+420
	PARTIAL PROJECT FOR MPS BGT GEN 0701S		+7
	OMS ASSIST ADJ (BASED ON 3169 USAGE)		+198
	SRB – M.P. UPDATES		-116
	 SRB – BR / 1.55 MIL HIGHER THAN 0.3705 AVG 		+310
	ISP/THST FOR GEN BLOCK 2 @ 104.5%		-225
	PROJ TO 5 MIN WINDOW FROM INPLANE		-600
	PERFORMANCE CHANGES ADJUSTMENT		<u>-22</u>
•	CURRENT BASELINED APM (08/05/08)		+846



SPACE SHUTTLE PROGRAM Space Shuttle Flight Operations and Integration Office NASA Johnson Space Center, Houston, Texas



STS-128 LAUNCH SITE REQUIREMENTS REVIEW

Present	Shelby Law	Shelby Lawson/MO3	
Date	08/14/08	Page 5	

PERFORMANCE MARGIN (CONT.)

CURRENT BASELINED APM (08/05/08)

+846

- IPT PROJECTED
 - ISS RENDEZVOUS ALT TO 190 NMILE (07/22/08 SSPCB) +600
 3 MINUTE LAUNCH WINDOW (FRD CR-003) +300
 INCREASE LMC CONTROL WT TO 4,035 LBS (66 LBM) -61
 INCREASE MPLM CONTROL WT TO 27,795 LBS (1000 LBM) -930
- PROJECTED APM +755

VOLUME III: ASCENT PERFORMANCE MANAGER'S RESERVE GUIDELINE AT FPSR/CIR IS 800 LBS



SPACE SHUTTLE PROGRAM Space Shuttle Flight Operations and Integration Office NASA Johnson Space Center, Houston, Texas



STS-128 LAUNCH SITE REQUIREMENTS REVIEW

Cheby Lawson/mos		
Date	08/14/08	Page 6

Presenter Shelby Lawson/MO3

FLIGHT MASS PROPERTIES

<u>CASE</u>	TOUCHDOWN WEIGHT pounds (LIMIT)	MACH 3.5 X C.G. inches (LIMIT)
NOMINAL	225625 (233000)	TBD (1075.7)
RTLS	240909 (245000)	TBD (1077.2)
TAL	238837 (244000)	TBD (1077.2)
AOA	232623 (242000)	TBD (1075.7)
CONT RTRN	201849 (233000)	TBD (1075.7)

⁻ CONT RTRN CASE IS NO MPLM, LMC empty, Full middeck, Fwd CG case

NOTE: RTLS INCLUDES 25 SEC FRCS DUMP
TAL INCLUDES 65 SEC FRCS DUMP
102 LBS AFT BALLAST (BOXES ONLY)

ESTIMATES BASED ON SPICE AND MODIFIED FOR WEIGHT CHANGES THRU 08/05/08.

STS-128 LSRR OV-104 FLIGHT 31 CONFIGURATION UPDATES

Alvin Jenkins
USA Orbiter Element

August 14, 2008





STS-128 OV-104 Flight 31 – LSRR Updates

Program Authorization Is Requested For The Following:

- Baseline one (1) Orbiter modification
- Baseline two (2) mission equipment modifications
- Baseline one (1) modification as Non-Flight Specific (NFS)
- Authorize Orbiter Mission Equipment changes

Information Only:

- Three (3) potential modifications under review
- LiOH Cartridge Protective Cover Implementation
- Wing Leading Edge Spar Structural Corrosion Inspection
- Additional OPF processing requirements
 - Chits, TPS Priorities

Back-up:

- Modification Records and MECSLSI Updates Summary
- Engineering, Hardware and Certification Status





STS-128 OV-104 Flight 31 – Modifications To Be Baselined

TAD 30179 – Mid Deck Partition Panels Protection Mod


- Adds protective covers to two mid deck aft partitions to prevent damage
 - The crew module (CM) PRT reviewed all the critical structures and CM skin exposed to on-orbit traffic and identified two mid deck partitions as a risk area
 - The mid deck partitions are located in high traffic area near the airlock hatch B and are exposed to crew activities
 - The side walls as thin as 0.051 in. thick are exposed to possible impact from other hardware with sharp edges moving nearby
 - Damage in a thin web could result in loss of shear capability for that panel
 - Two partitions carry approximately 34% of the aft bulkhead pressure load
 - Failure of a partition might cause a progressive failure of the aft bulkhead
 - Study recommended the implementation of 0.060" Lexan shields on port partition shield
 - 0.060" Lexan shield can provide adequate partition protection and accommodate proposed new quick-shoe installation on the port partition
 - Modification was approved at OCCB on 7/22/08





STS-128 OV-104 Flight 31 – Modifications To Be Baselined

TAD 30179 – Mid Deck Partition Panels Protection Mod (Cont.)



View looking outboard - Port Partition

View looking outboard - Starboard Partition

Shield installation: New Velcro pattern and existing nutplates in partition






STS-128 OV-104 Flight 31 – Mission Equipment Modifications To Be Baselined

TAD 30186 – OMS Pod Micro-WIS Strain Recorder Removal

- Removes the Micro-WIS Strain Gage Unit (SGU) from the left OMS Pod due to the expired certification
 - The Strain Gauge Unit was installed to obtain environment data for analysis of harmonics observed on STS-100 (OV-105) launch video and was certified for four flights

The recorder will be removed and the wiring will be stowed in the immediate area








STS-128 OV-104 Flight 31 – Mission Equipment Modifications To Be Baselined

TAD 30164 – TriDAR (DTO-701A) Installation

- The autonomous rendezvous and docking sensor (TriDAR) will be integrated into the Orbiter system to demonstrate technology for autonomous rendezvous and docking in Low Earth Orbit
 - The sensor will be mounted on the airlock truss next to the Trajectory Control Sensor #2 in the (TCS# 1) location
 - The TCS tech order installation drawings will be updated to establish a unique TriDAR installation configuration









STS-128 OV-104 Flight 31 – Modification To Be Authorized As NFS

MCR 23205 – Acreage Doublers Addition to Avionics Bays 4, 5 and 6

- Installs cold bonded protective doublers to the honeycomb facesheet on the aft avionics bay 4, 5 and 6 doors to provide additional resistance to impact loads and ensure life of honeycomb panels
 - Numerous dents and damages to the avionics bay 4, 5 and 6 doors occur during routine ground processing
 - Panels are honeycomb construction with a thin (0.020) aluminum facesheet located inside the 50-1 and 50-2 aft access doors in a high traffic and very susceptible to impact damage area
 - Damage is assessed each flow and doublers are installed as required
 - Requires PR documentation, detail inspection steps of damage, and stress analysis to support acceptance
 - Tight access makes hot bonded doubler difficult to install
 - Large PRACA history on honeycomb dents requiring MR doubler installation
 - Protective doublers over the entire acreage will prevent future damage and work stoppage during damage assessment and repair effort





- Update the V072-200208 MECSLSI with the following tech order changes:
 - WVS S-Band Antenna Installation (Two S-band antennas at Xo 759 port and starboard are installed per FRD17462-128 Basic)
 - Add M072-744004-013 (Antenna #2)
 - Add M072-744004-017 (Antenna #6)
 - Add M072-794026-002 (Wiring for Antenna #2)
 - Add M072-794026-006 (Wiring for Antenna #6)
 - WVS Antenna Load Plug Removal
 - Remove M072-794026-013 (Antenna #6 location)
 - Remove M072-794026-015 (Antenna #2 location)
 - Aft Fuselage Ballast Removal
 - Remove M072-851701-054
 - Airlock Fan and Ducting Installation
 - Remove M072-643402-010
 - Add M072-643402-009





- Update the V072-200208 MECSLSI with the following tech order changes (Cont.):
 - OMS Pod Micro-WIS Strain Recorder (OCR/D S164130N)
 - Remove M072-755111-001 (Micro-WIS SGU)
 - Add M072-755111-002 (SGU wires stowage)
 - TriDAR Installation
 - Add M072-730021-TBD (TriDAR installation)
 - Add M072-363838-TBD (TCS blanket)
 - Light Weight Tool and Stowage Assembly (per FRD17462-128 Basic)
 - Remove M072-660850-006 (STBD TSA)
 - Remove M072-660854-001 (STBD TSA tools)
 - Add M072-660850-005 (Port TSA)
 - Add M072-660853-002 (Port TSA tools)
 - ISS ODS Docking System Installation
 - Add M072-534077-001 (Cross-Hair)
 - Add M072-534077-007 (Light assembly)
 - Add M072-534077-019 (Docking mechanism)
 - Add M072-660828-002 (Centerline camera)





- Update the V072-200208 MECSLSI with the following tech order changes (Cont.):
 - Airlock Vent Tee Installation
 - Add M072-340828-001
 - N2O2 Docking Base to A/L I/F Installation
 - Add M072-643416-001
 - ISS Docking Harness Installation
 - Add M072-794741-004
 - OBSS Sensor Package 1 (OCR/D S165141)
 - Remove M072-710282-007 (PTU -508)
 - Add M072-710282-008 (PTU -510)
 - SRMS End Effector (EE) Configuration Change (OCR/D S165341)
 - Remove M072-544502-033 (EE 51140F36-13)
 - Add M072-544502-036 (EE 51140F36-11)





- Update the V072-200208 MECSLSI with the following tech order changes (Cont.):
 - External Airlock "D" Hatch Installation
 - Add M072-364828-TBD (TPS blanket)
 - Add M072-593828-TBD ("D" hatch)
 - Trajectory Control Sensor
 - Add M072-730021-019
 - Sidewire and EVA Tether
 - Remove M072-544700-016 (Slidewire)
 - Remove M072-661618-016 (Tether)






TAD 30189 – APU QD Heater Modification

- Add a heater to the GN₂ Quick Disconnect (QD) to prevent on-orbit pressure decay of the fuel system
 - During STS-121 and STS-123 APU system 1 experienced an on-orbit pressure decay of the fuel system
 - GN₂ fill QD was isolated as the most likely source of the leak in both cases
 - Post flight testing has identified on-orbit thermal environment as a probable contributor to the leaks
 - Tests of the two QDs which exhibited on-orbit leakage indicate that leakage occurs as a result of synergistic effects of contamination (including hydrazine) on the QD poppet sealing surface and the cold environment of space
 - Replacement of the poppet and seal assembly following STS-121 resulted in no leakage during the 3 subsequent flights of OV-103
 - Temperature increase may reduce the risk of QD leakage
 - No leakage detectable for either of the leaking QDs at ambient temperature (including helium mass spec at 400psi)
 - Preliminary thermal analysis shows that GN₂ QD temperature can be increased to the desired temperature of 40°F
 - Additional thermal analyses are currently being performed for heater failure conditions for on-orbit design environment of -45°F and to refine the heater distribution at the GN₂ QD






TAD 30189 – APU QD Heater Modification (Cont.)







TAD 30189 – APU QD Heater Modification (Cont.)








TAD 30099 – D-hatch Decal Relocation

- Relocates actuator handle position decals on the external airlock upper hatch to the correct location
 - The crew reported difficulty closing and latching the external airlock upper hatch during STS-124 (OV-103)
 - Attempts to position the actuator handle over the decal that indicated the correct "preclosing" position were unsuccessful, as a hard stop was encountered prior to reaching that position (Ref. PR MEQ-3-36-1710)
 - When D hatch was designed in 1982, the decal was inadvertently located in original A/B hatch position (20 degrees from fully unlatched)
 - The D-hatch installation drawings will be updated to reflect the correct decal locations (OCR/D S165361 is in work)








TAD 30192 – EVA Lock-out Bolt Retention Improvement

- Adds a secondary locking feature to the EVA lock-out bolt on the Payload Retention Latching Assembly (PRLA) standard / heavy weight longeron latch
 - The current hardware has only a single-locking method on the two lock-out bolts which clamp the EVA latch drive in a desired position
 - Prior to using the EVA feature on the latch, the two locking bolts are retained by the locking feature of the inserts
 - The locking inserts for the two bolts maintain the rigging and also keep the bolts from vibrating off
 - If the bolts, which are not preloaded, happen to vibrate off, the operation and/or locking of the EVA feature will be lost
 - The new design concept is a simple rework method for the secondary locking feature that will allow locking without prematurely tightening or loosening the bolt or hindering EVA operations







STS-128 OV-104 Flight 31 – Information Only

TAD 30156 – LiOH Cartridge Protective Cover Implementation

- Adds protective soft cover to LiOH canisters designated for ISS to protect the cartridge and flight wrapper from damage and reduce LiOH dust generation
 - During previous ISS flights, excessive dust was noted inside the wrappers of ISS stockpile LiOH canisters
 - LiOH dust released into the cabin is an irritant hazard
 - Nomex cloth covers placed over the LiOH canister will mitigate dust generation due to can-to-can contact during stowage
 - Also protects can flight wrapper from potential breach resulting in LiOH exposure to atmosphere
 - Fabric cover to be placed on LiOH canisters designated for ISS stockpile
 - Extra covers to be fabricated and flown to ISS for use on already stockpiled canisters
- Additional covers, if required, will be authorized by CCCD Directive







Wing Leading Edge Spar Structural Corrosion Inspection

- OMRSD Requirement
 - Perform a detailed external inspection of the wing leading edge (WLE) spar installation including spar fitting and spar insulator attach holes. Document evidence of structural degradation corrosion or other structural abnormalities. The intent of the requirement is primarily to find corrosion.
 - V30KG0.065: Sample inspection LH wing, RCC panels 9-11 & 20-22
 - V30LG0.065: Sample inspection RH wing, RCC panel 9-11 & 20-22
 - Requires removal of the noted RCC panels and associated attach fittings
- 3 Year sampling requirements noted above are planned for the STS-128, OV-104 Flight 31 flow
 - If significant corrosion is detected it may drive the full inspections earlier
- 4.5 Year full inspection of all 22 panels per side is due January 2010
 - Would be required prior to 104's last scheduled flight, STS-131 Flight 32
 - GO has been requested to assess performing additional inspections during the STS-128 flow
 - Spreading the inspections over the next 2 flows will allow more of an opportunity of assuring the requirements are met





Chits

CHIT	TITLE
J6116	AMES GAP FILLER REMOVAL AND REPLACEMENT (MULTI-FLOW CHIT LOW ON TPS PRIORITY LIST)
J6198	MID FUSELAGE LOCK BOLT SAMPLING (REQUIREMENT WAS COMPLETED ON PREVIOUS FLOWS)
J6275A	ORBITER STRUCTURE IML SURFACE CORROSION SAMPLING INSPECTION
J6327	WLE RCC JOGGLE INSPECTION
J6329	ASA #2 & #4 AND ATVC #3 & #4 R&R FOR OV-104, FLT 31
J6341A	EVALUATION OF OMS POD LI-900 TILE INSTALLED ON 0.090" SIP
J6351	OV-104 RUDDER / SPEEDBRAKE (RSB) ACTUATOR EXTERIOR INSPECTION
J6378	OV-104 BODY FLAP (BF) POWER DRIVE UNIT (PDU) GEARBOX FLUID LEVEL INSPECTION
J6380	EVA PDU TOOL INTERFACE VERIFICATION
J6387	PASSIVE DOCKING TEST ON OV-104 (IN REVIEW)
J6389	CLOSE CLEARANCE MEASUREMENTS OF ORBITER HARDWARE FOR STS-125
J6399	0-GAUGE PROTECTION FOR OV-103 FLIGHT 32-35 AND OV-104 FLIGHT 27-35 (IN REVIEW)
J6402	MICRO INSPECTIONS OF CAPTIVE GAP FILLERS





STR/TPS Priorities

- Mandatory
- Flight damage, OMRS Rqmts/Chits, LRU access, & deferred work
 - Deferred work may be redeferred with acceptable inspection
- Boundary Layer Transition Modification (Scheduled OV-103 flt 36 only)
- Continue G/F R & R on a best effort basis zones 2B subset
- Prioritized Opportunity
- 1. BRI-18 Tile MLGD FWD O/B Corner (complete)
- 2. BRI-18 Tile MLGD FWD Edge (complete)
- 3. BRI-18 Tile MLGD O/B Side (complete)
- 4. BRI-18 Tile STR side of ET Doors Aft & Outboard (complete)
- 5. BRI-18 Tile LESS Carrier Panels 8-10 (complete)
- 6. BRI-18 Tile STR side of ET Doors Inboard side AFT 4 Tiles (8 Tile)
- 7. Inboard Elevon "Hub" Tile Modification (2 Tiles on OV-104)
- 8. I/B Elevon 9lb/90 SIP Upgrade to FRCI-12 34 Tiles (17/side) AFT to FWD
- 9. O/B Elevon 9lb/90 SIP Upgrade to FRCI-12 6 Tiles (3/side)
- 9A. High Priority Putty Repairs Worst case masses/DTA (2 Tiles on OV-104)





STR/TPS Priorities

- 10. Structural Corrosion Sampling plan
- 11. MLGD Outboard Middle 1/3 (6 Door/6 STR)
- 12. MLGD Outboard AFT 1/3 (1/3 left) 6/door/6 str) 24 Tile
- 13. Putty Repairs 2nd subset of large mass repairs
- **14.** Nose Area 9lb/0.090 SIP Upgrade to FRCI-12 14* Tiles (7/side) (*103 16 tiles, *thruster*)
- 15. Base Heat Shield 9lb/90 SIP Upgrade to FRCI-12 42 Tiles (32/stinger, 10/Box Attach point)
- 16. Gap fillers in Subset 2B (Line across MLGD edge)
- 17. BRI-18 Tile Remaining MLGD (Top Priority) / LESS carrier panels/NLGD
 - 1. MLGD (Inboard, forward edge working to AFT door edge)
 - 2. LESS panels 8, 9, 10, 7, 6, 5, 4, 3, 2, 1, 11, 12, 13 (in that order)
 - 3. NLGD (attrition do leading edge first)
- 18. Mod work (WLE sneak flow, WLE Horsecollar Gap Fillers)
- 19. MADS Instrumentation Failures (104 & 105 L/H OMS Pod) (place holder)
- 20. Remaining Gap Fillers & Window BRI-18
 - 1. Windows 2, 3, 4, & 5 Upper Carrier Panels (top priority)





Current Vehicle Status - Completed Installations

Priority Number	Total	OV-103	OV-104	OV-105
1. BRI-18 Tile - MLGD FWD O/B Corner	28	complete	complete	complete
2. BRI-18 Tile - MLGD FWD Edge	22	complete	complete	complete
3. BRI-18 Tile - MLGD O/B Side	18	complete	complete	complete
4. BRI-18 Tile - STR side of ET Doors	20	complete	complete	complete
5. BRI-18 Tile – LESS Carrier Panels 8-10	24	complete	complete	2
6. BRI-18 Tile – STR side of ET Doors I/B	8	1 (I/W 7)	1	complete
7. Inboard Elevon "Hub" Tile Mod	4	0 (I/W 4)	2	complete
8. I/B Elevon 9lb/90 SIP	34	2 (I/W 32)	5	17 (I/W 17)
9. O/B Elevon 9lb/90 SIP	6	4 (I/W 2)	3	complete
9A. High Priority Putty Repairs	9 (6,2,1)	0	0	0
10. Structural Corrosion Sampling Plan	25 Zones	13	8	12
11. MLGD – Outboard Middle 1/3	24	0	0	3
12. MLGD - Outboard AFT 1/3	24	0	Ō	1
13. Putty Repair Removals	22 (11,6,5)	0	0	0
14. Nose Area 9lb/90 SIP	14 (16 ^{OV103})	1	0	0
15. Base Heat Shield 9lb/90 SIP	42	7	24	33
16. Gap fillers in Subset 2B	5 Zones	2	1	0
17. BRI-18 Tile – Remaining MLGD (Top Priority) / LESS carrier panels/NLGD	MLGD 100 NLGD 123 LESS 66	MLGD 0 NLGD 11 LESS 7	MLGD 1 NLGD 19 LESS 2	MLGD 0 NLGD 26 LESS 12
18. Mod work LESS internal	44 locations	37	39	complete
20. Remaining Gap Fillers & Window BRI-18	124	2	2	28





STS-128 LSRR Flight Crew Equipment/GFE

MV5/Kenneth Brown

Date August 14, 2008

Page 1

STS-128 LSRR FCE/GFE Status

Kenneth Brown
Manager, GFE & Flight Crew Equipment Office
Johnson Space Center




NASA

STS-128 LSRR Flight Crew Equipment/GFE

Presenter MV5/Kenneth	Brown
Date August 14, 2008	Page 2

- Need dates and delivery dates have not yet been partnered. Post CIR, team will work to partner remaining dates
- Tech orders and hardware list noted in backup charts, reference only
- Changes since STS-125:
 - -510 Pan Tilt Unit to be delivered for OBSS Sensor Pack 1, which flew a
 -508 PTU on STS-125. Remaining Camera/PTU locations flown on STS-125 used -510 PTUs.
 - Reconfigure from HST to ISS reinstall ODS mechanism, TCS, WVS antennas
 - OMS pod SGUs removal (end of certified service life)
 - Starboard TSA removed





August 14, 2008

STS-128 LSRR Flight Crew Equipment/GFE

- RMS End Effector (EE) Mod MDA Upgrading from -11 to -13:
 - Change the raybestos brakes/clutches to a ceramic material (since raybestos is no longer available)
 - Implement two design modifications to address issues that occurred on STS-103 (back-up release stall)
- OV-105 and OV-103 RMSs have upgraded EEs (STS-126 and STS-119 flows, respectively)
- EE S/N 403 to be returned to KSC late February '09 timeframe
 - Plan to swap for OV-104 arm EE S/N 402
- Tech Order M072-544502 has been updated to reflect the new -13 EE configuration



NASA

STS-128 LSRR Flight Crew Equipment/GFE

Presenter		
MV5/Kenneth	Brown	
Date August 14, 2008	Page 4	

- TriDAR DTO Combines Triangulation and LIDAR in a single optical path
 - Largely based on OBSS LCS flight hardware & software
 - Immune to lighting conditions
 - Takes advantage of the complementary nature of triangulation and Time of Flight (TOF)
 - Adds long range IR Camera capability
- Provides 6DOF relative pose information in real-time from 3D data
- Sensor Located on ODS, Next to TCS
- Control Software on standard Flight A31P PGSC
 - Minimal crew time required (start/stop/verify)





STS-128 LSRR Flight Crew Equipment/GFE

Presenter MV5/Kenneth	Brown
Date August 14, 2008	Page 5

- OPO implementing a DTO a Thrust Oscillation Seat DTO to gather launch vibration data
 - DTO will be done in conjunction with a DSO to record astronaut visual performance to aid in development crew performance specifications
 - DTO will instrument three Orbiter Seats (Seats 3, 5, 6 or 7)
 - Each seat will be instrumented with three triaxial accelerometers
 - Each accelerometer and corresponding sensor box will be attached to the crew seat
 - Data will be taken during launch
 - DTO is targeted for STS-119, STS-127, STS-128



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-128 Integrated Launch Site Requirements Review

Presenter Kenneth Nowak

Date 08-14-08

Backup Material

FRWG Presentation (With Minor Changes)



SPACE SHUTTLE PROGRAM Space Shuttle Flight Operations and Integration Office



ASA Johnson Space Center, Houston, Texas			
	Presen	ter Shelby Law	son/MO3
	Date	08/14/08	Page 1

Flight Operations and Integration (FO&I)

Flight Requirements:
MIP, PIPs, CIP
FDRD
FRD

Backup Charts



SPACE SHUTTLE PROGRAM Space Shuttle Flight Operations and Integration Office NASA Johnson Space Center, Houston, Texas



STS-128/17A Mission Requirements Status

Presenter Shelby Lawson/MO3

Date 08/14/08

Page 2

<u>Documentation</u>	ECD/Date
----------------------	----------

MIP - NSTS 21546, Rev B, (5/28/08)

CR-0003: LMC Control Weight Update

08/14/08

CIP- LMC, NSTS 21494, Rev B, Chg 1-11 (5/28/08) STS-128 Addendum

CR-0025: LMC Control Weight Update

08/14/08

FDRD:	
	_

PIP - MAUI, NSTS 21530, Basic, Chg 1-2 (5/5/08)

PIP - MPLM, NSTS 21499, Rev B, Chg 1-2 (12/7/07)

PIP - SEITE, NSTS 21542, Basic (11/19/07)

PIP - MISSE 6a and 6b, NSTS 21537, Basic, Chg 1-3 (01/24/08)

IP-DTO-701A TriDAR AR&D Sensor, NSTS 21547, Basic (06/05/08)

None pending None pending

None pending

None pending

None pending

None pending



SPACE SHUTTLE PROGRAM Space Shuttle Flight Operations and Integration Office NASA Johnson Space Center, Houston, Texas



STS-128/17A FRD Status

Presenter Frank Richmond/USA

Date 08/14/08

Page 3

- STS-128 Latest FRD Revision
 - Basic: Dated, June 19, 2008 (http://sspweb.jsc.nasa.gov/efrd)
- Open CRs
 - FRD 17462-128-003 Provide Launch Window Performance Reporting Requirements (3 min window)

Evaluations Due: 08/11/08

- Closed CR
 - FRD 17462-128-002 Remove Aft Ballast Boxes from STS-128 (OV-104)

ECD: 08/11/08 (A)

Disposition: Disapprove.

STS-128 OV-104 Flight 31 LSRR

Back-up

- Modification Record and MECSLSI Updates Summary
- Engineering, Hardware and Certification Status





Modification Records and MECSLSI Update Summary

MCR/ TAD NO.	TITLE	TECH ORDER IMPACT	REMARKS								
		Modifications To Be Baselined									
30179	Mid Deck Partition Panels Protection Mod Adds protective covers to two mid deck aft partitions to prevent damage and accommodate a new quick shoe installation.	No Tech Order Impact	No MECSLSI Impact								
	Mission Equipment Modifications To Be Baselined										
30186	OMS Pod Micro-WIS Strain Recorder Removal Removes the recorder box from the left OMS Pod and stows the wires.	030186, 0014, 0 - Stows the remaining wire	Micro-WIS SGU on OMS Pod Installation M072-755111-002 (is) M072-755111-001 (was) MV0886A	MECSLSI Impact							
30164	Autonomous Rendezvous and Docking Sensor - TriDAR Installs the TriDAR sensor for autonomous rendezvous and docking in Low Earth Orbit technology demonstration.	TriDAR Installation M072-730021-TBD TCS Blanket Installation M072-363838-TBD MV0828A	MECSLSI Impact								
		Modification To Be Authorized As NFS	,								
23205	Acreage Doublers Addition to Avionics Bays 4, 5 and 6 Installs cold bonded protective doublers to the honeycomb facesheet on the aft avionics bay 4, 5 and 6 top panels to provide additional resistance to impact loads and ensure life of honeycomb panels.	VK70-356734-001, 0104, 0 - Provides hardware for acreage doublers on honeycomb door panels	No Tech Order Impact	No MECSLSI Impact							
		Potential Modifications									
30189	APU QD Heating Modification Replaces the fuel fill heater (HR1n6) with a longer heater and runs the extension of the heater to the GN2 Quick Disconnect (QD) to prevent on-orbit pressure decay of the fuel system.	030189, 0104, 0 - Installs a longer heater to increase the GN₂ QD temperature	No Tech Order Impact	No MECSLSI impact							
30099	D-hatch Decals Relocation Relocates actuator handle position decals on the external airlock upper hatch to the correct location. TBD - Relocates "Latched / Unlatched" decals on the airlock up hatch		M072-593828-TBD M072-650701-TBD M072-364828-TBD	MECSLSI Impact							
30192	30192 EVA Lock-out Bolt Retention Improvement Adds a secondary locking feature to the EVA lock-out bolt on the Payload Retention Latching Assembly (PRLA) standard / heavy weight longeron latch. TBD - Enhances existing design		No Tech Order Impact	No MECSLSI Impact							
		Information Only									
30156	LiOH Cartridge Protective Cover Implementation Adds protective soft cover to LiOH canisters designated for ISS to protect the cartridge and flight wrapper from damage and reduce LiOH dust generation.	TBD - Installs the LiOH containers with the protective Nomex cloth cover under the middeck floor	Crew Station Equipment Installation M072-661627-TBD MV0627A	CCCD Impact							





Engineering, Hardware and Certification Status

MCR/ TAD NO.	TITLE	Est. Engr Release (MM/DD/YY)	G.O. Engr Need (MM/DD/YY)	Est. Hdwe Delivery (MM/DD/YY)	G.O. Hdwe Need (MM/DD/YY)	MOD/CERT GO / NO-GO	CERT SUBMITTAL DATE	CERT APPROVAL DATE	CERTIFICATION CR / CAR (BOEING)	REMARKS
			M	lodification	s To Be Ba	selined	1			
	Mid Deck Partition Panels Protection Mod Adds protective covers to two mid deck aft partitions to prevent damage and accommodate a new quick shoe installation.	9/30/08	9/30/08	10/16/08	10/16/08	GO	10/7/08	12/7/08	CAR# 149-04-331002H	JSERP approved 7/18/08; OCCB approved opt. A 7/22/08
	Mission Equipment Modifications To Be Baselined									
30186 OMS Pod Micro-WIS Strain Recorder Removal Removes the recorder box from the left OMS Pod and stows the wires. 7/25/08 7/25/08 N/A N/A GO N/A N/A N/A OCR/D S164130N							OCR/D S164130N			
	Autonomous Rendezvous and Docking Sensor - TriDAR Installs the TriDAR sensor for autonomous rendezvous and docking in Low Earth Orbit technology demonstration.	10/15/08	10/16/08	TBD	10/16/08	GO	TBD	TBD	TBD	FRD17462-128 Basic
			Modif	ication To	Be Authori	zed As NF	<u>s</u>			
23205	Acreage Doublers Addition to Avionics Bays 4, 5 and 6 Installs cold bonded protective doublers to the honeycomb facesheet on the aft avionics bay 4, 5 and 6 top panels to provide additional resistance to impact loads and ensure life of honeycomb panels.	Released	N/A	Delivered	N/A	TBD	TBD	TBD	TBD	Engineered for flight 31
				Potentia	l Modificati	<u>ons</u>				
	APU QD Heating Modification Replaces the fuel fill heater (HR1n6) with a longer heater and runs the extension of the heater to the GN2 Quick Disconnect (QD) to prevent on-orbit pressure decay of the fuel system.	TBD	10/16/08	TBD	10/16/08	TBD	TBD	TBD	TBD	Design has not yet been finalized
	D-hatch Decals Relocation Relocates actuator handle position decals on the external airlock upper hatch to the correct location.	TBD	TBD	TBD	TBD	GO	TBD	TBD	CR# 28-593201-001S CAR# 12-28-593201-001S	OCR/D S165361 submitted
	EVA Lock-out Bolt Retention Improvement Adds a secondary locking feature to the EVA lock-out bolt on the Payload Retention Latching Assembly (PRLA) standard / heavy weight longeron latch.	TBD	12/1/08	TBD	12/1/08	TBD	TBD	TBD	CR# 44-287-0025-0001F CAR# 04-44-287-00251F	OPO is planned for early September, if approved, engineering s/b relesed by end of November
				Inforr	mation Onl	Υ				
30156	LiOH Cartridge Protective Cover Implementation* Adds protective soft cover to LiOH canisters designated for ISS to protect the cartridge and flight wrapper from damage and reduce LiOH dust generation.	Released	N/A	Delivered	N/A	TBD	Submitted	Approved	CR# 22-621-0008-0009J CAR# 10-22-621-0008-0009J	* Engineering released and cert submitted for STS-123 (OCR/D S165299)







NASA

STS-128 LSRR Flight Crew Equipment/GFE MV5/Kenneth Brown

Date August 14, 2008

Page 1

BACKUP





STS-128 LSRR Flight Crew Equipment/GFE

Presenter MV5/Kenneth	Brown
Date August 14, 2008	Page 2

Tech Order numbers are identified for reference only.

Hardware	Tech Order	KSC Eng Need	Eng(TO) Release	In MEC	Cert O/C	KSC Need	JSC Planned	Comments	JSC Contact
A (port forward)	M072-750025-076							Camera from STS-119 (-510 Pan & Tilt Unit)	Randall Moore
B (port aft)	M072-750025-077							Camera from STS-119 (-510 Pan & Tilt Unit)	Randall Moore
C (starboard aft)	M072-750025-078							Camera from STS-119 (-510 Pan & Tilt Unit)	Randall Moore
D (starboard forward)	M072-750025-079							Camera from STS-119 (-510 Pan & Tilt Unit)	Randall Moore
Payload Ops camera(s)	M072-340042-006								Randall Moore
SRMS elbow camera	M072-544504-007							Camera from STS-119 (-510 Pan & Tilt Unit)	Randall Moore
SRMS wrist camera	M072-544504-008							Camera from STS-119	Randall Moore
Lefthand Umbilical Camera (aft)	M072-705001-016								Randall Moore
3	M072-705001-028 M072-705001-027								Randall Moore
Digital Television (DTV)	M072-710570-007							Installed Hardware.	Larry Schmidt
MCIU/RMS Situational Awareness Display (RSAD)	M072-710543-001							Installed Hardware.	Larry Schmidt
Tools for Rendezvous and Docking (TRAD)								HHL's only. TCS reinstallation required. TCS Tech order to be back in MECSLSI.	Larry Schmidt
Video Processing Unit (VPU)	M072-710338-006							Installed Hardware.	Larry Schmidt





STS-128 LSRR Flight Crew Equipment/GFE

Presenter MV5/Kenneth	Brown
Date August 14, 2008	Page 3

Tech Order numbers are identified for reference only.

Hardware	Tech	KSC Eng	Eng(TO)	In MEC	Cert	KSC	JSC	Comments	JSC
Hardware	Order	Need	Release	IN MEC	O/C	Need	Planned	Comments	Contact
Wireless Video System (WVS)	MO72-744007-001 UHF							Reinstall antennas on OV-104	Randall Moore
	M072-344828-001 mount								
	M072-744004-012 S-BAND								
	M072-744004-014 S-BAND								
	M072-744004-015 S-BAND								
	M072-744004-016 S-BAND								
	M072-744004-018 S-BAND								
Space to Space Orbiter Radio	M072-344828-002								Larry Schmidt
(SSOR)	M072-740828-002 antenna								
RMS Sideview Camera (RSC)	M072-710281-002							Camera from STS-119	Randall Moore
	M072-000416-004 camera								
0 0 0 7	M072-756111-007							Installed Hardware	Gary Cox
Instrumentation - Left Wing									
	M072-756111-008							Installed hardware	Gary Cox
Instrumentation - Right Wing									
OMS Pod Micro-Strain Gauge Unit (SGU)								Remove SGUs from OV-104 (end of certified service life).	Gary Cox
OBSS Sensor Package 2 (OPF)	M072-710282-006								Larry Schmidt
OMS POD MICRO-SGU Batteries	M072-755111-001							KSC has all SGU batteries.	Gary Cox
OBSS SENSOR PACKAGE 1 ** (OPF)	M072-710282-008							OBSS SP1 will fly -510 PTU.	Randall Moore
RMS-13 End Effector	M072-544502-036								Ken Ruta
TriDAR									Larry Schmidt




NASA

Prototype TriDAR

MV5/Kenneth Brown

Date August 14, 2008





NASA

DTO Primary Objectives

Presenter MV5/Kenneth	Brown
Date August 14, 2008	Page 5

- Intended to demonstrate operation of the sensor and to collect data required for tracking.
- 1) Collect long-range 3D TriDAR data of the ISS
- 2) Collect short-range 3D TriDAR data of the ISS
- Demonstrate geometry based tracking and pose estimation from TriDAR data without using cooperative targets
- 4) Provide AR&D cues to shuttle crew for demonstration purposes
- 5) Collect system status and health data (telemetry) for TriDAR hardware
- 6) Demonstrate TriDAR lighting immunity





KSC Requirements

Presenter MV5/Kenneth	Brown
Date August 14, 2008	Page 6

Installation

- TriDAR Unit onto the ODS
- Power Cable
- Ethernet Data Cable
- Command and Monitor Cable
- Blanket?

Testing

- Unit check out in the FCEL
- OPF IVT from inside the crew cabin.
 - Similar to the LCS IVT with Laser Safety

Removal after flight






Thrust Oscillation Seat DTO

Presenter	
MV5/Kenneth	Brown
Date August 14, 2008	Page 7

Accelerometer







Sensor Unit

Laptop/Software

- Used to program units pre-flight, and download data post-flight
- Not Required for Flight Ops







STS-128 Launch Site Requirements Review

Presenter		
MK-SIO / A. Swift		
Date	08-14-08	Page 1

Mandatory RCNs:

NONE

Non-Mandatory Value Added RCNs:

NONE

STS-128 Launch Site Requirements Review Flight Software Overview

Tom Stansel USA FSW

PRCB 8/14/08



STS-128 LSRR (FSWE)

- STS-128/OV-104 is the First Scheduled Flight of Operational Increment (OI) 34
 Flight Software (FSW)
 - SASCB SCR 98107A (pending approval) documents PASS and BFS OI-34 content
- STS-128/OV-104 Flight Software Payload Support:
 - ISS 17A
 - Orbiter Interface Unit (OIU)
 - Sequential Still Video (SSV)
 - Orbiter Docking System (ODS)
 - Trajectory Control System (TCS)
 - Multi-Purpose Logistics Module (MPLM)
 - ISS Caution and Warning (ISSCW)
 - Assembly Power Converter Units (APCUs) & Station to Shuttle Power Transfer System (SSPTS) (generic support for both configurations)
- Major New Flight Software Support Items:
 - None



STS-128 LSRR (FSWE)

- STS-128 Source Changes/Edits for Primary Flight Software (Base)
 - None
- STS-128 Patch Implementation for Primary Flight Software
 - None
- STS-128 Patch/Edit Implementation for Backup Flight Software (Base) (included on delivered Mass Memory)
 - None
- STS-128 Patch Implementation for Backup Flight Software
 - None



STS-128 LSRR (FSWE)

- Products
 - STS-128/OV-104 Base Cycle Product delivery schedule (available to field)

FPSB

Shuttle Data Tape
 January 15, 2009

Mass Memory
 January 23, 2009

- Open Items
 - None
- Concerns/Issues
 - No issues or concerns with STS-128 at this time







EVA Status

STS-128/Flight 17A Launch Site Readiness Review

XA/Maria Tullar
Johnson Space Center
August 14, 2008



EVA Tools Status - STS-128 LSFR



Bulkhead PFR – SED33105308-307

Bulkhead PFR installation – Tech Order: M072-661568-029

Winches

- Forward Winch, SED33101570-327
- Aft Winch, SED33101570-325

Port LWTSA

- Port LWTSA installation Tech Order: M072-660850-005
- Port LWTSA Tools installation Tech Order: M072-660853-002

STS-128/ISS-17A

MPLM, LMC and MISSE 6 A&B DTO-TriDAR

Launch Site Readiness Review (LSRR)

USA Payload/Cargo Engineering Status

Abbas Elsabagh Cargo Mission Manager 281-212-6186 August 14, 2008



Major Milestone

• Initial MECSLSI Release	09/22/08
CIR data Pack	10/13/08
• CIRD	10/15/08
• CIR	10/27/08
• FRED	01/13/09

Cargo Engineering Status:

• Flight requirements were baselined (FDRD) on 06/19/08

Issues:

Disconnect of TriDAR cables delivery date vs. KSC need date
 ECD: CIR



ICD Status:

Document	<u>Title</u>	ECD/Date	<u>Status</u>
ICD-A-21342	ODS-ISS	05/24/96	Baselined
- A05608	TriDAR DTO (STS-128 only)	09/05/08	In Development
100 4 04540 000	100 474 On Only (10D	00/40/00	In Development
ICD-A-21546-OOR	ISS-17A On-Orbit ICD	09/12/08	In Development
- A05588	ICD Baseline PIRN		
ICD-A-21494	Lightweight MPESS Carrier (LMC)	12/18/00	Baselined
ICD-A-21537	MISSE 6	07/10/2007	Baselined
ICD-A-21434-EF	MPLM	02/12/96	Baselined



ICD Status:

• The following payload ICDS have been Baselined for STS-128

Document	<u>Title</u>	ECD/Date	<u>Status</u>
ICD-A-21429	DTV	03/10/99	Baselined
ICD-A-21449	MINICAM/DOWNLINK	01/28/99	Baselined
ICD-A-21537	MISSE6	07/10/07	Baselined
ICD-A-21264	OIU	08/17/95	Baselined
ICD-A-21403	SSV	03/17/97	Baselined
ICD-A-21420	VPU	01/14/98	Baselined



OMRSD

• FII V2 (Post-Mate)

Baselined Files

•	P350	Multi-Purpose Logistics Module (MPLM)
•	P430	SL/ORB Generic I/F Requirements (LMC)

• P537 Materials on ISS Experiment (MISSE 6)

RCNS		Release	Baseline	
• TBD	P545 – ISS-17A Baseline	09/01/08	11/27/08	
• TBD	P430 – LMC Update	09/01/08	11/27/08	
• TBD	P350 – MPLM Update	09/01/08	11/27/08	
• TBD	P537- MISSE 6 Update	09/01/08	11/27/08	

• FII V4 (PRE-MATE)

RCNS		<u>Release</u>	Baseline
• DPSXXXX	Mission-Unique List	01/27/08	02/13/09
• DPSXXXX	Adjacent Pin Test	01/27/08	02/13/09
• DPSXXXX	FIII MUL	01/27/08	02/13/09

- Issues / Concerns:
 - None



ANNEX 1

Customer

• ISS-17A - NSTS 21545 Submittal CR Release ECD

- Baseline 06/30/08A 08/11/08 08/29/08

 <u>Data Required</u> – Official weight and mass properties data, payload axis system figure, static length, and mechanical and electrical drawing

- Interim CR 02/18/09 03/03/09 03/17/09

<u>Data Required</u>

– Safety-critical circuit diagram, FHRC & NTA center of gravity figures (if available)

Final Weight Update (L-1 M) 05/19/09 06/02/09 06/16/09

- Issues/Concerns
 - None



ANNEX 1- (Cont.)

Customer

• LMC - NSTS 21494 Submittal CR Release ECD

- Baseline 06/30/08A 08/11/08 08/29/08

 <u>Data Required</u> Official weight and mass properties data, payload axis system figure, static length, and mechanical and electrical drawing

- Interim CR 02/18/09 03/03/09 03/17/09

- <u>Data Required</u> safety-critical circuit diagram, mechanical and electrical drawing updates, and center of gravity figures
- Final Weight Update (L-1 M) 05/19/09 06/02/09 06/16/09
- Issues/Concerns
 - None



ANNEX 1- (Cont.)

Customer

• MISSE 6 - NSTS 21537 Submittal CR Release ECD

- Baseline 06/30/08A 07/31/08A 08/15/08

<u>Data Required</u>

– Official weight and mass properties data, payload axis system figure, static length, and mechanical and electrical drawing

- Interim CR 02/18/09 03/03/09 03/17/09

<u>Data Required</u>

– Safety-critical circuit diagram, mechanical and electrical drawing updates, and center of gravity figures

- Final Weight Update (L-1 M) 05/19/09 06/02/09 06/16/09

Issues/Concerns

- None



TGHR

Customer Submittal 03/30/09
Release for Review 04/30/09
Baseline 05/30/09

Issues/Concerns

None



Cargo Close Clearance Process

- The following Close Clearance areas have been identified:
 - MPLM Scuff Plate to MPM
 - CPK on LMC to AFT bulkhead EVA handhold
- Need to determine if CHIT to take as installed measurement required.
 Assessment still in work.
- Chit measurements will be performed at the PAD after payload installation



Cargo Integration Hardware Status

Delivery Status

All required CIH has been delivered except for TriDAR cables

Issues/Concerns

Disconnect in delivery of Tri DAR cables between delivery date vs KSC need date







STS-128 Integrated Launch Site Requirements Review

Presenter Kenneth Nowak

Date 08-14-08

Backup Material

SSP Systems Drawings
 Attachment 1

SSP Authorized Modifications/Non-Standard Work
 Attachment 2

SSP OMRS Waivers and Exceptions
 Attachment 3

Launch Window (Not Available)

Open Configuration Waivers
 Attachment 4





STS-128 Integrated Launch Site Requirements Review

Presenter Kenneth Nowak

Date 08-14-08

SSP System Drawings

The Drawings Baseline Was Released By PRCB S0721028 on 06-24-08

V072-000001-280 (Rev. TBD) Space Shuttle System (Rel. TBD)

• V072-200208-001 (Rev. TBD) Mission Equipment Cargo Support (Rel. TBD)

• SGD32104451-401 (Rev. TBD) Crew Compartment Configuration (Rel. TBD)

-402 Descent

V070-000001-004Orbiter General Assembly

V070-410100-018
 SSME Installation

• 10100-0061-176 Integrated SRB General Assembly (BI-139)

80901000000-530 External Tank Assembly (ET-132)

[•] STS-128 CIR + 70 days Mission Configuration Product Plan (MCPP) will be published on 12-29-08 and will be republished at LSRR +18 days on 09-01-08.





STS-128 Integrated Launch Site Requirements Review

Presenter Kenneth Nowak
Date 08-14-08

SSP System Drawings – (Continued)

Ferry Configuration

• V072-000001-281 (Rev. TBD) Space Shuttle System Drawing (Rel. TBD)

• V072-200208-002 (Rev. TBD) Mission Equipment Cargo Support (Rel. TBD)

• SGD32104451-001 (Rev. TBD) Crew Compartment Configuration (Rel. TBD)

• V072-300055-023 (Rev. BN01) Ferry Flight Configuration (Rel. 02-20-08)

SCA 905





STS-128 Integrated Launch Site Requirements Review

Presenter	Kenneth Nov	wak
Date 0	8-14-08	

Modification Impact Report

- Mission Equipment Modifications and Orbiter Modifications analyzed for impacts to OMRSD, LCC, ICD, EMI, Software, and GSE
- A total of 6 MCRs have been approved and/or pending mods
- Current MCR impact status:
 - No impacts for all six disciplines 0
 - One or more disciplines with impacts, documentation approved and/or pending approval
 - MCR 19271





STS-128 Integrated Launch Site Requirements Review

Presenter	Kenneth Nov	wak
Date 0	8-14-08	

<u>Modification Impact Report – (Continued)</u>

Possible impacts still under review

5

MCRs 30126, 30164, 30186, 19789, and 30189 are being reviewed for impacts

MRCS REPT. 4650-1

SSP SUMMARY MOD ITEMS - PRCBD MOD BASE LINE STS-0128 ECP-MCR/KIT SEQUENCE

ORB

PAGE NO. 1 RUN TIME 07:38 DATE 08/06/2008

MCR/ECP	STAT SITE	ITEM/KIT NUMBER TCTI NUMBER		DESCRIPTION / GENERAL REMARKS	PRCB AUTHDATE	PRIO FLT
	AUTH KSC	J6116	0104 003 SPAR	AMES GAP FILLER REMOVAL AND REPLACEMENT	ORB-0085B 2006-08-16	MAND 031
	AUTH KSC	J6198	0104 002 SPAR	OV-104 MID FUSELAGE LOCK BOLT OPPORTUNITY SAMPLING AND FASTENER REPLACEMENT	ORB-0085R01 2007-03-12	MAND 031
	AUTH KSC	J6275A	0103 002 SPAR	ORBITER STRUCTURE IML SURFACE CORROSION SAMPLING INSPECTION CORROSION SAMPLING CAPABILITIES WILL BE PROJECTED AT LSFR, AND FINALIZED AT DLSFR FOR EACH FLOW.	S-J6275A 2008-02-26	MAND 037
	AUTH KSC	J6275A	0104 001 SPAR	ORBITER STRUCTURE IML SURFACE CORROSION SAMPLING INSPECTION CORROSION SAMPLING CAPABILITIES WILL BE PROJECTED AT LSFR, AND FINALIZED AT DLSFR FOR EACH FLOW.	S-J6275A 2008-02-26	MAND 031
	AUTH KSC	J6327	0104 001 SPAR	WLE RCC JOGGLE INSPECTION	S-J6327 2008-02-14	MAND 031
	AUTH KSC	J6329	0104 000 SPAR	ASA #2 & #4 AND ATVC #3 & #4 R&R FOR OV-104, FLT 31	S-J6329 2008-05-15	MAND 031
	AUTH KSC	J6341A	0103 001 SPAR	EVALUATION OF OMS POD LI-900 TILE INSTALLED ON 0.090" SIP LI-900 TILE INSTLD ON .090 SIP WILL BE INSPD FOR DEFECTS PER CHIT ON NEAR TERM FLOWS UNTIL RCN IS	S-J6341A 2008-04-09	MAND 037
	AUTH KSC	J6351	0104 000 SPAR	OV-104 RUDDER/SPEEDBRAKE (RSB) ACTUATOR EXTERIOR INSPECTION	S-J6351 2008-05-15	MAND 031
	AUTH KSC	J6378	0104 000 SPAR	OV-104 BODY FLAP PDU GEARBOX FLUID LEVEL INSPECTION	S-J6378 2008-07-18	MAND 031
	AUTH KSC	J6380	0104 000 SPAR	EVA PDU TOOL INTERFACE VERIFICATION	S-J6380 2008-07-07	MAND 031
	AUTH KSC	J6389	0104 001 SPAR	CLOSE CLEARANCE MEASUREMENTS OF ORBITER HARDWARE	S-J6389 2008-07-10	MAND 031

TOTAL MODS = 11 MRCS REPT. 4650-1 SSP SUMMARY MOD ITEMS - PRCBD MOD BASE LINE STS-0128 SSME

ECP-MCR/KIT SEQUENCE RUN TIME 07:38 DATE 08/06/2008

PAGE NO.

2

STAT ITEM/KIT NUMBER SEQ PRCB PRIO MCR/ECP SITE TCTI NUMBER EISN NO. DESCRIPTION / GENERAL REMARKS AUTHDATE FLTAUTH KLO-1624 2050 000 INSPECT SSME FLEET ELECTRICAL HARNESS ROUTING AND SLACK S071807K MAND KSC NSW 2008-08-01 007

TOTAL MODS = 1

1Date: 08/06/08 07:42 PCASS Page: 1

FLIGHT-SPECIFIC

Approved STS-128 OMRS Waivers and Exceptions

		PRCBD NUM WAIVER# (S (INITIAL S	TAT)		EISN PAYLOAD	STS BEG	END
E	ORB	S053298ZC EK10572R1		OMRSD EXCEPTION REQUEST - MISSION LIFE ASSESSMENT OF WING LEADING EDGEINSULATORS (EK10572R1)	104	029	033
		S053298ZD EK10574R1	(A)	OMRSD EXCEPTION REQUEST - WING LEADING EDGE INSULATORS (EK10574R1)	104	029	036
		S053298ZE EK10575R1	(A)	OMRSD EXCEPTION REQUEST - MISSION LIFE ASSESSMENT OF WING LEADING EDGEINSULATORS (EK10575R1)	104	029	031
		S053299AQ EK10592	(A)	OMRSD EXCEPTION REQUEST - DRAG CHUTE DEPLOY SYSTEM 2 LIGHT FAILU RE(EK10592)	104	029	032
		S053299AT EK10593	(A)	OMRSD EXCEPTION REQUEST - DRAG CHUTE DEPLOY SYSTEM 2 LIGHT FAILU RE(EK10593)	104	029	032
W	ET	S053293FZ WK03850R1 (STS-093)	(A)	L02/LH2 TANK PRESSURE MONITOR FOR MOVE	ET	099	999
	OMS	S053298NV WK10522	(A)	OMRSD WAIVER REQUEST - RIGHT OMS SECONDARY REGULATOR CREEP RATE(W K10522)	0021	035	043
	ORB	S053296YT WK10332R2	(A)	OMRSD WAIVER REQUEST - PV6 PREVALVESCREEN PARTICLES (WK10332R2)	104	027	031

	S053298HY WK10502 (A)	OMRSD WAIVER REQUEST - BODY FLAP DRIVE RATE TEST (WK10502)	104	027 031
	S053299BLR1 WK10600R2 (A)	OMRSD WAIVER REQUEST - OXYGEN SYSTEM 1 RELIEF VALVE FAILED RESEA TLEAKAGE (WK10600R3)	104	029 032
RCS	S053296GY WK10188R1 (A)	OMRSD WAIVER REQUEST - LRCS OXIDIZER GHE ISOLATION VALVE LEAK(WK 10188R1)	0014	025 032

1

Date: 08/06/08 07:42 PCASS Page: 2

FLIGHT-SPECIFIC

Approved STS-128 OMRS Waivers and Exceptions

		74	STAT)	ABSTRACT RAS REQUIREMENTS PAY	EISN	STS B	EG	END
W	RCS			OMRSD WAIVER REQUEST - RIGHT RCS OXIDIZER GHE SYSTEM INTERNAL LEA KAGE (WK10318R1)	0021	0.	34	042
		S053298JF WK10503	(A)	OMRSD WAIVER REQUEST - RRCS OX TANKOUTLET TRANSDUCER ACCURACY (WK 10503)	0021	0	34	042
		S053299GW WK10634		OMRSD WAIVER REQUEST - LEFT REACTION CONTROL SYSTEM FUEL GHE ISO LATIONVALVE LEAKAGE (WK10634)	0014	0	30	032
	SRB	S053293WA WK03886 (STS-103)		LH FWD AND RH MID SRB JOINT TEMP SENSORS	BI	0	99	999
	+·			[°] Waivers [°] Except [°] Deviat [°] Ca				
		tal Extract			0 °	15 °		

Page 79 of 86

ACTIVE WAIVERS FOR OV-104

Item #	Authority	Date	Waiver Description	Effectivity	Wad
53	S052428A	03/27/91	Allows specified flights to fly with interim TPS repair after each mission to minimize damage to surrounding tile during ferry flight	STS-37, STS-39, STS-40, STS-42 thru STS-999	STAYS OPEN
101	S076972	11/19/91	Permit the modified GPCs (AP101-S) Battery Back-up Unit to fly with annotated fastener improvements without rolling the LRU Part Number	STS-42, STS-44, STS-47 and STS-49 thru STS-999	STAYS OPEN
325	S061956	07/15/03	Blanket on the Control Moment Gyro (CMG) Orbital Replacement Unit (ORU) on the Lightweight MPESS Carrier (LMC) will NOT be re-installed on-orbit per configuration defined in ICD-A-21494. It will be secured around the FSE and attached to the aft bulkhead.	OV-104, Flight 27	
334	S115115JR1	07/19/06	The following requirement is waived to allow OV-104 to fly with the following out-of-configuration condition:	OV-104, Flight 27 thru OV-104, Flight 999	STAYS OPEN
			Tech Order M072-544501-067 (RMS, MPM over-center stop and MPM pedestal insulation cover fasteners) will be implemented in total, less the requirement to perform bench rigging per updated specification requirements for for OV-104, Flight 27 and subsequent OV-104 flights until such time that all MPMs can be removed and bench rigging can be performed.		
339	S063652	07/09/07	The following requirement is waived to allow OV-104 to ferry from DFRC to KSC with the following out-of-configuration condition:	OV-104, Flight 28	
			Retain RH ET Camera installation for ferry flight MECSLSI V072-200197, reference flag note (3), removes (MV0456A) M072-705001-024 RH ET Sep Camera (Digital Camera with 35 mm lens) for ferry flight. The RH ET Camera needs to remain in flight configuration to support resolution of IFA STS-117-V07 Digital Umbilical Camera Image Corruption. Troubleshooting will be performed on the installed hardware after returning OV-104 to KSC.		

Prepared by: Jeff McRoberts USA CM/CVAS 861-2505

ACTIVE WAIVERS FOR OV-104

Item #	Authority	Date	Waiver Description	Effectivity	Wad
340	S063652	07/09/07	The following requirement is waived to allow OV-104, Flight 28 to ferry with the following out-of-configuration conditions:	OV-104, Flight 28	
			Remove LH OMS Pod LP04 (FIB) blankets prior to ferry flight thermal blanket V070-396376-241 on LOMS Pod lifted at forward leading corner and edges reported on orbit, IFA STS-117-V-02. Two blankets (V070-396376-241 and adjacent V070-396376-051) are removed. RTV ramp applied in cavity up to adjacent blankets per TLP04-28-2520 MRB approval.		
343	S115122GR4	12/07/2007	The following requirement is waived to allow OV-104 to fly with the following out-of-configuration condition:	OV-104, Flight 29	ECL-4-A0118 (was ECL-4-29-1637)
			Partial installation of Tech Order M072-660010-004, middeck air flow re-routing duct tech order, not to include one each bolt (NAS1003-8A) and one each washer (NAS620C10) in the lower aft corner of the vent housing cover assembly.		
			During vertical stowage, the nut plate (not under USA Tech Order configuration control) was noted missing from behind the starboard closeout panel. Without the nutplate, the bolt and washer cannot be installed. The area cannot be currently accessed to reinstall the missing hardware.		

Prepared by: Jeff McRoberts USA CM/CVAS 861-2505

ACTIVE WAIVERS FOR OV-104

Item #	Authority	Date	Waiver Description	Effectivity	Wad
344	S071024MP	12/20/07	During maintenance of an Advanced Master Events Controller (AMEC) it was discovered that the module cards are able to translate upward, away from connectors. The cards are retained by friction applied by wedge-locks. An assessment determined a 0.070 upward card translation, would result in card disengagement from connectors. The wedge-lock system can not assure the cards will not translate upwards. The AMEC vendor (Boeing Autonetics) is no longer on contract supporting SSP. A design proposal is to provide a secondary connector retention using the AMEC covers. The new design new lids will limit the upward translation to 0.055. The new design will reduce the milled section of the cover and add silicone pads to provide shock absorption. Due to the absence of the original vendor and no current alternate drawings available for the AMEC the modification is being requested via a program directed Material Review (MR). P/N MC450-0016-0029 S/N U6F0002, U6F0003, U6F0004, U6F0006, U6F0007, U6F0009, U6F0010 and U6F0011	OV-103, Flight 35 OV-104, Flight 30 OV-105, Flight 21	
			***** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS	****	

Prepared by: Jeff McRoberts USA CM/CVAS 861-2505

VEHICLE LIMITED LIFE STATUS REPORT

OV-104 FLT-31, STS-128

PRELIMINARY SUBMITTED 08/08/2008

NO.	SYS	REQT / PART DESC / PART NO	TOP / SEPAR	ANTICIPATED ACTION	CONSTR	ELE
		C00AA0.010.039	SEPAR - TBD	REMOVE/REPLACE/RECERT	2	0
1	PYRO	TIME DELAY ASSY - LOT NTA	TPS - TBD	N. West and a substitution of the second of		
		SKD26100115-0300				
		C00AA0.010.133	SEPAR - TBD	REMOVE/REPLACE/RECERT	2	0
2	PYRO	RETRACTOR CART - LOT HTR	V5012.002	The second of the second side of the second side of the second se		
		SKD26100134-201	V5012.003			
		C00AA0.010.135	SEPAR - TBD	REMOVE/REPLACE/RECERT	2	0
3	PYRO	REEFING LINE CUTTER(DRAG CHUTE) Lot	V5143.002			
S	FIRO	PCA				
		SED26139100-701				
		C00AA0.030.007	SEPAR - TBD	REMOVE/REPLACE	4	0
4	ECLSS	PPO2 SENSORs SYS 1 - 3	VENDOR REFURB			
		MC250-0002-3165				
		C00AA0.080.002	SEPAR - TC08-055	REFURB/REPLACE	2	0
5	OMS	GN2 RELIEF VLV RV001	TBD			
		1186804-39				
		C00AA0.090.010-B	SEPAR - TBD	REMOVE/REPLACE	2	0
6	APU	APU 1, 2 & 3	V5U01.XXX			
	e.	MC201-0001-0610				
		C00AA0.090.020, 022 & 024	SEPAR - TBD	RETEST/RECERT	2	0
7	APU	CONTROLLER APU #1 - 3	V1019			
		MC201-0001-1005				
		C00AA0.090.026, 028 & 030	SEPAR - TBD	RETEST/RECERT	2	0
8	APU	HEATERS & THERMOSTATS APU #1 - 3	V1019			
		MC363-002X				
		C00AA0.090.032, 034 & 036	SEPAR - TBD	RETEST/RECERT	2	0
9	APU	FUEL ISOLATION VALVE APU #1 - 3	V1019		77.57	
	10	V070-465238-00X				
		C00AA0.110.032	V5032.004	REMOVE/INSTALL	2	0
10	PYRO	NASA STANDARD DET.	V5029.001			
	and the statement of	SEB26100094-201	a service and a			
		C00AA0.110.033	V5032.004	REMOVE/INSTALL	2	0
11	PYRO	CARTRIDGE	V5127			
	96 96 258C 621	SKD26100098-301	WOORN STANISH			

Constraints

1=ET/SRB MATE 3=VAB ROLL 2=OPF ROLL 4=LAUNCH

OV-104 FLT-31, STS-128

VEHICLE LIMITED LIFE STATUS REPORT

PRELIMINARY SUBMITTED 08/08/2008

		C00AA0.110.034	V5032.004	REMOVE/INSTALL	4	0
12	PYRO	AFT ATTACH BSTR CART.	V5029.001			
3335-02	8 8 88 88	SKD26100099-401	THE TRANSPORTS AND ENGINEERING TO SERVICE			
		C00AA0.110.035	V5032.004	REMOVE/INSTALL	2	0
13	PYRO	NLG THRUSTER CART.	V5127			
V	W W 35 0	SKD26100100-301	AMERICAN STREET			
2		C00AA0.110.043	V5056	INSTALL	4	0
14	PYRO	GAS PRESS CTG.				
		SEB26100001-25X				
		C00AA0.115.001	V5012.001	REMOVE/INSTALL	4	0
15	PYRO	GAS SAMPLER BATTERY	V5029.004			
		SED33101116-321				
		C00AA0.140.004	S0007	TEST	4	0
16	INS	MADS TAPE RECORDER	V1200			
		ME435-0055-0003 THRU 0005	V1248			
	2	C00AA0.160.001	V5A71	R/R BATTERIES EVERY 12 MONTHS	4	0
17	COM	GPS RECEIVER (GPS MAGR'S)	SEPAR-TBD			
G.	s	MC478-0153-0001	<u> </u>			
		C00AB0.010.003	V1165.003	REMOVE/INSTALL	2	0
18	MEQLG	NLG TIRE	V1165.004			
	s	MC194-0007-0006 (2)	8			
CHING	abornació - com pager taco - areas	C00AB0.010.004	V1165.001	REMOVE/INSTALL	2	0
19	MEQLG	MLG TIE BOLTS & NUTS	V1165.002			
		MC621-0051-0038 (4 WHEELS)				
50000	19707-1970/00 1970	C00AB0.010.005	V1165.001	REMOVE/INSTALL	2	0
20	MEQLG	MAIN WHEEL ASSEMBLY	V1165.002			
		MC621-0051-0038 (4)	Company of Company Com		1910	
	97501_20020701 TV	C00AB0.010.006	V1165.003	REMOVE/INSTALL	2	0
21	MEQLG	NOSE WHEEL ASSEMBLY	V1165.004			
		MC621-0050-0004 (2)			70.27	
	1200 2001	C00AB0.160.020A	TPS-TBD	REMOVE/REFURB/INSTALL	4	M
22	PLM	VIDEOSPECTION CAMERA ASSY				
		SED39125120-310				

Constraints
1=ET/SRB MATE 3=VAB ROLL
2=OPF ROLL 4=LAUNCH

OV-104 FLT-31, STS-128

VEHICLE LIMITED LIFE STATUS REPORT

PRELIMINARY SUBMITTED 08/08/2008

		C00AB0.160.021	SEPAR - TC08-016	REMOVE/REPLACE	2	0
23	INS-MW	MICRO-WIS SGU ASSY	TBD			
		IVC911001-301				
		C00AB0.170.001	V5139.001	REMOVE/INSTALL	2	0
24	TPS	RCC ARROWHEAD PLATE	V5139.002			
		MC621-0007-7009				
		C00AB0.170.002	V5139.001	REMOVE/INSTALL	2	0
25	TPS	RCC ARROWHEAD PLATE	V5139.002			
		MC621-0007-7010				
		C00AB0.180.527A	SEPAR - TC07-013	REMOVE/REPLACE	2	0
26	STR	LOWER GAP SEAL INSULATOR	EXCEPTION - EK10575R1			
		V070-199843-002				
		C00AB0.230.100	SEPAR - TBD	RECERT/VERIFY WEIGHT	2	0
27	ECLSS	AVIONICS BAY FIRE EXTINGUISHERS	V1042.002			
	8	MC282-0065-0001	1/5000 00 4	DEMONIE (NICTAL)		
00	DVD0	C00AD0.030.009	V5032.004	REMOVE/INSTALL	2	0
28	PYRO	SPHERICAL BEARING ASSY	V5127			
		V070-562036-002 C00AD0.030.012	\(\(\in \) \(\)	REMOVE/INSTALL	2	0
200	DVDO	PYRO CENTERING MECHANISM	V5032.004	REMOVE/INSTALL	2	0
29	PYRO	SKD26100098-501	V5127			
		JSC24937 30	SEPAR - TC08-083	REMOVE/REFURBISH/INSTALL	2	М
30	PLM	PORTABLE FOOT RESTRAINT ASSY	TPS-TBD	REMOVE/REPORBISH/INSTALL		IVI
30	FLIVI	SED33105308-307	169-100			
	to .	JSC24937.36	SEPAR - TC08-084	REMOVE/REFURBISH	2	M
31	PLM	HIGH-STRENGTH BRIDGE CLAMP FITTING	TPS-TBD	THE WOVERNER ON BIOTT		101
0,	, ivi	SED33107177-305	11 0 1 00			
		JSC24937.45	SEPAR - TC08-081	REMOVE/REFURBISH	2	М
32	PLM	EVA SLIDEWIRE SUBASSY	TPS-TBD			,
	. =	SED33103377-311	1000 074 d 55.54)			
		JSC24937.53	SEPAR - TC08-082	REMOVE/REFURBISH/INSTALL	2	М
33	PLM	ERCM SAFETY TETHER (2)	TPS-TBD			
1970/98	5 = 1855TO	SED33105087-315	CHORN AN IN SECURIS			

Constraints
1=ET/SRB MATE 3=VAB ROLL
2=OPF ROLL 4=LAUNCH

OV-104 FLT-31, STS-128

VEHICLE LIMITED LIFE STATUS REPORT

PRELIMINARY SUBMITTED 08/08/2008

		JSC24937.56	TPS-TBD	REMOVE/INSTALL	4	М
34	FCS	EMER EGRESS SLIDE SYS				
		MC623-0015-0023				
		V05AA0.030/050	SEPAR - TBD	REMOVE/REPLACE	2	0
35	PVD	WCCS CHECK VALVES	V1076.XXX			
		ME284-0438-X113				
		V61AIL.010-C	TPS-TBD	INSTALL AT PAD	4	0
36	ECLSS	LIOH CANNISTER				
		MC621-0008-0409				
		V61AIL.015-C	TPS-TBD	INSTALL AT PAD	4	0
37	ECLSS	HYDRAZINE (CO RMVL CART.)				
		MC621-0008-0060				
		V61AIL.016-C	TPS-TBD	INSTALL AT PAD	4	0
38	ECLSS	ATCO CARTRIDGE				
		MC250-0024-0001				
	8	V61AJ0.141	V1053.010	RECALIBRATE SENSORS AT PAD	4	0
39	ECLSS	PPO2 SENSOR				
2		MC250-0002-3165	6			
		V66AIL.060	TPS-TBD	REMOVE/INSTALL	4	M
40	FCS	POLE CREW ESCAPE SYS ASSY				
		SED27101375-322	5			
	\$200 BOOM A	V74AD0.130	OMI-TBD	PERFORM 15 MINUTE TEST	4	0
41	COM	MSBLS RF #1, 2 & 3	SEPAR-TBD			
		MC409-0017-0007				

Constraints
1=ET/SRB MATE 3=VAB ROLL
2=OPF ROLL 4=LAUNCH