



STS-129 Delta Launch Site Flow Review

Presenter Kenneth Nowak

06-25-09

Program Freeze Point

PRCB Presentation

S115129C





STS-129 Delta Launch Site Flow Review

Baseline the STS-129 Mission Specific Requirements and Flow Plans.

The STS-129 Integrated Launch Site Requirements were established by PRCBD S115129AR1 dated 04-16-09. This CR and the Associated Data Package were reviewed at the 06-22-09 FRWG.

	MO3/USA-PI
Requesting Approval	USA-OE
	USA-PI
Requesting Approval	<u>MP21</u>
ng	UB-R3
	PH-A
Status in BackUp	
	MK-SIO
	USA-FSW
	MV5
	XA
	<u>Requesting Approval</u> ng



SPACE SHUTTLE PROGRAM Space Shuttle Flight Operations and Integration Office NASA Johnson Space Center, Houston, TX



STS-129 Delta LSFR

PRCB

Mass Properties and Flight Requirements Status

Michael Darnell, Lead MIM Robert Reynolds, USA Flight Manager June 25, 2009







STS-129 DELTA LAUNCH SITE FLOW REVIEW

Presenter Michael Darnell

Date JUNE 25, 2009





ULF 3 Cargo Bay Layout

Page 4 of 122





Presenter Michael Darnell **STS-129 DELTA LAUNCH SITE FLOW REVIEW** Date JUNE 25, 2009 LAUNCH ORBIT 11/12/09 39A/ MLP 3 51.6 DEG **CREW SIZE: 6UP/7DN** 122 NM DIRECT INSERTION **DURATION: 11 + 1 + 2 DAYS** CONFIGURATION OV-104(31) CONSUMABLES LP04:RP01 ET-133 **CRYO TANK SETS** 5 (FULL) **BI-140 GN2 TANKS** 5 (FULL) **RSRM-108** FWD RCS 2175# (MIDPOINT) PROPOSED: (1) 2048 (2) 2044 (3) 2058 AFT RCS 4970# (FULL) **OI-34** 22760# (FULL) OMS SRMS.ODS.OBSS LANDING PAYLOAD KSC SITE **ISS-ULF3 ISS-ULF3** ΤΔΙ ZARAGOZA (ELC1, ELC2, MAUI ALT. TAL **MORON & ISTRES** SASA, MISSE 7A, SEITE SCA 911 SIMPLEX MISSE 7B) **RAMBO-2**

FDRD UPDATE REQUIRED TO MANIFEST SSME'S





STS-129 DELTA LAUNCH SITE FLOW REVIEW Presenter Michael Darnell Date JUNE 25, 2009

PERFORMANCE MARGIN

•	SIMULATION MARGIN (OCFAF129)		+2184
•	OPERATOR CREW COMPARTMENT RCS MPS PROP RECONSTR ASCENT PERF COLLECTOR	182 - 274 - 4 - 263 - 260 <u>- 94</u> -517	- 517
•	OTHER PERFORMANCE PROJECTIONS PROTECTION FOR DOL DISPERSIONS USABLE IMPULSE FOR MPS BGT GEN0901S SRB – M.P. UPDATES SRB – BR / 2.40 MIL HIGHER THAN 0.3705 AVG ISP/THRUST FOR GENERIC BLOCK 2 @ 104.5% PROJ TO 5 MIN WINDOW FROM INPLANE PERFORMANCE CHANGES ADJUSTMENT		- 700 - 17 - 184 +480 +6 - 600 <u>+36</u>
•	CURRENT BASELINED APM (06/16/09) ISP/THRUST FOR SSME 2048, 2044,2058 		+ 688 <u>- 63</u>
•	PROJECTED APM		+ 625

VOLUME III: ASCENT PERFORMANCE MANAGER'S RESERVE GUIDELINE AT LSFR IS 400 LBS

STS-129 DLSFR OV-104 FLIGHT 31 CONFIGURATION UPDATES PRCB

Joe Rodriguez USA / VM

Elena Seastrom Boeing / VPE

June 25, 2009





STS-129 OV-104 Flight 31 – DLSFR Updates

Program Authorization Is Requested For The Following:

- Partial Modification Deferral
- MECSLSI Updates
- Mission Equipment Changes

Information Only:

- Potential Modification
- Summary of Previously Authorized Modifications
- Wing Leading Edge (WLE) Spar Inspection Status
- Chits
- TPS Priorities List / Current Status

Back-up:

- Modification Records and MECSLSI Updates Summary
- Engineering, Hardware and Certification Status
- Description of Previously Authorized Modifications
- TPS Allocation Breakdown





STS-129 OV-104 Flight 31 – Partial Modification Deferral

MCR 19393 – Air Duct Clamp and Cushion Modification Deferral

- Program approval is requested to partially defer baselined modification record until access is available for implementation
 - Mod record VK70-613604-001,0104,0 for avionics bay 3A duct orifice modification baselined at the LSRR includes three configuration changes in bays 1 and 2 for which access is not planned during the flight 31 flow
 - 1) Clamp missing from flex duct
 - 2) Two cushions installed but not shown on the drawing
 - 3) Two cushions installed per drawing, but installation documentation not located
 - Items 1 & 2 were noted during flight 27 flow routine inspection and PR EOTF ECL-4-27-1354 was written to correct the engineering discrepancies
 - Deferral to next available access approved per MR ECL-4-A0093
 - Item 3 was noted during flight 31 flow engineering evaluation and will be documented on PR ECL-4-A0093
 - Current access does not allow part number verification; MR acceptance rationale is in work






STS-129 OV-104 Flight 31 – Partial Modification Deferral

MCR 19393 – Air Duct Clamp and Cushion Modification Deferral (Cont.)

• Items 1 & 2:

- During flight 27 flow routine inspection, it was found that a clamp was missing from a flex duct, and that two cushions were installed but not shown in the drawings
- Engineering evaluation determined that the system will perform properly in this configuration, and the missing clamp and cushion installations were accepted by MR and deferred to the next OMDP or TACAN and MSBLS decoder removal







Avionics Bay 2 Ducting






STS-129 OV-104 Flight 31 – Partial Modification Deferral

MCR 19393 – Air Duct Clamp and Cushion Modification Deferral (Cont.)

- Item 3:
 - During flight 31 flow engineering evaluation for the avionics bay 3A modification, two cushions in bays 1 and 2 were noted, for which installation documentation could not be located
 - Current access does not allow part number verification
 - PR/TPS generation and MR acceptance rationale in work



Avionics Bay 1 Ducting

Avionics Bay 2 Ducting





STS-129 OV-104 Flight 31 – MECSLSI Updates

• Update the V072-200209 MECSLSI with the following tech order changes:

- GN2 Purge Line Installation

- Add M072-634545-002 (Mission Kit MV0727A)
 - Originally required for STS-125 HST mission to provide GN2 purge line to the Super Lightweight Interchangeable Carrier (SLIC) and the Orbital Replacement Unit Carrier (ORUC); Remains installed on the vehicle after HST service missions because the installation is below the payload bay liner

- Beam, Harness Routing, ODS Bay 2

- Remove M072-340175-001 (Mission Kit MV0828A)
 - Associated with the Station to Shuttle Power Transfer System (SSPTS) modification which was not implemented on OV-104 (paper only)






STS-129 OV-104 Flight 31 – Mission Equipment Changes

TAD 30010 - Starboard and Port Lightweight TSA Cushions

- Provides new cushions for the port and starboard Lightweight Tool Stowage Assembly (LWTSA) to accommodate additional tools that will remain on ISS
 - M072-660853-008 LW Port TSA tool stowage cushion and M072-660857-001 LW Starboard TSA have been incorporated into the MECSLSI
 - Requires authorization of the TSA modification record 030010,0104,5





STS-129 OV-104 Flight 31 – Mission Equipment Changes

- The following tech order change has been incorporated into the MECSLSI – tech order change is for information only:
 - RMS End Effector Configuration Change
 - Requires authorization of RMS End Effector configuration change MRCS record TCTIM0017222REF, 0006, 4
 - Tech Order M072-544502-036 Remote Manipulator Arm Installation






STS-129 OV-104 Flight 31 – Potential Modification

TAD 30260 – FRCS Rain Cover Redesign In-Throat Concept

- Develops a new Tyvek Rain Cover for the FRCS thruster positions F3D and F4D to prevent tearing/partial cover release during launch
 - Partial release of the FRCS thruster cover occurred on several Shuttle missions
 - During STS-119, the remnant was estimated from imagery to be 6-10 grams which was larger than remnants from previous flights
 - New cover concept, Rain Cover Plug (RCP), will replace the existing thruster covers at the positions F3D and F4D with smaller covers installed deeper in the thruster



 OCCB recommendation was to evaluate modifications to the current design vs. the RCP concept, and recommend the option which will best mitigate the risk for STS-129; Plan to return to OPO early June 26th





6-25-09

STS-129 OV-104 Flight 31 – Previously Approved Modification

The following modifications have been previously baselined

- TAD 30240 / MCR 19393 - Middeck ISS Payload Cooling Requirements

 Installs resized orifice in the ducting to middeck avionics bay 3A to provide sufficient airflow to cool the ISS payload

- TAD 30231 - Rudder Speed Brake Inconel Thermal Barrier Redesign

 Installs redesigned Rudder Speed Brake inconel thermal barrier tabs to improve strength of the tab attachment

- TAD 30250 - Oxygen Crossover Valve Signal Talkback Modification

 Modifies Orbiter electrical configuration for the O2 crossover valves to provide valve position indication

- TAD 30099 - Relocation of D-Hatch Actuator Handle Position Decal

 Relocates actuator handle position decal on the external airlock upper hatch to the correct location

- TAD 30099 - External Airlock Ducting Configuration Change

• Connects the Orbiter Docking System booster fan outlet duct prior to launch to have the airlock fan active from post-insertion through de-orbit preparation





STS-129 OV-104 Flight 31 – Previously Approved Modification

The following modifications have been previously baselined (Cont.)

- TAD 30186 OMS Pod Micro-WIS Strain Recorder Removal
 - Removes the recorder box from the left OMS Pod and stows the wires

- TAD 23205 - Acreage Doublers Addition to Avionics Bays 4, 5 and 6

 Installs cold bonded protective doublers to the honeycomb facesheet on the aft avionics bay 4, 5 and 6 doors to provide additional resistance to impact loads and ensure life of honeycomb panels (Authorized as Non Flight Specific)





STS-129 OV-104 Flight 31 – Information

Wing Leading Edge (WLE) Spar Inspection

- Structural inspections of the Wing Leading Edge spars are due prior to the last manifested flight of OV-104 (due date January 22, 2010)
 - Performance of these inspections is intrusive and classified as a significant flow impact. 16 panels per wing remaining to be inspected. PRT's position is full compliance with the requirement is required prior to 1/22/10
 - Last WLE spar full inspection on OV-104 was performed in July 2003; Prior OMDP inspections were performed in December 1997
 - Coating system refurbishment and re-performance of structural inspections was to be accomplished at the next OV-104 OMDP which was to occur prior to flight 29
- OPO recommended performing WLE spar inspection of 6 panels per wing during STS-129 flow
 - The current GO plan is to perform inspection of 4 panels per wing this flow
 - WLE Spar Inspection Requirement was briefed to the Launch Integration Manager on 4/8/09 and he concurred with the existing requirement to complete the full inspection prior to January 2010
 - Following the inspection this flow, OPO will review the results of all inspections performed to date on the OV-104 WLE spar in order to determine if an exception to the requirement is warranted. Plan is to report back to the Daily PRCB
- Exception and Program accepted risk would be required if inspections are not performed in full prior to January 22, 2010



6-25-09



CHIT	TITLE
J6116	AMES GAP FILLER REMOVAL AND REPLACEMENT
J6275A	ORBITER STRUCTURE IML SURFACE CORROSION SAMPLING INSPECTION
J6327	WLE RCC JOGGLE INSPECTION
J6378	OV-104 BODY FLAP (BF) POWER DRIVE UNIT (PDU) GEARBOX FLUID LEVEL INSPECTION
J6380	EVA PDU TOOL INTERFACE VERIFICATION
J6389	CLOSE CLEARANCE MEASUREMENTS OF ORBITER HARDWARE FOR STS-125 (post flight)
J6399	0-GAUGE PROTECTION FOR OV-103 FLIGHT 32-35 AND OV-104 FLIGHT 27-35
J6402	MICRO INSPECTIONS OF CAPTIVE GAP FILLERS
J6407	CLOSE CLEARANCE MEASUREMENTS OF SRMS MPM AND OBSS
J6410	AFT STUB CRACKED TILE INSPECTION
J6414A	RUDDER SPEED BRAKE THERMAL TAB INSPECTION
J6447	STS-126 POST FLIGHT INSPECTION AND CONTAMINATION SAMPLING OF LASER CAMERA SYSTEM AND ORBITER LOCATIONS
J6466	OMS POD PILLOW GAP FILLER INSTALLATIONS
J6481	MIDDECK PAYLOAD COOLING TEST FOR OV-104
J6497	OV-104 PUTTY REPAIR RCC AND WINDOW DTA
J6501	STS-129 CIH CLOSE CLEARANCE MEASUREMENTS
J6506	CAPTURE OV-104 OUTPUT WAVEFORMS TO ADDRESS IN3600 DIODE CONCERNS





Chits (Cont.)

CHIT	TITLE			
J6512	OV104 EVA SCU CHANGEOUT			
J6513	X-RAY INSPECTION OF MPS HELIUM SUPPLY SYSTEM CHECK VALVE CV4 ON OV-103 (STS- 128) AND OV-104 (STS-129)			
J6516A	WLE JOGGLE REGION IR THERMOGRAPHY REQUEST FOR HIGH LINE SCAN WF PANELS			
J6524	KU-BAND PL MAX MODULATION TESTING FOR OV-104			
J6525	PERFORM LEAK CHECK OF MPS LO2 OVERBOARD BLEED VALVE (PV19) AND T-0 QD (PD13) ON OV-103 (STS-128) AND OV-104 (STS-129)			
J6527	FRCS THRUSTER CANISTER STUD INSPECTIONS - F5R AND F5L (in review)			
J6528	PUTTY REPAIR TILE REPLACEMENT FOR RISK REDUCTION (in review)			
J6529	OV-104 OMS VAPOR ISOLATION VALVE CHECKOUT (in review)			
J6530	OV-104 ORBITER WIRE/CABLE INSPECTION DURING FLOW 31 (in review)			
J6533	PERFORM BORESCOPE INSPECTION OF MPS INBD RTLS DUMP VALVE (PV17) BALL SEAL ON OV-104 (STS-129) (in review)			





Potential Chit

• W2 and W5 Vespel window fastener preflight torque evaluation

- Pending post-flight measurement of prevailing torque on OV-105 multi-flight windows
 - W1 and W6 which were torqued at the pad prior to their first flight, and previously flown W3, W4, or W5
 - Adverse finding would raise new concern for OV-104's multi-flight mod locations and lead to request to retorque
 - OV-105 measurements expected in the August timeframe





TPS Priorities List

Mandatory (everyflow expectation)

Flight damage, OMRS Rgmts/Chits, LRU access, & deferred work

Multi-flow

- Corrosion Sampling (10% of total tile allocation) Chit J6275A
- Chits
 Putty repairs in RCC & Window DTA Zones of influence (10 tiles)
 Continue G/F R & R on a best effort basis zones 2B subset

 - Deferred work may be redeferred with acceptable inspection

Prioritized Opportunity

- 1 5 1 thru 5 complete on all vehicles
 - 6 BRI-18 Tile – STR side of ET Doors Inboard side – AFT 4 Tiles (8 Tile)
 - 7 Inboard Elevon "Hub" Tile Modification – 104 only remaining (4 Tiles)
 - 8 I/B Elevon 91b/90 SIP Upgrade to FRCI-12 – AFT to FWD, 34 Tiles (17/side)
 - O/B Elevon 9lb/90 SIP Upgrade to FRCI-12 6 Tiles (3/side) 9
 - 10 MLGD – Outboard Middle 1/3 - (6 Door/6 STR)



TPS Priorities List (Cont.)

- 11 ET Door Remaining STR side of Door & leading edge on Door 40 tiles (24 STR/ 16 door)
- **12 MLGD** Outboard AFT 1/3 24 Tile (6 door/6 str)
- 13 Nose Area 9lb/90 SIP Upgrade to FRCI-12 14* Tiles (7/side) (*103 16 tiles, thruster)
- 14 Base Heat Shield 9lb/90 SIP Upgrade to FRCI-12 42 Tiles (32/stinger, 10/Box Attach point)
- NEW Body Flap Stub "Piano Key" Upgrade to AETB-8 42 Tile (Order will be provided)
 - **15** Gap fillers in Subset 2B (Line across MLGD edge)
 - 16 Remaining BRI-18 Tile Remaining MLGD (top priority) / ET Door / LESS carrier panels/NLGD MLGD (Inboard, forward edge working to AFT door edge) ET Door LESS - panels 8, 9, 10, 7, 6, 5, 4, 3, 2, 1, 11, 12, 13 (in that order) NLGD (attrition – do leading edge first)
 - **17 Mod work** (WLE sneak flow, WLE Horsecollar Gap Fillers,)
 - **18** MADS Instrumentation Failures (104 & 105 L/H OMS Pod)(place holder)

19 Remaining Gap Fillers & Window BRI-18

Windows 2, 3, 4, & 5 Upper Carrier Panels (top priority)





STS-129 ISS-ULF3 ELC 1, ELC2, MISSE 7A & 7B, SASA Delta Launch Site Flow Review

Payload Cargo Engineering Status

Yvette Carmona 281-212-6492 06/22/09



P:\Payload_Cargo\Reconfiguration Engineering\STS-129

Engineering Flight Product Status

Drawing No	<u>Title</u>	<u>Rev</u>	EO	Released
V072-200209	MECSLSI	Α	A01	04/21/09A
VA72-200209	Cargo Arrangement	Basic	-	01/15/09A
VD72-200209	Avionics Diagram	Α	A01	04/22/09A
VS72-200209	Integrated Schematic	Α	A01	04/22/09A
VS70-540403	Retention Schematic	Α	A02	04/24/09A

FRED Release was completed on 04/27/09

Engineering Open Work

• ELC MGSE Design Incorporation

Standardization

• Mission Configuration does comply with Orbiter/Payload Integration Standardization Document, NSTS 60523



OMRS Status

ECD

06/30/09

Baselined Files

- P545 ISS-ULF3
- P548 MISSE 7

Open Work

- RCNs
 - FII, V2 Post Mate
 - PP17979R1 P545 MDS Fit Check & GLACIER IVT 06/16/09
 - FII, V4 Pre-Mate
 - PS17981 S07 RH/LH ROEU Test Dual Configuration 06/23/09
 - PS17964 S07 STS-129 F2/V4 Mission Unique List 07/07/09
 - PS17960 S07 STS-129 FIII Mission Unique List
 - PS17971 S07 STS-129 Adjacent Bent Pin Test 06/30/09
 - FII, V6 Shuttle Experiments
 - None

Issues/Concerns


• None




Cargo Close-Clearance Process

The following Close-Clearance areas have been identified:

- Starboard ROEU-to-stabilizer link bolt
 - 0.45" static, 0.26" dynamic
 - As-installed OPF measurements required
 - Chit J6501 approved 05/04/09
- Latch at X_o 892 and MPM wiring (port and starboard)
 - 0.45" static (approx) when latch travels full aft
 - Measurement not required
 - Re-dress of MPM cabling may be required if potential for contact
- Potential: MPM and scuff plate at X_o 1242
 - Less than 3" static, but currently >1" dynamic
 - As-installed measurement only required if VLA shows less than 1" dynamic (ECD: 08/03/09)







Cargo Integration Hardware Status

Delivery Status

- ROEU Cable Harnesses (Re-Make)
 - Cables returned to vendor for re-braiding
 - Hardware Delivery Date: 06/30/09
 - Certification Approval Date: N/A
 - KSC Need Date: 06/18/09
- ELC Bond Straps and Attach Hardware
 - Hardware Delivery Date: 07/01/09
 - Certification Approval Date: N/A
 - KSC Need Date: 08/20/09



Atlantis STS-129 Delta Launch Site Flow Review

Space Shuttle Main Engine

SSME - KSC Paul Brzeski (321) 861-4064




Page 29 of 122

Pratt & Whitney Rocketdyne, Inc.



STS-129 Delta Launch Site Flow Review SSME Allocations / Locations



A United Technologies Company

Pratt & Whitney Rocketdyne, Inc.



STS-129 Delta Launch Site Flow Review SSME Planned Modifications

Mods authorized by Shuttle Project Action Request (SPAR) or Level II Change Request (CR)

ECP	Title	Engine(s)	Kit Drawing	Weight Impact	SPARs / CRs	Status
1543	Joint F3 (LPF Duct-to-HPFTP) Liquid Air Insulation Redesign.	2048 2044 2058	2R112834-010	+0.37 lbs	ME-0247 R01 ME-0251 B ME-0249 R01	Complete In-Work Complete
1544	Joint F5 (HPF Duct-to-MFV) Liquid Air Insulation Redesign.	2058	2R112835-010	-0.15 lbs	ME-0249 R02	In-Work





STS-129 Delta Launch Site Flow Review

Rocketdyne Action Requests (RAR)

RAR	Title	Engine(s)	SPARs / CRs	Status
KLO-1636	Inspect HPFTP Inlet Housing.	2048 2058	ME-0247 B ME-0249 B	Complete.
KLO-1639	Inspect HPFTP Inlet Housing.	2044	ME-0251 B	In-work, part of postflight STS-125 processing.








KSC International Space Station and Spacecraft Processing

ISS-ULF3 ELC1 ELC2 SASA MISSE-7


Scott Higginbotham / UB-R ULF3 NASA-KSC Mission Manager

June 25, 2009

ULF3 ELC1 / ELC2 Launch Configuration



ELC1 Configuration



Page 35 of 122

ELC2 Configuration

Top Side/Port Face



Keel Side/Starboard Face





ExPRESS Logistics Carrier 1 (ELC1)

- Assembly operations are continuing
 - Top side kinematic mount match drilling/PFAP installations are complete
 - Keel side kinematic mount match drilling/PFAP installations to begin in late June
 - Harness routing/securing is underway
- PCAS/ACAS test and "risk mitigation" avionics testing planned for late July
- Flight ExPRESS Carrier Avionics (ExPCA) delivery has been significantly delayed Not expected to arrive at KSC until mid-August

ExPRESS Logistics Carrier 2 (ELC2)

- Assembly operations are continuing
 - Keel side ORU Integrated Assemblies (TUS-RA, PMA, NTA) have been installed
 - PVGF installation is underway
 - Top side ORU Integrated Assembly installation to begin in early July
 - PCAS/ACAS test scheduled for late June
- Flight ExPRESS Carrier Avionics (ExPCA) delivery has been significantly delayed Not expected to arrive at KSC until mid-August
- Final integrated testing will occur following ExPCA arrival/installation





Orbital Replacement Unit (ORU) Integrated Assemblies (IA)

- Seven of fourteen ORU IAs have been completed thus far (NTA s/n 03*, LEE, ATA s/n 05, PMA s/n 05*, BCDU, TUS-RA*, CTC) [* installed on ELC]
- The seven remaining ORU IAs are in various stages of build-up
 - CMG s/n 102 ORU to FSE integration is nearly complete
 - HPGT ORU oxygen servicing is in work at KSC; FSE integration onto ELC2 is in work
 - NTA s/n 02 ORU nitrogen servicing is scheduled for July; FSE integration is complete
 - PCU ORU xenon servicing preps are underway in California; FSE build-up is in work
 - PMA s/n 07 ORU to FSE integration is in work
 - CMG s/n 104 ORU to FSE integration is in work
 - SASA ORU rework is underway; FSE integration is underway

Materials on International Space Station Experiment-7 (MISSE-7)

• Hardware arrived at KSC on 6/22 – Standalone assembly/test is underway





ELC1 / ELC2

•	ELC1 / ELC2 keels on dock KSC	26 June 2009
•	ELC2 ExPCA on dock KSC	mid-August 2009 (U/R)
•	ELC1 ExPCA on dock KSC	mid-August 2009 (U/R)
•	ELC deck to keel attachment MGSE on dock KSC	22 August 2009
•	ELC1 / ELC2 CEIT	TBD
•	ELC1 / ELC2 closeouts complete / Start of Shuttle Integration	TBD
•	ICD Walkdown	TBD
•	ELC1 / ELC2 weight and c.g. measurements	TBD
•	ELC1 / ELC2 canister installation	TBD
•	ELC1 / ELC2 canister rotation to vertical	TBD

Late ExPCA deliveries seriously threaten the planned 10/11/09 delivery of ELC1/2 to Pad A





Sidewall Payload/ORU

- MISSE-7 SWC/PEC transfer to OPF / installation into Orbiter
- SASA/FSE transfer to OPF / installation into Orbiter
- SASA/FSE to Orbiter IVT
- Orbiter CEIT

Integrated Operations

- ELC1 / ELC2 transfer to Pad A
- SSV transfer to Pad A
- ELC1 / ELC2 transfer into Orbiter
- ELC1 / ELC2 MGSE removal / ROEU mate / Bond strap instl
- ELC1 / ELC2 to Orbiter IVTs
- Flight Crew walkdown / Interim payload closeouts
- Interim payload bay door closure
- PCU valve closure (NET L-100 hours)
- Delta payload closeouts / Final payload bay door closure
- Middeck experiment late stow / Orbiter IVTs
- Launch

25-26 August 200927 August 200928 August 200911-12 September 2009

- 11 October 2009
 14 October 2009
 15 October 2009
 16 October 2009
 17 October 2009
 20 October 2009
 20 October 2009
 9 November 2009
 9 November 2009
 11 November 2009
- 12 November 2009

STS-129 Delta Launch Site Flow Review

June 25,2009

Page 41 of 122

Agenda

- Assessment/Multi Flow
- Milestone Interface Chart
- Flight Element Processing

- A. Brewer/NASA
- A. Brewer/NASA
- **R. Propst/USA**

Multi Flow A. Brewer

Page 43 of 122

A BASELINE MANIFEST (FDRD) / PREL. PROGRAM PLAN

KSC ASSESSMENT / ORB MULTI-FLOW

OPR: USA - R. GILLETTE, MFM NASA - C. FORD, PH-0


 \bigwedge KSC ASSESSMENT (SLIP or OPTION)


٢r

★ DENOTES CHANGES TO BASELINE MANIFEST

SSP APPROVED MANIFEST MANIFEST REF. 09B-1

1000 EDT, 19 JUN 2009





Flight Element Processing

Ray Propst

Page 46 of 122


Flight Element Processing Overview

- Milestone Summary
- Significant Processing Deltas
- TPS Status
- Issues and Concerns
- Integrated Assessment

To Be Presented To Be Presented To Be Presented To Be Presented

To Be Presented

STATUS




STS-129/OV-104 OPF FLOW MILESTONES

'DOWN PAYLOAD: HST / UP PAYLOAD: ISS-31-ULF3

Creation Date:21-JAN-2009 Revision Date:11-JUN-2009 Revision :F

> OFR: USA-PROPST, RAYMOND D NASA-BREWER, ANGELA J



Significant Processing Deltas

Major Components Removal / Replacements

- Windows 1 & 7
- Thruster R5R
- Fuel Cell #1
- ODS Reinstallation
- ASA #1 R&R
- WLE Corrosion Inspection RCC 13 16 L&R
- Elevon Cove Seal Leak Check (Flt 32 Get Ahead)

<u>MODS</u>

- Av Bay 3A Cooling Mod
- Complete WLE Sneak Flow Path Mod
- RSB Thermal Tabs
- O2 Crossover Valve Talkback Mod

TPS Work Content

TPS Removals

<u>Priority</u>	Description_	<u>LSFR</u>	<u>DLSFR</u>				
Mand	Deferred Tile/ Fib For 1 Flight (Minimum)	3	4				
Mand	In-flight Tile/Blanket Damage (Estimate)	25	40				
15	-Piano Key (Upper Body-Flap-14 Flight Tile)						
Mand	Estimated Putty Removals (Grindouts)	14	14				
Mand	Operational Damage (Estimate)	20	20				
Mand	Putty Repairs in RCC and Window DTA Zones	10	10				
Mand	I/B Elevon 9lb/90 SIP Tile Upgrade (14 To Go)	14	14				
Mand	Instrumentation	2	2				
13	Nose Area 9lb/90 SIP Tile Upgrade	14	14				
BRI Replacer	nent:						
6	ET Inboard Structure Side	7	7				
Projected TPS Removals TOTAL (Estimate) *109 *12							
	* Final TPS Work Content Will Be Baselined At The Del	ta LSFR					
STS-129 DLSFR J. F. KENNEDY SPACE CEI	Page 50 of 122						

TPS Work Content (Additional Work)

Planned Work:

- LESS access panels
 - Restricted work 17R/22R (1) panel
 - Complete Priority 17 Sneak Flow Mod on 2L/4R (2) panels
 - LH/RH RCC 13-16 R&R (24) panel removals
 - Chit J6327 T-Seals on 14/15R, 17/18R, 11/12L (4) panels
 - Post-flight discrepancies (Torque, Horsecollar, Etc) (5) panels


Total LESS panel removals to date= (36) (24 Lower/12 Upper)

Potential Work:

- RH S-Band (Potential 25-30 Tiles)
- AMES R&R Zone 29 of 2A (fwd of LH MLGD)
- Elevon cove access panel removals (Pending Elevon Cove leak checks)

Issues and Concerns

- Radiator Freon Control Valve
- S-Band Lower Right Antenna (Potential 25-30 Tile)
- Right OMS Nozzle
- TPS Work Volume
- ROEU Late Delivery
- Inner Window #5







STS-129 Delta Launch Site Flow Review

Presenter Kenneth Nowak

06-25-09

Backup Material

FRWG Presentation (With Minor Changes)





Presenter STS-129 DELTA LAUNCH SITE FLOW REVIEW Presenter Michael Darnell Date JUNE 25, 2009

Backup Charts

Page 55 of 122





Program STS-129 DELTA LAUNCH SITE FLOW REVIEW

MISSION INTEGRATION PLAN (MIP) REQUIREMENTS STATUS

OPEN CR's

PRCB CR's

None

- NSTS 21545 MIP CR's
 - MIP CR#0011 Remove O2 Transfer Requirement and Add CGBA Middeck payload to ULF3 (ECD 6/24/09)
 - MIP CR#0012 Add CERISE Middeck Payload to ULF3 (ECD 6/24/09)
- NSTS 21530 MAUL PIP CR's
 - None
- <u>NSTS 21542 SEITE PIP CR's</u>
 - None
- NSTS 21327 SIMPLEX PIP CR's
 - None
- <u>NSTS21556 RAMBO-2 PIP CR's</u>
- None
- Issues and Concerns
 - None





Program Presenter STS-129 DELTA LAUNCH SITE FLOW REVIEW Michael Darnell Date JUNE 25, 2009

STS-129 FRD Status

- STS-129 FRD Latest Revision: 005, dated May 29, 2009
 - Open CR's
 - None

Back-up

- Modification Record and MECSLSI Updates Summary
- Engineering, Hardware and Certification Status
- Description of Previously Authorized Modifications
- **TPS Allocation Breakdown**





Modification Records and MECSLSI Update Summary

MCR/ TAD NO.	TITLE	KIT / MOD RECORD & DESCRIPTION	TECH ORDER IMPACT	REMARKS				
Mission Equipment Records To Be Baselined								
30010	Starboard and Port Lightweight TSA Cushions Provides new cushions for the port and starboard Lightweight Tool Stowage Assembly (LWTSA) to accommodate additional tools that will remain on ISS.	030010,0104,5 - End Item Kit record	Port LW TSA Tool Stowage M072-660853-008 (is) M072-660853-004 (was) Starboard LW TSA Tool Stowage M072-660857-001 (is) M072-660854-001 (was) MV0849A	Tech Order changes are incorporated into MECSLSI				
17222	RMS End Effector Configuration Change*_ Incorporates design modification during the End Effector refurbishment.	TCTIM0017222REF, 0006, 4 - End Item Kit record	Mech Instl - Remote Manipulator Arm Instl M072-544502-036 (is) M072-544502-033 (was) MV0082A	Tech Order changes are incorporated into MECSLSI				
		Potential Modification						
30260	FRCS Rain Cover Redesign In-Throat Concept Develops a new Tyvek Rain Cover for the FRCS thruster positions F3D and F4D to prevent tearing/partial cover release during the launch.	TED	No Tech Order Impact	No MECSLSI Impact				
		Modification Previously Baselined						
30186	OMS Pod Micro-WIS Strain Recorder Removal Removes the recorder box from the left OMS Pod and stows the wires.	TCTIM0030186REF, 0003, 0 - Stows the remaining wire	Micro-WIS SGU on OMS Pod Installation M072-755111-002 (is) M072-755111-001 (was) MV0886A	Tech Order changes are incorporated into MECSLSI				
23205	Acreage Doublers Addition to Avionics Bays 4, 5 and 6 Installs cold bonded protective doublers to the honeycomb facesheet on the aft avionics bay 4, 5 and 6 doors to provide additional resistance to impact loads and ensure life of honeycomb panels.	<u>VK70-356734-001,0104,0</u> - Provides hardware for acreage doublers on honeycomb door panels	No Tech Order Impact	No MECSLSI Impact				
30240/ 19393	Middeck ISS Payload Cooling Requirements Installs resized orffice in the existing ducting to the middeck avionics bay 3 to provide sufficient airflow balance to cool the ISS payload.	VK70-613604-001,0104,0 - Installs resized orifice in 3 locations VK70-613604-002,0104,0 - Installs a new bracket to support installation of a new orifice K609-613004-001,0002,0 - Provides caps for the duct	Middeck Bay 3A Cooling Installation M072-613800-005 (CCCD) Avionics HX & Fan Installation M072-613999-002 (MECSLSI) MV0609A	Tech Order changes are incorporated into CCCD and MECSLSI				
30231	Rudder Speed Brake Inconel Thermal Barrier Redesign Installs redesigned the Rudder Speed Brake inconel thermal barrier tabs to improve strength of the tab attachment.	TCTIV2930231REF, 0104, 0 - Installs redesigned RSB inconel thermal barrier tabs	No Tech Order Impact	No MECSLSI Impact				
30250	Oxygen Crossover Valve Signal Talkback Modification Modifies Orbiter electrical configuration for the O2 crossover valves to provide valve position indication.	TCTIV7930250REF, 0104, 0 - Repins the connector at the N2/O2 control panel and reworks the MDM and signal conditioners in the avionics bay	No Tech Order Impact	No MECSLSI Impact				
30099	Relocation of D-Hatch Actuator Handle Position Decal Relocates actuator handle position decal on the external airlock upper hatch / blanket to the correct location.	TCTIM3330099REF, 0001, 0 - Relocates "Latched / Unlatched" decals on the airlock upper hatch TCTIM0030099REF, 0001, 0 - Relocates decal on the blanket	D-Hatch M072-593828-005 MV0828A Blanket M072-364828-004 MV0828A	Tech Order changes are incorporated into MECSLSI				
30099	External Airlock Ducting Configuration Change Connects the Orbiter Docking System booster fan outlet duct to the booster fan outlet prior to launch.	N/A	ISS Fan & Ducting M072-643402-011 MV0828A	Tech Order changes are incorporated into MECSLSI				





Engineering, Hardware and Certification Status

MCR/ TAD NO.	TITLE	Est. Engr Release (MM/DD/YY)	G.O. Engr Need (MM/DD/YY)	Est. Hdwe Delivery (MM/DD/YY)	G.O. Hdwe Need (MM/DD/YY)	MOD/CERT GO / NO-GO	CERT SUBMITTAL DATE	CERT APPROVAL DATE	CERTIFICATION CR / CAR (BOEING)	REMARKS
	Mission Equipment Records To Be Baselined									
30010	Starboard and Port Lightweight TSA Cushions Provides new cushions for the port and starboard Lightweight Tool Stowage Assembly (LWTSA) to accommodate additional tools that will remain on ISS.	8/25/09	8/25/09	8/25/09	8/25/09	GO	Submitted	6/30/09	25-849-660516-001P 16-25-849-660516-001P	OCR/D S165421
17222	RMS End Effector Configuration Change* Incorporates design modification during the End Effector refurbishment.	N/A	N/A	N/A	N/A	GO	N/A	N/A	N/A	*NASA GFE
	Potential Modifications									
30260	FRCS Rain Cover Redesign In-Throat Concept Develops a new Tyvek Rain Cover for the FRCS thruster positions F3D and F4D to prevent tearing/partial cover release during the launch.	9/24/09	9/24/09	10/15/09	10/15/09	TBD	TBD	TBD	TBD	
	Modifications Previously Baselined									
30186	OMS Pod Micro-WIS Strain Recorder Removal Removes the recorder box from the left OMS Pod and stows the wires.	Released	N/A	N/A	N/A	GO	N/A	N/A	N/A	OCR/D S164130N Baselined at STS-128 LSRR
23205	Acreage Doublers Addition to Avionics Bays 4, 5 and 6 Installs cold bonded protective doublers to the honeycomb facesheet on the aft avionics bay 4, 5 and 6 doors to provide additional resistance to impact loads and ensure life of honeycomb panels.	Released	N/A	Delivered	N/A	GO	N/A	N/A	N/A	Baselined as NFS at STS-128 LSRR Engineered for flight 30
30240 / 19393	Middeck ISS Payload Cooling Requirements Installs resized orifice in the existing ducting to the middeck avionics bay 3A to provide sufficient airflow balance to cool the ISS payload.	Released	N/A	Delivered	N/A	GO	Submitted	Approved Approved	22-613400-001N 14-22-613400-001N	OCCB approved 10/28/08 (S165384A) OCR/D S165384A
30231	Rudder Speed Brake Inconel Thermal Barrier Redesign Installs redesigned the Rudder Speed Brake inconel thermal barrier tabs to improve strength of the tab attachment.	Released	N/A	Delivered	N/A	GO	Submitted	7/14/09	07-290101-001S 18-07-290101-001S	OCCB approved 1/27/09 OCR/D S165399
30250	Oxygen Crossover Valve Signal Talkback Modification Modifies Orbiter electrical configuration for the O2 crossover valves to provide valve position indication.	Released	N/A	N/A	N/A	GO	N/A	N/A	N/A	OCCB approved 2/24/09 OCR/D S165404
30099	Relocation of D-Hatch Actuator Handle Position Decal Relocates actuator handle position decal on the external airlock upper hatch / blanket to the correct location.	Released	N/A	N/A	N/A	GO	Submitted Submitted Submitted Submitted	Approved Approved Approved Approved	Hatch Actuator CR# 28-593201-001T CAR# 12-28-593201-001T Hatch Blanket CR# 09-362000-001CJ CAR# 71-09-362000-001CJ	OCR/D S165361 approved
30099	External Airlock Ducting Configuration Change Connects the Orbiter Docking System booster fan outlet duct to the booster fan outlet prior to launch.	Released	N/A	N/A	N/A	GO	Submitted	Approved Approved	CR# 35-643500-002W CAR# 20-35-643500-002W	OCR/D S165375 approved





TAD 30240 / MCR 19393 – Middeck ISS Payload Cooling Requirements


- Installs resized orifice in the ducting to middeck avionics bay 3A to provide sufficient airflow to cool the ISS payload
 - The ISS payload, Mice Drawer System (MDS), is currently planned to be installed in middeck avionics bay 3A
 - The current Orbiter configuration does not provide sufficient airflow to accommodate rear breathing payload in the middeck avionics bay 3A
 - Modification, increases the airflow to this location, providing the capability for avionics cooling in support of the MDS
 - Bay 3A requires installation of a bracket in the duct to allow the installation of an upgraded orifice at GPC 3 location, and installation of an upgraded orifice at SSOR and C&W locations
 - OCCB approved the implementation of the modification for bay 3A for flight 31 on 10/28/08



6-25-0




TAD 30240 / MCR 19393 – Middeck ISS Payload Cooling Requirements (Cont.)








TAD 30240 / MCR 19393 – Middeck ISS Payload Cooling Requirements (Cont.)







TAD 30240 / MCR 19393 – Middeck ISS Payload Cooling Requirements (Cont.)








Page 64 of 122

STS-129 OV-104 Flight 31 – Modifications To Be Baselined

TAD 30240 / MCR 19393 – Middeck ISS Payload Cooling Requirements (Cont.)




6-25-09

Page 65 of 122

United Space Allianc

TAD 30231 – Rudder Speed Brake Inconel Thermal Barrier Redesign

- Installs redesigned Rudder Speed Brake inconel thermal barrier tabs to improve strength of the tab attachment
 - During STS-124 an inconel tab was seen floating away from the vehicle while on orbit
 - STS-126 post-flight inspection found 7 inconel tabs were missing, even though improved pre-flight ground inspection procedures were used
- The redesign effort will reduce the moment arm and stress to the spot welds, and will provide a secondary mechanical attachment
 - Redesign lengthens tab to reach screw, slides tab into spring by .70" (.30" overhang), includes more spot welds and changes the spot weld from Class "C" to Class "B" (additional quality control to ensure weld conformance)





6-25-09




TAD 30250 – Oxygen Crossover Valve Signal Talkback Modification

- Modifies Orbiter electrical configuration for the O2 crossover valves to provide valve position indication
 - The N2/O2 control panel supports O2 and N2 flow to the crew cabin and provides O2 to the crew Launch Escape Suits (LES) and airlock
 - The O2 crossover valves are required to be open to support crew breathing on the Advanced Crew Escape Suit (ACES)
 - Current Orbiter configuration provides only switch scan instrumentation which verifies power applied to valve but not position indication
 - O2 crossover valve failure closed could result in the loss of oxygen to LES
 - The O2 crossover valve position indication is provided at the N2/O2 control panel electrical connector
 - Connecting to the available N2/O2 valve position will provide a reliable method for verifying that the O2 crossover valve is open
 - Electrical modification requires repinning the connector at the N2/O2 control panel and reworking the MDM and signal conditioners in the avionics bay
 - Utilizes two existing spare MSIDs for valve position indication
 - The first implementation of the modification is planned for STS-128, OV-103
 - Implementation on STS-129, OV-104 is contingent upon sufficient slack in harness to allow repinning of connectors without removal of MO10W panel






TAD 30250 – Oxygen Crossover Valve Signal Talkback Modification








TAD 30250 – Oxygen Crossover Valve Signal Talkback Modification (Cont.)







TAD 30250 – Oxygen Crossover Valve Signal Talkback Modification (Cont.)






6-25-09




TAD 30250 – Oxygen Crossover Valve Signal Talkback Modification (Cont.)







TAD 30250 – Oxygen Crossover Valve Signal Talkback Modification (Cont.)










TAD 30250 – Oxygen Crossover Valve Signal Talkback Modification (Cont.)




Overview of N2/O2 Control Panel and MDM/DSC's Wire Modifications





TAD 30099 – Relocation of D-Hatch Actuator Handle Position Decal

- Relocates actuator handle position decal on the external airlock upper hatch to the correct location
 - The crew reported difficulty closing and latching the external airlock upper hatch during STS-124 (OV-103)
 - Attempts to position the actuator handle over the decal that indicated the correct "preclosing" position were unsuccessful, as a hard stop was encountered prior to reaching that position (Ref. PR MEQ-3-36-1710)
 - When D-hatch was designed in 1982, the decal was inadvertently located in original A/B-hatch position (20 degrees from fully unlatched)
 - The D-hatch installation drawings are updated to reflect the correct decal locations








TAD 30099 – External Airlock Ducting Configuration Change

- Connects the Orbiter Docking System booster fan outlet duct prior to launch to have the airlock fan active from post-insertion through de-orbit preparation
 - MOD has indicated that future missions will not require the cryo savings associated with use of the booster fan bypass duct
 - The new duct configuration will reduce crew setup activity associated with booster fan operations
 - The mylar tape will not be required around the forward middeck floor diffuser; eliminating a crew procedure to remove the tape seal which can be misplaced during the mission
 - The option to fly the booster fan bypass duct will still be available




Airlock Booster Fan and Ducting Stowed for Launch (Current Configuration) Airlock Booster Fan and Ducting in Active Booster Fan Arrangement for Launch (Proposed Configuration)





TAD 30186 - OMS Pod Micro-WIS Strain Recorder Removal

- Removes the Micro-WIS Strain Gage Unit (SGU) from the left OMS Pod due to the expired certification
 - The Strain Gauge Unit was installed to obtain environment data for analysis of harmonics observed on STS-100 (OV-105) launch video and was certified for four flights
- Tech order M072-755111 was updated to -002 and added to the MECSLSI







MCR 23205 - Acreage Doublers Addition to Avionics Bays 4, 5 and 6

- Installs cold bonded protective doublers to the honeycomb facesheet on the aft avionics bay 4, 5 and 6 doors to provide additional resistance to impact loads and ensure life of honeycomb panels
 - Numerous dents and damages to the avionics bay 4, 5 and 6 doors occur during routine ground processing
 - Large PRACA history on honeycomb dents requiring MR doubler installation
- Protective doublers over the entire acreage will prevent future damage and work stoppage during damage assessment and repair effort





TPS Priorities / Current Status

Priority Number	Total	OV-103	OV-104	OV-105
1. BRI-18 Tile - MLGD FWD O/B Corner	28	complete	complete	complete
2. BRI-18 Tile - MLGD FWD Edge	22	complete	complete	complete
3. BRI-18 Tile - MLGD O/B Side	18	complete	complete	complete
4. BRI-18 Tile - STR side of ET Doors	20	complete	complete	complete
5. BRI-18 Tile – LESS Carrier Panels 8-10 (103 & 104)	24	complete	complete	n/a
6. BRI-18 Tile – STR side of ET Doors I/B	8	complete	1	complete
7. Inboard Elevon "Hub" Tile Mod	4	complete	2	complete
8. I/B Elevon 9lb/90 SIP	34	complete	20	complete
9. O/B Elevon 9lb/90 SIP	6	complete	complete	complete
10. MLGD – Outboard Middle 1/3	24	0	0	3
11. ET Door remaining STR side	40	1	7	0
12. MLGD - Outboard AFT 1/3	24	0	0	1
13. Nose Area 9lb/90 SIP	14 (16 ^{OV103})	2	0	0
14. Base Heat Shield 9lb/90 SIP	42	8	complete	complete
15. Gap fillers in Subset 2B	5 Zones	2	1	0
	MLGD 100	MLGD 0	MLGD 1	MLGD 0
16. Remaining BRI-18 - MLGD (top priority) / ET / LESS	NLGD 123	NLGD 12	NLGD 19	NLGD 47
carrier panels / NLGD	LESS 68 (92 ^{OV-105})	LESS 7	LESS 5	LESS 19
	ET Door 28	ET Door 5	ET Door 0	ET Door 1
17. Mod work LESS internal	44 locations	40	complete	complete
19. Remaining Gap Fillers & Window BRI-18	124	2	2	19



TPS Priorities / Top Five Complete


These items have been completed on all Vehicles

- 1. BRI-18 Tile MLGD (28 tile)
 - 1st subset fwd & o/b corner 14/door
- 2. BRI-18 Tile MLGD FWD Edge (22 tile)
 - 2nd subset fwd & o/b sides 11/door
- 3. BRI-18 Tile MLGD O/B Side (18 tile)
 - 3rd subset O/B side 9/door outboard side
- 4. BRI-18 Tile STR side of ET Doors (20 tile)
 - 4th subset ET doors 10/door
- 5. BRI-18 Tile LESS Carrier Panels 8-10 (24 tile)
 - 5th subset LESS hot panels 12/side
 - OV-103 & OV-104 only



6-25-09

TPS Priorities / Allocation Breakdown



- Orbiter's expectations for the work areas are shown on the pie chart
 - The above table is for reference only exact #'s are determined by the KSC Team
 - Access/configuration/length of flow
 - Distribution provides data/risk reduction in all areas of the list
 - · Does not allocate all the resources in one area
 - OV-104 to utilize this break down upon completion of priority numbers 6 & 8





6-25-09

Backup Charts



STS-129 DLSFR

Annex 1

Ba	selir	ed Files	Baselined				
•	ISS-	ULF3 MIP Annex 1	01/26/09A				
•	MISSE 7 PIP Annex 1						
<u>Op</u>	oen V	<u>Vork</u>					
•	ISS-	<u> ULF3 A01 – NSTS 21545</u>	ECD				
	_	Weight & Mass Properties Update	04/09/09A				
	—	Part Number Update	04/27/09A				
	-	Interim Update (includes: Mechanical & Electrical Drawings, ELC Keel Mass Properties, Grapple Fixture Data, Safety Critical Switch List)	06/30/09				
	_	L-4 Month Update	07/13/09				
		Customer input: ELC1 & 2 Functional Flow Diagram, ELC1 & 2 Electrical Schematic Diagram, ELC1 & 2 Safety-Critical Circuit Diagram	06/22/09				

Issues/Concerns

– None

TGHR Status

•	Customer	Submittal

- Release For Review
- Baseline
- No Issues/Concerns



07/13/09

08/12/09

09/11/09

STS-129 DLSFR

Payload ICDs/PIRNs

All Payload-Unique ICDs are baselined

PIRNS that Impact Flight Products

PIRN #	ICD/Payload	<u>Title</u> <u>ECD</u>	
A05744	ICD-A-21545-ELC1	Update Sec 3.0 Figures and Section 20	08/26/09
A05679	ICD-A-21545-ELC2	Update Sec 3.0 Figures and Section 20	06/18/09
A05751	ICD-A-21545-ELC1	ELC1 Update section 7, Elec. power	06/29/09
A05752	ICD-A-21545-ELC2	ELC2 Update section 7, Elec. power	06/29/09

Issues/Concerns

None


Rescue Flight Status

STS-129 Reconfiguration Engineering Products will be developed by the Engineering Order To Follow (EOTF) process.



BACKUP

Page 84 of 122



Page 85 of 122





Presenter Kenneth Nowak **STS-129 Delta Launch Site Flow Review** Date 06-25-09 **Overview** No Issues* **SSP System Drawings** • SSP Authorized Modifications/Non-Standard Work No Issues* • **To Be Presented** SSP OMRS Changes (RCNs) •





im	STS-129 Delta Launch Site Flow Review	Presenter MK-SIO / A. Swift	Swift
		Date	06-25-09

Mandatory RCNs:

KV17692V05 – WCCS SIDE/OVERHEAD DUAL DESC MOD6/26/09

Non-Mandatory Value Added RCNs:

OV17978 V74 – SENSOR PACKAGE 1 & 2 REQ DELETE PRELIM

STS-129 Delta Launch Site Flow Review Flight Software Overview

Judi Powell USA FSW FRWG 06/22/09 PRCB 06/25/09



STS-129 DLSFR (FSW)

- STS-129/OV-104 Flight Software (FSW) Versions
 - Second scheduled flight of Operational Increment (OI) 34 Flight Software (SASCB SCR 98107A documents PASS and BFS OI-34 content)
 - Second scheduled flight of MEDS IDP VI 07.00/MDUF VI 06.00 (SASCB SCR 98113 documents content)
 - Third scheduled flight of MAGRS-3S Link 613-996-008 Software (Link-008) (SASCB SCR 98115 documents content)
- STS-129/OV-104 Flight Software Payload/Vehicle Support:
 - ISS ULF3
 - Orbiter Interface Unit (OIU)
 - Sequential Still Video (SSV)
 - Orbiter Docking System (ODS)
 - Trajectory Control System (TCS)
 - ISS Caution and Warning (ISSCW)
 - Assembly Power Converter Units (APCUs) & Station to Shuttle Power Transfer System (SSPTS) (generic support for both configurations)
- Major New Flight Software Support Items:
 - None



STS-129 DLSFR (FSW)

- STS-129 Source Changes/Edits for Primary Flight Software (Base)
 - SCR 93211A Update of SSMEC Vehicle Data Table (VDT) for Enhanced Accelerometer
 - SCR 93262A Film ET Camera
 - SCR 93267A Removal of the Set and Reset to False Cmds For the RCS Tank Iso Valves
 - DR 126366 SM GPC Failure to Send GCIL Commands
- STS-129 Patch Implementation for Primary Flight Software
 - None
- STS-129 Patch/Edit Implementation for Backup Flight Software (Base) (included on delivered Mass Memory)
 - None
- STS-129 Patch Implementation for Backup Flight Software
 - None



STS-129 DLSFR (FSW)

- Products
 - STS-129/OV-104 Base delivery schedule (available to field)
 - FPSB
 - Shuttle Data Tape
 - Mass Memory Unit

March 10, 2009A March 30, 2009A

- An STS-129/OV-104 ADTL SDT will be required to support the O2 Cross Over Valve (PRCB CR S070006) FPSB
 - Shuttle Data Tape August 06, 2009
 - The ADTL Mass Memory is not be required.
- Open Items
 - Potential new requirements for an additional power safety inhibit to disconnect one or both of the Express Logistics Carrier (ELC)s from their associated Remotely Operated Electrical Umbilical (ROEU) (potentially implemented via a Payload Power Switching Unit (PPSU)).
 - Risk accepted by the Safety and FOICB boards so no change to the FSW is required
- Concerns/Issues
 - No issues or concerns with STS-129 at this time







Presenter MV6/Bill Lane Date June 25, 2009 Page 1

STS-129 DLSFR FCE/GFE Status

Page 92 of 122





- Except for RMS End Effector, need dates and delivery dates have been partnered. Delivery of modified RMS End-Effector is presently 5 weeks past KSC need date. Team actively working with MDA to refine delivery date.
- Tech orders and hardware list noted in backup charts, reference only
- Changes since STS-125:
 - Reconfigure from HST to ISS reinstall ODS mechanism, TCS, WVS antennas
 - NOTE: WVS antennas at Xo 1126 location (bay 10) not installed due to interference with ELC2 primary latches
 - OMS pod SGUs removal (end of certified service life)





- RMS End Effector (EE) Mod MDA Upgrading from -11 to -13:
 - Change the raybestos brakes/clutches to a ceramic material (since raybestos is no longer available)
 - Implement two design modifications to address issues that occurred on STS-103 (back-up release stall)
- OV-105 RMS EE was upgraded during STS-126 flow
- OV-103 RMS EE will be upgraded during STS-128 flow (EE S/N 403)
- OV-104 RMS EE will be upgraded during STS-129 flow (EE S/N 402)
 - EE S/N 402 will be upgraded following STS-119 and returned to KSC in August/September
- Tech Order M072-544502-036 reflects the new -13 EE configuration Page 94 of 122





Presenter MV6/Bill Lane Date June 25, 2009
Page 4

BACKUP



Masa

MV6/Bill Lane Date June 25, 2009 Page 5

Presenter

Tech Order numbers are identified for reference only. Report generated Jun-11-2009

Usedaaaa	Tech	KSC Eng	Eng(TO)		Cert	KSC	JSC	Quinning and a	JSC
Hardware	Order	Need	Release	In MEC	O/C	Need	Planned	Comments	Contact
A (port forward)	M072-750025-076	7/3/09	1/17/07	4/22/09	С	8/3/09	8/3/09	Camera/PTU from STS-127.	Randall Moore
B (port aft)	M072-750025-077	7/3/09	1/17/07	4/22/09	С	8/3/09	8/3/09	Camera/PTU from STS-127.	Randall Moore
C (starboard aft)	M072-750025-078	7/3/09	1/17/07	4/22/09	С	8/3/09	8/3/09	Camera/PTU from STS-127.	Randall Moore
D (starboard forward)	M072-750025-079	7/3/09	1/17/07	4/22/09	С	8/3/09	8/3/09	Camera/PTU from STS-127.	Randall Moore
SRMS elbow camera	M072-544504-014	7/3/09		4/22/09	С	8/3/09	8/3/09	Camera/PTU from STS-127.	Randall Moore
SRMS wrist camera	M072-544504-008	7/3/09	1/17/07	4/22/09	С	8/3/09	8/3/09	Camera from STS-127.	Randall Moore
Centerline Airlock Camera (stowed)	M072-660828-002, plus CCCD stow	1	3/17/99	4/22/09	С			Units last flown STS-127	Randall Moore
Lefthand Umbilical Camera (aft)	M072-705001-016	8/30/09	10/28/04	1/15/09	С	9/30/09	9/30/09	OPF Roll out planned for 10/07/2009.	Randall Moore
Righthand Umbilical Camera	M072-705001-028 M072-705001-027	8/30/09	10/28/04 10/28/04	4/22/09	С	9/30/09	9/30/09	OPF Roll out planned for 10/07/2009.	Randall Moore
Digital Television (DTV)	M072-710570-007	1	11/15/07		С			Installed Hardware	Larry Schmidt
MCIU/RMS Situational Awareness Display (RSAD)	M072-710543-001		3/7/00	1/15/09	С			Installed Hardware	Larry Schmidt
Tools for Rendezvous and Docking (TRAD)	M072-730021-019	7/13/09	7/20/07	4/22/09	С	8/13/09	8/13/09		Larry Schmidt
Video Processing Unit (VPU)	M072-710338-007		3/2/08	4/22/09	С			Installed Hardware	Larry Schmidt
L	4	-				400		-	





Presenter **MV6/Bill Lane** Page 6 Date June 25, 2009

Tech Order numbers are identified for reference only. Report generated Jun-11-2009

	Tech	KSC Eng	-		Cert	KSC	JSC		JSC
Hardware	Order	Need	Release	In MEC	O/C	Need	Planned	Comments	Contact
Wireless Video System (WVS)	M072-744007-001 UHF		6/2/04	4/22/09	0			Installed Hardware	Randall Moore
	M072-344828-001 mount								
	M072-744004-013 S-BAND								
	M072-744004-012 S-BAND								
	M072-744004-015 S-BAND								
	M072-744004-017 S-BAND								
	M072-744004-018 S-BAND								
Space to Space Orbiter Radio (SSOR)	M072-344828-002		9/24/04	4/22/09	С			Installed	Larry Schmidt
RMS Sideview Camera (RSC)	M072-710281-002	9/14/09	11/24/04	4/22/09	С	10/14/09	10/14/09	Camera from STS-128 after repressurization. SSV to	Randall Moore
	M072-000416-006 camera							PAD A 10/14/2009	
Wing Leading Edge (WLE) Instrumentation - Left Wing	M072-756111-007		8/21/07	4/22/09	С			Insatlled Hardware	Micheal Wright
Wing Leading Edge (WLE) Instrumentation - Right Wing	M072-756111-008		8/21/07	4/22/09	С			Installed Hardware	Micheal Wright
OBSS Sensor Package 2 *** (OPF)	M072-710282-006	7/17/09	4/18/08	4/22/09	С	8/18/09	8/18/09		Larry Schmidt
OBSS SENSOR PACKAGE 1 ** (OPF)	M072-710282-008	7/17/09	4/18/08	4/22/09	С	8/18/09	8/18/09	Same configuration as STS-127. S/N 1007 will fly.	Russell Yates
RMS-13 End Effector	M072-544502-036	7/13/09	D	4/22/09			9/22/09	The current plan is to swap the End Effector on OV-103 post STS-119 and return that End Effector back to MDA for upgrade and eventual use on STS-129. RMS guys at KSC will need no more that a few days in their lab to perform their off line check out and then a day or two to install in the vehicle prior to performing their V1175 test. JSC reports that the end effector delivery will move approximately 4 to 6 weeks to the right from the original 8/14/09 planned delivery.	Kenneth Ruta
			Pa	ige 97	0ľ	122			





EVA Status STS-129/ULF3 Delta Launch Site Flow Review

Marc Ciupitu EVA Office Johnson Space Center June 22, 2009





• Forward Bulkhead PFR

- Portable Foot Restraint, SED33105308-307 installed on forward bulkhead.
- Released Tech Order: M072-661568-029
- Required to protect for contingency EVA TPS inspection
- Lightweight Port TSA
 - Port LWTSA installation Tech Order: M072-660850-005
 - Port LWTSA Tools installation Tech Order: M072-660853-002
 - Port LWTSA Tools installation (MSA) Tech Order: M072-660853-008

Lightweight Starboard TSA

- Starboard LWTSA installation Tech Order: M072-660850-006
- Starboard LWTSA Tools installation Tech Order: M072-660857-001

• Winches

- Winch P/N SED33101570-327 on Forward Bulkhead
- Winch P/N SED33101570-325 on Aft Bulkhead





Presenter Kenneth Nowak **STS-129 Delta Launch Site Flow** Date Review 06-25-09 **Backup Material** Attachment 1 **SSP Systems Drawings** SSP Authorized Modifications/Non-Standard Work Attachment 2 Attachment 3 **SSP OMRS Waivers and Exceptions** Launch Window Attachment 4 **Open Configuration Waivers** Attachment 5





STS-129 Delta Launch Site Flow Review

06-25-09

Date

SSP System Drawings

The Drawings Baseline Was Released By PRCB S115129 on 02-23-09

- V072-000001-282 (Rev. VY01) Space Shuttle System (Rel. 04-08-09)
 - V072-200209-001 (Rev. A01) Mission Equipment Cargo Support (Rel. 04-21-09)
 - SGD32104452-401 (Rev. B1) Crew Compartment Configuration (Rel. 05-27-09)
 - -402 Descent
 - V070-000001-004
 Orbiter General Assembly
 - V070-410100-018
 SSME Installation
 - 10100-0061-177 Integrated SRB General Assembly (BI-140)
 - 80901000000-530 External Tank Assembly (ET-133)
 - STS-129 LSRR + 18 days Mission Configuration Product Plan (MCPP) was last published on 04-06-09 and will be republished at ORR -14 days on TBD.

Attachment 1





STS-129 Delta Launch Site Flow Review


06-25-09

SSP System Drawings – (Continued)

Ferry Configuration

- V072-000001-283 (Rev. VW01) Space Shuttle System Drawing (Rel.03-06-09)
 - V072-200209-002 (Rev. A01) Mission Equipment Cargo Support (Rel. 04-21-09)
 - SGD32104452-001 (Rev. B1) Crew Compartment Configuration (Rel. 05-27-09)
 - V072-300055-025 (Rev. BU) Ferry Flight Configuration (Rel. 05-11-09)

SCA 911



Page 103 of 122





STS-129 Delta Launch Site Flow Review

Modification Impact Report

- Mission Equipment Modifications and Orbiter Modifications analyzed for impacts to OMRSD, LCC, ICD, EMI, Software, and GSE.
- A total of 10 MCRs have been approved and/or pending mods
- Current MCR impact status:

•	No impacts for all six disciplines	8
•	One or more disciplines with impacts, documentation approved	2
	and/or pending approval	

• MCRs 19271 and 30250

Attachment 2





STS-129 Delta Launch Site Flow Review

Presenter Kenneth Nowak

06-25-09


Date

1

<u>Modification Impact Report – (Continued)</u>

- Possible impacts still under review
 - MCR <u>30250</u> is being reviewed for LCC impacts

<u>underlined MCRs</u> have impacts in other disciplines



1MRCS REPT. 4650-1 PAGE NO. 1	SSP SUMMARY	MOD ITEMS - PRCBD MOD BASE LINE STS-0129 MEQ
		ECP-MCR/KIT SEQUENCE RUN
TIME 13:55 DATE 06/1	6/2009	
STAT PRCB PRIO	ITEM/KIT NUMBER SEQ	
MCR/ECP SITE AUTHDATE FLT	TCTI NUMBER EISN NO.	DESCRIPTION / GENERAL REMARKS
019393 AUTH S115129A MAND	K609-613004-001 0002 000	AVIONICS HEAT EXCHNR INSTLN, ORIFICE RESIZE-BAY 3, ECLSS
KSC 2009-03-31 031	NOT REQUIRED	ADDED BY EDS I/F & K609-613004 NEW
030099 PLND S115129A MAND	TCTIM0030099REF 0001 000	D-HATCH DECALS RELOCATION ON UPPER HATCH BLANKET
KSC		ADDED PER V828-000002 F18 & V828-390179 A02 MVD TO STS-
129 2009-03-31	031	FRM STS-128 PER REMANIF/S042013HQ
AUTH S115129A MAND	TCTIM3330099REF 0001 000	RELOCATE ACTUATOR HATCH HANDLE POSITION DECAL, MV0828A
KSC 2009-03-31 031		ADDED PER V519-331035 A08 & V519-331051 A16
030186 AUTH S115128 MAND	TCTIM0030186REF 0003 000	OMS POD MICRO-WIS STRAIN RECORDER REMOVAL
KSC	0.2.1	ADDED PER V886-000002 A14, REPLACES 030186,0014,0 MOVED
TO 2008-08-25	031	STS-129 FROM STS-128 PER REMANIFEST

TOTAL MODS = 4

1MRCS REPT. PAGE NO.	4650-1 2	SSP	SUMMARY M	NOD ITEMS - PRCBD MOD BASE LINE STS-0129 ORB
				ECP-MCR/KIT SEQUENCE RUN
TIME 13:55	DATE 06/16	/2009		
	STAT	ITEM/KIT NUMBER	SEQ	
PRCB	PRIO			
MCR/ECP	SITE	TCTI NUMBER	EISN NO.	DESCRIPTION / GENERAL REMARKS
AUTHDATE	FLT			
		J6116	0104 003	AMES GAP FILLER REMOVAL AND REPLACEMENT
ORB-0085B	MAND KSC		SPAR	
2006-08-16	031		SPAR	
0005001	COMP	J6198	0104 002	OV-104 MID FUSELAGE LOCK BOLT OPPORTUNITY SAMPLING AND
ORB-0085R01	MAND KSC		SPAR	FASTENER REPLACEMENT
2007-03-12	031		DIAR	
TNODECETON	AUTH	J6275A	0104 001	ORBITER STRUCTURE IML SURFACE CORROSION SAMPLING
INSPECTION	S-J6275A KSC	MAND	SPAR	CORROSION SAMPLING CAPABILITIES WILL BE PROJECTED AT
LSFR, 200	08-02-26	031		
				AND FINALIZED AT DLSFR FOR EACH FLOW.
	AUTH	J6327	0104 001	WLE RCC JOGGLE INSPECTION
S-J6327	MAND	00527	0101 001	
	KSC		SPAR	
2008-02-14	031			
	COMP	J6329	0104 000	ASA #2 & #4 AND ATVC #3 & #4 R&R FOR OV-104, FLT 31
S-J6329	MAND	-		
0000 05 15	KSC		SPAR	PER USA PE:JEFF SCHIECK, TO PERF ON FLT 30, NOT 31
2008-05-15	031			

Page 108 of 122

a TC2412	COMP	J6341A	0104 000	EVALUATION OF OMS POD LI-900 TILE INSTALLED ON 0.090" SIP
S-J6341A	MAND KSC		SPAR	TILES WERE REMOVED AND REPLACED DURING FLT 30 PROCESSING
2008-04-09	031			
	COMP	J6351	0104 000	OV-104 RUDDER/SPEEDBRAKE (RSB) ACTUATOR EXTERIOR
INSPECTION	S-J6351	MAND		
2008-05-15	KSC 031		SPAR	PER USA PE, JEFF SCHEICK TO PERF ON FLT 30, NOT 31
S-J6378	AUTH MAND	J6378	0104 000	OV-104 BODY FLAP PDU GEARBOX FLUID LEVEL INSPECTION
5 00570	KSC		SPAR	
2008-07-18	031			
	AUTH	J6380	0104 000	EVA PDU TOOL INTERFACE VERIFICATION
S-J6380	MAND			
2008-07-07	KSC 031		SPAR	
		- 60 0 7		
S-J6387	COMP MAND	J6387	0104 000	PASSIVE DOCKING TEST ON OV-104
	KSC		SPAR	WORKED ON FLT 30 DUE TO ROLLBACK
2008-08-15	031			
	AUTH	J6389	0104 001	CLOSE CLEARANCE MEASUREMENTS OF ORBITER HARDWARE
S-J6389	MAND KSC		SPAR	
2008-07-10	031		SPAR	
	7 T T T T T	TC200	0104 000	A CALLER DROWEGHTON FOR ON 104 DI TOURS 21 25
S-J6399	MAND	J6399	0104 000	0-GAUGE PROTECTION FOR OV-104, FLIGHTS 31-35
	KSC		SPAR	
2008-10-03	031			
		J6402	0104 001	MICRO INSPECTION OF CAPTIVE GAP FILLERS
S-J6402	MAND			

	KSC		SPAR	DOCUMENTS MICRO INSPECTION OF SPECIFIC CAPTIVE GAP
FILLERS	2008-08-08	031		DUE TO OBSERVED FLT DEGRADATION.
0 76407	AUTH MAND	J6407	0104 001	STS-125 CLOSE CLEARANCE MEASUREMENTS OF SRMS MPM AND OBSS
S-J6407	MAND KSC		SPAR	VEH/EFF:OV-104 FLTS 30, 31.
2008-09-02	2 031			
	AUTH	J6410	0104 000	AFT STUB CRACKED TILE INSPECTION
S-J6410	MAND	00110	0101 000	
	KSC		SPAR	
2008-09-18	031			
	AUTH	J6414A	0104 000	RUDDER SPEED BRAKE THERMAL TAB INSPECTION
S-J6414A	MAND			
0000 10 10	KSC		SPAR	
2008-12-19	031			
	COMP	J6430	0104 000	MIDDECK PARTITION INSPECTION
S-J6430	MAND			
	KSC		SPAR	WILL BE WORKED DURING FLT 30 PROCESSING DUE TO ORB
ROLLBACK	2008-10-14	031		

1MRCS REPT. PAGE NO.	4650-1 3	SSP	SUMM	ARY M	NOD ITEMS - PRCBD MOD BASE LINE STS-0129 ORB	
					ECP-MCR/KIT SEQUENCE R	RUN
TIME 13:55	DATE 06/16	5/2009				
	STAT	ITEM/KIT NUMBER		SEQ		
PRCB	PRIO					
MCR/ECP	SITE	TCTI NUMBER	EISN	NO.	DESCRIPTION / GENERAL REMARKS	
AUTHDATE	FLT					
	COMP	J6441	0104	001	OV-104 LARGE PUTTY REPAIRS	
S-J6441	MAND					
2000 11 20	KSC		SPAR		TPS REPLACEMNT WILL BE PARALLEL TO PLANNED OPF PRO C	CESSG.
2008-11-20	031				TILE REPLCMT FOR OV104-F30:OPPORTUNITY BASIS	
	AUTH	J6447	0104	000	STS-126 POST FLT INSP AND CONTAMINATION SAMPLING	
S-J6447	MAND					
	KSC		SPAR			
2008-12-19	031					
	AUTH	J6466	0104	001	OMS POD PILLOW GAP FILLER INSTALLATIONS	
S-J6466	MAND	00400	0104	001	OMS POD FILLOW GAP FILLER INSTALLATIONS	
5 00100	KSC		SPAR			
2009-02-09	031					
g TC 4 0 1	AUTH	J6481	0104	000	MIDDECK PAYLOAD COOLING TEST FOR OV-104	
S-J6481	MAND KSC		SPAR			
2009-04-03	031		DEAK			
	AUTH	J6497	0104	000	OV-104 LARGE PUTTY REPAIR REMOVAL	
S-J6497	MAND					
2000 04 00	KSC		SPAR		REQ'D TPS REPLACEMENTS HAVE BEEN REVIEWED AT THE STS	5-129
2009-04-28	031				LSFR & INTEGRATED INTO GRND PROCESS'G PLAN	
					TOLK & INTEGRATED INTO GRUD FROCEDD & FLAN	

S-J6501	AUTH MAND	J6501	0104 000	STS-129 CIH CLOSE CLEARANCE MEASUREMENTS
2009-04-28	KSC		SPAR	CLOSE CLEARANCE MSRMNTS WILL BE PERF'D IN PARALLEL W/ P/L
2009-04-28	031			UP MISSION PROCESS'G & POST FLT DWNLD RECON
		J6506	0104 000	CAPTURE OV-104 OUTPUT WAVEFORMS TO ADDRESS 1N3600 DIODE
S-J6506	MAND KSC		SPAR	CONCERNS
2009-05-12	031			
(OV- S-J6509		J6509 MAND	0104 000	REMVL OF MPS GH2 FLOW CONTROL VALVES FOLLOWING STS-125
2009-05-12	KSC 031		SPAR	104), STS-127 (OV-105), AND STS-128 (OV-103)
2009-05-12	031			
S-J6512	AUTH MAND	J6512	0104 000	OV104 EVA SCU CHANGEOUT
OK'D 2009-05-	KSC	031	SPAR	DOCMNT RQMT TO R&R SCU'S DUE TO AGE-LIFE ITEMS. RQMT
0K D 2009-03-	-10	031		AT LSFR. WITHIN 129 OPF PROCESS'G PERIOD
102 0 70512		J6513	0104 000	X-RAY INSPN OF MPS HELIUM SUPPLY SYS CHK VLV CV4 ON OV-
103 S-J6513	KSC	MAND	SPAR	(STS-128) AND OV-104 (STS-129)
2009-05-12	031			
		J6516A	0104 000	WLE JOGGLE REGION IR THERMOGRAPHY REQUEST FOR HIGH LINE
SCAN S-J6516A	M. KSC	IAND	SPAR	WF PANELS
2009-06-16	031			
	AUTH		0104 000	PERFORM LEAK CK OF MPS LO2 OVERBD BLEED VALVE (PV19)& T-0
QD S-J6525	MAN KSC	שו	SPAR	(PD13) ON OV-103 (STS-128) & OV-104 (STS-129)
2009-06-10	031			

	PLND	S062831	0104 001	REMOVAL OF TEMP SENSING LABELS ON APU GN2 QD'S
S062831	MAND			
	KSC		NASA	
2009-04-15	031			
010000			0104 000	
019393	AUTH	VK70-613604-001	0104 000	AV BAY 3A FAN MOD, OV104, W/W -002 KIT, (+ BAYS 1&2 EOTF)
S115129A	MAND	NOT DECUTDED		
2009-03-31	KSC 031	NOT REQUIRED		PAR'D FROM FLT 30 TO 31 PER KSC-1879 (TO BE WORKED UNDER
2009-03-31	031			TAD 30240), W/W-002 KIT, REF ECL-4-27-1354
				TAD 50240), W/W-002 KII, KEF ECL-4-27-1554
	AUTH	VK70-613604-002	0104 000	KIT - AVIONICS BAY 3A FAN MOD, OV 104 (W/W -001 KIT)
S115129A	MAND	VIC/0 015001 002	0101 000	
222022271	KSC	NOT REQUIRED		ADDED BY EDS I/F & VK70-613604 A02. PAR'D FROM FLT 30 TO
31 2009-03-31		31		
				PER KSC-1879
019735	AUTH	TCTIV1019735REF	0104 004	WLE FRONT SPAR PROTECTION FOR SNEAK FLOW - STRUCTURES
S115117CR4	MAND			
	KSC			TRANSFERRED TO GEU FROM GC5. PART DEF FROM OV-104/27. REF
2006-11-21	031			
				SEQ 1/STS-117, SEQ 2/STS-122, SEQ 3/125

1MRCS REPT. PAGE NO.	4650-1 4	SSP SUMMA	ARY MO	DD ITEMS - PRCBD MOD BASE LINE STS-0129	ORB
10	0.0 (1.1			ECP-MCR/KIT SEQUENCE	RUN
TIME 13:55	DATE 06/16	5/2009			
PRCB	STAT PRIO	ITEM/KIT NUMBER	SEQ		
MCR/ECP	SITE	TCTI NUMBER EISN	NO.	DESCRIPTION / GENERAL REMARKS	
AUTHDATE	FLT				
019735 S115117CR4	AUTH MAND	TCTIV1919735REF 0104	004	FRONT SPAR PROTECTION FOR SNEAK FLOW (TPS/RCC	2)
SIIJII/CR4	KSC			PART DEF'D FROM OV-104/27. SEE SEQ 1 FOR OV-1	L04/28 WORK,
2006-11-21	031				
				SEQ 2 104/29, SEQ 3 104/30, SEQ 4 REMAINDER	
019763	AUTH	TCTIV1919763REF 0104	004	WING LEADING EDGE (WLE) HORSE COLLAR REDESIGN	1
S115117CR4	MAND KSC			PART DEF'D FROM OV-104/27. REF SEQ 1 FOR OV-1	L04/28 WORK.
2006-11-21	031			-	,
				SEQ 2 104/29, SEQ 3 104/30, SEQ 4 REMAINDER	
030231 S115129A	AUTH MAND	TCTIV2930231REF 0104	000	RUDDER SPEED BREAK INCONEL THERMAL BARRIER RE	EDESIGN STUDY
	KSC	NOT REQUIRED		ADDED BY EDS I/F & V070-298115 A07	
2009-03-31	031				
030250	AUTH	TCTIV7930250REF 0104	000	02 CROSSOVER VALVE SIGNAL TALKBACK MOD, REF H	ECN 25005
S115129A	MAND KSC	NOT DECLITED		ADDED BY EDS I/F & V070-778302 D05	
2009-03-31	031	NOT REQUIRED		CON 70C011-010 X/L & A010-110 207 IQ CON	

TOTAL MODS = 37

1MRCS REPT. 4650- PAGE NO. 5	1 SSE	SUMMARY M	OD ITEMS - PRCBD MOD BASE LINE STS-0129	PIH
PAGE NO. 5			ECP-MCR/KIT SEQUENCE	RUN
TIME 13:55 DATE	06/16/2009			
PRCB PR	STAT ITEM/KIT NUMBER	R SEQ		
MCR/ECP AUTHDATE	SITE TCTI NUMBER FLT	EISN NO.	DESCRIPTION / GENERAL REMARKS	
008836 NOT REQD	APPD TCTIM0008836REF	0020 000	PROVISIONS TO SUPPORT EXPRESS LOGISTICS CARR	IER (ELC) PDA
031	KSC		ADDED PER V785-714912 E07 - MOVED TO STS-128	FROM STS-129
031			PER REMANIFEST PER S042013HQ	
008850	APPD K712-774041-001	0005 000	ADDITIONAL HARDWARE REQUIREMENT TO SUPPORT S	TS-129, CIH
KIT NOT REQD	KSC		ADDED PER KIT EO NEW	
031				

TOTAL MODS = 2

1MRCS REPT. PAGE NO.	4650-1 6	SSP	SUMMARY M	OD ITEMS - PRCBD MOD BASE LINE STS-0129	SRB
				ECP-MCR/KIT SEQUENCE	RUN
TIME 13:55	DATE 06/16	5/2009			
PRCB	STAT PRIO	ITEM/KIT NUMBER	SEQ		
MCR/ECP	SITE	TCTI NUMBER	EISN NO.	DESCRIPTION / GENERAL REMARKS	
AUTHDATE	FLT				
			-140.000		
S084539LR3	AUTH	FEC A-10358B	B140 000	EDAS SENSOR INSTALLATION SUPPLEMENT FOR BI14	U SRB'S
0000 00 10	KAS				
2009-03-10					
S084539LR3	AUTH	FEC A-10361B	B140 000	SUPPLEMENTAL EDAS INSTALLATION FOR BI140	
5004539LR3	KAS				
2009-03-10					
	PLND	FEC RSRM-120	B140 000	STIFFENER RING FOAM BONDLINE VERIF PULL-TEST	LOC CHANGE
S171478	KAS		NASA		
2009-04-22					
TOTAL MODS	=	3			

1Date: 06/16/09 14:05

PCASS

Page: 1

FLIGHT-SPECIFIC

Approved STS-129 OMRS Waivers and Exceptions

		PRCBD NUMBE	ER			STS	
				ABSTRACT RAS REQUIREMENTS	EISN PAYLOAD	BEG	END
E	ORB			OMRSD EXCEPTION REQUEST - MISSION LIFE ASSESSMENT OF WING LEADING EDGEINSULATORS (EK10572R1)	104	029	033
		S053298ZD EK10574R1 (A		~	104	029	036
		S053298ZE EK10575R1 (A		OMRSD EXCEPTION REQUEST - MISSION LIFE ASSESSMENT OF WING LEADING EDGEINSULATORS (EK10575R1)	104	029	031
		S053299AQ EK10592 (A			104	029	032
		S053299AT EK10593 (A		~	104	029	032
W	ET			L02/LH2 TANK PRESSURE MONITOR FOR MOVE	ET	099	999
	OMS	803323011	Y)		0021	035	043

ORB	S053296YT WK10332R2 (A)	OMRSD WAIVER REQUEST - PV6 PREVALVESCREEN PARTICLES (WK10332R2)	104	027 031
	S053298HY WK10502 (A)	OMRSD WAIVER REQUEST - BODY FLAP DRIVE RATE TEST (WK10502)	104	027 031
	S053299BLR1 WK10600R2 (A)	OMRSD WAIVER REQUEST - OXYGEN SYSTEM 1 RELIEF VALVE FAILED RESEA TLEAKAGE (WK10600R3)	104	029 032
RCS	S053296GY WK10188R1 (A)	OMRSD WAIVER REQUEST - LRCS OXIDIZER GHE ISOLATION VALVE LEAK(WK 10188R1)	0014	025 032

-

1

-

Date: 06/16/09 14:05

PCASS

Page: 2

FLIGHT-SPECIFIC

Approved STS-129 OMRS Waivers and Exceptions

EXC			AT)	ABSTRACT RAS REQUIREMENTS		BEG	END
				OMRSD WAIVER REQUEST - RIGHT RCS OXIDIZER GHE SYSTEM INTERNAL LEA KAGE(WK10318R1)	0021	034	042
				OMRSD WAIVER REQUEST - RRCS OX TANKOUTLET TRANSDUCER ACCURACY (WK 10503)	0021	034	042
				OMRSD WAIVER REQUEST - LEFT REACTION CONTROL SYSTEM FUEL GHE ISO LATIONVALVE LEAKAGE (WK10634)	0014	030	032
	SRB	WK03886 ((STS-103)	A)	LH FWD AND RH MID SRB JOINT TEMP SENSORS	BI	099	999
	0		c	Waivers ° Except ° Deviat			
				+++ 10 ° 5 ° 0			

ACTIVE WAIVERS FOR OV-104

Item #	Authority	Date	Waiver Description	Effectivity	Wad
53	S052428A	03/27/91	Allows specified flights to fly with interim TPS repair after each mission to minimize damage to surrounding tile during ferry flight	STS-37, STS-39, STS-40, STS-42 thru STS-999	STAYS OPEN
101	S076972	11/19/91	Permit the modified GPCs (AP101-S) Battery Back-up Unit to fly with annotated fastener improvements without rolling the LRU Part Number	STS-42, STS-44, STS-47 and STS-49 thru STS-999	STAYS OPEN
325	S061956	07/15/03	Blanket on the Control Moment Gyro (CMG) Orbital Replacement Unit (ORU) on the Lightweight MPESS Carrier (LMC) will NOT be re-installed on-orbit per configuration defined in ICD-A-21494. It will be secured around the FSE and attached to the aft bulkhead.	OV-104, Flight 27	
334	S115115JR1	07/19/06	The following requirement is waived to allow OV-104 to fly with the following out-of-configuration condition:	OV-104, Flight 27 thru OV-104, Flight 999	STAYS OPEN
			Tech Order M072-544501-067 (RMS, MPM over-center stop and MPM pedestal insulation cover fasteners) will be implemented in total, less the requirement to perform bench rigging per updated specification requirements for for OV-104, Flight 27 and subsequent OV-104 flights until such time that all MPMs can be removed and bench rigging can be performed.		
339	S063652	07/09/07	The following requirement is waived to allow OV-104 to ferry from DFRC to KSC with the following out-of-configuration condition:	OV-104, Flight 28	
			Retain RH ET Camera installation for ferry flight MECSLSI V072- 200197, reference flag note (3), removes (MV0456A) M072-705001- 024 RH ET Sep Camera (Digital Camera with 35 mm lens) for ferry flight. The RH ET Camera needs to remain in flight configuration to support resolution of IFA STS-117-V07 Digital Umbilical Camera Image Corruption. Troubleshooting will be performed on the installed hardware after returning OV-104 to KSC.		

ACTIVE WAIVERS FOR OV-104

Item #	Authority	Date	Waiver Description	Effectivity	Wad
340	S063652	07/09/07	The following requirement is waived to allow OV-104, Flight 28 to ferry with the following out-of-configuration conditions:	OV-104, Flight 28	
			Remove LH OMS Pod LP04 (FIB) blankets prior to ferry flight thermal blanket V070-396376-241 on LOMS Pod lifted at forward leading corner and edges reported on orbit, IFA STS-117-V-02. Two blankets (V070-396376-241 and adjacent V070-396376-051) are removed. RTV ramp applied in cavity up to adjacent blankets per TLP04-28-2520 MRB approval.		
343	S115122GR4	12/07/2007	The following requirement is waived to allow OV-104 to fly with the following out-of-configuration condition:	OV-104, Flight 29	ECL-4-A0118 (was ECL-4-29-1637)
			Partial installation of Tech Order M072-660010-004, middeck air flow re-routing duct tech order, not to include one each bolt (NAS1003-8A) and one each washer (NAS620C10) in the lower aft corner of the vent housing cover assembly.		
			During vertical stowage, the nut plate (not under USA Tech Order configuration control) was noted missing from behind the starboard closeout panel. Without the nutplate, the bolt and washer cannot be installed. The area cannot be currently accessed to reinstall the missing hardware.		

ACTIVE WAIVERS FOR OV-104

Item #	Authority	Date	Waiver Description	Effectivity	Wad
344	S071024MP	12/20/07	 During maintenance of an Advanced Master Events Controller (AMEC) it was discovered that the module cards are able to translate upward, away from connectors. The cards are retained by friction applied by wedge-locks. An assessment determined a 0.070 upward card translation, would result in card disengagement from connectors. The wedge-lock system can not assure the cards will not translate upwards. The AMEC vendor (Boeing Autonetics) is no longer on contract supporting SSP. A design proposal is to provide a secondary connector retention using the AMEC covers. The new design new lids will limit the upward translation to 0.055. The new design will reduce the milled section of the cover and add silicone pads to provide shock absorption. Due to the absence of the original vendor and no current alternate drawings available for the AMEC the modification is being requested via a program directed Material Review (MR). P/N MC450-0016-0029 S/N U6F0002, U6F0003, U6F0004, U6F0006, U6F0007, U6F0007, U6F0009, U6F0010 and U6F0011 ****** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS 	OV-103, Flight 35 OV-104, Flight 30 OV-105, Flight 21	