

SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-20-10	

Program Freeze Point

PRCB Presentation

S115133C



Flight Operation 9 Interretion

SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter Kenneth Nowa		wak
Date	05-20-10	

MO2/LICA DI

Baseline the STS-133 Mission Specific Requirements and Flow Plans.

The STS-133 Integrated Launch Site Requirements were established by PRCBD S115133AR1 dated 03-04-10. This CR and the Associated Data Package were reviewed at the 05-17-10 FRWG.

Flight Operation & Integration		MO3/USA-PI
Orbiter Engineering*	Requesting Approval	USA-OE
Payload/Cargo Engineering*		USA-PI
SSME		MP21
KSC ISS and Payload Processing*		UB-R3
Launch Vehicle Processing		PH-A
	Status in BackUp	
KSC Integration*		MK-SIO
Flight Software		USA-FSW
Orbiter GFE*		MV5
EVA		XA

^{*}Backup material included



STS-133 Delta LSFR

PRCB Flight Requirements Status

May 20, 2010

Michael Darnell, Lead MIM






On Orbit Cargo Bay Configuration

mioriaci Barrion		
Date	5/20/10	Page 2

Michael Darnell

Presenter



Page 4 of 100





STS-133Delta LSFR **Flight Overview**

Michael Darnell Date

5/20/10

Presenter

Page 3

LAUNCH

09/16/10

*39A/ MLP3

CREW SIZE: 6UP/6DN

CONFIGURATION

OV-103(39)

LP01;RP03

*ET-137

*BI-144

*RSRM-112

*(1) 2048 (2) 2044 (3) 2058

OI-34

SRMS, OBSS, ODS, SSPTS

PAYLOAD

ISS-ULF5 ISS-ULF5 (ELC4, PMM) **MAUI**

SEITE

SIMPLEX

RAMBO-2

per PRCBD S042013HZ (signed)

ORBIT

51.6 DEG **122 NM**

DIRECT INSERTION

DURATION: 8 + 1 + 2 DAYS

CONSUMABLES

CRYO TANK SETS 4 (OFFLOAD)

GN2 TANKS 5 (FULL)

FWD RCS 1912# (OFFLOAD)

4970# (FULL) AFT RCS 22760# (FULL) **OMS**

LANDING

SITE **KSC**

TAL **ZARAGOZA**

ALT. TAL **MORON & ISTRES**

SCA 911





SPACE SHUTTLE PROGRAM
Space Shuttle Flight Operations and Integration Office
NASA Johnson Space Center, Houston, Texas

STS-133 Delta LSFR

Shuttle	Performance Margin	Presenter Michael Darnell
rogram	un i enomiance margin	Date 5/20/10 Page 4
	PERFORMANCE MARGIN	
SIMULATION	MARGIN (OCFAF133)	+2101
PAYLOAI OPERATO ORBITER CREW CO ET	OR	+671 - 414 +41 +189 <u>+154</u> +641 - 641
RENDEZY PROTECT SRB – M. SRB – BI NEW ISPA PROJ TO	ORMANCE PROJECTIONS VOUS ALT OF 190 NM TION FOR DOL DISPERSIONS P. UPDATES R / 0.80 MIL LOWER THAN 0.3705 AVG /THST FOR ENG SET 2048/2044/2058 5 MIN WINDOW FROM INPLANE MANCE CHANGES ADJUSTMENT	+1160 - 700 - 106 - 288 - 94 - 600 <u>+45</u>
ADD 191	LBS TO MIDDECK	+877 - 176
PROJECTED A	100 LB OMS ASSIST (NO COPV) APM SCENT PERFORMANCE MANAGER'S RESERVE 0	<u>+83</u> +784 GUIDELINE AT LSFR/LSRR IS 400 LBS





STS-133 Delta LSFR MASS Properties

Michael Darnell

Date 5/20/10

Page 5

FLIGHT MASS PROPERTIES

CASE	TOUCHDOWN WEIGHT pounds (LIMIT)	MACH 3.5 X C.G. inches (LIMIT)
NOMINAL	203122 (233000)	1080.2 (1075.2)
RTLS	240923 (245000)	1081.4 (1076.7)
TAL	238807 (244000)	1080.9 (1076.7)
AOA	233614 (242000)	1077.1 (1075.2)
CONT RTRN**	235056 (233000)	1078.7 (1075.2)

^{**} Contingency Return case exceeds 233K NEOM weight limit. (See Vol. X Bk. 1 Sec. 3.3.1.1.9)

NOTE: 104 LBS AFT FUS. BALLAST (EMPTY BOXES)
RTLS INCLUDES 25 SEC FRCS DUMPS
TAL INCLUDES 60 SEC FRCS DUMPS

ESTIMATES BASED ON OCFAF133 AND MODIFIED FOR WEIGHT CHANGES THRU 05/11/10.





Flight Requirements Status

Michael Darnell			
Date	5/20/10	Page 6	

Presenter

PRCB CR's

- None

<u>ULF5 MIP (NSTS 21554):</u>

- Current version available on PILS: Rev. A PCN-2, March 12, 2010
- Open CRs:
 - 21554, MIP CR#0007 Update ULF5 MIP Priorities and Replace TriDAR DTO with Dragon Eye DTO





STS-133 Delta LSFR Potential Changes

	Present	ter Michael D	arnell
•	Date	5/20/10	Page 7

Mission Content and Cargo Configuration

- Addition of up to two EVA for ISS homeless EVA tasks
 - 1 EVA drives mission duration to 10+1+2
 - 2 EVAs drives mission duration to 11+1+2
- Addition of the LMC for Nitrogen Tank Assembly (NTA) and /or Light Weight Adapter Plate Assembly (LWAPA) return
 - OV-103 currently configured to support LMC. Decision needed by 6/1 to remove/retain the bridges and latches for LMC
- Addition of Bay 13 sidewall for LWAPA return if LMC not added

Aft Ballast Boxes

 Due to cargo manifest uncertainty, the Aft ballast boxes cannot be removed.

STS-133 Delta LSFR

OV 103 / FLT 39 PRCB

Belinda Soublet
USA Orbiter Element
May 20, 2010





STS-133 OV 103/FLT 39 – Orbiter DLSFR Baseline

Mission Kit Modifications To Be Baselined at DLSFR for OV 103 / FLT 39

- TAD 30234 DragonEye DTO 701B Implementation
- PRSD Tank Set 3/5 LH Purge Duct Tech Order change

Potential Modifications (Info Only)

Additional Requirements being tracked:

- Tech Order Updates (Info Only)
- Chits
- STR/TPS Priorities Current Vehicle Status

Backup

- Information previously presented at STS-133 LSRR/LSFR
 - STR/TPS Priorities Detailed List
 - Opportunity modifications previously presented (Info Only)
 - STS-133 Weight Saver Mission Kit Changes (Info Only)





Mission Kit Modifications To Be Baselined at STS-133 DLSFR

TAD 30234 Dragon Eye DTO 701B Implementation

- Per STS-133 FRD, DragonEye will replace TriDAR DTO on OV-103
- DragonEye LRU mounts at same location as TriDAR on external airlock truss
- Authorization requested for mission kit end item mod record 030234,0103,0 to reflect the addition of the GFE DragonEye LRU to the mission kit
- Installation tech order M072-730021-023 to be manifested on STS-133 MECSLSI
- Engineering release ECD 5/20/10
- Hardware is provided by GFE; GO need date is July 14

PRSD Tank Set 3/5 LH Purge Duct

- Tank set 5 to be removed per FRD requirements for APM
- Tech order M072-384006-002 is required to be added back to the STS-133
 MECSLSI
 - This air duct is used to support both tank sets 3 & 5 and was inadvertently demanifested as part of the tank set 5 removal - will leave installed to support tank set 3 LH purge





STS-133 Potential Modifications (Info Only)

TAD 30091 BLT FE DTO Flight 4

- Re-flight of protuberance tile and associated thermocouple installation with likely protuberance height increase to 0.50"
- Thermal analysis results of flying 0.50" protuberance reviewed by thermal and aero panels week of May 10 and no issues were found
- Review of STS-131 BLT data is complete and STS-133 recommendation was presented at OCCB on May 18
- Targeting baselining at PRCB / DPRCB ~ June 10
- Protuberance tile with height options of 0.35", 0.45" and 0.50" are being fabricated – engineering release for chosen option to be released by June 11 in support of GO implementation schedule

TAD 30246 Catalytic Coating DTO Flight 3

- Re-flight of catalytic coating applied to one tile in BLT DTO region of influence
- Shelf life extension testing of existing lot of catalytic coating completed with no issues
- Thermal analysis shows no concern with heating from larger 0.50" protuberance
- No mod to baseline as there is no configuration change from previous flight
- Ground Ops to remove STS-131 catalytic coated tile and replace with new coated tile





STS-133 Potential Modifications cont'd (Info Only)

TAD 30286 Ceramic Insert Plug Mod

- TPS PRT recommendation for corrective actions related to ceramic insert plug loss / protrusion as seen on STS-131
- Will address changes to the plug braided cord to reduce configuration variability and provide plug installation running torque consistency to improve plug retention
- A multiple vehicle CR will be brought forward the first week of June

Port and Starboard Wing Leading Edge Reference Marks

- Imagery has determined the docked OBSS LDRI inspection involves different trajectories from the nominal OBSS survey, due to ISS hardware considerations.
- Pan and tilt unit (PTU) adjustments for proper LDRI sensor pointing made during survey auto-sequences are based on visual cues from the LDRI imagery.
- Because WLE surfaces viewed with these flight-specific pause points are fairly nondescript, adding the position identifying symbols on the starboard and the port WLE RCC panels or associated T-seals will facilitate the survey and help diminish the likelihood of missed coverage during a contingency docked late inspection
 - Reference marks will be applied with approved black Sharpie (similar to nose cap fiducial markings)
- Program CR (similar to STS-134 CR) will be processed OSB at a later date





STS-133 Tech Order Updates (Info Only)

- MEI Instrumentation Filter Tech Order Configuration
 - Tech order M072-755113-004 update to be picked up in STS-133 MECSLSI (post STS-133 LSFR change)
 - -004 documents acoustic sensor filters added late in the STS-131 flow





STS-133 Chits

Approved

าร
ot 1
tener
)





STS-133 Chits cont'd

Approved cont'd

K6516A Ground Lightning Monitoring System (GLMS) Installation

K6566
 SSME Nozzle Purge Hot Wall Corrosion Prevention

K6610 Dual Docking Contamination Sampling

Pending/Draft

J6628 OV-103 Insert Removal due to Suspect Ceramic Adhesive

Potentials

- Multiple Voltage Injection for new calibration curve
- EVA Winch Attach Point Inspection





STR/TPS Priorities Current Vehicle Status

STATUS AS OF 5-03-2010

Priority Number	Total	OV-103	OV-104	OV-105
1. BRI-18 Tile - MLGD FWD O/B Corner	28	complete	complete	complete
2. BRI-18 Tile - MLGD FWD Edge	22	complete	complete	complete
3. BRI-18 Tile - MLGD O/B Side	18	complete	complete	complete
4. BRI-18 Tile - STR side of ET Doors	20	complete	complete	complete
5. BRI-18 Tile – LESS Carrier Panels 8-10 (103 & 104)	24	complete	complete	n/a
6. BRI-18 Tile – STR side of ET Doors I/B	8	complete	complete	complete
7. Inboard Elevon "Hub" Tile Mod	4	complete	2	complete
8. I/B Elevon 9lb/90 SIP	34	complete	complete	complete
9. O/B Elevon 9lb/90 SIP	6	complete	complete	complete
10. MLGD – Outboard Middle 1/3	24	complete	complete	complete
11. ET Door remaining STR side	40	1	10	12
12. MLGD - Outboard AFT 1/3	22	0	0	9
13. Nose Area 9lb/90 SIP	14 (16 ^{OV103})	10	complete	complete
14. Base Heat Shield 9lb/90 SIP	42	22	complete	complete
15. Body Flap Stub "Piano Key" tiles	40	18	20	18
16. Gap fillers in Subset 2B	5 Zones	2	1	0
	MLGD 100	MLGD 0	MLGD 1	MLGD 0
17. Remaining BRI-18 - MLGD (top priority) / ET / LESS	NLGD 123	NLGD 20	NLGD 22	NLGD 55
carrier panels / NLGD	LESS 68 (92 ^{OV-105})	LESS 8	LESS 12	LESS 27
	ET Door 28	ET Door 5	ET Door 4	ET Door 1
18. Mod work LESS internal	44 locations	41	complete	complete
20. Remaining Gap Fillers & Window BRI-18	124	3	2	23





STS-133 ISS – ULF5 PMM, ELC4

Delta Launch Site Flow Review (DLFR)

Payload Cargo Engineering Status

ABBAS ELSABAGH 281.212.6186 05-20-2010



STS-133 DLSFR

STS-133 Payload Integration Services/Interfaces

Middeck Powered Payloads

- GLACIER rear breather (36 CFM) (Up/Dn) 160 W
- CGBA-NLP 65W ↑
- Commercial Biomedical Testing Module 1 & 2 ↑ (CBTM1 & CBTM2) - 36W each
- Mouse Immunology (MI) Animal Enclosure Module (AEM 1 & AEM 2) - 36W each

Dragon Eye (Pending MIP CR approval).


• 28 VDC for heater and avionics (Wavelength trans.)

ELC 4 \wedge

- Deck Assembly:
 - Deployable
 - -4 active longeron latches (fwd primary)
- Keel Assembly: **↑**
 - 2 passive longeron latches
 - -1 Active keel latch (Not wired to A6U panel)
- No power required for ELC4

↑ MPLM (PMM)- 1st Flight this location

- 4 active longeron latches with aft primary
- 1 active keel latch
- ROEU provides 28V heater power, 124V for temp and pressure checks, and 1553 for command / telemetry





STS-133 DLSFR

Engineering Flight Product Status

Drawing No	<u>Title</u>	<u>Released</u>
V072-200213	MECSLSI	02/18/10
VA72-200213	Cargo Arrangement	04/13/10
VD72-200213	Avionics Diagram	02/18/10
VS72-200213	Integrated Schematic	02/18/10
VS70-540423	Retention Schematic	02/11/10

Engineering Open Work

- V072-200213 MECSLSI Update ECD: 06/03/2010
 - DLSFR Mods
 - Add AFT Winch
 - Add New dash number for the return configuration of the drop bridge adaptor
 - Dragon Eye TO instead of TriDAR (will require VA/VS/VD updates)

Standardization

- Configuration Waiver S070045 dated 9/21/09 to Orbiter/Payload Integration
 Standardization Document NSTS 60523. This is required to add the PPSU and to direct
 the Software to support it.
 - PPSU was removed from flight when ELC4 power requirement was deleted
 - No change to Software, due to late requirement change Waiver is still applicable



STS-133 DLSFR

Cargo Close Clearance Process

- The following Close Clearance areas have been identified:
 - 1. ELC aft port and starboard scuff plates to MPM
 - 2. PMM to top centerline latches
 - 3. ASI flag (PMM) to sidewall
- Chit 6601 was developed to take Close Clearance measurements of item 1 above
 - Other locations already measured or not accessible for as-installed measurements
- Chit measurements will be performed at the (PAD) after payload installation
- Chit 6600 was developed to measure the ELC4 longeron latch centerline locations to set-up CEWS for ELC MGSE installation (similar to STS-129/ULF3)
 - Same chit will also measure the ELC4 keel 'droop' when it arrives at the PAD prior to payload installation for the PGHM operators



Discovery STS-133 Delta Launch Site Flow Review

Space Shuttle Main Engine

SSME - KSC Paul Brzeski (321) 861-4064






Pratt & Whitney Rocketdyne, Inc.

STS-133 Delta Launch Site Flow Review

SSME Allocations / Locations





STS-133 Delta Launch Site Flow Review

SSME Planned Modifications

Mods authorized by Shuttle Project Action Request (SPAR) or Level II Change Request (CR)

ECP	Title	Engine(s)	Kit Drawing	Weight Impact	SPARs / CRs	Status
1537	Joint F2 (LPFTP-to-LPF Duct) Liquid Air Insulation Redesign, with Helium supply.	2058	2R112833-010	+3.13 lbs	ME-0261 B	Complete
1544	Joint F5 (HPF Duct-to-MFV) Liquid Air Insulation Redesign.	2048 2044	2R112835-010	-0.15 lbs	ME-0260 B ME-0262 B	Complete Complete





STS-133 Delta Launch Site Flow Review

Rocketdyne Action Requests (RAR)

RAR	Title	Engine(s)	SPARs / CRs	Status
KLO-1645	Reallocate HPFTP.	2058	ME-0261 B	HPFTP 8031R1: Removed 14-Jan-2010. HPFTP 8121: Installed 21-Jan-2010.
KLO-1646	Allocate LPFTP.	2058	N/A	LPFTP 2232: Removed 14-Jan-2010. LPFTP 4208R1: Installed 21-Jan-2010.





STS-133 Delta Launch Site Flow Review




KSC International Space Station and Spacecraft Processing

ISS-ULF5

ExPRESS Logistics Carrier 4 (ELC4) with Heat Rejection System Radiator (HRSR) Orbital Replacement Unit (ORU)

Permanent Multi-purpose Module (PMM)

Scott Higginbotham / UB-R
ULF5 NASA-KSC Mission Manager
May 20, 2010



Page 28 of 100



ULF5 Hardware Processing Status Summary



ExPRESS Logistics Carrier 4 (ELC4)

- Assembly operations are continuing on schedule
 - Keel side PFAP (five each) build up/installation operations are complete
 - Top side HRSR FSE installation/alignment operations are complete
 - Cable harness testing operations are underway
- Flight ExPRESS Carrier Avionics (ExPCA) standalone testing is underway
- HRSR ORU in dwell flight installation scheduled for late June

Permanent Multi-purpose Module (PMM)

- Leonardo (MPLM FM1) STS-131/19A destow/deintegration operations are complete
- TAS-I modification work is underway
 - All external MLI/MDPS has been removed
 - Feed through leak checks underway
 - Harness removals/modification underway
- CBM seals have been replaced leak check is underway
- First cargo bench review planned for 5/19



ULF5 Processing Milestones



ELC4

•	ELC4 On Dock KSC	15 August 2009
•	ExPCA #4 On Dock KSC	19 February 2010
•	HRSR FSE On Dock KSC	1 April 2010
•	Install ExPCA #4 onto ELC4	21 May 2010
•	Install HRSR ORU onto ELC4	25 June 2010 (U/R)
•	ELC4 Testing	29 June - 12 July 2010 (U/R)
•	ELC4 Deck To Keel Mate	mid July 2010 (U/R)
•	ELC4 Closeouts Complete	late July 2010 (U/R)
•	ELC4 CEIT	TBD
•	ELC4 ICD Walkdown	TBD
•	ELC4 Weight and C.G. Measurements	TBD
•	ELC4 Canister Installation	TBD



ULF5 Processing Milestones



PMM

•	FM-1 MPLM 19A Deintegration Start	28 April 2010
•	PMM External Modifications Start	28 April 2010
•	FM-1 MPLM 19A Deintegration Complete	14 May 2010
•	PMM Internal Modification "Window"	11 May – 4 June 2010
•	PMM Testing Complete	18 June 2010 (U/R)
•	PMM Rack Integration Complete	15 July 2010 (U/R)
•	PMM External Modifications Complete	27 July 2010 (U/R)
•	CEIT	TBD
•	PMM Closeouts Complete	TBD
•	PMM ICD Walkdown	TBD
•	PMM Weight and C.G. Determination	TBD
•	PMM Installation into Canister	TBD



Issues / Concerns



- There are multiple threats to the MPLM to PMM conversion/processing campaign:
 - 19A FOD damage to MPLM/PMM pressure vessel
 - Conversion mod scope growth
 - Anticipated late cargo "integrated assembly" deliveries
 - Workforce changes/turnover
- Potential addition of sidewall PFIP for LWAPA return

KSC Launch and Landing Project STS-133 DLSFR

May 20, 2010

Agenda

Orbiter Multi Flow
 S.Stilson / NASA

Milestone Interface Chart
 S. Stilson / NASA

Flight Element Processing
 W.Bingham / USA





Multi Flow

S.Stilson

STS-133 DLSFR

J. F. KENNEDY SPACE CENTER





Flight Element Processing

W. Bingham

STS-133 DLSFR

J. F. KENNEDY SPACE CENTER

Flight Element Processing Overview

Milestone Summary
 To Be Presented

Significant Processing Deltas
 To Be Presented

TPS Status
 To Be Presented

Issues and Concerns
 To Be Presented

STS-133 DLSFR

J. F. KENNEDY SPACE CENTER

STS-133/OV-103 OPF FLOW MILESTONE

STATUS

USA NASA

C C

C=Concour NC-Not-concour

DOWN PAYLOAD: ISS-33-19A UP PAYLOAD: ISS-36-ULF5 OFFICIAL MILESTONE REPORT REVISION: J REVISION DATE: 14-May-10

****States Milestone Change

Page: 1 of 1

OPR: USA-BINGHAM, WAYNE W. NASA-STILSON, STEPHANIE S.

010 May 2010						June 2010				July 2010				August 2010 per 201						
18	25	02	09	16	23	Τ	30	06	13	20	27		04 11	18	25	01	08	15	22	29
						П														
	Ī					1						П		Ī	1					
▲ KSCI	ÁNDING, 20-/	pr-10 A				Ш	1											İ	İ	
▲ ORBI	TER AT OPF D	OOR, 20-Ap	-10 A			Ш														
▲ CF	O OFFLOAD	COMPLETE	21-Apr-10	A		!		!						-	-			!	!	
Δ	PLBDS OPEN	COMPLETE,	23-Apr-10	A																
	▲ PAYLOAD	REMOVAL C	OMPLET	E, 25-Apr-10 A		Ш														
	▲ OBSS	REMOVAL C	OMPLET	, 27-Apr-10 A		Ш														
		▲ HYPER O	FFLOAD	OMPLETE, 0	2-May-10 A			ļ						İ	ļ			ļ	ļ	
	į	▲ HEAT	SHIELD R	EMOVAL CO	MPLETE, 05-M	aý-10	Α .	į			İ		į	į	į	İ		į	į	
		Δ:	SME REN	IOVAL COMP	LETE, 07-May-	16 A														
				Δο	BSS INSTALLA	νπο	COMPLE	TE, 19-May	10											
	•		!	Δ	ET DOOR PUS	sid III	вт сом	LETE, 20-M	ay-10				İ	į	ļ			ļ	ļ	
	İ		į	İ	∆ OMS X	rie e	DRAIN ¢	OMPLETE,	14-May-10		į į		į	į	į	į		į	į	
					Δ	ricons	OBSS EN	ID-TO-END	ESTING CO	IPLETE, 26-I	day-10									
								:	SPECTION C											
							Δ ****RH	POD REMO	WAL COMPLE	ETE, 02-Jun-	0									
									Δ ****PA	YLOAD PRE	MATE TEST ¢	MIF	PLETE, 15-Jun-10							
						Ш				SSME INST	ALLATION C	MPI	LETE, 20-Jun-10							
						Ш					: :		ON COMPLETE, 22	Jun-10						
										∆ SP2	VT COMPLET	E, 2	3-Jun-10							
												ш	ION COMPLETE, 2	5-Jun-10						
						Ш				_	: :	ш	RFACE VERIFICA	1	TE. 26-Jun-10	1		İ	İ	
											: :	ш	GEAR FUNCTION	:	1					
												ш	HELD INSTALLATION	i	i					
												ш	GRATED HYD OP:							
						Ш						ш	FINAL AEROSUF		:	LETE 06-Jul-1	10			
												П	:	APLETE, 10-Ju	1	, 00 00.	~			
	İ		!	į	į	!	!	į	į					į i	İ	i PLETE, 18-Ju	-10	ļ	į	
	į		i	İ	į		li	į			į į		İ		i	SERVICE C		LIUL-1D	į	
						Ш									:	PLB DOORS		;		
															2.1100	:		:	PLETE, 04-Au	n-10
!			ļ					į					ļ	ļ	!	1	l	LETE, 05-Aug	I	
l				ĺ				į					İ			i	i	OLL, 06-Aug	ì	
																_ ^		_	:	ın.
				1	1	Ш											A ROLLOU	I PIROS I MO	ION, 09-Aug	IU

Legend: △ Milestone △ Milestone Complete

Significant Processing Deltas


- Major Component Removal and Replacements
 - 5TH PRSD Tank Set Removal
- Will Complete Remaining "Red" OMDP Requirements
- Mods
 - BLT Tile Update
 - Catalytic Coating
 - Ceramic Plug Thicker Cord Mod (Potential)
 - Port And Starboard Wing Leading Edge Reference Marks

TPS Work Content (STS-133)

Priority	<u>Description</u>	<u>LSFR</u>	DLSFR
Mand	Deferred Tile/Fib For 1 Flight (Minimum)	2	6
Mand	In-Flight Tile/Fib Damage	*40	*40
Mand	Operational Damage (Estimate)	*10	*10
Mand	BLT Mod (1-Trip Tile/1-Cover Tile)	4	4
Mand	Putty Repairs form Grind-outs	*20	*20
Mand	Additional Putty Removals (Chits)	10	10
Mand	Corrosion Sampling (Chit J6275A)	5	5
Mand	Catalytic Coating	2	2
Mand	Rudder Speed Brake (Chit 6625)	0	*2
Mand	RTV Sampling (OMS & Elevon)	0	3
P-11	ET Door BRI (STR Side)	24	24
	Total	*117	*126
\$	Projected TPS Removals TOTAL (Estimate) *126		

Issues and Concerns

Payload Bay Configuration (Sidewall Carriers)





SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter Kenneth Nowak

Date 05-20-10

Backup Material

FRWG Presentation (With Minor Changes)

STS 133 DLSFR BACKUP


- Information previously presented at STS-133 LSRR/LSFR
 - STR/TPS Priorities Detailed List
 - Opportunity modifications (Info Only)
 - STS-133 Weight Saver Mission Kit Changes (Info Only)





STS-133 Risk Reduction ~ Percentages Shown

TPS Priorities



- Orbiter's expectations for the work areas are shown on the pie chart for STS-133
- Exact numbers are determined by the KSC Team based on vehicle configuration, access, and flow duration
 - Distribution provides data/risk reduction in all areas of the list and does not allocate all the resources in one area
- Mandatory:
 - Flight damage, OMRS Requirements / Chits, LRU access, & deferred work
 - Corrosion Sampling (10% of total tile allocation) Chit J6275A
 - •Putty repairs in RCC & Window DTA Zones (23% with 10 tile min.) Chit Pending
 - •Continue G/F R & R on a best effort basis zones 2B
 - •Deferred work may be re-deferred with acceptable inspection





OV-103 STR/TPS Priorities

Prioritized Opportunity

- 1 10 1 thru 10 complete on OV 103
- 11.ET Door Remaining STR side of door & leading edge on door 40 tiles (24 STR/16 door) 39 remaining
- 12.MLGD Outboard Aft (1/3 left) 6/door/6 STR)- 24 Tile None completed
- 13. Nose Area 9lb/90 SIP Upgrade to FRCI-12 14* Tiles (7/side) (*103 16 tiles, thruster) 6 remaining
- 14.Base Heat Shield Stinger 9lb/90 SIP Upgrade to AEBT-8 42 Tiles (32/stinger, 10/Box Attach point) 20 remaining
- 15. Body Flap Stub "Piano Key" Upgrade to AETB-8 40 Tile 22 remaining
- **16.**Gap fillers in Subset 2B (Line across MLGD edge) 3 zones remaining





OV-103 STR/TPS Priorities (cont)

- 17.BRI-18 Tile Remaining MLGD (top priority)/ET Door/LESS carrier panels/NLGD
 - 1. MLGD (Inboard forward edge working to AFT door edge) None Completed
 - 2. ET Door 23 remaining
 - 3. LESS panels 8, 9, 10, 7, 6, 5, 4, 3, 2, 1, 11, 12, 13 (in that order) 60 tiles remaining
 - 4. NLGD (attrition do leading edge first) 103 tiles remaining
- 18. Mod work (WLE sneak flow, WLE Horsecollar Gap Fillers) 3 locations remaining
- 19.MADS Instrumentation Failures (placeholder)
- 20. Remaining Gap Fillers & Window BRI-18 121 remaining

Windows 2, 3, 4, & 5 Upper Carrier Panels (top priority)





STS-133 Opportunity Mods previously presented

19735 WLE Spar "Sneak Flow" Protection

- Increases RCC panel damage tolerance by adding a flow restrictor to limit allowable plume flow to 50% across the flow restrictor
- Mod completed at all panel locations with the exception of LH panels 2-4.

19763 Lower WLE Carrier Panel Horse Collar Gap Filler Redesign,

- Redesigns the lower WLE access carrier panel horse collar gap fillers with an enhanced design with additional sleeving
- Mod completed at all panel locations with the exception of LH panels 2-4

• 23227 Connector Saver (ME414-0630) Redesign (OMS Pod, Ku Band)

- Connector Saver mod provides proper interfacial seal and wavy washer engagement retention force to reduce risk of inadvertent demate during use.
- Only Left POD and KU band locations remain to be worked





STS-133 Weight Saver Mission Kit Changes (Info Only)

Changes currently authorized by STS-133 FRD NSTS 17462-133:

- Removal of 5th PRSD Tank Set
 - Tech order configuration updates incorporated in MECSLSI

Aft Winch Removal

- Removed for STS-131 to provide payload clearance
- Decision made to not remove aft winch for weight savings
- Will be re-addressed as part of LMC payload addition CR

Aft Bulkhead Wireless Video System Antenna Removal

- Currently removed for STS-131 to provide payload clearance
- Antenna coverage assessment complete; antenna will remain off for STS-133
- Removal tech order configuration incorporated in MECSLSI





Backup



ICD Status (* = Impact Flight Products)

Document	<u>Title</u>	ECD	<u>Status</u>
ICD-A-21403-ELC4A	ELC4		Baselined
- A05858	Updates to sections 3 and 20	06/02/10	In Tech Review
- A05872	Add thermal surfaces and table	05/27/10	In Tech Review

ICD-A-21449-MPLMA MPLM (PMM) Baselined

- A05793 Add non-compliances 05/28/10 In Review

- A05868 Removal of power reference 05/31/10 In review

Forward Work: Structural/Stress reports; Thermal properties/reports

Issues/Concerns

- None



OMRSD

FII V2 Payload (Post-Mate)

Baselined Files

- P350 MPLM Core Requirement (Permanent Multi-Purpose Module (PMM))
- P554 ISS-ULF5 (Baseline)

RCNs

- None
- FII V4 (Pre-Mate) Baseline
 - PS18163R1 Mission-Unique List
 - PS18164 FIII MUL
 - PS18173R3 Adjacent Pin Test

RCNs

- None
- FII V6 (Shuttle Experiments)
 - XDT701A TriDAR Will be replaced XDT701B Dragon Eye

RCN

None

Issues / Concerns: None



Annex 1: ISS-ULF5-NSTS 21554-A01: Baselined on 11/12/09

L-4 M Update ECD

Customer submittal 04/23/10A

 Data needed: Weight and Mass Properties Update & Drawing Releases

• CR approval 05/16/10

L-1 M Update

• Customer Submittal 07/23/10

Data needed: Weight and Mass Properties

• CR Approval 08/16/10

• Final weight log 08/23/10

Issues/Concerns

None



Time-Critical Ground Handling Requirements

• Activity <u>ECD</u>

Customer Submittal (L-4M) 05/17/10

Release for review (L-3M) 06/16/10

Baseline (L-60 Days) 07/16/10

- Issues / Concerns
- None



Payload Integration Hardware

- Cargo Integration Hardware Allocation Assessment
 - Hardware assessment completed No open work
 - All hardware were delivered:
 - New Build Hardware
 - Crows Foot V826-340001-005
 - Extended Fitting V826-340003-003
- Issues / Concerns
 - None








BACK UP


ELC4 Configuration



ELC4 Berthing Location on ISS




PMM External Configuration (proposed)




Modifications to include: Removal of +Y FRGF, removal of ROFU components, replacement of CBM seal, installation of new forward end cone MMOD shields, feed through seal replacement, visiting vehicle retro-reflector installation, modification of MLI underneath MMOD shields to add Nextel/Kevlar "mattresses", and much more!


PMM Berthing Location on ISS



PMM Rack Configuration for Launch (proposed)



PMM Rack Configuration on Orbit (proposed)



STS-133 Delta Launch Site Flow Review Flight Software Overview

Tom Stansel USA FSW

PRCB 05/20/2010



STS-133 DLSFR (FSW)

- STS-133/OV-103 Flight Software (FSW) Versions
 - Sixth scheduled flight of Operational Increment (OI) 34 Flight Software (SASCB SCR 98107A documents PASS and BFS OI-34 content)
 - Fourth scheduled flight of MEDS IDP VI 07.01/Sixth scheduled flight of MDUF VI 06.00 (SASCB SCR 98113A documents content)
 - Seventh scheduled flight of MAGRS-3S Link 613-996-008 Software (Link-008) (SASCB SCR 98115 documents content)
- STS-133/OV-103 Flight Software Payload Support:
 - ISS ULF5
 - Orbiter Interface Unit (OIU)
 - Orbiter Docking System (ODS)
 - Sequential Still Video (SSV)
 - Payload Power Switching Unit (PPSU)
 - Trajectory Control System (TCS)
 - ISS Caution and Warning (ISSCW)
 - Permanent Multipurpose Module (PMM)
 - Assembly Power Converter Units (APCUs) & Station to Shuttle Power Transfer System (SSPTS) (generic support for both configurations)
- Major New Flight Software Support Items:
 - None



STS-133 DLSFR (FSW)

- STS-133 Source Changes/Edits for Primary Flight Software (Base)
 - SCR 93211A Update of SSMEC Vehicle Data Table (VDT) for Enhanced Accelerometer Operations
 - SCR 93262A Film ET Camera
 - SCR 93267A Removal of the Set and Reset to False Cmds For the RCS Tank Iso Valves
 - SCR 93284 Update PASS HUD Body Flap Warning Limit K-Load
 - DR 126366 SM GPC Failure to Send GCIL Commands
- STS-133 Patch Implementation for Primary Flight Software
 - None.
- STS-133 Patch/Edit Implementation for Backup Flight Software (Base) (included on delivered Mass Memory)
 - SCR 93282 Update PASS/BFS HUD Body Flap Warning Limit K-Loads
- STS-133 Patch Implementation for Backup Flight Software
 - None



STS-133 DLSFR (FSW)

- Products
 - STS-133/OV103 Base delivery schedule (available to field)

FPSB

Shuttle Data Tape
 February 22, 2010 Actual

Mass Memory Unit
 March 12, 2010 Actual

An STS-133/OV103 ADTL SDT/Mass Memory is not planned

- Open Items
 - None
- Concerns/Issues
 - No issues or concerns with STS-133 at this time







EVA Status STS-133/ULF5 Delta Launch Site Flow Review

David Foltz EVA Office Johnson Space Center May 20, 2010



STS-133 Delta LSFR EVA Hardware



Forward Bulkhead PFR

- Portable Foot Restraint, SED33105308-307 installed on forward bulkhead.
- Released T.O. M072-661568-029
- Required to protect for contingency EVA TPS inspection

Lightweight Starboard TSA

- Starboard LWTSA installation Tech Order: M072-660850-006
- Starboard LWTSA Tools installation Tech Order: M072-660858-001

No Port TSA

Winches

- Winch P/N SED33101570-327 on Forward Bulkhead
- Winch P/N SED33101570-325 on Aft Bulkhead



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter	Kenneth Nowak					
Date	05-20-10					

Backup Material

• SSP Systems Drawings Attachment 1

SSP Authorized Modifications/Non-Standard Work Attachment 2

• SSP OMRS Waivers and Exceptions Attachment 3

Launch Window
 Attachment 4

Open Configuration Waivers
 Attachment 5



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter Kenneth Nowak

Date 05-20-10

Overview

SSP System Drawings
 No Issues*

SSP Authorized Modifications/Non-Standard Work No Issues*

• SSP OMRS Changes (RCNs) No Issues*



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Preser	nter	
	Swift	
Date	5-20-10	Page 1

Mandatory RCNs:

NONE

Non-Mandatory Value Added RCNs:

NONE



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter	Kenneth N	lowak
Date	5-20-2010	Page 1

 STS-133 Orbiter/Ferry Mass Properties Have Been Reviewed by Space Shuttle Program Integration and Are Within Specified Limits

	Ferry	Center o	of Gravity (i	nch)		
<u>Case</u>	Weight (lb)	<u>X</u>	<u>Y</u>	<u>Z</u>		
Nominal - Orbiter c.g.	202538	1117.9	-0.3	371.7		
(SCA c.g.)		(1413.6)	(N/A)	(514.0)		
(No CM Ballast, No Fluids Off-Loaded, No Payload Bay Opening)						
AOA - Orbiter c.g.	232474	1108.6	0.0	375.4		
(SCA c.g.)		(1404.5)	(N/A)	(518.2)		
(No CM Ballast, No Fluids Off-Loaded, No Payload Bay Opening)						
TAL - Orbiter c.g.	213101	1067.5	-0.1	376.2		
(SCA c.g.)		(1363.5)	(N/A)	(521.1)		
(3 SSME's Removed, No Fluids Of	f-Loaded, No Payload Bay	Opening, Max W	eight 21700	0 lb)		

X c.g. Limi	ts (Or	<u>biter Coordinates)</u>	Z c.g. Limit	ts (Or	biter Coordinates)
Nominal	=	1060.0 TO 1128.4	Nominal	=	360.0 TO 380.0
AOA	=	1060.0 TO 1116.0	AOA	=	360.0 TO 380.0
TAL	=	1060.0 TO 1120.9	TAL	=	360.0 TO 380.0





STS-133 DLSFR Flight Crew Equipment/GFE

MV6/Tom Goebel

Date May 20, 2010

Page 1

STS-133 DLSFR FCE/GFE Status

Kenneth Brown
Manager, GFE and Flight Crew Equipment Office
Johnson Space Center

BACKUP





STS-133 DLSFR Flight Crew Equipment/GFE

Presenter MV6/Tom Goe	bel
Date May 20, 2010	Page 2

- Delivery dates for Camera C and OBSS SP1 are still being coordinated.
- Tech orders and hardware list noted in following 2 charts.





STS-133 DLSFR Flight Crew Equipment/GFE

MV6/Tom Goebel

Date May 20, 2010

Page 3

Tech Order numbers are identified for reference only. Report generated 5/11/10.

Hardware	Program	Tech	KSC Eng	Eng(TO)	In MEC	Cert	KSC	JSC	Comments	JSC
	Authorization	Order	Need	Release		O/C	Need	Planned		Contact
A (port forward)	FRD	M072-750025-072	5/5/2010	1/7/2005	2/19/2010	С	6/5/2010	6/5/2010	OPF Installation Desirable. Assembly from STS-131. note: Changed Ptu isolators.	Randall Moore
B (port aft)	FRD	M072-750025-073	5/5/2010	1/7/2005	2/19/2010	С	6/5/2010	6/5/2010	OPF Instl for testing PAD Installation. Assembly from STS-131.	Randall Moore
C (starboard aft)	FRD	M072-750025-074	5/5/2010	1/7/2005	2/19/2010	С	6/5/2010	Date In Work.	CCTV to be swapped out. OPF Instl for testing. Pad Installation. Assembly from STS-131. Note:Camera C will be a spare. Note: PTU Isolators wont be available until the beginning of July.	Randall Moore
D (starboard forward)	FRD	M072-750025-075	5/5/2010	1/7/2005	2/19/2010	С	6/5/2010	6/5/2010	OPF Installation Desirable. Assembly from STS-131. Note: Changed PTU Isolators.	Randall Moore
SRMS elbow camera	FRD	MO72-544504-013	5/5/2010	3/3/2008	2/19/2010	С	6/5/2010	6/5/2010	OPF Instl for testing. Pad Instl for flight. Assembly from STS-131.	Randall Moore
SRMS wrist camera	FRD	M072-544504-006	5/5/2010	3/3/2008	2/19/2010	С	6/5/2010	6/5/2010	OPF Installation Desirable. Assembly from STS-131.	Randall Moore
Centerline Airlock Camera (stowed)	FRD	M072-660828-002, plus CCCD stow		3/17/1999	2/19/2010	С			OPF Installation mandatory for alignment. Assembly from STS-131.	Randall Moore
Lefthand Umbilical Camera (aft)	FRD	M072-705001-016	7/2/2010	10/28/2004	2/19/2010	С	8/2/2010	8/2/2010	VAB installation mandatory.	Randall Moore
Righthand Umbilical Camera	FRD	M072-705001-028 M072-705001-027	7/10/2010	10/28/2004 10/28/2004		С	8/2/2010	8/2/2010	VAB installation mandatory.	Randall Moore
Digital Television (DTV)	FRD	M072-710570-007		11/15/2007		С				Larry Schmidt
MCIU/RMS Situational Awareness Display (RSAD)	FRD	M072-710543-001		3/7/2000	2/19/2010	С				Larry Schmidt
Tools for Rendezvous and Docking (TRAD)	FRD	M072-730021-019*		7/20/2007	2/19/2010	С			Installed.	Larry Schmidt





STS-133 DLSFR Flight Crew Equipment/GFE

MV6/Tom Goebel

Date May 20, 2010

Page 4

Tech Order numbers are identified for reference only. Report generated 5/11/10.

Hardware	Program	Tech	KSC Eng	Eng(TO)	In MEC	Cert	KSC	JSC	Comments	JSC
Haraware	Authorization	Order	Need	Release	III WEE	o/c	Need	Planned	Comments	Contact
Video Processing Unit (VPU)	FRD	M072-710338-007		3/2/2008		С				Larry Schmidt
Wireless Video System (WVS)	FRD	M072-344828-001 mount M072-744007-001 UHF M072-744004-012 S-BAND M072-744004-013 S-BAND M072-744004-014 S-BAND M072-744004-016 S-BAND M072-744004-017 S-BAND M072-744004-017 S-BAND		8/24/2004 6/2/2004 3/21/2008 3/21/2008 3/21/2008 3/21/2008 3/21/2008 3/21/2008	2/19/2010	0	4/24/2010			Randall Moore
Space to Space Orbiter Radio (SSOR)	FRD	M072-344828-002 M072-740828-002 Harness		9/24/2004	2/19/2010	С				Larry Schmidt
RMS Sideview Camera (RSC)	FRD	M072-710281-002 M072-000416-006 camera	7/9/2010	11/24/2004	2/19/2010	С	8/9/2010	8/9/2010	Pad instl only. Assembly from STS-131 after return to JSC for repressurization. Note: JSC requests a later delivery date because they want to pressurize as late as possible.	Randall Moore
OBSS Sensor Package 1	FRD	M072-710282-008	5/5/2010	4/18/2008	2/19/2010	С		Date In Work.	OPF Instl for testing. Pad Instl for flight. Unit from STS- 132.	Russell Yates
OBSS Sensor Package 2	FRD	M072-710282-006		4/18/2008	2/19/2010	С			Unit from STS-131.	Larry Schmidt



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-20-10	

SSP System Drawings

The Drawings Baseline Was Released By PRCB S115133 on 01-26-10

V072-000001-290 (Rev. WL) Space Shuttle System (Rel. 05-12-10)

• V072-200213-001 (Rev. A) Mission Equipment Cargo Support (Rel. 02-18-10)

• SGD32104456-301 (Rev. NC) Crew Compartment Configuration (Rel. 02-24-10)

-302 Descent

• V070-000001-003 Orbiter General Assembly

• V070-410100-017 SSME Installation

• 10100-00061-181 Integrated SRB General Assembly (BI-144)

80901000000-530 External Tank Assembly (ET-137)

[•] STS-133 LSRR + 18 days Mission Configuration Product Plan (MCPP) was last published on 02-15-2010 and will be republished at ORR-14 days on TBD.



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter	Kenneth Nowak			
Date	05-20-10			

<u>SSP System Drawings – (Continued)</u>

Ferry Configuration

 V072-000001-291 (Rev. WH) Space Shuttle System Drawing (Rel. 02-11-10)

V072-200213-002 (Rev. A) Mission Equipment Cargo Support (Rel. 02-18-10)


• SGD321004456-001 (Rev. NC) Crew Compartment Configuration (Rel. 02-24-10)

• V072-300055-015 (Rev. BU) Ferry Flight Configuration (Rel. 05-11-09)


SCA 911

STS-133 OCF LAUNCH WINDOW

C. Osgood/USH-483L M. Jamroz/USH-483L September 22, 2009



Note: EOM lighting lines, based on an OMS2 phase angle of 251 deg, are representative only. The ISS beta angle ($|\beta|$ < 60°) for mated operation begins ~ 2/19:52:00 MET (FD4 Rendezvous) and ends ~ 8/13:52 MET.





SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter	Kenneth Nowak				
Date	05-20-10				

Modification Impact Report

- Mission Equipment Modifications and Orbiter Modifications analyzed for impacts to OMRSD, LCC, ICD, EMI, Software, and GSE.
- A total of 4 MCRs have been approved and/or pending mods
- Current MCR impact status:
- No impacts for all six disciplines One or more disciplines with impacts, documentation approved and/or pending approval MCRs 30234



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-133 Delta Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-20-10	

<u>Modification Impact Report – (Continued)</u>

Possible impacts still under review

0

1MRCS REPT. 4650-1 SSP SUMMARY MOD ITEMS - PRCBD MOD BASE LINE STS-0133

PAGE NO. 1

ECP-MCR/KIT SEQUENCE RUN TIME

ORB

12:08 DATE 05/11/2010

	STAT	ITEM/KIT NUMBER	SEQ	
PRCB	PRIO			
MCR/ECP	SITE	TCTI NUMBER	EISN NO.	DESCRIPTION / GENERAL REMARKS
AUTHDATE	FLT			
	PLND	J6163	0103 002	OV-103 BODY FLAP PDU GEARBOX FLUID LEVEL INSPECTION
ORB-0090B	MAND			
	KSC		SPAR	
2007-01-30	039			
	AUTH	J6275A	0103 004	ORBITER STRUCTURE IML SURFACE CORROSION SAMPLING INSPECTION
S-J6275A	MAND			
	KSC		SPAR	CORROSION SAMPLING CAPABILITIES WILL BE PROJECTED AT LSFR,
2008-02-26	039			
				AND FINALIZED AT DLSFR FOR EACH FLOW.
	AUTH	J6526	0103 001	EVALUATION OF OMS POD LI-900 TILE INSTALLED ON 0.090" SIP
S-J6526	MAND			
	KSC		SPAR	EFFECTIVITY: OV-103, FLT. 39
2009-07-01	039			
	PLND	J6531	0103 002	METRIS SCAN OF OV-103 LOWER SURFACE
S-J6531	MAND			444
	KSC		SPAR	OV-103, FLT. 39
2009-06-26	039			
	_	J6534	0103 001	PUTTY REPAIR TILE REPLACEMENT FOR RISK REDUCTION
S-J6534	MAND			
	KSC		SPAR	EFFECTIVITY: OV-103, FLTS 38 & 29
2009-07-29	039			
	3	TCE 40	0100 000	TH TERRU TI TOUR DOOD ARRIVE THERETIS TWODESTA
	AUTH	J6543	0103 002	ET FERRY FLIGHT DOOR ATTACH FITTING INSPECTION
S-J6543	MAND			
	KSC		SPAR	NDE OF FERRY FLT DOOR ATTACH FITTINGS WILL ONLY BE REQ'D
2009-09-17	039			
				FOLLOWING A F/FLT BACK TO KSC. F/FLT ONLY.

0 76577	AUTH	J6577	0103 000	AMES GAP FILLER REMOVAL AND REPLACEMENT
S-J6577	MAND KSC		SPAR	GAP FILLER REPLACEMENTS WILL BE PERF'D OVER REMAIN ING
2010-01-29	039			MANIFESTED FLTS BASED ON PROG LSFR PRIORITIES.
	PLND	J6578	0103 000	CAPTURE OV-103 OUTPUT WAVEFORMS TO ADDRESS 1N3600 DIODE CON-
S-J6578	MAND KSC		SPAR	CERNS
2009-12-14	039			
S-J6585	PLND MAND	J6585	0103 001	OPTIGO AND Z-SCAN OF BLT PROTUBERANCE TILE
	KSC		SPAR	BLT TPS SCAN HAS BEEN INTEGR'D INTO & IS ACCOMMODA TED BY
2010-01-14	039			CURRENT STS-131/STS-133 OPF PROCESS'G PLANS
	PLND	J6587	0103 000	R&R OF IMU S/N 213 WITH S/N 204 ON OV-103 IN IMU SLOT1 PRIOR
S-J6587	MAND KSC		SPAR	TO STS-133
2010-02-11	039			
	PLND	J6599	0103 000	PRE-FLIGHT CITRIC ACID FLUSH
S-J6599	MAND KSC		SPAR	REQUESTED CITRIC ACID FLUSH WILL BE INTEGRATED INTO PLANNED
2010-03-05	039			POST FLT WASTE TANK SERVICING PROCESS
				TOOT TIT WASTE TANK SERVICING TROUBS
s-J6600	AUTH MAND	J6600	0103 000	ORBITER MEASUREMENTS FOR STS-133
	KSC		SPAR	LATCH AND TRUNNION MEASUREMENTS ARE INTEGRATED INT O
2010-03-29	039			PLANNED STS-133 MIDBODY OPERATIONS.
	PLND	J6601	0103 000	STS-133 PAYLOAD CLOSE CLEARANCE MEASUREMENT
S-J6601	MAND KSC		SPAR	THE EXPRESS LOGISTICS CARRIER SCUFF PLATE CLEARANC E
2010-03-22	039		JEAN	IND DAIREDS BOSISIICS CARRIER SCOFF FRAIE CHEARANC E
				MEASUREMENTS WILL BE INTEG'D INTO P/L HANDLG OPS

	AUTH J6613	0103 000 DTV MUX BYPASS SWITCH VERIFICATION	
S-J6613	MAND		
	KSC	SPAR DIGITAL TV MULTIPLEXER BYPASS SWITCH VERIFICATION IS	
2010-04-13	039		
		INTEGRATED WITH PLANNED OPF COM TESTING.	
	PLND J6620	0103 000 EVALUATION OF CLEARANCE BETWEEN CERAMIC PLUG & CARRIER PAN	EL
S-J6620	MAND		
	KSC	SPAR FASTENER	
2010-04-13	039		

1MRCS REPT. 4650-1 SSP SUMMARY MOD ITEMS - PRCBD MOD BASE LINE STS-0133

ECP-MCR/KIT SEQUENCE RUN TIME

ORB

12:08 DATE 05/11/2010

2

PAGE NO.

	STAT	ITEM/KIT NUMBER	SEQ	
PRCB	PRIO	MOMT 127.0000		
MCR/ECP	SITE	TCT1 NUMBER	EISN NO.	DESCRIPTION / GENERAL REMARKS
AUTHDATE	FLT			
	AUTH	J6622	0103 001	THERMAL WINDOWS TORQUE EVALUATION FOR OV-103
S052924DV	MAND			
	KSC		NSW	
2010-05-06	039			
	AUTH	J6625	0103 000	RSB TE TILE INSPECTION FOR STS-133
S052924DT	MAND			
	KSC		NSW	
2010-05-04	039			
	AUTH	J6626	0103 000	WASTE WATER SAMPLE AND URINE SOLIDS FILTER REQUEST
S-J6626	MAND	00020	0103 000	MADIE WATER DANFIE AND ORTHE DOLLDS FILLER REQUEST
5 00020	KSC		SPAR	SAMPLING&FILTER REPLACEMENTS WILL BE PERF'D W/POST FLT
2010-05-06	039		SIAK	SAMPLINGGETHIER REPLACEMENTS WILL BE PERF D W/FOST FIT
2010 03 00	033			POTABLE & WASTE WATER SERVICING/DE-SERVICING.
	3	W.C.F.C.1.3	0100 001	CDOURD I TOURNING MONTHODING GUGHTM (CIMC) INCHILI HICK
005000407	AUTH	K6561A	0103 001	GROUND LIGHTNING MONITORING SYSTEM (GLMS) INSTALLATION
S052924CZ	SCHD		NCH	
2000 10 12	KSC 039		NSW	
2009-10-13	039			
	AUTH	K6566	0103 001	SSME NOZZLE PURGE HOT WALL CORROSION PREVENTION
S052924DA	SCHD			
	KSC		NSW	
2009-10-13	039			
	PLND	K6610	0103 000	DUAL DOCKING CONTAMINATION SAMPLING
S-K6610	MAND			
-	KSC		SPAR	SAMPLE WIPES OF SELECTED AREAS OF RADIATORS & MID-BODY WIRE
2010-04-13	039		· · ·	· · · · · · · · · · · · · · · · · · ·
_				TRAY COVERS WILL BE TAKEN POST-FLT.NIB.

	AUTH	6589A	0103	000	CREW	MODULE	CONTAMINATION	SAMPLING	
S052924DU	MAND								
	KSC		NSW						
2010-05-06	039								
TOTAL MODS =		22							

1MRCS REPT. 4650-1	SSP SUMMARY MOD ITEMS - PRCBD MOD BASE LINE STS-0133	PIH
PAGE NO. 3		
	ECP-MCR/KIT SEQUENCE	RUN TIME

12:08 DATE 05/11/2010

	STAT	ITEM/KIT NUMBER	SEQ	
PRCB	PRIO			
MCR/ECP	SITE	TCTI NUMBER	EISN NO.	DESCRIPTION / GENERAL REMARKS
AUTHDATE	FLT			
000050		7006 240001 001	0001 000	ADDITIONAL MADDIADE TO CURDODE CEC 122
008852	PLND	K826-340001-001	0001 000	ADDITIONAL HARDWARE TO SUPPORT STS-133
NOT REQD	KSC			ADDED PER V826-340001 B04
039	KSC			WDDED LEK A050-240001 D04
039				

TOTAL MODS = 1

1Date: 05/11/10 12:14 PCASS Page: 1

FLIGHT-SPECIFIC

Approved STS-133 OMRS Waivers and Exceptions

		PRCBD NU	MBER			STS	
EXC				ABSTRACT RAS REQUIREMENTS	EISN PAYLOAD	BEG	END
+	ORB	S053300BÇ EV10771			103	039	039
		S053300DE EV10763	(A)	OMRSD EXCEPTION REQUEST - WASTE WATER TANK FLUSH (EV10763)	103 104		039 033
	RCS	S053296YF EK10327	(A)	OMRSD EXCEPTION REQUEST - RIGHT RCSOXIDIZER B-LEG PAD REGULATOR L OCKUPPRESSURE (EK10327)	0023	032	040
W	ET	S053293F2 WK03850R1 (STS-093)	. (A)	L02/LH2 TANK PRESSURE MONITOR FOR MOVE	ET	099	999
	OMS	S053296UN WK10299	í (A)	OMRSD WAIVER REQUEST - RP03 TK302 DYNATUBE LEAK RATE (WK10299)	0023	032	040
	ORB	S053298VM WK10557R1		~	103	033	042
		S053299BE WK10603	3 (A)	OMRSD WAIVER REQUEST - FORWARD OXYGEN REGULATOR LOCK UP PRESSURE (WK10603)	103	034	039
		S053299JU WK10653	J (A)	OMRSD WAIVER REQUEST - WATER SPRAY BOILER #1 EXCEEDED 44 PSIA MAX	103	035	040

IMUMLIMITATION (WK10653)

RCS	S053298VTR1	OMRSD WAIVER REQUEST -	0023	035 043
	WK10559 (A)	RIGHT RCS OXIDIZER B-LEG SECONDARY REGULAT ORLOCK UP HIGH (WK10559R1)		
SRB	S053293WA WK03886 (A) (STS-103)	LH FWD AND RH MID SRB JOINT TEMP SENSORS	ВІ	099 999

--

1

Date: 05/11/10 12:14 PCASS Page: 2

FLIGHT-SPECIFIC

Approved	d	STS-133 O	MI	RS Waive	rs	s and Ex	CE	eptions			
0	 °	Waivers '	0	Except	0	Deviat	0	Cannib	0	Total	- + 。
°	-+		+-		+-		+-		+-		-°
° Total Extracted	•	7 '	0	3	0	0	0	0	0	10	•

Item #	Authority	Date	Waiver Description	Effectivity	Wad
47	S052310A	02/14/91	Fly with FRSI instead of tile	OV-103, Flight 12 & Subs (flight by flight evaluation)	OK TO RETIRE S061954B MV 4-2 RTF-130 Briefing
53	S052428A	03/27/91	Allows specified flights to fly with interim TPS repair after each mission to minimize damage to surrounding tile during ferry flight	STS-37, STS-39, STS-40, STS-42 thru STS-999	STAYS OPEN
101	S076972	11/19/91	Permit the modified GPCs (AP101-S) Battery Back-up Unit to fly with annotated fastener improvements without rolling the LRU Part Number	STS-42, STS-44, STS-47 and STS-49 thru STS-999	STAYS OPEN
327	S115114VR5	03/17/05	Partial installation of M072-784633-014 (harness installation - interface panel - MADS #3). The M072-784663-014 Technical Order was established to incorporate the crossover bracket modification at locations X0863 and X0750. The dash number configuration for the Technical Order was not baselined until January 25, 2005 (PRCBD S115114VR2). This area was closed out before this time and would cause significant impact to verify configuration of this Technical Order dash number -014.	OV-103, Flight 31 OV-103, Flight 32 WAIVER for STS-121	INS-3-28-279 (installed Tech Order)
			***** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS **	***	
328	S115114WR1	04/07/05	Partial installation of M072-794500-004, for Integrated Vehicle Health Monitoring (IVHM) harness installation, calls for the removal of the unused IVHM harness and routing hardware. This requirement was manifested after the Bay 13 Longeron Bridge installation was complete. With the installation of the bridge, the removal of the IVHM harness is no longer possible without the removal of the bridge.	OV-103, Flight 31 OV-103, Flight 32 WAIVER for STS-121	OEL-3-31-304 PTL OEL-3-31-4432 PTL
			***** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS **	***	

Item #	Authority	Date	Waiver Description	Effectivity	Wad
329	S115114AM	08/15/05	The following requirements are waived to allow OV-103, Flight 31 to fly (ferry) with the following out-of-configuration conditions:	OV-103, Flight 31	Ferry Flight from Dryden
			1) V070-391139-025 (blanket under window #1 removed for ferry flight)		
			 M072-421502-002 (did not perform acetone wipe prior to universal thruster plug assemblies - procedural omission) 		
			3) V070-753110-003 (camera mount will not be installed for ferry flight)		
			***** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS *	****	
330	S115114VR15	09/16/05	The following requirement is waived to allow OV-103 to ferry from DFRC to KSC with the following out-of-configuration condition:	OV-103, Flight 31 Ferry Flight	Ferry Flight from Dryden
			TCS blanket V070-362917-001 located at Door #44 NOT installed.		
			***** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS *	****	

Item #	Authority	Date	Waiver Description	Effectivity	Wad
331	S115114VR15	09/16/05	The following requirement is waived to allow OV-103 to ferry from DFRC to KSC with the following out-of-configuration condition:	OV-103, Flight 31 Ferry Flight	Ferry Flight from Dryden
			 Two switches on Panel A15 will ferry without switch guards (P/N G070-700904-001). In lieu of switch guards at two locations, tape was installed. 		
			 Eight GSE switch guards were left installed and not removed as required by Technical Order M072-710700-002 as called out in the ferry flight drawing. 		
			 Three switch guards are not installed on Panel L4 for TACAN circuit breakers. The procedure does not include the switch guard installation. 		
			***** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS *	****	
332	S115121TR8	05/04/06	The following requirement is waived to allow OV-103 to fly with the following out-of-configuration condition:	OV-103, Flight 32	
			M072-794500-004 IVHM harness installation Bay 13 called out by MECSLSI V072-200201 NOT removed from OV-103.		
			During STS-114 processing this Tech Order configuration called for the removal of an un-used IVHM harness along with the routing hardware. At the time the Tech Order was made a requirement for Flight 31, the Bay 13 longeron had already been installed for flight. The harness was demated and stowed inplace per MR and was deferred to a future flight at which time Bay 13 longeron will be removed since the Bay 13 longeron was not removed this flight, a configuration waiver is needed for STS-121.		

Item #	Authority	Date	Waiver Description	Effectivity	Wad
333	S115121TR8	05/04/06	The following requirement is waived to allow OV-103 to fly with the following out-of-configuration condition:	OV-103, Flight 32	
			Partial installation of M072-784633-014 (harness installation - interface panel - MADS#3). The M072-784633-014 Tech Order was established to incorporate the crossover bracket modification at locations X0863 and X0750. The dash number configuration for the Tech Order was not baselined until January 25, 2005 (PRCBD S115114VR2). This area was closed out before this time and would cause significant impact to verify configuration of this Tech Order dash number -014.		
			***** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS **	***	
335	S115116NR2	08/18/06	The following requirement is waived to allow OV-103 to fly with the following out-of-configuration condition:	OV-103, Flight 33	
			M072-794500-004 IVHM harness installation Bay 13 called out by MECSLS V072-200195 not removed from OV-103.	1	
			During STS-114 processing, this Tech Order configuration called for the removal of an unused IVHM harness along with the routing hardware. At the time the Tech Order was made a requirement for Flight 31, the Bay 13 longeron had already been installed for flight. The harness was demated and stowed in place per MR and was deferred to a future flight at which time Bay 13 longeron will be removed since the Bay 13 longeron was not removed this flight, a configuration waiver is needed for STS-116.	e	

Item #	Authority	Date	Waiver Description	Effectivity	Wad
336	S115116NR2	08/18/06	The following requirement is waived to allow OV-103 to fly with the following out-of-configuration condition:	OV-103, Flight 33	
			M072-794500-004 IVHM harness installation Bay 13 called out by MECSLS V072-200201.	1	
			During OMDP, the crossover bracket modification was successfully implemented at all four locations with no technical issues by engineering defined by Orbiter drawings as well as three Tech Orders (M072-794011, M072-794021 and M072-794051). The M072-784633-014 Tech Order was established to incorporate the crossover bracket modification at two locations (X0863 and X0750).		
			At the X0863 location, M072-784633-014 called for the removal of a clamp and six screws to reflect the change harness mounting due to the new wire tray shape. TPS OEL-3-31-245 incorporated the electrical portion of this modification per the vehicle drawings as well as the three tank set harness Tech Orders. During STS-114 processing, the WAD was reviewed and it was determined that an error exists in the M072-784633 engineering. This Tech Order reflects harness routing at the X0863 that does not reflect the as-built configuration on the Orbiter. A one flight configuration waiver was processed and approved for STS-114 and STS-121. All hardware on this Tech Order supports MADS wire routing, there were no observed wire		

routing violations noted during Flight 31 midbody closeout and all MADS testing will be completed and verified. No technical issue with hardware, installation, or function of MADS. There was no access to this area this flow to perform wire routing as-designed condition. A configuration waiver is

needed for STS-116 for this Tech Order.

Item #	Authority	Date	Waiver Description	Effectivity	Wad
337	S115116NR4	10/27/06	Tech Order M072-544501-087 - install, M072-544501-027 - remove, -087 configuration is for the new over-center stops being installed. Mission-unique loads will not require these new stops. Program decision was made to not remove the RMS.	OV-103, Flight 33	
			This configuration will incorporate the over-center stops mod, the change is to all four MPM locations. The new stops, replace existing GFE stops, incorporate a stronger design to address mission-unique loads that have a potential to exceed the current mechanism capability. The decision was made not to incorporate this mod during STS-116 flow due to the low potential for load exceedence. Since -087 established the over-center stops mod along with other mods that were completed for this flow,a configuration waiver is needed for STS-116. In addition the removal of the -027 from the previous mission was not completed.		
338	S115116NR4	10/27/06	Tech Order M072-794021-026 install, M072-794021-019 remove, -026 configuration is for the new over-center stops being installed. The change is rerouting and retaping of the wire harnesses near the over-center stops to alleviate any interference. Program decision was made to not remove the RMS.	OV-103, Flight 33	
			This configuration would reroute and retape harnesses on the MPMs to support the over-center stops mod. Since -026 established a new configuration in support of the over-center stop mod and this was not worked this flight, a configuration waiver is needed for STS-116. In addition, the removal of the -019 from the previous mission was not completed.	,	

Item #	Authority	Date	Waiver Description	Effectivity	Wad
342	S115120DR3	09/12/07	The following requirement is waived to allow OV-103 to fly with the following out-of-configuration condition:	OV-103, Flight 34 thru OV-103, Flight 999	
			Tech Order M072-784633-015 harness installation - interface panel - MADS#3 called out by MECSLSI V070-200199 was established to re-route MADS harness in support of SSPTS at location X0863. There was no access to this area this flow to re-route harness to meet as-designed congiguration. At this time there is NO plan to ever open up this area again.		
344	S071024MP	12/20/07	During maintenance of an Advanced Master Events Controller (AMEC) it was discovered that the module cards are able to translate upward, away from connectors. The cards are retained by friction applied by wedge-locks. An assessment determined a 0.070 upward card translation, would result in card disengagement from connectors. The wedge-lock system can not assure the cards will not translate upwards. The AMEC vendor (Boeing Autonetics) is no longer on contract supporting SSP. A design proposal is to provide a secondary connector retention using the AMEC covers. The new design new lids will limit the upward translation to 0.055. The new design will reduce the milled section of the cover and add silicone pads to provide shock absorption. Due to the absence of the original vendor and no current alternate drawings available for the AMEC the modification is being requested via a program directed Material Review (MR). P/N MC450-0016-0029	OV-103, Flight 35 OV-104, Flight 30 OV-105, Flight 21	
			S/N U6F0002, U6F0003, U6F0004, U6F0006, U6F0007, U6F0009, U6F0010 and U6F0011		
			***** SEE NSTS 07700 VOLUME IV BOOK 2 FOR COMPLETE DETAILS *	****	

Item #	Authority	Date	Waiver Description	Effectivity
352	S115128CR6	10/05/09	The Post-Landing/Ferry Flight Configuration requirement is waived to allow OV-103 to ferry from DFRC to KSC with out-of-configuration conditions for removal of FCV assemblies for ferry flight and install MPS cap and plug set GSE plugs:	OV-103, Flight 37 Ferry Flight
			Three MPS GH2 FCV solenoid and poppet sleeve assemblies (P/N 80420-1301) for each engine.	
			Engine 1 GH2 FCV LV56	
			Engine 2 GH2 FCV LV57	
			Engine 3 GH2 FCV LV58	
			Note: The following MPS cap and plug set GSE plugs will be installed in place of the FCVs: 3 G070-602824-001.	
			RATIONALE: There is adequate access and time to remove the requested parts. Removal of these parts is well within USA's experience base. These valves have been removed numerous times at KSC. Removal at DFRC will be no different than removal at KSC. There is no increase in risk performing this work at DFRC, and the early removal will better support the upcoming manifest. There is no GH2 FCV position specified for ferry flight, and no blanket pressure is required. The manifold is firmly mounted/ restrained and requires no additional support due to removed FCV components.	

Wad