

SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-20-10	

Program Freeze Point

PRCB Presentation

S115335A



Flight Operation & Integration*

SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-20-10	

MO3/USA-PI

Baseline the STS-335 Mission Specific Requirements and Flow Plans.

The STS-335 Integrated Launch Site Requirements were established by PRCBD S115335 dated 03-25-10. This CR and the Associated Data Package were reviewed at the 05-03-10 FRWG.

riigiit Operation & integration		WO3/O3A-F1
Orbiter Engineering*		USA-OE
Orbiter GFE*		MV5
Payload/Cargo Engineering*		USA-PI
Launch Vehicle Processing*		PH-A
	Status in BackUp	
KSC Integration*		MK-SIO
Flight Software		USA-FSW
EVA		XA
KSC ISS and Payload Processing*		UB-R3
SSME	Baseline at DLSFR	MP21

*Backup material included





Presenter MO3/Phyllis	Grounds
Date May 2010	Page 1

STS-335

Launch Site Flow Review (LSFR)

Flight Requirements Status

FRWG May 3, 2010

PRCB May 20, 2010

Phyllis Grounds, MO3 MIM Robert Reynolds, USA Flight Mgr



SPACE SHUTTLE PROGRAM


Flight Management Office NASA Johnson Space Center, Houston, Texas



Presenter MO3/Phyllis Grounds

Date May 2010

Page 2





SPACE SHUTTLE PROGRAM

Flight Management Office NASA Johnson Space Center, Houston, Texas

STS-335 Launch Site Flow Review



Presenter MO3/Phyllis Grounds

Date May 2010

Page 3

LAUNCH

11/29/10

39A/ MLP 3

CREW SIZE: 4 UP/10 DN

CONFIGURATION

OV-104(33)

LP04;RP01

ET-122

BI-146

RSRM-114

(1) TBD (2) TBD (3) TBD

OI-34

SRMS, ODS, OBSS, APCU'S

ROEU, SPDU

PAYLOAD

MPI M

ORBIT

51.6 DEG

122 NM

DIRECT INSERTION

DURATION: 11 + 1 + 2 DAYS

CONSUMABLES

CRYO TANK SETS

GN2 TANKS 5 (FULL)

~95 hrs (H2 limited) PAD HOLD FWD RCS 2175# (MIDPOINT)

5 (FULL)

AFT RCS 4970# (FULL) 22760# (FULL)

OMS

LANDING

SITE **KSC**

TAL ZARAGOZA

ALT. TAL **MORON & ISTRES**

SCA 911





STS-335 LON-MPLM Mission Overview

Presenter MO3/Phyllis Grounds		
Date May 2010	Page 4	

Mission Objectives:

- Transfer stranded crew and critical support equipment/supplies required for return of the stranded Shuttle crew from the ISS to the rescue Orbiter
- Transfer available water from Shuttle to ISS
- Berth MPLM to ISS Node 2 nadir port, activate and checkout the MPLM
- Replenish depleted crew supplies from ISS (per transfer priority list)
- Transfer ISS System/Science Racks, RSP, and RSR (TBD quantity) racks to ISS
- Transfer O₂, N₂ (if consumables allow)
- Miscellaneous Items
 - TPS Inspection
 - FD2 TPS inspection
 - Rbar Pitch Maneuver with ISS imagery
 - Focused Inspection (if required)
 - Late inspection





PERFORMANCE MARGIN

Presenter MO3/Phyllis Grounds

Date May 2010

Page 5

PERFORMANCE MARGIN

•	SIMULATION MARGIN (CIRAF335)		+4236
•	WEIGHT CHANGES SINCE SIMULATION		
	• PAYLOAD	- 2075	
	• OPERATOR	+22	
	ORBITER	<u>+114</u>	
	TOTAL WEIGHT CHANGES	- 1939	+1939
•	OTHER PERFORMANCE PROJECTIONS		
	RENDEZVOUS ALT OF 190 NM		+1160
	 PROTECTION FOR DOL DISPERSIONS 		- 700
	SRB – M.P. UPDATES		- 134
	 SRB – BR / 1.55 MIL HIGHER THAN 0.3705 AVG 		+310
	 PROJ TO 5 MIN WINDOW FROM INPLANE 		- 600
	PERFORMANCE CHANGES ADJUSTMENT		<u>- 136</u>
•	CURRENT BASELINED APM (05/04/10)		+6075

VOLUME III: ASCENT PERFORMANCE MANAGER'S RESERVE GUIDELINE AT LSFR IS 400 LBS





tor to o mile on the part of t		
	Presenter MO3/Phyllis Grounds	
	Date May 2010	Page 6

FLIGHT MASS PROPERTIES

	TOUCHDOWN	MACH 3.5
CASE	WEIGHT pounds (LIMIT)	X C.G. inches (LIMIT)
NOMINAL	223019 (233000)	1082.5 (1075.7)
RTLS	233038 (245000)	1082.0 (1077.2)
TAL	231675 (244000)	1082.1 (1077.2)
AOA	227639 (242000)	1080.4 (1075.7)
CONT RTRN	202285 (233000)	1080.2 (1075.7)

NOTE: 102 LBS AFT FUS. BALLAST (EMPTY BOXES)

RTLS INCLUDES 185 SEC ARCS & 25 SEC FRCS DUMPS TAL INCLUDES 120 SEC ARCS & 65 SEC FRCS DUMPS

ESTIMATES BASED ON CIRAF335 AND MODIFIED FOR WEIGHT CHANGES THRU 05/04/10.

OV-104 FLIGHT 33 CONFIGURATION UPDATES

PRCB

May 20, 2010

Alvin Jenkins, USA Orbiter Element Greg Manuel, Boeing VPE





STS-335 OV-104 Flight 33 – LSFR Updates

Program Authorization Is Requested For The Following:

No new Orbiter modifications have been identified to date for implementation

Information Only:

- Potential modifications
- Chits
- Potential OMRS Exceptions

Back-up:

- Modification Records and MECSLSI Updates Summary
- Engineering, Hardware and Certification Status
- TPS Risk Reduction Priorities List





Potential Modifications

- TPS Ceramic Plug/Insert Redesign (TAD 30286 OCR/D S165481)
 - Redesigns ceramic plug sleeving/retainer for all 0.75" diameter plugs & 0.875" shorter diameter plugs (0.75" length and less) to increase cord thickness to meet the installation torque requirements preventing plug from potentially backing out due to vibration loads during ascent
 - Standard Specification ERD 5-21-10
 - Engineering (Installation) ERD 5-28-10
- Starboard LWTSA Cushion
 - Definition of light-weight tool stowage assembly (LWTSA) contents configuration is TBD



Chits

CHIT	TITLE	
J6399	0-Gauge Protection for OV-104, Flights 31-35	
J6527	FRCS THRUSTER CANISTER STUD INSPECTIONS - F5R AND F5L	
J6528	PUTTY REPAIR TILE REPLACEMENT FOR RISK REDUCTION	
J6543	ET FERRY FLIGHT DOOR ATTACH FITTING INSPECTION (FERRY FLIGHT ONLY)	
J6577	AMES GAP FILLER REMOVAL AND REPLACEMENT	
J6589A	Crew Module Contamination Sampling	
J6599	PRE-FLIGHT CITRIC ACID FLUSH	
J6614	DTV MUX BYPASS SWITCH VERIFICATION	
J6626	WASTE WATER SAMPLE AND URINE SOLIDS FILTER REQUEST	
J6629	CAPTURE OV-104 OUTPUT WAVEFORMS TO ADDRESS DIODE CONCERNS (IN REVIEW)	
JXXXX	WLE RCC 25 mm IR THERMOGRAPHY on panels 9L and 18R (POTENTIAL)	
JXXXX	CERAMIC INSERT EVALUATION (POTENTIAL)	
JXXXX	STS-335 CLOSE CLEARANCE VERIFICATION (POTENTIAL)	





Potential OMRS Exceptions

- Nominal Time Age Cycle Items will have to be performed prior to the 33rd flight of OV-104 (ref. USA Change Eval of CR S042013HW)
- In addition, the following Structures and ECL requirements will be due and are very intrusive in that they drive radiator and waste tank removals:
 - Radiator Hinge Inspection Requirements
 - V30CB0.100 SPC DTL INSP LH MID-FWD RAD VAFB33I33F
 - V30CC0.120 SPC DTL INSP LH MID-AFT RAD VAFB33I33F
 - V30CD0.100 SPC DTL INSP LH AFT RADIATO VAFB33I33F
 - V30CF0.100 SPC DTL INSP RH MID-FWD RAD VAFB33I33F
 - V30CG0.120 SPC DTL INSP RH MID-AFT RAD VAFB33I33F
 - V30CH0.100 SPC DTL INSP RH AFT RADIATO VAFB33I33F
 - V30CD0.120 SPC DTL INSP LH AFT EXP JNT VAFB33I40F
 - V30CH0.120 SPC DTL INSP RH AFT EXP JNT VAFB33I40F
 - The requirement to flush the waste water tank with nitric acid (Waste Water Tank V070-623022-003 C00AB0.230.003) is due prior flight 33

STR and ECL PRT's have completed the requirement review and rationale exists to extend past the 33rd flight







SPACE SHUTTLE PROGRAM Space Shuttle Orbiter Project Office NASA Johnson Space Center, Houston, Texas

NASA

STS-335 LSFR Flight Crew Equipment/GFE

Presenter
MV6/Bill Lane

Date May 20, 2010

Page 1

STS-335 LSFR FCE/GFE Status

Kenneth Brown
Manager, GFE & Flight Crew Equipment Office
Johnson Space Center



SPACE SHUTTLE PROGRAM Space Shuttle Orbiter Project Office NASA Johnson Space Center, Houston, Texas

STS-335 LSFR Flight Crew Equipment/GFE

Prese	nter	
	MV6/Bill Lane	
Date	May 20, 2010	Page 2

- GFE hardware delivery dates under review manifest change moving STS-134 to November results in cameras and Sensor Package 1 coming from OV-103 post STS-133 (was OV-105 post STS-134)
 - Final delivery dates to be partnered by the dLSFR
- Sensor Package 1 LDRI availability no longer an issue once STS-134 moved after **STS-133**
 - STS-134 plan remains to leave OBSS on ISS
 - STS-335 LDRI to come from OV-103 post STS-133
 - LDRI qual unit verification as flight spare continuing (decision package to be brought to OPO)
- Tech orders and hardware list noted in backup charts, reference only
- No modifications planned for STS-335
- Starboard TSA currently manifested for flight but final decision expected at dLSFR
- Planned PTU swap for cameras D and Elbow in order to manage 5 flight cert limit no affect on planned delivery date

STS-335 ISS – LON MPLM Launch Site Flow Review

Payload Cargo Engineering Status

Maria Randall

281-212-6269

FRWG: 05/03/10

PRCB: 05/20/10



Engineering Flight Product Status

Drawing No	<u>Title</u>	Rev	EO	Released
V072-200215	MECSLSI	New	-	04/26/10
VA72-200215	Cargo Arrangement	Α	A01	04/26/10
VD72-200215	Avionics Diagram	Α	A01	04/26/10
VS72-200215	Integrated Schematic	Α	A01	04/26/10
VS70-540434	Retention Schematic	New	_	03/01/10

Engineering Open Work

None

Mission-Unique Deviation to NSTS 60523

- NSTS 60523, Orbiter/Payload Integration Standardization Document, defines a standard payload avionics configuration for all vehicles and requires PRCB approval for changes or mission-unique exceptions
- PRCB CR S070126 : mission-unique waiver to NSTS 60523 (Approved through *PRCB 03/31/10*)
 - To allow non-standard cables installed in OV-104 during the STS-132 flow to remain installed
 - Cables do not remove or change any of the standard avionics services provided to standard Shuttle equipment flown in support of ISS missions



OMRSD

• FII V2 Payload (Post-Mate)

Baselined Files

• P321 APCU Requirements

P350 MPLM Requirements

RCNs Baseline

• PP18192 P1558 – ISS-LON Baseline 04/06/10A

• FII V4 (Pre-Mate)

<u>RCNs</u>	<u>Release</u>	<u>Baseline</u>	
• PS18201	F2V4 Mission Unique List	06/09/10	06/16/10
• PS18202	FIII Mission Unique List	06/09/10	06/16/10
• PS18TBD	Adjacent Bent Pin Test	06/09/10	06/16/10

- FII V6 (Shuttle Experiments) None
- Issues / Concerns
 - None



Cargo Close Clearance Process

- The following Close Clearance areas have been identified as standard close clearance for MPLM flights and will require as installed measurements:
 - MPLM Scuff Plate to MPM
- Chit measurements will be performed at the PAD after payload installation



ECD: DLSFR (06/17/10)

KSC Launch and Landing Project

STS-335

Launch Site Flow Review

NASA Flow Director

A. Brewer

USA Flow Manager

R. Propst

May 20, 2010





	STS-33	5 KSC Mileston	e Interfac	e Chart	OPR: USA - R. GILLETT NASA - C. FORD,	
OV-104 / 33 / LON - MPL CREW / DURATION: 4 U	M ss	SP APPROVED PRCB 9-24-09 (R	EF. CR #S042013HW		nnor orrono,	
ET-122 / BI-146 / RSRM	114 / MLP-3 / PAD-A / VAB HB3	Status as of: 04/20/2010				
		CY2010				CY2011
	PR MAY JUN	JUL AUG	SEP	OCT NO	V DEC	JAN
FDRD B/L: 9-24-09			2 ▽	CEIT		
OPF R/I: 5-26-10	14 T STS-132 LAUNCH (REF.					
OPF R/O: 11-5-10	26 🛇 ORB. LANDING @	1	16[]22 L	ON CALL-UP WINDOW		
SSV TO PAD: 11-12-10	27	142+3H+6D			PROCESSING	
LAUNCH: 11-29-10	6 ∅ LSFR			25 (ORB/ET M		
	17 ∅ DLSF	Ř I		(7+0C) VAB OP		
	<u> </u>		_	1 ∅ SSV T		
SŞME RE	M. / INSTLN. COMPLETE 6 ✓		∇15			
	İ			(21+8C)	PAD A OPS	
	į				29 (C) LAUNCH	
	į				MISSION	
					5 ♦ ORB. LANDIN	NG @ KSC
			PAYLO,	AD TO PAD (
	REVIEW STS-134 L		(18+00	-	CLOSEOUTS	
			ET/SRB MATE	7		
	STS-134 L	AUNCH (REF.) (\$\infty\$ 29				
		MLP-3 @ P/	I .			
	I RV	5[MLP-3 MO\	/E TO VAB HB-3			
7	L i V		MLP-3 IN HB-3			
~~\``\	Ť		2 9 MLP-3 STA			
~(()\r	į		10 V START STA	_		
11/1/2		,	C+1LO)	6 SRB STACK OPS/JO		
19 A LH AFT SRM	LH AFT SK	T O/D KSC Ø 23		818 SRB INTEGR	ATED CLOSEOUTS	
	LH SRB AFT A	ASSV B/U 23	—			
		3 AFT ASSY B/U 2	17			
	1		ET-122 O/D KSC	⁄Λ 6		
	ļ	FT	NEED DATE △ 21	0,		
	İ		_	☐6 ET-136 PROCESSIN	G (HB4 FAST)	
	DELIVERY / PROCESSING	NOT	ES: 1. LON FOR	STS-133		
2. SRB AF	T SKIRT DELIVERIES		2. STS-335 F	REFLECTS NOMINAL PR	OCESSING FOR PAD FL	OW
Prepared By: Manifest Plannir	a FILE: STDY129		Dur	n Time/Date: 12:49:52PM 04/	00/2010 ¥ Denotes changes	since last publication

BASELINE MANIFEST (FDRD) / PREL. PROGRAM PLAN KSC ASSESSMENT (SLIP or OPTION)


KSC ASSESSMENT / ORB MULTI-FLOW

OPR: USA - R. GILLETTE, MFM NASA - C. FORD, PH-0

* DENOTES CHANGES TO BASELINE MANIFEST

SSP APPROVED MANIFEST MANIFEST REF. 09B-9

1300 EST, 22 APR 2010



Flight Element Processing Overview

Non-Standard Processing Activities
 Presented

Modification Summary
 Presented

Chit Summary
 Presented

OPF Flow Milestones
 Presented

• TPS Work Content Presented

Issues and Concerns
 Presented

Integrated Operations Summary
 Presented





Non-Standard Processing Activities

- RCC/LESS Removals and Replacement to Support WLE SPAR Corrosion Inspections
- Complete non-extendable OMDP Requirements, 15 of 22 completed last flow
- Time and cycle reviewed thru June 2011, no major issues have been identified





CHITS

CHIT	Title	Status
J6399	0-Gauge Protection for OV-104, Flights 31-35	Approved
J6527	FRCS Thruster Canister Stud Inspections - F5R and F5L	Approved
J6528	Putty Repair Tile Replacement for Risk Reduction	Approved
J6543	ET Ferry Flight Door Attach Fitting Inspection	Approved
J6577	Ames Gap Filler Removal And Replacement	Approved
J6589	Crew Module Contamination Sampling	Pending
J6599	Pre-Flight Citric Acid Flush	Approved
J6614	DTV MUX Bypass Switch Verification	Approved
J6626	Waste Water Sample and Urine Solids Filter Request (OV-103/OV-104/OV-105)	Pending







Modification Work Summary

- Tile Attrition
- RCC Spar Fitting Spacer






STATUS USA NASA

STS-335/OV-104 OPF FLOW MILESTONES DOWN PAYLOAD: ISS-34-ULF4/UP PAYLOAD:LON/MPLM

Creation Date: 15-FEB-2010 Revision Date: 24-FEB-2010

Revision :B



STS-335 TPS Work Content

TPS Removal Estimate

<u>Priority</u>	<u>Description</u>	<u>LSFR</u>
Mand	Deferred Tile/ Fib For 1 Flight (Minimum)	2
Mand	In-flight Tile/Blanket Damage (Estimate)	25
Mand	Estimated Putty Removals (Grindouts-Fleet Avg)	14
Mand	Operational Damage (Estimate)	10
Mand	Putty Repairs (Chit Driven)	15
Mand	OMRS Requirement V09AW0.030	1
Mand	OMRS Requirement V09AWO.040	1
15	Piano Key (Upper Body Flap Carrier Panels)	10
BRI Replacer	nent:	
11	LET Door remaining STR Side	10

Projected TPS Removals TOTAL (Estimate)

* Final TPS Work Content Will Be Baselined At The Delta LSFR





*88

TPS Work Content (Additional Work)


LSFR Planned Work:

- Elevon Cove Inspection OMRS requirement LIB/ROB Full-Up
 - Remove End panels and Center panels (4-Total) Perform Borescope
- LESS Carrier Panel Removals
 - Perimeter GF Rework LH19, RH8, RH21, RH22
 - WLE Corrosion Inspection LH1 Thru 12
 - 28 Total LESS C/P's
- OMRS Requirement: Re-waterproof all upper surface blankets on Flt-33
 - Midbody Sidewalls, PLBD Sidewalls, Upper Wings
 - Vertical Tail completed during Flt-32





BRI Planning STS-335 (Flt 33)



STS-335 LSFR

J. F. Kennedy Space Center








Issues and Concerns

• None









SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nowak		
Date	05-20-10		

Backup Material

FRWG Presentation (With Minor Changes)





NASA Juliisur Space Center, Houston, Texas	Presenter MO3/Phyllis Grounds	
	Date May 2010	Page 7

FO&I Backup Charts



SPACE SHUTTLE PROGRAM





STS-335 Requirements Status

Presenter MO3/Phyllis Grounds

Date May 2010

Page 8

1. <u>STS-335 MIP (NSTS 221558)</u>

- ➤ Current version available on PILS: Basic + Change 1, dated 3/29/10
- ≻Open CR's -- None
 - ➤ CR -0003 Update Rendezvous Altitude

Closed 5/4/10

- ➤ Pending CR's:
 - >TBD closures -

STS-335 Flight Requirements Document (FRD) LSFR Status

Robert J. Reynolds FRWG 5/3/10 PRCB 5/20/10



STS-335 FRD Status

STS-335 FRD Revision 002, dated April 2, 2010: https://sspweb.jsc.nasa.gov/efrd/

Closed CRs

FRD17462-335-0006 - Clarify +1 Day

Open CRs

FRD17462-335-0007 – Update LiOH Requirements (Evaluations due 5/12/10)



STS-335 OV-104 Flight 33 LSFR

Back-up

- Modification Record and MECSLSI Updates Summary
- Engineering, Hardware and Certification Status
- TPS Risk Reduction Priorities List





Modification Records and MECSLSI Update Summary

MCR/ TAD NO.	TITLE	KIT / MOD RECORD & DESCRIPTION TECH ORDER IMPACT		REMARKS			
	WLE RCC Panel Spar Fitting Spacer Mod (LH) Adds two rivets to the spacer on the installed rib splice #1 spar fitting on the left hand side to complete the deferred rivet installation per drawing. TCTIV1911620REF, 0104, 013 - Completes PR EOTF TES-4-27-0839 action which corrected the rivets omission on the RCC Installation drawing.		No Tech Order Impact	No MECSLSI Impact			
	Potential Modifications To Be Baselined						
30286	TPS - Ceramic Plug/Insert Redesign Redesigns ceramic plug sleeving/retainer for all 0.75" diameter plugs & 0.875" shorter diameter plugs (0.75" length and less) to increase cord thickness to meet the installation torque requirements	030286REF,0104,0 - TPS - CERAMIC PLUG/INSERT REDESIGN	No Tech Order Impact	No MECSLSI Impact			





Page 39 of 77

Engineering, Hardware and Certification Status

MCR/ TAD NO.	TITLE	Est. Engr Release (MM/DD/YY)	G.O. Engr Need (MM/DD/YY)	Est. Hdwe Delivery (MM/DD/YY)	G.O. Hdwe Need (MM/DD/YY)	MOD/CERT GO / NO-GO	CERT SUBMITTAL DATE	CERT APPROVAL DATE	CERTIFICATION CR / CAR (BOEING)	REMARKS
	Modifications Previously Baselined									
11620	WLE RCC Panel Spar Fitting Spacer Modification Adds two rivets to the spacers on the left hand rib splice 1 spar fitting to complete the deferred rivet installation per drawing	Released	N/A	N/A*	N/A*	Go	N/A	N/A	N/A	* Hardware available on site
	Potential Modifications To Be Baselined									
30286	TPS - Ceramic Plug/Insert Redesign Redesigns ceramic plug sleeving/retainer for all 0.75" diameter plugs & 0.875" shorter diameter plugs (0.75" length and less) to increase cord thickness to meet the installation torque requirements	5/28/10	5/28/10	N/A*	N/A*	Go	6/30/10P	7/14/10P	CR 07-391001-001AD CAR 37-07-391001AD CR 07-394710-002K CAR 13-07-394710-002K	* Hardware available on site





Current Fleet TPS Status

STATUS AS OF 5-03-2010

Priority Number	Total	OV-103	OV-104	OV-105
1. BRI-18 Tile - MLGD FWD O/B Corner	28	complete	complete	complete
2. BRI-18 Tile - MLGD FWD Edge	22	complete	complete	complete
3. BRI-18 Tile - MLGD O/B Side	18	complete	complete	complete
4. BRI-18 Tile - STR side of ET Doors	20	complete	complete	complete
5. BRI-18 Tile – LESS Carrier Panels 8-10 (103 & 104)	24	complete	complete	n/a
6. BRI-18 Tile – STR side of ET Doors I/B	8	complete	complete	complete
7. Inboard Elevon "Hub" Tile Mod	4	complete	2	complete
8. I/B Elevon 9lb/90 SIP	34	complete	complete	complete
9. O/B Elevon 9lb/90 SIP	6	complete	complete	complete
10. MLGD – Outboard Middle 1/3	24	complete	complete	complete
11. ET Door remaining STR side	40	1	10	12
12. MLGD - Outboard AFT 1/3	22	0	0	9
13. Nose Area 9lb/90 SIP	14 (16 ^{OV103})	10	complete	complete
14. Base Heat Shield 9lb/90 SIP	42	22	complete	complete
15. Body Flap Stub "Piano Key" tiles	40	18	20	18
16. Gap fillers in Subset 2B	5 Zones	2	1	0
	MLGD 100	MLGD 0	MLGD 1	MLGD 0
17. Remaining BRI-18 - MLGD (top priority) / ET / LESS	NLGD 123	NLGD 20	NLGD 22	NLGD 55
carrier panels / NLGD	LESS 68 (92 ^{OV-105})	LESS 8	LESS 12	LESS 27
	ET Door 28	ET Door 5	ET Door 4	ET Door 1
18. Mod work LESS internal	44 locations	41	complete	complete
20. Remaining Gap Fillers & Window BRI-18	124	3	2	23





STS-335 OV-104 Flight 33 – Information


Wing Leading Edge (WLE) Spar Inspection

- Structural inspections of the wing leading edge spars were due prior to the next flight of OV-104, STS-132, to meet the 4½ year OMRS requirement (due date January 22, 2010)
- 12 RCC panels and required Spar fittings were removed during the STS-129 flow to perform sampling inspections – Panels 12L-16L and 10R-16R
 - No active corrosion and or no structural anomalies identified or documented
- During the current flight 32 (STS-132) flow, 9 RCC panels (1R-9R) and required Spar fittings were removed for the sampling inspections
 - No active corrosion and or no structural anomalies identified or documented
- From the areas of the inspections performed over the past three flows (~75% of the entire wing spar), the structural condition of the wing spar is very good
 - Only two small isolated locations of suspect corrosion were noted one area was cleaned without any active corrosion noted, and one area determined active but minor and removed without need for structural repair
- 3/2/10 DPRCB approved OMRS Exception EK10769 to allow one flight deferral for continuation of detailed structural inspections of the WLE spar
 - Remaining detail inspections behind LH RCC panels 1 thru 11 and spar fittings 1 thru 11 will be performed during the flight 33 flow
 - Approval of an Exception will be requested for locations in which spar fittings were not removed (panels 17L/R, 12L & 10R)





Introduction (photo)






Example of Wing Spar Location (OV104 1-9 spar fitting) During flight 32 processing





Panels and fittings removed









SPACE SHUTTLE PROGRAM Space Shuttle Orbiter Project Office NASA Johnson Space Center, Houston, Texas

	STS-335 LSFR	
Flight	Crew Equipment/GFE	-

Presenter **MV6/Bill Lane** Page 3

May 20, 2010

Date

BACKUP



SPACE SHUTTLE PROGRAM Space Shuttle Orbiter Project Office NASA Johnson Space Center, Houston, Texas

NASA

STS-335 LSFR Flight Crew Equipment/GFE

Presenter						
	MV6/Bill Lane					
Date	May 20, 2010	Page 4				

Tech Order numbers are identified for reference only. Report generated 3-May-10

Hardware	Tech	Eng(TO)	In MEC	Cert	KSC	JSC	Remarks	JSC
	Or der Creation of the Creatio	Release		O/C	Need O/D	Planned O/D		Contact
(port forward)	M072-750025-076	1/17/07	4/26/10	С	TBD	TBD	Camera/PTU from STS-133/0V-103.	Randall Moore
(port aft)	M072-750025-077	1/17/07	4/26/10	С	TBD	TBD	Camera/PTU from STS-133/0V-1053.	Randall Moore
(starboard aft)	M072-750025-078	1/17/07	4/26/10	С	TBD	TBD	Camera/PTU from STS-133/0V-1053.	Randall Moore
(starboard forward)	M072-750025-079	1/17/07	4/26/10	С	TBD	TBD	Camera from STS-133/OV-103. Requires PTU swap.	Randall Moore
Payload Ops camera	M072-340109-002	11/15/01	4/26/10	С	TBD	TBD	Camera from STS-131/OV-103.	Randall Moore
SRMS elbow camera	M072-544504-014	8/4/08	4/26/10	С	TBD	TBD	Camera from STS-133/OV-103. Requires PTU swap.	Randall Moore
SRMS wrist camera	M072-544504-008	8/4/08	4/26/10	С	TBD	TBD	Camera from STS-133/OV-103.	Randall Moore
Centerline Airlock Camera (stowed)	M072-660828-002, plus CCCD stow	3/17/99		С	TBD	TBD		Randall Moore
efthand Umbilical Camera (aft)	M072-705001-016	10/28/04	4/26/10	С	TBD	TBD		Randall Moore
Righthand Umbilical Camera	M072-705001-028 M072-705001-027	10/28/04 10/28/04	4/26/10	С	TBD	TBD		Randall Moore
Digital Television (DTV)	M072-710570-007	11/15/07		С				Larry Schmidt
MCIU/RMS Situational Awareness Display (RSAD)	M072-710543-001	3/7/00	4/26/10	С				Larry Schmidt
ools for Rendezvous and Docking TRAD)	M072-730021-019*	7/20/07	4/26/10	С			Note: The TCS will not be required to be changed out.	Larry Schmidt
ideo Processing Unit (VPU)	M072-710338-007	3/2/08		С				Larry Schmidt



SPACE SHUTTLE PROGRAM Space Shuttle Orbiter Project Office NASA Johnson Space Center, Houston, Texas

NASA

STS-335 LSFR Flight Crew Equipment/GFE

Prese	nter MV6/Bill Lane	
Date	May 20, 2010	Page 5

Tech Order numbers are identified for reference only. Report generated 3-May-10

Hardware	Tech	Eng(TO)	In MEC	Cert	KSC	JSC	Remarks	JSC
Hardware	Order	Release	III IIILO	O/C	Need O/D	Planned O/D	Remarks	Contact
Wireless Video System (WVS)	M072-344828-001 mount	8/24/04	4/26/10	C				Randall Moore
	M072-744007-001 UHF	6/2/04						
	M072-744004-012 S-BAND	3/21/08						
	M072-744004-013 S-BAND	3/21/08						
	M072-744004-014 S-BAND	3/21/08						
	M072-744004-015 S-BAND	3/21/08						
	M072-744004-016 S-BAND	3/21/08						
	M072-744004-017 S-BAND	3/21/08						
	M072-744004-018 S-BAND	3/21/08						
Space to Space Orbiter Radio	M072-344828-002	9/24/04	4/26/10	С				Larry Schmidt
(SSOR)	M072-740828-002 Hamess							
RMS Sideview Camera (RSC)	M072-710281-002	11/24/04	4/26/10	С	TBD	TBD	Camera from STS-133/OV-103. Requires return to JSC	Randall Moore
	M072-000416-006 camera						for repressurization.	
Wing Leading Edge (WLE)	M072-756111-007	8/21/07	4/26/10	С				Micheal Wright
Instrumentation - Left Wing								
Wing Leading Edge (WLE)	M072-756111-008	8/21/07	4/26/10	С				Micheal Wright
Instrumentation - Right Wing								-
OBSS Sensor Package 2 *** (OPF)	M072-710282-006	4/18/08	4/26/10	С			At KSC FCEL	Larry Schmidt
_ ` ` ′								
OBSS SENSOR PACKAGE 1 **	M072-710282-008	4/18/08	4/26/10	С	TBD	TBD	Note: Qual unit is being looked at. Unit will come from	Russell Yates
(OPF)							STS-133.	

Payload Cargo Engineering Backup Charts



Cargo Integration Hardware Status

- Open Work ECD
 - FRED Assessment 04/23/10A
- Delivery Status
 - All required CIH has been delivered
 - No new hardware required for this flight
- Issues/Concerns
 - None



Annex 1: ISS-LON-NSTS 21558-A01

<u>Activity</u>	ECD
 Baselined 	02/19/10
•Post-CIR Update	
CR approval	03/05/10
•L-4 M Update	
 Customer submittal 	07/08/10
CR approval	07/29/10
al 4 M Unalete	

•L-1 M Update

Customer Submittal	10/22/10
CR Approval	10/29/10
 Final weight log 	11/15/10



Time-Critical Ground Handling Requirements

• Activity <u>ECD</u>

Customer Submittal (L-4M) 07/29/10

Release for review (L-3M) 08/30/10

• Baseline (L-60 Days) 09/29/10

- Issues / Concerns
- None



Payload ICDs/PIRNs

- All Payload-Unique ICDs are baselined
- Issues/Concerns
 - None



BACKUP



J. F. Kennedy Space Center







CONFIGURATION / Facilities

• OV-104: Flight 33

OMS Pods: LP04 / RP01

• ET: 122

SRB: BI-145/RSRM 114

SSME: TBD (#1), TBD (#2), TBD (#3)

Payload: LON MPLM

Flight Software: Ol-34

Firing Room: 4

OPF Bay: 1

• MLP: 3

VAB High Bay: 3

Pad: A





STS-335 (LON-MPLM) Launch Site Flow Review Flight Software Overview

Tom Stansel USA FSW

PRCB 05/20/2010



STS-335 (LON-MPLM) LSFR (FSW)

- STS-335/OV-104 LON Flight Software (FSW) Versions
 - Eighth scheduled flight of Operational Increment (OI) 34 Flight Software (SASCB SCR 98107A documents PASS and BFS OI-34 content)
 - Sixth scheduled flight of MEDS IDP VI 07.01/Eighth scheduled flight of MDUF VI 06.00 (SASCB SCR 98113A documents content)
 - Ninth scheduled flight of MAGRS-3S Link 613-996-008 Software (Link-008) (SASCB SCR 98115 documents content)
- STS-335/OV-104 LON Flight Software Payload Support:
 - ISS-LON
 - Orbiter Interface Unit (OIU)
 - Orbiter Docking System (ODS)
 - Sequential Still Video (SSV)
 - Trajectory Control System (TCS)
 - ISS Caution and Warning (ISSCW)
 - Multipurpose Logistics Module (MPLM)
 - Assembly Power Converter Units (APCUs) & Station to Shuttle Power Transfer System (SSPTS) (generic support for both configurations)
- Major New Flight Software Support Items:
 - None



STS-335 (LON-MPLM) LSFR (FSW) ...

- STS-335 Source Changes/Edits for Primary Flight Software (Base)
 - SCR 93298 Expand Effectivity of SCR 93211A (Update of SSMEC Vehicle Data Table (VDT) for Enhanced Accelerometer Operations) to include STS-335
 - SCR 93301 Expand Effectivity of SCRs to Include STS-335
 - SCR 93262A Film ET Camera
 - SCR 93267A Removal of the Set and Reset to False Cmds For the RCS Tank Iso Valves
 - SCR 93284 Update PASS HUD Body Flap Warning Limit K-Load
 - DR 126366 SM GPC Failure to Send GCIL Commands
- STS-335 Patch Implementation for Primary Flight Software
 - None.
- STS-335 Patch/Edit Implementation for Backup Flight Software (Base) (included on delivered Mass Memory)
 - SCR 93301 Expand Effectivity of SCR 93282 (Update PASS/BFS HUD Body Flap Warning Limit K-Loads) to include STS-335
- STS-335 Patch Implementation for Backup Flight Software
 - None



STS-335 (LON-MPLM) LSFR (FSW) ...

Products

STS-335/OV104 LON Base delivery schedule (available to field)

FPSB

Shuttle Data Tape
 June 14, 2010

Mass Memory Unit July 9, 2010

- This is a LON system to support STS-134
 - Also contains requirement for MPLM
 - Full FSW products will be built and delivered
- Open Items
 - None
- Concerns/Issues
 - No issues or concerns with STS-335 at this time







EVA StatusSTS-335 Launch Site Flow Review

Bridget Ziegelaar EVA Office Johnson Space Center May 20, 2010



STS-335 LSFR EVA Hardware



Forward Bulkhead PFR

- Portable Foot Restraint, SED33105308-307 to be installed on forward bulkhead
- Released T.O. M072-661568-029
- Required to protect for contingency EVA TPS repair
- Lightweight Port TSA contains standard EVA contingency tools
 - Port LWTSA installation Tech Order: M072-660850-005
 - Port LWTSA Tools installation Tech Order: M072-660853-002
- Lightweight Starboard TSA no contents identified
 - Requirement to manifest starboard TSA may be deleted pending SSP direction

Winches

- Winch P/N SED33101570-327 on Forward Bulkhead
- Winch P/N SED33101570-325 on Aft Bulkhead
- All EVA PLB hardware delivery dates have been successfully coordinated with KSC



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-06-10	

Backup Material

•	SSP Systems Drawings	Attachment 1
•	SSP Authorized Modifications/Non-Standard Work	Attachment 2
•	SSP OMRS Waivers and Exceptions	Attachment 3
•	Launch Window	(Unavailable)
•	Open Configuration Waivers	Attachment 5



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-06-10	

Overview

SSP System Drawings
 No Issues*

SSP Authorized Modifications/Non Standard Work
 No Issues*

SSP OMRS Changes (RCNs)
 No Issues*

STS-335 Launch Site Flow Review



LON STS-335

KSC ISS & Spacecraft Processing
Joseph T. Delai, NASA, KSC Mission Manager





PRE-SHUTTLE INTEGRATION ACTIVITIES

Space Station Processing Facility

•	ECLSS tests	Complete
•	Rack Installation	8/2-9/1
•	Front side stowage	9/1-9/16
•	CBM operations	9/7-9/27
•	AEC stowage	9/22-10/11
•	MPLM closeouts	10/8-10/29
•	Hatch activities	10/28-11/9
•	Payload to pad (U/R)	11/11 (L-17)

Planned Processing Milestones



SHUTTLE INTEGRATION ACTIVITIES

<u>PAD</u> (U/R)

Payload install into Orbiter

TBD

• IVT TBD

Close Payload Bay Doors for Flight
 TBD

• Launch 11/29/10

KSC/ISS Processing Summary



Watch Items:

LON launch date

The KSC STS-335/LON Mission Processing Team is ready to proceed with processing the STS-335 Mission payload complement.



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-06-10	

SSP System Drawings

The Drawings Baseline Will Be Released By PRCB S115315 on TBD

V072-000001-294 (Rev. TBD) Space Shuttle System (Rel. TBD)

• V072-200215-001 (Rev. A) Mission Equipment Cargo Support (Rel. 04-22-10)

• SGD32104458-401 (Rev. TBD) Crew Compartment Configuration (Rel. TBD)

-402 Descent

V070-000001-004Orbiter General Assembly

V070-410100-018
 SSME Installation

• 10100-0061-173 Integrated SRB General Assembly (BI-146)

80901000000-510
 External Tank Assembly (ET-122)

• STS-335 LSRR + 18 days Mission Configuration Product Plan (MCPP) was last published on 04-12-10 and will be republished at ORR -14 days on TBD.



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nov	wak
Date	05-06-10	

SSP System Drawings – (Continued)

Ferry Configuration

• V072-000001-295 (Rev. TBD) Space Shuttle System Drawing (Rel. TBD)

• V072-200215-002 (Rev. NC) Mission Equipment Cargo Support (Rel. 02-02-10)

• SGD321004458-001 (Rev. TBD) Crew Compartment Configuration (Rel. TBD)

• V072-300055-025 (Rev. BU) Ferry Flight Configuration (Rel. 05-11-09)

SCA 911



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nowak				
Date	05-06-10				

Modification Impact Report

- Mission Equipment Modifications and Orbiter Modifications analyzed for impacts to OMRSD, LCC, ICD, EMI, Software, and GSE.
- A total of 1 MCR have been approved and/or pending mods
- **Current MCR impact status:**
- No impacts for all six disciplines One or more disciplines with impacts, documentation approved and/or pending approval



SPACE SHUTTLE PROGRAM Space Shuttle KSC Integration Office NASA Kennedy Space Center, Florida



STS-335 Launch Site Flow Review

Presenter	Kenneth Nowak					
Date	05-06-10					

<u>Modification Impact Report – (Continued)</u>

Possible impacts still under review

0

1MRCS REPT. 4650-1	SSP	SUMMARY	MOD	ITEMS	_	PRCBD	MOD	BASE	LINE	STS-0335	
TIMED RELIE 1000 I		DOIMME	1101			TICLE	1101			DID 0333	

PAGE NO. ECP-MCR/KIT SEQUENCE RUN TIME

ORB

11.10	D3 mm	04/27/2010	
11:12	I DATER:	04/2//2010	

1

DD GD	STAT	ITEM/KIT NUMBER	s	SEQ	
PRCB MCR/ECP	PRIO SITE	TCTI NUMBER	ETCN N	TO	DESCRIPTION / GENERAL REMARKS
AUTHDATE	FLT	ICII NUMBER	ETSN N	10.	DESCRIPTION / GENERAL REMARKS
AUIHDAIE					
	AUTH	J6543	0104 0	102	ET FERRY FLIGHT DOOR ATTACH FITTING INSPECTION
S-J6543	MAND	00313	0101 0		II I I I I I I I I I I I I I I I I I I
5 00515	KSC		SPAR		NDE OF FERRY FLT DOOR ATTACH FITTINGS WILL ONLY BE REO'D
2009-09-17	033		D		THE OF THE POOR HITTINGS WILL ONLY DE NEW D
2005 05 17					FOLLOWING A F/FLT BACK TO KSC. F/FLT ONLY.
		J6577	0104 0	01	AMES GAP FILLER REMOVAL AND REPLACEMENT
S-J6577	MAND				
	KSC		SPAR		GAP FILLER REPLACEMENTS WILL BE PERF'D OVER REMAIN ING
2010-01-29	033				WW
					MANIFESTED FLTS BASED ON PROG LSFR PRIORITIES.
	AUTH	J6599	0104 0	000	PRE-FLIGHT CITRIC ACID FLUSH
S-J6599	MAND	00333	0101 0	, , ,	THE LEGIT CLINES LEGIT
2 00033	KSC		SPAR		REQUESTED CITRIC ACID FLUSH WILL BE INTEGRATED INTO PLANNED
2010-03-05	033		D		Mayorata Cities note 11001 Will be intended into 111111112
					POST FLT WASTE TANK SERVICING PROCESS
	AUTH	J6614	0104 0	000	DTV MUX BYPASS SWITCH VERIFICATION
S-J6614	MAND				
	KSC		SPAR		DIGITAL TV MULTIPLEXER BYPASS SWITCH VERIFICATION IS
2010-04-13	033				
					INTEGRATED WITH PLANNED OPF COM TESTING.
011620	AUTH	TCTIV1911620REF	0104 0	13	ADDITION OF SPACERS TO RCC SPAR FITTING ANGLE INSTL (LH)
s115335					
	KSC				PARTIAL DEFRL FROM FLT-27 (SEQ 10), (RH SEQ 11)
2010-03-31	033				

TOTAL MODS = 5 1Date: 04/27/10 10:58 PCASS Page: 1

FLIGHT-SPECIFIC

Approved STS-135 OMRS Waivers and Exceptions

) ABSTRACT RAS REQUIREMENTS	EISN PAYLOAD	STS BEG	END
E	ORB		OMRSD EXCEPTION REQUEST - MISSION LIFE ASSESSMENT OF WING LEADING EDGEINSULATORS (EK10572R1)	104	029	033
			OMRSD EXCEPTION REQUEST - WING LEADING EDGE INSULATORS (EK10574R1)	104	029	036
W	ET	S053293FZ WK03850R1 (A) (STS-093)	L02/LH2 TANK PRESSURE MONITOR FOR MOVE	ET	099	999
	OMS	S053298NV WK10522 (A)	OMRSD WAIVER REQUEST - RIGHT OMS SECONDARY REGULATOR CREEP RATE(W K10522)	0021	035	043
		S053299YG WK10723 (A)	OMRSD WAIVER REQUEST - RIGHT OMS FUEL CV501 ELEMENT 4 LEAK CHECK FAIL(WK10723)	0021	038	040
	RCS		OMRSD WAIVER REQUEST - RIGHT RCS OXIDIZER GHE SYSTEM INTERNAL LEA KAGE(WK10318R1)	0021	034	042
		S053298JF WK10503 (A)	~	0021	034	042
	SRB	S053293WA	LH FWD AND RH MID SRB	ві	099	999

WK03886 (A) JOINT TEMP SENSORS (STS-103)

+ o	0	Waivers	0	Except	0	Deviat	0	Cannib	0	Total	0
° Total Extracted	0	6	0	2	0	0	0	0	0	8	0

Item #	Authority	Date	Waiver Description	Effectivity	Wad
53	S052428A	03/27/91	Allows specified flights to fly with interim TPS repair after each mission to minimize damage to surrounding tile during ferry flight	STS-37, STS-39, STS-40, STS-42 thru STS-999	STAYS OPEN
101	S076972	11/19/91	Permit the modified GPCs (AP101-S) Battery Back-up Unit to fly with annotated fastener improvements without rolling the LRU Part Number	STS-42, STS-44, STS-47 and STS-49 thru STS-999	STAYS OPEN
325	S061956	07/15/03	Blanket on the Control Moment Gyro (CMG) Orbital Replacement Unit (ORU) on the Lightweight MPESS Carrier (LMC) will NOT be re-installed on-orbit per configuration defined in ICD-A-21494. It will be secured around the FSE and attached to the aft bulkhead.	OV-104, Flight 27	
334	S115115JR1	07/19/06	The following requirement is waived to allow OV-104 to fly with the following out-of-configuration condition: Tech Order M072-544501-067 (RMS, MPM over-center stop and MPM pedestal insulation cover fasteners) will be implemented in total, less the requirement to perform bench rigging per updated specification requirements for for OV-104, Flight 27 and subsequent OV-104 flights until such time that all MPMs can be removed and bench rigging can be performed.	OV-104, Flight 27 thru OV-104, Flight 999	STAYS OPEN
339	S063652	07/09/07	The following requirement is waived to allow OV-104 to ferry from DFRC to KSC with the following out-of-configuration condition: Retain RH ET Camera installation for ferry flight MECSLSI V072-200197, reference flag note (3), removes (MV0456A) M072-705001-024 RH ET Sep Camera (Digital Camera with 35 mm lens) for ferry flight. The RH ET Camera needs to remain in flight configuration to support resolution of IFA STS-117-V07 Digital Umbilical Camera Image Corruption. Troubleshooting will be performed on the installed hardware after returning OV-104 to KSC.	OV-104, Flight 28	

Prepared by: Jeff McRoberts USA CM/CVAS 861-2505

Item #	Authority	Date	Waiver Description	Effectivity	Wad
340	S063652	07/09/07	The following requirement is waived to allow OV-104, Flight 28 to ferry with the following out-of-configuration conditions:	OV-104, Flight 28	
			Remove LH OMS Pod LP04 (FIB) blankets prior to ferry flight thermal blanket V070-396376-241 on LOMS Pod lifted at forward leading corner and edges reported on orbit, IFA STS-117-V-02. Two blankets (V070-396376-241 and adjacent V070-396376-051) are removed. RTV ramp applied in cavity up to adjacent blankets per TLP04-28-2520 MRB approval.		
343	S115122GR4	12/07/2007	The following requirement is waived to allow OV-104 to fly with the following out-of-configuration condition:	OV-104, Flight 29	ECL-4-A0118 (was ECL-4-29-1637)
			Partial installation of Tech Order M072-660010-004, middeck air flow re-routing duct tech order, not to include one each bolt (NAS1003-8A) and one each washer (NAS620C10) in the lower aft corner of the vent housing cover assembly.		
			During vertical stowage, the nut plate (not under USA Tech Order configuration control) was noted missing from behind the starboard closeout panel. Without the nutplate, the bolt and washer cannot be installed. The area cannot be currently accessed to reinstall the missing hardware.		

Item #	Authority	Date	Waiver Description	Effectivity	Wad
344	S071024MP	12/20/07	During maintenance of an Advanced Master Events Controller (AMEC) it was discovered that the module cards are able to translate upward, away from connectors. The cards are retained by friction applied by wedge-locks. An assessment determined a 0.070 upward card translation, would result in card disengagement from connectors. The wedge-lock system can not assure the cards will not translate upwards. The AMEC vendor (Boeing Autonetics) is no longer on contract supporting SSP. A design proposal is to provide a secondary connector retention using the AMEC covers. The new design new lids will limit the upward translation to 0.055. The new design will reduce the milled section of the cover and add silicone pads to provide shock absorption. Due to the absence of the original vendor and no current alternate drawings available for the AMEC the modification is being requested via a program directed Material Review (MR). P/N MC450-0016-0029 S/N U6F0002, U6F0003, U6F0004, U6F0006, U6F0007, U6F0009, U6F0010 and U6F0011	OV-103, Flight 35 OV-104, Flight 30 OV-105, Flight 21	
			511 5 57 7 6 7 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5		

Prepared by: Jeff McRoberts USA CM/CVAS 861-2505

Item #	Authority	Date	Waiver Description	Effectivity
351	S115125BR9	06/03/2009	Allow OV-104 to ferry from DFRC to KSC with out-of-configuration conditions for removal of Flow Control Valve (FCV) assemblies for ferry flight and install Main Propulsion System (MPS) cap and plug set GSE plugs:	OV-104, Flight 30 (Ferry Flight)
			Three MPS GH2 FCV solenoid and poppet sleeve assemblies (P/N 80420-1301) for each engine.	
			Engine 1 GH2 FCV LV56	
			Engine 2 GH2 FCV LV57	
			Engine 3 GH2 FCV LV58	
	NOTE: The following MPS cap and plug set GSE plugs will b		NOTE: The following MPS cap and plug set GSE plugs will be	
			installed in place of the Flow Control Valve System (FCSV):	
			3 G070-602824-001.	
	RATIONALE: There is adequate access and time to remove the		RATIONALE: There is adequate access and time to remove the	
			requested parts. Removal of these parts is well within USA's	
			experience base. These valves have been removed numerous	
			times at KSC. Removal at DFRC will be no different than removal at	
			KSC. There is no increase in risk performing this work at DFRC,	
			and the early removal will better support the upcoming manifest.	
			There is no GH2 FCV position specified for ferry flight, and no	
			blanket pressure is required. The manifold is firmly mounted/	
			restrained and requires no additional support due to removed FCV	
			components.`	

Prepared by: Jeff McRoberts USA CM/CVAS 861-2505 Wad