



STS-134 SSP Flight Readiness Review

MS/Anthony Griffith March 31, 2011





Pre-decisional. Internal Use Only.





Page 2

Pre-decisional. Internal Use Only.

Agenda

Presenter

03/31/11

Date


MS/Anthony Griffith

Systems Engineering & Integration ٠

- SE&I FRR Roadmap
- Flight Preparation Readiness ٠
- Integrated Debris Risk Summary
- Integrated Hazard Report Summary
- Integrated In-flight Anomalies (IFAs)
- Special Topic- PE Certification Impact to Ascent Thermal Environments
- **Imagery Status**
- Radar Status
- Flight Software Readiness
- Payload and General Support Computer Readiness
- Non-Standard Open Work Summary ٠
- Alternate/Dissenting Opinions ٠
- Certificate of Flight Readiness
- Launch On Need (LON) ٠










Page 3

Pre-decisional. Internal Use Only.







Flight Preparation Readiness


Presenter MS/Anthony Griffith Date 03/31/11 Page 4

- All standard Systems Engineering and Integration flight preparation activities have been completed or are planned. Non-standard open work will be addressed.
 - System requirements verification
 - Design requirements and induced environment updates; verification of element incorporation
 - Integrated vehicle performance evaluation
 - Real-time mission support preparation and certification of personnel as applicable
 - Review and disposition of waivers, deviations, and exceptions
 - Updates to Integrated Hazards baseline
 - Flight Software verification/Payload and General Support Computer (PGSC) Readiness
 - Review of element requirements changes and verifications for integration impacts









Page 5

STS-134 SSP FRR

Presenter


Date

STS-134 Debris Risk Summary

Doug Drewry, MS2 **Systems Engineering & Integration Office Space Shuttle Program Office**







Debris Risk Assessment, 9/2010

Six IDBR-01 debris risks remain Infrequent/Catastrophic

- <u>Liftoff Debris</u> is expected to remain at this risk level for the life of the Program due to the diversity of potential Debris sources although rigorous controls have been implemented and continuous vigilance is policy.
- ET Umbilical Ice: Accepted Risk; Closely monitored during pre-launch
- **Putty Repair:** Windows zero impact allowable keeps any impact in the "catastrophic" category, forward work may be used to reduce the likelihood to "Remote".
- **<u>T-0 Umbilical Ice</u>**: Accepted Risk; NSTS 08303 Updated to include 0.1 lbm allowable external ice
- LOX IFR: Implemented NDE of all IFR ramps to screen for large voids
- ET Intertank Foam Loss: Changed to Infrequent Catastrophic for STS-128
 - Continued Tensile Testing of ET high risk debris areas to mitigate risk









Presenter

Date

Issues & Integrated In Flight Anomalies

3/31/11 Page 7

•STS-133-I-002 ET Intertank Stringer Cracks:

•CLOSED for STS-134 at 3/22/11 SICB

•STS-133-I-003 Unexpected Debris/Expected Debris Exceeding Mass Allowable Prior to PAD **Clearance (Liftoff Debris):**

•Reviewed at 3/21/11 DIG •CLOSED at 3/22/11 SICB


STS-133-I-004 Debris Released From LH2 Flange Area Near the Bipod:


•Reviewed technical data for closure at 3/23/11 DIG.

•CLOSED at 3/29/11 SICB.









STS-133 debris count is below the baselined average and within family of the last several flights.








SPACE SHUTTLE PROGRAM Space Shuttle Systems Engineering and Integration Office NASA Johnson Space Center, Houston, Texas

Tracking and Trending Liftoff Debris IIFA

Mike Mitchell/MP-71 Pre-decisional. Internal Use Only.

Date


Presenter **MS/ Doug Drewry** 3/31/11 Page 9



Does Not Include Rust








• Total # of TPS Hits = 56 / TPS Hits w/damage > 1" = 6 (5 lower surface, 1 window)

• Prior to RTF Average for >1" = 30.5 per flight / Average Since RTF = 16 per flight



- STS-133 elliptical volume Hits>1" = 0.246 in³ / RTF Average = 2.192 in³
- STS-133 Total elliptical volume ALL Hits = 0.474 in³ / RTF Average = 3.187 in³





STS-133 Putty Repair Debris Summary

ES/ Cooper Snapp




Page 11

Pre-decisional. Internal Use Only.

- TPS putty repairs are listed as expected debris in NSTS 60559
- Putty Repair loss is listed in IDBR-01 as cause AK and carried as an Infrequent/Catastrophic **Risk primarily because Windows have zero capability for impacts**

Since RTF, 3 losses have had transport to windows – largest mass was 0.0009 lbs

ZERO losses experienced during STS-133




Missing Putty Repairs Since RTF









STS-134 SSP FRR

Presenter

STS-133-I-004

Debris Released from LH2 Flange Area near the Bipod









STS-133-I-004: Debris Released from LH2 Flange Area near the Bipod

3/31/11

Date

MS/ Doug Drewry

- At approximately 231 seconds MET a large piece of TPS foam was released from the ET LH2 Intertank flange area between the bipod struts.
 - Several smaller particles are also observed related to the primary release.
- Debris impacted the Orbiter at least four times:
 - contacts the vehicle near the ET/Orbiter attach point,
 - then contacts the starboard bipod strut and possibly re-contacts the ET,
 - then re-contacts the Orbiter fuselage aft of the bipod.
 - Debris eventually travels along the -Z side of the Orbiter fuselage & may re-contact well aft on the Orbiter belly.
- No tile damage was noted in on-orbit imagery that could be correlated to these losses
 - However minor damage to a shave repair on the NLGD documented during the post landing inspection could be related.
- The foam loss occurred from the upper part of the LH2-to-Intertank Flange closeout and extended into the Intertank Acreage.
 - Based on available imagery the divot maximum dimensions are Length = 14.9 in., Width = 10.5 in., and Depth = 2.8 inches.
 - CATIA estimated the mass of the total foam loss at 0.154 lbm.
- Because of the late release time and relatively benign aero environment the initial pop-off velocity is the primary force acting on the Debris







STS-133-I-004:

Debris Released from LH2 Flange Area near the

Bipod



Date

3/31/11 Page 14

- There is no indication or evidence suggesting that a stringer or possible stringer defect/crack may have been a cause.
 - The loss site appearance and video footage is consistent with what would be expected from cryoingestion.
 - Return-to-Flight design and process improvements were made to mitigate the likelihood of cryoingestion as a result of process voids in the TPS foam closeout.
- Most likely cause of this occurrence is cryo-ingestion into TPS cracks between the tank surface and TPS foam that may have been exacerbated as a result of multiple ET loadings.
 - These cracks form due to differential coefficients of thermal expansion (CTE) between the TPS and metal structure during tanking.
- The resulting cracks or "voids" can then act as reservoirs for condensed nitrogen purge gas that is ingested from the intertank through structural leak paths (such as rivets).
 - During ascent, the reservoir begins to warm due to substrate heating from reduced liquid levels inside the tank.
- If the original leak path is not sufficient to vent the buildup of gas, pressure builds inside the reservoir causing additional TPS crack growth and/or TPS loss.







SPACE SHUTTLE PROGRAM Space Shuttle Systems Engineering and Integration Office NASA Johnson Space Center, Houston, Texas




3/31/11

STS-133-I-004: Debris Released from LH2 Flange Area near the Bipod

Page 15

CATIA Model Showing STS-133 TPS Loss




CATIA model of STS-133 loss shown with underlying structure


- Footprint of the base of the divot encompasses two or possibly three fasteners that pass through both the lower chord and skin.
- These fasteners provide a leak path to the pooling LN2 that forms in the Intertank/LH2 flange area.







 As shown in the thermal assessment, the entire Intertank Chord remains below the saturation temperature of N₂ at 1 atm (-320°F) through 190s MET.



- At the time of the STS-133 foam loss, the highest predicted temperature in the void was -313°F (consistent with a nitrogen saturation pressure of 23 psia).
- Foam debris originating at the Intertank chord would be expected to occur no earlier than 190 sec. if it occurred at an internal void pressure of 1 atm







STS-133-I-004:

Debris Released from LH2 Flange Area near the


Bipod



Pre-decisional. Internal Use Only.

Present	er MS/ Doug D	MS/ Doug Drewry				
Date	3/31/11	Page 17				

- This is a known failure mode with a well understood mechanism
 - Proposed mitigations were not implemented in RTF flange modifications due to marginal benefits, risk of unintended consequences, and since considered a low debris risk (late time of release)
- Aero and Transport analysis has shown there is a low probability of experiencing significant TPS damage from these late releases.
 - STS-133 analysis indicated all impacts were below the TPS threshold and no damage was predicted.




- Analysis is substantiated by 2006 SSP Aero Panel Study that indicated no critical damage to Orbiter Tile or RCC for debris smaller than 0.4 lbm. after 166 sec. MET.
- Pop-off velocities were reviewed for small to large masses and all remained below Orbiter damage thresholds.



STS-133-I-004:

Debris Released from LH2 Flange Area near the

Bipod



3/31/11 Page 18

Presenter

Date

- Current NSTS 60559 Risk Assessment Mass for LH2-to-Intertank Flange closeout Cryo-ingestion is 0.041 lbm.
 - Based on max expected voids within TPS only
 - Does not address structural gap/LN2 leak paths through the chord, skin and/or fasteners
- ET Project is initiating CR (S063545AW) to add an additional failure mechanism to NSTS 60559 for the LH2 Intertank Flange Closeout which will include a risk assessment mass for Cryo-Ingestion due to structural /LN2 leak paths of 0.220lbm.
 - Based on ET-137's loss model (~.154 lbm) with minor modifications:
 - Foam -loss forward "run-out" extended ³/₄"
 - Larger exposed substrate area (exposed base center XT 1120.095)
 - Additional 20% uncertainty factor
 - Consistent with flight history and comparable to LH2 IFR and Adjacent Acreage Crack/Cryo-Pumping 0.25 lbm assessed release mass
- A VTL item was added to update IDBR-01 with the NSTS 60559 identifier as well as adding the 2006 SSP Aero Panel study to the acceptance rationale.
- Integrated IFA was closed at 3/29/2011 SICB.









STS-134 SSP Flight Readiness Review

Integrated Hazard Report and Integrated In-flight Anomalies Summary

MS3/JJ Hill March 31, 2011









Page 20

Pre-decisional. Internal Use Only.

03/31/11

MS3/J. Hill

Presenter

Date

Integrated Hazard Report Changes Since STS-133

- •IDBR-01 Ascent Debris Impact to SSV
 - •Routine Update
 - •Updated to include most relevant PRA set per cause
 - •All IIFA closures removed from background section and replaced with a link to PRACA
 - •Added ET-122 rationale to the applicable Causes
 - Updated Reference section
 - •Updated Fault Tree to Revision J
 - •Updated mass distribution, rate of release and time of release distributions for
 - LH2 and LO2 IFR Ramps
 - •Updated mass distribution, rate of release for LH2 and time of release
 - distributions Adjacent Acreage
 - •No change in overall risk classification: ACCEPTED RISK









Date

Integrated Hazard Report Changes Since STS-133

•IMPS-09 Hazardous Environment due to H2 External to Space Shuttle Vehicle Routine Update

•Updated Hazardous Condition Description to correct transfers in from ISPR-02

•Updated Cause E to transfer to Integrated Control ISPR-02 instead of ET Hazard **Report S.06**

•Updated Fault Tree (Rev H) to capture Cause E transfer change

•Updated Flight Effectivity to STS-134 through STS-999

No change in overall risk classification: ACCEPTED RISK







Integrated Hazard Report Changes

Since STS-133



Pre-decisional. Internal Use Only.

Presenter MS3/J. Hill Date 03/31/11 Page 22

•ISPR-02 ET Vent Arm System (ETVAS) Umbilical System Malfunction

Routine Update

•Updated Acceptance Rationale section to include risk trade associated with vent valve cycling to mitigate a H2 leak at the GUCP

•Update ISPR-02 Cause Z to eliminate reference to ice formation and by adding additional integrated controls and verifications and new element controls for H2 leakage at the GUCP

•Update ISPR-02 Cause AQ to more accurately address ice suppression

•Update Background section to include GUCP Leak Investigation IFA STS-133-I-

001 closure rationale

•Update flight effectivity to STS-134 through STS-999

Update signature approval page

•No change in overall risk classification: CONTROLLED









Integrated In-Flight Anomalies (IIFAs) **Summary**

Pre-decisional. Internal Use Only. Presenter

Date

MS3/J. Hill Page 23 03/31/11

- STS-133-I-001, Hydrogen Leak at ET Ground Umbilical Carrier Plate (GUCP)
 - Status Closed
- STS-133-I-002, ET Intertank Stringer Crack
 - Status Closed for STS-134 only
- STS-133-I-003, Unexpected Debris/Expected Debris Exceeding Mass Allowable Prior to Pad Clearance (Liftoff Debris)
 - Status Closed
- STS-133-I-004, Debris Released From LH2 Flange Area Near the Bipod
 - Status Closed
- STS-133-I-005, Debris Observed Near Right SRB Nozzle
 - Status Closed









Date

Integrated In-flight Anomalies(IFAs)

Presenter MS3/J. Hill

03/31/11 Page 24

IFA Number: <u>Title</u> Description	STS-134 Status and Rationale			
 STS-133-I-001, Hydrogen Leak at ET Ground Umbilical Carrier Plate (GUCP) During the launch attempts of STS-127/ET-137 on November 5th, 2010, hydrogen leak detectors 23 and 25 located at the ET/GUCP interface observed leakage exceeding the Launch Commit Criteria (LCC) Haz-09 limit of 40,000 ppm. Consequently, the launch was scrubbed. 	 Following the scrub, a GUCP leak investigation team, developed a working theory that leakage occurred between the flight and ground sides of the quick disconnect (QD) assembly as a result of misalignment of the QD causing side loading of the flight seal. After STS-127, hardware modifications (larger guide pins) and procedural changes (use of concentricity measurement tool) were made to minimize initial misalignment and reduced potential for movement during assembly. For STS-134, the ground probe will be "clocked" to offset the concentricity measurement of the GUCP. The LCC (HAZ-09) use leak detectors (LD 23 and 25) to monitor the interface. In addition, ISPR-02 specifies controls for umbilical fluid system failures prior to T-0 sep due to leakage above the lower flammability limit. Status – Closed 			









Date

Integrated In-Flight Anomalies (IIFAs)

Presenter MS3/J. Hill

03/31/11

Page 25

IFA Number: Title				
Description	STS-134 Status and Rationale			
STS-133-I-002: ET Intertank Stringer Crack	• ET-137 cracked stringers were repaired.			
 TPS crack observed on the LO2 Intertank (IT) flange closeout at Xt-852 on Panel 2. 	 Radius block modification were implemented on all accessible stringers. 			
 Subsequent NDE following the 12/17/10 tanking test revealed additional cracks on Panel 6. 	 ET-137/STS-133 was loaded and launched successfully on 2/24/11. 			
	 Suspect material lots identified during the STS- 133 investigation were not used on ET-122 (STS-134). 			
	 Radius block mods were performed on the LO2 flange end of ET-122 (STS-134). 			
	 No impact of radius block mods on integrated loads. 			
	 No indication that the loss at the LH2 flange is due to a stringer crack (STS-133-I-004); it has the characteristics of a cryoingestion loss. 			
	 No significant increase in the risk of TPS release due to re-spray in areas of stringer mods. 			
	 Status – Closed for STS-134 only 			









Presenter MS3/J. Hill Integrated In-Flight Anomalies (IIFAs) Date Page 26 03/31/11 **IFA Number: Title** STS-134 Status and Rationale Description STS-133-I-003: Unexpected Debris/Expected Risk Assessment indicates that given the **Debris Exceeding Mass Allowable Prior to Pad** proposed mitigations, observed debris poses no **Clearance (Liftoff Debris)** appreciable increase in risk. Multiple pieces of debris were found on pad post-• Liftoff debris risk is currently characterized as launch that include liberated pad hardware, and infrequent, catastrophic due to significant foreign object debris. uncertainties in controls and significant limitations in analysis. Debris release has been mitigated for identified potential sources of critical debris by performing repairs and adding inspections for system-level components. Ongoing mitigations include FOD awareness, attrition-based hardware removal, routine inspections and monitoring for facility corrosion. Facility debris larger than allowable fell from drain holes of both TSMs on MLP-3 during STS-133 liftoff. KSC will implement mitigation to prevent MLP-3 TSM drain holes from liberating mass exceeding the NSTS-60559 allowable. Status – Closed







Integrated In-Flight Anomalies (IIFAs)

Presenter MS3/J. Hill Page 27 03/31/11

Date

DescriptionSTS-134 Status and Rationale•STS-133-I-004: Debris Released From LH2 Flange Area Near the Bipod•The foam loss occurred from the upper part of the LH2-to-Intertank Flange closeout and extended into the Intertank Acreage. • Because of the late release time and relatively benign aero environment, the initial pop-off velocity is the primary force acting on the Debris.•Debris impacted the Orbiter at least four times, however, no tile damage was noted in on-orbit imagery that could be correlated to these losses.• There is no indication or evidence suggesting that a stringer or possible stringer defect/crack may have been a cause.• The loss site appearance and video footage is consistent with what would be expected from cryoingestion.• This is a known failure mode with a well understood mechanism.• ET Project has initiated a CR to update NSTS 60559 with a new debris risk mass for cryoingestion after 190 seconds.• Status – Closed	IFA Number: Title				
 Flange Area Near the Bipod At approximately 231 seconds MET. a large piece of TPS foam was released from the ET LH2 Intertank flange area between the bipod struts. Debris impacted the Orbiter at least four times, however, no tile damage was noted in on-orbit imagery that could be correlated to these losses. There is no indication or evidence suggesting that a stringer or possible stringer defect/crack may have been a cause. The loss site appearance and video footage is consistent with what would be expected from cryoingestion. This is a known failure mode with a well understood mechanism. ET Project has initiated a CR to update NSTS 60559 with a new debris risk mass for cryoingestion after 190 seconds. 	Description	STS-134 Status and Rationale			
	 STS-133-I-004: Debris Released From LH2 Flange Area Near the Bipod At approximately 231 seconds MET. a large piece of TPS foam was released from the ET LH2 Intertank flange area between the bipod struts. Debris impacted the Orbiter at least four times, however, no tile damage was noted in on-orbit 	 the LH2-to-Intertank Flange closeout and extended into the Intertank Acreage. Because of the late release time and relatively benign aero environment, the initial pop-off velocity is the primary force acting on the Debris. There is no indication or evidence suggesting that a stringer or possible stringer defect/crack may have been a cause. The loss site appearance and video footage is consistent with what would be expected from cryoingestion. This is a known failure mode with a well understood mechanism. ET Project has initiated a CR to update NSTS 60559 with a new debris risk mass for cryoingestion after 190 seconds. 			







Date

Integrated In-Flight Anomalies (IIFAs)

Presenter MS3/J. Hill

03/31/11

Page 28

IFA Number: Title Description	STS-134 Status and Rationale
 STS-133-I-005: Debris Observed Near Right SRB Nozzle At approximately 11 seconds MET, a single piece of light-colored, linearshaped,flexible debris was first observed hear the RH SRB thermal curtain (IIFA STS-133-I-005, NIRD 133-010) No external debris sources are observed to travel toward the RH SRB thermal curtain area during liftoff/ascent. 	 Elements were polled for possible debris sources. There is no specific "most-probable" source due to exhaustive evaluation and unusual appearance of debris Proximity/timeframe indicate SRB or L&L as source, but no specific candidate for actual material exists. Debris Integration Group has indicated that this occurrence posed no threat to the vehicle. IIFA closed as a unexplained anomaly. Status – Closed






SPACE SHUTTLE PROGRAM Space Shuttle Systems Engineering and Integration Office NASA Johnson Space Center, Houston, Texas



Pre-decisional. Internal Use Only.





Space







Program			Presenter MS3/J. H				J. ⊢	lill			
Integrated Hazard Risk Matrix			Date	03	3/31/11		F	Page 3			
	"Controlled Risk" Hazard Reports										
ARO-01	Aerodynamics Environment not per Specified Design	1			1	0					
EPD-01	Inability to Power Critical Functions	8		3	5	0					
-SI-01	ET/SRB System Interface Failure	6			6	0					
SI-02	ET/Orbiter System Interface Failure	10			10	0					
SI-03	SSME/Orbiter System Interface Failure	14			14	0					
SI-04	Outer Mold Line Configuration Error	3			3	0					
-SW-01	Flight Software Generic Problems can cause loss of vehicle command and control	1			1	0					
-SW-02	Erroneous Inputs to Flight Software can cause loss of vehicle command and control	9			9	0					
/IEO-02	Malfunction of Integrated Hydraulic System (Systems 1, 2 and 3)	4			4	0					
MEO-03	SSME Nozzle/OMS Pod/ Body Flap Interference	2			2	0					
MPS-05	Over pressurization of the Integrated MPS H2 System	7			7	0					
MPS-06	Under pressurization of the Integrated MPS H2 System	7			7	0					
MPS-07	Over pressurization of the Integrated MPS O2 System	7			7	0					
MPS-08	Under pressurization of the Integrated MPS O2 System	7			7	0					
MPS-12	Excessive O2 from ET/Orbiter/SSME External to SSV	7			7	0					
MPS-15	LO2 Geyser Event during Cryo Loading	8			8	0					
VPS-16	Loss of MPS He System	4			4	0					
MPS-17	Inadvertent SSME Shutdown	3			3	0					
PYR-01	Pyrotechnic System Malfunction	11			11	0					
SPR-02	ET Vent Arm System (ETVAS) Umbilical System Malfunction	14			14	0					
SPR-03	Tail Service Mast (TSM) T-0 Umbilical System Malfunction	40		5 6	29	0					
/LD-02	System Instability Results In Structural Failure of SSV	13			13						
	Controlled Risk Distribution Totals	291	2	11 1	1 267	148	0 2	2	132	0 0	12 0









Program Integrated Hazard Risk Matrix Count Changes		^{ter} MS3/J.	MS3/J. Hill		
	Date	03/31/11	Page	31	

Infrequent Catastrophic

 None
 Remote Catastrophic

 None

 Improbable Catastrophic

 None









STS-134 SSP Flight Readiness Review

PE Certification Impact to Ascent Thermal Environments

March 31, 2011










STS-133 Orbiter Peak Heat Rate Exceedances



- Found during the Post Flight reconstruction were Ten Orbiter Wing Leading Edge (WLE) peak heat rate exceedances occurred late in the trajectory during the rarified, non-continuum flow regime
 - Peak heat rates occurred from MET 495 sec to 505 sec
 - Orbiter Project reviewed and cleared exceedances using the certification entry heating environments which drive the Orbiter WLE design
- Software program (XF0002) calculates non-continuum heating by multiplying a rarefaction factor to the continuum heating calculation
- STS-133 was launched out of plane, requiring additional steering during the second stage that resulted in the vehicle flying at a Beta of approximately -4° for an extended period of time
 - In plane launches typically fly at a beta of approximately 0° during this phase
 - The non-zero beta increased the Effective Flow Angle (EFA) for the body points with exceedances and caused their non-continuum heating to be higher
 - Per design, PE Certification trajectories have beta's of +/- 10° during this phase that should envelope STS-133 trajectory









PE Certification Heating Environments

Presenter USA/Joe Craft
Date 03/31/11
Page 34

- The alpha/beta combination that is selected from the matrix search does not maximize the rarefaction factor for non-continuum, rarefied flow
 - Coding errors in these subroutines of XF0002 software lead to the selection of an alpha/beta combination that does not maximize the PE Certification heating when flying in non-continuum, rarefied flow
 - Effectively eliminates alpha/beta envelopes by setting EFA to 0°
 - The main heating routine of XF0002 does not contain these errors it only affects the selection of alpha/beta angles from dispersed trajectories in the non-continuum regime
- These software routines are not used for Day-of-Launch work or in the reconstruction assessments









Date

Thermal Issue Resolution Options

Presenter **USA/Joe Craft** Page 35 03/31/11

OPTION	PROS	CONS
1) Do Nothing	 No Products, Tools, or Analysis Changes Supports In-Plane Launch 	 DOL Constraint: In-Plane Launch only Early/Late Launch Potential for ET/Orbiter Heating > PE Cert During Ascent
2) Mission Specific Certification	 Standard Flight Margin Assessment (FMA) Product Development and Verification Supports Launch Window of ± 5 Min No Products to Hardware Elements All Body Points ≤ PE Cert Values 	 Critical Math Model (CMM) Tool Revisions to Eliminate Code Errors NSTS 07700, Vol. X Waiver, Heating Design Criteria Develop and Implement New DOL Thermal (S9) Rule DOSP Waiver to Lockdown requirement for new Thermal (S9) rule CoFR Exception for PI (if not completed in time)
3) Performance Enhancement (PE) Certification Update	 Supports Launch Window of ± 5 Min No Impact to DOSP or DOLILU Ops Standard but Expedited Product Development 	 CMM Tool Revisions to Eliminate Code Errors New Products to Orbiter, ET Elements for Body Points > Existing PE Cert CoFR Exception for PI, Orbiter, and ET (if not completed in time)









Preliminary Thermal Environment Results Summary

Presenter USA/Joe Craft
Date 03/31/11
Page 36

- PE Certification was selected by the Program as the best approach
 - Limited the PE Certification run matrix based on current manifest (in back up)
- Impacts to Elements:
 - ET
 - 23 heat load exceedances on mainly nose cone area
 - Thermal Panel discussions suggest new environment within element capability
 - ET analysis is in work
 - Orbiter
 - Wing Leading Edge (WLE) has ~25 heat rate and ~91 heat load exceedances
 - WLE exceedances are in family with STS-133 mission assessment and expected to be cleared by comparison with hardware temperature limit
 - RTLS case caused small exceedances to five OMS Pod loads Body Points (BP) (max increase 2.41%) and fourteen Vertical Tail loads BP (max increase 3.33%)
 - Orbiter analysis is in work







SPACE SHUTTLE PROGRAM Space Shuttle Systems Engineering and Integration Office NASA Johnson Space Center, Houston, Texas



Pre-decisional. Internal Use Only.

71269 📀

71263

71256

71250

71269

71263

71363

0 71256

71356

71150

70300 70400 60130

70350 70450 70550 70650

71150

71250

71350


60133

41256

41356

ET Total Heat Load BP Exceedances

Presenter USA/Joe Craft Date 03/31/11 Page 37












Date

Presenter **USA/Joe Craft** Page 38 03/31/11











Summary and Forward Work

Presenter USA/Joe Craft
Date 03/31/11 Page 39

- STS-133 reconstruction found the Orbiter Wing Leading Edge exceedances caused by an error in the creation of PE Certification Heating
 - Coding errors caused the calculation of PE Certification heating to use an incorrect alpha/beta combination that does not maximize heating in noncontinuum, rarefied flow
- The PE Certification approach was selected using trajectories that are representative of configurations to be flown on the next two missions
- Formal delivery of new environments to ET and Orbiter was on 3/25/11 (PRCBD S052158FB)
- Elements reported results to the SICB OSB on 3/30/11
 - All new PE Certification Environments were cleared by the Orbiter and ET Elements
- CR to update thermal CMMs ECD: post STS-134









STS-134 SSP Flight Readiness Review






MS3/Brenda Eliason









Page 41

Pre-decisional. Internal Use Only.

3/31/11

Presenter

Date

Imagery Hardware ELVIS

MS3/B ELIASON

ET LO2 Feedline Camera (ET-122)

- Camera system installed and on schedule with nominal checkouts
- Ready to support. No open issues.

Ground Network & TV

- Nominal ground network and TV truck status
- Ready to support. No open issues.

SRB Cameras (BI-145)

- STS-133 RH SRB DAS did not record video of thrust panel (IFA STS-133-B-001)
 - Problem attributed to connector contact contamination/excessive potting
 - For STS-134, new DAS controllers/connectors will be built up for both boosters to prevent recurrence
- Ready to support. No open issues. •

Crew Handheld Digital Still and HD Video Cameras

- STS-133 crew did not take post-separation HH imagery of ET
- Expect dark conditions 19 20 April
- Ready to support. No open issues.

Digital ET Thermal Protection System (DETTPS)


- Camera configured for **Daylight** settings through 29 May
- Images expected to show several faint vertical streaks (bad pixels)
 - Similar to last flight of this unit (STS-130) see next chart
- Ready to support. No open issues. ٠

DETTPS Camera Settings

- Davlight:
 - f/8. ISO 100, 1/250
 - Bracketing: 0EV=f/8, +1EV= f/5.6
- Night
 - f/2.8, ISO 200, 1/250
 - Bracketing 0EV=f/2.8, +1EV= f/2.0









Page 42

Pre-decisional. Internal Use Only.


3/31/11

MS3/B ELIASON

Presenter

Date

STS-134 DET TPS Enhanced VAB Test Image



Pixel defects are most apparent when extreme contrast enhancement is applied to image. They are not a concern or hindrance for ET TPS assessments.









non-ELVIS

Presenter

Date

Airborne Cameras

- HYTHIRM/Cast Glance is working entry support planning
- No open issues.

Orbiter MiniCam

- STS-133:
 - Imagery observed LO2 IFR 676 TPS liberation (ref NIRD 133-013, ~112sec MET)
 - Exposure settings will be same as STS-133, intended for remaining flights, day or night
- Ready to support. No open issues.











Date

Imagery Hardware Ground

Presenter MOO/D ELLACON

nter	MS3/B ELIASON				
3	8/31/11	Page	44		

Ground Cameras

- Patrick Distant Object Attitude Measurement System (DOAMS) camera focus quality issue
 - Mitigation is to add tracker at Cocoa Beach DOAMS, as was done for STS-133
 - This plan is expected for STS-135 as well
- Experimental cameras at FSS 275-ft level and around the pad (e.g., CS2, CS3) to investigate new techniques
 - Not for operational use or analysis
- Ready to support. No open issues.

Photo Targets

- STS-133 FSS and MLP-3 targets performed as expected
 - Differences in placement (expected vs. actual) require survey of re-installed targets
- Most survived the STS-133 launch intact
- Thermal degradation on some targets (as expected)
- All FSS and MLP-2 targets are installed for STS-134
 - Survey complete 3/23/11; report expected week of 3/28/11









Lighting F	Predictions,	April	19 –	May	30
------------	--------------	-------	------	-----	----

Presenter MS3/B ELIASON 3/31/11 Page 45

Launch*

- Apr 19: DAYLIGHT, Non-Optimal
- Apr 20 May 22: Daylight ٠
- May 23 May 30: DARK

ET Sep Imagery *

- Apr 19: DAYLIGHT, Non-Optimal ٠
- Apr 20 May 28: DAYLIGHT ٠
- May 29: DAYLIGHT, Non-Optimal ٠
- May 30: DARK ٠

Handheld ET (post-pitcharound) Imagery*

- Apr 19 Apr 20: DARK •
- Apr 21: DAYLIGHT, Non-Optimal ٠
- Apr 22 May 30: DAYLIGHT

* Based on December reference trajectory; minor adjustments possible

Post ET-Sep Mnvrs*

- Apr 19 Apr 20: Nominal +X**, No Pitch
- Apr 21 May 30: Nominal +X, Nominal Pitch

Date

** For launch on Apr 19, 20: MOD may execute modified +X (20 sec) vs. the nominal (11 sec) burn

MOD, SE&I Agreements for Crew HH ET Photography

- 1. Pitch mnvr for handheld ET photography will not be attempted if nominal photography time is dark.
- 2. Pitch mnvr will not be performed "late"
- Pitch mnvr and ET handheld photography will not be 3. attempted on LON mission









Date

CoFR Products & Readiness

Presenter MS3/B ELIASON

3/31/11 Pa	age	46
------------	-----	----

- All 20 STS-133 NIRD Reportables have been Closed with supporting rationale
- STS-134 Imagery Readiness Review was held with the IATs and hardware teams on 3/21/11

Area of Responsibility	Statement	Status
Operations Integration Plan	NSTS 60540, Operations Integration Plan, Rev B approved at 06/27/06 SICB. End-to-end readiness level of hardware, procedures, tools, and facilities have been assessed to ensure Open Work and issues will be resolved prior to flight.	Ready
Engineering Image Analysis Products, Training, and Staffing	Imagery engineering analysis, and "I-Squared" SE&I personnel and tools are ready to support STS-134.	Ready
Imagery Laboratory Readiness	Imagery labs at JSC, KSC, and MSFC have the required capabilities and configurations to support anticipated and unexpected analysis.	Ready
Camera Hardware Readiness	All ground and vehicle requirements for imagery and other data collection assets have been implemented for flight and associated operational readiness has been demonstrated.	Ready









STS-134 SSP Flight Readiness Review Radar Status

MS/Joe Hamilton



Pre-decisional. Internal Use Only.





Page 48

Pre-decisional. Internal Use Only.

3/25/11

Date

PresenterMS/J.A. Hamilton

Debris Radar Configuration for STS-134:

- STS-134 NDR Configuration:
 - 1 MCR C-band radar
 - 2 NASA X-band radars
 - NASA #1 on SRB vessel Liberty Star
 - NASA #2 on Runnymede-Class ARMY LCU
- Operational SRB tracking, following ASTT, by both X-bd radars
- NDR Readiness scheduled 3/30/11.







3/25/11

NDR Issues During STS-133:

Presenter MS/J.A. Hamilton

NDR-C1 Radar:

Problem: Pre-mission calibration indicated an error applying Phase Compensation Tables (PCTs) at some power settings. PCT's were not used for this mission resulting in slight degradation in data quality.

Resolution: Could not duplicate, cause unknown. PCT's worked properly at all power settings for 3/11/11 Delta launch.

NDRX-3 Radar:

Problem: None.

NDRX-4 Radar:

Problem: None.







Page 50

Pre-decisional. Internal Use Only.

3/25/11

Date

Readiness for STS-134:

PresenterMS/J.A. Hamilton

٠	Team	Readin	ness

- Complete, both ascent and analysis teams ready ٠
- Training new team members for transition •

Facility Readiness •

Complete •

Radar Readiness •

- NDR-C1 GREEN
- NDR-X3 GREEN
- NDR-X4 GREEN •







STS-134 SE&IO Pre-Flight Readiness Review Flight Software









Date

Program STS-134 FLIGHT SOFTWARE SUMMARY

Presenter USA/John Magley Page 52 03/25/11

- Seventh flight of PASS and BFS Operational Increment 34 (OI-34)
 - No logic changes from previous flight software systems
- Seventh flight of MEDS Multifunction Display Unit Function (MDUF) VI 6.00 and fifth flight of MEDS Integrated Display Processor (IDP) VI 7.01
 - No changes from previous flight software
- Eighth flight of MAGRS-3S Link 613-9966-008 GPS FSW
 - No changes from previous flight software









FSW READINESS SUMMARY

Presenter USA/John Magley Date 03/25/11 Page 53

- Integrated Avionics Verification (IAV) is complete
 - A total of 17 cases were executed and analyzed in support of STS-134
 - Included testing of full flight system (PASS/BFS STS-134/OI-34 with flight-specific I-Loads; MEDS VI 7.01/6.00 (IDP/MDUF); MAGRS-3S Link 8; and SSME AD08/DA05 software)
- SAIL facility will be in a condition of readiness for mission support
- Formal Software Readiness Review (SRR) was conducted on 03/10/11
 - No known constraints
- With the completion of planned open work, FSW will be ready to support STS-134 launch









LAUNCH ON NEED STATUS

Presenter USA/John Magley Date 03/25/11 Page 54

- In the event of call-up, the STS-135 flight software products would be flown on OV-104
 - Some flight software products have been or will be generated as STS-335 products
 - These are authorized for use on STS-135 by SASCB direction (SCR 98119 and associated product release documentation)
 - OI-34 STS-335 [STS-135] Base 2 Load and associated products
 - Flight specific I-Load patches for STS-335 [STS-135] (full payload bay)
 - OI-34 compatible MEDS IDP and MDUF software (VI 7.01/6.00)
 - MAGRS-3S Link 8
- Completion of the development and verification of flight-specific FSW products for STS-135 will be performed in time to support the 06/28/11 target launch date
- Formal Software Readiness Review to be conducted after call-up











Presenter USA/John Magley

 FLIGHT READINESS STATEMENT
 Date
 03/25/11
 Page 55

 Full compliance with SPOC Flight Software CoFR requirements is documented in the STS-134 Software Readiness Review packages along with signed readiness statements and identification of open work.

Pending completion of standard open work and identified non-standard open work, Flight Software is ready to support flight.

/s/ Patti A. French 3-23-2011

Patti A. French Date Associate Program Manager USA Flight Software









STS-134 SSP Flight Readiness Review PGSC









Payload and General Support Computer Readiness – STS-134

Presenter MS4/E. Jones Date Mar 2011 Page 57

Hardware and Software Summary

- STS-134 will be the thirteenth flight of the IBM ThinkPad A31p PGSC
 - 8 PGSC units + 1 Backup (Stowed) (None currently planned for ISS transfer)
 - Note: **AMS laptop** is payload dedicated; Not attached to PGSC network
 - Fifteenth flight of the A31p Docking Station (OCA and WinDecom)
 - Thirteenth flight of Netgear Wireless Access Point.
 - Note: No network issues observed during STS-133
 - New software
 - STORRM

IFA Summary

1. OCA Hard drive – hard drive replaced with backup. OCA returned to nominal operations.

- IFA closed; Post-flight testing confirmed damage. Drive removed from flight inventory

Maior Milestones **Cable Testing** SAIL Testing Launch **Bench Review** Late Update Disk** PGSC Review 11 ~4/05 04/19 1/25 3/17 3/08 **FD1 Late Update may be performed on ground at an earlier date **BOEING**





Date


Alternate/Dissenting Opinions

Presenter MS/Anthony Griffith Page 58 03/31/11

- Alternate/dissenting opinions were actively solicited at the • SE&I STS-134 Pre-FRR.
 - No dissenting opinions were identified. ٠









Presenter MS/Anthony Griffith
Date 03/31/11
Page 59

The Space Shuttle Program, Systems Engineering and Integration Office's Flight Preparation Process Plan, documented in NSTS 08117, Requirements and Procedures for Certification of Flight Readiness have been satisfied. Required products and other responsibilities identified in NSTS 08117, paragraph 8.5.12 and Appendix M, have been or will be scheduled for completion. All technical functions and responsibilities are ready and the Systems Engineering and Integration Office is prepared to sign the Certificate of Flight Readiness for STS-134, pending completion of open work.


/s/Donald S. Noah

Donald S. Noah Manager Systems Engineering and Integration Office















^{Page} 60

Pre-decisional. Internal Use Only.

03/31/11





Page 61

Pre-decisional. Internal Use Only.

03/31/11

	-
Back-up	charts







SPACE SHUTTLE PROGRAM Space Shuttle Systems Engineering and Integration Office NASA Johnson Space Center, Houston, Texas




Pre-decisional. Internal Use Only.

STS-133 TPS Damage

Presenter MS/ Doug Drewry

Date 3/31/11 Page 62












STS-133 Putty Repair Debris Summary



Pre-decisional. Internal Use Only.

Presenter MS/ Doug Drewry
Date 3/31/11 Page 63


- OPO/TPS PRT continues risk reduction steps
- Inspection/repair procedures strengthened to identify suspect repairs
 - Areas with transport to windows/RCC undergo tactile evaluation
 - Where repairs have transport to Windows or RCC tighter restrictions limit masses
 - Tiles with large repairs are being removed in critical areas FWD of the RCC and windows per CHIT



Missing Putty Repair Total Volumes Since RTF









Integrated Hazard Report Changes Since STS-133 (Delta FRR)

Presenter MS3/J. Hill
Date 03/31/11
Page 64

•IMPS-01 "Contamination in the Integrated MPS H2 System" was updated to document increase in risk associated with IPR133V-0070 where PV-13 was incorrectly configured open.

•A safety issue briefing (SIB) was presented to the November 18th PRCB,

acknowledging some additional likelihood of contamination.

•SIB Flight Effectivity for STS-133

•CR S050425KC was approved with mods at the January 18th SICB and OSB PRCB.

•IMPS-01 Cause F updated to document nominal drain configuration does not allow LH2 flow through the unfiltered 4" recirculation line.

•Included OMRSD S00E00.250 MPS LH2 Detank Valve Config. as a control.

•Cause F remains Remote Catastrophic

•Change Flight Effectivity to STS-134 through STS-999

•No change to overall IMPS-01 Classification of ACCEPTED RISK







STS-133 L+2 day Orbiter Peak Heat Rate

Exceedances



Pre-decisional. Internal Use Only.

Presenter USA/Joe Craft Date 03/31/11 Page 65

NOTE: Body points on both the port and stbd. side of Orbiter exceeded PECERT. Values shown in table are maximized between port and stbd.

	F	Peak Heat Ra	te (BTU/ft ² -	s)		Total Heat Lo	bad (BTU/ft ²	¹)
	STS-133	STS-110		Delta (STS-	STS-133	STS-110		Delta (STS-
Body Point	L+15	BET	PECERT	133 & PE)	L+15	BET	PECERT	133 & PE)
5455	4.83	4.83	4.64	0.19	467.1	485.4	595.8	-128.7
5456	4.45	4.44	3.95	0.5	442.9	456.8	547.9	-105.0
5457	4.20	4.19	3.73	0.47	420.5	434.6	512.1	-91.6
5458	3.98	4.01	3.57	0.41	402.4	415.9	486.5	-84.1
5459	3.84	3.87	3.45	0.39	388.2	401.6	467.0	-78.8
5460	3.73	3.76	3.35	0.38	376.8	390.1	453.0	-76.2
5461	3.56	3.60	3.21	0.35	359.6	373.0	439.1	-79.5
5462	3.42	3.49	3.11	0.31	348.2	363.2	424.3	-76.1
5463	3.32	3.40	3.03	0.29	338.2	353.6	412.7	-74.5
5464	3.36	3.44	3.06	0.3	342.1	357.3	417.0	-74.9









Corrected Coding Errors in PE Certification in
STS-133 reconstruction

Presenter	USA/Joe C		
Date	03/31/11	Page	66

	Peak Heat Rate (BTU/ft ² -s)				
	STS-133 L+15				
	Minute	Existing	Delta (STS-133	Modified	Delta (STS-133
Body Point	Trajectory	PECERT	& Existing PE)	PECERT	& Modified PE)
5455	4.83	4.64	0.19	5.24	-0.41
5456	4.45	3.95	0.5	5.24	-0.79
5457	4.20	3.73	0.47	5.08	-0.88
5458	3.98	3.57	0.41	4.80	-0.82
5459	3.84	3.45	0.39	4.59	-0.75
5460	3.73	3.35	0.38	4.44	-0.71
5461	3.56	3.21	0.35	4.21	-0.65
5462	3.42	3.11	0.31	4.05	-0.63
5463	3.32	3.03	0.29	3.93	-0.61
5464	3.36	3.06	0.3	3.97	-0.61

NOTE: Values shown in table are maximized between port and stbd.

> PE Certification heating eliminates exceedances for the STS-133 L+15 minute trajectory with Corrected Coding











Corrected PE vs. Existing PE

Presenter **USA/Joe Craft** Page 67

03/31/11

Date





Vectors drawn for illustrative purposes only









Date

Limited PE Certification Trajectories

Presenter **USA/Joe Craft** Page 69 03/31/11

- For the limited PE Cert approach, only PE Cert trajectories that are • representative of configurations to be flown on the next two flights were analyzed
 - Analyzed:
 - Baseline No-Fail, RTLS, TAL, ATO
 - 1st Stage TAL
 - Late TAL and Delayed TAL ONLY 51.6° Inclination, 104.5% Power Level TAL Flights to Moron or Zaragoza
 - Istres TAL Only Heavy Payload Flights
 - Not Analyzed ٠
 - 54nm MECO all flight modes
 - No Roll to Heads Up all flight modes
 - 109% Intact Abort all flight modes
 - Late TAL and Delayed TAL 28.5°, 39°, or 57° Inclination; 106% or 109% Power Level, and TAL Flights to Ben Guerir
 - Istres TAL Light Payload Flights









DOLILU Operational	Support System
--------------------	----------------

Presenter USA/David Bowers
Date 03/31/11
Page 70

- NSTS 08329, Vol VIII, DOSP update to clarify Contingency Procedure R for potential USA/Boeing vehicle loads comparison differences for indicators FO1 and FOA.
- SICB approved CR S052550PP on 3/22/11.
 - FO1 limit value to return to 100% (vs. 94% for STS-133)
 - Sources of load indicator calculation differences identified and quantified
 - 6% mis-compare allowable (vs. 4% baseline) for FO1 and 5% mis-compare allowable for FOA acknowledges known USA/Boeing calculation differences









DOLILU Operational Support System

Presenter USA/David Bowers
Date 03/31/11
Page 71


- Background
- During Dec 20, 2010 weather SIM indicator FO1 produced a 5% miscompare on the L-3:35 balloon. Violated DOSS rule and indicated a NO-GO condition. Investigation initiated.
- S052550PN updated DOLILU Contingency Procedure R prior to STS-133
- STS-134 Rationale
- Investigation completed and determined cause of the mis-compare
 - Conversion of moments due to inertia
 - USA: Incorrectly divides by gravity when converting slugs*ft^2/sec^2 to in*lbf
 - Orbiter c.g. and moments of inertia
 - Mission Specific values vs. static c.g. values
- Exception to Contingency Procedure R revised to document the understanding of the mis-compare and to remove some conservatism from the rule
- Change reviewed and approved by the DOWG and Loads Panel





Lighting Predicts

Pre-decisional. Internal Use Only.



SPACE SHUTTLE PROGRAM Space Shuttle Systems Engineering and Integration (SE&I) NASA Johnson Space Center, Houston, Texas Space



Pre-decisional. Internal Use Only.

Presenter

Date

Lighting Predicts (cont.)

enter	MS3/B ELIA	SON	
3/31/11		Page	73

Launch Date	Launch	Umbilical Ops	Hand-Held Ops	Pitch-Up	
(2011 GMT)		(8:46 - 9:30 MET)	(11:43 - 13:43 MET)	Maneuver	
Apr 01	DARK	DARK	Partly DAYLIGHT	Yes	
Apr 02 - Apr 18	DARK	DARK	DARK		
Apr 19	Partly DAYLIGHT	Partly DAYLIGHT	DARK	No	
Apr 20	DAYLIGHT	DAYLIGHT	DARK		
Apr 21	DAYLIGHT	DAYLIGHT	Partly DAYLIGHT		
Apr 22 - May 22	DAYLIGHT	DAYLIGHT	DAYLIGHT		
May 23 - May 28	DARK	DAYLIGHT	DAYLIGHT	Yes	
May 29	DARK	Partly DAYLIGHT	DAYLIGHT		
May 30	DARK	DARK	DAYLIGHT		



Data provided by DM/Angela Lenort based on DEC 2010 ISS Reference Trajectory.







Date

STS-134 Standard Open Work

Presenter MS/Anthony Griffith

03/31/11	Page	74
----------	------	----

	ECD
TDDP - TDDP-DOL (Supports DOL Products)	04/11/11
- TDDP Change Notice (RSRM L-3 Day PMBT Prediction Update)	04/15/11
DOSS	
- L-3 Week Test / TCDT	04/01/11
- L-7 Day SIRB Review	04/12/11
 L-3 Verification Test (Incorporate DOL TDDP & L-4 Day Change Notice) 	04/15/11
GN&C	
- Update FRV Results to SIRB	04/12/11
 Normal Prelaunch Configuration & Testing 	04/15/11
Loads & Dynamics	
- Final CE Weight & CG Assessment	03/28/11
- Normal Prelaunch Configuration & Testing	04/15/11
Flight Rules	
 Assessment of Late Flight Rule Changes 	04/19/11









Page 75

Pre-decisional. Internal Use Only.

Presenter MS/Anthony Griffith **STS-134 Standard Open Work** Date 03/31/11 ECD Software - Update NIRD CCT L-3 Days ELVIS - Cabin Stow of Crew Handheld Cameras S0017 - SRB DAS Install in Fwd Skirt* S5009 - Recharge of ET LO2 Camera Battery* T1303* - Cabin Stow of DETTPS Camera IVA Converter Box L-3 Days - ET LO2 Camera Cover Removal / Window Cleaned T6446[†] - SRB Cameras Cover Removal / Windows Cleaned S0007 - ET LO2 Camera Open Loop MILA Comm Check S0007 - Cabin Stow of Crew Handheld Camera Batteries DOL **Orbiter GFE** - Minicam bracket/camera installation/alignment L-21 Days - Minicam system functionality verification L-3 Days - Minicam alignment verification DOL Ground Cameras - Trackers Towed to Camera Site Locations L-1 Week - Cameras Positioned and Rough Set L-3 Days L-1 Day

- Film Loaded and Final Set

* Prior to ordnance ops, usually at L-1 week [†] Prior to RSS retract, usually at L-1 day









Page 76

Pre-decisional. Internal Use Only.

STS-134 Standard Open Work

Presenter MS/Anthony Griffith


03/31/11

Date

	ECD
 FSW Complementary Load Processing Dump and Compare Processing 	L-10 L-5
PGSC L-14 Late Update Disk L-14 Cable Testing 	04/05/11 04/05/11









Date

STS-134 SYSTEM LEVEL WAIVERS

Presenter USA/John Magley Page 77 03/25/11

- No changes or waivers to NSTS 07700 Vol X impacting software for ٠ **STS-134**
- No new software-induced waivers to NSTS 07700 Vol X •



