

MIT/IL SOFTWARE ANOMALY REPORT

MIT REPORT NO. LNY-45
PROGRAM LUMINARY
PROGRAM REVISION 69

1.1 ORIGINATOR: R. A. Harwood	1.2 ORGANIZATION: TRW	1.3 DATE: 3/26/69	1.4 ORIGINATOR CONTROL NO. A-174-F-01
----------------------------------	--------------------------	----------------------	--

1.5 DESCRIPTION OF ANOMALY:
 An error due to truncation in the computation of engine cutoff time during long burns can cause burn residuals of up to 0.64 fps. This is caused by a shift right 10 instruction at program location TGOALC+16₁₀. After this operation the intermediate result in MPAC is scaled at B19 with unit of meters/centisecond. Recommended action is to change the SR 10D at TGOALC+16₁₀ to a SR 7D and rescale the constant -FOURDT from -800 B-18 to -800 B-21. This would reduce the maximum residual due to truncation to about 0.08 fps.

CONTINUED ON PAGE

1.6 DESCRIPTION OF RUN:
 Visual inspection.

CONTINUED ON PAGE

- MIT ANALYSIS -

2.1 CAUSE:
 See 1.5

CONTINUED ON PAGE

2.2 RECOGNITION:
 None

CONTINUED ON PAGE

2.3 MISSION EFFECT:
 See 1.5

CONTINUED ON PAGE

2.4 AVOIDANCE PROCEDURE:
 None

CONTINUED ON PAGE

2.5 RECOVERY PROCEDURE:
 None

CONTINUED ON PAGE

2.6 PROGRAM CORRECTION: While it is true that the proposed change does reduce the truncation in the TGO calculations, it should also be noted that it also reduces the maximum value of TGO to about 17 minutes (due to divide overflow).

CONTINUED ON PAGE 2

2.7 RECOMMENDED DISPOSITION (Fix, Work-around, etc):
 None

CONTINUED ON PAGE

2.8 RECOMMENDED RE-TESTING:
 None

CONTINUED ON PAGE

2.9 MIT/IL SIGNATURE: <i>George Cherry J.K.</i>	2.10 DATE: 4-22-69
--	-----------------------

3.1 NASA DIRECTION:

CONTINUED ON PAGE

4.1 CLOSING ACTION TAKEN:

CONTINUED ON PAGE

3.2 NASA/MSC SIGNATURE:	3.3 ORGANIZATION:	3.4 DATE:	4.2 SIGNATURE:	4.3 ORGANIZATION:	4.4 DATE:
-------------------------	-------------------	-----------	----------------	-------------------	-----------

MIT/IL SOFTWARE ANOMALY REPORT

MSC REPORT NO.	LNy-45
PROGRAM	LUMINARY
PROGRAM REVISION	69

L1 ORIGINATOR: R. A. HARWOOD	L2 ORGANIZATION: TRW	L3 DATE: 3/26/69	L4 ORIGINATOR CONTROL NO. A-174-F-01
---------------------------------	-------------------------	---------------------	--

2.6 Program Correction, cont'd.

In long burns with a heavy vehicle, and especially before 'DPS throttle-up' TGO can easily be larger than 17 minutes. The effect of the overflow limiting would be to display a more or less constant TGO of 17 minutes without counting down until the actual value of TGO became less than the maximum. Nonetheless, a fix to this anomaly should be contemplated for future programs, possibly by using normalization which would overcome the overflow problem. However, the increase in accuracy does not seem to warrant changing the current programs.