

MIT/IL SOFTWARE ANOMALY REPORT

1.1 ORIGINATOR: G. W. Cherry		1.2 ORGANIZATION: MIT/IL		1.3 DATE: 4/29/68		1.4 ORIGINATOR CONTROL NO. Y4		MIT REPORT NO.	
1.5 DESCRIPTION OF ANOMALY: <p style="text-align: center;">CENTANG is loaded with garbage at the beginning of P34.</p>								PROGRAM SUNDANCE	
								PROGRAM REVISION all revisions	
1.6 DESCRIPTION OF RUN: <p style="text-align: center;">Observed by Astronaut Schweickart during every Rendezvous simulation.</p>								CONTINUED ON PAGE	
- MIT ANALYSIS -									
2.1 CAUSE: <p style="text-align: center;">CENTANG is time-shared.</p>								CONTINUED ON PAGE	
2.2 RECOGNITION: <p style="text-align: center;">Sees garbage.</p>								CONTINUED ON PAGE	
2.3 MISSION EFFECT: <p style="text-align: center;">More time required to proceed through P34.</p>								CONTINUED ON PAGE	
2.4 AVOIDANCE PROCEDURE: <p style="text-align: center;">Load CENTANG every time.</p>								CONTINUED ON PAGE	
2.5 RECOVERY PROCEDURE: <p style="text-align: center;">N/A</p>								CONTINUED ON PAGE	
2.6 PROGRAM CORRECTION: <p style="text-align: center;">Load CENTANG from fixed at the beginning of P34 with 130°.</p>								CONTINUED ON PAGE	
2.7 RECOMMENDED DISPOSITION (Fix, Work-around, etc): <p style="text-align: center;">Fix</p>								CONTINUED ON PAGE	
2.8 RECOMMENDED RE-TESTING: <p style="text-align: center;">Special hybrid test of P34.</p>								CONTINUED ON PAGE	
3.1 NASA DIRECTION:				2.9 MIT/IL SIGNATURE: <i>G. W. Cherry</i>		2.10 DATE:			
				CONTINUED ON PAGE				CONTINUED ON PAGE	
3.2 NASA/IL SIGNATURE:				3.3 ORGANIZATION:		3.4 DATE:		4.1 CLOSING ACTION TAKEN:	
CONTINUED ON PAGE				CONTINUED ON PAGE		CONTINUED ON PAGE		CONTINUED ON PAGE	
3.2 NASA/IL SIGNATURE:		3.3 ORGANIZATION:		3.4 DATE:		4.2 SIGNATURE:		4.3 ORGANIZATION:	