

Payload Powerdown


STS-118

**Mission Operations Directorate
Operations Division**

**Final, Rev A
June 15, 2007**

National Aeronautics and
Space Administration

Lyndon B. Johnson Space Center
Houston, Texas



United Space Alliance

Verify this is the correct version for the pending operation (training, simulation or flight).
Electronic copies of FDF books are available. URL: <http://mod.jsc.nasa.gov/do3/FDF/index.html>

JSC-48097-118

MISSION OPERATIONS DIRECTORATE


**PAYOUT LOAD POWERDOWN
STS-118**

FINAL, REVISION A
June 15, 2007

PREPARED BY:


Yvette L. Fuller
Publication Manager

APPROVED BY:


Kimberly A. Johnson
Manager, Shuttle
Procedures Management

ACCEPTED BY:


Michael T. Hurt
FDF Manager

This document is under the configuration control of the Crew Procedures Control Board (CPCB). All proposed changes must be submitted via FDF Workflow Crew Procedure Change Request (CR) to DO3/FDF Manager.

Additional distribution of this book, for official use only, may be requested in writing to DO3/PMO Administrator. The request must include justification and requester's name, organization, position, and phone number. Contractor requests are made through the NASA or DOD organization supported. Deletions, reduction in quantity, or change of address may be submitted to DO3/FDF Management Office, 281-244-1184.

PL PWR/118/FIN A

Incorporates the following:
482#: PL PWR-0111
PL PWR-0112

AREAS OF TECHNICAL RESPONSIBILITY

Publication Manager	DO35/Y. Fuller	281-244-1174
Alternate Publication Manager	DO35/L. Giles	281-244-9068
ORB PWRDNS	DF73/C. Sweitzer	281-483-6355
PL PWRDN	DO5/S. Tripodi	281-483-3521

NOTES

1. Section 1 of this book is inserted at the back of the Ascent Pocket Checklist.
2. Sections 2 and 3 of this book are inserted at the back of the Orbit Pocket Checklist.
3. Section 4 of this book is inserted at the back of the Entry Pocket Checklist.

PAYLOAD POWERDOWN
STS-118

LIST OF EFFECTIVE PAGES

FINAL 03/14/07
REV A 06/15/07

Sign Off * 118/FIN A
PL ii * 118/FIN A
PL iii * 118/FIN A
PL iv * 118/FIN A
PL v * 118/FIN A
PL vi * 118/FIN A
PL 1-1..... 118/A/FIN A
PL 1-2..... 118/A/FIN A
PL 1-3..... 118/A/FIN A
PL 1-4..... 118/A/FIN A
PL 2-1..... 118/O/FIN A
PL 2-2..... 118/O/FIN A
PL 2-3..... 118/O/FIN A
PL 2-4..... 118/O/FIN A
PL 2-5..... 118/O/FIN A
PL 2-6..... 118/O/FIN A
PL 2-7..... 118/O/FIN A
PL 2-8..... 118/O/FIN A
PL 2-9..... 118/O/FIN A
PL 2-10..... 118/O/FIN A
PL 3-1..... 118/O/FIN A
PL 3-2..... 118/O/FIN A
PL 3-3..... 118/O/FIN A
PL 3-4..... 118/O/FIN A
PL 4-1..... 118/E/FIN A
PL 4-2..... 118/E/FIN A
PL 4-3..... 118/E/FIN A
PL 4-4..... 118/E/FIN A

* – Omit from flight book

PL iii

PL PWR/118/FIN A

This Page Intentionally Blank

PL iv

PL PWR/118/FIN A

<u>CONTENTS</u>	<u>PAGE</u>
<u>PL PWRDN – ASCENT</u>	PL 1-1
PL PWRDN MATRIX.....	PL 1-2
ACTION.....	PL 1-3
PWRDN A.....	PL 1-3
MIDDECK PAYLOADS	PL 1-3
CBTM	PL 1-3
CCM-A.....	PL 1-3
MERLIN.....	PL 1-3
PWRDN B.....	PL 1-3
MIDDECK REAR-BREATHER PAYLOADS	PL 1-3
MERLIN.....	PL 1-3
<u>PL PWRDN – ORBIT</u>	PL 2-1
PL PWRDN MATRIX.....	PL 2-2
ACTION.....	PL 2-3
PRIORITY PWRDN PP3A.....	PL 2-3
FLIGHT DECK/MIDDECK.....	PL 2-3
SSV	PL 2-3
OCAC.....	PL 2-3
PRINTER	PL 2-3
SPACEHAB.....	PL 2-3
OIU.....	PL 2-3
PWRUP	PL 2-4
SPACEHAB.....	PL 2-4
PRIORITY PWRDN PP3B	PL 2-5
MIDDECK PAYLOADS (CCM-A, MERLIN)	PL 2-5
CCM-A.....	PL 2-5
MERLIN.....	PL 2-5
OBSS	PL 2-5
SPACEHAB.....	PL 2-5
ESP-3.....	PL 2-6
MIDDECK PAYLOADS (CBTM).....	PL 2-6
CBTM	PL 2-6
PWRDN A.....	PL 2-7
SPACEHAB.....	PL 2-7
PWRDN B.....	PL 2-7
SPACEHAB.....	PL 2-7
PWRDN C.....	PL 2-8
SPACEHAB.....	PL 2-8
PWRUP C	PL 2-9
SPACEHAB.....	PL 2-9
PWRDN D	PL 2-10
MIDDECK REAR-BREATHER PAYLOADS	PL 2-10
MERLIN.....	PL 2-10

<u>PL SAFING – ORBIT</u>	PL 3-1
PL SAFING MATRIX	PL 3-2
ACTION	PL 3-2
PL SAFING A.....	PL 3-2
MIDDECK TRANSFER (IF NOT ALREADY PERFORMED)	PL 3-2
MIDDECK PAYLOADS	PL 3-2
CBTM	PL 3-2
CCM-A.....	PL 3-2
MERLIN.....	PL 3-2
SPACEHAB TRANSFER (IF NOT ALREADY PERFORMED)	PL 3-3
OIU.....	PL 3-3
PL SAFING B.....	PL 3-3
SPACEHAB.....	PL 3-3
PL SAFING C	PL 3-3
SPACEHAB.....	PL 3-3
PL SAFING D	PL 3-3
APCU	PL 3-3
 <u>PL PWRDN – ENTRY</u>	PL 4-1
PL PWRDN MATRIX.....	PL 4-2
ACTION	PL 4-3
PWRDN/PWRUP A	PL 4-3
SPACEHAB.....	PL 4-3
PWRDN B	PL 4-3
SPACEHAB.....	PL 4-3
PWRDN/PWRUP C	PL 4-4
SPACEHAB.....	PL 4-4
PWRDN D	PL 4-4
MIDDECK PAYLOADS	PL 4-4
CBTM	PL 4-4
CCM-A.....	PL 4-4
PWRDN E	PL 4-4
MIDDECK REAR-BREATHER PAYLOADS	PL 4-4
MERLIN.....	PL 4-4

PL PWRDN – ASCENT

PL PWRDN MATRIX.....	PL 1-2
ACTION.....	PL 1-3
PWRDN A	PL 1-3
MIDDECK PAYLOADS.....	PL 1-3
CBTM	PL 1-3
CCM-A	PL 1-3
MERLIN.....	PL 1-3
PWRDN B	PL 1-3
MIDDECK REAR-BREATHER PAYLOADS	PL 1-3
MERLIN.....	PL 1-3

118

PL 1-1

PL PWR/118/A/FIN A

PL PWRDN MATRIX

PL PWRDN ASC	PROCEDURE	ACTION
PWRDN FOR LOSS OF:		
2 CAB FANS		A
CAB PRESS		A
(MINOR PWRDN; from step 3 for OV-105)		A
(MAJOR PWRDN; from step 4 for OV-105)		A
AV BAY COOLING/AV BAY FIRE		B
2 H ₂ O LOOPS		A
[PLT PWRDN, SYS AOA, <u>2 H₂O LOOPS</u> <u>(AOA)</u> ; (CDR/PLT PWRDNS)]		A
(POST OMS-2)		A
1 FREON LOOP		N/A
HI LOAD EVAP		N/A
2 FREON LOOPS		A
[PLT PWRDN, SYS AOA, <u>2 FREON</u> <u>LOOPS (AOA)</u> ; (CDR/PLT PWRDNS)]		A
(POST OMS-2)		A
FES /1 FC		N/A
2nd FC		A
MN BUS UNDERVOLTS/FC VOLTS		
(from step 6; permanent loss of PL PRI)		N/A
(from step 14; temporary loss of PL PRI)		N/A

118

PL 1-2

PL PWR/118/A/FIN A

ACTION

A	PWRDN	PWRUP
<u>MIDDECK PAYLOADS</u>		N/A
	<u>NOTE</u> When orbiter pwr removed, science degradation or loss will occur to MERLIN (5 min), all CBTM (15 min) and CCM-A (15 min)	
	<u>CBTM</u>	
ML85E	1. DC 10 AMP MNB S2 – OFF	
	<u>CCM-A</u>	
ML85E	2. DC 10 AMP MNB S4 – OFF	
	<u>MERLIN</u>	
ML85E	3. DC 10 AMP MNB S3 – OFF	

B	PWRDN	PWRUP
<u>MIDDECK REAR-BREATHER PAYLOADS</u>		N/A
IF AV BAY 2:		
	<u>MERLIN</u>	
ML85E	1. DC 10 AMP MNB S3 – OFF	

118

PL 1-3

PL PWR/118/A/FIN A

This Page Intentionally Blank

118

PL 1-4

PL PWR/118/A/FIN A

PL PWRDN – ORBIT

PL PWRDN MATRIX.....	PL 2-2
ACTION.....	PL 2-3
PRIORITY PWRDN PP3A.....	PL 2-3
FLIGHT DECK/MIDDECK	PL 2-3
SSV.....	PL 2-3
OCAC	PL 2-3
PRINTER	PL 2-3
SPACEHAB	PL 2-3
OIU	PL 2-3
PWRUP	PL 2-4
SPACEHAB	PL 2-4
PRIORITY PWRDN PP3B.....	PL 2-5
MIDDECK PAYLOADS (CCM-A, MERLIN)	PL 2-5
CCM-A	PL 2-5
MERLIN.....	PL 2-5
OBSS.....	PL 2-5
SPACEHAB	PL 2-5
ESP-3	PL 2-6
MIDDECK PAYLOADS (CBTM)	PL 2-6
CBTM.....	PL 2-6
PWRDN A	PL 2-7
SPACEHAB	PL 2-7
PWRDN B	PL 2-7
SPACEHAB	PL 2-7
PWRDN C	PL 2-8
SPACEHAB	PL 2-8
PWRUP C	PL 2-9
SPACEHAB	PL 2-9
PWRDN D	PL 2-10
MIDDECK REAR-BREATHER PAYLOADS	PL 2-10
MERLIN.....	PL 2-10

PL PWRDN
ORB

**PL PWRDN
ORB**

PL PWRDN MATRIX

PROCEDURE	ACTION
PWRDN FOR LOSS OF:	
HI LOAD EVAP	N/A
1 FREON LOOP	PP3A,PP3B (on MCC call) as reqd*
AV BAY COOLING (from MAL GPC FRP-7)	D
1 FC	PP3A, PP3B (on MCC call) as reqd* until TOT FC kW < 17
FES (ON ORBIT) (DEORBIT PREP)	PP3A*,PP3B** (on MCC call) as reqd*
MN BUS UNDERVOLTS/FC VOLTS (from step 6; permanent loss of PL PRI)	A
(from step 14; temporary loss of PL PRI)	B
AV BAY FIRE	C
PRIORITY PWRDN GROUP 3	D
	PP3A,PP3B (on MCC call) as reqd*

* PRIORITY PWRDN 3A (PP3A) contains recoverable PL ops pwrndn Steps

**PRIORITY PWRDN 3B (PP3B) is a total PL pwrndn that may cause PL ops to be nonrecoverable

ACTION

PP3A	PRIORITY PWRDN (Recoverable) (On MCC call only)
<u>FLIGHT DECK/MIDDECK</u>	
	1. Pwr dn non-essential PGSCs 2. Pwr dn unnecessary cabin lighting 3. Pwr dn unnecessary camera equip
<u>SSV</u>	
SSV	4. SSV pwr – 0 (off)
PDIP 2	5. DC PWR 1 CAB PL – OFF
<u>OCAC</u>	
MO52J	6. DC UTIL PWR MNA – OFF 7. AC UTIL PWR AC1 – OFF
<u>PRINTER</u>	
PRINTER	8. Printer pwr – OFF
<u>SPACEHAB</u>	
	If Subsystem PGSC on:
FC06	9. Press [ALT]/[Q] to exit software 10. [Shift]/[F10] to confirm 11. Shut down Windows 12. √Automatic pwr off PGSC 13. Close PGSC 14. A31P 28VDC Pwr Supply INPUT POWER sw – OFF (OUTPUT POWER lt off) 15. cb DC3 – OFF
Pwr Supply	Else continue to next step
	If portable fluorescent light on:
EXCP1	16. Portable fluorescent light sw – OFF 17. cb AC1 – OFF
	Else continue to next step
<u>OIU</u>	
SSP 1	18. OIU PWR 1(2) – OFF (tb-bp) If addnl pwrndn reqd: 19. Go to PRIORITY PWRDN 3B (PP3B)
----- (Cont next page)	

PP3A (Cont)	PRIORITY PWRDN (Recoverable) (On MCC call only)
	PWRUP
	1. On MCC GO
<u>SPACEHAB</u>	
EXCP1	2. cb DC3 – ON
	3. A31P 28VDC Pwr Supply INPUT PWR
	SW – ON (OUTPUT PWR lt - lt on)
PGSC	4. PGSC Pwr – on
	5. √Windows displayed
	6. Double-click: SHUTTLE APPS folder on desktop SPACEHAB folder SPACEHAB MONITOR icon
	PGSC: SPACEHAB SUMMARY
EXCP1	7. √Spacehab tlm is present on display
	8. cb AC1 – ON
	9. Portable fluorescent light sw – ON

PP3B	PRIORITY PWRDN (Non-Recoverable) (On MCC call only)	PWRUP
	<u>MIDDECK PAYLOADS (CCM-A, MERLIN)</u>	N/A
	<u>NOTE</u> When orbiter pwr removed, science degradation or loss will occur to MERLIN (5 min) and CCM-A (15 min)	
	<u>CCM-A</u>	
MF71H	1. POWER – OFF (\sqrt{POWER} lt – OFF)	
	<u>MERLIN</u>	
MF71E	2. cb MAIN – op (\sqrt{lt} – OFF)	
	<u>OBSS</u>	
	3. LCC DEACT (P/TV Cue Card, <u>LCS</u>) LCH DEACT (P/TV Cue Card, <u>LCS</u>) LDRI/ITVC DEACT (P/TV Cue Card, <u>LDRI/ITVC</u>)	
	<u>SPACEHAB</u>	
	4. Perform SPACEHAB 30-MIN DEACTIVATION (SH OPS, <u>SH CONTINGENCY PROCS</u>) omitting steps 14 and 25, then:	
SSP 2	5. MN PWR – KILL – NO-OP If PL AC3 unavailable: <div style="border: 1px solid black; padding: 2px;">SM 214 SPACEHAB ACT/DEACT</div>	

118

PL 2-5

PL PWR/118/O/FIN A

PP3B (Cont)	PRIORITY PWRDN (Non-Recoverable) (On MCC call only)	PWRUP
CRT	6. H2O PUMP 1/2 OFF – ITEM 71 EXEC (*)	
C3	7. H2O LN HTRS – ON	
SSP 1	8. cb SW PWR 2 – cl	
	9. ORB H2O LINE HTR PWR A – ON	
	10. √B – OFF (A ENA)	
	SM 215 SPACEHAB ECS	
CRT	11. √H2O LN HTR HAB STATUS – 1	
	12. √ORB AMPS > 1	
MA73C:E	13. cb AC3 PL 3Φ – op	
	On MCC GO:	
R1	14. PL PRI MNC(MNB,FC3) – OFF (tb-OFF) AUX – OFF	
<u>ESP-3</u>		
A15	15. APCU 1 CONV – OFF	
	SM 179 POWER TRANSFER	
CRT	√PTU 1 APCU OUT VOLTS: < 10 V	
A15	APCU 1 OUPUT – OFF	
	<u>MIDDECK PAYLOADS (CBTM)</u>	
	<u>NOTE</u>	
	When orbiter pwr removed, science degradation or loss will occur to all CBTM (15 min)	
	<u>CBTM</u>	
MF43E	16. LIGHTS – OFF FANS – OFF cb MAIN BREAKER – op	
MF57E	17. LIGHTS – OFF FANS – OFF cb MAIN BREAKER – op	
MF43K	18. LIGHTS – OFF FANS – OFF cb MAIN BREAKER – op	

A	PWRDN	PWRUP
<u>SPACEHAB</u>		N/A
SSP 2	1. MN PWR – KILL – NO-OP	
C3	2. H2O LN HTRS – ON	
SSP 1	3. cb SW PWR 2 – cl 4. ORB H2O LINE HTR A – ON 5. √B – OFF (A ENA)	
	If spec available: SM 215 SPACEHAB ECS	
CRT	6. √H2O LN HTR HAB STATUS – 1 7. √ORB AMPS > 1	
R1	8. PL PRI MNC(MNB,FC3) – OFF (tb-OFF)	

B	PWRDN (PL PRI permanently lost)	PWRUP
<u>SPACEHAB</u>		N/A
	If PL AC3 unavailable:	
C3	1. H2O LN HTRS – ON	
SSP 1	2. cb SW PWR 2 – cl 3. ORB H2O LINE HTR PWR A – ON 4. √B – OFF (A ENA) SM 215 SPACEHAB ECS	
	5. √H2O LN HTR HAB STATUS – 1 6. √ORB AMPS > 1 SM 214 SPACEHAB ACT/DEAC	
MA73C:E	7. FANS ARS OFF – ITEM 61 EXEC (*) 8. H2O PUMP 1/2 OFF – ITEM 71 EXEC (*) 9. cb AC3 PL 3Φ – op 10. Perform SPACEHAB 30-MIN DEACTIVATION (SH OPS, <u>SH CONTINGENCY PROCS</u>)	
SSP 2	11. MN PWR – KILL – NO-OP	
R1	12. √PL PRI MNC,MNB,FC3 (three) – OFF (tb-OFF)	

C	PWRDN (PL PRI temporarily lost)
<u>SPACEHAB</u>	
If PL AC3 unavailable:	
C3 1. H2O LN HTRS – ON	
SSP 2 2. cb SW PWR 2 – cl	
3. ORB H2O LINE HTR PWR A – ON	
4. √B – OFF (A ENA)	
SM 215 SPACEHAB ECS	
5. √H2O LN HTR HAB STATUS – 1	
6. √ORB AMPS > 1	
MA73C:E 7. cb AC3 PL 3Φ – op	
SSP 2 8. MN PWR – KILL – NO-OP	
9. Return to calling procedure: MN BUS UNDERVOLTS/FC VOLTS, 1.1c '214 SH MN BUS V ↑↓' or '214 SH SEC BUS V ↑↓' (SH MAL, <u>EPS</u>)	

118

PL 2-8

PL PWR/118/O/FIN A

C (Cont)	PWRUP (PL PRI recovered)
	PWRUP (PL PRI recovered)
R1	1. PL PRI MNC(MNB,FC3) – ON (tb-ON)
	<u>SPACEHAB</u>
	If PL PRI recovered and PL AC3 not available: 2. Perform MN PWR KILL RECOVERY – ARS FAN AND PUMP ON INVERTER AC (SH OPS, <u>SH CONTINGENCY PROCEDURES</u>)
	If PL PRI recovered and PL AC3 never lost: 3. Perform MN POWER KILL RECOVERY ARS FAN AND PUMP ON ORB AC (SH OPS, <u>SH CONTINGENCY PROCS</u>)
	If PL PRI and PL AC3 recovered: SM 214 SPACEHAB ACT/DEAC
CRT	4. FANS ARS OFF – ITEM 61 EXEC (*)
MA73C:E	5. cb AC3 PL 3Φ – cl
CRT	6. √HX H2O FLOW ARS > 75 √CAB > 250
	<u>NOTE</u> Expect SM ALERT msgs: '215 SH H2O HTR ORB' '215 SH H2O HTR HAB'
C3	7. H2O LN HTRS – OFF
SSP 1	8. ORB H2O LINE HTR PWR A – OFF (B ENA) √B – OFF (A ENA)
CRT	9. cb SW PWR 2 – op 10. FANS ARS ON – ITEM 67 EXEC (*) 11. Perform MN PWR KILL RECOVERY – ARS FAN AND PUMP ON ORBITER AC (SH OPS, <u>SH CONTINGENCY PROCS</u>)

D	PWRDN	PWRUP
<u>MIDDECK REAR-BREATHER PAYLOADS</u>		N/A
IF AV BAY 2:		
	<u>MERLIN</u>	
ML85E	1. DC 10 AMP MNB S3 – OFF	

118

PL 2-10

PL PWR/118/O/FIN A

PL SAFING – ORBIT

PL SAFING MATRIX.....	PL 3-2
ACTION.....	PL 3-2
PL SAFING A	PL 3-2
MIDDECK TRANSFER	
(IF NOT ALREADY PERFORMED)	PL 3-2
MIDDECK PAYLOADS.....	PL 3-2
CBTM	PL 3-2
CCM-A	PL 3-2
MERLIN.....	PL 3-2
SPACEHAB TRANSFER	
(IF NOT ALREADY PERFORMED)	PL 3-3
OIU	PL 3-3
PL SAFING B	PL 3-3
SPACEHAB	PL 3-3
PL SAFING C	PL 3-3
SPACEHAB	PL 3-3
PL SAFING D	PL 3-3
APCU	PL 3-3

PL SAFING
ORB

118

PL 3-1

PL PWR/118/O/FIN A

PL SAFING MATRIX

PROCEDURE	ACTION
9.101 JOINT EXPEDITED UNDOCKING AND SEPARATION, from step 17b (SODF: JOINT OPS, <u>EMERGENCY RESPONSE</u> ; JEUS)	PL SAFING A,B
PWRDN FOR LOSS OF:	
2 CAB FANS	PL SAFING A,B
2 H2O LOOPS	PL SAFING A,B
CAB PRESS	PL SAFING A,C
2nd FC (TIG < 4 hr) (from step 5) (TIG > 4 hr) (from step 15)	PL SAFING A,C,D PL SAFING A,C,D
2 FREON LOOPS	PL SAFING A,C,D

ACTION

A	PL SAFING
<u>MIDDECK TRANSFER (IF NOT ALREADY PERFORMED)</u>	
If transfer hardware in ODS: 1. Complete transfer to ISS Else: 2. Stow in Middeck	
<u>MIDDECK PAYLOADS</u>	
<u>CBTM</u> ML85E 3. DC 10 AMP MNB S2 – OFF <u>CCM-A</u> ML85E 4. DC 10 AMP MNB S4 – OFF <u>MERLIN</u> ML85E 5. DC 10 AMP MNB S3 – OFF	

PL SAFING
ORB

118

PL 3-2

PL PWR/118/O/FIN A

A (Cont)	PL SAFING
<u>SPACEHAB TRANSFER (IF NOT ALREADY PERFORMED)</u>	
If one of the following is loose in SPACEHAB,	
	6. STOW ASAP : <ol style="list-style-type: none"> OBSS OSE Boom Stand secure at AS01 OBSS OSE Boom Stand secure at AS03

B	PL SAFING
<u>SPACEHAB</u>	
If AOS:	
	1. Perform <u>SPACEHAB EMERGENCY EGRESS</u> (Cue Card)
If LOS:	
	2. Perform <u>SPACEHAB EMERGENCY DEACTIVATION</u> (Cue Card), then:
L1	3. √FLOW PROP VLV LOOP 1,2 (two) – ctr (tb-ICH)

C	PL SAFING
<u>SPACEHAB</u>	
	1. Perform <u>SPACEHAB EMERGENCY DEACTIVATION</u> (Cue Card), then:
L1	2. √FLOW PROP VLV LOOP 1,2 (two) – ctr (tb-ICH)
R1	3. PL PRI MNC(MNB,FC3) – OFF (tb-OFF) AUX – OFF

D	PL SAFING
<u>APCU</u>	
A15	1. APCU 1,2 CONV (two) – OFF 2. OUTPUT (two) – OFF

This Page Intentionally Blank

118

PL 3-4

PL PWR/118/O/FIN A

PL PWRDN – ENTRY

PL PWRDN MATRIX.....	PL 4-2
ACTION.....	PL 4-3
PWRDN/PWRUP A	PL 4-3
SPACEHAB	PL 4-3
PWRDN B	PL 4-3
SPACEHAB	PL 4-3
PWRDN/PWRUP C	PL 4-4
SPACEHAB	PL 4-4
PWRDN D	PL 4-4
MIDDECK PAYLOADS.....	PL 4-4
CBTM.....	PL 4-4
CCM-A	PL 4-4
PWRDN E	PL 4-4
MIDDECK REAR-BREATHER PAYLOADS	PL 4-4
.MERLIN.....	PL 4-4

PL PWRDN
ENT

118

PL 4-1

PL PWR/118/E/FIN A

PL PWRDN MATRIX

PROCEDURE	ACTION
PWRDN FOR LOSS OF:	
2 CAB FANS	D,E
2 H ₂ O LOOPS (ENTRY)	D,E
CAB PRESS	D,E
AV BAY COOLING (ENTRY)	E
1 FREON LOOP/HI LOAD EVAP (ENTRY)	A
FES	A
1 FC (ENTRY)	A
2 FREON LOOPS (ENTRY)	A,D,E
2nd FC (ENTRY)	A,D,E
MN BUS UNDERVOLTS/FC VOLTS (from step 6; permanent loss of PL PRI) (from step 14; temporary loss of PL PRI)	B C

PL PWRDN
ENT

118

PL 4-2

PL PWR/118/E/FIN A

ACTION

A	PWRDN/PWRUP	
<u>SPACEHAB</u>		
R1	1. PL CAB – OFF PRI MNC – OFF (tb-OFF) AUX – OFF AFT MNB – OFF	
R1	If time to TIG is greater than 20 minutes: 2. PL CAB – MNA(MNB) AFT MNB – ON	
C3	3. H2O LN HTRS – ON	
SSP 1	4. cb SW PWR 2 – cl 5. ORB H2O LINE HTR PWR A – ON 6. √B – OFF (A ENA)	
	If spec available: SM 215 SPACEHAB ECS	
CRT	7. √H2O LN HTR HAB STATUS – 1 8. √ORB AMPS > 1	
<hr/>		
R1	1. PL AUX – ON	
SSP 2	2. MN PWR – KILL – NO-OP	
	3. √MCC for further action	

B	PWRDN	PWRUP
<u>SPACEHAB</u>		N/A
SSP 2	1. MN PWR – KILL – NO-OP	

C	PWRDN/PWRUP
<u>SPACEHAB</u>	
SSP 2	<ol style="list-style-type: none"> 1. MN PWR – KILL 2. Return to MN BUS UNDERVOLTS/FC VOLTS
R1	<ol style="list-style-type: none"> 1. √PL PRI MNC – ON (tb-ON) <p>On MCC GO:</p> <ol style="list-style-type: none"> 2. MN PWR – NO-OP ORB SEC DC BUS – OFF,ON (tb-gray) INVERTER – ON,NO-OP (tb-gray) EXP DC BUS – ON,ctr (tb-gray) SS DC BUS – ON (tb-gray)

D	PWRDN	PWRUP
<u>MIDDECK PAYLOADS</u>		N/A
	<u>NOTE</u> When orbiter pwr removed, science degradation or loss will occur to CBTM (15 min) and CCM-A (15 min)	
	<u>CBTM</u> <ol style="list-style-type: none"> ML85E 1. DC 10 AMP MNB S2 – OFF <u>CCM-A</u> <ol style="list-style-type: none"> ML85E 2. DC 10 AMP MNB S4 – OFF 	

E	PWRDN	PWRUP
<u>MIDDECK REAR-BREATHER PAYLOADS</u>		N/A
IF AV BAY 2:		
	<u>MERLIN</u> <ol style="list-style-type: none"> ML85E 1. √DC 10 AMP MNB S3 – OFF 	

118

PL 4-4

PL PWR/118/E/FIN A

Space Shuttle Program
FLIGHT DATA FILE

JSC-48097-118
FINAL, REV A



**PAYLOAD
POWERDOWN**

**STS
118**

Flight Cover (trim bottom to expose tabs)