

Description

Presenter Glen Finneman		
Date 7/15/2011	Page 1	

- GPC 4 (SM) failed during crew sleep
- GPC 2 was brought online and configured for SM
- GPC 4 was powered OFF
- GPC 1 HISAM was performed following crew wakeup
- GPC 4 HISAM was performed
- Data Dump first look shows
 - CPU Store Protect Error
 - PC 1 Timer Interrupt
- GPC 4 was IPL' ed and added to Redundant Set in G2
- GPC 4 was freeze dried in G2 and put in STBY









Forward Plan

Presenter Glen Finneman		
Date 7/15/20	l1 Pa	^{ige} 2

- Analysis of Memory Dump continues
- MOD investigating any contributing factors
 - South Atlantic Anomaly (SAA)
 - Coronal Mass Ejection (CME)
 - Stored Program Command (SPC)
- PRACA history review for similar failure signatures
- Discussions on any Confidence Runs prior to deorbit prep
- MOD discussing Entry configurations





