Figure #1

Micro Shorts caused by a dull shear
Figure #2



Figure #3



Thermalite with only one wire wrap remaining
Figure #4



Figure #5



Thermalite wire wrapping tool
(not to scale)
Figure #6



Igniter wire wrapping tool
(not to scale)
Figure #7



Figure #8

For large throats

For small throats



Figure #11



Figure #9



Figure #10



Figure #12