
# MANUFACTURING PLAN FOR PROJECT APOLLO-LUNAR EXCURSION MODULE

LPL-850-1



GRUMMAN AIRCRAFT ENGINEERING CORPORATION



LPL-850-1 "A" 14 May 1963 Revised 14 Oct. 1963

# REVISIONS

# SECOND SUBMITTAL - 14 OCTOBER 1963

Revised or Added Pages*	Revision Description
General	Plan downgraded from confidential to unclassified.
Introduction	Introduction re-written to define Revision "A" to LPL-850-1.
1-2, 1-3	Expanded write-up with respect to use of advanced engineering information.
1-3	Revised tooling discussion of structural and installation rates.
1-4	Revised Figure 1-2 in accordance with Master Phasing Chart, dated 15 September 1963.
1-5	Added discussion of follow-on manufacturing engineering efforts.
1-6 Thru 1-14	Expanded the management control of LEM activities.
1-9	Added Figure 1-4.
1-13, 1-14	Added discussion of re-training for space manufacturing skills.
1-14 Thru 1-17	Up-dated "make or buy" discussions & figure.
Section 2	Expanded and revised manufacturing facilities plan. Percent utilization of non-exclusive areas noted. All plant layouts up-dated
3-1 Thru 3-5	Added schedule development and priority data.
3-6	Added discussion of tool movement & tool storage control.
3-6 Thru 3-12	Revised schedule discussion and added TM-2 charts, and summary schedule of TM-2, M-5, & PD units. Deleted Obsolete LTA-4 Schedule.
3-23, 3-24	Added Interchangeability and Replaceability data.
3-27	Added discussion of LEM standards.
3-28	Manufacturing, Assembly and Inspection Record (MAIR) as shown in QC Plan is referenced.
3-29, 3-20	Up-dated review and analysis of subcontractor proposals.
3-36, 3-37	Added discussion of balancing work load.
3-40, 3-41	Revised traceability and configuration control description.

\*Revised or added pages are dated 14 October 1963.

# REVISIONS

# SECOND SUBMITTAL - 14 OCTOBER 1963

Revision Description
Revised and up-dated all technical discussions to agree with design configuration data available as of 1 October 1963.
Expanded tooling requirements lists. Added fixture sketches.
Revised Subassembly Breakdown & Manufacturing Flow Diagrams in accordance with October 1 configuration.
Area for installation of Electrical Power Subsystem changed to clean room.
Up-dated the discussion of Manufacturing Test Program.
Up-dated the GSE/STE discussions and Planning Flow Diagram.
Expanded the Field Site Support data.



# TABLE OF CONTENTS

Section		Page
	Introduction	xii
	Summary	xiii
1	DESCRIPTION AND IMPLEMENTATION - LEM MANUFACTURING PLAN	
1.1	Development Manufacturing Approach • • • • • • • • • • • • • • • • • • •	1-1
1.2	Implementation of the LEM Manufacturing Plan	1-6
1.3	Make or Buy Summary	1-14
2	MANUFACTURING FACILITIES	
2.1	Facility Utilization and Manufacturing Flow	2-1
2.1.1	Plant 5 - Centralized LEM Assembly, Installation, and Test	2-5
2.1.2	Plant 3 - Ascent Stage Structural/Mechanical Manufacturing · · · ·	2-10
2.1.3	Plant 2 - Descent Stage Structural/Mechanical Assembly and Manufacture of Detail Parts & Minor Subassemblies	2-18
2.1.4	Plant 12 - Plastic Parts	2-18
2.1.5	Plant 4 - Electronic Bench Test and Bench Maintenance · · · · ·	2-22
2.1.6	Tool Manufacturing Facilities · · · · · · · · · · · · · · · · · · ·	2-22
2.1.7	GSE/STE Manufacturing Facilities	2-27
3	SCHEDULING, PLANNING, METHODS, AND CONTROLS	
3.1	Scheduling	3-1
3.1.1	Manufacturing Scheduling	3-1
3.1.2	Tool Scheduling	3-3
3.1.3	LEM Manufacturing Program Schedules • • • • • • • • • • • • • • • • • • •	3-6
3.2	Planning	3-13
3.2.1	Manufacturing Planning	3-13
3.2.2	Tool Planning	3-17
3.2.3	Procurement Planning	3-22
3.3	Methods and Controls • • • • • • • • • • • • • • • • • • •	3-23
3.3.1	Mechanical Interface Control	3-23
3.3.2	Electrical/Electronic Interface Coordination	3-26

vi

Gumman L E M

# TABLE OF CONTENTS (Cont.)

Section		Page
3.3.3	Manufacturing Reliability Control	3-27
3.3.4	Control of Subcontractor Tooling and Manufacturing Activities	3-28
3.3.5	Schedule Control • • • • • • • • • • • • • • • • • • •	3-35
3.3.6	Cost Control	3-37
3.3.7	Parts Control (Production Control)	3-40
3.3.8	Traceability and Configuration Control	3-40
4	STRUCTURAL/MECHANICAL, FLUID, AND ELECTRONIC SUBSYSTEMS	
4.1	Structural/Mechanical and Crew Provisions Subsystems $\cdots$ · · ·	4-1
4.1.1	Structural/Mechanical Subsystems	4-2
4.1.2	Crew Provisions Subsystem • • • • • • • • • • • • • • • • • • •	4-36
4.2	Fluid Subsystems	4-36
4.2.1	Propulsion Subsystem - Ascent Stage • • • • • • • • • • • • • • • • • • •	4-37
4.2.2	Propulsion Subsystem - Descent Stage	4-43
4.2.3	Reaction Control and Environment Control Subsystems	4-43
4.3	Electrical/Electronic Subsystems	4-43
4.3.1	Electrical Power Subsystem	4-44
4.3.2	Communications Subsystem • • • • • • • • • • • • • • • • • • •	4-44
4.3.3	Navigation and Guidance and Stabilization and Control Subsystems $\cdot$	4-44
5	FINAL ASSEMBLY	
5.1	Final Assembly Description	5-1
5.2	Final Assembly and Subsystems Installations - Ascent Stage	5-1
5.3	Final Assembly and Subsystems Installations - Descent Stage	5-5
5.4	Ascent/Descent Joining and Critical Subsystem Alignment	5-6
6	MANUFACTURING TEST PROGRAM	
6.1	Description and Implementation • • • • • • • • • • • • • • • • • • •	6-1
6.2	Manufacturing Tests - Structural/Mechanical, and Crew Provisions Subsystems	6-3
6.2.1	Structural/Mechanical Subsystem	6-3



Gumman L € M

vii

# TABLE OF CONTENTS (Cont.)

Section		Page
6.2.2	Crew Provisions Subsystem	6-4
6.3	Manufacturing Test - Fluid Subsystems	6-5
6.3.1	Reaction Control and Propulsion Subsystems	6-5
6.3.2	Environmental Control Subsystem	6-6
6.4	Manufacturing Test - Electrical/Electronic Subsystems	6-7
6.4.1	Electrical Power Subsystem	6-7
6.4.2	Communications, Instrumentation, Displays and Controls, Stabilization and Control, and Navigation and Guidance Subsystems	6-8
6.5	Ground and Flight Test Programs Support	6-10
7	MANUFACTURE OF GSE/STE	
7.1	GSE/STE Manufacturing Plan	7 - 1
7.1.1	Electronic GSE/STE • • • • • • • • • • • • • • • • • • •	7 - 4
7.1.2	Fluid Systems GSE/STE ••••••••••••••••••••••••••••••••••••	7-5
7.1.3	Handling and Transportation GSE	7-7
7.1.4	Training Equipment	7-8
8	FIELD SITE SUPPORT	
8.1	Test and Launch Site Activities • • • • • • • • • • • • • • • • • • •	8-1



# LIST OF ILLUSTRATIONS

Figure		Page
1-1	Previous Grumman Application of Three Manufacturing Plan Types	1-2
1-2	LTA and LEM Manufacturing Rates	1-4
1-3	Organization Chart	1-8
1-4	LEM Manufacturing Organization Chart	1-9
1-5	Make or Buy Summary - Ascent Stage	1-15
1 - 6	Make or Buy Summary - Descent Stage	1-16
2-1	Basic LEM Manufacturing Flow Through Bethpage Facility	2-4
2-2	Plant 5 LEM Assembly, Installation, & Test	2-6
2-3	Plant 5 - Clean Room for Bench Test, Assembly and Installation of RCS, ECS, and EPS	2-7
2-4	Clean Room - RCS, ECS, and EPS Installation & Testing	2-8
2-5	Clean Room - Inspection and Cleaning Facilities	2-9
2-6	Plant 3 - LEM Ascent Stage Structural/Mechanical Manufacturing	2-11
2-7	Plant 3 - Vertical Lathe Equipment	2-12
2-8	Plant 3 - Milling Equipment	2-13
2-9	Plant 3 - Forming and Bonding Equipment	2-14
2-10	Plant 3 - Resistance and Automatic Fusion Welding Equipment	2-15
2-11	Plant 3 - Automatic Welding Equipment	2-16
2-12	Plant 3 - Chemical Milling Facility	2 - 17
2-13	Plant 2 - LEM Descent Stage Structural/Mechanical Assembly & Manufacture of Detail Parts & Minor Subassemblies	2-19
2-14	Plant 2 - Forming Equipment and Consolidated Detail PartsFacility	2-20
2-15	Plant 2 - Forming and Age-Hardening Facilities	2-21
2-16	Plant 12 - Fiberglass Manufacturing Facilities	2-23
2-17	Jig and Fixture Manufacturing Facilities	2-24
2-18	Template and Tooling Mockup Facilities	2-25
2-19	GSE/STE Manufacturing Facilities	2-28
2-20	Test Equipment Shop	2-29
3-1	Manufacturing Scheduling Flow	3-12



# LIST OF ILLUSTRATIONS (Cont.)

Figure		Page
3-2	Tool Scheduling Flow	3-5
3-3	LEM TM-2 Descent Stage Subassembly Breakdown & Manufacturing Flow and LEM TM-2 Descent Stage Manufacturing Schedules	3-8
3-4	Manufacturing Schedule Summary - LEM TM-2, M-5, PD-4, PD-1, PD-5, and PD-2	3-12
3-5	Manufacturing Planning Flow	3-14
3-6	Sample LEM Shop Work Order and Route Card	3-16
3-7	Tool Planning Flow	3-18
3-8	ME-269 Record Sheets	3-19
3-9	Grumman Tool and Equipment Letter Codes	3-21
4-1	LEM General Arrangement Configuration	4-3
4-2	LEM Subassembly Breakdown	4-4
4-3	Ascent Stage Structural Subassembly Flow	4-5
4-4	Descent Stage - Subassembly Breakdown	4-6
4-5	Chem-Milling of a Typical LEM Detail	4-9
4-6	Face Subassembly Breakdown and Manufacturing Flow	4-12
4-7	Cabin Subassembly Breakdown and Manufacturing Flow	4-13
4-8	Mid Section Subassembly Breakdown and Manufacturing Flow	4-14
4-9	Aft Equipment Bay Subassembly Breakdown and Manufacturing Flow	4-15
4-10	Typical Combination Fixture-Welding and Machining of Skin and Cruciform Assemblies	4-19
4-11	Combination Fixture-Welding of N&G Dome to Cabin Subassembly	4-20
4-12	Weld Fixture-Welding of Face to Cabin Subassembly	4-21
4-13	Weld Fixture-Weld Tunnel to Top Deck	4-23
4-14	Combination Fixture-Welding of Lower Deck, Side Skin/Cruciform and Upper Deck/Docking Tunnel Subassemblies	4-24
4-15	Combination Fixture-Welding of Aft Ring and Forward Bulkhead	4-25
4-16	Joining of Face/Cabin and Mid Section Subassemblies	4-27
4-17	Final Structural Assembly Fixture-Ascent Stage	4-29
4-18	Final Structural Assembly Fixture-Descent Stage	4-33



## LIST OF ILLUSTRATIONS (Cont.)

Figure		Page
4-19	Manufacturing Flow Diagram-Ascent/Descent Lines and Ascent Tanks	4-40
4-20	Automatic Fusion Welding of Aluminum Ascent Tanks	4-41
4-21	Induction Brazing of Line Assemblies	4-42
5-1	Installation, Joining, and Alignment Flow	5-2
5-2	Manufacturing Alignment and Functional Test Fixture	5-7
7 - 1	GSE/STE Planning and Manufacturing Flow	7-3
7-2	Preventive Maintenance Procedure Form	7-6

# LIST OF TABLES

Table		Page
2-1	LEM Area Allocation Summary	2-1
2-2	LEM Facility Availability and Usage Schedule	2-2
4-1	Ascent Stage - Major Assemblies and Major Tools Required	4-10
4-2	Descent Stage - Major Assemblies and Major Tools Required	4-31
4-3	Ascent Stage - Flight-Weight Propulsion Tank Fixtures	4-38
4-4	Ascent Stage - Boiler Plate Tank Fixtures	4-39



#### INTRODUCTION

Revision "A" to the "LEM Manufacturing Plan" is submitted in fulfillment of the requirements of paragraph 3.4 – Documentation Requirements List for Type I Documents.

NASA/MSC approval of this document was forwarded in letter SLP-22-63-496, Subject: "Contract NAS 9-1100, Item #22, Manufacturing Plan, Grumman Report LPL-850-1".

This approved plan incorporates the refinements requested by NASA during the draft review held in Houston, Texas on 17 and 18 October 1963. The RASPO has also provided a review prior to release for printing. A third submittal of the LEM Manufacturing Plan is scheduled for publication during April 1964.

In accordance with a NASA/MSC agreement, all data contained in this second submittal is based on LEM Program information which was available as of 1 October 1963.

NASA recipients of this document may refer questions or comments to MSC, Attention: SLP, Mr. Donald B. Sullivan. Grumman comments shall be directed to Chris Hansen, Manufacturing Engineering, Plant 2.



#### SUMMARY

xiii

The "LEM Manufacturing Plan" emphasizes a unified team effort for the management, implementation, and control of all manufacturing phases. This LEM manufacturing team concept assures closely coordinated technical and managerial programs for effectively performing the following major LEM functions:

- LEM Fabrication, assembly, and subsystem installations.
- Manufacturing test programs for both in-house fabricated units and vendor supplied subsystem components.
- Fabrication of LEM handling and Transportation GSE; fluid systems GSE/STE; electronic GSE/STE; and training equipment.
- Design and manufacture of tooling for LEM fabrication, assembly, and installation operations.
- Selection, utilization, and maintenance of manufacturing equipment and processes.
- Manufacturing team support of field-site activities.

Summarized approaches to these six major LEM manufacturing functions are described in Section 1.1. As stated throughout this plan, the primary goals of highest mission reliability, on-schedule performance, and lowest possible over-all costs have established the criteria for the evaluation and selection of all manufacturing procedures and techniques.

Grumman fully recognizes the responsibility to NASA for the control of both in-house and vendor manufacturing performance. Section 3.3 outlines the methods and controls which are planned for satisfying these requirements.

SECTION 1 - Description and Implementation - LEM Manufacturing Plan

# <u>SECTION 1</u> DESCRIPTION AND IMPLEMENTATION -LEM MANUFACTURING PLAN

#### 1.1 DEVELOPMENT MANUFACTURING APPROACH

Grumman has selected a proven Development Manufacturing Plan to satisfy the high reliability requirements, to meet the critical schedule milestones, and to achieve lowest possible over-all program costs.

The effectiveness of this manufacturing approach which is specifically geared for low-volume/low-rate production, has been demonstrated by the on-schedule development of the highly sophisticated Grumman A-6A Intruder and E-2A Hawkeye manned flight systems.

For comparative purposes, Figure 1-1 shows previous Grumman applications of the Experimental, Development, and Production Plans.

Negotiated LEM Program costs reflect the use of the ideally suited development manufacturing approach. The factors which have influenced this selection are summarized as follows:

• Primary consideration has been given to the extreme program flexibility required for rapid response to LEM refinements and changes. Engineering design details will be continuously influenced by further accumulation of scientific manned space flight data and by test program results. Anticipated refinements and allowance for future LEM growth potential must be accommodated by giving advanced consideration to ease of tool and equipment modification and to adjustment of manufacturing and testing techniques. The Development Plan combines the flexible and adaptable features of the Experimental Plan with the reliable and economical characteristics of the Production Plan.


#### Experimental Manufacturing Plan

Grumman Application:

The "Experimental Manufacturing Plan" is used when only one or two units are to be produced. Follow on manufacture is not considered.

**Previous Example:** 

Flying engine test cell for attachment to the B-45 aircraft.



Experimental Fabrication of Engine Test Cell

Manufacturing Data:

Two units were produced. The first was completed eight months after go-ahead and the second unit three months thereafter.

**Development Manufacturing Plan** Also Selected for LEM Program

Grumman Application:

The "Development Manufacturing Plan" is used for programs requiring a transition from the design, development, test and evaluation phases to a low quantity followon manufacturing phase.

**Previous Example:** 

A-6A Intruder, the latest jet aircraft for carrier and land based general purpose attack.



Manufacture of A-6A Intruder Aircraft

#### Manufacturing Data:

Thirty-six systems have been produced to date. This aircraft is being produced at a rate of two units per month. (Maximum LEM rate will also be two units per month).

The "Production Plan" is used for programs which warrant highly refined tooling, equipment, process, and handling concepts, commensurate with high production rates.

**Previous Example:** 

The completed Grumman F9F-6 & 7 series Navy jet aircraft programs.





Manufacturing Data:

# Grumman Application:

Production Line for F9F Series Aircraft

A total of 816 F9F-6 & 7 aircraft were produced at a maximum rate of 67 units per month.

> Figure 1-1. Previous Grumman Application of Three Manufacturing Plan Types



- Overlapping of engineering design, tooling, manufacturing, and equipment program efforts will be necessary, because of the critical LTA and LEM schedules. Advanced engineering design information, such as layouts and jig point locations, will be used to initiate tool designs, as well as to expedite the fabrication of fixture frames and incorporation of major jig point fittings. Therefore, on-schedule availability of major fixtures is made possible by the judicious use of advanced information. The Development Manufacturing Plan is particularly applicable to this method of program acceleration.
- Figure 1-2 shows a peak structural manufacturing rate of two units per month for the 23rd and 30th month, and peak installation rates of two units per month for the 24th and 27th month after go-ahead. Fabrication of LTA-2 through LTA-6 and LEM-1 will be completed during the manufacturing peak period between mid October 1964 and mid February 1965. Completion of these six units during the 4-month period will yield an average structural manufacturing rate equivalent to 1.5 units per month for the peak period. Seven installations (LTA-1 through LTA-6 and LEM-1) will be completed during the 4.5-month installation peak period between December 1, 1964 and mid April 1965 for an average of 1.6 units per month. The Grumman tooling program was planned for the average rates stated above utilizing a double-shift production shop operation for the structural assembly phases.

Previous Grumman aircraft programs of comparable manufacturing rates have proven that high reliability at the lowest cost is most readily achieved by applying the Development Manufacturing Plan.

Since reliability, cost, and schedule objectives are also directly related to manufacturing producibility, the LEM engineering design concepts are being developed with maximum emphasis on use of existing state-of-the-art fabrication and testing techniques. The contribution of the LEM manufacturing team for producibility assurance is discussed in Section 3.3.3.

	FGODIDTION				9	1963						1964										1965										1966										1967						
L	DESCRIPTION J F M A M J J A S O N D					D,	J F M A M J J A S O N D							D	J F M A M J J A S O N D										D J F M A M J J A S O N D										J F M A M J J													
			2																										33 3																		55	
											T																																					
	LTA-1																																															
	LTA-2																																			1												
	LTA-3																																														_	
	LTA-4												¢																							-											_	
	LTA-5														-					2-14																												
urt 33)	LTA-6													[						12 / 8				8																							_	
Cha 19(	LTA-7																																			1											_	
ing oer	LTA-8 **																									8																					_	
laster Phasing Chart 1 15 September 1963)	LTA-9**																							_				9				3				1								-				
on Master Ph Dated 15 Sept	· · · · · ·																		-			•																		-							-	
Master ed 15 Sej	LEM-1				1					-																	1													1							_	
Ma ed	LEM-2																										8																				-	
on Dat	LEM-3				1											1																																
sed	LEM-4																			[										3													-				-	
Based I	LEM-5																																		1					1							_	
$\smile$	LEM-6			1						1																													-	1								
	LEM-7																														-									-								
	LEM-8			1	1		1								1																C				Post of											-	-	
	LEM-9																					1																					3				_	
	LEM-10														1																																	
	LEM-11			-					-						+											-																						
															+																										T						-	
5																					Ť										Ť			_							T						-	
	STRUCTURAL															1	0	0	1 1	1 2	2 1	1	1	1	1 (	) 2	0	0	1 (	0 0	1	0	0	1 (	0 0	1	1	0 0	) 1	0	0	1	0 0	) 1			-	
E E	RATE/MONTH																				T										T										T						-	
MANUFACTUR- ING RATES				+	+										1				-			-		-		-									-	+					++			+			-	
	INSTALLATION			1																1	2	0	1	2	1 0	) 1	1	1	1	1 0	1	0	0	0 1	1 0	0	1	0 (	) 1	1	0	0	1 (	0 0	1	0 0	0	
	RATE/MONTH																				T										T		-				_		-	-	Ĩ	-	-		_		-	
																							T	ECI	END		1																				=	
	* Detail shown																						1	UL GI	UND			] Fa	brica	ation	ı																	
	** LTA-8	8 &-9 egotia	are	tenta	ative	ly sl	howi	n as																					ssem																			
	n	egouia	ileu	D	ecen	nner	190	2																				In In	stall	ation	1 and	d Ch	ecko	out o	f Lin	nes,	Equ	ipme	ent,	and	Instr	rum	enta	tion				

Figure 1-2. LTA and LEM Manufacturing Rates



Highly skilled development shop technicians and minimum tooling of good quality will be utilized for the manufacture of the early LTA test modules. Some detail parts and minor subassemblies for these initial units will be fabricated on an experimental basis with adequate quality control. Subassembly and assembly fixtures for all manufacturing, up to and including the LTA-3 module, will incorporate the major jig point locations. As engineering designs progress, these tools will be improved and refined by the addition of other locating and clamping devices and by provisions for completing interchangeability/ replaceability requirements. The subassembly breakdown will be expanded and additional tool families provided to accommodate the manufacturing rate and the concurrent development requirements shown in Figure 1-2 and also for achieving the lowest possible combined tooling and manufacturing costs.

The basic tooling program will be completed during the manufacture of the LTA-4 Environmental Development Module. This tooling progression will result in early tool deliveries to meet initial LTA completion schedules, and will allow for the development of LTA-5 and subsequent modules using finally configured tooling.

The continued tooling program will provide for incorporation of normal engineering changes resulting from LTA and LEM test programs; initial tool prove-out changes; tool maintenance and repair; trouble shooting production problems, and subcontractor liaison. Tooling personnel will also be provided for assistance during periodic inspection of tools, liaison and tooling efforts for maintaining the I&R program requirements, and for maintaining precision optical alignment tool systems.

The sophisticated nature of the LEM Program dictates the use of manufacturing team technicians identified with each LTA and LEM. Each member of this team will be identified with a given subsystem from its acceptance through installation, testing, and field – site support. Upon completion of the mission, this experienced team will revert to a subsequent module within the same booster series. This assures clear lines of task continuity and the benefit of a high experience factor. The manufacturing test plans also emphasize the aforementioned "subsystem team approach" for assurance of the highest quality and reliability levels. Manufacturing test teams will make maximum use of GSE/STE for bench tests of mechanical, fluid, and electrical/electronic subsystems. Periodic maintenance and calibration of manufacturing test GSE/STE will be dictated by an "IBM alerting system". This periodic servicing will assure the highest level of equipment performance.

1 - 6

Gumman L E M

A team of subsystem test technicians, under the direction of the Structural/Mechanical Lead Technician, will also install test instrumentation and will participate in the set-up, performance, and documentation of the ground and flight test programs.

LEM GSE/STE requirements are divided into the four general classifications of handling and transportation GSE, electronic GSE/STE, fluid systems GSE/STE, and training equipment. The manufacturing approach has been established to enable efficient fabrication of the four distinctly different equipment types.

Grumman will use existing Avionic, Hydraulic, Tool and Test Equipment Shops which are presently organized with the necessary specialized skills, equipment, and facilities. This plan affords the advantages of optimum flexibility and maximum utilization of existing capabilities. Although many equipment types are required, production line or completely centralized facility concepts are not warranted since the manufacturing rate for each unit is minimal.

Sections 4 through 7 describe specific manufacturing, tooling, process, equipment, and manufacturing test plans for each LEM subsystem.

#### 1.2 IMPLEMENTATION OF THE LEM MANUFACTURING PLAN

As stated in the original proposal, Grumman has fully recognized that accomplishing the LEM objectives requires a "single product organization" which is solely concerned with the successful development of the LEM.

Accordingly, the "LEM Manufacturing Team", as shown in Figure 1-3, has been specifically organized to implement and manage all phases of the LEM manufacturing program. Maximum emphasis has been placed on the utilization of the best available managerial and technical talent, coupled with a manufacturing organization which is best suited for the LEM Program objectives. Key personnel assigned to the LEM Program are shown in Figure 1-4.

1 - 7

Mr. William Bruning, the LEM Manufacturing Manager, reports directly to the Program Manager. He is responsible for the coordination and management of all LEM fabrication, assembly, and installation operations; equipment fabrication; manufacturing testing; tooling; processes, and on-site and field support activities. In addition, he is responsible for the control of all applicable interfaces with NASA-MSC, NAA, and Grumman subcontractors.

As a member of the Program Management Team, the LEM Manufacturing Manager implements his responsibilities in the following manner:

- In conjunction with the other managers, Mr. Bruning reports weekly to the Program Manager and provides information such as completed activities for the preceding week and anticipated effort for the succeeding week.
- He consults with the Program Manager on a regular basis with regard to cost/ schedule performance of all tooling, test equipment, process, and manufacturing functions for the LEM Program. Further, he informs the Program Manager of manpower and facility planning status and unique technical aspects of the manufacturing program which may require support from the Program Office.
- He attends and participates in the monthly reviews of all contract line items as called by the Program Director and Program Manager. Mr. Bruning is also responsible for maintaining cognizance of all technical, cost, and schedule performance for Line Item 012, Final Assembly and Acceptance Tests.




Figure 1-3. Organization Chart



Gumman, L E M




Figure 1-4. LEM Manufacturing Organization Chart



- The release of engineering information for maintaining tooling and fabrication schedules, and concepts for design producibility are frequently reviewed with the Engineering Manager.
- Quality control and reliability requirements, as outlined by NPC-200-2 and augmented by the RASPO Quality Control Representative, are reviewed with the Quality Control Manager to assure unified approaches for maintaining the required degree of manufacturing quality. To further a common understanding, the Manufacturing Manager attends and participates in the biweekly review meetings scheduled by the RASPO Quality Control Representative and the Grumman Quality Control Manager.
- Requirements and plans for field-site test technician support and the training program for test technicians, both for field-site and in-house test, are discussed with the Test and Support Manager.
- Reviews are conducted with the Business Manager for timely delivery of subcontracted components. Personnel are supplied for evaluation of subcontractor proposals and for assistance with the monitoring of subcontractor cost, schedule, and technical performance. The Manufacturing Manager reviews and supplies data such as estimates, manpower distributions, and justifications for Manufacturing personnel requirements, change proposals, and overtime requests.
- Manufacturing milestones and corresponding time estimates are approved and supplied by the LEM Manufacturing Manager.
- He attends and participates in the Management Reviews scheduled by MSC.

Mr. Bruning is assisted by a LEM Manufacturing Management Staff which directly supervises and controls the performance of all functional manufacturing tasks. The following three team members are directly assigned to the LEM Program Management Staff:

Gumman LEM

- Robert Wagensiel, the LEM Project Manufacturing Engineer, is responsible for developing, providing, and maintaining all tooling necessary for the manufacture of the LEM, and is responsible for coordinating with LEM engineering to assure that the end items are producible. The responsibility of establishing and maintaining proper tool planning schedules; adequate facility arrangements for manufacturing; fabricating and maintaining handling equipment and providing optical measurement support for tests and alignment of hardware, also belongs to the LEM Project Manufacturing Engineer.
- Kenneth Dow, the LEM Test Equipment and Process Project Engineer, is responsible for the manufacturing, modification, and sustaining efforts required for fluid and electrical/electronic subsystem test equipment which is designed by the test equipment and process engineers. He is also responsible for developing the process systems necessary for the manufacture of the LEM; establishing test equipment fabrication schedules, monitoring the fabrication and maintenance of test equipment, and for translating engineering design information into process requirements for producing hardware.
- Thomas Stewart, the Shop Project Manager, is responsible for converting LEM engineering information into parts, subassemblies, final assembly, and followup through acceptance testing and field operations of the LEM. He establishes internal and external lead times in accordance with schedules and budgets, establishes and maintains proper production planning schedules, and coordinates with LEM engineering to assure compatibility of manufacturing plans with engineering progress. He also has the responsibility of providing technicians for field support activities, controlling spares (both in-house and in the field), shipping of hardware and completed LEM assemblies, and the supervision of procurement planning and controls. LEM representatives for each participating Grumman plant have been assigned to assist the Shop Project Manager in the control of LEM manufacturing activities. In addition, each major shop section or group has an assigned representative for direct manufacturing supervision.

1 - 11



The LEM Manufacturing Manager and his staff maintain their offices in the Plant 25 Engineering Center, and are located adjacent to the Program Management, Engineering, Quality Control, Test, and Business Management Sections. Immediate proximity to the over-all LEM Program allows for close observation and review of all program phases by virtue of the shortest possible lines of communication. This arrangement is presently resulting in a thorough knowledge of the latest LEM Program status; close coordination for initial manufacturing and equipment planning and schedule development; rapid investigations for make or buy decisions, and early contacts regarding producibility.

Figures 1-3 and 1-4 show "key personnel" who are responsible for coordinating the design and fabrication activities of the Manufacturing Engineering, Test Equipment and Process Engineering, and corporate manufacturing organizations. They are responsible for the direct supervision of participating sections and groups within the corporate organization.

Some key section personnel assigned for LEM planning and control, tool and equipment design, and process planning are presently located in the Plant 25 LEM offices. Other key section personnel will be assigned to this facility as the manufacturing effort increases.

Management control of LEM priority, with respect to other Grumman programs, is implemented in the following manner:

- The LEM Manufacturing Manager periodically reports the status of the program to the Director of Manufacturing. He requests priority action on items which require the specific attention of the Director. As indicated in Figure 3-1 and described in Section 3.1.1, the Director of Manufacturing approves and signs the manufacturing schedules. This establishes the over-all priority with respect to other programs.
- The Shop Project Manager reports the status of the program to the LEM Manufacturing Manager weekly. He requests action on priority items as required from the corporate Production Manager and meets with him monthly for a complete LEM Program review.

- The LEM Plant Representatives report to the LEM Shop Project Manager at a weekly meeting in Plant 25. All manufacturing program aspects, including priority are reviewed at this meeting.
- The LEM Plant Representatives are responsible for maintaining priority control for the tasks being performed within his plant.

The reputation for producing military and commercial aircraft of consistently high quality is evidence of the manufacturing skills available at Grumman. The effectiveness of retraining flexible and versatile personnel for space manufacturing is illustrated by the workmanship, cleanliness, and accuracy standards being maintained for the current NASA-OAO Spacecraft Program. However, these space skills must be expanded to meet the requirements of the LEM Program, and a training program has been established for this purpose.

All LEM training is directed by Mr. T. Moorman, LEM Support Manager, thus LEM manufacturing training requirements are directed to his office. Present plans are for all LEM system and subsystem instruction to be provided by the Grumman Service School, under the supervision of Mr. D. Wolf. The Service School is a group within the Service and Product Support Department.

All non-system LEM manufacturing training requirements are provided by Manufacturing Training under the direction of Mr. B. L. Brown, Manufacturing Training Manager, and his appointed LEM Coordinator, Mr. G. Ballard. This department is responsible for the development of additional skills and refinements of others. Some of the skill courses currently being presented are:

- Soldering School
- Maintenance and Servicing of High Vacuum Equipment
- Vibration Theory
- Vibration Parameters and Relationships





- Optics Technician Training
- Basic Electronics
- Rocket Engine Technician Training Program, which includes operation and maintenance of engine system components; cleaning and purging of components and engine systems; propellant handling and safety precautions; use of ground service equipment; altitude simulation, and instrumentation.

Specific training will be included at Grumman and at subcontractor sites for subsystems such as Ascent and Descent Propulsion, Reaction Control, Electrical Power, Environmental Control, Communication and other electronic subsystem components.

Grumman procedures for implementing and managing the LEM manufacturing program are as follows:


- The Manufacturing Manager and his three staff members form a team which is an integral part of the "single product organization".
- Key section personnel are assigned to supervise and coordinate the design and fabrication activities.
- Skilled engineers and technicians within sections and groups of the corporate organization are responsible for performance of program tasks.

#### 1.3 MAKE OR BUY SUMMARY

At Grumman, LEM "make or buy" decisions and source selections are determined by the LEM and corporate management committees.

The present status of the "make or buy" plans for LEM subsystems are shown in Figures 1-5 and 1-6. This summary is solely intended as a reference for familiarization with the Grumman subsystem manufacturing tasks which are described in Section 4.






C. I	Primary	Source	
Subsystem	Grumman	Subcontractor	Grumman Manufacturing Tasks
Structural/Mechanical Subsystems	X		All Fabrication & Assembly
Propulsion Subsystem		Bell Aero- systems	Fabrication & Assembly of Fuel Tanks, O <sub>2</sub> Tanks & Lines. System Integration & Test.
Reaction Control Subsystem Propulsion & Thrust Chambers Propellant Tanks		Marquardt Bell Aero-	Fabrication of Lines, System Integration & Test.
Environmental Control Subsystem		systems. Hamilton– Standard.	Fabrication of Lines. System Integration & Test.
Crew Provisions & Displays Subsystems	х		Fabrication & Assembly of Seats & Restraints; Lighting; Panels & Consoles. Installation of Dis- plays
Navigation & Guidance Subsystem Inertial Measurement Unit Rendezvous & Landing Radar		GFE RCA	Subsystem Integration, Installation, Alignment & Systems Test.
Stabilization & Control Subsystem Attitude & Translation Control Descent Engine Control Guidance Coupler In-Flight Monitor Gimbal Drive Actuator; Rate	}	RCA X <sup>*</sup>	Fabrication, Integration & Test Network Control Panels For Attitude Reference/Control Coupling Electronics.
Gyro; Attitude Reference; Computer Electrical Power Subsystem Fuel Cell Auxiliary Batteries; Cryogenic	}	Pratt & Whitney X*	Fabrication of Cryogenic Reactant Lines. Integration & Test
Storage & Supply; Battery Charger Communications Subsytem	)	RCA	VHF-LEM/CM Antenna, Wiring, Installation & Test.
Instrumentation Subsystem Pulse Code ModTiming Equip. Data Storage Equipment In-Flight Test System		Radiation Leach RCA	Installation & Test
Final Assembly	X		All Assembly, Installation, Alignment & Test.
* Subcontr	actor(s) To Be	Announced At A	Later Date.

1 - 15

Figure 1-5. Make or Buy Summary-Ascent Stage.



Grumman	a l	Grumman Manufacturing Tasks
	Subcontractor	
X		All Fabrication, Assembly & Test
X		All Fabrication, Assembly & Test
	Rocketdyne & STL (Parallel Engine Devel – opment Pro– gram)	Fabrication of Lines. System Integration & Test.
	X*	
	Hamilton- Standard	Fabrication of ECS Lines. Syste Integration & Test.
X		Assembly, Installations, & Test.
	.*	
		* Subcontractor To Be Announce At A Later Date
	X	X Rocketdyne & STL (Parallel Engine Devel - opment Pro- gram) X* Hamilton- Standard

1 - 16

Complete "make or buy" plans are described in the individual Subsystem Procurement Plans. The preliminary Ground Support Equipment Planning and Requirements List No. LLI-400-1 Revision A shows the GSE items which are tentatively planned for Grumman use.

Consistent with the Grumman concept of good business management in the areas of manufacturing planning and long-range programing, further LEM "make or buy" decisions will be made in accordance with the following basic corporate policy:

- Aerospace structural assemblies are "make" items. Some of these items may be purchased from vendor sources when such action is deemed necessary to normalize the manufacturing workload.
- Grumman does not generally compete in electronic design and manufacture, although integration considerations have occasionally made it necessary for Grumman to fabricate components to its own specifications.
- Mechanical assemblies such as valves and cylinders are "buy" items. On occasion, limited quantities may be produced on-site, but follow-on quantities are purchased.
- Machined parts are generally "buy" items. All requirements in excess of the quantities which can be produced on company-held equipment are purchased from outside sources, most of whom are "small business" concerns.

Fully recognizing the responsibility for subcontractor performance, Grumman will monitor and control subcontractor tooling and manufacturing activities using the procedures described in Section 3.3.4.

1 - 17



Section 2

SECTION 2 - Manufacturing Facilities

# SECTION 2 MANUFACTURING FACILITIES

# 2.1 FACILITY UTILIZATION AND MANUFACTURING FLOW

Present facility planning for the LEM Program indicates that virtually all Grumman manufacturing tasks, outlined in Section 1.3, will be performed within the Bethpage, New York, facilities. The plants selected for LEM manufacturing are located within a 1-mile radius; thus allowing for an efficient flow of parts, components, and subassemblies to the centralized assembly, installation and test facility.

Table 2-1 summarizes the total manufacturing areas allocated for exclusive LEM utilization, and also shows the equivalent LEM areas programmed within commonly utilized departments. A facility availability schedule is shown in Table 2-2.

Grumman Plant Number	Exclusive LEM Area Allocations (Square Feet)	LEM Area Assigned Within Commonly Utilized Departments (Square Feet)
5	62,800	9100
3	12,100	19,200
2	8000	13,800
All Plants Total	82,900	42,100



#### LEM Area Allocation Summary

2 - 1

OPERATION OR	1963	1964	1965	1966	1967	1968	
FUNCTION	J F M A M J J A S O N D 1 2 3 4 5 6 7 8 9 1011 12	J F M A M J J A S O N D . 1 2 3 4 5 6 7 8 9 10 11 12	F M A M J J A S O N I 2 3 4 5 6 7 8 9 10 11	D J F M A M J J A S O N I 2 I 2 3 4 5 6 7 8 9 10 11	J F M A M J J A S O N D J           2 1 2 3 4 5 6 7 8 9 10 11 12 1	FMAMJJAS0	
MOCK-UP FABRICATION							
M-3							
M-5 DISPLAY MOCK-UP							
SLOSH TESTS	<i></i>				SCHEDULED OPERATIONS		
PROPULSION PREPA- RATION DEVELOPMENT	22 Marca				* DEVELOPMENT * * QUALIFICATION		
PROPULSION PREPARA- TION MANUFACTURING							
L E M HYDROSTATIC TEST – LTA-3				**			
WELDING							
MIT G.&N. FIELD SUPPORT FACILITY							
E C S CLEAN ROOM INSTALLATION AREA		3//////3					
ASCENT FABRICATION LTA'S & LEM'S		<i></i>					
DESCENT FABRICATION LTA'S & LEM'S		<i></i>					
R C S CLEAN ROOM INSTALLATION AREA							
GSE ELECTRONIC BENCH TEST							
GSE BENCH MAINTE- NANCE EQUIPMENT							
PACE - MANUFACTUR- ING DEVELOPMENT		<b>E</b> 2010/10/10/10/10/10/10/10/10/10/10/10/10/					
EPS CLEAN ROOM NSTALLATION AREA		<i></i>					
LTA-I							
CENTRALIZED ASSEM NSTALLATION & TEST							
	2 3 4 5 6 7 8 9 10 11 12 1	2 3 4 5 6 7 8 9 10 11 12 1	2 3 4 5 6 7 8 9 0 11 2	J F M A M J J A S O N D 1 2 3 4 5 6 7 8 9 10 11 12	JFMAMJJASONDJ 123456789011121	M A M J J A S O N 2 3 4 5 6 7 8 9 10 11	
Γ	1963	1964	1965	1966	1967	1968	


Gumman L E M

Grumman will provide liaison space for LEM Program subcontractors at the Bethpage facility. It is planned that rework on vendor supplied components, other than bench maintenance operations, will be performed at the vendors' manufacturing facility.

As shown in Figure 2-1, Plant 5 has been delegated the responsibility for all operations beginning with assembly and continuing through shipment of the LEM. In addition, the Plant 5 final assembly area will be utilized for manufacturing modification and rework operations. This facility, which also houses the Grumman corporate offices and other NASA programs (e.g. the OAO Spacecraft and the Echo A-12 Satellite Canister Assemblies), was selected for the following reasons:

- The Grumman class II clean room which will be used for installation and test of the Environmental Control, Reaction Control, and Electrical Power Subsystems, is located within Plant 5.
- Adequate area, directly adjacent to the clean room, will be available for modification into a better-than-standard shop environment. This area is required for all other subsystem installations, interwiring, Ascent/Descent Stage mating, final installations, optical alignment of critically positioned subsystem components, and complete LEM test programs.
- Plant 5 houses the laboratories to be used for LEM static, vibration and environmental tests.
- The close proximity of Plant 5 to the Plant 25 Engineering Center, which contains the LEM Engineering and Management offices, will allow for the shortest possible lines-of-communication between engineering, manufacturing, and test personnel. This proximity will result in close coordination for producibility and will contribute to the effective control of all program phases.

Other Grumman plants shown in Figure 2-1 will manufacture the Structural/Mechanical Subsystem, other detail parts and subassemblies, and bench test vendor-supplied electronic



#### LEGEND

## DESCRIPTION OF LEM ACTIVITIES

## Centralized LEM Assembly, Installation and Test

Assembly and integration of all systems requiring a clean room environment; final assembly, integration, and test of all electrical, fluid, and structural/mechanical subsystems; preparation and shipping of complete LEM to appropriate site; also fabrication of electrical assemblies and some machined parts.

#### LEM Structural/ Mechanical Manufacturing

Machining operations, fabrication of honeycomb and welded assemblies, windshield fabrication, chem-milling, fabrication of tanks, and assembly of LEM ascent structural/mechanical subsystems.

## LEM Structural/Mechanical Assembly and Detail Part and Minor Subassembly Manufacture

Fabrication of sheet metal detail parts, skins, tubular assemblies, controls, landing gear components, crew provisions, and assembly of LEM descent structural/mechanical

#### Electronic Bench Test and Bench Maintenance

Bench test and maintenance of subcontractor supplied elec-

Receipt of Vendor Subsystem Components and Raw Materials

Cold Flow Testing of Propulsion and Reaction Control Systems

Figure 2-1. Basic LEM Manufacturing Flow Through Bethpage Facility



subsystem components. Sections 2.1.1 through 2.1.5 describe present plans for manufacturing facility utilization. Tool and GSE/STE fabrication facilities are described in Sections 2.1.6 and 2.1.7.

#### 2.1.1 Plant 5 - Centralized LEM Assembly, Installation, and Test


Figure 2-2 shows exclusive LEM utilization of 57,200 square feet of existing Plant 5 area and 5600 square feet for the Cold Flow Test Facility which is under construction. The existing area is subdivided into 5000 square feet of clean room area for the RCS, ECS, and EPS requirements, and 52,200 square feet for other assembly, installation, and test operations. Specific areas within the assembly and test areas are also shown in Figure 2-2.

Preliminary data from floor stability tests conducted by MIT indicates that the 4700 square foot area proposed for MIT test and bench maintenance of LEM Navigation and Guidance Subsystem is acceptable, and a firm decision is expected in December 1963. MIT has verbally stated that floor drift was negligible and that isolation blocks will not be required for their equipment.

Areas within the clean room are shown in Figure 2-3, and photographs of the Grumman clean room are shown in Figures 2-4 and 2-5.

In addition to the exclusive LEM areas, some Plant 5 shop departments which manufacture details and electrical and other subassemblies for all Grumman programs will also be utilized for LEM manufacturing. The machine shop will fabricate some of the machined parts for the Structural/Mechanical Subsystem.

An analysis has been made of the utilization of the final assembly, installation, and acceptance test area to verify its adequacy in the event of a lengthened installation and checkout cycle. In this analysis the cycle was increased from 4 to 10 months resulting in peak facility loadings at the end of 1964 and in the second quarter of 1965. It was concluded that there were sufficient stations available to accommodate the modules during each of these peaks.



#### LEGEND

I AREA DESCRIPTION	SQUARE FEET
urea	3300
removal of trapped particles	1700
nt location for subsystem test aft	ter 1000
ut of fixture area. Ascent/ nd alignment check; fastening crew provisions, bracketry and ary wiring and tankage installation	7000 n;
stem test in adjacent cold flow	3000
n test of the following subsystems: tion and guidance, stabilization an rumentation. Alignment and func- subsystem components	d
reen room and area for communic	a- 1200
checkout and location of PACE	1100
	1500
	1200
sture and out of fixture area	1100
t for pressure test	1200
g of baffle systems developed for	500

AREA	EXCLUSIVE LEM AREA DESCRIPTION	SQUARE FEET
(16)	M-3 mockup location	2100
17	LTA-1 location	1200
18	PACE equipment location. First floor - 6600 Sq Ft Mezzanine - 5400 Sq Ft	12,000
(19)	Cleaning and packing of parts, bracketry, lines, & tankage to be in stalled in the clean room and final assembly areas	
20	Internal Environment Simulator ECS system components developme and evaluation	ent 1600
(21)	MIT - Navigation & Guidance Field Support Area - Test and bench maintenance	4700
22	Stock area for vendor supplied subsystem components	2500
23	Office area, supervisor, QC inspection area	1600
24	Cold flow test of propulsion system and RCS	5600
25	Clean Room Area - RCS, ECS, and EPS	5000
	Total Exclusive LEM Area	62,800


AREA	AREA DESCRIPTION (COMMON UTILIZATION)	EXISTING AREA	% LEM	LEM AREA
26	Shipping & Receiving	2810	40	1100
27	Machine Shop	16,075	30	4800
28	Avionics (Electronic Fabrication)	4000	80	3200

Figure 2-2. Plant 5 LEM Assembly, Installation, & Test

Gumman L E M

1400

2000







Figure 2-4. Clean Room- RCS, ECS and EPS Installation and Testing



2 - 8



Ultrasonic Cleaning Facility for Cleaning Detail Parts



Inspection Area for Monitoring Cleanliness of Area and Detail Parts Inspection

Figure 2-5. Clean Room - Inspection & Cleaning Facilities



The analysis was made primarily to assure adequate facilities. It is planned, however, to satisfy modifications and contingencies by use of an extended and/or second shift as described in Section 3.1.3.

#### 2.1.2 Plant 3 – Ascent Stage Structural/Mechanical Manufacturing

This facility has been selected for ascent stage structural fabrication since it is specially equipped with a complete range of equipment and facilities for: manual or automatic fusion welding, resistance welding, chemical milling, spin forming, honeycomb, and machining.

As shown in Figure 2-6, approximately 12,100 square feet of assembly area will be allocated for the manufacture of the Ascent Stage Structural/Mechanical Subsystem. All major ascent stage subassembly, assembly, and welding fixtures, described in Section 4, will be located in this area. Note the adjacent location of existing fusion and resistance welding departments. This arrangement was specifically established to assure a smooth manufacturing flow between all subassembly and major assembly operations of mechanical fastening, automatic fusion welding, and resistance welding.

Plant 3 will also produce the fuel and oxidizer tanks required to the Ascent Propulsion Subsystem. Special equipment for flow forming, circumferential fusion welding, tank-half machining, heat treating, and age hardening are available for the tank program.


All chemical milling operations for structural weight reduction will be performed in Plant 3.


LEM details such as bonded honeycomb shelves will be fabricated in a specialized shop area which is fully equipped for parts preparation and autoclave or platen press bonding techniques.

Plant 3 major manufacturing equipment and facilities scheduled for utilization throughout the LEM Program are shown in Figures 2–7 through 2–12.

Incoming Raw Material, Subcontractor Supplied Components, Electrical Assemblies and Detail Parts from Warehouse and Other Grumman Plants

> LEM Ascent Structural/Mechanical Subsystem to Plant 5





AREA AREA

- (1)Exclusive LI Structural/M system
  - Fusion Weldi
  - Resistance W
  - Machining
- (4)(5)Inspection

(2)

3

8

9

(12)

- (6)
  - Honeycomb
- $\overline{7}$ Chemical Mil
  - Forming
  - Shear and Ro
  - Heat Treat
- (10)(11)Spin Forming
  - Shipping and

Exclusive LEM Area-12,000 Sq Ft for Ascent Structural/Mechanical Subsystem Manufacture

Existing Shop Departments - Common Utilization For LEM & Other Programs

LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963

North


2 - 11

### LEGEND


DESCRIPTION	EXISTING AREA	% LEM	LEM AREA
EM Area for Ascent Mechanical Sub-	12,100	100	12,100
ling	12,000	8	1000
Welding	6900	8	600
	75,700	3	2300
	9100	20	1800
	49,250	8	4000
illing	9100	6	500
	21,900	10	2000
out	11,800	6	700
	5600	12	700
g .	5900	75	4400
Receiving	11,900	10	1200

Figure 2-6. Plant 3-LEM Ascent Stage Structural/Mechanical Manufacturing





14-Ft Vertical Lathe for Machining LEM Ring Details and Subassemblies




62-In. Vertical Turret Lathe for Machining Smaller LEM Rings and Spherical Parts

Figure 2-7. Plant 3 - Vertical Lathe Equipment






Planer Milling Machine for Descent Structure Main Beam Components




Hydrotel - Tracer Milling Machine for LEM Contoured & Pocketed Detail Parts

Figure 2-8. Plant 3- Milling Equipment




BOKO Flow-Forming Machine for Forming and Machining of Propulsion Tank Details




Autoclave for Honeycomb Bonding of LEM Equipment Shelves

Figure 2-9. Plant 3 - Forming and Bonding Equipment





Boom Type Torch Manipulator-Automatic Fusion Welding for Joining Major LEM Subassemblies




Resistance Seam Welder for Joining Secondary Subassemblies

Figure 2-10. Plant 3 - Resistance and Automatic Fusion Welding Equipment

LPL-850-1 "A" 14 May 1963 Revised 14 Oct. 1963




Combination Longitudinal & Circumferential Welder for Combined Automatic Welding Operations - LEM Docking Tunnels



Automatic Longitudinal Fusion Welder for Welding of Large Ascent Stage Subassemblies

Figure 2-ll. Plant 3- Automatic Welding Equipment





Planned for Utilization Throughout the LEM Program for Reduction of Structural Weight.

Figure 2-12. Plant 3- Chemical Milling Facility



# 2.1.3 <u>Plant 2 – Descent Stage Structural/Mechanical Assembly and Manufacture of</u> Detail Parts and Minor Subassemblies.

As shown in Figure 2–13, Plant 2 has been selected for the manufacture of LEM detail parts and for assembly of the descent stage structure, which consists primarily of basic sheet metal construction. Since this plant is presently producing the majority of the sheet metal parts for all Grumman programs, fabrication of LEM detail parts in this plant will result in continued manufacturing efficiency. These consolidated facilities are fully equipped with the most modern machinery ranging from Hufford stretch wrap forming equipment to conventional drill presses.

The assembly of the descent stage in Plant 2 is also advantageous by virtue of available shop skills and facilities presently being utilized for the fabrication of similar mechanically fastened assemblies.

Tubular line assemblies for the Propulsion, Reaction Control, Environmental Control, and Electrical Power Subsystems will be fabricated using tube bending and induction brazing equipment housed in Plant 2.


Welding equipment available in various capacity ranges will be used during the manufacture of Lunar Landing Gear subassemblies.

Bench assembly areas will produce the mechanically fastened or welded secondary structural subassemblies for both the ascent and descent stages.

Major equipment located within Plant 2 are shown in Figures 2-14 and 2-15.

#### 2.1.4 Plant 12 – Plastic Parts

Plastic parts, such as the LEM/CM VHF antenna components and other details, which will be located within the crew and equipment compartment subassemblies will be fabricated in Plant 12. This facility is fully equipped to satisfy all tooling process, fabrication,



LPL-850-1 "A" 14 May 1963 Revised 14 Oct. 1963


Exclusive LEM Area - 8000 Sq Ft for Descent Structural/Mechanical

Existing Shop Departments - Common Utilization for LEM & Other Programs


ESCRIPTION	EXISTING AREA	% LEM	LEM AREA
l Tool Storage	7630	13	1000
at	11,200	12	1300
and Receiving	14,000	5	700

Figure 2-13. Plant 2- LEM Descent Stage Structural/ Mechanical Assembly & Manufacture of Detail Parts and Minor Subassemblies





Stretch Wrap Forming Machine for LEM Ascent Stage Skins



Direct Acting Hydraulic Press. Also Shows a Partial View of the Consolidated Detail Parts Manufacturing Facility.


Figure 2-14. Plant 2- Forming Equipment & Consolidated Detail Parts Facility

LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963





Rubber Forming Press for LEM Detail Parts



Age-Hardening Ovens for Aluminum LEM Details

Figure 2-15. Plant 2- Forming and Age-Hardening Facilities



inspection, and test requirements for the development of aerospace plastic components. The Plant 12 facility is shown in Figure 2-16.

#### 2.1.5 Plant 4 - Electronic Bench Test and Bench Maintenance

Plant 4 will be utilized for electronic bench test and maintenance of vendor supplied electronic subsystem components. This plant is presently performing electronic testing, repair, modification, and updating of Grumman electronic instrumentation and equipment for other programs.


#### 2.1.6 Tool Manufacturing Facilities

The Grumman tool manufacturing facilities represent approximately 126,000 square feet of plant area. The tool shop areas and all specialized production and maintenance shops will be fully utilized to insure on-time delivery of all tooling requirements for the LEM Program. The facilities are arranged according to either the degree of specialization or the needs of individual plants to provide the necessary close support for the production areas.

The Jig and Fixture Shops, shown in Figure 2–17, constitute the largest of the tool manufacturing facilities. These shops occupy approximately 36 percent of the total area. Tools varying from two-story assembly fixtures to small intricate drill jigs are produced. Set-up and assembly of jigs and fixtures comprise the bulk of the effort. Details such as machined parts and some weldments are supplied by supporting shops. Precision jig boring and grinding facilities and extensive use of optical tooling techniques are utilized to provide the accurate production tooling required for rapid assembly procedures.

The Template Shop, shown in Figure 2–18, produces router, trim, and other similar templates that are developed from loftings. These templates are used to facilitate the fabrication of sheet metal detail parts. The Template Shop work involves highly skilled manual labor, thus minimizing the equipment and facility requirements. Approximately

Grumman. L E M



Fiberglass Facility



Electric Oven for Curing Vacuum Bagged Fiberglass Reinforced Parts

Figure 2-16. Plant 12 - Fiberglass Manufacturing Facilities

LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963








Tooling Machine Shop Lathe Area

Tool Jig Boring Area



Rockford Openside Planer for Heavy Machining



Radial Arm Drill Press Area

Figure 2-17. Jig and Fixture Manufacturing Facilities





Template Shop for After-Form Detail Tools



Plaster Shop for Plaster Tooling Mock-Ups & Models

Figure 2-18. Template and Tooling Mockup Facilities



16 percent of the total tool manufacturing shop area is allotted to template manufacture. The majority of this area is located in Plant 2 where most sheet metal parts are fabricated.

Patterns and three-dimensional form blocks of wood, masonite, or aluminum are fabricated in the Pattern Shops for use in the manufacture of sheet metal parts. Planers, jointers, circular saws, sanders, and other conventional wood working machinery are used in the manufacture of these tools. Cam-controlled routers for high-speed profiling and other specialized production-type equipment are used to attain a high degree of efficiency. These shops, occupying about 10 percent of the total tool shop area, are also primarily located in Plant 2.

The Plaster Shop, shown in Figure 2–18, provides all plaster tooling mock-ups, models, and a major portion of the compound curvature skin tooling for all plants. These mock-ups are constructed using carefully aligned templates which are filled in and fixed with plaster compounds. Dies and skin tooling are fabricated by taking plaster or plastic casts from these mock-ups. All tooling mock-ups and models for compound curved LEM skins will be produced in this facility. The Plaster Shop is located entirely in Plant 11 and represents approximately 20 percent of the tool manufacturing facilities.

The Die Shop, located in Plant 2, occupies approximately 6 percent of the total Tool Shop area. Close tolerance steel dies for production blanking, forming, and rolling operations are fabricated in this shop utilizing precision grinding equipment and support from the Tooling Machine Shops.

The Tooling Machine Shops provide support for all of the Tool Shops. Machine Shop equipment including milling machines, lathes, shapers, and grinders are available for any metal cutting operations required. Approximately 12 percent of the Tool Shop area is utilized for these shops.

In addition to the tooling facilities, the complete manufacturing capability of the company is available for tool fabrication on an "as required" basis. This includes heat treat, paint and

other finishing operations, and specialized production equipment which could not be justified for full time Tool Shop usage.

Complete coordination of all cognizant personnel and constant monitoring of shop loading and control procedures is the key to efficient use of the Tool Shop capabilities described herein.

#### 2.1.7 GSE/STE Manufacturing Facilities

LEM Ground Support Equipment, including Handling and Transportation GSE, Electronic GSE/STE, Fluid Systems Support GSE/STE, and Training Equipment will be manufactured in existing shop facilities currently producing similar components for other aerospace programs. The manufacturing tasks will be routed to the Tool, Test Equipment, or Avionic Shops based on the specialized skills, equipment, or facilities required for fabrication.

The GSE manufacturing facility, within the Tool Shop organization will fabricate the Handling and Transportation Equipment, and also some cabinets, chassis, and work benches for other equipment. This shop, shown in Figure 2–19, is equipped for all heavy fabrication utilizing standard metal cutting, forming, and welding equipment.

The Test Equipment Shops and Avionic Shop Departments are responsible for Electrical/ Electronic GSE/STE used during manufacturing and off-site tests. In addition, the Test Equipment Shops have the primary responsibility for all Fluid Systems Support GSE/STE. These shops, shown in Figures 2-19 and 2-20, are equipped to handle the fabrication and functional test of hydraulic, pneumatic, and environmental ground support equipment, in addition to fabrication, calibrating, and maintaining all types of test equipment for electronic or fluid subsystems.

A section of the Avionic Production Shop also participates in electronic GSE/STE manufacture. This area is equipped to manufacture circuit boards, harnesses, and other electronic subassemblies, and to integrate these components into panels, consoles, and chassis manufactured by supporting shops. This shop is also responsible for calibration and functional checkout of test units.

Gumman L EM



Fabrication Shop for Handling & Transportation GSE



Test Equipment Shop for Fluid Systems & Electronic GSE/STE

Figure 2-19. GSE/STE Manufacturing Facilities





Test Equipment Shop-Mechanical Instrument Calibration Area



Test Equipment Shop-Electronic GSE/STE Calibration Area

Figure 2-20. Test Equipment Shop



SECTION 3 - Scheduling, Planning, Methods, and Controls

#### SECTION 3

#### SCHEDULING, PLANNING, METHODS, AND CONTROLS

#### 3.1 SCHEDULING

On-schedule performance is a major consideration for the LEM Program, and our past record is a matter of particular significance. A detailed accounting of Grumman schedule performance is shown in the original LEM Proposal. All major milestones regarding development, customer evaluation, and manufacturing for the current A-6A and E-2A aircraft programs have been, and continue to be met.


At Grumman, scheduling and planning operations are closely interrelated since coordination is mandatory – from the initial planning stage through completion of the manufacturing task. However, for clarity of presentation, planning and scheduling for the LEM Program are described in separate report sections.


The LEM Master Program Schedule and individual subsystem schedules form the basis for development of detailed schedules for tooling, GSE, equipment, and manufacturing. Past contributions for manufacturing and installation lead-time requirements are presently re-flected in the Master Schedule.

Manufacturing and tool scheduling systems are described in Sections 3.1.1 and 3.1.2. LEM Program manufacturing schedules are shown in Section 3.1.3.

#### 3.1.1 Manufacturing Scheduling

As shown in Figure 3-1, the lead-time requirements for tooling, equipment, and manufacturing are established by the LEM Manufacturing Management Staff. During the







development of manufacturing lead-times, the LEM Shop Project Manager uses manufacturing flow and tool/equipment lead-time data provided by the LEM Project Manufacturing Engineer and the Test Equipment and Process Project Engineer. This coordination results in agreement and assurance of compatible program sequences and approaches.

Lead time information is forwarded to the Manufacturing Projects Planning Section where the basic manufacturing schedules are developed. These schedules, as shown in Section 3.1.3, include major engineering drawing release requirements, due-dates for all primary tooling and manufacturing activities necessary to satisfy the master program charts, receipt of subcontractor supplied components, and final assembly installation and test operations.

These schedules are forwarded to the Manufacturing Scheduling Section where detailed "family tree" priority groups are established for engineering drawing releases, shop work orders, and procured items. Basic manufacturing schedules are used by this group to develop the detailed schedule requirements for component manufacturing. These procedures are repeated for each different configuration module. Identical units will be scheduled completely within the Manufacturing Scheduling Section.

Recognizing the importance of effective manufacturing schedules, review and approval by the LEM Manufacturing Manager, LEM Shop Project Manager, and the Grumman Production Manager is mandatory. The signatures of the Grumman Director of Manufacturing and the LEM Manufacturing Manager constitute final approval of all schedules. Copies of all schedules are forwarded to the Manufacturing Planning Group for release of route cards to the shop departments. The Material Processing Group also receives copies of the schedules for preparation of contract item and raw material requirements which are forwarded to the Purchasing Department.

#### 3.1.2 Tool Scheduling

Major tooling schedules are integrated within the aforementioned basic manufacturing schedules, and are programmed to satisfy the fabrication lead time requirements in



3-3

accordance with the selected subassembly breakdown. The initial development and periodic up-dating of these basic manufacturing schedules (including tooling) are the responsibility of the LEM Project Manufacturing Engineer. As shown in Figure 3-2, he is assisted by a LEM planner who represents the Project Planning and Controls Section. These schedules are forwarded to the Tool Fabrication Section where basic shop-loading data is developed. The shop-loading data and schedules are forwarded to the Manufacturing Engineering Scheduling Group where detailed tool due-date schedules are generated within the structure of the LEM Master Schedule and basic manufacturing schedules. The Scheduling Group develops these tool due-dates by closely considering the following factors:

- Conformance with PERT/Time Networks.
- Availability of engineering information.
- Allowance for manufacturing lead-times for determining individual tool completion dates.
- For design-type tools, allowance for tool fabrication lead-times for determining individual tool design completion dates.
- Tool design progress reports.
- Status of Tool Shop loading for balancing and adjustment of work effort.
- Schedule compatibility to facilitate use of masters during tool fabrication.

The procedures for schedule implementation, recording, and status reporting are also shown in Figure 3-2. The Methods Engineering Section (Tool Planning) determines the tooling requirements and prepares "Methods Engineering Record Sheets, ME-269" for both design and non-design type tools. This procedure is described in Section 3.2.2. The Record Sheets, together with tool fabrication estimates, tool drawings, and destinations are forwarded to the scheduling groups for review of due-dates and status of shop loading. When acceptable due-dates and priorities have been established, the ME-269 Record Sheet

Grumman L E M




Figure 3-2. Tool Scheduling Flow

is processed and forwarded to the IBM Key Punch Section where IBM cards are made. The cards are forwarded to the IBM Open File and to the Shop Loading Section where they become the sole authorization order for initiation of tool shop effort. Completed tools are inspected and subsequently delivered to the manufacturing departments. Manufacturing Engineering retains the responsibility for tool improvements, rework, maintenance, repair, and replacement, but may not perform these functions until the tool is released by the Production Department. This insures the completion of all required parts which are fabricated in the tool before rework is initiated. This requirement is necessary since the revision may be for a particular or subsequent module and not applicable to the one presently being assembled.

The Manufacturing Engineering Scheduling Group is responsible for the monitoring of/and initiating authorization for all tool movements into and out of Grumman in coordination with Purchasing, Production, Tool Control, and Subcontracts. All tool movement and storage within Grumman is controlled by the Tool Control Section. This section is under the jurisdiction of the Production Department.

Recording of the tool program and status reporting is accomplished using an IBM key punch card system. This system is used for maintaining cognizance of "completed and incomplete tools". Thus, tool program status can readily be reported to the LEM Project Manufacturing Engineer, Manufacturing Engineering Management, and PERT/Time representatives. Further, the IBM system satisfies the requirements of Tool Control Records, Accounting Department Records, and the Certified Tool File.

#### 3.1.3 LEM Manufacturing Program Schedules

Detailed tooling and manufacturing schedules are being developed using the LEM Phasing Charts, dated 15 September 1963, as shown in the Master Program Plan LPL-13-1.

Concentrated scheduling efforts are presently being applied to the early modules such as the TM-2 Thermal Model of the Descent Stage, M-5 Master Metal Mockup, the PD units, and LTA-1 through LTA-4.

3-6

The NASA Mock-up Review, held at Grumman on 16 through 18 September 1963, has resulted in design changes to the ascent stage face assembly. In addition, very recent design changes, based on the continuation of the design phase through 1 October 1963, have also affected the aft pressure dome, unpressurized equipment bay, and the mid-section tunnel area. Consequently, manufacturing tasks and operational sequences, which have already been defined, must be reviewed and revised in accordance with the latest configuration as shown in the Section 4 flow diagrams.

The manufacturing schedule for TM-2 (Thermal Model of Descent Stage without Landing Gear) is shown in Figure 3-3. This pictorial arrangement has been adopted as a standard format for all LEM manufacturing schedules (and is also being used for all other Grumman programs). The inclusion of the LEM subassembly breakdown sequences as a visual aid is a factor which has made this type of chart a universally accepted working tool by the Manufacturing Departments. These initial schedules establish the requirements for receipt of engineering design information, and are also used as the basis for detailed manufacturing planning and scheduling. As such, they are reviewed by the Director of Manufacturing and the LEM Manufacturing Manager, and are revised to indicate progress at 2 week intervals.


Figure 3-4 shows a summary schedule for TM-2, M-5, PD-1, PD-2, PD-4, and PD-5 descent stages. A similar summary of the ascent stages will be developed in accordance with the aforementioned review of the ascent changes.

A single-shift shop operation is planned for subsystem installations, as well as functional and factory checkout. An extended shift and a second shift will be added when necessary for modifications and contingencies. Experience in development programs indicates that the above concept is best suited for these tasks.

GSE usage and availability requirements will be used to develop manufacturing schedules for Handling and Transportation GSE, Fluid Systems and Electronic GSE/STE. All items shown on the approved "GSE Planning and Requirements List, LLI-400" will be subject to a detailed analysis for "make or buy" decisions, and schedules will be developed for items to

Grumman. L E M


## LEM TM-2




LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963

Figure 3-3. LEM TM-2 Descent Stage Subassembly Breakdown & Manufacturing Flow. Sheet 1 of 4

#### MANUFACTURING SCHEDULE





LPL-850-1 "A" 14 May 1963 Revised 14 Oct. 1963


Figure 3-3. LEM TM-2 Descent Stage Manufacturing Schedule Sheet 2 of 4

# MANUFACTURING SCHEDULE

LEM TM-2 DESCENT STAGE (CONTINUED)

	JAN FEB MAR APR MAY JUN	I963 E JULY AUG SEP OCT	
5. LTM-280-20503, 20504, 20505	JAN         FEB         MAR         APR         MAY         JUN           6         I3         20         27         3         IO         17         24         3I         7         I4         21         28         5         I2         19         26         2         9         I6         23		NOV DEC JAN FEB MAR 3 10 17 24 1 8 15 22 29 5 12 19 26 2 9 16 23 1 8 15 22 29 5
	DESIGN BULKHEAD ASSEMBLY DRILL JIG		
$\sim$	FABRICATE BUIKHEAD ASSEMBLY DRILL JIG		
$\leq 2 > 2$			
	FABRICATE DETAILS FOR BULKHEADS		
	FABRICATE BEIKHEAD SUBASSEMBLIES	0000	×C
UPPER BULKHEAD	FABRICATE BORRIEAD SUBASSEMBILES		
SUBASSEMBLIES			
6. LTM-280-20516		\$	
1996) Districtions Francisco Discontinue (1997)	DESIGN ENGINE MOUNT WELD FIXTURE		
	FABRICATE ENGINE MOUNT WELD FIXTURE		
	FABRICATE ENGINE MOUNT DETAILS	xxxxxx	
	FABRICATE ENGINE MOUNT		
ENGINE MOUNT			
	╂┼┼┼╊┝┼┼┠┼┼┼╋┼┼╎╂┾┿┿┼╋┼┼╴		<u>、┼┼┼┼╂┼┼┼╂┼┼┼╂</u> ┼┼┼╂┤
7. LTM-280-20025	FABRICATE MACHINED PARTS		
	PADITOATE PROTINED PARTS		0000
A			
INTERSTAGE ATTACH			
FITTINGS			
8. LTM-280-20500 FINAL STRUCTURAL			3
B. LIM-280-20500 FINAL STRUCTURAL ASSEMBLY	ASSEMBLE AS NOTED (USE ASSEMBLY FIXTURE		
	SHOWN IN STEP 4)		
A Real Real Real Real Real Real Real Real			
ASSEMBLY OF UPPER BULKHEADS,			
ENGINE MOUNT & INTERFACE			
ATTACH FITTINGS			
9. LTM-280-20507, 20519	FABRICATE FUEL & OXIDIZER TANKS (USE		
$\frown$	PREVIOUSLY PROGRAMMED LEM BOILERPLATE TOOLS)		
		3	
		₩ 1	
	DESIGN BONDING FIXTURE FOR TANK SKIRTS		
	FABRICATE BONDING FIXTURE	11111111111111111111111111111111111111	
	FABRICATE TANK SKIRTS	╶┼╶┼╌┼╌┼╌┼╌┼╶┼╶┼╶┼╼╴	
PROPULSION TANKS & SKIRTS	ASSEMBLE TANKS & SKIRTS		
10 LTN 280 2051 20512			
IO. LTM-280-20511, 20512, 20513, 20514	DESIGN FORMING TOOLS FOR SECONDARY TANKS (5)	3	
20010, 20014	FABRICATE FORMING TOOLS FOR SECONDARY TANKS (5)		
		92	
()			
()	FABRICATE SECONDARY TAIKS (ECS(1), EPS(2), HE(2))		
SECONDARY TANKS			
(2) HE, (1) H <sub>2</sub> , (1) O <sub>2</sub> , 8 (1) H <sub>2</sub> O		70 7 14 21 22 4 11 12 25 1 2 15 22 20 6 17 20 27	
	6         13         20         27         3         10         17         24         3         17         14         21         28         5         12         19         26         2         9         16         23           JAN         FEB         MAR         APR         MAY         JUNE	JOI 7         I4         ZI         Z8         4         II         I8         Z5         I         8         I5         Z2         29         6         I3         2027           E         JULY         AUG         SEP         OCT	NOV DEC JAN FEB MAR A
		1963	
PLASTER MOCK-UP FAB	SKIN DIE FAB	////// DESIGN (DESIGN TOOLS-ALL)	NOTED AS NOTED-PRODUCTION
		FAB (DESIGN TOOLS-ALL)	WHITE MASTER INFORMATION SHEET
LEGEND	SKIN FAB	SUBASSEMBLY-PRODUCTION	
		SUBASSEMBLY - PRODUCTION	C ) I. ENGRO, LATOUT REQU
COOC DETAIL TOOL FAB	WHITE MASTER LAMINATES-FAB WHITE MASTER-ENGINEERING	ASSEMBLY-PRODUCTION	I. ENGRG. LAYOUT REQD 2.COMPL. JIG INFO REQD 3.FINAL DETAIL INFO REQD

.



3 - 10

# MANUFACTURING SCHEDULE LEM TM-2 DESCENT STAGE (CONTINUED)

I. LTM-280-20506 LTM-280-20550	JAN         FEB         MAR         APR         MAY         JUNE         JULY         AUG         SEP         OCT         NOV           6         13         20         27         3         10         17         24         31         7         14         21         28         5         12         19         26         2         9         16         23         30         7         14         21         28         5         12         19         26         2         9         16         23         30         7         14         21         28         5         12         19         26         2         9         16         23         30         7         14         21         28         5         12         19         26         2         9         16         23         30         7         14         21         28         5         18         15         22         29         6         13         20         27         3         10         17	V	DEC	JAN	FEB MAR	
			15 EEES	5 12 13 20 2	5 10 25 1 0 15 22 25	
	FABRICATE DETAIL PARTS TOOLS FOR NOTED ITEMS	~~~~	****			
	FABRICATE DETAIL PARTS FOR NOTED ITEMS	xxxx	0000	000		
	DESIGN LOWER BUIKHEAD ASSEMBLY DRILL JIG					
LTM - 280-20510	FABRICATE LOWER BUIKHEAD ASSEMBLY DRILL JIG					
	FABRICATE LOWER BUIKHEADS					
	FABRICATE THERMAL SHIELDING		+++-			
10	FABRICATE END PANELS		=			
E LOWER BULKHEADS,	FABRICATE TANK SUPPORTS					
L SHIELDING, TANK , & END PANELS						
						-
20500 INSTALLATIONS			3			
	DESIGN HOLDING FIXTURE, SLING, SCAFFOLD & HANDLING DOLLY					
	FABRICATE HOLDING FIXTURE, SLING, SCAFFOLD & HANDLING DOLLY					
	FABRICATE DETAIL PARTS TOOLS FOR THERMAL SIMULATORS, SKINS, COVERS, ETC.	****	*****	0000		
8	FABRICATE LINES, ELECTRICAL HARNESSES, INSTRUMENTATION, TUBULAR LINES, THERMAL SIMULATORS, ETC.			0000000	o	
h	INSTALL TANK/SKIRT SUBASSEMBLIES; & LOWER BUIKHEADS		INST			
	INSTALL INSULATION, THERWAL SHIELDING, LINES, WIRING, INSTRUMENTATION, THERWAL SIMULATORS, SKIN HEATERS & UMBILICALS			INSTALLATIC	/N\$	
7 > 7 > 7	DESCENT STAGE CHECKOUT & CALIBRATION					
$ \times $						
$\sim$						
$\searrow$						
ANK/SKIRT SUB- , LOWER BULKHEAD,						
ELDING, INSULATION,						
ES, CABLES,						
IN HEATERS,						
ALS						
			15 0000	E 10 10 00 0	0.16.07.1.0.15.00.00	-
	6 13 2027 3 10 17 24 3 10 17 24 31 7 14 21 28 5 12 19 26 2 9 16 23 30 7 14 21 28 4 11 18 25 1 8 15 22 29 6 13 2027 3 10 17 3 1		15 22 29 DEC	5 12 19 26 2 JAN	9 16 23 1 8 15 22 29 FEB MAR	5
	I JAN   FEB   MAR   AFR   MAT   JUNE   JULI   AUG   JEF   UCI   NOV		520			<u> </u>
LASTER MOCK-UP FAB	SKIN DIE FAB	TED	AS NO	TED-PRODU	CTION	
MODEL	SKIN FAB	~	WHITE	MASTER INF	ORMATION SHEET	
S DETAIL TOOL FAB	WHITE MASTER LAMINATES - FAB SUBASSEMBLY - PRODUCTION	$\diamond$	I. ENGE	RG. LAYOUT	REQD	-
OOO DETAIL PARTS FAB	WHITE MASTER-ENGINEERING ASSEMBLY-PRODUCTION		3. FINA	L DETAIL IN	FO REQD	

3-11

		1964					3-11	
APR	MAY	JUNE	JULY	AUG	SEP	OCT	NOV DEC 3 15 2229 6 13 2027	
	(							
	j							
	6							
	*							
	45							
	1							
12 19 24	3 10 17 24 31	7 14 21 28 5 13	2 19 26 2 9	16 23 30 6	3 20 27 4	1 18 25 1 8	15 22 29 6 13 2027	
APR	MAY	JUNE 1964	JULY	AUG	SEP	OCT	NOV DEC	
$\bigcirc$	INDICATES R		E FOR I, 2,	0 7				
$\check{\bigcirc}$	INDICATES R DATE COINCI	EQD & RELE			HANGE	DATE	APPROVED	
	- % COMPLETI	ON		L	NC	9.17.63	3 Eralen	
				_9 Do	goont	Store	Monu	
гі	gure 3-						e Manu– et 4 of 4	
	facturing Schedule Sheet 4 of 4							

# MANUFACTURING SCHEDULE SUMMARY LEM TM-2; M-5; PD-4; PD-1; PD-5; & PD-2

Sec. Sec. Sec. Sec. Sec. Sec. Sec. Sec.						1963	1	1			TAGES ON	1				
TM-2 DESCENT	JAN FEB 6 13 20 27 3 10 17 24		APR ·		JUN 6 2 9 16 2		28 4 11 18 25							6 23 I	MAR 8 15 22	
(SEE DETAILED MANUFACTURING SCHEDULES)	TOOL DESIGN						- UNIXIXI	NIXINININ	INIXINI		IXIXIXIXI					
DESCRIPTION: HEAVY WEIGHT STRUCTURE TO SIMULATE LEM THERMAL RESPONSE. THERMAL MODELS OF SUBSYSTEM COMPONENTS. NO LANDING GEAR	DETAIL TOOL FABR	ICATION											0000			
TANKAGE DESCRIPTION: FUEL & OXIDIZER TANKS - USE LEM BOILERFLATE TOOLS. ALUMINUM SECONDARY TANKS - (2) HE; (1) H2; & H20), RCS TANKS TO BE VENDOR SUPPLIED	SUBASSEMBLY MANU: ASSEMBLY — INSTALLATIONS — CHECKOUT - CALIBI												=		r	
M-5 DESCENT															++-	
DESCRIPTION: METAL MOCKUP - HEAVYWEIGHT STRUC- TURE & LANDING GEAR "HARD" MOCKUPS OF EQUIPMENT & SUBSYSTEMS.	FABRICATE DUPLIC		EMBLY FI	IXTURE (A	₩2) —								V			
TANKAGE DESCRIPTION: (TO BE INCLUDED AT A SUBSEQUENT REVISION)	INSTALLATIONS -		utus —	1.1.1							*		=]			
				_						_				+++	++-	
PD-4 DESCENT																
DESCRIPTION: DESCENT STAGE IDENTICAL TO PD-1	FINAL ASSEMBLY (1	JSE AF#1)														
TANKAGE DESCRIPTION: (TO BE INCLIDED AT A SUBSEQUENT REVISION)	INSTALLATION & CI	ECKOUT											*			
PD-1 DESCENT DESCRIPTION: PROTOTYPE RIG NEED NOT BE FLIGHT WEIGHT BUT WILL REPRESENT FLIGHT DESIGN IN EVERY WAY POSSIBLE. PICK-UP POINTS, ENCINE SUPPORT POINTS & OVERALL SIZE WILL BE INTERFACE AREAS WITH ROCKET MANUPACTURERS.	FINAL ASSEMBLY (I													- *		
TANKAGE DESCRIPTION: ALL PROPULSION TANKS WILL CON- TAIN BAFFLES. OTHER INFORMATION TO FOLLOW.																
PD-5 DESCENT																
DESCRIPTION: STRUCTURE & TANKS IMPROVED TOWARD FINAL FLIGHT WEIGHT CONFIGURATION.	FINAL ASSEMBLY (1	JSE AF#1)														
TANKAGE DESCRIPTION: (TO BE INCLUDED AT A SUBSEQUENT REVISION)	INSTALLATION & C	ECKOUT														*
PD-2 DESCENT														+++		
DESCRIPTION: SAME AS PD-1 ABOVE	FINAL ASSEMBLY (1	jse af#2)														
	INSTALLATION & CH		14 01 00	E 10 10 22				9 15 2025		3 101701		5 10 10 0			9 15 00	29 5 10
	6 13 2027 3 10 17 24 JAN FEB		APR	MAY		E JULY 1963		8 15 22 29 SEP		NOV	DEC	JAN		EB	MAR	
PLASTER MOCK-UP FAB MODEL GEND		SKIN DIE FA SKIN FAB WHITE MAST	TER LAN		- FAB		DESIGN (DESI FAB (DESIGN SUBASSEMBL	TOOLS - AL	L) FION	$\sim$	WHITE	TED-PRO MASTER RG. LAYOL	INFORM	D QD	SHEET	( 4
OOOOO DETAIL PARTS FAB	×	<pre>WHITE MAST   INITIAL INS</pre>			_		ASSEMBLY-P ER BULKHEADS				3. FINA	L DETAIL	L INFO	REQD	ER LEI	M PROGR






Figure 3-4. Manufacturing Schedule Summary LEM TM-2, M-5, PD-4, PD-1, PD-5, & PD-2

be fabricated in-house. PERT networks being developed for all items of GSE will be used as a guide for generating GSE/STE manufacturing schedules.

3 - 13

#### 3.2 PLANNING


Conversion of engineering design information into LEM hardware and associated GSE/STE will be accomplished in accordance with the established planning procedures presently being applied to other Grumman aerospace manufacturing programs.

Planning operations for LEM, which include Manufacturing, tool and procurement planning are described in Sections 3.2.1 through 3.2.3. For clarity and convenience, GSE planning procedures are outlined in Section 7.

#### 3.2.1 Manufacturing Planning

A Manufacturing Planning Coordinator has been assigned to the LEM Program for implementation and control of the corporate manufacturing planning functions. He reports to the Grumman Production Planning Manager, and provides the LEM Shop Project Manager with program status information. He also serves as the central agent for distribution of engineering design data to all cognizant Grumman departments.

Effective manufacturing planning is accomplished through the utilization of the four primary functions: processing engineering information, multilith preparation of work orders and route cards, manufacturing planning releases, and expediting through shop departments. These functions are shown in Figure 3–5 and are described as follows:






Figure 3-5. Manufacturing Planning Flow

LEM

Manager

Manufacturing

ŧ

Reporting

LEM Shop

Project

Manager

Report Status

Representatives

LEM Shop

(All Plants)

Coordination



- LEM Processing personnel translate and convert engineering information into types of detail parts, assemblies, and installations required during the manufacturing program. This group also initiates shop authorization orders for all advanced, released, and changed design data. Constant liaison is maintained with all cognizant Grumman departments for a unified planning activity. As described in Section 3.3.8, key punched cards for configuration control, serialization, and traceability originate in this group. Thus, the processors, under the supervision of the LEM Manufacturing Planning Coordinator, are responsible for determining necessary action and for distribution of information through the manufacturing organization.
- Multilith personnel produce the shop work orders and route cards which were initiated by the processors. This group also issues the work orders to the delegated shop departments. Route cards are forwarded to the Manufacturing Planning Release Group, and master files are kept of all work orders. Sample work order and route cards are shown in Figure 3-6.
- Manufacturing Planning Release personnel evaluate all work orders and process these orders by establishing Kardex records which contain information such as part numbers, groupings, originating departments, and final part destination. Route cards issued to the shop departments state the applicable job charge number and indicate a given number of parts required. Part quantity releases are determined by periodic review of manufacturing program schedules. Kardex records are used to record part quantities ordered, date of issue, and total cumulative quantity. Original route cards are retained by Quality Control for filing.
- Expediting personnel maintain close coordination with the shop and parts control groups to provide constant monitoring of part availability requirements.

PART NUMBER LDW -280-10000-11 PART NAME BRACKET		LEM			LDW -280-10000-11			Blue	Blue		PART NUMBER LDW -280-1000 PART NAME				
				RELEASE	A	28010	JOB					BRACKE			
ASSEMBLY -3					Blu		Blue	DATE					ROUTE CARD		LDW-280
-:	)	_	20240- 001-001 group		QUANTITY		INT		LEFT		Accompanies Work				
			GROOT			MATERIAL		F	RIGHT _		Order And Shows	NOIL	PONENT NAME		
			PER PLANE	E	4	SIZE					Job No., Quantity And Release		erial 075-0-(clad		
СОМРО	NENT NAME Sta 11	4	DA	ATE ISS		5126					Alla Release	of P	roc 040 x 3		
MATERI	A1		4	-15-	DUE IN		OPERATI	NC					PT. OPERAT		
	7075 -0 (clad	)			STOCK	SQUARE	SHEAR		BLANK			Z 01	Flat De		
SIZE	Proc 040 x 3	x 10				MITRE	DRILL		PIERCE			LL_}	Tool Burr &		
	ROUTING		QUAN	TITY	INSPECTION	RIP	CHAMFER		FORM			201	Degre		
DEPT.	OPERATIONS	TOOLS	IN	оит	CO. CUST.	TRIM	ROUT	1	NIBBLE			NAMMUU 2 02	Versor		
201	Shear					BURR	SEPARATE		TUMBLE			2 05 205			
201	Flat Pattern Tool							1	DEGREA	SE		2 09	** / **		
201	Burr & Degrease											224	/ Heat T 270 Inspec		
	Verson Press					PART NUMBER		GROU		RELEASE	-	2 05	5 Straig		
205	Block Check Contour									RELEASE	WORK ORDER	2 09	Age H		
205	& Flanges					Α	28010	JOB			Authorizing Shop	270	Inspec		
209	Heat Treat to T4			$\wedge$	$\langle \Sigma \rangle$	PRESS	ROLL	1	TRIM		Effort 7	207			
224	Heat Treat Inspection		~	$\mathcal{D}/\mathcal{D}$	$\bigvee$ -	DRAW	JOGGLE		GANGPU	NCH		211	. Plant		
210	Inspection				·	BRAKE	STRETCH		POWER H	HAMMER					
205	Straighten	C	elen.										243 REC		
209	Age Harden					PART NUMBER		GROUP	P	RELEASE			LTA1		
270	Inspection					A	28010	JOB				S APP	NGE EFFECTIVE		
						HAMMER	HEAT TREAT					PA			
207	Alodine		_			STRAIGHTEN	DRILL								
211	Plant #10					CHECK	TRIM					DET			
						WELD						-			
DESTIN	ATION QUANTITY	DATE	RECEIVED									9-62 (PLSO)			
S-24	43 RECEIVED											CB3			
A	28010 RECEI	VED BY	CL	оск #								ŭ L			

MOL	DEL EM			LDW 280	-10000-1	GROUP	RELEASE				
	- 414		RELEASE				JOB	Blue			
+	JOB		Blue	DATE		QUANTIT					
	GROUP QUANTITY			INT		.EFT					
			QUANTITY	MATERIAL			,				
	PER PLANE 4		0175								
	1	DATE IS	SUED	SIZE							
4	1-15	-'63			0	PERATIO	N				
				SQUARE	SHE	AR	в	LANK			
				MITRE	DRIL	.L	Р	IERCE			
		NTITY	INSPECTIO		СНА	MFER	F	ORM			
-1	IN	OUT	co. cus	TRIM	ROU	т	N	IBBLE			
				BURR	SEP	RATE	т	JMBLE			
							D	EGREASE			
1											
+											
_								00000			
				PART NUMBER			GROUP	RELEASE			
							JOB	_			
-				-	1						
-	-1	2		PRESS	ROLI			RIM			
_ !,	2	$\mathbb{N}$		DRAW	JOGG			ANGPUNCH			
6	5)	$\mathcal{I}$		BRAKE	STRE	тсн	PC	OWER HAMMER			
/	5										
1	54										
54				PART NUMBER			GROUP	RELEASE			
							JOB				
+	-			HAMMER	HEA	TREAT					
-				STRAIGHTEN	DRIL						
				СНЕСК	TRIM						
				WELD							
+											
REC	EIVED	.		_							
£				_							
			PERM. #	_							
4											
		AUTH	ORIZATION	NC	PROC	ESSED BY	nola	DATE			
				NC			BYD	4-9-'63			
t	41		51	19 08	44 20	21	PROD QTY	UTHER QTY			
f											
-											

# Figure 3-6. Sample LEM Shop Work Order And Route Card



3.2.2 Tool Planning

In accordance with the manufacturing planning approach, a LEM Methods Engineering Coordinator has been assigned to supervise the corporate tool planning functions. He reports directly to the Supervisor of Grumman Methods Engineering and provides program status information to the LEM Project Manufacturing Engineer. Tool planning procedures are shown in Figure 3-7.

The Methods Engineering Group receives all advanced, released and changed LEM engineering information from Manufacturing Planning. Information receipt dates and change status are entered on Grumman Form GT-2009-R1 for a continuous record of drawing disposition.


Planning and ordering of LEM tools is accomplished using the "Methods Engineering Record Sheet, ME 269", which is shown in Figure 3-8. Copies are forwarded to Manufacturing Planning for tooling information and also to Tool Scheduling for issuance of tool fabrication orders.


All LEM tooling revisions are initiated by the Methods Engineering Group using the "Rework Sheet, ME-269A", which is also shown in Figure 3-8. The procedures for distribution and ordering are basically the same as described for original tools.

Tool Shops manufacture non-designed LEM detail tools using the engineering information and the instructions stated in the ME 269 Form. Where applicable, tool shops follow the standards outlined in the Grumman "Detail Tool Manual".

Designed tools and equipment for the LEM Program are manufactured and identified in accordance with the individual drawings. All tooling, both detail and assembly, is inspected by the Tool Inspection Group of the Quality Control Department.

Grumman is using an existing tool and equipment identification system for the LEM Program. A number for a piece of equipment or a tool is formed by adding a letter code to a LEM part number. If the part number is LPT 280-10026-11, three typical tools to make







	MANUF	AIRCRAFT ENGINEERING CORP. FACTURING ENGINEERING INEERING TOOL REWORK RECORD
dwg. no. LSS 210-10210	MODEL DWG. NAME	SUPPORT ASSY.
JOB NO. 74240 001-001		STA 241. CONSOLE
DASH NO. TOOL TYP. EST. CODE ORD. HRS.		T.D. P.T. INFO. R.C. R S SCHED. TOOLING INFORMATION
	- AJ - 5/1/3 - ADV	TOOLED -11 THRU - 16
-11-12 TTP PR 1.0	AJ J-3 $\frac{6}{4}$ $\frac{02}{206}$ $\frac{02}{003}$ ADV	$\checkmark$ ADD 1/8 TO FLAT PATTERN IN AREA OF JOGGLE.
-11-12 PBT. TR 0.6	" " " 5.02 "	$\checkmark \qquad \text{MOVE JOGGLE LINE}_{\bullet}$
-11 HPB PR 2.5	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	$\checkmark$ $\rightarrow$ revise joggle location & slope
-12 HPB PR 2.5		✓ J PER PBT & VIEW A-A, 2ND ADV REL. DWG.
SAN		

PART NO	LSS 21	0-10210-11-12	PER PL	LOP	TED			1	IG AFF	ECTED P	ART	
PART NA		CKET		YES		YES	NO	>			JIG N	о.
NEXT ASS	EM. -1-2				AD <sub>V</sub>		X					
MODEL		SHIP EFFECTIVITY		1		742	40-0	01-00	1 REA	ARKS		
LEM		LTA #1		2								
MATERIAL 2	024- <b>0</b> A	LAL		3								
		40x4x8 1/4			TOOL		TYP. ORD.	EST. HRS.	ORD. BY	DUE	DATE	w
		ROUTING										
DEPT	OPERAT	ION & PRODUCTION TO		TTP		PO	2.3	AJ	G-3	5/1/	3	
	FOR	M IN "O" CON	D.									
				]	PBT	_	то	2.1	AJ	G-3	5/1/:	3
												+
												$\vdash$
			-11	I	IPB		PO	4.0	AJ	G-3		
			-12	I	IPB	_	PO	4.0	AJ	G-3	5/1/3	3
			,									-
	Tar	AND PE				-			-			-
(	262					_						
											OLING	
				REV.		DAT	E	BY		REV.	D	ATE
E 269												

# ME - 269A Methods Engineering Tool Rework Record

ME - 269 Methods Engineering Record Sheet

		GRUMMAN AIRCRAFT ENGINEERING CORP.											
1		MANUFACTURING ENGINEERING METHODS ENG'G RECORD											
KMAN	DESTI- NATION	SCHED.	M		T	OOLING INST	RUCTIONS		_				
$\frac{2}{16}$	$\begin{array}{c} 02\\001 \end{array}$			PER	ADV. I	RELDWO	÷.						
				(FOR	CARTI	ER BOX)							
				#30 /	ALL HO	DLES							
				(REF	': SD 13	2)							
$2_{6}$	$\frac{S-02}{206}$			PER ADV REL DWG & TTP									
				USE :	USE PRODUCTION HOLES								
				FOR	W HOL	ES							
				(REF	SD 12	6)							
2 07	02 003			PER									
2 57	$\begin{array}{c} 02\\ 003\end{array}$			FOR	FOR "O" MAT'L								
				MINI	MUM H	Т.			_				
				NOTE	C: SEE	VIEW A-	-A FOR						
				JOGG	LE SLO	OPE IN 5	/8 FLG.						
				(REF	: SD11	0							
		_	PAR	TS FABRICA									
Bì		REV.		DATE	BY	REV.	DATE	BY					
	,					n.		QB-31	3				

Figure 3-8. ME - 269 Record Sheets

this part would be LPT 280-10026-11 ADJ, LPT 280-10026-11 DRJ, and LPT 280-10026-11 ICF. A single part number plus a code thus represents a basic number for a tool or piece of equipment. There is only one exception to this rule; when a tool can make a part and its opposite, the odd and even dash numbers become part of the tool number, i.e., LPT 280-10026-11-12 DJ. Grumman Tool and Equipment Codes are shown in Figure 3-9.

Occasionally, more than one work station will be used to meet LEM manufacturing schedules. This will require that a duplicate of an existing tool be made. By simply adding #2 to the original tool number, the new tool number is derived, i.e., LPT 280-10026-17 DJ#2. Note that the number symbol (#) must be included.

There are many parts that require several tools to complete a basic operation (i.e., one part might require three separate drilling operations and therefore three separate jigs). The Designer assigns the basic tool number to the drill jig performing the first of these operations; the basic tool number, followed by the number 2 and 3, etc., for subsequent operations, but which may or may not be the actual second or third operation on the part.

- First drill jig ordered LPT 280-10026-7 DJ
- Second drill jig ordered LPT 280-10026-7 DJ2
- Third drill jig ordered LPT 280-10026-7 DJ3

Note, the last number is for identification only, not to determine sequence of manufacturing operations.

If a tool or piece of equipment can be used to perform the same operation on more than one part, the Designer adds a star (\*) to the basic number (i.e., LPT 280-10026-DJ#). The Methods Engineer lists all other parts made with this basic tool. Although the star (\*) must be stamped on the physical tool, all other part numbers must not appear on the tool. By convention, the basic tool number is that one bearing the lowest part number of a group of parts, for which multiple usage tools are applicable.

ADJ Assembly Drill Jig AF APT Assembly Fixture Air Punch Template . . . ARB Arbor BB Bending Block Blanking Die Blanking Die Template Bucking Bar BD BDT BKB BMF Boring Mill Fixture Bonding Fixture Blank and Pierce Die Blank and Pierce Die Template BOF BPD BPT BRF Broaching Fixture BSP BT Special Adapter Brake Template Blank, Pierce and Form Die BXD BXT Blank, Pierce and Form Die Template Brazing Fixture Pneumatic Router Box Template BZF CBT CC Contour Cam CF Checking Fixture COF Combination Fixture CP Plug CR Contour Rollers CRD Corner Radius Die Chamfer Routing Fixture Contour Template CRF CT DA Die Accessories Draw Die Draw Die Rubber Draw Die Template DD DDR DDT DHD Drop Hammer Die Drop Hammer Male Die DHR Diameter Die Drill Jig Dinking Die DID DJ DKD DKT Dinking Die Template Dimpling Die Drill Plate DMD DP DRB Drill and Router Board DRJ Drill and Ream Jig Drill and Ream Plate Drill and Router Template Drill and Scribe Template DRP DRT DST (Formed) Drill and Scribe Template DSU (Flat) DT Drill Template (Formed) . . DU Drill Template (Flat) . . . Drill and Trim Jig Expanding Die Electrical Wiring DTJ ED EHB Harness Board End Radius Die Erco Riveting Fixture Expendable Tools ERD ERF • • • EXT . . . FAD Flattening Die . . . Form Die Forming Die Template Flanging Die FD FDT FLD . . . FPC Formed Piece Form and Pinch-Off Die Form Tool FPD FT FTD Form and Trim Die FWF Flashwelding Fixture . . . FWM Flex White Master Grind Check Template GCT  $\mathbf{GF}$ . . . Grinding Fixture


GHE				General Handling Equipment
GHT				General Hand Tools
GMC				General Miscellaneous Cutter
GMX				Miscellaneous Gage
GPT		•		Gang Punch Template
HB		•	•	Hammer Block
HBT			•	Hammer Block Template
HD	-			Hufford Die
HDT		•		Hufford Die Template
HE			•	Handling Equipment
HF	0	•	•	Holding Fixture
HFD	•	•	•	Hydroform Die
HFT	•	•	•	Hydroform Die Template
HPB		•	•	High Pressure Block
HRJ		•		High Flessure Block
		•	•	Hand Router Jig
HTA		•		Heat Treat Accessories
HTF		•		Hydrotel Fixture
IBF	•	•	•	Induction Brazing Fixture
ICF	•	•	٠	Inspection Checking Fixture
ICT	•	•	•	Inspection Checking Template
$\mathbf{IF}$	•	•	•	Installation Fixture
IJ				Installation Jig
JD			•	Joggle Die
JDT				Joggle Die Joggle Die Contour Template
JI				Jaw Inserts
JLT				Joggle Location Template
JST				Joggle Set-Up Template
LF				Lathe Fixture
LT	•	•		Locating Template
LTE		•		Locating Template Lab Test Equipment
MA		•		
			•	Milling Accessories
MAT			•	
MCA			٠	Machine Accessories
MCT	•			
MCX	•	•	•	Numerical Control Media
				Continuous Path
MDP		•	•	Master Drill Plate
MEX		•		Numerical Control Media
				Engineering
$\mathbf{MF}$	•	٠	•	Milling Fixture
MFB		•		Male and Female Block
MFT		•		Male and Female Block Temp.
MOD		•		Model
MOF		•	•	Molding Form
MOT			2	Molding Template
MP			÷	Molding Template Master Part
MPD	•	•		Miscellaneous Press Die
MPT	•		•	Miscellaneous Press Die
1,11 1	•	•	•	Template
MPX				Numerical Control Media
WIT A	٠	•	٠	Point To Point
MTX				Numerical Control Media
MITA	٠	•	•	Tooling
MITT				
MUF	•	٠	٠	Mockup Fixture
OAF	٠	٠	•	Optical Alignment Fixture
OE	•	٠		Office Equipment
OTA	•		•	Optical Tooling Accessories
PB	•	•		Press Block
PBD	•		•	Press Brake Die
PBH		•		Combination Press and
				Hammer Block
PBT	•			Press Block Template
PCD	•			Pierce and Cut-Off Die
PCT				Part Check Template
PD				Piercing Die
PDT				Pierce Die Template
PE				Plating Equipment
PF			:	Profiling Fixture
PLF		-		Proof Loading Fixture

PMF		0		Portable Mill Fixture
PNT				
PRF	- 7			
		0	•	Portable Router Fixture
PRJ		•		Pedestal Router Jig
PRT		•		Press Brake Die Template
PST				
PT				
			•	
PTD		ø	•	Pierce and Trim Die
PTN				Pattern
RAF				Radial Arm Router Fixture
RCT				Radial Arm Router Fixture Roll Contour Template
DD	•	0	•	non contour rempiate
RD	•	٠	•	Roll Die
RDT				Radial Arm Drill and
				Router Template
RF				Riveting Fixture
		•	•	Riveting Fixture
RJ		•	•	Reaming Jig
ROJ		•		Router Jig Rivet Set
RVS				Rivet Set
SAF	•	•	•	Sofotr Fauinmont
				Safety Equipment
SC		•		Spinning Chuck
SCA		•		Spinning Chuck Accessories
SCF				Scribe Fixture
SCI	•	•	•	Special Clamp
SCL SCT SD	•	•	•	Special Clamp Scribe Template
SCT		•		Scribe Template
SD		•		Stretch Die
				Maust Stretch Die
CDD	•	•	•	Calamente De l
SDR	•	•	٠	Schematic Drawings
SDR SDT	•	•		Shear and Drill Template
SF		•		Saw Fixture
SKF	1	2	2	Skin Mill Fixture
CMT	•	•	•	Shin Mill Pistere
SMF	•	•	٠	Spar Mill Fixture
SPT				Strippit Punch Template
SBJ				Setback Router Jig
SRT	•	•	2	Shear Template
SRT		•		
	•	•	•	Saw Template
STE				Silk Screen Stencil
STT				Scribe and Trim Template
SUG				Scribe and Trim Template Set-Up Gage
CITTA	•	•	•	Greet ald Association
OWA	٠	٠		spotweru Accessories
SWD			•	Swaging Die Spotweld Fixture
SWF				Spotweld Fixture Spotweld Template
SWT				Spotweld Template
TDA	•	•	•	Tuba Danding Assessments
IDA				Tube Bending Accessories Tube Bending Die
TBD		•	•	Tube Bending Die
TD	•			Trim Die
TEQ				Testing Equipment
TEQ TFT	•	•	•	
111	•	٠	•	Tube Forming Tools
ΤP	•	•	•	Test Plug
TTA				Arvey Die Master Jig Master Jig Template Control Master
TTB				Jig Master
TTC	•	•	•	Lig Tomplete
110	٠	•	•	Jig Template
TTD	•	٠	٠	Control Master
TTE				Master Tool Template
TTF		•		Control Master Master Tool Template Facility Gage
TTC	č.			General Tooling Tool
110	•	•	•	General Tooling Tool
TTH	٠	•	•	Master Flat Pattern Template Flat Pattern Production Template
TTP				Flat Pattern Production Template
TTR	į			Record Template
	•	•	•	Wiping Template
TTW	•	•	•	wiping remplate
UPT URT WA	٠			Upholstery Template
URT	•			Universal Router Template
WA				Welding Accessories
			÷.	Welding Accessories Washer Die
WD				Washer Die
WD		•		
WF	•			Welding Fixture
WF WM	•	•	•	White Master
WF WM WPB	•		•	Welding Fixture White Master Verson Press Block
WF WM WPB	•		•	Welding Fixture White Master Verson Press Block
WF WM WPB WPD	•	•		Weite Master Verson Press Block Wiping Die
WF WM WPB	•	•		Welding Fixture White Master Verson Press Block

Tool Category Prefix (Example: XADJ, YAF, ZSRJ):


X - Acceptance Gages

- Acceptance Gages to be saved from routine scrap Y
- Z To be saved from routine scrap





The Designer may add as many symbols to the basic tool number as are needed to make a completely descriptive tool number. An example follows:



## 3.2.3 Procurement Planning

The Procurement Planning Department is responsible for manufacturing scheduling (previously described in Section 3.1.1), material processing, and engineering drawing distribution.

LEM engineering information is analyzed to determine the specific contractual requirements for materials and vendor services. The resulting information is processed and transmitted to the Electronic Data Processing Department (EDP), for incorporation with the "Where Used Requirements Procurement Inventory Tape". The following three basic documents are developed and sent to the Purchasing Department by EDP:

- Raw Material Procurement Lists.
- Material Requirements and Status Reports.
- Min/Max Requirements and Status Reports.

Identical procedures are used for satisfying the requirements of Spare Parts and Support Material Lists, Requests for Diversion of Material, Field Changes, and Discrepant Material Tags. Departmental Spare Requirements Lists are prepared for Grumman fabricated parts and subassemblies.

Further, the Procurement Planning Department is the central agency for issuance, control, and recording of engineering information for the manufacturing departments. These releases are distributed in accordance with Manufacturing Planning instructions.

#### 3.3 METHODS AND CONTROLS

Satisfying the LEM Program objectives requires formal and proven techniques for control of schedules, costs, manufacturing reliability, subcontractor activities, mechanical/elec-tronic interfaces, and for traceability and configuration control. Methods for maintaining these controls are described in Sections 3.3.1 through 3.3.8.

#### 3.3.1 Mechanical Interface Control

Planning and managing the LEM interchangeability/replaceability program for mechanical interfaces will begin by establishing requirements for interface design, tolerance ranges, master gage control, matched tooling, manufacturing/inspection procedures, and an I&R List.

Although the I&R List is primarily an Engineering responsibility, Manufacturing Engineering will generate a preliminary list in conjunction with Engineering. Primary considerations in establishing this list include NASA I&R Requirements, part design, reliability, and producibility. To attain the required producibility features necessary for I&R, Manufacturing Engineering reviews and influences part design concepts. As basic Engineering designs progress, Manufacturing Engineering will revise and up-date the preliminary list and negotiate with Engineering to establish the final I&R List. This list will be submitted by Engineering for NASA approval.

Successful accomplishment of interchangeability/replaceability requirements for any given component is directly related to the degree of tooling and the method of fabrication. Hard

masters will be utilized to achieve full interchangeability at structural interface points such as engine mounts, landing gear and adapter connect fittings, and separation plane fittings. Doors and access panels will be master controlled at attach points only, thus minimizing costly trim and contour mastering.

Basic tooling information which is utilized for fabrication of masters, is represented by master contour templates, tooling mockups, and white masters. Additional information is obtained from basic engineering geometry and incorporated in the master gages.

The four primary areas which require mechanical interface control are described below:

• Docking interfaces between LEM and the Command Module and integration of the LEM with the Apollo System will require Grumman coordination and agreements with NASA and NAA. Since NAA is responsible for docking arrangements and interfaces, it is expected that master control tooling, if necessary, will also be provided to Grumman by NAA. Integration of LEM with the Apollo System will be accomplished using structural provisions located within the NAA Service Module Adapter. Although these structures are an NAA responsibility, the assignment of the contractor responsible for the LEM/SM Adapter interface design details has not been established.

Thus, Grumman will use or will provide master control and inspection tooling in accordance with future NASA decisions.

3-24

• Mechanical interfaces between fluid, electrical/electronic and structural LEM subsystems and components will require Grumman coordination with NASA and subcontractors. Some non-critically located subsystem components will be coordinated to the Structural Subsystem by manufacturing to specified engineer-ing drawing tolerances, without master gage tooling. However, subcontractor supplied components such as ascent/descent rocket engines, reaction control engines, and all other critically positioned subsystem components will require master gage coordination. A proven tooling policy will be applied to satisfy the interchangeability requirements for structure/subsystem mating.

Grumman will manufacture a master gage to coordinate jig and fixture fabrication for the Structural Subsystem. An inspection checking fixture will be provided for assurance of product quality. A master and inspection checking fixture will also be supplied to the subcontractor. Thus, Quality Control acceptance, as dictated by the use of the inspection checking fixtures at both Grumman and at subcontractor locations, will assure the interchangeability of corresponding interfaces. This plan and documented vendor requirements are further detailed in Section 3.3.4.

• Mechanical interfaces between the major subassemblies within the Landing Gear and Structural Subsystems are controlled by the in-house tooling, manufacturing, and quality control programs. Prime examples of these interfaces are the mating of ingress/egress hatches to the crew compartment tunnels, seats to the support structures, ascent/descent separation plane, and landing gear to the descent stage structure. Grumman assembly tools used to complete these interchangeability requirements will be coordinated using master gage control.

In addition, some fixtures used to establish the ascent/descent major subassembly jig point locations must also be coordinated with master gages. This concept assures the necessary tolerance control during the structural assembly sequence which is shown in Section 4, and also provides an efficient means for duplication of major tools.

Compound curved areas of the Structural Subsystem configuration will be controlled by the plaster tooling mockup program. These mockups serve as masters for the development and coordination of all sheet metal tools. Tooling mockups will not be required for the descent stage prime structure since the geometry consists of straight line elements. Local mockups and models will be provided for secondary structure such as indented skin details.

• Whenever possible, coordination between the mechanical interfaces of LEM subsystems and associated Handling and Transportation GSE will be achieved without need for master gage tooling. On occasion, the GSE may be required to support the LEM subsystems in interchangeable areas. This coordination of subsystems and in-house manufactured GSE can be readily accomplished since Grumman will retain a complete set of all LEM master gages.

## 3.3.2 Electrical/Electronic Interface Coordination

During the early stages of LEM development, Design Control Specifications will be written and will include requirements for coordination of electrical/electronic interfaces. With this information, a cable and harness checker can be programmed to make the necessary checks concerning signal flow paths.

Once the subsystem design has been formally released, interfaces cannot be revised, either by Grumman or the vendor, without prior approval of the LEM Business Office. Since Grumman subsystem and GSE engineers are in constant contact with the vendors, proposed changes can be reviewed and documentation can be monitored. Subsequent to approval, GSE/STE changes can be incorporated to accommodate revised interface requirements.

#### 3.3.3 Manufacturing Reliability Control

Because of the direct relationship between ultimate LEM reliability and producibility, constant liaison is presently being maintained with Design Engineering to provide information regarding the latest manufacturing and testing techniques, processes, and equipment. Whenever necessary, producibility surveys will include the manufacture of sample structural elements to investigate manufacturing feasibility of the structural design. These surveys will assist in establishing the trade-offs between design concepts and producibility.

Grumman will make maximum use of proven fabrication techniques and available manufacturing equipment. This approach, rather than attempting to exceed the present state-ofthe-art, will assure optimum reliability and on-schedule performance.

If new cost or performance improvement concepts in manufacturing techniques are indicated during the course of the LEM Program, the Grumman Manufacturing Development Organization will immediately institute programs for method or process development. However, the new technique will be thoroughly proven and tested while LEM fabrication is maintained using an interim proven technique.

The LEM Structural Subsystem manufacturing breakdowns shown in Section 4 were influenced toward producibility by giving full consideration to manloading, lead times, tolerance requirements, and assembly and handling convenience.

Copies of applicable specifications are maintained in the office of the shop foreman. It is his responsibility to supply parts and assemblies which conform to these manufacturing standards. Specifications are also maintained by the Quality Control Department and are used during inspections to verify product conformance. Control of product quality and tool/equipment accuracy is assured by virtue of the procedures outlined in the "Grumman Quality Control Program Plan", Report LPL-81-1, Volume I.

The LEM Quality Control Plan sets forth the Grumman procedures for implementing the requirements of NASA Quality Publication NPC-200-2 and Contract NAS 9-1100. The ultimate objective of this plan is to provide optimum quality assurance that the LEM meets design criteria, contract reliability and performance levels, and maintainability and serviceability requirements.

The Manufacturing, Assembly, and Inspection Record (MAIR) is shown in the Quality Control Plan and will be used as documentary evidence of all manufacturing and inspection operations completed for LEM assemblies.

Inspection and test plans are described for detail parts, assembly, installations, checkout, and for witnessing and verifying the acceptance test programs. In addition, plans are described for tool inspection, process control, monitoring of clean room operations, and calibration of precision measuring and test equipment.

Consequently, the manufacturing concepts for "building producibility into the system", and the quality control measures integrated throughout all LEM development phases are a vital contribution for achieving optimum LEM reliability.

#### 3.3.4 Control of Subcontractor Tooling and Manufacturing Activities

Grumman has established a four phase program for control of LEM subcontractor manufacturing performance. The objectives are to monitor technical approaches, and to assist the LEM Program Management and Business Offices in the control of subcontractor schedule and financial performance. This program is outlined as follows and is discussed in Paragraphs 3.3.4.1 through 3.3.4.4:

- Review and analysis of all subcontractor cost and technical proposals, with regard to tooling, equipment, processes, and manufacturing approaches.
- Contribution to the "Vendor Requirements" documents for inclusion of associated manufacturing program requirements.
- Monitoring and review of subcontractor manufacturing programs.
- Procurement control to notify the LEM Purchasing Office of subcontractor delivery performance.

3.3.4.1 Review and Analysis of Subcontractor Proposals

Grumman assigned representatives to the "Effort Analysis Team" are engaged in a continuing review of proposed subcontractor approaches to tooling, equipment, processes, and manufacturing. The review and analysis of proposals and subsequent selection of a subcontractor has been completed as follows:

٠	Rocketdyne	-	Descent Propulsion Subsystem – Engine
•	STL		Descent Propulsion Subsystem – Engine (Parallel Engine Development Program)
•	Hamilton-Standard	_	Environmental Control Subsystem
•	Bell Aerosystems	_	Ascent Propulsion Subsystem – Engine Reaction Con- trol Subsystem – Propellant Tanks
۲	Marquardt	-	Reaction Control Subsystem – Propulsion and Thrust Chambers



- RCA Navigation and Guidance Subsystem Rendezvous and Landing Radar
   Stabilization and Control Subsystem - Attitude and Translation Control, Descent Engine Control, Guidance Coupler, and the In-Flight Monitor Components
   Communications Subsystem
   Instrumentation Subsystem - In-Flight Test System
- Pratt & Whitney Electrical Power Subsystem Fuel Cell
- Radiation
   Instrumentation Subsystem Pulse Code Modulation
   and Timing Equipment
- Leach Instrumentation Subsystem Data Storage Equipment

As a prerequisite to formal contract acceptance, the manufacturing representatives of the "Effort Analysis Team" have performed the following functions and will continue their activities for future vendor negotiations:

- Evaluate technical approaches and cost estimates for tooling, equipment, process, and manufacturing tasks.
- Determine application and use of special test equipment.
- Review the basis for the cost estimates and evaluate changes due to original task omissions, reestimates of original tasks, and new tasks resulting from schedule and vendor work statement changes.
- Preliminary review of manufacturing approaches for compatibility between the mechanical and electrical/electronic interfaces of corresponding subsystems or components.

#### 3.3.4.2 "Vendor Requirements" Documentation

Statements regarding the procedures and concepts required for satisfactory vendor manufacturing performance are included in the "Vendor Requirements" documentation. These documents being completed for applicable LEM subsystems show vendor manufacturing guidelines, program controls which Grumman will exercise, and services and/or items, which will be supplied to facilitate vendor manufacturing programs.

"Vendor Requirement" Document LVR-270-4, dated 12 March 1963, for the LEM Descent Propulsion Subsystem contains the manufacturing conditions developed by Grumman for assurance of satisfactory vendor performance. Excerpts from LVR-270-4 are as follows and are generally typical for all documentation of this type:

- Processes The vendor shall submit a list of process specifications to be used in the manufacture of the rocket engine. Where a process is controlled by an internal document, rather than a government specification, the entire document shall be submitted for approval.
- Grumman Supplied Tooling It is the intent of Grumman to supply any tooling necessary for mechanical interface coordination. Each deliverable item will be considered acceptable for physical dimensions of mechanical interfaces by Grumman only when it has been certified by Grumman Quality Control Personnel as having been checked using a Grumman supplied inspection checking fixture. Grumman will make available master gauges if required by the Vendor.

3 - 31

- Dimensional tooling is to be provided by the vendor in order to adequately meet all of the hardware requirements as specified herein. The Vendor shall indicate what limitations and/or assumptions have been made in providing the tooling program. For a LEM component that is used commonly on the Apollo Command Module or Service Module, the same acceptance procedure is required as specified above. However, due to the common usage, it may be necessary for the master gages and/or checking fixtures to originate with a source other than Grumman. The vendor shall specify that the proposed tooling is adequate for fabrications of\_\_\_\_quantities of parts (specified by components referenced in LVR-270-4, Item 1.1) at the rate of \_\_\_\_\_parts per month. (Item 1.1 includes the list of hardware components to be included in the vendors task description.)
- Special Tooling Report After delivery of the first unit(s) of supplies called for in this purchase order, Vendor shall submit to Grumman in accordance with Table I, a list of tools per Manufacturing Engineering Form 224 and completed as of the delivery of the first unit, detailing the quantity, the description, tool number and the individual cost (reasonably estimated if necessary) of each tool together with the part number for which it is used. (Table I is the Documentation Type and Delivery Schedule included in the Vendor Requirements document.)
- Quarterly Special Tooling Report Vendor shall submit in accordance with Table I, a similar list of tools which have been completed since the submission of the previous list. If there are no additional completed tools to report at the date of quarterly submission, a statement to that effect will be submitted. The completion invoice shall be accompanied by a list of any tools completed and not previously reported.

- Tool List Each special or quarterly special tooling list shall be certified as follows: "We certify that we, as custodian, are accountable to Grumman for the above tools, that they are the property of the U.S. Government, that they have been so identified and that they are available for inspection by Government Representatives".
- Tool and Equipment Codes Vendor shall identify all tools using Grumman Tool and Equipment Codes. In addition, the vendor may use his own existing identi-fication system.
- Manufacturing Plan The Vendor shall prepare a manufacturing plan that includes such items as plans, schedules, methods and controls. This is to be submitted 1 month after purchase order go-ahead.

# 3.3.4.3 Monitoring and Review of Subcontractor Manufacturing Programs

The Grumman manufacturing team will participate in the Monitoring and Review Plan as outlined in the "Vendor Requirements" documents. This plan is described below:

- Quarterly Program Review Meetings. This is a 1-day review devoted to program progress and will include a review of manpower, facilities, organiza-tional problems, cost, and schedules. This will be held at the vendor's facilities.
- Bi-Monthly Meetings. The bi-monthly meetings between the Vendor and Grumman constitute the primary personal contact for review and monitoring of the detail development program at the working level. On specific occasions it might be desirable to have second tier subcontract personnel in attendance at these meetings. Minutes will be published by Grumman and the appropriate content thereof, as approved by the LEM Purchasing Manager, will constitute technical direction to the vendor. Meeting agendas will be jointly determined between the Grumman and vendor project personnel at least 1 week prior to each meeting. These meetings will normally convene at Grumman on a scheduled basis. They may, on occasion, be convened at the vendor's plant.

• Other Meetings. - From time to time as the program develops, there will be a need for less formal meetings primarily for the exchange of technical information. It is desired that there be sufficient mutual confidence between Grumman and the vendor that these meetings can take place with minimum disruption of useful work. The object is the exchange of technical information. Technical direction can originate only from the designated subsystem engineer. Technical direction resulting in cost changes cannot be acted upon until authorized by purchase order amendments.

In addition to the Monitoring and Review Plan, Grumman will closely control the mechanical and electrical/electronic interface programs (as defined in Sections 3.3.1 and 3.3.2) by maintaining personal liaison with NASA, NAA, and cognizant subcontractors.

Support will also be provided to the LEM Business Office when necessary for evaluation of cost and schedule performance pertaining to the vendor manufacturing, tooling, and equipment programs.

3.3.4.4 Procurement Control

The Procurement Control Department, operating as an integral part of the Manufacturing organization has the prime responsibility of notifying the LEM Purchasing Office of contract items and materials in limited supply. This effort, and the subsequent follow-up for Grumman use of received components, is accomplished in the following manner:

- Expedite the procured items to the Grumman departments to meet LEM manufacturing schedules.
- Control and monitor Grumman repair of defective LEM purchased items if such items are considered repairable and if they are critically needed to support the manufacturing program.



- Monitoring of purchased parts which are borrowed or permanently diverted from the manufacturing cycle.
- Allocation and control of serialized subsystems.
- Coordinate procured items needed for spares, field changes, and GSE/STE.
- Publish critical shortage documents for purchased parts.
- Coordinate the efforts of receiving and inspection on critical purchased items by priority.

# 3.3.5 Schedule Control

Grumman willutilize PERT/Time reports for analyzing current manufacturing progress and for projecting future performance. PERT specialists have been assigned to assist the LEM Manufacturing Management Staff for providing the tooling, equipment, and manufacturing contributions to the over-all PERT program.

The primary responsibilities of these specialists are as follows:

- Coordinate and assure the comprehensive development of all manufacturing milestones.
- Contribute to the preparation and up-dating of the diagrams.
- Collect initial and revised time estimates for manufacturing activities.
- Analyze computer output data for up-dating requirements.
- Distribution of PERT information to the Manufacturing Management Staff.

In addition to monitoring of Grumman schedules, PERT/Time reports will be used as a means of evaluating and adjusting schedules for the receipt of materials, vendor activities, information releases, and management of manufacturing manpower.

Normalizing the shop workload for maintaining tool fabrication and LEM manufacturing schedules will be accomplished through an analysis of the specific condition and the application of one or more of the following procedures:

- The flexibility of the Grumman organization allows for the immediate transfer of personnel from one department or section to another for optimum skill utilization. Consequently, a stable level of skilled personnel is maintained, and efficient resolution of critical priority items in tooling and product manufacture is assured. This same flexibility is inherent in the tool and equipment design sections.
- Other Grumman shop departments or plants which maintain the required manufacturing specialty are frequently contacted for "open-time", thus allowing for temporary transfer of the manufacturing task.
- The subassembly breakdown sequence is thoroughly analyzed to determine whether the priority of the component can be temporarily altered to permit installation at a later assembly stage.
- In selected instances, the authorization of overtime, multiple-shift shop operations, and/or maximum manloading of assembly stations is an effective means for solution.

- Occasionally, maximum manloading is hampered by the relatively small size or the confining configuration of the component. Based on an analysis of over-load duration and economics, duplicate tools or a refined subassembly tooling breakdown may be provided to improve manloading for maintaining schedule performance.
- Some detail parts are re-processed and in some cases are re-designed by engineering for utilization of less critical equipment and facilities.
- A stable machined parts workload is maintained by producing initial quantities at Grumman and subcontracting the balance. If schedules allow, the complete release of machined parts may be subcontracted.

#### 3.3.6 Cost Control

Performance within the established budgets for the manufacturing functions, tooling equipment, and processes is a major goal of the LEM manufacturing program.

Expenditures will be monitored using a PERT Companion Cost System as outlined in the Program Master Plan. Present methods and procedures for controlling the manufacturing functions can be adapted to generate and monitor a PERT Companion Cost System.

Electronically processed expenditure reports, prepared and distributed by the Accounting Department, form the basis for the accumulation of all cost monitoring data.

Because of the recurring nature of the manufacturing operation and the primarily non-recurring nature of tool and equipment functions, the allocation of the budgets for implementing the two efforts must be somewhat different. The manufacturing budget is distributed to the various shop departments who are assigned work tasks in the LEM Program. To make this distribution more meaningful and functional in control, the budget is further subdivided

Gumman LEN

into contractual line items, subsystems, and major systems. This breakdown will be developed in accordance with the future requirements of the PERT Companion Cost System.

The established accounting codes of the company will be assigned as usual to indicate the type of labor (manufacturing as distinct from engineering, etc.) and item identification. The introduction of cost coding into the work orders authorizing the Manufacturing Department to proceed with its tasks, provides the proper account to which labor is charged. The EDP equipment summarizes the actual labor charges in a manner which allows for periodic summaries of:

- Planned vs actual man-hour expenditures.
- Planned vs actual manpower utilization.
- Percent cost expended vs percent hardware accomplishment.

The tabulations supplied by EDP make it possible to distribute control data to all levels of management at frequent intervals. An important element in this program of planned expenditures is planned cost reduction on selected learning curves which tend to demand improvement in techniques, methods, and programming.

The system is flexible enough to readily encompass changes in budget allotments, planned expenditures, as well as changes in scope, and has the additional advantages of ready comprehension throughout the organization.

Tool and equipment budget breakdowns will also be developed in accordance with the requirements of the PERT Companion Cost System. Approval to proceed with any given task is being, and will continue to be, managed in the following manner:



- As engineering information is generated, cognizant LEM key personnel who represent the tooling and equipment design functions, prepare Work Authorization Statements. These statements contain itemized estimates of anticipated group effort.
- The LEM Project Manufacturing Engineer or the Test Equipment and Process Project Engineer review the Work Statements to determine conformance with the Manufacturing Plan and the validity of the estimates. The Project Engineers are assisted in these reviews by the LEM Project Planning and Control Specialists.
- Approval of the Work Statements by the cognizant Project Engineer constitutes authorization to proceed with the work tasks.
- Work Authorization Statements are revised as dictated by further engineering information. Again, each revision requires approval of the Project Engineer.
- Tool and equipment fabrication is initiated by Shop Work Orders which contain the estimated cost for each task. This Work Order constitutes the authorization for a particular shop department to proceed with a specific task.
- Electronically processed feedback of actual expenditures are compared to the Work Statement Budget. The Project Planning and Control Specialists forward the comparative data to the Project Engineers. Thus, immediate action can be initiated to assure lowest over-all program costs.

#### 3.3.7 Parts Control (Production Control)

Parts Control, as an adjunct of the Plant Superintendents Office, assists the individual plants by monitoring the LEM manufacturing process, with special emphasis on the expeditious flow of parts and materials. A Parts Control Representative is assigned to each assembly department for the following production control functions:

- Develop Shortage Reports and expedite departmental requirements to meet the schedule of the affected subassemblies.
- Record and expedite shortage items for incorporation of parts into those assemblies which have progressed to a subsequent assembly station.
- Monitor detail parts stock inventories to maintain schedules for the subassemblies and assemblies.

#### 3.3.8 Traceability and Configuration Control

Configuration management on LEM will be effected through a set of procedures by which the configuration of deliverable modules is identified, controlled, and documented. The LEM Engineering Department will provide a "Controlled Items List", which serves as a basis of manufacturing efforts in configuration control. Manufacturing will account for these traceable items by indicating on the Work Order and Route Cards that these items are traceable. As the part is manufactured, it is accompanied by a punched card containing the serial number and all pertinent information related to that particular part. The punched card remains with the part until it is issued by the stockroom. At that time, the module number on which it will be used is recorded.

Upon receipt of an Engineering Change Notice, the Manufacturing Planning Department processes the change and establishes module effectivity. Each Work Order will be accompanied by a punched card which is retained by the Quality Control Department until the change has been accomplished in the pre-established module. The completed punched card is forwarded to the data retention center to become incorporated in the records for that particular module. The punched card contains the information necessary for producing a complete configuration list at any time during the life of a specific module. Implementation of configuration management procedures assures that:

- All delivered end items are configured in accordance with the applicable released information required to fabricate, test, accept, operate, maintain, and support the end item.
- Appropriate procedures, systems, and organizations are initiated in the design and development phase to facilitate transition into formal configuration control after the "configuration freeze".
- All delivered end items are accurately and completely described by readily available documentation.
- For approved changes in an end item configuration, corresponding changes are made in all related support elements (i.e., test equipment, support equipment, spares, manuals, tooling, training equipment, documentation, etc.).
- There exists a configuration status list documenting the configuration and all approved changes.
- The specific location and status of each "controlled item" of equipment, by part number and serial number, is known at all times.
- All proposed changes to end items will be controlled by a Change Control Board.

The Quality Control Department will be responsible for assurance of module conformance with the change information specified on the key punched card.

SECTION 4 - Structural/Mechanical, Fluid, and Electronic Subsystems

#### SECTION 4

## STRUCTURAL/MECHANICAL, FLUID, AND ELECTRONIC SUBSYSTEMS

#### 4.1 STRUCTURAL/MECHANICAL AND CREW PROVISIONS SUBSYSTEM.

Grumman is responsible for the manufacture and assembly of the Structural/Mechanical and Crew Provisions Subsystems, as described in Section 1.3, "Make or Buy" Summary. The following Sections 4.1.1 through 4.1.1.3 describe the manufacturing plans for the Structural/Mechanical Subsystem. The basic manufacturing approaches for the Crew Provisions Subsystem are described in Section 4.1.2.

The Development Manufacturing Plan for these subsystems requires a logical progression from initial LTA fabrication to subsequent LTA and LEM follow-on manufacture. The following three basic steps are planned for assurance of on-schedule performance, maximum manufacturing reliability, and lowest over-all program costs:

- For all manufacturing up to and including the LTA-3 Grumman plans to use a minimum subassembly breakdown and a minimum tooling concept. Specially skilled shop technicians, who are completely adaptable to this procedure, will manufacture the early LTA units. Only the major assembly and subassembly type tools will be provided. These tools will incorporate the major jig-point locations. Detail tools used for after-form manufacturing operations will be minimized.
- As Engineering designs progress and after some designs have been modified to incorporate the initial manufacturing and test program results, the subassembly breakdown will be expanded and the tooling program will be refined. This expansion is planned to accommodate the manufacturing rate and concurrent

development requirements as shown in Figure 1-2. During LTA-4 fabrication, the initial major assembly tools will be refined by the addition of other locating and clamping devices, additional detail and subassembly tools will be provided, and a few major tools will be duplicated. This tooling phase is planned for completion during the assembly of the LTA-4 Environmental Development Module. Thus, LTA-5 and subsequent LTA's and LEM's will be developed using finally configured structural assembly tooling.

4 - 2


• The structural manufacturing technicians who participate in the initial LTA development will also form the nucleus of an expanded manufacturing team. These key technicians will provide the experience factor which is necessary for planned 'learning-curve'' cost reductions.


#### 4.1.1 Structural/Mechanical Subsystems

All tooling and manufacturing procedures described herein for the ascent structure, descent structure, and lunar landing gear are based on the October 1, 1963 LEM General Arrangement Configuration which is shown in Figure 4-1. Figure 4-2 shows the LEM subassembly breakdown.

The Ascent and Descent Stage subassembly breakdown and manufacturing flows are shown in Figures 4-? and 4-4, respectively. All breakdowns were established by closely reviewing the manufacturing lead times and manloading capabilities for maximum reduction of elapsed manufacturing time, commensurate with the critical assembly schedules. In addition, full consideration has been given to satisfying the tolerance and anticipated interchangeability requirements, utilization of available equipment ranges and facilities, and convenient handling throughout the manufacturing phases.

The Ascent Stage breakdown will permit optimum manloading for installation of secondary equipment mounting structure in the individual major subassemblies. This feature, and the concept for providing interchangeability between the subsystem components and the





LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963







Figure 4-3 Ascent Stage Structural Subassembly Flow





LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963

Prepare & Ship Landing Gear to Appropriate Site.

Figure 4-4. Descent Stage-Subassembly Breakdown

mating structure will minimize the structural work during the ascent subsystem installation phase. These factors are extremely important for meeting the compressed subsystem installation schedules, because of the manloading limitations within a completed Ascent Stage structure.

The Descent Stage subassembly breakdown and manufacturing flow shown in Figure 4-3 indicates one major assembly stage and various component subassembly operations. This minimum breakdown is considered adequate for the average manufacturing rate of 1.5 units per month.

All structural subassembly and assembly operations for the Ascent and Descent Structural/ Mechanical Subsystem will be performed by maintaining clean assembly practices in standard shop environments.

4.1.1.1 Manufacture of Detail Parts

Detail parts for the LEM Program will be manufactured in the various specialized shop departments which are located throughout the Bethpage Facility.

The centralized sheet metal parts fabrication facility shown in Section 2 will produce the majority of the formed skin and frame details. Forming tools will be provided for compound curved skins, as well as details with curved heel-lines, deep joggles, and changing flange angles. After-form drill and trim tools will be held to a practical minimum. Tooling will be more extensive for some sheet metal parts, depending on configuration, tolerances, or coordination requirements.

Honeycomb equipment shelves will be produced in a specialized shop which is fully equipped for parts preparation and platen press or autoclave bonding.

In accordance with the Grumman procurement policy, initial quantities of machined parts will be manufactured in-house, and some follow-on quantities will be competitively subcontracted. In-house manufacture of initial machined parts will be accomplished by fully

Gumman LEN

utilizing standard set-up and clamping tools, overlay templates, part layout methods, numerical control, and jig boring techniques in lieu of formal tooling. For those parts which remain a Grumman manufacturing responsibility, some drill jigs, drill plates, and machining tools will be provided to replace hand layout and shop set-up. In addition, some numerical control applications will be expanded.

Chemical-milling will have wide application for minimizing the weight of the Structural/ Mechanical Subsystem. Typical manufacturing procedures for a chem-milled LEM crew compartment frame detail are shown in Figure 4-5. All operations from vapor degreasing through ultrasonic inspection of detail thickness are shown.

4.1.1.2 Manufacture of Subassemblies and Final Structural Assembly - Ascent Stage

The Ascent Stage is primarily a double walled pressurized structure fabricated of formed skin and frame members. Internal aluminum skins are designed for pressurization of the Cabin & Mid Section, while external skins serve as meteoroid shielding. The unpressurized Aft Equipment Bay is a subassembly which is fabricated using conventional mechanical fastening methods.

Structural subassembly and final structural assembly operations for the Ascent Stage will require the utilization of manufacturing techniques such as automatic fusion welding, resistance welding, and mechanical fastening.

Table 4-1 lists the major Ascent Stage subassemblies and also shows the major tooling requirements. Figures 4-6 through 4-9 show the manufacturing breakdown and flow for the major Ascent Stage subassemblies.

The highest degree of manufacturing reliability is required to satisfy the specifications for Ascent Stage pressurization. Consequently, automatic fusion welding techniques, very similar to those employed for the welding of man-rated booster structures, will also be extensively applied for the LEM Program. All automatic fusion welding stations will be

Gumman L € M




Figure 4-5. Chemical Milling of a Typical LEM Detail

Grumman L E M

	······	ASCENT STAGE*
Major Assembly Operation And Fixture Number	Major Tool Type	Assembly Name Or Operation Description
1	Weld Fixture	Joining of Face Center Panel Machined parts
2	Weld Fixture	Joining of L/R Face Outboard Panel Machined parts
3	Weld Fixture	Joining of Assemblies 1 and 2
4	Weld Fixture	Forward Docking Tunnel
5	Combination Fixture	Weld Assemblies 3 and 4. Install glass attach points, and sealing members.
6	Combination Fixture	Navigation & Guidance Dome. Final machine cruciform edges.
7	Combination Fixture	Cabin Skin Subassembly. Machine trim cruciforms in fixture prior to each weld.
8	Combination Fixture	Weld Assemblies 6 and 7. Machine Cabin Subassembly to accommodate Face.
9	Weld Fixture	Join Assemblies 5 and 8 (Face/Cabin Subassembly)
10	Combination Fixture	Mid-Section Skin Subassembly. Machine trim cruci- forms in fixture prior to each weld.
11	Weld Fixture	Upper Docking Tunnel
12	Weld Fixture	Upper Docking Tunnel to Upper Deck
13	Combination Fixture	Join Assemblies 10, 12, and Lower Deck. Machine trim forward and aft faces.
14	Combination Fixture	Join Fwd Bulkhead and Aft Ring to make Mid Section Subassembly. Machine trim Forward Bulkhead flange.
15	Assembly Fixture	Unpressurized Equipment Bay
16	Weld Fixture	Join Assemblies 9 and 14
17	Assembly Fixture	Separation Deck
*See Figure 4-:	Fixture	age Subassembly Breakdown, and Figures 4-6 through 4-

Table 4-1. Ascent Stage - Major Assemblies and Major Tools Required (Cont.)


ASCENT STAGE* (Cont)				
Major Assembly Operation And Fixture Number	Major Tool Type	Assembly Name Or Operation Description		
18	Assembly Fixture	Cabin Y-22 Beams		
19	Assembly Fixture	Mid Section Y-22 Beams		
20	Assembly Fixture	Ascent Stage Final Structural Assembly		
21	Assembly Fixture	Forward Bulkhead Secondary Structure		
22	Assembly Fixture	Aft Bulkhead		
23	Installation Fixtures	All installations of external structure, tank and engine mounts, Separation Plane, and equipment mounting provisions requiring an Installation Fixture		
24	Inspection Checking Fixture	Inspection of Separation Plane, Engine Mount, and RCS Mount Hole Patterns		

\*See Figure 4-3 for Ascent Stage Subassembly Breakdown, and Figures 4-6 through 4-9 for Ascent Stage Manufacturing Flow.

Table 4-1 Ascent Stage - Major Assemblies and Major Tools Required

developed to include the following practices which are presently used at Grumman for assurance of highest quality:

- Close tolerance fit-up for preparation of mating weld joint edges on details or subassemblies will be accomplished by trimming after all previous manufacturing operations have been completed.
- Tooling will be provided to assure a close tolerance relationship between corresponding diameters of welded parts or subassemblies.
- Only a minimum of elapsed time will be permitted between cleaning and welding operations. Clean handling and assembly practices will be exercised during all phases of welding.




and the second


LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963

Figure 4-6 Face Subassembly Breakdown & Manufacturing Flow






LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963



Weld Navigation & Guidance Dome to Cabin Skin Subassembly and Machine Fwd Face. Radiographic Inspection & Pressure Test.

Figure 4-7 Cabin Subassembly Breakdown & Manufacturing Flow





LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963






Figure 4-9 Aft Equipment Bay Subassembly Breakdown & Manufacturing Flow



- An inert gas environment will shield all "under-the-torch" welding operations. Shielding will also be provided on the underside of the weld area.
- Tooling for holding, aligning, clamping, and chilling will be integrated with the welding equipment. Some equipment may be programmed for contour welding.
- All equipment such as presently available longitudinal welders, combination longitudinal/circumferential welder, and boom welders will be serviced at periodically scheduled intervals.
- All welding operations will be performed by certified equipment operators. Periodic re-certification is mandatory.
- Sample weldments will be produced and tested prior to all LEM welding phases to qualify the equipment settings. All settings are documented for future reference and control.
- Pressure tests and radiographic, visual, and dimensional inspections will be integrated into the manufacturing cycle. These tests will be planned in a sequence to allow for assurance of quality at the earliest practical stages of subassembly.

All of the welded subassemblies will require secondary mechanical fastening-type assembly operations, and the non-pressurized Aft Equipment Bay will be completely fabricated using these conventional aircraft techniques.

The fixtures listed in Table 4–1 contain provisions for establishing index references in the individual subassemblies. Thus, positioning these subassemblies during subsequent joining operations can be readily and accurately accomplished. The major manufacturing sequences are outlined in the following paragraphs.

4.1.1.2.1 <u>Face Subassembly Fabrication</u> - Fabrication of the Face Subassembly (Figure4-6) is accomplished in the following manner:

Grumman LEI

- Fabricate Center Panel machined parts. Weld, machine, and radiographic inspect Face Center Panel Subassembly (Table 4-1, Operation 1).
- Finish machine Face Center Panel
- Fabricate Outboard Panel machined parts. Weld beam and upper and lower panels to complete L/R Face Outboard Panel Subassemblies. Radiographic inspect (Table 4-1, Operation 2).
- Finish machine L/R Face Outboard Panel Subassemblies.
- Prepare and weld L/R Outboard Panels to Face Center Panel. Radiographic inspection (Table 4-1, Operation 3).
- Machine window openings and Cabin mating face using a portable milling attachment.
- Fabrication of standoffs and secondary structure.
- Weld and assemble standoffs and secondary structure.
- Fabricate skin details and machine cruciforms for Forward Docking Tunnel.
- Prepare, weld, and radiographic inspect the Forward Docking Tunnel (Table 4-1, Operation 4).
- Prepare and weld Forward Docking Tunnel to Face. Install glass attach points and sealing members. Radiographic Inspect (Table 4-1, Operation 5).

4.1.1.2.2 <u>Cabin Subassembly Fabrication</u> - The Cabin Subassembly (Figure 4-7) is fabricated in the following manner:

- Fabricate Navigation and Guidance (N&G) Dome skin details.
- Machine N & G Dome frames and cruciforms.

Grumman L E M

- 4-18
- Prepare and weld skins, frames, and cruciforms to complete N & G Dome Subassembly. Final machine cruciform edges and radiographic inspect. (Table 4-1, Operation 6).
- Fabricate Cabin skin details and machine cruciforms.
- Prepare skins and cruciforms and weld Cabin Skin Subassembly using the combination fixture shown in Figure 4-10. Machine trim cruciforms in fixture prior to each weld (Table 4-1, Operation 7).
- Radiographic inspection of weld joints.
- Prepare and weld N & G Dome to Cabin Skin Subassembly using the combination fixture shown in Figure 4-11. Radiographic inspect and pressure test local weld joints (Table 4-1, Operation 8).
- Trim Cabin Subassembly in fixture to accommodate Face, utilizing a guided portable machining attachment. Install some secondary structure required for equipment provisions. Establish index references for subsequent assembly.

4.1.1.2.3 <u>Face and Cabin Subassemblies Joining</u> – The Face and Cabin Subassemblies are joined as follows:

- Prepare and weld Face and Cabin Subassemblies in the weld fixture shown in Figure 4-12 utilizing a "track" guide (Table 4-1, Operation 9).
- Radiographic inspection and pressure test.

4.1.1.2.4 <u>Mid Section Subassembly Fabrication</u> - The Mid Section Subassembly (Figure
4-8) requires the following major operations:

• Fabricate skin details and machine cruciforms.






Figure 4-10 Typical Combination Fixture-Welding & Machining of Skin & Cruciform Assemblies

LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963






Figure 4-11 Combination Fixture-Welding of N&G Dome to Cabin Subassembly

LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963






Figure 4-12 Weld Fixture–Welding of Face to Cabin Subassembly





- Prepare, weld, and machine L/R side skin and cruciform subassemblies in a combination fixture similar to the fixture shown in Figure 4-10. Radiographic inspect all welds (Table 4-1, Operation 10).
- Machine top and lower decks.
- Machine Upper Deck, and fabricate secondary details and assemble.
- Machine ring details, and fabricate cylindrical and supporting structure. Prepare, weld, radiographic inspect, and pressure test Tunnel Subassembly (Table 4-1, Operation 11).
- Prepare and weld Tunnel to Top Deck using the weld fixture shown in Figure 4-13. Attach supporting structure and radiographic inspection of weld (Table 4-1, Operation 12).
- Prepare and weld side skin and cruciform subassemblies, Lower Deck and Upper Deck/Upper Docking Tunnel Subassembly utilizing the combination fixture shown in Figure 4-14. Trim forward and aft faces. Radiographic inspection and pressure test (Table4-1, Operation 13).
- Machine Aft Ring and Forward Bulkhead utilizing numerical control techniques.
- Machine rings and fabricate honeycomb core, skins, and sheet metal cylinder. Assemble Engine Cover Subassembly.
- Preparation and welding of Aft Ring and Forward Bulkhead to Upper Deck, L/R Side Skin and Lower Deck Subassembly utilizing the Figure 4-15 combination fixture. Machine trim Forward Bulkhead flange in the fixture. Radiographic inspection of all welds (Table 4-1, Operation 14).
- Pre-fit Engine Cover Subassembly and pressure test.
- Fabricate and install beams and secondary structure for equipment mounting.

Gumman LEM











Figure 4-14 Combination Fixture-Welding of Lower Deck, Side Skin/ Cruciform and Upper Deck/ Docking Tunnel Subassemblies





LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963 Figure 4-15 Combination Fixture-Welding of Aft Ring & Forward Bulkhead



4.1.1.2.5 <u>Aft Pressure Dome Fabrication</u> – The Aft Pressure Dome is produced as follows:

- Prepare material for spinning.
- Spin to required shape and chem-mill to reduce weight.
- Drill attach hole pattern.

4.1.1.2.6 <u>Aft Equipment Bay Subassembly Fabrication</u> – The Aft Equipment Bay (unpressurized) Subassembly (Figure 4-9) is fabricated using mechanical fastening techniques as previously mentioned. Procedures are as follows:

- Manufacture rings, webs, frames, skins, and access panels. Cut cold plate extrusions to length.
- Fabricate tank attach fittings and secondary structure.
- Progressively join these details in major fixture 15 (Table 4-1). This fixture contains tooling locators and clamps for maintaining position of details.

4.1.1.2.7 <u>Face/Cabin and Mid Section Subassemblies Joining</u> - Structural joining of the Face/Cabin and Mid Section Subassemblies (Figure 4-16) is accomplished utilizing automatic fusion welding as follows:

- Automatic welding equipment incorporating standard accessories and a welding fixture is used to produce the circumferential weld joint (Table 4-1, Operation 16).
- Hoisting bars, slings, and overhead hoisting equipment assure proper and safe loading operations.






Figure 4-16 Joining of Face/Cabin and Mid Section Subassemblies




- Since index references were established during the final stages of subassembly manufacturing, the three assembly sections can be accurately coordinated in this welding station.
- All previously described welding and inspection practices for achieving optimum weld integrity will be applied during this major assembly operation.

4.1.1.2.8 <u>Ascent Stage Assembly</u> – Final structural Ascent Stage assembly is completed by joining the previous major welded structure to the unpressurized Equipment Bay. Prior to joining, the following structural operations are accomplished:

- Fabricate sheet metal details and machined parts for Separation Deck and assemble (Table 4-1, Operation 17).
- Fabricate sheet metal details and machined parts and assemble Cabin and Mid Section Y-22 Beams (Table 4-1, Operations 18 and 19).
- Locate Separation Deck and Cabin and Mid Section Y-22 Beams in the final assembly fixture shown in Figure 4-17. (Table 4-1, Operation 20).
- Locate and join Face/Cabin and Mid Section Subassembly to the Separation Deck and Y-22 Beams.
- Manufacture necessary secondary structure and complete fabrication of Forward and Aft Bulkheads (Table 4-1, Operations 21 and 22).
- Fabrication and installation of Cabin Floor and internal secondary structure required for equipment mounting provisions.
- Fabricate and attach external structure and some closure panels.
- Fabricate and install RCS Thruster Mounts and Propulsion Engine Mount.

Grumman LEM



LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963 Figure 4–17 Final Structural Assembly Fixture-Ascent Stage

- Incorporate structural provisions for accepting the fuel, oxidizer, and helium tanks.
- Fit, install, and seal windshield subassemblies.
- Installation of remaining equipment mounting provisions and secondary structure.
- Pre-fit Aft Pressure Dome and unpressurized Equipment Bay.
- Check Ascent Stage separation, RCS, and Propulsion Engine Mount interfaces using inspection checking fixtures (Table 4-1, Operation 24). (Methods for achieving interchangeability between Grumman structure and vendor supplied components are discussed in Section 3.3.1.)

After completion of final structural assembly, the Ascent Stage is removed from the fixture using a GSE hoisting sling. Transfer to the cleaning area is accomplished using a GSE handling dolly. The beginning of subsystem installation in the Grumman clean room is described in Section 5. The external meteoroid shielding skins which are installed after subsystem installations are also described in Section 5.

4.1.1.3 Manufacture of Subassemblies and Final Structural Assembly - Descent Stage.

The Descent Stage is an assembled aluminum beam and skin structure which contains pick-up provisions for the Descent Engine, Landing Gear, fuel and oxidizer tanks, critical oxygen supply, and other Descent equipment. The manufacture of the Lunar Landing Gear is also discussed in this section.

This Structural/Mechanical Subsystem is generally representative of typical aircraft construction. Subassembly and assembly tools are similar in design to those presently used at Grumman for aircraft beam and skin structures.

Table 4-2 lists the subassembly tool families and the major tooling requirement for the Descent Stage and Landing Gear. Figure 4-4 shows the Lunar Landing Gear and Descent Stage Subassembly breakdown and manufacturing flow.

* DESCENT STAGE				
Major Assembly Operation And Fixture Number	Major Tool Type	Assembly Name or Operation Description		
1	Assembly Fixture	Descent Structure- Main Beams		
2	Assembly Fixture	Descent Structure – Intermediate Beams & Intermediate Beam/Closure Panel Subassembly.		
3	Assembly Drill Jig	Upper Bulkhead		
4	Assembly Drill Jig	Lower Bulkhead		
5	Bonding Fixture	Tank Skirts		
6	Assembly Fixture (2 Req'd.)	Descent Stage Final Structural Assembly		
7	Installation Fixtures	Installation of Tanks, Tank Skirts and Separation Plane Fittings.		
8	Holding Fixture	Final Structure		
9	Inspection Checking Fixtures	Inspection of Ascent/Descent Separation Plane and Engine Mount Hole Pattern.		
10	Welding Fix- tures (Family of Tools)	Welding of Landing Gear and Outrigger Struts		
11	Keller Drill Jigs(Family of Tools)	Drilling of Landing Gear and Outrigger Strut Connections.		
12	Inspection Checking Fixtures	Dimensional Inspection of Assembled Landing Gear and Outrigger Subassembly.		


\*See Figure 4-4 for Descent Stage Subassembly Breakdown and Manufacturing Flow

Table 4-2- Descent Stage- Major Assemblies and Major Tools Required.

Gru

4.1.1.3.1 <u>Descent Structural Subsystem Assembly</u> – The major manufacturing sequences for the Descent Structural Subsystem are outlined below:

- An assembly fixture is provided for the fabrication of the main beams (Table 4-2, Operation 1).
- An assembly fixture is used to produce the intermediate beams. The same fixture is utilized for the manufacture of the Intermediate Beam Closure Panel Subassembly (Table 4-2, Operation 2).
- Assembly drill jigs are used for the manufacture of the upper and lower bulkheads (Table 4-2, Operation 3 and 4).
- Fabrication and inspection of attach fittings for tanks, tank skirts, engine, and miscellaneous components. Also, fabrication and inspection of landing gear fittings.
- Fabrication of Upper Bulkhead attach fittings and inspect.
- Fabricate details and machine fittings and assemble landing gear outriggers.
- Fabricate and inspect tank skirts (Table 4-2, Operation 5).
- Fabrication and inspection of tank mounts.
- Fabricate and inspect end panels and thermal shielding.
- Final structural assembly is accomplished using the assembly fixture shown on Figure 4-18. This tool provides for initial joining of main beams, intermediate beams, and the Intermediate Beam-Closure Panel Subassembly, and for the secondary structure installation. Master controlled surfaces are established. These include the Landing Gear attachment points and supporting structure. gimbal and actuating pick-ups, Ascent/Descent Separation Plane, fuel and auxiliary tank and tank skirt fittings, and RCS mounting provisions (Table 4-2, Operation 6, 7, and 8). A unique feature incorporated in this fixture is the integral track and dolly arrangement. This arrangement is provided to unload



LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963 Figure 4-18 Final Structural Assembly Fixture-Descent Stage



the fully assembled Ascent Stage from the fixture and make it accessible to inplant overhead hoisting equipment. This feature facilitates unloading and minimizes the possibility of damage during unloading by confining the movement of the assembly.

- Inspection checking fixtures (Table 4-2, Operation 9), are used to check the interchangeable areas, such as separation plane, and engine mount provisions.
- The completed Descent Structural Subsystem is transferred to the cleaning area using a GSE hoisting sling and a handling dolly. Subsequent installations are discussed in Section 5.

4.1.1.3.2 <u>Lunar Landing Gear Fabrication</u> – The Lunar Landing Gear Assembly consists of a series of welded strut subassemblies which couple the Descent Structure with the landing pads. Although a maximum of two sets are required per month, duplicate tools will not be required since the subassembly breakdown allows for fabrication using a single family of tools.

It is expected that landing gear design modifications will be essential throughout the development program. Thus, all tools will be designed with maximum consideration for removing and relocating tool components to rapidly and economically respond to these engineering changes.

4.1.1.3.3 <u>Landing Gear Outrigger Fabrication</u> – The Landing Gear Outriggers are similar to the Landing Gear in design. They are also constructed of machined parts and welded strut assemblies. The Outrigger Subassembly contains the adapter interface in addition to the Landing Gear attach points.

The basic manufacturing plans for both the Lunar Landing Gear and Outriggers are outlined as follows:

- Machine end fittings and prepare tubular sections.
- These details are joined using welding equipment and locating and clamping tooling. A series of these tools (Table 4-2, Fixture 10) are required because of the different strut configurations for each gear assembly. All equipment settings are certified for the particular application.
- All ferrous welded struts are magnafluxed and proof-load tested.
- Welded struts are located in drill jigs (Table 4-2, Fixture 11) for establishing finished hole sizes and accurate distances between the end fitting holes of each strut subassembly. Semi-portable, automatic feed pneumatic drilling equipment is used to assure consistency of quality.
- Landing Gear pad details are machined and drilled using conventional equipment and standard clamping tools. Honeycomb details are prepared and bonded to the gear pads. Bonding tools and an autoclave are used for this operation. Completed Landing Gear and Outrigger Strut Subassemblies are joined in inspection checking fixtures (Table 4-2, Fixture 12) to check overall length and to assume compatibility with the mating Descent pick-up points. The Landing Gear assemblies, including the pad, are trial mated with the Descent Structure to assure proper fit. To test functional operation, the Landing Gear is cycled from fold to open several times and the "up-lock" fit and "down-lock" action checked. The electrical circuit to firing squibs is also checked. These procedures occur during the installation phase as described in Section 5.



• Since the Landing Gear are not shipped as an integral part of the LEM, these assemblies are packaged in the transportation GSE, and are forwarded to the appropriate site after the completion of Grumman test programs.

## 4.1.2 Crew Provisions Subsystem

Grumman is responsible for fabrication and installation of panels, consoles, seats, and restraints, and for the installation of lighting, displays, and control components.

The seats, containing a number of units for achieving the adjustment requirements, consist primarily of welded tubular type subassemblies. Master gages, containing only common jig points, are used to fabricate both floor and seat tools to insure interchangeability of seat assemblies. Combination type fixtures, for welding and drill and ream operations, are provided for producing seat subassemblies. This method of manufacture, proven during previous aircraft welded seat fabrication, is the most economical procedure based on the manufacturing rate. This concept also allows for convenient replacement of seat components.

Panels and consoles are fabricated utilizing standard sheet metal construction methods. Lighting, displays, and control components are mainly purchased items. They are integrated with in-house manufactured items to complete the Crew Provisions Subsystem.

## 4.2 FLUID SUBSYSTEMS

Grumman plans for the fabrication and installation of the Ascent Stage propulsion tanks and lines are described in Section 4.2.1. Manufacture of lines for Descent Propulsion, Environmental Control, and Reaction Control Subsystems are described in Sections 4.2.2 and 4.2.3. Production testing of these components is described in Section 6. Refer to Section 1.3 for the present summary of Fluid Subsystem ''make or buy'' plans.



4 - 36

## 4.2.1 Propulsion Subsystem - Ascent Stage

The aluminum Ascent Stage flight-weight and boiler-plate fuel and oxidizer tanks and associated line assemblies will be produced at Grumman. Accurate tooling for independent detail fabrication and assembly methods will be used to maintain high reliability and to minimize hand-fitting on assembly. The fixture requirements for the flight-weight and boiler-plate tanks are listed in Table 4-3 and 4-4, respectively. Figure 4-19 shows the detailed manufacturing flow for Ascent Stage flight-weight tanks and Ascent/Descent lines.

Tank welding operations are accomplished using the gas tungsten welding process with localized shielding as shown in Figure 4-20. A radiographic inspection is performed to insure a quality weld. The tanks are pressure and helium leak tested. Following inspection, the tanks are ready for cleaning and sealing prior to final assembly.

The line assemblies will be produced from steel tubing formed on a tube-bending machine and trimmed to size. The required valves, fittings, and other purchased hardware are cleaned, positioned in a fixture, and brazed in an inert atmosphere, without flux, using an induction brazing unit as shown in Figure 4-21. The detail line assemblies are inspected, and pressure and helium leak tested prior to cleaning. The above operations will not be performed under clean room conditions since the parts are cleaned, sealed, and packaged prior to entering the assembly area.

Installation of engines and tanks to the structural subsystem and the integration of line assemblies will be performed in a better-than-standard environment, maintaining clean assembly practices. Section 5 contains a more complete description of these operations.

	T	
Part	Fixture Type	Assembly Name or Operation Description
Hemisphere	Spin Chuck Spin Chuck Spin Chuck Spin Chuck Spin Chuck	First Forming Second Forming Third Forming Upper Final Forming and Trim Lower 1/8" Full
	Expanding Die Lathe Fixture	Size I.D. at Girth Machine Trim and Cone Area
Boss	Lathe Fixture Lathe Fixture	Machine Inside of Boss Machine Outside of Boss
Mounting Cones	Lathe Fixture Lathe Fixture	Machine Inside of Mounting Cones Machine Outside of Mounting Cones
Hemisphere & Boss Sub-Assy	Weld Fixture Assy Drill Jig	Weld Hemisphere to Boss Cone Attachment
Tank Assembly	Weld Fixture	Final Joining – Girth Weld
Tank Assembly	Boring Mill Fixtures	Face Cones
	Boring Mill Fixtures	Bore Cones
	Drill Jig	Cover Attach Holes
Cap Assembly	Lathe Fixture Drill Jig Drill Jig Weld Fixture	Machine Cap Attach Holes Weep Holes Standpipe
Handling Equipment	Dollies Hoist Rig	For Transporting, Spin Chucks, Raw Material, Preforms, Hemispheres, and Spheres. In-Plant Handling.

\*See Figure 4-19 For Flight-Weight Propulsion Tank Manufacturing Flow

Table 4-3 Ascent Stage LEM Flight-Weight Propulsion Tank Fixtures


Gumman. L ⊑ M

Fixture Type	Assembly Name or Operation Description
Spin Chuck Spin Chuck Lathe Fixture	First Forming First Forming Trim
Lathe Fixture	Machine Boss
Weld Fixture	Weld Hemisphere to Boss
Weld Fixture	Final Joining- Weld at Girth
Lathe Fixture Drill Plate	Final Machining Cover Attach Holes
Lathe Fixture Drill Plate	Machine Cover Cover Attach Holes
Dollies Hoist Rig	For Transporting Spin Chucks, Raw Material, Preforms, Hemispheres, and Spheres. In-Plant Handling
	Lathe Fixture Veld Fixture Veld Fixture Lathe Fixture Drill Plate Lathe Fixture Drill Plate



## DESCENT TANKS (TITANIUM)

Receive Descent Stage Titanium Tanks From Vendor; Inspect and Test.



LPL-850-1 ''A'' 14 May 1963







Figure 4-19 Manufacturing Flow Diagram-Ascent/Descent Lines & Ascent Tanks








LPL-850-1 "A" 14 May 1963 Revised 14 Oct. 1963







# 4.2.2 Propulsion Subsystem - Descent Stage

As shown in Figure 4–19, the Descent Stage titanium tanks will be "vended" items. The fabrication of line assemblies and the subsequent integration of engine, tanks, and line assemblies into the structural subsystem is similar to that described for the Ascent Stage in Section 4.2.1.

#### 4.2.3 Reaction Control and Environmental Control Subsystems

The titanium-helium pressurization tanks required for the Reaction Control Subsystem will be "vended" items. Line assemblies for the Reaction Control and Environmental Control Subsystems are Grumman "make" items. Production methods similar to those described for the Ascent Stage lines in Section 4.2.1 will be used. Integration of the line assemblies, tanks, and vendor supplied Reaction Control and Environmental Control components into the Structural Subsystem will be performed under controlled clean room conditions. A product conforming to the required degree of reliability and cleanliness will thus be assured. Refer to Section 5 for a complete description.

#### 4.3 ELECTRICAL/ELECTRONIC SUBSYSTEMS

Manufacturing plans for in-house fabrication and integration of Electrical Power Subsystem line assemblies, and for fabrication of antennas and subsequent installation of these antennas and vendor supplied Communications Subsystem components into the Structural Subsystem are described in Section 4.3.1 and 4.3.2. Grumman will also fabricate the network control panels for attitude reference/control coupling electronics, and will integrate the critically positioned Navigation and Guidance and Stabilization and Control



Subsystems into the module as described in Section 4.3.3. Production testing of Electrical/Electronic Subsystem components is discussed in Section 6.

Refer to Section 1.3 for a summary of "make or buy" plans.

#### 4.3.1 Electrical Power Subsystem

The Electrical Power Subsystem fuel cell will be supplied by Pratt & Whitney. The line and valve subassemblies required to join the cryogenic tanks to the fuel cells will be manufactured at Grumman. Production methods and subsequent integration of these line assemblies into the Structural Subsystem will be similar to that described in Section 4.2.1.

# 4.3.2 Communications Subsystem

Grumman is responsible for the manufacture and subsequent installation of two types of VHF-LEM/CM antennas. The helical-type antennas are produced by wire winding methods, very similar to the techniques used in the fabrication of tension or compression springs. The conical-type antenna consists of a wire winding on the exterior of a fiberglass cone. The cone detail is manufactured by laying-up fiberglass over a male molding form. This cone is drilled and trimmed to size after a vacuum bag and oven curing operation. A wire-winding applied to the exterior of the cone completes the antenna assembly.

These antenna assemblies, and the vendor supplied communications subsystem components are installed into the Structural Subsystem. An interwiring operation completes the Communications Subsystem installation.

#### 4.3.3 Navigation and Guidance and Stabilization and Control Subsystems

Grumman will fabricate the network control panels for attitude reference/control coupling electronics, using standard sheet metal construction methods, and will integrate the N & G and S & C Subsystems into the module. Grumman will also be responsible



for alignment and functional testing of the critically positioned Inertial Measurement Unit, Scanning Telescope, and Radar Antenna components of the N & G Subsystem, and the functional testing of the S & C Subsystem components.

The alignment and functional testing of the critically positioned N & G and S & C Subsystems components will be performed in one common fixture utilizing a precision air bearing indexing table. The accuracies required may be achieved only through the use of optical tooling techniques. The precision indexing system requires fewer pieces of optical equipment, a smaller structure, and a more compact design which alone suggests lower initial costs. Simplicity of operation and the use of the precision indexing table as a positioning stand for the Radar Antenna Test Range will definitely contribute to lower operating costs in performing the module alignment and functional testing operations. Alignment and functional test procedures are described in Section 5.4.



SECTION 5 - Final Assembly

# SECTION 5 FINAL ASSEMBLY


#### 5.1 FINAL ASSEMBLY DESCRIPTION

Final assembly operations will begin with the cleaning of the Ascent and Descent Structural/Mechanical Subsystems and continue through all subsystem installations, interwiring, external ascent skin panel installations, ascent/descent mating, final installations, and optical alignment of critically positioned subsystem components. Production tests will be integrated throughout these operations as described in Section 6. Maximum utilization of GSE will be made during the final assembly phases since a capability for performing the majority of these tasks will also be required at various field-site locations. For economy, all handling GSE fabricated specifically for the in-house manufacturing cycle will not necessarily conform to military specifications for outdoor environmental conditions, transportability, special hardware and fittings, etc.

Figure 5-1 shows the basic installation, joining, and alignment flow up to the beginning of the test program for the complete module.

#### 5.2 FINAL ASSEMBLY AND SUBSYSTEMS INSTALLATIONS - ASCENT STAGE

Prior to partial installations in the existing Grumman "clean room", the Ascent Structural/ Mechanical Subsystem received from the subassembly manufacturing area will be cleaned using tumbling, vacuum, and possibly exterior washing methods. Tumbling for removal of trapped particles will be accomplished using a cleaning fixture which will be a duplicate of the NAA/CM apparatus or a modification thereof. After cleaning, the Ascent Structure will be secured to a GSE handling dolly for entrance into the clean room.



shop environment and maintained as a clean installation & test facility.

Figure 5-1. Installation, Joining and Alignment Flow



LPL-850-1 ''A'' 14 May 1963 Revised 14 Oct. 1963

All tests and installations for the Environmental Control, Electrical Power, and Reaction Control Subsystems must be performed under controlled environmental conditions. A 5000-square-foot area within the 8900-square-foot Plant 5 clean room manufacturing and test facility is presently planned for these LEM requirements. Adequate Plant 5 clean room area will be available for both the LEM Program and the NASA/OAO Spacecraft installations, alignment, and tests which will continue in this facility.

As a continuation of the OAO policy, the Class II clean room, which is temperature, humidity, and particle size controlled, will be staffed with technically competent manufacturing personnel who also possess demonstrated orderliness and cleanliness work habits. Personnel who participated in establishing the OAO clean room manufacturing program will be utilized to a maximum extent in the LEM Program so that the benefits of experience will be derived in the areas of tool and handling equipment design concepts, cleaning and packaging process applications, efficient clean room area arrangement, as well as optimum manufacturing, installation, inspection, and testing techniques.

Constant monitoring and surveillance of work area cleanliness levels, housekeeping standards, incoming parts and tools, cleaning methods and media, and personnel work habits will maintain and assure performance within established cleanliness standards.

All Environmental Control, Electrical Power, and Reaction Control Subsystem components will be completely integrated and sealed prior to removal of the Ascent Stage from the clean room. Induction brazing techniques will probably be used for the installation of all line assemblies.

The Propulsion Subsystem and other subsequent installations do not presently require the degree of clean room control as described for the two previous subsystems. However, Grumman plans to allocate a LEM area directly adjacent to the clean room, which will be a better-than-standard shop environment and maintained as a clean installation and test facility.


One of the initial operations in this facility will be the installation of the ascent engine; fuel, oxidizer, and helium tanks; and associated line assemblies. This station will consist of a GSE holding fixture and workstand, GSE engine mating fixture, hoisting provisions, and an induction brazing unit. All integration of the tanks, valves, engine and line subassemblies will probably be accomplished using induction brazing methods for maximum reliability and cleanliness.

5 - 4

Since the Structural Subsystem engine pick-up points will be master controlled and jig located during the final structural assembly phase, only an optical alignment check of engine position relative to the ascent separation plane will be required. A boresight reference gage will be inserted in the engine nozzle and set to the center line of thrust established from engine mounting faces and pickup holes. Portable tooling bars and optical transit squares will be used to set the mirror reference.

Upon completion of the ascent engine installation, an optical check will be made between the engine boresight reference gage and the Ascent/Descent Stage interface hard points. If misalignment is indicated, the engine position must be corrected in this station. An indexing cube and electronic leveling device will be oriented to the thrust center line and fixed to the top of the Ascent Stage. The indexing cube and electronic leveling device will serve as the optical reference for all future alignment and functional testing of the Navigation and Guidance, and Stabilization and Control Subsystem components as described in Section 5.4.

Other subsystems such as Crew Provisions and Displays, Stabilization and Control, Electrical Power, Communications and Instrumentation will be installed and interwired in the engine mating and a subsequent handling station. A sequence flow for these subsystems has not been established. The installation of the Navigation and Guidance Subsystem is shown in Section 5.4.



Fastening of Ascent Stage exterior skin panels and insulation will also be accomplished in the handling station. After final inspection and test, the Ascent Stage will be joined to the Descent Stage as described in Section 5.4

#### 5.3 FINAL ASSEMBLY AND SUBSYSTEM INSTALLATIONS - DESCENT STAGE

All final operations for the Descent Stage can be performed in the LEM installation and test facility which will be located directly adjacent to the clean room. As previously mentioned, this area will be a better-than-standard shop environment. Clean assembly practices will also be maintained for the Descent Stage.

The completed Structural Subsystem will be cleaned after receipt from the subassembly manufacturing area. Vacuum and manual washing methods will be used. The tumbler method may also be used, pending further study of cleaning requirements. For this report, tumbler cleaning has been included in the Figure 5-1 flow diagram.

A Descent Propulsion Subsystem installation fixture, similar in design to the ascent station, is provided for joining the structure, engine, fuel, oxidizer, and helium tanks; as well as associated line and valve subassemblies. All connections will probably be induction brazed. A minimum of structural fabrication will be required since the Descent Stage, tanks, and engines are planned as interchangeable units. The positional relationship of the engine and descent separation plane is checked using optical methods. As described for the ascent engine, a boresight reference gage will be inserted in the nozzle of the descent engine and set to the center line of thrust established from engine mounting faces and pick up holes. Portable tooling bars and optical transit squares will be used. The center line of thrust established will be for a cold engine and may change due to engine firing and corrosion of the nozzles. An attempt to determine the extent of deviation will be made during future test firings of the engines, and corrections made if necessary.

5-5

An optical check will be made between the engine boresight reference gage and the Descent Stage interface hard points after engine installation. If misalignment is indicated, engine position must be corrected in this station. The mirror reference will also be used in the Manufacturing Alignment and Functional Test Fixture, described in Section 5.5, to check the orientation of the descent engine to the indexing cube fixed to the top of the Ascent Stage.

Other components such as the supercritical oxygen and scientific equipment will be installed in the engine mating and a subsequent handling station. Final operations will include the fastening of insulation and some skin panels. To assure proper fit and operation, the Lunar Landing Gear will be trial mated to the Descent Stage and cycled in the engine mating station.

# 5.4 ASCENT/DESCENT JOINING AND CRITICAL SUBSYSTEM ALIGNMENT

The Ascent and Descent Stages, less Landing Gear, will be mated in a GSE handling dolly. Compatibility of the separation plane between the two stages will be checked and final interwiring will be performed.

The LEM will be transferred to a Manufacturing Alignment and Functional Test Fixture (Figure 5-2) for installation and alignment of critically positioned Navigation and Guidance Subsystem components such as the inertial measurement unit, radar antenna, and scanning telescope.

As shown in Figure 5-2, the LEM will be installed on the precision air-bearing indexing table of the alignment fixture. Jig points will be provided to obtain an approximate location. The module will be leveled using the three jacks provided under the module mounting ring and the electronic leveling unit fixed to the top of the Ascent Stage. The ascent engine center line of thrust and the faces of the indexing cube will be parallel to the axis of table rotation and "gravity vector".

Grumman L E M




Figure 5-2. Manufacturing Alignment and Functional Test Fixture



The optical transit square provided for indexing will be collimated to the indexing cube. The optical transit square will be dumped and collimated to another optical transit square located on tooling bar "A". Through the use of a theodolite and additional optical and telescopic transit squares, all control lines of sight may be established.

The Radar Antenna mirror reference gage will be installed on the antenna mounting surface. This Radar Antenna mount will be adjusted until the optical transit squares are collimated to the mirror references and locked in position.

An Inertial Measurement Unit (IMU) mirror reference gage will be installed on the IMU isolation mount with stainless steel inserts attached. This isolated mount will serve as a common mount for the IMU and the Scanning Telescope (SCT). The weight and cg location of the mirror reference gage should correspond with that of the actual IMU and SCT components. This requirement must be met to eliminate possible "slumping" of the isolated mount and to achieve the required accuracies. The mirror reference gage will be adjusted until it is leveled out and the optical transit square will be collimated to the mirror reference reference. A plastic shim will then be poured around the stainless steel inserts to maintain their proper orientation.

Connections between the Ascent and Descent Stage will then be released. Collimation of the optical transit squares to the mirrors on the IMU, Radar Antenna, and Descent Engine mirror reference gages will be checked. If excessive deviations are noted, shims may have to be used to minimize the "racking" of the structure during the mating operation. If shims are required, the alignment procedure must be repeated.

The IMU and Radar Antenna mirror reference gages will be removed and the two units installed per specifications. The SCT will be placed on its mount and the SCT mirror reference gage will be installed. The SCT mount will be adjusted until the optical transit squares are collimated to the mirror references and locked in position.

5-8

In addition to functional testing of the Navigation and Guidance Subsystem, the close tolerance positions of the Reaction Control Engines required for stabilization and control, must also be checked in the fixture. These functional tests will be accomplished in four table indexing positions as described below:

- The initial indexing position, used for the aligning operations, will also be used to functionally check the gimbal axis of the Radar Antenna, and the shaft and trunnion axes of the SCT. These axes must be coincident with the Radar Antenna gimbal axis, as the SCT will be used to slave the Radar Antenna for acquisition. The location of one TCA cluster of Reaction Control Subsystem engines may also be checked in the initial indexing position. A gage containing a boresight reference mirror will be inserted into the nozzle of two of the engines. Collimation of the optical transit square to the mirror on the gage will be checked. The vertical line of sight to the boresight reference mirror on the engine cluster will be established with a plumbing mirror. Collimation of the alignment telescope to the boresight reference mirror on the gage will be checked to determine the amount of error. If engine assembly is out of tolerance, corrections must be made and location rechecked at this time. This procedure will be followed for all Reaction Control System engine assemblies. The location of the Descent Engine may also be checked to the indexing cube at this position using the mirror reference gage and an optical transit square.
- For the second index position, the table will be rotated 90 degrees clockwise, controlling the table position with the indexing cube and electronic leveling device and the optical transit square provided for indexing. The location of the second TCA cluster of Reaction Control Subsystem engines may then be checked. Note that instrument alignments will not be changed from the initial index position to accomplish this measurement.

LPL-850-1 "A" 14 May 1963



- For the third index position, the table will be rotated 90 degrees clockwise, controlling the table position as noted above. The location of the third TCA cluster of Reaction Control Subsystem engines may then be checked. Procedures and instrumentation alignments will remain the same as those of the preceding index position. The functional testing of the Radar Antenna on the range will also be accomplished in the third index position. It may be performed then or after the fourth TCA cluster of Reaction Control System engines have been checked.
- For the fourth index position, the table will be rotated 90 degrees clockwise, and the location of the fourth TCA cluster of Reaction Control Subsystem engines checked. Procedures and instrumentation alignments remain the same as those for the preceding index position.

Functional testing of the complete Navigation and Guidance Subsystem will also be accomplished in the fixture. Once the module equipment has been aligned, functional testing of the subsystem will be performed. This will be accomplished by rotating the precision indexing table until the IMU is aligned on a due North-South line. This point will be coincident with one of the four indexing positions. Utilizing optical instrumentation on the tooling bars, the IMU can be displaced to any angular position with a high degree of accuracy, permitting calibration of its outputs.

To repeat this procedure at other sites, the IMU mirror reference gage will be used to locate the module to the orthogonal axis of a fixture oriented to a due North-South line by jacking and rotating a positioning table. An optical transit square and a level on the IMU mirror reference gage will be used to control table position.

The manufacturing alignment and functional test operations discussed herein represent the completion of the LEM manufacturing phase. LEM Manufacturing Team support during the Ground and Flight Test Programs is described in Section 6.5.

14 May 1963

SECTION 6 - Manufacturing Test Program

#### SECTION 6

## MANUFACTURING TEST PROGRAM

#### 6.1 DESCRIPTION AND IMPLEMENTATION

Satisfying the LEM mission reliability objectives requires strict conformance with the detailed test plans and specifications, constant surveillance of the test equipment used for manufacturing test, and the utilization of highly trained teams of test technicians.

All testing will meet maximum reliability requirements and Grumman test specifications. Test data will be logged for maintaining complete records of an individual component and supplier.

As described in Section 7.1.1, the test equipment must be continuously monitored for assurance of optimum equipment performance. Thus, periodic calibration and maintenance operations are scheduled using an "IBM alerting system".

Consistent with the manufacturing approach, test program plans emphasize the use of manufacturing test technician teams identified with each LEM. Each team member is also responsible for a given subsystem. This procedure allows for achieving a high experience level, which is vital to the LEM manufacturing test program. Manufacturing test technicians will perform testing of components and subsystems, and will support all Ground and Flight Test Programs. Specimens, models, and components will be produced for development testing, and assistance will be provided to the Engineering Department for conducting these tests.



Manufacturing test technicians will also participate in the development, reliability, qualification, and acceptance test programs, as well as assure the orderly flow of subsystems and components to maintain test schedules and checkout requirements. Planning and scheduling procedures will be flexible to absorb changes which will be generated by development test programs.

Ground and Flight Test Programs established by the Engineering Flight Test Departments will be supported by manufacturing test technicians. This effort will be coordinated and supervised by the LEM Structural/Mechanical Test Leader who will work with Manufacturing Planning, Quality Control, and Engineering. His tasks will include witnessing, monitoring, and assisting in the documentation of tests performed on his assigned module. In addition, the Structural/Mechanical Test Leader and his team of technicians will assist in implementing the failure analysis corrective cycle and will support the off-site test program operations.

Prior to the beginning of any manufacturing test program, the Quality Control Department will assure conformance with the following requirements:

- Materials and processes used in all previous fabrication operations are in accord with the applicable specifications.
- Fabrication and inspection operations performed previously have been performed by properly trained and certified personnel and equipment.
- Test facilities and equipment have been evaluated for adequacy.
- Visual and operational inspection and checkout of a unit to be tested has been satisfactorily accomplished to applicable specifications and procedures.
- Test equipment and instrumentation to be used has been properly and currently calibrated.





- Parts and materials have been inspected and personnel have complied with the proper cleanliness procedures.
- Detailed Test Plan to be used has been reviewed and approved.

During all test programs, Quality Control will provide the following assurances:

- Tests are conducted in accordance with the specified test procedures.
- Adequate and accurate documentation including data sheets and test logs, is maintained throughout the test program.
- Tests are halted when any deviation from the test procedure is noted. In the event of a failure, an analysis is conducted, corrective and preventive action incorporated, and proper documentation and notification instituted.

# 6.2 MANUFACTURING TEST - STRUCTURAL/MECHANICAL, AND CREW PROVISIONS SUBSYSTEMS

This report section describes the manufacturing test approaches for the Structural/Mechanical Subsystem and the Crew Provisions Subsystem.

# 6.2.1 Structural/Mechanical Subsystem

The testing of the Structural Subsystem starts with the manufacture and testing of specimens and sections of the Structure and continues through the assembly period. A structural/mechanical technician will work full time during the assembly of a module to assure the timely and smooth flow of structural elements through acceptance testing into the assembly sequence, to assure the integrity of the subsystem, and to provide quick reaction to incorporation of design changes at the proper time in the assembly sequence. The structural/mechanical technician will become the LEM Team Leader when subsystems integration begins. As previously mentioned, he is also responsible for the supervision of the Manufacturing Team throughout the Ground and Flight Test Program for a specific module.

The testing of the Lunar Landing Gear will start with the construction of a 1/6-scale Landing Stability Model and Transitional Drop Test Rig. Various arrangements of Landing Gear and honeycomb shock absorber combinations will be set up and tested.

A honeycomb development test program will be conducted. The necessary test fixture will be constructed and maintained by manufacturing test and instrumentation technicians for this program.

Fittings and major components will be tested to qualify the design reliability. A prototype tripod will be made and tested prior to the testing of the complete subsystem. Subsequent vacuum and drop testing will continue through the LTA Program. This test program will be coordinated by the manufacturing test technician who is responsible for the Landing Gear Subsystem.

## 6.2.2 Crew Provisions Subsystem

Manufacturing test and instrumentation technicians will assist Engineering set up and conduct tests in support of the Crew Provisions Subsystems Test Plan; seat testing and occupant restraint, as well as seat support and lighting will be included. Additional test support will be maintained while other provisions are being tested by demonstration in mock-ups.

Grumman LEM

Crew provisions testing will be conducted in the Structural and Lighting Test Laboratories and in the Environmental Test Center, Manufacturing technicians working with Engineering, Planning, and Quality Control will conduct, witness, and assist in the documentation of tests to qualify all components of the Crew Provisions Subsystem.

#### 6.3 MANUFACTURING TEST - FLUID SUBSYSTEMS

This report section describes the manufacturing test approaches for the Reaction Control, Propulsion, and Environmental Control Subsystems.

# 6.3.1 Reaction Control and Propulsion Subsystems

Manufacturing test requirements of the Reaction Control and Propulsion Subsystems are primarily the same, and will be comprised of non-firing or "cold flow" tests to permit the exercise of the systems electrical or continuity checks, as well as pressure and leakage checks. These test programs will be conducted at three levels:

- Component Propellants and helium.
- Section Propellant feed and helium pressurization.
- Subsystem Integratrated helium pressurization and propellant feed.

# 6.3.1.1 Component

Propellant tests will include a visual inspection for conformance to the Specification Control Drawings and leakage and functional tests on referee propellant flow benches. Hydrostatic proof pressure checks will be performed for all propellant tanks.

Helium tests will also include visual inspection and hydrostatic proof pressure tests of each helium tank. Leakage and functional tests or helium flow benches will be performed using helium leak detectors. If the helium pressurization section requires grouping of specific components into isolated modules, the module will be tested as a whole.

6.3.1.2 Section

Propellant feed (also helium pressurization) will require visual inspection for conformance with Configuration Design Drawings. Leakage and functional tests will be performed where possible through ground test connections using high pressure gas, leak detectors, instrumentation, and external or module controls.

6.3.1.3 Subsystem

Integrated propellant feed and helium pressurization testing will be accomplished using procedures identical to those previously described for Section testing. After completion of the test program, the subsystems will be purged, pressurized, and sealed.

The test programs for the Reaction Control and Propulsion Subsystems will utilize GSE/STE such as component test stands, propellant storage and temperature conditioning units, stage structures for hot firing, purge and flush units, as well as instrumentation and control consoles. This test equipment will be maintained and calibrated periodically to insure accuracy and cleanliness. Quality Control will monitor all test phases for assurance of test reliability.

#### 6.3.2 Environmental Control Subsystem

Because of the extreme cleanliness requirements associated with the Environmental Control Subsystem, all Grumman tasks for this subsystem, including manufacturing testing, will be performed in a Class II clean room area.

The subsystem will be inspected when received from Hamilton-Standard to insure dimensionally correct components. The subsystem will also be functionally tested. Parameters



to be monitored include, but are not limited to, pressure drop at rated flows, proof pressure, leakage, response to stimuli, and power.

The subsystem will be installed in the LEM and a performance verification test performed. This test will insure that the installed subsystem is performing within its proper design envelope.

# 6.4 MANUFACTURING TEST - ELECTRICAL/ELECTRONIC SUBSYSTEMS

This report section describes the manufacturing test approaches for the Electrical Power, Communications, Instrumentation, Displays and Controls, Stabilization and Control, and Navigation and Guidance Subsystems.

# 6.4.1 Electrical Power Subsystem

The Electrical Power Subsystem requires both electrical and fluid manufacturing test programs. Since the electrical test procedures are primarily the same as those described in Section 6.4.2, only the fluid test plans are described herein.

The fluid manufacturing testing will be conducted on the following three levels:

- Component Fluid storage and supply.
- Section Fluid storage and supply and energy conversion package.
- Subsystem Integrated fluid storage and supply and energy conversion package.

All test phases will require a visual inspection for conformance to the Specification Control Drawings and the Configuration Design Drawings. All components will be purged and prepared for shipment to subsequent areas. Sections and Subsystems will be purged, pressurized with inert gas, and sealed after the completion of test phases.



# 6.4.1.1 Component

Fluid storage and supply will require leakage and functional tests on cryogenic reactant flow benches. The fluid storage tanks will require a supply of liquid reactants for loading and thermodynamic tests.

#### 6.4.1.2 Section

Fluid storage and supply will include leakage and functional tests using a supply of liquid reactants, gaseous reactants, external or module controls, leak detectors, and instrumentation.

Energy conversion package will be tested for leakage and functional operation using a gas supply system, electrical loading equipment, leak detectors, instrumentation, and controls.

# 6.4.1.3 Subsystem

Integrated fluid storage and supply and energy conversion package will be functionally and leak tested using a liquid reactants supply, a gaseous reactants supply, leak detectors, instrumentation, module or external controls, and loading equipment.

6.4.2 Communications, Instrumentation, Displays and Controls, Stabilization and Control, and Navigation and Guidance Subsystems

The basic manufacturing test plans for all LEM Electrical/Electronics Subsystems are similar. Therefore, all test approaches will be discussed as a whole. This basic test plan is discussed in the following three phases:

- Receiving tests of incoming components and subsystems.
- Assembly and integration testing during manufacturing build-up.
- Acceptance testing of the complete module.



### 6.4.2.1 Receiving Tests

The bench test station is a receiving test facility where subsystems, assemblies, and units shipped by the vendor as qualified units are verified upon receipt at Grumman. It will be designed for semi-automatic operation with manual control and will be capable of fault isolating to a replaceable element and rechecking a subsystem after repair or modification.

The bench test station will be capable of testing subsystems and simulating any interface with other subsystems. This station will verify all the subsystems operational parameters. It will check out the PACE test functions and the ability of PACE data to check out the subsystem. Simulated failures will be made in this manner. Where redundant paths exist, sufficient tests will be performed to assure their operating conditions.

An understanding of operation between the several test stations will develop by using standard electronics test equipment and test techniques. The test equipment complexity will be minimized, consistent with the type of test required, and the designs will permit maximum expansion capabilities to include new tests using the same equipment where possible.

6.4.2.2 Assembly and Integration Tests

The assembly and integration (A&I) test stations' function will be to test the subsystems during manufacturing build-up of the LEM. The approach to testing will be in building block fashion to enable a unit to be installed and checked out for operational parameters, a second unit installed and checked out, and the two units mated for an operational check on the integrated package. This technique will be used up to the complete integration of all subsystems.

The A & I test station will be capable of checking all operational parameters of each unit, assembly or subsystem, as it is installed. It will check out those PACE functions included in the unit, assembly, or subsystem, with or without the mating interfaces. It will accomplish checkouts via the PACE data. The A & I test stations will do end-to-end testing, and will verify redundant signal paths and interface signal paths. To keep the complexity of testing and training to a minimum, and to allow for maximum expansion of testing and utilization of personnel, standard electronic test equipment and techniques will be used where possible. Self-checking features will be designed into the equipment where possible.

6.4.2.3 Acceptance Tests

The final acceptance test phase will begin when the subsystems have been integrated and tested for proper interface and performance.

The PACE test equipment will be connected to the complete module and acceptance testing initiated. The function of PACE will be the checkout of the operational parameters of the LEM via the PACE data lines.

The PACE equipment will stimulate the several subsystems, measure the response, and compare it with the required answer. In the event of a failure, the PACE will be programmed to trace the source to a section (a group of components). The faulty component will be replaced and the tests affected will be repeated.

The documented test results and histories are sent to Reliability where the various factors can be determined for reliability analysis concerning mission safety and success.

# 6.5 GROUND AND FLIGHT TEST PROGRAM SUPPORT

The manufacturing team will support the LTA Ground Test and LEM Flight Test Programs during all phases of test and launch activities. The following functions will be performed:

- Rocket engine and fuel handling personnel will be engaged in the performance of flow tests and hot firings for the Propulsion and Reaction Control Subsystems at WSMR.
- Manufacturing test teams will participate in the static, drop, environmental, and vibration tests at Grumman.
- Manufacturing and instrumentation technicians will erect test equipment, install instrumentation, conduct, witness, and document the tests required by the Engineering Test Plan.
- Follow the LTA's and LEM's through checkout and acceptance phases and proceed to off-site facilities as described in Section 8.
- Provide the proper planning and scheduling functions to maintain the continuity of tests.
- Assure orderly replacement of parts and components during the test programs.
- Operate, maintain, and calibrate all GSE/STE both at Grumman and at field-site locations. Personnel will also repair and modify the GSE/STE as required.

Gumman LEN

Section 7

SECTION 7 - Manufacture of GSE/STE



# <u>SECTION 7</u> MANUFACTURE OF GSE/STE

# 7.1 GSE/STE MANUFACTURING PLAN

LEM Ground Support Equipment and Special Test Equipment requirements are divided into the four general classifications: Handling and Transportation Support Equipment, Fluid Systems Support Equipment, Electronic Support Equipment, and Training Equipment. This report section describes the present manufacturing plans for GSE/STE. The GSE designs and utilization are not included since these descriptions are shown in the GSE Planning and Requirements List.

The plan described herein is for items which will be manufactured at Grumman. "Make" items are based on a logical extension of the company's existing capabilities and experience. Further "make or buy" decisions will also be influenced by critical GSE/STE schedule requirements which dictate in-house manufacture to maintain these schedules.

A "buy" decision will result in the provision of a specification which will accompany the requests for competitive vendor quotations. The resulting proposals will be evaluated and a subcontractor selected.

Close monitoring of the selected subcontractor, as described in Section 3.3.4, shall be maintained throughout the program. Concurrent with the subcontractor effort, test specifications will be originated by Grumman. Maintenance and calibration procedures will be developed upon completion of the GSE/STE, and the equipment will be tested at the vendor location in accordance with the test specification. Equipment will be inspected upon receipt at Grumman.



The GSE/STE Manufacturing Plan emphasizes the use of existing Avionic, Hydraulic, Tool, and Test Equipment shops which are presently organized with the specialized skills, equipment, and facilities. Grumman facilities for GSE/STE fabrication are described in Section 2.1.8.

Although many equipment types are required, production line or completely centralized facility concepts are not warranted since the manufacturing rate for each unit is minimal. Consequently, the GSE/STE plan affords the advantages of optimum flexibility for low-rate manufacturing through the use of existing skills and facilities.

The planning, scheduling, and manufacturing flow for all LEM GSE/STE is shown in Figure 7-1. For continuity and maximum efficiency, GSE/STE manufacturing planning, scheduling, and program control will closely parallel the procedures described for the LEM Manufacturing Program (Sections 3.1, 3.2, and 3.3). Familiarity with one system is especially desirable since some common shop departments are used for both LEM and GSE/STE manufacturing. Although the Test Equipment Shop is primarily concerned with only GSE/STE manufacturing, closely related concepts are applied.

In general, the following procedures summarize the implementation plan for all in-house GSE/STE manufacturing:

- LEM Subsystem GSE Engineers for the Fluid, Electronic, and Handling/ Transportation equipment develop and are responsible for the completion due dates of all equipment.
- Corporate LEM scheduling or planning representatives provide assistance for determining the GSE/STE manufacturing lead-times. These groups also maintain detailed manufacturing schedules and charts for measuring GSE/STE progress, shop workload, and manpower forecasts.
- Purchased GSE/STE component requirements are determined by the LEM Subsystem GSE Engineers and procurement requests are forwarded to the Purchasing Department.

7 - 2




Figure 7-1 GSE/STE Planning & Manufacturing Flow

- Work Authorization Statements are required for all tasks and must be approved by the cognizant corporate supervisor and/or LEM representative.
- Electronically processed expenditure reports, prepared and distributed by the Accounting Department, are used for the accumulation of all cost monitoring data. Cost control will be accomplished in accordance with the future requirements of the PERT Companion Cost System.

Items and quantities of items which will be used as GSE are listed in the 'Ground Support Equipment Planning and Requirements List', LLI-400-1, dated 18 March 1963. This listing is not repeated herein.

# 7.1.1 Electronic GSE/STE

Electrical/Electronic GSE/STE for manufacturing tests or for site delivery is fabricated in the Grumman Test Equipment Shops and the Avionic Shop Departments. In-house fabrication generally implies the manufacture of wiring harnesses, panels, cabinets, and chassis. In addition, Grumman performs the subassembly, assembly, installation, functional testing, calibration, and maintenance operations. Electronic components are usually "buy" items.

The Test Equipment Shops and the Avionic Shop Departments have produced reliable test equipment ranging from resistance measurement units to sophisticated equipment used for testing highly complex computer systems. These shops utilize the latest tools and techniques, and are able to draw support from development groups when new techniques must be applied.

The engineer responsible for the design of a piece of test equipment also prepares an acceptance test, maintenance, and calibration manual. This manual will enable criteria to be established for quality control acceptance prior to release for the production test phase.

The maintenance and calibration portion will establish the servicing intervals and supply information for the performance of calibration operations. Once the interval of maintenance is established, an IBM card is cut and fed into the Grumman equipment cycle which automatically notifies the calibration and maintenance personnel when it is time to service the equipment. In this way Grumman is able to maintain high confidence in its production test equipment.

The sample "Preventive Maintenance Procedure Sheet" shown in Figure 7-2 provides detailed instructions for all equipment maintenance operations. This sheet is also used to initiate the IBM "service interval alerting system".

#### 7.1.2 Fluid Systems GSE/STE

The development of Fluid Systems GSE/STE begins with the receipt of detailed test parameters from the appropriate subsystem engineer. These test parameters are then collated and used to generate a series of specifications for the required test equipment. These specifications thus generated will include interface documentation. Upon approval of the specifications by NASA, when required, the test equipment will be submitted for a ''make or buy'' decision. ''Make or buy'' determinations are discussed in Section 7.1.

A "make" decision will initiate an in-house design effect and the concurrent development of a detailed manufacturing schedule in conjunction with the LEM Test Equipment and Process Engineering Fabrication Coordinator. During the design phase, there will be continuous review to insure compliance with applicable specifications, including a reliability check. Toward the latter phase of the design effect, test equipment fabrication will be initiated.

Primary manufacturing responsibility for all Fluid Systems Support test equipment has been assigned to the Test Equipment and Process Project Engineer. The Test Equipment Shop, which is the primary shop for Fluid System test equipment, is supported by other shops for heavy structural fabrication of frames and trailer components. The LEM GSE/STE Fabrication Coordinator maintains constant liaison between support shops, Fluid Systems Support Engineering, and the Purchasing Department to provide the Test Equipment Shop with all information necessary for satisfactory and timely fabrication completion.

·		NO. 20167
Nam		EQUIPMENT DESCRIPTION       Issue Date         Vacuum System       Mode       L-DW410-100         No       Date
		turerGAEC ModelNo. Date
FREQ. CODE		
CODE	1.0	Scope
	1.1	This procedure covers electrical, electronic, and mechanical inspection of the
		vacuum chamber in plant 23.
	2.0	Special Equipment Req'd.
	2.1	None
	3.0	Instructions
04	3.1	Check all relays, coils, contacts and mechanical parts. Repair or replace def tive components.
	3.2	Check all electrical connections for tightness.
12	3.3	Clean, lubricate and calibrate electronic temperature recorder as per calibrati procedure 256000-03.
	3.4	Check ionization amplifier.600P tubes should be returned to original tube socke
	ETC.	
	ETC.	

Figure 7-2. Preventative Maintenance Procedure Form

Maintenance, calibration, and checkout procedures are developed concurrently with the design and fabrication phases. Functional checkouts will be performed after completion of fabrication.

#### 7.1.3 Handling and Transportation GSE

This category of GSE includes all of the equipment required to handle and transport the LEM and its stages plus associated equipment (e.g. work stands, mating fixtures, and special tools).

Since the prime purpose of this GSE is to protect the LEM from excessive loads and other damage during all handling operations, the majority of this equipment is ruggedly constructed of fabricated sheet and structural members. The GSE manufacturing facility within the tool shop organization is particularly well suited for this type of GSE because of heavy equipment availability. In addition, specially skilled tool shop personnel are completely familiar with heavy structural fabrication. The Tool Shop GSE facility is described in Section 2.

LEM Program schedules require the concurrent fabrication of GSE and the LTA Ground Test Modules. This factor, and the low rate of GSE manufacture requires a manufacturing approach which is adjusted for "experimental shop" methods. The tool shop personnel are particularly adaptable to prototype concepts since they are accustomed to "one-of-a-kind" tool manufacture.

Past Grumman experience indicates that this method provides the earliest possible GSE availability, and enables the incorporation of design refinements in sufficient time to reflect usage data into the first off-site deliveries.

The prototype equipment will serve as a model for the follow-on units. Minimum tooling for reduced over-all GSE costs will be provided after the prototype units have been proven.

Gumman LEM

The final operations for the Handling and Transportation GSE are qualification, test, and acceptance. These operations are performed within the structural test, instrumentation, and environmental test laboratories. All tests and inspections are performed in accordance with the applicable specifications.

# 7.1.4 Training Equipment

The LEM Training Equipment Program has not been sufficiently defined to permit a manufacturing analysis. Therefore, the approaches developed for previous aerospace "maintenance trainer panel or test bench" programs are described herein.

Training equipment which serves as a visual aid of operating systems, usually simulates or in most cases duplicates the operational systems. Therefore, this type of GSE is assembled in the same shop departments which integrate the systems in the aerospace product. Thus, full advantage is taken of the manufacturing experience factor. These procedures are also planned for LEM training equipment which is scheduled for in-house manufacture.

The benches and equipment chassis or mounts are fabricated in shops which are equipped for sheet metal fabrication. These items are routed to the Avionics or Hydraulics Shop Departments for equipment installation and assembly. Calibration and qualification or acceptance tests are performed in the equipment shops or specialized laboratories.



SECTION 8 - Field Site Support

# SECTION 8 FIELD SITE SUPPORT

# 8.1 TEST AND LAUNCH SITE ACTIVITIES

The Grumman concept for providing a "Team of Manufacturing and Manufacturing Test Technicians identified with each LTA and LEM" will begin during subsystem acceptance, and will continue through the launch of the Apollo System. Field-site operations support, which is considered a continuation of on-site activity, will be provided during all phases of the test and launch activities required for the LTA Ground Test and LEM Flight Test Programs.



Grumman "Team" personnel will perform the following primary field-site functions:

- Major LEM assembly, test and checkout, as well as repair, replacement, and modification.
- Operation and maintenance of test stands and electronics, fluid, and handling/ transportation GSE.
- Manufacturing support to Design Engineering and Flight Test Departments during the performance of special and pre-launch tests.
- Liaison with the Facilities Design Group to insure consideration of Manufacturing needs in the design or alteration of facilities.

A thorough review of all plant personnel is presently being conducted to assure the selection of only top-level, highly-skilled, competent personnel for the LEM Field-site Support Program. Mr. Edward Mc Mullen has been appointed as Coordinator of the LEM Field-

