

CP NO	V-20030
REVISION	007
DATE	JANUARY 17. 1969
CTIVITY	AS-503 & SUBS

## RELEASED FOR AS 506

SPACECRAFT/LAUNCH VEHICLE MATE & DEMATE

# THIS TCP CONTAINS HAZARDOUS OPERATION CAPE KENNEDY FACILITY

## RELEASED FOR AS 506

TCP NO.	V-20030
REVISION	007
DATE	JANUARY 17, 1969
EFFECTIVITY_	AS-503 & SUBS
INC. PCR'S	

SPACECRAFT/LAUNCH VEHICLE MATE & DEMATE



THIS	TCP	CONTAINS
HAZARI		OPERATIONS

CONTRACTOR

F.w. Flint 1-13-69

PREPARED BY IBM

CONCURRENCE

JE Sewis Jaw Balan 1-15-69 JIBM PROJECT MANAGER

F.w. Filint 1-13-69
IBM TEST CONDUCTOR

Spall. 1-14-69

NASA APPROVAL

SAFETY OFFICE JAN 15 1989

LVB BRANCH CHIEF

LVO TEST CONDUCTOR

NASA/SCO

NR

APOLLO/SATURN TEST AND OPERATIONS CATALOG SHEET	PAGE 1 OF 2
TEST TITLE	V-20030
SPACECRAFT/LAUNCH VEHICLE MATE & DEMATE	503 & SUBS
TEST OBJECTIVES	
A. TO MECHANICALLY MATE THE SPACECRAFT TO THE LAUNCH V	EHICLE.
B. TO MECHANICALLY DE-MATE THE SPACECRAFT FROM THE LAU	NCH VEHICLE.
TEST DESCRIPTION/EQUIPMENT STATUS/CONFIGURATION	
THIS TEST XX DOES DOES NOT CONTAIN HAZARDOUS OPERATION	·s.
THIS OPERATION IS DIVIDED INTO TWO PARTS.	
ALL PROTECTIVE DEVICES, EXCEPT CABLE TRAY COVERS, O	VER THE INSTRUMENT UNIT ARE
ALL PROTECTIVE DEVICES, EXCEPT CABLE TRAY COVERS, OR REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.	THEN LOWERED AND MATING
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU,	THEN LOWERED AND MATING THE MATING HARDWARE
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT.	THEN LOWERED AND MATING THE MATING HARDWARE THE LAUNCH VEHICLE.
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT. IS REMOVED AND THE SPACECRAFT IS THEN REMOVED FROM CONFIGURATION: PART A. LAUNCH VEHICLE STACKED.	THEN LOWERED AND MATING THE MATING HARDWARE THE LAUNCH VEHICLE.
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT. IS REMOVED AND THE SPACECRAFT IS THEN REMOVED FROM CONFIGURATION: PART A. LAUNCH VEHICLE STACKED.	THEN LOWERED AND MATING THE MATING HARDWARE THE LAUNCH VEHICLE.
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT. IS REMOVED AND THE SPACECRAFT IS THEN REMOVED FROM CONFIGURATION: PART A. LAUNCH VEHICLE STACKED.	THEN LOWERED AND MATING THE MATING HARDWARE THE LAUNCH VEHICLE.
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT. IS REMOVED AND THE SPACECRAFT IS THEN REMOVED FROM CONFIGURATION: PART A. LAUNCH VEHICLE STACKED.	THEN LOWERED AND MATING THE MATING HARDWARE THE LAUNCH VEHICLE.
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT. IS REMOVED AND THE SPACECRAFT IS THEN REMOVED FROM CONFIGURATION: PART A. LAUNCH VEHICLE STACKED.	THEN LOWERED AND MATING THE MATING HARDWARE THE LAUNCH VEHICLE.
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT. IS REMOVED AND THE SPACECRAFT IS THEN REMOVED FROM CONFIGURATION: PART A. LAUNCH VEHICLE STACKED.	THEN LOWERED AND MATING  THE MATING HARDWARE THE LAUNCH VEHICLE.  STACKED.  TEST REQUIREMENT
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT. IS REMOVED AND THE SPACECRAFT IS THEN REMOVED FROM CONFIGURATION: PART A. LAUNCH VEHICLE STACKED.	THEN LOWERED AND MATING THE MATING HARDWARE THE LAUNCH VEHICLE. STACKED.
REMOVED. THE SPACECRAFT IS POSITIONED OVER THE IU, HARDWARE IS INSTALLED AND TORQUED.  B. THE HOISTING SLING IS ATTACHED TO THE SPACECRAFT. IS REMOVED AND THE SPACECRAFT IS THEN REMOVED FROM CONFIGURATION: PART A. LAUNCH VEHICLE STACKED.	THEN LOWERED AND MATING  THE MATING HARDWARE THE LAUNCH VEHICLE.  STACKED.  TEST REQUIREMENT

					20/	0110
С	6/26/68	MODIFY BLOCK I	16	,	Il log her li	for I. Puell
В	6/3/68	MODIFY BLOCK	5	2	S/ T.T.KOZMOSKI	S/ I.RIGELL
А	4-23-68	TO CORRECT SIGN	VATURE LEVELS AND		S/T.T.KOZMOSKI	S/I.RIGELL
6. REV.	DATE		REASON		Contractor Approval	KSC Approval
7. CONT	RACTOR APP	ROVAL	8. ORGANIZATION	9.	DATE	
S/	W. B. HU	NT	IBM - 906		29 SEPTEMBER 196	57
10. NASA	-KSC APPRO	VAL	11. ORGANIZATION	12.	APPROVAL DATE	
5/	PAUL W.	SCHMID	JD - 25		10/6/67	

APOLLO/S	ATURN TEST AND OPERATIONS CATALOG (SHEET 2)	PA	GE _2 OF2_	
TEST TITLE			ST NUMBER	
SPACECRAFT/LAUNCH VEHICLE MATE AND DEMATE		3. EFFECTIVITY 503 & SUBS		
S. LOCATION VAB	14. COMPUTER PROC. INDENTIFICATION		N 8 HOURS	
6. SUPPORT REQUIREM	ENTS			
INTERSTAGE:	NR S IVB MECH.			
OFF-COMPLEX:	N/A			
ON-COMPLEX:	IBM QA SWING ARMS PLATFORMS 750/75 TON CRANE KSC SAFETY			
	SECURITY FIREMAN RD-40090			
7. OTHER APPLICABLE NR / PROC. I K-V-053	HEFERENCE DOCUMENTATION  K-3117 13M50103 MIL-C-5541  10M14503 10M15003	,		
	10/11/505			

PAGE

TEST NO.

VEHICLE

DAIF. REVISION

007

JANUARY 17, 1969

LIST OF EFFECTIVE PAGES

TOTAL NUMBER OF PAGES IN THIS D	OCUMENT IS 22 CONSISTING	OF:
Page No.	ISSUE	
COVER	007	
APPROVAL PAGE	007	
CATALOG SHEET (2)	C	
LIST OF EFFECTIVE PAGES (i )	007	
REVISION HISTORY (ii )	007	
BAR CHART (2)	001	
TEST OUTLINE (1)	001	
TEXT 1 THRU 13	007	

REVISIO	ON RECORD	DATE JAN. 17,	1968	EFFECTIVITY AS-506	TEST NUMBER V-20030	REVISION 007	PAGE
REVISION	PAGES AFF	ECTED	en establication and project of a section	REASON/SUP	PORTING DOCUM	ENT	
001	COMPLETE REVIS	SION	OF J	ROVIDE INITIAL REL HE BASIC RELEASE F FOLLOWING:	LEASE FOR AS-504 FOR THE AS-503 PI	. THIS TCP ( LUS INCORPORA	CONSISTS
			<b>,</b>	PCR'S - I-1-2, I DCN - I-1, I-2 NR S/C REDLINED	?, I-3		
002	ALL		INC.	DCN I-3			
003	ALL		FOR A	AS-503		· .	
004	ALL		INCOF	RPORATE PCR I-6-3 WARE CHANGE VIA EO	TO BRING TCP INT	O AGREEMENT	WITH A
005	COMPLETE REVIS	ION	OF TH	ROVIDE INITIAL REL HE BASIC RELEASE F DWING:	EASE FOR AS-505. OR AS-504 PLUS I	THIS TOP C	ONSISTS OF THE
				DCN - I-1, I-3 GAEC INPUTS			
006	COMPLETE REVIS	ION	INC P	CR I-14-2	•		
007	COMPLETE REVISI	ION		OVIDE INITIAL RELE E BASIC RELEASE FO WING.			
-				DCN - I-1		* * * * * * * * * * * * * * * * * * *	
мандолинено							
Voll-deleving bloom							
CO-COMPANIES AND							
		-			*		, a
To Company of the Com							
Carrichage							
Michelloces					8		
Respondence of the second		POSSESSES AND ADDRESS AND ADDR					

YEHICLE: AS-

DATE: JANUARY 17,

REVISION: 002

V-20030 V-20030

#### TEST OUTLINE

I. TEP TITLE	2. TOP NUMBER	3. REV.	4. VEHICLE NUMBER	n.
SPACECRAFT/LV MATE				PAGE 1 OF 1
AND DEMATE.	V-20030	001	SA-503 & SUBS.	

6. CONTENT:

#### PART I IU SPACECRAFT MATE

THE SPACECRAFT IS POSITIONED IN THE VAB, LEVELED AND PREPARED FOR ERECTION, WHILE THE IU MATING SURFACE IS PREPARED TO RECEIVE THE SPACECRAFT. SWING ARMS NO. 7 AND NO. 9 ARE EXTENDED. THE EXTENSIBLE PLATFORMS A & B ARE OPENED AND THE SPACECRAFT IS RAISED AND POSITIONED OVER I. U. THE SPACECRAFT IS THEN CENTERED OVER THE IU AND LOWERED TO ENGAGEMENT. MATING HARDWARE IS INSTALLED; THE EXTENSIBLE PLATFORMS A & B ARE CLOSED; THE INTERFACE IS INSPECTED AND SHIMMED, IF REQUIRED. THE MATING HARDWARE IS THEN TIGHTENED AND THE HOISTING SLING IS REMOVED.

#### PART II IU SPACECRAFT DEMATE

THE SPACECRAFT IS PREPARED FOR DEMATING AND ALL INTERFACING CONNECTIONS ARE DISCONNECTED. THE HOISTING SLING IS INSTALLED AND MATING HARDWARE IS REMOVED. THE EXTENSIBLE PLATFORMS A & B ARE OPENED AND THE SPACECRAFT IS HOISTED TO CLEAR THE IU, TRAVERSED AND LOWERED TO ITS TRANSPORTER IN THE TRANSFER AISLE.

J. TRICARD 1-18-68 DE COMPER 10. DATE 10. DATE

KSC FORM 23-339 (7/67)

REVISION

PAGE TEST NO. VEHICLE 1 V-20030 AS-506

#### SPACECRAFT/LAUNCH VEHICLE MATE AND DEMATE

THE OPERATIONS ENGINEER WILL ANNOUNCE THE REVISION LEVEL AND ALL OUTSTANDING PROCEDURE CHANGE REQUESTS (PCR) OF THE PROCEDURE USED AS THE OFFICIAL
TEST COPY TO ALL PERSONNEL INVOLVED IN THE TEST.

IBM QV----

#### A. EQUIPMENT REQUIREMENTS

1. TWO SETS OF MECHANIC'S GENERAL PURPOSE TOOLS. (CALIBRATED)

IBM QV----

- 2. TORQUE WRENCHES.
- 3. IU/SLA MATING HARDWARE.

IBM QV----

- (A) NAS 625-8 BOLTS 108 REQUIRED.
- (B) 10M12286-1 NUTS 108 REQUIRED.
- (C) MS 20002-C5 WASHERS 108 REQUIRED.
- (D) MS 20002-5 WASHERS 216 REQUIRED.
- (E) 10M15103-1,3 SHIMS AS REQUIRED
- (F) 10M12285-1 WASHERS 108 REQUIRED.
- 4. TRICHLORETHYLENE, METHYL ETHYL KETONE OR ISOPROPYL ALCOHOL (FOR DEGREASING).
- 5. CLEAN RAGS, KIM-WIPES.
- 6. SAFETY EQUIPMENT
  - (A) HARD HATS
  - (B) NEOPRENE GLOVES
  - (C) SAFETY GOGGLES OR FACESHIELD
  - (D) COTTON COVERALLS
- 7. SEALANT EC-1291 OR PR-1201-Q (IF REQUIRED)

IBM QV----

- 8. FEELER GAUGE
- 9. ALUMINUM LADDERS
- 10. CABLE TRAY COVERS

IBM QV----

30 EA, P/N JB-20023

DATE: REVISION 007

#### B. SUBTASK PROCEDURES

- V-30030-IBM PREPS FOR PLATFORM B RETRACTION. 1.
- 2. V-36048-IU UPPER PROTECTIVE RING INSTALLATION & REMOVAL
- V-36049-IU PROTECTIVE COVER INSTALLATION & REMOVAL. 3.
- 4. KL10005-IMU/AMA THERMAL CONTROL.
- K3117-S/C TRANSPORTATION TO VAB AND MATE.

#### SPECIAL REQUIREMENTS

- 1. MATING/DEMATING OF THE SPACECRAFT TO THE LAUNCH VEHICLE IS ACCOMPLISHED AS A JOINT OPERATION BETWEEN NORTH AMERICAN ROCKWELL (NASA-SCO) AND IBM (NASA-LVO). THE OVERALL RESPONSIBILITY FOR THE OPERATIONS RESTS WITH THE TEST SUPERVISOR (DLO-HC).
  - (A) NR WILL PREPARE THE SPACECRAFT FOR MATING/DEMATING AND DIRECT THE HOISTING AND POSITIONING OF THE SPACECRAFT EXCEPT WHEN ITS LOWER SURFACE IS WITHIN APPROXIMATELY 18 INCHES OF THE IU UPPER SURFACE.
    - (1) MATING WILL BE ACCOMPLISHED PER K-3117.
    - (2) GAEC OPERATIONS WILL BE ACCOMPLISHED PER TCP-KL10005.
    - (3) DEMATING WILL BE ACCOMPLISHED PER TPS.
  - IBM WILL PREPARE THE IU FOR MATING/DEMATING, INSTALL OR REMOVE MATING HARDWARE AND DIRECT THE HOISTING AND POSITIONING OF THE SPACECRAFT WHEN ITS LOWER SURFACE IS WITHIN APPROXIMATELY 18 INCHES OF THE IU UPPER SURFACE.
- THIS OPERATION WILL BE CONDUCTED IN ACCORDANCE WITH THE REQUIREMENTS OF SOP VAB-SC-1 OF K-V-053.
  - (A) A CONTROLLED AREA WILL BE ESTABLISHED AND MAINTAINED DURING HOISTING OPERATIONS.

ACCESS BADGES, IF REQUIRED, WILL BE SECURED BY TEST OPERATIONS FROM THE COMPLEX SUPPORT CONTROLLER. TEST OPERATIONS SHALL CONTROL DISTRIBUTION OF ACCESS BADGES.

- SUPERVISION SHALL INSURE THAT ONLY TRAINED AND QUALIFIED PERSONNEL PARTICIPATE IN THE OPERATION.
- OTHER OPERATIONS IN THE AREA OF THE INSTRUMENT UNIT WHICH MIGHT INTERFERE WITH THE MATING/DEMATING OPERATION MUST BE DEFERRED UNTIL THE MATING/DEMATING OPERATION IS COMPLETED.

PAGE

TEST NO.

VEHICLE

- TOOLS, HARDWARE AND PERSONAL EFFECTS INVENTORY CONTROL MUST BE PLACED IN EFFECT WHEN PERSONNEL ARE INSIDE THE IU.
- THE DAC 402 ACCESS PLATFORMS MUST BE INSTALLED TO PROVIDE ACCESS TO THE MATING RING. LIGHT STANCHIONS SHOULD NOT BE INSTALLED.
  - (A) LOOSE HARDWARE OR OBJECTS THAT COULD FALL ON THE FORWARD DOME OF THE SIVB FUEL TANK MUST BE TETHERED OR OTHERWISE RESTRAINED TO PREVENT SIVB TANK DAMAGE.

\* ANY OBJECTS DROPPED OR SUSPECTED OF \* \* BEING DROPPED IN THE SIVB FORWARD \* INTERSTAGE SHOULD BE REPORTED TO LVO \* IMMEDIATELY. 

- PERSONNEL REQUIREMENTS: 5.
  - (A) IBM TECHNICAL
    - (1) MECHANICAL SYSTEMS ENGINEER.
    - (2) SIX MECHANICAL SYSTEMS TECHNICIANS.
    - (3) TWO QUALITY INSPECTORS.

#### NOTE

THE ABOVE TECHNICAL REQUIREMENTS MAY BE VARIED BY THE IBM SYSTEMS ENGINEER.

- (B) NASA-LVO
  - (1) MECHANICAL SYSTEMS ENGINEER.
  - (2) QUALITY INSPECTOR.
- (C) NR AND NASA-SCO

REFER TO NR PROCEDURE K-3117 FOR PERSONNEL REQUIREMENTS.

(D) GAEC

REFER TO TCP KL 10005 FOR GAEC PERSONNEL REQUIREMENTS.

(E) OTHER

JANUARY 17, 1969

007

- (1) CRANE COORDINATOR.
- (2) CRANE OPERATOR.
- (3) PLATFORM A AND B OPERATORS.
- (4) SWING ARM NO. 7 AND NO. 9 OPERATORS.
- (F) SAFETY
  - (1) KSC SYSTEM SAFETY SUPERVISOR.
  - (2) TWO SECURITY PATROLMEN.
  - (3) SECURITY SERGEANT.
  - (4) FIREMAN.
- THE KSC SYSTEM SAFETY SUPERVISOR WILL VERIFY ALL SUPPORT ORGANI-ZATIONS ARE ON STATION PRIOR TO THE START OF OPERATIONS AND WILL MONITOR THE OPERATION TO INSURE THAT SAFETY PRECAUTIONS ARE FOLLOWED.

#### NOTE

THE KSC SYSTEMS SAFETY SUPER-VISOR MAY STOP THE OPERATION IF AN APPARENT HAZARD TO PERSONNEL OR PROPERTY DEVELOPS AND WILL CO-ORDINATE CORRECTIVE ACTION WITH THE TEST SUPERVISOR

- SUPPORT ORGANIZATIONS MUST BE NOTIFIED AT LEAST 24 HOURS PRIOR TO 7. THE START OF OPERATIONS.
- RUBBER GLOVES, EYE PROTECTION AND COTTON COVERALLS MUST BE WORN WHEN HANDLING DEGREASING SOLUTION. IF ANY OF THE CHEMICALS COME IN CONTACT WITH THE SKIN, WASH IMMEDIATELY WITH SOAP AND WATER. IF ANY OF THE CHEMICALS COME IN CONTACT WITH THE EYES, FLUSH WITH COPIOUS AMOUNTS OF WATER AND SEEK MEDICAL ASSISTANCE IMMEDIATELY. METHYL ETHYL KETONE IS FLAMMABLE AND SHOULD BE USED ONLY IN A WELL VENTILATED AREA AWAY FROM SPARKS OR OPEN FLAME. BOTH METHYL ETHYL KETONE AND TRICHLORETHYLENE FUMES ARE TOXIC. AVOID BREATHING THE FUMES AND USE IN A WELL VENTILATED AREA.

#### D. INITIAL TEST CONDITIONS

JANUARY 17, 1969

REVISION

- VERIFY ALL EQUIPMENT LISTED UNDER A IS AVAILABLE IN THE IU AREA. IBM OV----1.
- 2. SWING ARM NO. 7 MUST BE EXTENDED TO THE IU DOOR, WITH THE SLA UMBILICAL ACCESS PLATFORM RETRACTED.
- 3. PREPARATIONS FOR PLATFORM RETRACTIONS MUST BE COMPLETED. PER V-30030
- 4. SECURITY GUARDS MUST BE STATIONED TO ESTABLISH AND MAINTAIN A LIMITED ACCESS AREA.
- 5. SUPPORT PERSONNEL MUST BE ON STATION AND READY TO BEGIN THE OPERATION.
- THE IU UPPER PROTECTIVE RING AND PROTECTIVE COVER MUST 6. BE REMOVED FOR MATING AND AVAILABLE FOR INSTALLATION FOR DEMATING. PER V-36048 & V-36049.

IBM QV----

- VERIFY FIT CHECK OF BOLTS AND WASHERS AND VISUALLY INSPECT 7. FOR BURRS, CORROSION, NICKS AND FREE OF LUBRICANT. (MATE ONLY)
- HARDWARE SPECIFIED IN PARAGRAPH A.4 MUST BE WEIGHED AND WEIGHT RECORDED LBS. (MATE ONLY)

IBM QV----

- 9. IU AIR PURGE SYSTEM MUST BE OPERATING.
- 10. REMOVE IU DOOR FRAME AND PROTECTIVE COVER AND INSTALL GUIDE PIN BRACKETS PER PROCEDURE V-36048. VERIFY SPACECRAFT GUIDEPIN BRACKETS INSTALLED (AS REQUIRED).
- SAFETY SUPERVISOR MUST CONCUR WITH READINESS TO BEGIN AND 11. A PUBLIC ADDRESS ANNOUNCEMENT MUST BE MADE:

"LIGHTS PROVIDED FOR I.U./SLA AREA.

"ALL NON-ESSENTIAL PERSONNEL CLEAR EXTENSIBLE PLATFORMS A AND B FOR SPACECRAFT MATING (DEMATING) OPERATION."

#### Ε. MATING OPERATION

1. IBM PREPARE THE IU UPPER MATING SURFACE TO RECEIVE THE SPACECRAFT.

XX	жжжжжжжжжжж	><><><>
25		×
×	PERSONNEL MUST WEAR SAFETY	×
×	GOGGLES OR FACESHIELDS,	×
×	COTTON COVERALLS AND NEO-	×
×	PRENE GLOVES WHEN HANDLING	>5
×	DEGREASING SOLUTIONS.	25
26		×
2000	eseseseseseseseseseseseseseseseseseses	36363636

(A) WIPE THE MATING SURFACE USING A RAG SATURATED WITH METHYL ETHYL KETONE OR TRICHLORETHYLENE.

IBM QV----

- (B) INSPECT THE IU MATING SURFACE TO VERIFY THE ABSENCE OF NICKS, BURRS OR CORROSION. REPAIR DEFECTS AS REQUIRED.
- (C) INSPECT THE IU MATING SURFACE TO VERIFY IT HAS BEEN IBM QV----ALODINED.

NR BEGIN PREPARATION OF THE SPACECRAFT FOR MATING PER 2. K - 3117.

#### NOTE

IBM MECHANICAL SYSTEMS ENGINEER AND QUALITY INSPECTOR WILL VERIFY THE SPACECRAFT MATING SURFACE IS LEVEL WITHIN TWO INCHES AND THE LOWEST POINT IS NOT AT THE SPACECRAFT +Y AXIS (IU ACCESS DOOR). INSPECTOR WILL INSPECT MATING SURFACE FOR NICKS, BURRS, CORROSION AND ALODINED.

IBM QV----

- 3. HAVE CRANE COMMUNICATOR STATIONED ON THE EXTENSION OF SWING ARM NO. 7 AND AT LEAST THREE IBM MECHANICAL SYSTEMS TECHNICIANS STATIONED IN THE IU. THE IBM SYSTEMS ENGINEER WILL BE STATIONED IN THE IU TO DIRECT THE CRANE COMMUNICATOR.
- 4. HAVE EXTENSIBLE PLATFORMS A AND B SUFFICIENTLY RETRACTED BY BENDIX.
  - NR WILL DIRECT THE HOISTING OF THE SPACECRAFT ABOVE THE 16TH 5. FLOOR CROSSWALK.

#### NOTE

REQUEST DAC OPERATIONS TO REMOVE ANY POSSIBLE INTERFERING GSE, HAND-RAILS, DOME COVERS, ETC. VERIFY THAT ALL LEM HARDWARE IS FREE OF INTERFERENCE WHILE BEING LOWERED TO THE IU MATING SURFACE.

6. NR DIRECT CRANE OPERATOR/COMMUNICATOR TO POSITION THE SPACECRAFT OVER THE IU AND LOWER UNTIL THE SLA MATING SURFACE IS WITHIN APPROXIMATELY 18 INCHES OF THE IU MATING SURFACE.

DATE: JANUARY 17, 1969
REVISION 007

#### NOTE

AT THIS POINT RESPONSIBILITY FOR DIRECTING CRANE OPERATOR/COMMUNICATOR IS TRANSFERRED TO IBM (NASA-LVO).

- 7. VISUALLY ALIGN THE IU POSITION MARKINGS I, II, III, AND IV WITH IBM QV----- SPACECRAFT POSITION MARKINGS I, II, III, AND IV.
- 8. IBM SYSTEMS ENGINEER DIRECT CRANE OPERATOR/COMMUNICATOR TO LOWER THE SPACECRAFT UNTIL THE LOWEST POINT IS WITHIN APPROXIMATELY 3/16" OF THE IU MATING SURFACE, AND THE GUIDE PINS ARE ENGAGED.

9. INSTALL MATING HARDWARE

IBM QV----

#### NOTE

NON FLIGHT MATING HARDWARE MAY BE USED FOR NON FLIGHT SPACECRAFT MATING.

- (A) AT THE LOW POINT OF THE SPACECRAFT, INSERT A NAS 625-8 BOLT THROUGH A MS20002-C5 WASHER (COUNTERSUNK FACE UP) INTO THE HOLE IN THE SPACECRAFT FLANGE AND CORRESPONDING HOLE IN THE IU FLANGE.
- (B) SIMILARLY INSTALL BOLTS IN THE HOLES ADJACENT TO THE LOW POINT WHILE HAVING THE SPACECRAFT INCREMENTALLY LOWERED TO PERMIT INSTALLATION OF ALL (108) BOLTS LOWER THE SPACECRAFT UNTIL ITS ENTIRE WEIGHT RESTS ON THE IU. INITIAL CONTACT SHALL NOT BE IN THE ACCESS DOOR QUADRANT OR AT B OR C SPLICES.
- (C) INSTALL A 10M12286-1 NUT & A MS20002-5 WASHER ON EACH BOLT. DO NOT TIGHTEN THE NUTS.
  - (1) VERIFY THAT EACH NUT THREAD IS CLEAN AND DRY, AND FREE OF ANY LUBRICANT.

VEHICLE

V-20030

IBM QV----

AS-506

- (2) CHECK THE THREAD EXTENSION ON EACH BOLT BY OBSERVING IT IN THE GAP BETWEEN THE SPACECRAFT AND THE IU MATING RINGS. SHIM AS REQUIRED UNDER THE NUT TO AVOID ENGAGEMENT OF IMPERFECT THREADS ON THE BOLT USING A MAXIMUM OF TWO MS20002-5 OR 10M12285-1 WASHERS UNDER EACH NUT. MAINTAIN A MINIMUM BOLT-THRU-NUT PROTRUSION OF TWO THREADS.
- DO NOT REMOVE SLINGS OR DISMISS CRANE OPERATOR UNTIL ALL BOLTS ARE POSITIONED AND NUTS HAVE BEEN INITIALLY ENGAGED.
- 10. HAVE EXTENSIBLE PLATFORMS A AND B CLOSED.
- MEASURE THE GAP AT THE IU/SLA INTERFACE ALONG THE OUTBOARD 11. EDGE USING A FEELER GAUGE. THE MAXIMUM GAP SHALL NOT EXCEED .020 INCHES NOR SHALL THE GAP DIFFERENTIAL OVER ANY 10 INCHES EXCEED .010 INCHES. RECORD ANY OUT OF TOLERANCE GAPS ON TSS. INCLUDE GAP, LOCATION, AND SHIMMING REQUIRED. SHIM AS REQUIRED USING 10M15103-1, 3 SHIMS TO ACHIEVE THESE LIMITS.
- SNUG, MATING HARDWARE AT THE INTERFACE. EITHER BOLT OR NUT 12. MAY BE TIGHTENED.

#### NOTE

SHIMMING OF GAPS ABOVE THE IU ACCESS DOOR WILL BE DECIDED ON A REAL TIME BASIS BY IBM ENGINEER AND LVO ENGINEER.

#### NOTE

AFTER 25% OF THE MATING HARDWARE HAS BEEN TIGHTENED, NOTIFY NR THEY MAY BEGIN POST MATE OPERA-TIONS, PER K-3117: NOTIFY GAEC THEY MAY BEGIN POST MATE OPERA-TIONS PER KL10005.

TORQUE THE MATING HARDWARE PER 10M15016 (AS-506) OR APPLICABLE 13. STAGE TO STAGE TORQUE SEQUENCE. NON-FLIGHT SPACECRAFT MATING HARDWARE SHOULD BE TORQUED TO 115±10 INCH-POUNDS.

IBM QV----

жжжжжжжжжжжжжжжжжжжжжжжжжжжжж " THE TORQUE VALUES GIVEN ARE FOR NON-\* LUBRICATED SURFACES. PRESENCE OF LUBRI- \* CANT COULD RESULT IN OVERSTRESS.

- JANUARY 17, 1969 REVISION 007
  - (A) TIGHTEN ALL OF THE BOLTS EQUALLY IN THE SPECIFIED SEQUENCE TO 115 ± 10 INCH POUNDS.
  - (B) TIGHTEN ALL OF THE BOLTS EQUALLY IN THE SPECIFIED SEQUENCE TO 170 ± 10 INCH POUNDS.
  - (C) TIGHTEN ALL OF THE BOLTS EQUALLY IN THE SPECIFIED SEQUENCE TO 230 ± 10 INCH POUNDS.
  - 14. IF THIS IS THE FINAL INSTALLATION, HAVE QAI TORQUE SEAL MATING HARDWARE.

IBM OV----

IF THIS IS THE FINAL INSTALLATION APPLY EC-1291 OR PR-1201-Q 15. SEALANT AT THE INTERFACE PER 10M15006 (AS-506) OR APPLICABLE VEHICLE ASSEMBLY.

IBM QV--

#### NOTE

SEALANT APPLICATION MAY BE COMPLETED AT A LATER DATE ON A NON-INTERFERENCE BASIS PER CAP.

VERIFY HOISTING SLING HAS BEEN REMOVED. 16.

IBM QV----

- NOTIFY TEST CONDUCTOR MATING OPERATION IS COMPLETE AND MAKE PUBLIC 17. ADDRESS ANNOUNCEMENT "SPACECRAFT MATING OPERATION HAS BEEN COMPLETED. THE AREA IS NOW OPEN FOR NORMAL WORK."
- WEIGH HARDWARE NOT INSTALLED. SUBTRACT TOTAL FROM WEIGHT IN PARA-18. GRAPH C.7 AND RECORD WEIGHT OF HARDWARE INSTALLED IN THE IU WEIGHT AND BALANCE LOGBOOK. TOTAL WEIGHT HARDWARE NOT INSTALLED WEIGHT OF HARDWARE INSTALLED

IBM QV--

- IF THIS IS NOT THE FINAL INSTALLATION REMOVE GUIDE PIN BRACKET AT 19. IU DOOR AND REINSTALL THE DOOR FRAME AND PROTECTIVE COVER.
- IF THIS IS THE FINAL INSTALLATION, REMOVE THE THREE GUIDE PIN 20. BRACKETS AND INSTALL FLIGHT HARDWARE PER PROCEDURE V-36048 AND REINSTALL DOOR FRAME & PROTECTIVE COVER.
- DEMATING OPERATION F.

#### NOTE

APPROXIMATELY 85% OF THE MATING BOLTS MAY BE REMOVED PRIOR TO STEP 1. THE REMAINING BOLTS SHALL BE EVENLY DISTRIBUTED.

- VERIFY NR HAS CONNECTED THE HOISTING SLING PER TPS AND IS PREPARED TO START DEMATING.
- 2. REMOVE IU DOOR FRAME AND PROTECTIVE COVER.
- VERIFY THE GUIDE PIN BRACKETS ARE INSTALLED PER PROCEDURE V-36048 3. AND ENGAGED WITH SPACECRAFT GUIDE PINS. IBM OV----
- VERIFY THE IU UPPER PROTECTIVE RING AND PROTECTIVE COVER ARE AVAIL-ABLE FOR INSTALLATION. IBM QV----
- VERIFY ALL ITEMS WHICH MIGHT PREVENT IU/SLA SEPARATION ARE 5. REMOVED.

IBM QV----

6. REMOVE MATING BOLTS (108 TOTAL) FROM THE IU/SLA INTERFACE. IBM QV----

HAVE CRANE COMMUNICATOR STATIONED ON THE EXTENSION OF SWING ARM 7. NO. 7 AND AT LEAST THREE IBM MECHANICAL SYSTEMS TECHNICIANS STATIONED IN THE IU. THE IBM SYSTEMS ENGINEER WILL BE STATIONED IN THE IU TO DIRECT THE CRANE COMMUNICATOR.

#### NOTE

MATING BOLTS AND NUTS MAY NOT BE REUSED FOR FLIGHT INSTALLATION.

#### NOTE

IBM ENGINEER SHALL BE ON STATION PRIOR TO STEP E.7.

- 8. TAKE A GRADUAL STRAIN ON THE HOISTING SLING. STOP THE CRANE WHEN THE FIRST SEPARATION OF THE IU/SLA OCCURS. LOCATION OF FIRST SEPARATION SHOULD BE AT ACCESS DOOR BY RESTRAINT ON OPPOSITE SIDE OF IU. WEIGHTS SHOULD NOT REMAIN ON SPLICES DURING SEPARATION.
- 9. HAVE BENDIX RETRACT EXTENSIBLE PLATFORMS A AND B.
- IF THE INITIAL SEPARATION OCCURS AT A LOCATION OTHER THAN 10. BETWEEN IU PANELS 16 AND 24, SLOWLY HOIST THE SPACECRAFT UNTIL IT IS APPROXIMATELY TWO FEET ABOVE THE IU. REMOVE ANY SHIMS INSTALLED AT THE INTERFACE AND RETAIN FOR WEIGHING.

IBM QV---

35

\* PERSONNEL IN THE IU WILL

" GUIDE THE SPACECRAFT TO

36 INSURE IT DOES NOT CONTACT X

\* THE IU CABLE TRAY.

- DATE: 007 REVISION
  - NR WILL DIRECT CRANE OPERATOR/COMMUNICATOR TO COMPLETE THE DEMATING OPERATING IN ACCORDANCE WITH THE TPS.
  - 12. WHEN THE SPACECRAFT IS CLEAR OF THE PLATFORMS, HAVE BENDIX CLOSE THE EXTENSIBLE PLATFORM B.
  - INSPECT AND RECORD ANY DAMAGE TO IU MATING SURFACE. 13.
  - 14. INSTALL THE IU UPPER PROTECTIVE RING PER PROCEDURE V-36048, AND IF THE IU IS TO REMAIN MATED, INSTALL THE PROTECTIVE COVER PER PROCEDURE V-36049 AND UPPER PROTECTIVE RING NEED NOT BE INSTALLED.

#### NOTE

IF A SPACECRAFT IS TO BE INSTALLED WITHIN 24 HOURS, PLATFORM B COVER MAY BE USED IN PLACE OF IU/S-IVB PROTECTIVE COVER.

IF SPACECRAFT MATE IS NOT GOING TO BE PERFORMED WITHIN 24 HOURS AFTER DEMATE REMOVE GUIDE PIN BRACKET BY THE IU ACCESS DOOR AND INSTALL THE IU DOOR FRAME AND PROTECTIVE COVER.

IBM QV----

RECORD WEIGHT OF REMOVED HARDWARE IN THE IU WEIGHT AND 15. BALANCE LOGBOOK. WEIGHT \_\_\_\_

IBM QV----

- NOTIFY TEST CONDUCTOR OF COMPLETION OF DEMATING AND MAKE PUBLIC ADDRESS "SPACECRAFT DEMATING OPERATION HAS BEEN COMPLETED. THE AREA IS NOW OPEN FOR NORMAL WORK."
- G. EMERGENCY PROCEDURE
  - 1. STOP ALL OPERATIONS.
  - 2. CLEAR THE AREA OF ALL PERSONNEL.

" IN THE EVENT OF SLING OR \* CABLE FAILURE, PERSONNEL \* \* WILL IMMEDIATELY MOVE TO \* \* A SAFE LOCATION, MAKING NO ATTEMPT TO PROTECT EQUIPMENT. 

ENGINEER IN CHARGE INVESTIGATE MALFUNCTION TO DETERMINE IF 3. OR WHEN OPERATIONS WILL CONTINUE AND INITIATE SECURING STEPS IF OPERATIONS ARE TO BE DISCONTINUED.

END OF TEST PROCEDURE V-20030.

REVISION 007 17, 1969

DATE: JANUARY 17, 1969
REVISION 007

### APOLLO/SATURN LAUNCH OPERATIONS

PAGE TEST NO. VEHICLE

13 V-20030 AS-506

	OPE	RATING PERS	ONNEL		
TECHNICIAN(S)			NAME OF STATE STATE SAME SAME SAME AND OTHER PART SAME		
			and note and the time can dair one dair one	THE CALL THAN THE	
		MANN LITTLE SAID CLASS CLASS CAMP SAID SAID SAID SAID SAID SAID SAID SAID	and also take the data take here are are the		
<u> </u>					<b>B</b>
	The state of the s				
QUALITY INSPECTOR(S)					
	er et			-	
PAD ENGINEER(S)					