

SATURN HISTORY DOCUMENT University of Alabama Research Institute

History of Science & Teechoogy Group Doc 非 __

SATURN AS-501 **EVALUATION BULLETIN**

NO. 1

NOVEMBER 14, 1967

SATURN FLIGHT EVALUATION WORKING GROUP

THE FINDINGS HEREIN ARE PRELIMINARY. SEE FUTURE BULLETINS FOR LATEST INFORMATION

GEORGE C. MARSHALL SPACE FLIGHT CENTER HUNTSVILLE, ALABAMA

Memorandum

TO

Addressees

DATE: November 14, 1967

FROM

Chairman, Saturn Flight Evaluation

In Reply Refer to:

Working Group, R-AERO-F

R-AERO-F-187-67

SUBJECT: AS-501 Flight Evaluation Bulletin No. 1

Summary

The early engineering evaluation of the Saturn V Launch Vehicle, AS-501 indicated that all primary and secondary mission objectives were accomplished. Launch occurred at 7:00 am EST on November 9, 1967. All systems and subsystems appear to have performed near nominal.

Preliminary results indicate adequate clearance with close in support equipment. A yaw maneuver was accomplished as programmed and tower clearance was maintained during liftoff.

The S-IC Stage flight was near nominal with the outboard engines being cut off 1.2 seconds earlier than predicted. The maximum angle of attack was 1.3 degrees and the maximum engine deflections were 0.6 degrees during first stage burn.

Camera film showed the S-IC/S-II separation and S-II second plane separations to be smooth and the clearances adequate.

The S-II stage burn time was 4.7 seconds longer than nominal. The LH₂ tank insulation performed satisfactorily with no defects noted during countdown or in flight.

The S-IVB first and second burn times were 6.2 seconds longer and 15.2 seconds shorter than predicted, respectively.

Introduction

The findings reported herein are the results of the combined evaluation efforts of the various Laboratories of Research and Development Operations at MSFC, The Boeing Company, North American Rockwell/Space Division, Douglas Aircraft Company, International Business Machines, and Rocketdyne. The results quoted are preliminary and are subject to change as the evaluation progresses. This memo is the first of a series of evaluation bulleten to be published during the AS-501 flight test evaluation period. These bulletins are intended for internal use only.

3. Event Times

The following event times indicate a near nominal flight: $AS-501 \ Significant \ Event \ Times$

EVENT	RANGE TIME (SEC)		
	ACTUAL	PRED	ACT-PRED
First Motion	-0.48		
Liftoff Signal (IU)	0.265		3 5.57 5
Start Yaw Maneuver	1.3		
Start Pitch and Roll	11.7	10.5	1.2
S-IC IECO	135.5	135.0	0.5
S-IC OECO	150.8	151.9	-1.1
S-II	151.2	152.4	-1.2
S-IC Retro Motor Ignition	151.4	152.6	-1.2
S-IC/S-II Separation	151.4	152.7	-1.3
S-II Engines Start Command	152.2	153.3	-1.1
S-II 2ND Plane Separation	181.4	182.6	-1.2
Jettison LET	187.1	188.3	-1.2
Jettison S-II AFT Cameras	189.8	191.0	-1.2
Initiation of IGM	190.2	191.9	-1.7
S-II ECO	519.8	516.3	3.5
S-IVB Ullage Motor Ignition	520.4	517.0	3.4
S-II Retro Motor Ignition	520.5	517.1	3.4
S-II/S-IVB Separation	520.5	517.2	3.3
S-IVB Engine Start Command	520.7	517.3	3.4
S-IVB Ullage Case Jettison	532.5	529.1	3.4
S-IVB First Guidance Cutoff	665.6	656.0	9.6
Insertion Into Parking Orbit	675.6	666.0	9.6
S-IVB Restart Preparations (TB6)	11,159.6	11,158.5	1.1
S-IVB Restart Command	11,486.6	11,484.5	2.1
S-IVB Second Guidance Cutoff Signal	11,786.3	11,799.4	-13.1
Waiting Orbit Injection	11,796.3	11,809.4	-13.1
S-IVB/CSM Separation	12,386.5	12,399.4	-12.9

4. Trajectory

A preliminary powered flight trajectory has been established through S-IVE first burn. The performance of all three stages was satisfactory as indicated by comparisons at S-IC cutoff, S-II cutoff, and S-IVB (first burn) cutoff which are as follows:

S-II ECO

	S-IC	0EC0	
PARAMETER	ACTUAL	NOMINAL	ACT - NOM
Range Time(SEC)	150.75	151.91	-1.16
Altitude(KM)	63.54	63.61	-0.07
Range(KM)	82.63	85.01	-2.38
Cross Range(KM)	0.57	1.12	-0.55
Cross Range Velocity(M/SEC)	6.0	21.2	-15.2
Space-Fixed Velocity(M/SEC)	2693.3	2711.6	-18.3

PARAMETER	ACTUAL	NOMINAL	ACT - NOM
Range Time(SEC)	519.85	516.33	3.52
Altitude(KM)	191.41	189.74	1.67
Range(KM)	1477.99	1471.79	6.20
Cross Range(KM)	22.35	22.99	-0.64
Cross Range Velocity(M/SEC)	158.5	152.9	5.6
Space-Fixed Velocity(M/SEC)	6807.4	6852.6	-45.2

	S-IVB ECO (First Burn)	
PARAMETER	ACTUAL	NOMINAL	ACT - NOM
Range Time(SEC)	665.64	656.00	9.64
Altitude(KM)	191.39	191.44	-0.05
Range(KM)	2448.94	2404.08	44.86
Cross Range(KM)	52.44	51.03	1.41
Cross Range Velocity(M/SEC)	259.5	255.2	4.3
Space-Fixed Velocity(M/SEC)	7791.21	7791.00	0.21

MACH one was reached at 61.5 seconds at an altitude of 7.4 KM. This occurred approximately 0.1 seconds early at an altitude of 0.1 kM lower than nominal. Maximum dynamic pressure (3.440 N/CM_2) was reached in 78.0 seconds at an altitude of 13.1 kM, which is approximately 0.4 seconds earlier and 0.1 kM lower than nominal. S-IVB second burn cutoff was given by the

guidance system based on vehicle energy (a function of velocity and radius). Preliminary telemetered guidance data indicated a space-fixed velocity of 9390.4 M/SEC compared with a predicted value of 9399.9 M/SEC. Radius at cutoff was 6,904,070 meters.

5. Guidance and Control

Based on available inertial platform instrumentation, the ST-124M inertial platform performed as predicted with no anomalies. Vehicle control was satisfactory for the entire flight.

The maximum observed noise on the unfiltered roll and pitch body rate gyros at liftoff were 8 DEG/SEC and 4 DEG/SEC peak-to-peak, respectively. During transonic flight, noise amplitudes were 8 DEG/SEC in roll and 4 DEG/SEC in pitch. The maximum noise on yaw rate gyro was 1 DEG/SEC peak-to-peak. The electrical filter network was effective in reducing gyro signal noise such that the input to the Emergency Detection System was satisfactory.

6. Propulsion

The S-IC and S-II quick-look data indicated that the engine performance, stage propellant utilization systems, pressurization systems, and pneumatic control pressure systems operated satisfactorily and were within expected tolerances on both stages. Also there were no apparent anomalies in the propulsion system performances.

The S-IVB Stage operated satisfactorily and within limits except that the LH₂ ullage pressure and the pneumatic control system pressure were below the predicted during second burn operation. The LH₂ ullage pressure decreased to a minimum of 19.0 N/CM² (28 PSIA) prior to engine restart. After engine start the ullage pressure increased to approximately 21 N/CM² (31 PSIA) and stabilized there for the duration of the burn. The lower than expected LH₂ ullage pressure had no adverse effects on engine operation.

After propulsive vent cutoff approximately 326 seconds prior to S-IVB restart, the measured pressure in the vent lines showed an extremely slow decay rather than the rapid decrease expected when the vent valve was closed. Possible causes of this slow decay include the propulsive vent valve not seating properly, or the transducer line being partially blocked causing a slow decay in the pressure transducer line.

The S-IVB pneumatic control system operated properly during both burns. However, the stage pneumatic pressure was low during second burn with a sphere pressure of approximately 1034.2 N/CM² (1500 PSIA). Sufficient pneumatics were available to perform all S-IVB programmed functions.

Further investigation of the above problems is continuing.

7. Ground Engineering Cameras

Camera malfunctions were responsible for an estimated 75 percent of lost filmed data. The cameras and problems encountered are as follows:

- a. The KSC perimeter tracking cameras dumped backwards when power was applied at T-30 seconds and could not be returned.
- b. Eight cameras used for optical verification of stage structured integrity and tower clearance malfunctioned. All tower clearance optical data was lost.
- c. The IGOR tracking camera at Patrick gave an extremely erratic track. Additionally, timing was erratic. This caused loss of S-IC stage track and tumble rate data after separation.
- d. One second prior to launch the entire camera system on the launch table LUT and perimeter sites lost control power and time for a period of approximately one second, causing several jams in the rotary prism type cameras. This makes it impossible to project a time curve, resulting in loss of all GSE timed events, particularly optically determined vehicle first motion.
- e. Alots camera broke film before staging occurred.

J. P. Lindberg

ADDRESSEES: (CONT)

R-QUAL

IBM

Mr. Chandler, R-QUAL-R Mr. Wittmann, R-QUAL-T

Mr. Weaver (5)

R-SSL

Rocketdyne

Dr. Stuhlinger, R-SSL-DIR

Mr. Johnson (2)

Mr. Heller, R-SSL-DIR

TBC/Michoud

R-TEST

Mr. Kornell (10)

Mr. Heimburg, R-TEST-DIR Mr. Tessmann, R-TEST-DIR TBC/Huntsville

Dr. Sieber, R-TEST-I

Mr. Krausse (10)

Mr. Driscoll, R-TEST-S

NAR/SD

Mr. Reilmann, R-TEST-SB

Mr. Garcia (10)

MS

MS-I

MS-IP(4)

MS-IPL (15)

CC-P

Mr. Wofford, PAT

KSC

Dr. Debus, AA-DIR

Mr. Poppel, MD

Mr. Sparks, NAA-ZK-64

Mr. Darby, MJ-4

Mr. Sendler, PA Dr. Bruns, PB

Mr. Jelen, PB-1

Mr. Collins, PF

Col. Bagnulo, MA

Lt. Col. Petrone, LO (3)

Mr. Mathews, DG

Mr. Body, DD

Dr. Knothe, CA

KSC

Dr. Gruene, LVO

Mr. Rigell, LVO-2

Mr. G. Williams, MJ

Mr. Pickett, LVO-3

Mr. O'Hara, LVO-7

MSC

Mr. Mardell, MSC/ASPO PK

Mr. McKann, MSC/ASPO PK

DAC

Mr. Schar (10)

ADDRESSEES: AS-501 Evaluation Bulletin No. 1, November 14, 1967

FROM: R-AERO-F

Mr. Klauss, R-QUAL-J Mr. Brooks, R-QUAL-P Mr. Corder, R-QUAL-DIE

Dr. von Braun, DIR	R&D	R-COMP
Mr. Sheperd, DIR	Mar Dishard D TO DID	Mr. Foutenhouse D COMP A
Dr. Rees, DEP-T	Mr. Richard, R-TO-DIR	Mr. Fortenberry, R-COMP-A
Mr. Gorman, DEP-A	Dr. Johnson, R-EO-DIR	Mr. Prince, R-COMP-R
	Mr. Vreuls, R-TO-DIR	Mr. Conchran, R-COMP-RR
E-S	Mr. Fellows, R-OM-DIR	R-ME
Mr. Maus, E-DIR	R-AERO	COL. DON'S THAT BUILDING WEREHOLD
Mr. Rhodes, E-D		Mr. Kuers, R-ME-DIR
Mr. Smith, E-S	Dr. Geissler, R-AERO-DIR	Mr. Crumpton, R-ME-A (4)
,	Mr. Jean, R-AERO-DIR	D DOVE
<u>I</u>	Mr. Dahm, R-AERO-A (2)	R-P&VE
NUMBER OF STREET	Mr. Holderer, R-AERO-A Mr. Horn, R-AERO-D	Dr. Lucas, R-P&VE-DIR
Gen. O'Connor, I-DIR	Mr. Deaton, R-AERO-DA	Mr. Hellebrand, R-P&VE-DIR
Dr. Hueter, I-DIR Dr. Mrazek, I-DIR	Mr. Ryan, R-AERO-DD	Mr. Palaoro, R-P&VE-DIR
Mr. Wear, I-E-J	Mr. Baker, R-AERO-G	Mr. Goerner, R-P&VE-A
Mr. Wheeler, I-E-F	Mr. McNair, R-AERO-P (3)	Mr. Stein, R-P&VE-A
Mr. Wood, I-SC-C (3)	Mr. Teague, R-AERO-P	Mr. Kingsbury, R-P&VE-M
Dr. Rudolph, I-V-MGR	Mr. Reed, R-AERO-AU	Mr. Brooksbank, R-P&VE-X
Mr. Peters, I-V-S-IVB	Mr. Cummings, R-AERO-T	Mr. McCool, R-P&VE-X
Mr. Galey, I-V-IU	Mr. Vaughan, R-AERO-Y (3)	Mr. Paul, R-P&VE-P (2)
Dr. Speer, I-MO-MGR (4)	Mr. Lindberg, R-AERO-F (25)	Mr. Thompson, R-P&VE-PA
Dr. Constan, I-MICH-MGR	2	Mr. Fuhrmann, R-P&VE-PM
Mr. Reimer, I-MICH-QP	R-ASTR	Mr. McKay, R-P&VE-PP (2)
Mr. Balch, I-MT-MGR	476	Mr. Cobb, R-P&VE-PPE
Mr. Auter, I-MT-H	Dr. Haeussermann, R-ASTR-DIR	Mr. Black, R-P&VE-PPE
Mr. Schmidt, I-K-Q	Mr. Hoberg, R-ASTR-DIR	Mr. Nelson, R-P&VE-PPE
Mr. Simmons, I-I/IB-U	Mr. Digesu, R-ASTR-A	Mr. Wood, R-P&VE-PT
Col. Teir, I-I/VB MGR	Mr. Fichtner, R-ASTR-E	Mr. McAnelly, R-P&VE-PTD
Mr. Haley, I-V-SIC	Mr. Stroud, R-ASTR-EA	Mr. Platt, R-P&VE-PTF
Mr. Odom, I-V-SII	Mr. Vann, R-ASTR-EAA	Mr. Kroll, R-P&VE-S
Mr. Higgins, I-V-SIVB	Mr. Robinson, R-ASTR-ESA	Mr. Hunt, R-P&VE-S
Mr. Sanders, I-V-G	Mr. Hosenthien, R-ASTR-F	Mr. Blumrich, R-P&VE-SA
Mr. Ginn, I-V-E	Mr. Blackstone, R-ASTR-F	Mr. Garrett, R-P&VE-SE
Mr. Cushman, I-V-T	Mr. Justice, R-ASTR-F	Mr. Katz, R-P&VE-SER
Mr. Robertson, I-V-T	Mr. Mandel, R-ASTR-G	Mr. Showers, R-P&VE-SL
Mr. Belew, I-S/AA-MGR	Mr. Ferrell, R-ASTR-GSA	Mr. Frederick, R-P&VE-SS
Mr. Bell, I-V-E	Mr. Powell, R-ASTR-I	Mr. Farrow, R-P&VE-SVM
Mr. Burns, I-V-T	Mr. Avery, R-ASTR-IMD	Mr. Green, R-P&VE-SVM
Mr. Urlaub, I-V-SIC	Mr. Ely, R-ASTR-IRD	Mr. Aberg, R-P&VE-V
Mr. Godfrey, I-V-SII	Mr. Threlkeld, R-ASTR-ITP	Mr. Glover, R-P&VE-VA
Mr. McCulloch, I-V-SIVB	Mr. Boehm, R-ASTR-M	Mr. Marmann, R-P&VE-VAW Mr. Devenish, R-P&VE-VNW (2)
Mr. Duerr, I-V-IU	Mr. Moore, R-ASTR-N	
Mr. Rowan, I-V-F	Mr. Krume, R-ASTR-NFE	Mr. Sells, R-P&VE-V00
Mr. Smith, I-V-G	Mr. Lominick, R-ASTR-NFS	Mr. Schulze, R-P&VE-VS (2)
Mr. Sneed, I-V-P	Mr. Nicaise, R-ASTR-NGI	Mr. Rothe, R-P&VE-XF Mr. Griner, R-P&VE-XJ
Mr. Moody, I-V-Q	Mr. Taylor, R-ASTR-R	Mr. Boone, R-P&VE-XK
Lt. Col. Murphy, I-K-V	Mr. Wolfe, R-ASTR-S	Mr. Boone, K-FavL-AK
The second secon	Mr. Mack, R-ASTR-S Mr. Mink, R-ASTR-FO	D_OUAL
R&D	Mr. Hammers, R-ASTR-S	R-QUAL
	Mr. Erickson, R-ASTR-ESA	Mr. Grau, R-QUAL-DIR
Mr. Weidner, R-DIR	III. LI TORSON, N-ASTN-LOA	Mr. Henritze, R-QUAL-A
Mr. Cook, R-DIR	2) R-COMP	Mr. Klauss, R-QUAL-J
Mr. Williams, R-AS-DIR (2) 1. John 1	Mr. Brooks, R-QUAL-P

Mr. Hamilton, MSC/RL (11) Dr. Hoelzer, R-COMP-DIR